PRINTED: 11/14/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155799	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE COMP	(X3) DATE SURVEY COMPLETED 10/30/2024	
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 614 WEST 14TH STREET MARION, IN 46953				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOULE CROSS-REFERENCED TO THE APPRO DEFICIENCY)	ON BE PRIATE	(X5) COMPLETION DATE	
K 0000							
Bldg. 01	that exited on 09/30 Recertification and exited on 08/08/24 Department of Heal Subpart 483.90(a). Survey Date: 10/30 Facility Number: 0 Provider Number: 1 AIM Number: 200 At this PSR survey, was found not in co for Participation in Subpart 483.90(a), 2012 edition of the Association (NFPA)	12809 155799	K 0000				
	determined to be of was fully sprinklere system with smoke open to the corridor facility has a capaci 56 at the time of thi All areas where the access were sprinkl facility services were	residents have customary ered. All areas providing					

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE OF THE PROVIDER OF THE P	URE	TITLE	(X6) DATE
Tamera Shirels	ED		11/08/2024

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 02PG23 Facility ID: 012809 If continuation sheet

PRINTED: 11/14/2024 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155799	A. BUILDING B. WING	01	(X3) DATE SURVEY COMPLETED 10/30/2024	
NAME OF PROVIDER OR SUPPLIER APERION CARE MARION LLC	STREET ADDRESS, CITY, STATE, ZIP COD 614 WEST 14TH STREET MARION, IN 46953			
(X4) ID SUMMARY STATEMENT OF DEFICIENCIE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE	
K 0741 NFPA 101 SS=E Smoking Regulations Bldg. 01				
Bldg. 01 Based on observation and interview, the facility failed to ensure 1 of 1 smoking area and 1 of 1 nonsmoking area were maintained by disposing cigarette butts in a metal or noncombustible container with self-closing cover devices. This deficient practice could affect staff and 20 residents using two emergency exits. Findings include: Based on observation with the Administrator on 10/30/24 at 11:28 a.m., outside the employee exit (a nonsmoking area) there were over 50 cigarette butts disposed on the ground around the exit. Also, in the designated smoking area there were over 30 cigarette butts on the ground and combustible material mixed with cigarettes in the butt-can. Based on interview at the time of observations, the Administrator agreed there were cigarette butts on the ground in the staff smoking area and outside the employee exit. This finding was reviewed with the Administrator at the exit conference. This deficiency was cited on 09/30/24. The facility failed to implement a systemic plan of correction to prevent recurrence. 3.1-19(b)	K 0741	Tag number: K 741 I. What corrective action will be accomplished for those residents found to have been affected by the deficient practic Smoking areas were cleaned all cigarette butts and No Smosigns have been placed in nor smoking areas. II. How other residents hat the potential to be affected by same deficient practice will be identified and what corrective action(s) will be taken; All staff were reminded that the red casmoking areas were the only place that cigarette butts are the placed. III. What measures will be into place and what systemic changes will be made to ensure the deficient practice does recur; All staff have been in-serviced on the designated smoking area and that the red cans are for cigarette butts on IV. How the corrective action(s) will be monitored to ensure the deficient practice whot recur i.e what quality assurance program will be put place; the Executive director/designee will inspect to	ice; up of oking ne aving the series in the series not series in the series not series in the serie	

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED:

FORM APPROVED

11/14/2024

OMB NO. 0938-039 STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 155799 B. WING 10/30/2024 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 614 WEST 14TH STREET APERION CARE MARION LLC MARION, IN 46953 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY) PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DATE smoking court yard 2 times a day, Monday - Friday, to ensure staff are depositing cigarette butts in the red can. The results of these audits will be reviewed in Quality Assurance Meeting monthly x6 months or until an average of 90% compliance or greater is achieved x3 consecutive months. The QA Committee will identify any trends or patterns and make recommendations to revise the plan of correction as indicated.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 02PG23 Facility ID: 012809 If continuation sheet Page 3 of 3