

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/12/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155042	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED C 09/10/2024
NAME OF PROVIDER OR SUPPLIER APERION CARE VINCENNES			STREET ADDRESS, CITY, STATE, ZIP CODE 3801 OLD BRUCEVILLE ROAD, BOX 136 VINCENNES, IN 47591		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
E 000	Initial Comments An investigation of Complaint Number IN00442152 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Complaint IN00442152 - No deficiencies related to the allegation were cited. Survey Dates: 09/10/24 Facility Number: 000016 Provider Number: 155042 AIM Number: 100291500 At this Complaint survey, Aperion Care Vincennes was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73 The facility has a capacity of 170 certified beds and had a census of 79 at the time of this visit.	E 000			
K 000	Quality Review completed on 09/11/24 INITIAL COMMENTS An investigation of Complaint Number IN00442152 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Complaint IN00442152 - No deficiencies related to the allegation were cited. Survey Dates: 09/10/24 Facility Number: 000016	K 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/12/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155042	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED C 09/10/2024
NAME OF PROVIDER OR SUPPLIER APERION CARE VINCENNES			STREET ADDRESS, CITY, STATE, ZIP CODE 3801 OLD BRUCEVILLE ROAD, BOX 136 VINCENNES, IN 47591		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	<p>Continued From page 1</p> <p>Provider Number: 155042</p> <p>AIM Number: 100291500</p> <p>At this Complaint survey, Aperion Care Vincennes was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility with a lower level was determined to be of Type V (000) construction and was fully sprinklered. The facility has a fire alarm system with hard wired smoke detectors in the corridors, spaces open to the corridors, and all resident sleeping rooms. The facility has a capacity of 170 and had a census of 79 at the time of this survey.</p> <p>All areas where the residents have customary access were sprinklered, including the smoking building, and all areas providing facility services were sprinklered, except, an enclosed metal carport used for storage of landscaping equipment, and a wood minibarn used for storage of biohazardous waste.</p>	K 000			