

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155292	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/26/2024
NAME OF PROVIDER OR SUPPLIER AMERICAN VILLAGE			STREET ADDRESS, CITY, STATE, ZIP CODE 2026 EAST 54TH ST INDIANAPOLIS, IN 46220		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{E 000}	Initial Comments A Post Survey Revisit (PSR) to the Emergency Preparedness Survey that exited on 02/02/24 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Survey Date: 03/26/24 Facility Number: 000189 Provider Number: 155292 AIM Number: 100267330 At this PSR Emergency Preparedness survey, American Village was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has 150 certified beds. At the time of the survey, the census was 120.	{E 000}			
{K 000}	Quality Review completed on 03/28/24 INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey that exited on 02/02/24 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 03/26/24 Facility Number: 000189 Provider Number: 155292 AIM Number: 100267330 At this PSR Life Safety Code survey, American Village was found in compliance with	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/01/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155292	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/26/2024
NAME OF PROVIDER OR SUPPLIER AMERICAN VILLAGE			STREET ADDRESS, CITY, STATE, ZIP CODE 2026 EAST 54TH ST INDIANAPOLIS, IN 46220		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>Continued From page 1</p> <p>Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>American Village consists of two wings, Harrison Hall which is one story and Washington Manor which is two stories. This facility was determined to be of Type III (211) construction and was fully sprinklered. The east wing of the second floor of Washington Manor houses the Moving Forward rehab wing. The facility has a fire alarm system with smoke detection on all levels in the corridors and in all areas open to the corridor. The facility has battery operated smoke detectors in 59 of 82 resident sleeping rooms. The facility has smoke detectors hard wired to the facility's electrical system in 23 of 82 resident sleeping rooms. The facility has a capacity of 150 and had a census of 120 at the time of this survey.</p> <p>All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered except for a detached storage and repair shed.</p> <p>Quality Review completed on 03/28/24</p>	{K 000}			