Indiana Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>		(X3) DATE SURVEY COMPLETED	
		001128	B. WING		R 03/26/2025	
NAME OF PI	ROVIDER OR SUPPLIER		RESS, CITY, STA	TE, ZIP CODE	1 00/2	0/2020
FRIENDS FELLOWSHIP COMMUNITY  2030 CHESTER BLVD  RICHMOND, IN 47374						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	D BE COMPLETE	
{K 000}	A Post Survey Revisit (PSR) to the PSR conducted on 01/21/25 to the Life Safety Code State Licensure Survey conducted on 11/26/24 was conducted by the Indiana State Department of Health.  Survey Date: 03/26/25  Facility Number: 001128 Provider Number: NA AIM Number: NA At this PSR survey, Friends Fellowship Community was found in compliance with Requirements of the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.		{K 000}			
	fully sprinkled. The far system with smoke do including the baseme open to the corridors detectors in the 24 Co and battery operated Health Center Hall reshas a capacity of 92 at the time of this visit.  All areas where reside	ype V (111) construction and acility has a fire alarm etection on all levels nt, the corridors, spaces and hard wired smoke purtyard Hall resident rooms smoke detectors in the 35 sident rooms. The facility and had a census of 35 at ents have customary access I areas providing facility ed.				

Indiana Department of Health

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE