

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/18/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155701	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 02 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2024
NAME OF PROVIDER OR SUPPLIER CHRISTIAN CARE RETIREMENT COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 720 E DUSTMAN RD BLUFFTON, IN 46714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
E 000	Initial Comments An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Survey Date: 11/15/24 Facility Number: 000576 Provider Number: 155701 AIM Number: 100267760 At this Emergency Preparedness survey, Christian Care Retirement Community was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has a capacity of 86 and had a census of 54 at the time of this survey.	E 000			
K 000	Quality Review completed on 11/15/24 INITIAL COMMENTS A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 11/15/24 Facility Number: 000576 Provider Number: 155701 AIM Number: 100267760 At this Life Safety Code survey, Christian Care Retirement Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), the original building was surveyed with Life Safety	K 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/18/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155701	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 02 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2024
NAME OF PROVIDER OR SUPPLIER CHRISTIAN CARE RETIREMENT COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 720 E DUSTMAN RD BLUFFTON, IN 46714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	Continued From page 1 from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. The original 1989 two story facility was determined to be of Type II (111) construction and was fully sprinklered. Healthcare was located on the second floor separated with a 2hr fire barrier from assisted living on the first floor. The facility has a fire alarm system with smoke detection in the corridors, areas open to the corridors and hard-wired smoke detectors in the resident rooms. The facility has a capacity of 86 and had a census of 54 at the time of this survey. All areas where residents have customary access were sprinklered. All areas which provided facility services were sprinklered except for the attic space which was constructed of non-combustible material. Quality Review completed on 11/15/24	K 000			
K 000	INITIAL COMMENTS A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 11/15/24 Facility Number: 000576 Provider Number: 155701 AIM Number: 100267760 At this Life Safety Code survey, Christian Care Retirement Community was found in compliance	K 000			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/18/2024
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155701	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 02 B. WING _____		(X3) DATE SURVEY COMPLETED 11/15/2024
NAME OF PROVIDER OR SUPPLIER CHRISTIAN CARE RETIREMENT COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 720 E DUSTMAN RD BLUFFTON, IN 46714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	<p>Continued From page 2</p> <p>with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), the new Southwood wing was surveyed with Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 18, New Health Care Occupancies and 410 IAC 16.2.</p> <p>The 2018 rehabilitation two story addition was determined to be of Type II (111) construction and was fully sprinklered. The rehab-wing was located on the second floor separated with a 2hr fire barrier from assisted living on the first floor. The facility has a fire alarm system with smoke detection in the corridors, areas open to the corridors and hard-wired smoke detectors in the resident rooms. The facility has a capacity of 86 and had a census of 54 at the time of this survey.</p> <p>All areas where residents have customary access were sprinklered. All areas which provided facility services were sprinklered except for the attic space which was constructed of non-combustible material.</p> <p>Quality Review completed on 11/15/24</p>	K 000			