



69. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.



70. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Please note the concrete headwall in the background. This structure will not be impacted as part of this project. Photo taken October 7, 2020.



71. Looking east along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken October 08, 2020.



72. Looking north at a double barrel culvert located on the south side of SR 32. This structure will not be impacted as part of this project. Photo taken October 8, 2020.



73. Looking northwest along the south side of SR 32 (EB lane) at the surrounding landscape just northwest of the double barrel culvert. Photo taken October 8, 2020.



74. Looking south/southwest at a double barrel culvert located on the north side of SR 32. Photo taken October 7, 2020.



75. Looking northwest just west of the double barrel culvert pipe located on the north side of SR 32. Photo taken October 7, 2020.



76. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



77. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



78. Looking east along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



79. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



80. Looking northwest along the north side of SR 32 and at CR 500 W. Please note the concrete headwall for a small diameter culvert pipe that conveys drainage underneath CR 500 W. Photo taken October 7, 2020.



81. Looking northeast at a close up of the small diameter culvert pipe that conveys drainage underneath CR 500 W. on the west side of CR 500 W. Note that it is partially buried. Photo taken October 7, 2020.



82. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape just east of CR 500W. Photo taken October 7, 2020.



83. Looking east along the south side of SR 32 (EB lane) at the surrounding landscape just east of CR 500W. Photo taken October 7, 2020.



84. Looking south/southwest down the east side of CR 500 W. just south of SR 32. Photo taken October 8, 2020.





85. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape just west of CR 500 W. Photo taken October 8, 2020.



86. Looking east along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



87. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



88. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



89. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



90. Looking east along the south side of SR 32 (EB lane) from just east of the Pleasant View Church. Photo taken October 8, 2020.



91. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



92. Looking west along the south side of SR 32 (EB lane) from the drive to Pleasant View Church. Photo taken October 8, 2020.



93. Looking south (upstream) of Wolf Creek located on the south side of SR 32. Photo taken October 8, 2020.



94. Looking south (upstream) of Wolf Creek and underneath Bridge No. 032-06-00583 D. Photo taken October 7, 2020.



95. Looking northeast (downstream) of Wolf Creek located along the north side of SR 32. Photo taken October 7, 2020.



96. Looking west up the north side (WB lane) of SR 32 just west of Wolf Creek. Photo taken October 7, 2020.



97. Looking west along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2021.



98. Looking east along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2021.



99. Looking west along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2021.



100. Looking east along the north side (WB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2021.





101. Looking west along the north side (WB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2021.



102. Looking east at the surrounding landscape along the south side (EB lane) of SR 32 from a farm field drive. Photo taken October 8, 2020.



103. Looking west at the surrounding landscape along the south side (EB lane) of SR 32 from a farm field drive. Photo taken October 8, 2020.



104. Looking east at the surrounding landscape along the north side (WB lane) of SR 32. Photo taken July 6, 2021.



105. Looking west at the surrounding landscape along the north side (WB lane) of SR 32 from a residential drive. Photo taken July 6, 2021.



106. Looking south at CV 032-006-54.47 located on the north side of SR 32. No stream or wetland feature was found. This structure will not be impacted as part of this project. Photo taken October 7, 2020.



107. Looking northeast at CV 032-006-54.47 located along the south side of SR 32. No stream or wetland features were observed. Photo taken July 6, 2021.



108. Looking south along the west side of CR 600 W. at the surrounding landscape just south of SR 32. Photo taken October 8, 2020.



109. Looking north along the west side of CR 600 W. just north of SR 32 at the surrounding landscape. Photo taken October 7, 2020.



110. Looking west along the north side (WB lane) of SR 32 at the surrounding landscape from the CR 600 W. intersection. Photo taken October 7, 2020.



111. Looking west from an access drive to an electric substation along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken October 8, 2020.



112. Looking west at the surrounding landscape located along the north side (WB lane) of SR 32 just east of large box culvert (CV 032-006-54.25). Please note that Wetland C can be seen in the background. Photo taken October 7, 2020.



113. Looking east at Wetland C located on the north side of SR 32 just east of Little Sugar Creek. No impacts to Wetland C will occur with this project. Photo taken October 7, 2020.



114. Looking southwest from Wetland C at Little Sugar Creek which originates here at the inlet side of CV 032-006-54.25. There will be no impacts to Little Sugar Creek or this structure as part of this project. Photo taken October 7, 2020.



115. Looking west at Little Sugar Creek along the south side of SR 32. CV 032-006-54.25 can be seen to the right. Photo taken October 8, 2020.



116. Looking northeast at CV 032-006-54.25 along the south side of SR 32. Photo taken October 8, 2020.





117. Looking east at the surrounding landscape located along the north side (WB lane) of SR 32. Photo taken July 6, 2021.



118. Looking west at the surrounding landscape located along the north side (WB lane) of SR 32. Photo taken July 6, 2021.



119. Looking east at the surrounding landscape located along the north side (WB) lane of SR 32. Photo taken July 6, 2021.



120. Looking west at the surrounding landscape located along the north side (WB lane) of SR 32. Photo taken July 6, 2021.



121. Looking east along the south side of SR 32 (upstream) Little Sugar Creek from the wingwall of CV 032-006-53.90. This structure will not be impacted as part of this project. Photo taken October 8, 2020.



122. Looking northwest (downstream) Little Sugar Creek underneath structure CV 032-006-53.90. Photo taken October 8, 2020.



123. Looking west at Little Sugar Creek and CV 032-006-53.90 along the northside of SR 32. Photo taken October 7, 2020.



124. Looking northwest (downstream) Little Sugar Creek along the north side of SR 32. Photo taken October 7, 2020.



125. Looking west along the south side (EB lane) of SR 32 just west of CR 650 W. This photo also denotes the end of the second EB passing lane. Photo taken October 8, 2020.



126. Looking east along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2020.



127. Looking west along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2020.



128. Looking east along the north side (WB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2020.



129. Looking west along the north side (WB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2020.



Looking north along the south side of SR 32 at Structure No. 123 that conveys drainage from the existing landscape underneath SR 32. No stream or wetland features were observed. This structure will be replaced as part of this project. Photo taken October 8, 2020.



131. Looking south from Structure No. 123 at the surrounding landscape south of SR 32. No stream or wetland feature was observed. Photo taken October 8, 2020.



132. Looking west along the south side (EB lane) of SR 32 at the existing landscape just west of Structure No. 123. Photo taken October 8, 2020.





133. Looking south at Structure No. 123 located on the north side of SR 32. No stream or wetland feature was observed. Photo taken July 6, 2021.



134. Looking west along the north side (WB lane) of SR 32 just west of Structure No. 123. Photo taken July 6, 2021.



135. Looking east along the north side (WB lane) of SR 32 at the existing landscape just east of CR 700 W. Photo taken October 7, 2020.



136. Looking west along the north side (WB lane) of SR 32 at the existing landscape just west of CR 700 W. Photo taken October 7, 2020.



137. Looking east along the south side (EB lane) of SR 32 at the existing landscape just east of CR 700 W. Photo taken October 8, 2020.



138. Looking south/southwest at the existing landscape located along the east side of CR 700 W just south of SR 32. Photo taken October 8, 2020.



139. Looking west along the south side (EB lane) of SR 32 at the existing landscape just west of CR 700 W. Photo taken October 8, 2020.



140. Looking northwest at a CV 032-006-53.38 (Structure No. 122) that conveys drainage underneath SR 32. This structure will be replaced as part of this project. No stream or wetlands were observed. Photo taken October 8, 2020.



141. Looking west along the south side (EB lane) of SR 32 just west of CV 032-006-53.38. Photo taken October 8, 2020.



142. Looking south from the north side of SR 32 at Structure No. CV 032-006-53.38 (Structure No. 122) that conveys drainage underneath SR 32. Photo taken October 7, 2020.



143. Looking west along the north side (WB lane) of SR 32 just west of CV 032-006-53.38. Photo taken October 7, 2020.



144. Looking east along the south side (EB lane) of SR 32 at the surrounding landscape located just east of a private drive. Photo taken October 8, 2020.



145. Looking west along the south side (EB lane) of SR 32 at the surrounding landscape located just west of a private drive. Photo taken October 8, 2020.



146. Looking west along the south side (EB lane) of SR 32 located just west of a private drive. Photo taken October 8, 2021.



147. Looking east along the south side (EB lane) of SR 32 just east of Structure No. 121. Photo taken July 6, 2021.



148. Looking north at Structure No. 121 located along the south side of SR 32. No stream or wetland features were observed. This structure will be replaced as part of this project. Photo taken July 6, 2021.





149. Looking west along the south side (EB lane) of SR 32 just west of Structure No. 121. Photo taken July 6, 2021.



150. Looking south at Structure No. 121 located along the north side of SR 32. No stream or wetland features were observed. Photo taken July 6, 2021.



151. Looking west, just west of Structure No. 121 located along the north side (WB lane) of SR 32. Photo taken July 6, 2021.



152. Looking east along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken October 8, 2020.



153. Looking west along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken October 8, 2020.



154. Looking north at Structure No. 120 located along the south side of SR 32. No stream or wetland feature was observed. This structure will be replaced as part of this project. Photo taken July 6, 2020.



155. Looking west along the south side (EB lane) of SR 32 just west of Structure No. 120. Photo taken July 6, 2021.



156. Looking south at Structure No. 120 located along the north side of SR 32 in front of the Western Boone High School. No stream or wetland features were observed. Photo taken July 6, 2021.



157. Looking west along the north side (WB lane) of SR 32 just west of Structure No. 120. Photo taken July 6, 2021.



158. Looking west along the south side (EB lane) of SR 32 at the surrounding landscape. This photo is just east of the second EB passing lane. Photo taken October 8, 2020.



159. Looking west along the north side (WB lane) of SR 32 at the surrounding landscape. Photo taken October 7, 2020.



160. Looking east along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken October 8, 2020.



Looking west down SR 32 just west of the SR 75 intersection. The Marathon gas station is located to the left of photo. 161. Des No. 2101655 proposes to install a curbed island at this location to better define the entrance/exit to the gas station to alleviate conflicts for motorists accessing SR 32 from SR 75. Photo taken October 8, 2020.



162. Looking west along the north side (WB lane) of SR 32 just west of the SR 75 intersection at the surrounding landscape. Photo taken October 7, 2020.



163. Looking west along the north side (WB lane) of SR 32 from a residential drive at the surrounding landscape. This photo is just east of where the second WB passing lane begins. Photo taken July 6, 2020.



164. Looking west along the south side (EB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2020.





165. Looking north/northeast at the surrounding landscape located just north of Structure No. 112 along the north side of SR 32. Photo taken October 7, 2020.



166. Looking southeast at Structure No. 112 located along the north side of SR 32. No stream or wetland features were observed. This structure will be replaced as part of this project. Photo taken October 7, 2020.



167. Looking north at Structure No. 112 located along the south side of SR 32. No stream or wetland features were observed. Photo taken July 6, 2021.



168. Looking east along the south side (EB lane) of SR 32 just southwest of Structure No. 111. No stream or wetlands were observed. This structure will be replaced as part of this project. Photo taken October 8, 2020.



169. Looking east along the north side (WB lane) of SR 32 just east of Structure No. 111. Photo taken July 6, 2021.



170. Looking south at Structure No. 111 located on the north side of SR 32. Photo taken July 6, 2021.



171. Looking north along the north side (WB lane) of SR 32 just north of Structure No. 111 at the surrounding landscape. No stream or wetland features were observed. Photo taken July 6, 2021.



172. Looking west along the north side (WB lane) of SR 32 just west of Structure No. 111. Photo taken July 6, 2021.