

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/07/2016

FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: <b>15G141</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>02</u> B. WING _____	(X3) DATE SURVEY COMPLETED <b>02/24/2016</b>	
NAME OF PROVIDER OR SUPPLIER <b>PUTNAM COUNTY COMPREHENSIVE SERVICES INC</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>914 TENNESSEE ST GREENCASTLE, IN 46135</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0000  Bldg. 02	<p>A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j).</p> <p>Survey Date: 02/24/16</p> <p>Facility Number: 000678 Provider Number: 15G141 AIM Number: 100234430</p> <p>At this Life Safety Code survey, Putnam County Comprehensive Services Inc. was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies.</p> <p>This one story facility was sprinklered. The facility has a fire alarm system with hard wired smoke detectors in the corridors, sleeping rooms, and common living areas. The facility has a capacity of six and had a census of six at the time of this survey.</p> <p>Calculation of the Evacuation Difficulty</p>		K 0000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: <b>15G141</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>02</u> B. WING _____	(X3) DATE SURVEY COMPLETED <b>02/24/2016</b>
NAME OF PROVIDER OR SUPPLIER <b>PUTNAM COUNTY COMPREHENSIVE SERVICES INC</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>914 TENNESSEE ST GREENCASTLE, IN 46135</b>	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
K S056 Bldg. 02	<p>Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 1.72.</p> <p>Quality Review on 02/26/16 - DA</p> <p>483.470(j)(1)(i) LIFE SAFETY CODE STANDARD PROMPT Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7, 33.2.3.5.2 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction.</p> <p>Exception No. 1: In prompt evacuation facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of Sprinkler Systems in One and two Family Dwellings and Manufactured Homes, is permitted. Automatic sprinklers are not required in closets not exceeding 24 sq. ft. and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or materials providing a 15 minute thermal barrier.</p> <p>Exception No. 2: Not applicable</p> <p>Exception No. 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft and in bathrooms not exceeding 55 sq.</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G141	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>02</u> B. WING _____	(X3) DATE SURVEY COMPLETED 02/24/2016
NAME OF PROVIDER OR SUPPLIER  PUTNAM COUNTY COMPREHENSIVE SERVICES INC			STREET ADDRESS, CITY, STATE, ZIP CODE  914 TENNESSEE ST GREENCASTLE, IN 46135	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
	<p>ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier.</p> <p>Exception No. 4: In prompt and slow evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted.</p> <p>Exception No. 5: Not applicable</p> <p>Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.</p> <p><b>SLOW</b> Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction.</p> <p>Exception No. 1: Not Applicable</p> <p>Exception No. 2: Not Applicable</p> <p>Exception No. 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft. and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier.</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G141	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>02</u> B. WING _____	(X3) DATE SURVEY COMPLETED 02/24/2016
NAME OF PROVIDER OR SUPPLIER  PUTNAM COUNTY COMPREHENSIVE SERVICES INC			STREET ADDRESS, CITY, STATE, ZIP CODE  914 TENNESSEE ST GREENCASTLE, IN 46135	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
	<p>Exception No. 4: In prompt and slow evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted.</p> <p>Exception No. 5: Not Applicable</p> <p>Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.</p> <p><b>IMPRactical</b> Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction. 33.2.3.5.2.</p> <p>Exception No. 1: Not Applicable.</p> <p>Exception No. 2: In slow and impractical evacuation capability facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of Sprinkler Systems in One and Two Family Dwellings and Manufactured Homes, with a 30 minute water supply, is permitted. All habitable areas and closets are sprinklered. Automatic sprinklers are not required in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or materials providing a 15 minute thermal barrier.</p> <p>Exception No. 3: Not Applicable.</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G141	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>02</u> B. WING _____	(X3) DATE SURVEY COMPLETED 02/24/2016
NAME OF PROVIDER OR SUPPLIER PUTNAM COUNTY COMPREHENSIVE SERVICES INC			STREET ADDRESS, CITY, STATE, ZIP CODE 914 TENNESSEE ST GREENCASTLE, IN 46135	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>Exception No. 4: Not Applicable.</p> <p>Exception No. 5: In impractical evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted. All habitable areas and closets are sprinklered. Automatic sprinklers are not required in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or materials providing a 15 minute thermal barrier.</p> <p>Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.</p> <p>1. Based on observation and interview, the facility failed to ensure 1 of 1 automatic sprinkler head storage cabinet was provided with at least two of each type of sprinkler heads used in the facility. LSC 9.7.5 requires automatic sprinkler systems be inspected, tested and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems. NFPA 25, 2-4.1.4 requires a minimum of two sprinklers of each type and temperature rating installed shall be stored in a cabinet on the premises for replacement purposes. This deficient practice could affect all clients, as well as staff and visitors in the facility.</p> <p>Findings include:</p>	K S056	<p>1. Although we have had regular inspections of the sprinkler system since the installation we were unaware that the extrasprinkler heads did not include both types. The company that completes the inspections was contacted immediately to order the correct replacementsprinkler heads. The sprinkler heads were ordered and were in place by March 4, 2016. B &amp; R has been advised that they need to be more thorough in their inspections. The House Manager will work with B &amp; R to ensure the compliance with NFPA 25. See attached report.</p> <p>1. The Sprinkler system has been inspected regularly since installation. Due to an oversight by B &amp; R inspectors they had not specifically documented the</p>	03/04/2016

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G141	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>02</u> B. WING _____	(X3) DATE SURVEY COMPLETED 02/24/2016
NAME OF PROVIDER OR SUPPLIER  PUTNAM COUNTY COMPREHENSIVE SERVICES INC			STREET ADDRESS, CITY, STATE, ZIP CODE  914 TENNESSEE ST GREENCASTLE, IN 46135	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
	<p>Based on observation on 02/24/16 at 11:45 a.m. during a tour of the facility with the Residential House Manager, the spare sprinkler head cabinet in the sprinkler riser room had six spare sprinkler heads, however, there were no spare quick response pendent type heads. Quick response pendent type sprinkler heads were observed throughout the entire facility during the tour of the facility with the Residential House Manager. This was acknowledged by the Residential House Manager at the time of observation.</p> <p>2. Based on observation, record review and interview; the facility failed to ensure 1 of 1 sprinkler systems was continuously maintained in reliable operating condition and inspected and tested periodically. NFPA 25, 2-3.2 requires gauges shall be replaced every 5 years or tested every 5 years by comparison with a calibrated gauge. Gauges not accurate to within 3 percent of the full scale shall be recalibrated or replaced. This deficient practice could affect all clients, as well as staff and visitors in the facility.</p> <p>Findings include:</p> <p>Based on observation on 02/24/16 at 11:45 a.m. during a tour of the facility</p>			<p>gauge was inspected. Immediately following the Life Safety Survey B&amp;R was contacted to inspect/replace the gauge and document. The gauge was replaced on February 26, 2016. The House Manager will work with B&amp;R to ensure compliance with NFPA 25. See Attached report.</p>

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: <b>15G141</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>02</u> B. WING _____	(X3) DATE SURVEY COMPLETED <b>02/24/2016</b>
NAME OF PROVIDER OR SUPPLIER <b>PUTNAM COUNTY COMPREHENSIVE SERVICES INC</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>914 TENNESSEE ST GREENCASTLE, IN 46135</b>	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
	<p>with the Residential House Manager, the sprinkler system located in the sprinkler riser room had one pressure gauge. The gauge had a date of 2004 provided. Furthermore, there was no gauge replacement information in the sprinkler system inspection reports provided. Based on interview at the time of observation, the Residential House Manager acknowledged the sprinkler system gauge and sprinkler inspection reports provided lacked documentation the sprinkler system gauge has ever been replaced.</p>			