STATE OF INDIANA

INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

http://www.in.gov/iurc
Office: (317) 232-2701
Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: City Of Decatur Water Utility

UPPAC Database Record ID: 4483

Report Date: 7/17/2013 Investigator: Mike Orr

Damage Date: 2/25/2013 3:42:42 PM Damage Address: 816 Winchester St, Washington, Adams

The Parties

Excavator: **City Of Decatur Water Utility**

Address: 225 West Monroe Street, Decatur, In 46733

Facility Owner: **NIPSCO**

Pipeline Facility

Facility Type: Natural Gas Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe Type of Work Performed: Water

Damage Impact

Product Release: Yes Ignition: No

Service Interruption: True Number of Customers Affected: 1

Injuries: 0 Fatalities: 0 Repair Cost (if known): $

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes Indiana 811 Ticket Number: 1302250144 Original Start Date:

Locate Instructions: LOCATE THE SIDEWALK AREA NEXT TO THE DRIVEWAY

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing water work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 4/16/2013. The excavator had a valid locate ticket; however, the gas operator self reported a failure to provide locate markings.

Conclusion: There was a failure to provide facility locate markings.

Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.

150 West Market Street, Suite 600
Indianapolis, IN 46204

April 22, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 4483
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 4483

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 2/25/2013

Event Location: 816 Winchester St

City: Washington

Facility Owner: Northern Indiana Public Service Company

Excavator: City Of Decatur Water Utility

Other Party: N/A

Pipeline Division Case No. 4483

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit") Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 4483	
Date of Event	2/25/2013
Event Location	816 Winchester St
Event City	Washington
Facility Owner	Northern Indiana Public Service Company
Excavator	City Of Decatur Water Utility
Date of IURC Information Request	3/27/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	City of Decatur Water Utility
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	225 West Monroe Street
CITY/ STATE/ZIP	Decatur / IN / 46733
PREFERRED TELEPHONE	(260)724-7171
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	816 Winchester Street
CITY/STATE/ZIP	Decatur / IN / 46733
NEAREST INTERSECTION	W. Grant Street
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8”
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	
REPAIR COST (IF KNOWN) ($)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	X
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scrapper	
Hand Tools	
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	X
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y – 1302250652
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1302250144
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	N
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	Y
POLICE DEPARTMENT RESPONSE (YES/NO	Y
AMBULANCE RESPONSE (YES/NO)	N/A
ADDITIONAL INFORMATION/COMMENTS	
Facility marking or location not sufficient (Facility was marked OK clear by USIC)	

Facility: Distribution Lines; Folder: N/A; Assigned To: USIC

```
NIPSCO 00050 IUPPSa 02/25/2013 07:54:35 1302250144-00A EMER NEW  STRT

EMERGENCY SEE REMARKS

Ticket : 1302250144 Date: 02/25/2013 Time: 07:51 Oper: AGRIGGS Chan:074

State: IN Cnty: ADAMS Twp: WASHINGTON
Cityname: DECATUR  Inside: Y Near: N
Subdivision:

Address : 816
Street  : WINCHESTER ST
Cross 1 : W GRANT ST   Within 1/4 mile: Y
Location: LOCATE THE SIDEWALK AREA NEXT TO THE DRIVEWAY
:
Grids   : 4049C0455B   4049C0455C   4049D0455B
Boundary: n 40.821958    s 40.819174    w -84.927922    e -84.924764

Work type : REPAIR WATER MAIN
Done for  : DECATUR WATER
Start date: 02/25/2013  Time: 07:53  Hours notice: 0/000  Priority: EMER
Ug/Oh/Both: U  Blasting: N  Boring: N  Railroad: N  Emergency: Y
Duration  : 1 DAY         Depth: 6 FEET

Company : CITY OF DECATUR WATER UTILITY  Type: MEMB
Co addr : 225 WEST MONROE STREET
City    : DECATUR State: IN Zip: 46733
Caller  : BILL CARPENTER Phone: (260)724-7171
Contact : BILL CARPENTER (CELL) Phone:
BestTime:
Mobile  : (260)223-5198
Fax     : (260)724-7213
Email   : DECATURWATER@YAHOO.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW EN ROUTE
Will you be white-lining the dig site area? NO
:

Submitted date: 02/25/2013 Time: 07:51
Members: AEPIN  ID2034 ID3814 ID5857 ID8822 ID9036 NIPSCO SM
```

Facility: Distribution Lines; Folder: N/A; Assigned To: USIC

NIPSCO 00163 IUPPSa 02/25/2013 09:50:00 1302250652-00A EMER DAMG STRT

DAMAGE SEE REMARKS

Ticket : 1302250652 Date: 02/25/2013 Time: 09:46 Oper: ALOUIE Chan:015

State: IN Cnty: ADAMS Twp: WASHINGTON
Cityname: DECATUR Inside: Y Near: N
Subdivision:

Address : 816
Street : WINCHESTER ST
Cross 1 : W GRANT ST Within 1/4 mile: Y
Location: LOCATE THE SIDEWALK AREA NEXT TO THE DRIVEWAY
:
Grids : 4049C8455B 4049C8455C 4049D8455B
Boundary: n 40.821958 s 40.819174 w -84.927922 e -84.924764

Work type : REPAIR WATER MAIN
Done for : DECATUR WATER
Start date: 02/25/2013 Time: 09:46 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 6 FEET

Company : CITY OF DECATUR WATER UTILITY Type: MEMB
Co addr : 225 WEST MONROE STREET
City : DECATUR State: IN Zip: 46733
Caller : BILL CARPENTER Phone: (260)724-7171
Contact : BILL CARPENTER (CELL) Phone:
BestTime:
Mobile : (260)223-5198
Fax : (260)724-7213
Email : DECATURWATER@YAHOO.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
A NIPSCO GAS LINE HAS BEEN DAMAGED---THE GAS LINE IS NOT BLOWING---WHEN THE LINE
WAS CUT IT WAS PINCHED---THE DIGGING WAS DONE ON THE FRONT OF THE PROPERTY NEAR
THE STREET---THE LINE WAS AN ORANGE OR CREAM COLOR LINE SOMEWHERE BETWEEN HALF
INCH AND THREE QUARTER INCH---THE CREW IS STILL ON SITE---NIPSCO HAS BEEN
CALLED--- ADVISED TO CALL 911
Will you be white-lining the dig site area? NO
:

Submitted date: 02/25/2013 Time: 09:46
Members: AEPIN ID2034 ID3814 ID5857 ID8822 ID9036 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA FORT WAYNE MAXIMO WO # M683952

OPERATING AREA CONTACT Jason Hamers JOB ORDER # S 8958852

TRACKING NUMBER 018 20130225002 LOCATE REF # 1302250144

Locate Performed By: USIC

DATE AND TIME OF ACCIDENT 2-25-13 2013 9:34AM DATE OF REPORT 2-25-13

PLACE OF DAMAGE (INCLUDE CITY) 816 WINCHESTER ST, DECATUR 46733

DAMAGE WAS TO:

ELECTRIC - POLE / TRANSFORMER: # _____ SIZE _____ YEAR INSTALLED _____ BROKEN YES ( ) NO ( )

OTHER (DESCRIBE) _____

GAS: SERVICE (X) MAIN ( ) SIZE 5/8 MATERIAL: PLASTIC (X) STEEL ( ) METER ( ) REG STATION ( ) STUB ( )

OTHER (DESCRIBE) _____

DEPTH OF FACILITY (Inches) 24" PRESSURE (PSI) 45 Lbs.

RELEASE OF GAS: YES (X) NO ( ) IGNITION OF GAS: YES ( ) NO (X) EVACUATION REQUIRED: YES ( ) # _____ NO (X)

INTERRUPTION OF SERVICE: YES (X) NO ( ) NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED 9:34AM TIME SHUT OFF 10:00AM TIME RESTORED 11:00AM

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 5/8

LOCATE MARKS ON SITE: YES (X) DISTANCE BETWEEN FACILITY AND LOCATE MARKS JUST MARKED OK NO ( )

HOW LOCATED: PAINT (X) FLAGS ( ) BOTH ( ) WHITE LINED ( )

PARTY THAT CAUSED DAMAGES (NAME) CITY OF DECATUR

ADDRESS OF PARTY (INCLUDE CITY) _____

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE ABOVE

WITNESS NAME AND ADRESS _____

WITNESS REMARKS _____

AGENCIES NOTIFIED / ONSITE: POLICE (X) AGENCY _____ REPORT # _____

FIRE (X) AGENCY _____ REPORT # _____

OTHER ( ) _____ Any Injuries? ( ) YES # _____ ( ) NO

PHOTOS TAKEN: YES ( ) NO (X) TAKEN BY: _____ (ATTACH PHOTOS TO REPORT)

MEDIA ON SITE YES ( ) NO ( )

WORK IN PROGRESS WHEN FACILITY DAMAGED – CHECK APPROPRIATE CHOICE BELOW

( ) AGRIGULTURE/FARMING	( ) CABLE TV	( ) CURB/SIDEWALK	( ) TELECOMMUNICATIONS
( ) BLDG CONSTRUCTION	( ) DEMOLITION	( ) DRAINAGE	(X) WATER
( ) DRIVEWAY	( ) ELECTRIC	( ) SURVEYING	( ) DRAINS/CULVERTS
( ) FENCING	( ) GRADING	( ) IRRIGATION	( ) MOWING
( ) LANDSCAPING	( ) PIPELINE	( ) MILLING	( ) OTHER _____
( ) POLE/SIGN POST	( ) ROAD WORK	( ) SEWER	

TYPE OF EQUPMENT USED – CHECK APPROPRIATE CHOICE BELOW

( ) AUGER	( ) HAND TOOLS	(X) BACKHOE/TRACKHOE
( ) MILLING EQUIPMENT	( ) PROBING DEVICE	( ) BORING / DRILLING
( ) EXPLOSIVES	( ) TRENCHER	( ) FARM EQUIPMENT
( ) VACCUUM EQUIPMENT	( ) GRADER	( ) OTHER

REASON DAMAGE OCCURRED– CHECK APPROPRIATE CHOICE BELOW

( ) AUTOMOTIVE ACCIDENT	( ) EXCAVATING BEFORE LOCATES DUE	( ) CARELESS MACHINE OPERATOR
( ) NO NOTIFICATION	( ) MARKS DISTURBED	( ) STUB (X) OTHER MISLOCATED

- **SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM**

SIN #110601 Rev. 6-12

COMMENTS: LOCATE MARKS JUST SAID OK

PERSON PREPARING REPORT [illegible]

FIELD SUPERVISOR [illegible] 022505

FIELD MANAGER RANDALL DUNN [illegible]

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information



FOR OFFICE USE ONLY:

• DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE	YES	NO
• NO IN 811 LOCATE CALLED IN	YES	NO
• DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE	YES	NO
• EXPIRED LOCATE	YES	NO
• WAS WHITE LINING INDICATED ON LOCATE REQUEST	YES	NO

COMPLETED BY: _____ DATE: _____

Fact Based Investigation Report

Notification ID	01820130225004
Damage Date	02/25/2013 09:50
Notified By	BILL CARPENTER ()
Damage Address	816 WINCHESTER ST DECATUR, IN
District	Northern Indiana
Notification Date	02/25/2013 09:55

Damaged Customer NIPSCO

Investigation Date From 02/25/2013 00:00:00 **To** 02/25/2013 00:00:00

Excavator Involved DECATUR WATER DEPT
Type of Excavation WATER MAIN REPAIR

Orig. Locate Request 1302250144 **Start Date** 02/25/2013 00:00
Type of Ticket Emergency **Locate Req. Info N/A**

Damage Request # 1302250652 **Start Date**

Pictures Taken By TOM WILL **Date** 02/25/2013 00:00
Photography Type Digital **Frame #**

Investigator Emp. # 117465 **Investigator Name** TOM WILL
Based on your investigation, is further investigation needed? Possibly

Fact Based Investigation Customer Information
Facility Description Low Profile **Facility ID** Gas Service
Locator Name & EMP # Perez Victor - 124414 **Locator Not Known**

Investigation Findings
Other
Other Notes
NOT MARKED

Investigation Methods
Investigator Verified Existing Marks By Hooking Up
Visual, Facility Exposed At Time Of Investigation

Investigator Statement/Causal Factors
NO MARKS VISIBLE ON SITE. I WAS TOLD THERE WAS AN OK ON SITE, BUT AREA WAAS DUG UP UPON ARRIVAL.
Names of Utility Representatives Contacted or on Site and Statement
JOHN HARTMAN VIA PHONE. JOHN STATED THERE WAS AN OK MARKED ON SITE.
Names of Excavator's Representatives Contacted or on Site and Statement
BILL CARPENTER. BILL STATED THERE WAS AN OK MARKED ON SITE.
Other individuals on site
WATER DEPT CREW

Were any markings visible on the damage site upon arrival? No

Were any other indicators of facility present in the area?	Yes
Was the excavation within the tolerence zone of marks?	No
Extent of facility damage	CUT 5/8 PL SRV
Replacement Footage	APPROX 12"
Was contractor assistance required? If yes, who?	No
What contractor equipment was used?	N/A
Is the facility shown on the utility records?	No
If yes, list record numbers	N/A

Property of United States Infrastructure Corporation
Photo taken on 2/23/2013 11:37:38 AM

INFORMATION REQUEST
State Form 54909 (R / 3-13)
INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

RECEIVED
APR 16 2013
INDIANA UTILITY
REGULATORY COMMISSION

Case Number: 4483

Date of Damage *(month, day, year)*: 2/25/2013

Location of Damage:

Address (*number and street*): 816 Winchester St.

City, State and ZIP Code: Decatur,IN 46733

Nearest Intersection: W Grant St.

Excavator Information:

Business Name: City of Decatur Water

Responsible Party Personal Name: Jim Inskeep

Title (*if any*): Water Supt.

Address (*number and street*): 225 W. Monroe St.

City, State and ZIP Code: Decatur, IN 46733

Preferred Telephone Number (area code): 260-724-3814

Email Address: decaturwater@yahoo.com

Utility Information:

Utility Name: City of Decatur Water

Contact Person: Bill Carpenter

Title (*if any*): Assistant Water Supt.

Cause of Damage Information

Type of Equipment *(select one)*: Backhoe/Trackhoe

Type of Work Performed *(select one)*: Water

Repair Cost: $ _____

Did a leak result from damage:	☒ Yes	☐ No
Was there ignition:	☐ Yes	☒ No
Excavator Notify 911 due to leak:	☒ Yes	☐ No
Excavator Notify 811 upon damage:	☒ Yes	☐ No
Excavator Notify Utility upon Damage:	☒ Yes	☐ No

Locate Information

Excavator Request Locate:	☒ Yes	☐ No

Indiana 811 Locate Ticket Number: 1302250144

Locate Marks Visible:	☒ Yes	☐ No
Locate Marks Correct:	☐ Yes	☒ No
Excavator "White Lined":	☐ Yes	☒ No
Was Locate Provided within Two (2) Working Days:	☒ Yes	☐ No
Utility Employees On-site during Excavation:	☒ Yes	☐ No

Incident Information:

Fire Department Response:	☐ Yes	☒ No
Police Department Response:	☐ Yes	☒ No
Ambulance Response:	☐ Yes	☒ No

Additional Information / Comments

Locate request was called in as emergency,to repair a water main break.The locate company responded to the address of 816 Winchester St. and marked the area OK, The water department proceeded to dig ,and cut what appeared to be 1/2" to 3/4" gas service line. The water superintendent called the gas company, 911and 811 to report the damage. Nipsco service repair came and made the repairs to the gas service.The water department then finished the repair to the broken water main.

Printed Name: JIM INSKEEP

Signature: Jim Inskeep Date *(month, day, year)*: 4-11-13

**If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

Please return completed form to:

PipelineDamageCase@urc.in.gov

Or mail to:

Indiana Utility Regulatory Commission
Pipeline Safety Division - Case Number _____
101 West Washington Street, 1500E
Indianapolis, IN 46204

Or fax to:
317-233-2410

DECATUR WATER DEPT.

LOCATE #
1302250144

NAME

ADDRESS
816 Winchester st.

DATE RECEIVED
2-25-13

location
in street

DISCRIPTION OF WORK
repair water main

-

DESCRIPTION OF MATERIALS

1-6" x 8" s.s. repair clamp106022

-
-
-
-
-

VALVES OPENED & CLOSED

Measurements;

HOURS CHARGED TO JOB

MAN HRS.	EQUIPMENT HRS.
4 men 4 hrs	backhoe, dumptruck 4 hrs.

PREPARED BY
B.C.

Date job completed
2-25-13

COPY

ID3814 00001 IUPPSa 02/25/2013 07:54:35 1302250144-00A EMER NEW STRT

EMERGENCY SEE REMARKS

Ticket : 1302250144 Date: 02/25/2013 Time: 07:51 Oper: AGRIGGS Chan:074

State: IN Cnty: ADAMS Twp: WASHINGTON
Cityname: DECATUR Inside: Y Near: N
Subdivision:

Address : 816
Street : WINCHESTER ST
Cross 1 : W GRANT ST Within 1/4 mile: Y
Location: LOCATE THE SIDEWALK AREA NEXT TO THE DRIVEWAY
:
Grids : 4049C8455B 4049C8455C 4049D8455B
Boundary: n 40.821958 s 40.819174 w -84.927922 e -84.924764

Work type : REPAIR WATER MAIN
Done for : DECATUR WATER
Start date: 02/25/2013 Time: 07:53 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 6 FEET

Company : CITY OF DECATUR WATER UTILITY Type: MEMB
Co addr : 225 WEST MONROE STREET
City : DECATUR State: IN Zip: 46733
Caller : BILL CARPENTER Phone: (260)724-7171
Contact : BILL CARPENTER (CELL) Phone:
BestTime:
Mobile : (260)223-5198
Fax : (260)724-7213
Email : DECATURWATER@YAHOO.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW EN ROUTE
Will you be white-lining the dig site area? NO
:

Submitted date: 02/25/2013 Time: 07:51
Members: AEPIN ID2034 ID3814 ID5857 ID8822 ID9036 NIPSCO SM

1302250652

COPY

ID3814 00002 IUPPSa 02/25/2013 09:50:11 1302250652-00A EMER DAMG STRT

DAMAGE SEE REMARKS

Ticket : 1302250652 Date: 02/25/2013 Time: 09:46 Oper: ALOUIE Chan:015

State: IN Cnty: ADAMS Twp: WASHINGTON
Cityname: DECATUR Inside: Y Near: N
Subdivision:

Address : 816
Street : WINCHESTER ST
Cross 1 : W GRANT ST Within 1/4 mile: Y
Location: LOCATE THE SIDEWALK AREA NEXT TO THE DRIVEWAY
:
Grids : 4049C8455B 4049C8455C 4049D8455B
Boundary: n 40.821958 s 40.819174 w -84.927922 e -84.924764

Work type : REPAIR WATER MAIN
Done for : DECATUR WATER
Start date: 02/25/2013 Time: 09:46 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 6 FEET

Company : CITY OF DECATUR WATER UTILITY Type: MEMB
Co addr : 225 WEST MONROE STREET
City : DECATUR State: IN Zip: 46733
Caller : BILL CARPENTER Phone: (260)724-7171
Contact : BILL CARPENTER (CELL) Phone:
BestTime:
Mobile : (260)223-5198
Fax : (260)724-7213
Email : DECATURWATER@YAHOO.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
A NIPSCO GAS LINE HAS BEEN DAMAGED---THE GAS LINE IS NOT BLOWING---WHEN THE LINE WAS CUT IT WAS PINCHED---THE DIGGING WAS DONE ON THE FRONT OF THE PROPERTY NEAR THE STREET---THE LINE WAS AN ORANGE OR CREAM COLOR LINE SOMEWHERE BETWEEN HALF INCH AND THREE QUARTER INCH---THE CREW IS STILL ON SITE---NIPSCO HAS BEEN CALLED--- ADVISED TO CALL 911
Will you be white-lining the dig site area? NO
:

Submitted date: 02/25/2013 Time: 09:46
Members: AEPIN ID2034 ID3814 ID5857 ID8822 ID9036 NIPSCO SM

COPY