



Sidekick II™ Receiver

SK2-SS

Digital Alerting Device

*Super-bright,
multi-function alerting!*



A new generation of alerting systems with increased range, outstanding features, and fresh, elegant styling.

The NEW Signature Series Sidekick II™ 418 MHz Receiver works with all 418 MHz Silent Call transmitters and includes many new features. The bright, flashing strobe and front indicator panel alerts you quickly to visitors, calls, and emergencies. The strobe light and distinctive LEDs are activated and a digital icon is displayed indicating which transmitter sent the signal (and optional vibrator when plugged into the output connector on the back of the unit). The Sidekick II™ 418 MHz Receiver will monitor:

- Telephone
- Smoke detector
- Doorbell
- Sound monitor
- Weather Alert System
- Other Silent Call Signature Series 418 MHz transmitters

Benefits / Features:

- Increased range of up to 2000 feet
- Supervision of up to 3 smoke detectors
- Built in alarm clock
- 24 hour operation
- Direct plug in for telephone notification
- Easily installed, simple to operate
- Pulsating Bed Vibrator with predetermined output vibrations for each transmitter type (sold separately Model # VIB-PJ)
- Includes Battery Backup
- 110 candela strobe light
- 5 year limited warranty

30 Day Return Policy if not Completely Satisfied

Specifications

Power:

120VAC 60Hz

Strobe output:

110 Candela

Direct telephone input:

Modular telephone receptacle.

Vibrator output:

12V, for Silent Call VIB-PJ vibrator (optional).

Range:

Up to 2000 feet, depending on conditions.

5095 Williams Lake Road
Waterford, Michigan

(800) 572-5227 (Voice or TTY)

(248) 673-7353 (Voice or TTY)

www.silentcall.com



5 Year Warranty: Your Sidekick II™ Receiver is warranted to be free of defects in material and workmanship for five years from the date of initial purchase. During that time, the unit will be repaired or replaced free of charge (3-5 day turnaround) when shipped prepaid in original packaging to Silent Call Communications. This warranty is void if the defect is caused by customer abuse or neglect.