

Paved Shld. Width, (ft)	Shoulder Cross Slope
$\leq 4$	2% <sup>1</sup>
$> 4$	4%

Notes:

- <sup>1</sup> Where the travel lane tangent cross slope differs from 2%, the shoulder cross slope should match the travel lane cross slope.
- The shoulder pavement section should be as described in Section 52-9.02(06).

**PAVED-SHOULDER CROSS SLOPES,  
TANGENT SECTION, WITHOUT UNDERDRAINS**

**Figure 45-1A(2)**