

Paved Shld. Width, (m)	Shoulder Cross Slope
≤ 1.2	2% ¹
> 1.2	2% ¹ for the 0.6 m closest to the travel lane, then 4%

Notes:

- ¹ Where the travel lane tangent cross slope differs from 2%, the shoulder cross slope should match the travel lane cross slope.
2. The shoulder pavement section should be as described in Section 52-9.02(06).

**PAVED-SHOULDER CROSS SLOPES,
TANGENT SECTION, WITH UNDERDRAINS**

Figure 45-1A(1)