TITLE 675 FIRE PREVENTION AND BUILDING SAFETY COMMISSION

Agency Correction

LSA Document #13-339(AC)

Under <u>IC 4-22-2-38</u>, corrects the following typographical, clerical, or spelling errors in LSA Document #13-339(F), posted at <u>20140827-IR-675130339FRA</u>:

- (1) In 675 IAC 13-2.6-31, delete the text of subsections (c) though (e) and redesignate the remaining subsections accordingly.
- (2) In <u>675 IAC 13-2.6-34</u>, after subsection (c) insert:
 - "(d) Delete Section 3401.4 in its entirety without substitution.
 - (e) Delete Section 3401.5 in its entirety without substitution.
- (f) Delete Section 3401.6 in its entirety without substitution." and redesignate the remaining subsections accordingly.

Filed with Publisher: October 6, 2014, 8:09 a.m.

Under IC 4-22-2-38(g)(2), this correction takes effect 45 days from the date and time filed with the Publisher.

Posted: 10/29/2014 by Legislative Services Agency

An html version of this document.

Page 1