

Company		Mine
Gibson County Coal		Gibson South Mine
Inspection Date:	Wednesday, October 6, 2021	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	75.809	
Corrective Actions Taken:	The breaker and receptacle were appropriately labeled by the operator.	
Recommendation(s):	None.	
Inspection Date:	Monday, October 18, 2021	
Areas Inspected:	Unit #1	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, October 26, 2021	
Areas Inspected:	Unit #2, 2A3 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, November 1, 2021	
Areas Inspected:	Slope belt, Mantrips: 5502, 5507, 5517, 5520, 5521, 5701, 5795, 5796, 5799.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, November 8, 2021	
Areas Inspected:	1B beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, November 17, 2021	
Areas Inspected:	#2 overland refuse beltline, clean coal tunnel, truck loadout.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

cont...

Gibson County Coal		Gibson South Mine
Inspection Date:	Monday, November 29, 2021	
Areas Inspected:	2C12 primary escapeway, 3C beltline, Unit #3	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, December 13, 2021	
Areas Inspected:	Pumps	
Findings / Law(s) Violated:	75.601-1	
Corrective Actions Taken:	Addressed with Management.	
Recommendation(s):	None.	
Inspection Date:	Monday, December 20, 2021	
Areas Inspected:	Pump Permissibility	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, December 27, 2021	
Areas Inspected:	Books, Tracking, Hoist House, Fan House, Electrical Room	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
Peabody Midwest Mining		Francisco Mine
Inspection Date:	Monday, October 4, 2021	
Areas Inspected:	2 Left Submain beltline, Unit #1	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, October 20, 2021	
Areas Inspected:	8th Main West beltline and secondary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, October 27, 2021	
Areas Inspected:	Unit #3	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, November 4, 2021	
Areas Inspected:	Unit #1	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, November 10, 2021	
Areas Inspected:	#102 Genie Lift, Tank Duster, P.C. 5020, D.V.B. 5111, Slope Belt, Mantrips: 89, 87, 2, 4.	
Findings / Law(s) Violated:	75.1910(d), 75.1722(a)	
Corrective Actions Taken:	Addressed with Management.	
Recommendation(s):	None.	
Inspection Date:	Thursday, November 18, 2021	
Areas Inspected:	Offices, Safety Building, Lift Station, Warehouse, Shop	
Findings / Law(s) Violated:	77.809	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	

cont...

Peabody Midwest Mining		Francisco Mine
Inspection Date:	Tuesday, November 30, 2021	
Areas Inspected:	1W, 2W, 3W, 4W secondary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, December 6, 2021	
Areas Inspected:	pumps	
Findings / Law(s) Violated:	75.512-2, 75.1100(2)(e), 75.517	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, December 14, 2021	
Areas Inspected:	Permissibility on PC's, Unit #1 and Unit #3 chargers, coal haulers, and battery scoops.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, December 30, 2021	
Areas Inspected:	Unit #3	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	The Unit Looked Great!	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Tuesday, October 5, 2021	
Areas Inspected:	Unit #3, #2 Double Boom Roof Bolter	
Findings / Law(s) Violated:	75.211(d)	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Thursday, October 21, 2021	
Areas Inspected:	M16 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Friday, October 29, 2021 3rd Shift	
Areas Inspected:	Unit #4	
Findings / Law(s) Violated:	75.904	
Corrective Actions Taken:	The operator properly identified the breaker, receptacle, and cathead.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, November 2, 2021	
Areas Inspected:	1 North A beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, November 9, 2021	
Areas Inspected:	4H, 4I beltlines and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, November 16, 2021	
Areas Inspected:	S4-J, S4-K, S4-M beltlines and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

cont...

Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Monday, November 22, 2021	
Areas Inspected:	S4M, S4N, S4O beltlines and primary escapeways.	
Findings / Law(s) Violated:	75.515	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, December 1, 2021	
Areas Inspected:	M17, SB3 beltlines and primary escapeways, M16 tail.	
Findings / Law(s) Violated:	75.1731(b)	
Corrective Actions Taken:	Addressed with Management.	
Recommendation(s):	None.	
Inspection Date:	Thursday, December 2, 2021	
Areas Inspected:	PM 17 beltline and primary escapeway, Unit #3	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, December 7, 2021	
Areas Inspected:	Pumps Permissibility	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, December 16, 2021	
Areas Inspected:	Pumps Permissibility	
Findings / Law(s) Violated:	75.517	
Corrective Actions Taken:	Pump was removed from service.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, December 28, 2021	
Areas Inspected:	Unit #1	
Findings / Law(s) Violated:	75.1106-3(a)(2)	
Corrective Actions Taken:	The operator secured the cylinder.	
Recommendation(s):	None.	

Company		Mine
Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Tuesday, October 19, 2021	
Areas Inspected:	Books/Records	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, October 25, 2021	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, November 3, 2021	
Areas Inspected:	M4 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, November 15, 2021	
Areas Inspected:	PM-16 and PM-16 1st Left belting and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, November 23, 2021	
Areas Inspected:	M8A, M9, M10 1st Right Seals, M9 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, December 15, 2021	
Areas Inspected:	Unit #1	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

cont...

Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Wednesday, December 29, 2021	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		