

Company		Mine
<b>Gibson County Coal</b>		<b>Gibson South Mine</b>
Inspection Date:	<b>Wednesday, April 13, 2022</b>	
Areas Inspected:	<b>Unit #3</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, April 18, 2022 2nd Shift</b>	
Areas Inspected:	<b>1st North East 2 beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>75.512, 75.512</b>	
Corrective Actions Taken:	<b>The access doors for both VFD's were closed by the operator.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, April 27, 2022</b>	
Areas Inspected:	<b>Unit #2</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, May 9, 2022</b>	
Areas Inspected:	<b>Main North and 1st North East Main beltlines and primary escapeways.</b>	
Findings / Law(s) Violated:	<b>75.1731(a)</b>	
Corrective Actions Taken:	<b>Addressed with management.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, June 1, 2022</b>	
Areas Inspected:	<b>Unit #1</b>	
Findings / Law(s) Violated:	<b>75.515</b>	
Corrective Actions Taken:	<b>The operator restrained the cable.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, June 15, 2022</b>	
Areas Inspected:	<b>5th North East Main beltline, 1A4 beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>75.400, 75.402, 75.1731, 75.380(d)(7)(vi) X 6</b>	
Corrective Actions Taken:	<b>Addressed with management.</b>	
Recommendation(s):	<b>Make sure transfer sprays at belt drives are properly functioning.</b>	

cont...

<b>Gibson County Coal</b>		<b>Gibson South Mine</b>
Inspection Date:	<b>Thursday, June 23, 2022</b>	
Areas Inspected:	<b>Prep Plant</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, June 29, 2022</b>	
Areas Inspected:	<b>Unit #4</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:	<b>Thursday, April 14, 2022 3rd Shift</b>	
Areas Inspected:	<b>Unit #3</b>	
Findings / Law(s) Violated:	<b>75.904</b>	
Corrective Actions Taken:	<b>The operator labeled the breaker.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, April 25, 2022</b>	
Areas Inspected:	<b>4th Main West beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, May 4, 2022</b>	
Areas Inspected:	<b>3 Main West beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Tuesday, May 10, 2022</b>	
Areas Inspected:	<b>Unit #1</b>	
Findings / Law(s) Violated:	<b>75.515</b>	
Corrective Actions Taken:	<b>The operator tightened the restraining clamp.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Thursday, May 19, 2022</b>	
Areas Inspected:	<b>2 Main West beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>75.380(d)(7)(vi)</b>	
Corrective Actions Taken:	<b>Addressed with management.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Thursday, June 16, 2022</b>	
Areas Inspected:	<b>Main South and 1st Main West beltlines.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	

cont....

<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:	Wednesday, June 22, 2022	
Areas Inspected:	1 South, 9 West beltlines and primary escapeways.	
Findings / Law(s) Violated:	75.809, 75.512, 75.515, 75.512, 75.601-1, 75.601-1, 75.380(d)(7)(vii)	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	

Inspection Date:	Tuesday, June 28, 2022	
Areas Inspected:	Prep plant, surface belts.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	<b>Monday, April 4, 2022</b>	
Areas Inspected:	<b>S1-D beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>75.515</b>	
Corrective Actions Taken:	<b>The operator tightened the strain relief clamp.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Tuesday, April 12, 2022</b>	
Areas Inspected:	<b>Unit #4</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Thursday, April 21, 2022</b>	
Areas Inspected:	<b>M10 beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Thursday, April 28, 2022 3rd Shift</b>	
Areas Inspected:	<b>Unit #2</b>	
Findings / Law(s) Violated:	<b>75.370(a)(1)</b>	
Corrective Actions Taken:	<b>The operator rolled down the curtain to maintain ventilation to the face.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Friday, May 6, 2021</b>	
Areas Inspected:	<b>M-7 beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, May 16, 2022</b>	
Areas Inspected:	<b>M6 beltline and intake air course.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	

cont....

<b>Sunrise Coal</b>		<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	<b>Thursday, June 2, 2022</b>	
Areas Inspected:	<b>Unit #2, Main East beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>75.1403, 75.211(d), 75.1100-2€</b>	
Corrective Actions Taken:	<b>Addressed with management.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, June 6, 2022</b>	
Areas Inspected:	<b>M2 beltline</b>	
Findings / Law(s) Violated:	<b>75.515, 75.515, 75.515</b>	
Corrective Actions Taken:	<b>Addressed with management.</b>	
Recommendation(s):	<b>The operator should consider rock dusting the M2 beltline.</b>	
Inspection Date:	<b>Monday, June 20, 2022</b>	
Areas Inspected:	<b>M4 intake, beltline, and belt transformer #21</b>	
Findings / Law(s) Violated:	<b>75.601-1</b>	
Corrective Actions Taken:	<b>The operator adjusted the instantaneous to 300A.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Thursday, June 30, 2022</b>	
Areas Inspected:	<b>M3 beltline and intake air course.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	Tuesday, April 5, 2022	
Areas Inspected:	M10 1st Right, M9, and M8A Seals.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, April 19, 2022	
Areas Inspected:	Seals: M7A, S1A, 3rd Main South, 2nd Main South.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, May 2, 2022	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, May 12, 2022 3rd Shift	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, June 14, 2022	
Areas Inspected:	M1 seals, beltline, and intake air course.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, June 21, 2022	
Areas Inspected:	Prep Plant	
Findings / Law(s) Violated:	77.206(a), 77.1109(c)(1), 77.1606(p)	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	

cont....

<b>Sunrise Coal</b>		<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	Monday, June 27, 2022	
Areas Inspected:	Surface belts and rail load out.	
Findings / Law(s) Violated:	77.206A, 77.205B	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	Make sure that portable fire extinguishers comply with NFPA-10.	

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		