

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/24/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155203	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED R 01/20/2023
NAME OF PROVIDER OR SUPPLIER HILLCREST VILLAGE			STREET ADDRESS, CITY, STATE, ZIP CODE 203 SPARKS AVE JEFFERSONVILLE, IN 47130		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 12/13/22 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).</p> <p>Survey Date: 01/20/23</p> <p>Facility Number: 000110 Provider Number: 155203 AIM Number: 100271120</p> <p>At this PSR survey, Hillcrest Village was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>Hillcrest Village is a two story building with a finished partial basement. The building was constructed at two different times. The original building was built in 1966 and constructed with mixed construction consisting of a two and one-half inch thick concrete decks separating each floor, one hour fire rated smoke barrier walls, two fire barrier walls constructed of two hour construction on each level, brick exterior walls with metal studs and one-half hour rated drywall, a mix of concrete and metal stud interior walls with one-half hour rated drywall, and metal trusses and wooden rafters in the roof assembly. Based on the lowest construction type, the facility construction type was classified as Type V (111) construction. The original building was built with an open column foundation exposed at the entire</p>	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/24/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155203	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED R 01/20/2023
NAME OF PROVIDER OR SUPPLIER HILLCREST VILLAGE			STREET ADDRESS, CITY, STATE, ZIP CODE 203 SPARKS AVE JEFFERSONVILLE, IN 47130		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>Continued From page 1</p> <p>south length of the facility. In 1974, a two story addition including the level 1 Transcare Unit and level 2 East Wing was constructed to the southeast of the original building and the column foundation was converted into a poured finished partial basement for physical therapy and is also of Type V (111) construction. Because the original building and the addition are the same type of construction, the facility was surveyed as one building.</p> <p>The facility is fully sprinklered. The facility has a fire alarm system with smoke detection on all levels including the corridors, spaces open to the corridors, and battery operated smoke detectors in all resident sleeping rooms. The facility has a capacity of 149 and had a census of 118 at the time of this survey.</p> <p>All areas where residents have customary access were sprinkled and all areas providing facility services were sprinkled except the detached laundry building and storage shed.</p> <p>Quality Review completed on 01/23/23</p>	{K 000}			