

MASTER BEAD SUBGRANT AGREEMENT (GRANT AGREEMENT)
for the award of
BROADBAND EQUITY, ACCESS, AND DEPLOYMENT (BEAD) FUNDS
between
THE STATE OF INDIANA – INDIANA BROADBAND OFFICE (IBO)
and
CENTRAL INDIANA COMMUNICATIONS, INC. F/K/A NINESTAR CONNECT

CONTRACT #00000000000000000000101849

This **Master BEAD Subgrant Agreement** ("Grant Agreement" or "Agreement"), entered into by and between the State of Indiana acting by and through the Indiana Broadband Office (the "State" or "IBO" or "Eligible Entity" or "Grantee") and Central Indiana Communications, Inc. f/k/a NineStar Connect (the "Subgrantee" or "Subrecipient" or "Lower Tier Participant"), is executed pursuant to the terms and conditions set forth herein. In consideration of those mutual undertakings and covenants, the parties agree as follows:

1. Purpose of this Grant Agreement; Funding Source. The purpose of this Grant Agreement is to enable the State to award subgrants¹ totaling **\$16,742,798.00** (the "Grant" or "Award Funds") to the Subgrantee for eligible costs of the broadband infrastructure project (the "Project" or "Deployment Project") described in each individual **Exhibit and corresponding Appendixes** to this Grant Agreement, which are incorporated fully herein. The funds shall be used exclusively in accordance with the provisions contained in this Grant Agreement and in conformance with Indiana Code IC § 4-4-38.6, the federal Infrastructure Investment and Jobs Act (P.L. 117-58, "IIJA" or "Infrastructure Act"), the BEAD NOFO, 2 CFR Part 200, the General Terms and Conditions for the BEAD Program, and the Department of Commerce Standard Terms and Conditions, as well as any regulations, rules and guidance adopted thereunder. This Grant Agreement is issued as a Fixed Amount Subaward per 2 CFR 200.333 and in accordance with the National Telecommunications and Information Administration's (NTIA) [Policy Notice – Tailoring the Application of the Uniform Guidance to the BEAD Program](#). The funds received by the Subgrantee pursuant to this Grant Agreement shall be used only to implement the Project or provide the services in conformance with this Grant Agreement and for no other purpose.

FUNDING SOURCE:

Federal Funds - Program Name per Assistance Listings:

CFDA No.:	11.035
TITLE:	Broadband Equity, Access, and Deployment Program
AWARD No.:	18-20-B297; 07/19/2024
FEDERAL AGENCY:	Department of Commerce
STATE:	Indiana Broadband Office

2. Representations and Warranties of the Subgrantee.

A. The Subgrantee expressly represents and warrants to the State that it is statutorily eligible to receive these Grant funds and that the information set forth in its Grant Application is true, complete and accurate. The Subgrantee expressly agrees to promptly repay all funds paid to it

¹ Subgrant and Subaward are used interchangeably throughout this Grant Agreement and has the meaning for Subaward set forth in 2 CFR 200.1.

under this Grant Agreement should it be determined either that it was ineligible to receive the funds, or it made any material misrepresentation on its grant application.

B. The Subgrantee certifies by entering into this Grant Agreement that neither it nor its principals are presently debarred, suspended, proposed for debarment, declared ineligible or voluntarily excluded from entering into this Grant Agreement by any federal or state department or agency. The term "principal" for purposes of this Grant Agreement is defined as an officer, director, owner, partner, key employee or other person with primary management or supervisory responsibilities, or a person who has a critical influence on or substantive control over the operations of the Subgrantee.

3. Implementation of and Reporting on the Project.

A. The Subgrantee shall implement and complete the Project in accordance with each separate **Exhibit** to this Grant Agreement and with the plans and specifications contained in its Grant Application, which is on file with the State and is incorporated by reference. Modification of the Project shall require prior written approval of the State.

B. The Subgrantee shall submit to the State written progress reports until the completion of the Project. These reports shall be submitted on a semiannual basis and shall contain such detail of progress or performance on the Project as is requested by the State as detailed in **Paragraph 6** of each **Exhibit** to the Grant Agreement.

4. Term.

A. **Effective Date.** This Grant Agreement commences on the date of last signature (Effective Date). Unless terminated earlier in accordance with this Grant Agreement, the parties' respective performances under this Grant Agreement shall commence on the Effective Date and shall expire **four (4) years** from the Effective Date ("Period of Performance"). The primary term of this Grant Agreement shall be from the Effective Date and shall continue until the State accepts the Subgrantee's certification of Project completion (as detailed in **Paragraph 8.F** of each separate Exhibit to this Grant Agreement) evidencing completion of all work in accordance with the terms of each **Exhibit** to the Grant Agreement, unless terminated earlier in accordance with this Grant Agreement.

B. **Extension of the Period of Performance.**

(1) The Grant Agreement, or any individual Subaward attached as an Exhibit to the Grant Agreement, at the State's discretion, may be extended beyond the four-year Period of Performance for a period of one year or less under the same terms specified in this Grant Agreement if: (1) the Subgrantee has a specific plan for use of the grant funds, with project completion expected by a specific date not more than a year after the four-year deadline; (2) the construction project is underway; or (3) extenuating circumstances require an extension of time to allow the project to be completed. An extension shall be only by written instrument signed by both the State and the Subgrantee and attached hereto as an amendment.

(2) The Subgrantee must submit an extension request in writing to the IBO no later than ninety (90) days before the expiration of the Period of Performance and provide documentation about the qualifying circumstance that warrants the extension.

5. Grant Funding.

A. The State shall fund the subgrants in the amount listed in **Paragraph 1(vii)** of each **Exhibit** to this Grant Agreement. The approved Project Budget for each subgrant is set forth in **Appendix C** of each Subaward attached to this Grant Agreement as an Exhibit to this Grant Agreement, attached hereto and incorporated herein. Project costs funded by this Grant Agreement and those funded by any local and/or private share shall not be changed or modified without the prior written consent of the State.

B. The disbursement of Grant funds to the Subgrantee shall not be made before all documentary materials required by this Grant Agreement have been received and approved by the State and this Grant Agreement has been fully approved by the State.

6. Payment of Claims; Permissible Costs.

A. All payments shall be made thirty five (35) days in arrears in conformance with State fiscal policies and procedures. As required by IC § 4-13-2-14.8, all payments will be by the direct deposit by electronic funds transfer to the financial institution designated by the Subgrantee in writing unless a specific waiver has been obtained from the Indiana State Comptroller. The Subgrantee may change its financial institution or accounts upon ninety (90) days written notice to the State.

B. Requests for payment will be processed only upon presentation of a Claim Voucher in the form designated by the State. Such Claim Vouchers must be submitted with the budget expenditure report detailing disbursements of state, local and/or private funds by project budget line items.

C. All payments are subject to the State's determination that the Subgrantee's performance to date conforms with the Project as approved, notwithstanding any other provision of this Grant Agreement.

D. All final claims and reports must be submitted to the State within **90 calendar days** after the expiration or termination of this agreement. Payment for claims submitted after that time may, at the discretion of the State, be denied.

E. Claims must be submitted with accompanying supportive documentation as designated by the State. Claims submitted without supportive documentation will be returned to the Subgrantee and not processed for payment. Failure to comply with the provisions of this Grant Agreement may result in the denial of a claim for payment.

F. The closeout of a Federal Award does not affect the right of the Federal Awarding Agency or the State to disallow costs and recover funds on the basis of a later audit or other review.

G. Payment of claims for reimbursable costs.

(1) Reimbursable Costs. The Subgrantee shall use Federal Award funds and any non-federal cost share committed to an Award to pay for reimbursable costs under the BEAD Program. Reimbursable costs are those that are reasonable, necessary, allocable, and allowable for the proposed project or other eligible activity and conform to generally accepted accounting principles. While the Federal cost principles do not apply to allowable costs for BEAD Program reimbursement, the State will look to those principles as a guide when reviewing reimbursement requests.

(2) Non-reimbursable costs are those specifically prohibited under the BEAD Program and costs that are not reasonable, necessary, allocable, nor allowable for the proposed project or other eligible activity. If the Subgrantee is found to have used grant or matching funds on a prohibited cost, the State or the Assistant Secretary may take remedial action, including but not limited to deobligation or clawback of funding.

(a) The following costs are specifically identified as prohibited under the BEAD Program:

(i) Prohibition on Use of Grant Funds for Covered Communications Equipment or Services under the Secure and Trusted Communications Networks Act. The Subgrantee (including contractors and subcontractors of subgrantees) may not use grant funds received under the BEAD Program to purchase or support any covered communications equipment or service (as defined in Section 9 of the Secure and Trusted Communications Networks Act of 2019 (47 U.S.C. § 1608)).

(ii) Prohibition on Profit and Fees. A profit, fee, or other incremental charge above actual cost incurred by the Subgrantee is not an allowable cost under this Program.

- (iii) Prohibition on Use of Grant Funds to Support or Oppose Collective Bargaining. The Subgrantee may not use grant funds, whether directly or indirectly, to support or oppose collective bargaining.
- (b) Ineligible or non-reimbursable costs include but are not limited to the following:
 - (i) Personal expenses of employees, executives, board members, and contractors, and family members thereof, or any other individuals affiliated with the Subgrantee, including but not limited to personal expenses for housing, such as rent or mortgages, vehicles for personal use and personal travel, including transportation, lodging and meals;
 - (ii) Gifts to employees; housing allowances or other forms of mortgage or rent assistance for employees except that a reasonable amount of assistance shall be allowed for work-related temporary or seasonal lodging; cafeterias and dining facilities; food and beverage except that a reasonable amount shall be allowed for work-related travel; entertainment;
 - (iii) Expenses associated with: tangible property not logically related or necessary to the broadband infrastructure project or authorized non-deployment use; corporate aircraft, watercraft, and other motor vehicles designed for off-road use except insofar as necessary or reasonable to access portions of the project area not readily accessible by motor vehicles travelling on roads; tangible property used for entertainment purposes; consumer electronics used for personal use; kitchen appliances except as part of work-related temporary or seasonal lodging assistance; artwork and other objects which possess aesthetic value;
 - (iv) Political contributions; charitable donations; scholarships; membership fees and dues in clubs and organizations; sponsorships or conferences or community events not logically related or necessary for the intended use of the subgrant; nonproduct-related corporate image advertising; and
 - (v) Penalties or fines for statutory or regulatory violations; penalties or fees for any late payments on debt, loans, or other payments.
- (3) Funds committed to each Subaward may only be used to cover allowable costs incurred during the period of performance, except for reasonable pre-award expenses² per 2 CFR 200.458³, and for allowable closeout costs incurred during the grant closeout process.

7. Project Monitoring by the State. If deemed necessary by the State and upon advance written notice, the State may conduct on-site or off-site monitoring reviews of the Project during the term of this Grant Agreement and for up to ninety (90) days after it expires or is otherwise terminated. The State may, pursuant to 2 CFR 200.332 and 200.208, change its monitoring procedures and requirements at any time during the term of this Grant Agreement, including, but not limited to placing specific award conditions on a Subaward. The Subgrantee shall extend its full cooperation and give full access to the Project site and to relevant documentation to the State or its authorized designees for the purpose of determining, among other things:

- A. Whether Project activities are consistent with those set forth in each separate **Exhibit** to this Grant Agreement, the Grant Application, and the terms and conditions of the Grant Agreement;
- B. The actual expenditure of federal, state, local and/or private funds expended to date on the Project is in conformity with the amounts for each Budget line item as set forth in **Appendix C** of each Subaward attached to this Grant Agreement as an Exhibit and that unpaid costs have been properly accrued;

² Written approval by the State will be required for subgrantees before incurring pre-subgrant costs, including pre-subgrant costs associated with equipment and materials, right of way and pole attachments, and environmental review. Pre-subgrant expenses should be clearly identified in the Budget attached to each Exhibit to the Grant Agreement.

³ Pre-award costs are those incurred before the start date of the subgrant directly pursuant to the negotiation and in anticipation of the subgrant where such costs are necessary for efficient and timely performance of the project. These costs are allowable only to the extent that they would have been allowed if incurred after the start date of the subgrant and only with the written approval of the State.

C. That Subgrantee is making timely progress with the Project, and that its project management, financial management and control systems, procurement systems and methods, and overall performance are in conformance with the requirements set forth in this Grant Agreement and are fully and accurately reflected in Project reports submitted to the State.

8. Compliance with Audit and Reporting Requirements; Maintenance of Records.

A. The Subgrantee shall submit to an audit of funds paid through this Grant Agreement and shall make all books, financial statements, accounting records and other documents available at all reasonable times to the State and auditors during the term of this Grant Agreement and for a period of three (3) years after final payment for inspection by the State or its authorized designee. The Federal agency or State's rights of access are not limited to the required retention period of this Section but last as long as the records are retained. Copies shall be furnished to the State at no cost.

B. Because the Subgrantee is a "subrecipient" of federal grant funds under 2 CFR 200.331, the Subgrantee shall arrange for a financial and compliance audit that complies with 2 CFR 200.500 *et seq.* if required by applicable provisions of 2 CFR 200 (Uniform Administrative Requirements, Cost Principles, and Audit Requirements). The Subgrantee shall submit a copy of the results of the audit under 2 CFR 200.500 to the State within the same timelines as the submission to the federal government.

C. If the Subgrantee is an entity that is not subject to Subpart F of 2 CFR Part 200 (e.g., commercial entities), the Subgrantee shall:

(1) file the Form E-1 annual financial report required by IC § 5-11-1-4. The E-1 entity annual financial report will be used to determine audit requirements applicable to non-governmental units under IC § 5-11-1-9. Audits required under this Section must comply with the State Board of Accounts *Uniform Compliance Guidelines for Examination of Entities Receiving Financial Assistance from Governmental Sources*, <https://www.in.gov/sboa/files/guidelines-examination-entities-receiving-financial-assistance-government-sources.pdf>. Guidelines for filing the annual report are included in **Attachment B** (Guidelines for Non-governmental Entities);

(2) in the case where it expends \$1,000,000 or more in grant funds during its fiscal year, submit to the National Institute of Standards and Technology (NIST) Grants Officer either (i) a financial related audit of each Department of Commerce (DOC) award or Subaward in accordance with Generally Accepted Government Auditing Standards; or (ii) a program-specific audit for each award or Subaward in accordance with the requirements contained in 2 CFR 200.507;

(3) submit a copy of the Form E-1 annual financial report from this Subsection 8.C.(1) and the results of the audit from this Subsection 8.C.(2) to the State within thirty (30) days of submission; and

(4) submit to an audit of the subgrant award upon request from the State.

D. The Subgrantee shall promptly submit to the State a copy of any final audit report of an audit performed on Subgrantee's records that related to or affects this Grant, Agreement or the Work, whether the audit is conducted by the Subgrantee or a third party.

9. Compliance with Laws.

A. With the exception of IC § 5-22, the Subgrantee shall comply with all applicable federal, state and local laws, rules, regulations and ordinances, and all provisions required thereby to be included herein are hereby incorporated by reference. The enactment or modification of any applicable state or federal statute or the promulgation of rules or regulations thereunder after execution of this Grant Agreement shall be reviewed by the State and the Subgrantee to determine whether the provisions of this Grant Agreement require formal modification.

B. The Subgrantee and its agents shall abide by all ethical requirements that apply to persons who have a business relationship with the State as set forth in IC § 4-2-6, *et seq.*, IC § 4-2-7, *et seq.* and the regulations promulgated thereunder. **If the Subgrantee has knowledge, or would have acquired knowledge with reasonable inquiry, that a state officer, employee, or special state appointee, as those terms are defined in IC 4-2-6-1, has a financial interest in the Grant, the Subgrantee shall ensure compliance with the disclosure requirements in IC § 4-2-6-10.5 prior to the execution of this Grant Agreement.** If the Subgrantee is not familiar with these ethical requirements, the Subgrantee should refer any questions to the Indiana State Ethics Commission, or visit the Inspector General's website at <http://www.in.gov/ig/>. If the Subgrantee or its agents violate any applicable ethical standards, the State may, in its sole discretion, terminate this Grant immediately upon notice to the Subgrantee. In addition, the Subgrantee may be subject to penalties under IC §§ 4-2-6, 4-2-7, 35-44.1-1-4, and under any other applicable laws.

C. The Subgrantee certifies by entering into this Grant Agreement that neither it nor its principal(s) is presently in arrears in payment of taxes, permit fees or other statutory, regulatory or judicially required payments to the State. The Subgrantee agrees that any payments currently due to the State may be withheld from payments due to the Subgrantee. Additionally, payments may be withheld, delayed, or denied and/or this Grant suspended until the Subgrantee is current in its payments and has submitted proof of such payment to the State.

D. The Subgrantee warrants that it has no current, pending or outstanding criminal, civil, or enforcement actions initiated by the State, and agrees that it will immediately notify the State of any such actions. During the term of such actions, the Subgrantee agrees that the State may suspend funding for the Project. If a valid dispute exists as to the Subgrantee's liability or guilt in any action initiated by the State or its agencies, and the State decides to suspend funding to the Subgrantee, the Subgrantee may submit, in writing, a request for review to the Indiana Department of Administration (IDOA). A determination by IDOA shall be binding on the parties. Any disbursements that the State may delay, withhold, deny, or apply under this Section shall not be subject to penalty or interest.

E. The Subgrantee warrants that the Subgrantee and any contractors performing work in connection with the Project shall obtain and maintain all required permits, licenses, registrations, and approvals, and shall comply with all health, safety, and environmental statutes, rules, or regulations in the performance of work activities for the State. Failure to do so may be deemed a material breach of this Grant Agreement and grounds for immediate termination and denial of grant opportunities with the State.

F. The Subgrantee affirms that, if it is an entity described in IC Title 23, it is properly registered and owes no outstanding reports to the Indiana Secretary of State.

G. As required by IC § 5-22-3-7:

(1) The Subgrantee and any principals of the Subgrantee certify that:

(a) the Subgrantee, except for de minimis and nonsystematic violations, has not violated the terms of:

(i) IC § 24-4.7 [Telephone Solicitation Of Consumers];

(ii) IC § 24-5-12 [Telephone Solicitations]; or

(iii) IC § 24-5-14 [Regulation of Automatic Dialing Machines];

in the previous three hundred sixty-five (365) days, even if IC 24-4.7 is preempted by federal law; and

(b) the Subgrantee will not violate the terms of IC § 24-4.7 for the duration of this Grant Agreement, even if IC § 24-4.7 is preempted by federal law.

(2) The Subgrantee and any principals of the Subgrantee certify that an affiliate or principal of the Subgrantee and any agent acting on behalf of the Subgrantee or on behalf of an affiliate or principal of the Subgrantee, except for de minimis and nonsystematic violations,

(a) has not violated the terms of IC § 24-4.7 in the previous three hundred sixty-five

(365) days, even if IC § 24-4.7 is preempted by federal law; and
(b) will not violate the terms of IC § 24-4.7 for the duration of this Grant Agreement even if IC § 24-4.7 is preempted by federal law.

10. Debarment and Suspension.

A. The Subgrantee certifies by entering into this Grant Agreement that it is not presently debarred, suspended, proposed for debarment, declared ineligible or voluntarily excluded from participating in covered transactions or entering into this Grant by any federal department or agency or by any department, agency or political subdivision of the State. The term "principal" for purposes of this Grant Agreement means an officer, director, owner, partner, key employee or other person with primary management or supervisory responsibilities, or a person who has a critical influence on or substantive control over the operations of the Subgrantee.

B. The Subgrantee certifies that it has verified the suspension and debarment status for all subcontractors receiving funds under this Grant Agreement and shall be solely responsible for any recoupments or penalties that might arise from non-compliance. The Subgrantee shall immediately notify the State in writing: (1) if at any time the Subgrantee learns that its certification was erroneous when submitted, or (2) if any subcontractor becomes debarred or suspended, and shall, at the State's request, take all steps required by the State to terminate its contractual relationship with the subcontractor for work to be performed under this Grant Agreement.

C. The certification in this Section is a material representation of fact upon which reliance was placed when this transaction was entered into. If it is later determined that the Subgrantee knowingly rendered an erroneous certification, in addition to other remedies available to the federal government, the department or agency with which this transaction originated may pursue available remedies, including suspension or debarment.

D. BEAD Specific Debarment Certifications. The Subgrantee further provides the certification set out below and shall comply with the requirements of 2 CFR Parts 180, 1200 and 1326.

(1) The terms covered transaction, civil judgment, debarment, suspension, ineligible, participant, person, principal, and voluntarily excluded, as used in this clause, are defined in 2 CFR Parts 180, 1200 and 1326. The Subgrantee may contact the person in Section 18 of this Grant Agreement for assistance in obtaining a copy of those regulations.

(2) The Subgrantee agrees by entering this Grant Agreement that, should the proposed covered transaction be entered into, it shall not knowingly enter into any lower tier covered transaction with a person who is proposed for debarment under 48 CFR Part 9, Subpart 9.4, debarred, suspended, declared ineligible, or voluntarily excluded from participation in this covered transaction, unless authorized by the department or agency with which this transaction originated.

(3) The Subgrantee further agrees by entering this Grant Agreement that it will include the clause titled "Instructions for Lower Tier Participant Certification" including the "Certification Regarding Debarment, Suspension, Ineligibility and Voluntary Exclusion- Lower Tier Covered Transaction," without modification, in all lower tier covered transactions and in all solicitations for lower tier covered transactions and will require lower tier participants to comply with 2 CFR Parts 180 and 1200.

(a) A participant in a covered transaction may rely upon a certification of a prospective participant in a lower tier covered transaction that it is not proposed for debarment under 48 CFR Part 9, Subpart 9.4, debarred, suspended, ineligible, or voluntarily excluded from the covered transaction, unless it knows that the certification is erroneous. A participant is responsible for ensuring that its principals are not suspended, debarred, or otherwise ineligible to participate in covered transactions. To verify the eligibility of its principals, as well as the eligibility of any prospective lower tier participants, each participant may, but is not required to, check the System for Award Management Exclusions website (<https://www.sam.gov>).

(b) Nothing contained in the foregoing shall be construed to require establishment of a system of records in order to render in good faith the certification required by this clause.

The knowledge and information of a participant is not required to exceed that which is normally possessed by a prudent person in the ordinary course of business dealings.
(c) Except for transactions authorized under subsection D(2) of these instructions, if a participant in a covered transaction knowingly enters into a lower tier covered transaction with a person who is proposed for debarment under 48 CFR Part 9, Subpart 9.4, suspended, debarred, ineligible, or voluntarily excluded from participation in this transaction, in addition to other remedies available to the federal government, the department or agency with which this transaction originated may pursue available remedies, including suspension or debarment.

11. Drug-Free Workplace Certification. As required by Executive Order No. 90-5, April 12, 1990, issued by the Governor of Indiana, the Subgrantee hereby covenants and agrees to make a good faith effort to provide and maintain a drug-free workplace. Subgrantee will give written notice to the State within ten (10) days after receiving actual notice that the Subgrantee, or an employee of the Subgrantee in the State of Indiana, has been convicted of a criminal drug violation occurring in the workplace. False certification or violation of the certification may result in sanctions including, but not limited to, suspension of grant payments, termination of the Grant and/or debarment of grant opportunities with the State of Indiana for up to three (3) years.

In addition to the provisions of the above sections, if the total amount set forth in this Grant Agreement is in excess of \$25,000.00, the Subgrantee certifies and agrees that it will provide a drug-free workplace by:

- A. Publishing and providing to all of its employees a statement notifying them that the unlawful manufacture, distribution, dispensing, possession or use of a controlled substance is prohibited in the Subgrantee's workplace and specifying the actions that will be taken against employees for violations of such prohibition; and
- B. Establishing a drug-free awareness program to inform its employees of: (1) the dangers of drug abuse in the workplace; (2) the Subgrantee's policy of maintaining a drug-free workplace; (3) any available drug counseling, rehabilitation, and employee assistance programs; and (4) the penalties that may be imposed upon an employee for drug abuse violations occurring in the workplace; and
- C. Notifying all employees in the statement required by subsection (A) above that as a condition of continued employment the employee will: (1) abide by the terms of the statement; and (2) notify the Subgrantee of any criminal drug statute conviction for a violation occurring in the workplace no later than five (5) days after such conviction; and
- D. Notifying in writing the State within ten (10) days after receiving notice from an employee under subdivision (C)(2) above, or otherwise receiving actual notice of such conviction; and
- E. Within thirty (30) days after receiving notice under subdivision (C)(2) above of a conviction, imposing the following sanctions or remedial measures on any employee who is convicted of drug abuse violations occurring in the workplace: (1) take appropriate personnel action against the employee, up to and including termination; or (2) require such employee to satisfactorily participate in a drug abuse assistance or rehabilitation program approved for such purposes by a federal, state or local health, law enforcement, or other appropriate agency; and
- F. Making a good faith effort to maintain a drug-free workplace through the implementation of subsections (A) through (E) above.

12. Employment Eligibility Verification.

As a condition precedent to entering this Grant Agreement, and as required by IC § 22-5-1.7 and Executive Order 25-29, the Subgrantee swears or affirms under the penalties of perjury that the

Subgrantee has not knowingly employed, and will not knowingly employ, an unauthorized alien. Subgrantee further affirms that:

A. The Subgrantee has enrolled in, and verified the work eligibility status of all his/her/its employees through, the E-Verify program as defined in IC § 22-5-1.7-3. The Subgrantee is not required to participate should the E-Verify program cease to exist. Additionally, the Subgrantee is not required to participate if the Subgrantee is self-employed and does not employ any employees.

B. The Subgrantee has not knowingly employed or contracted with, and shall not knowingly employ or contract with, an unauthorized alien. The Subgrantee has not retained, and shall not retain, an employee, and has not contracted and shall not contract with a person, that the Subgrantee subsequently learned or learns is an unauthorized alien.

C. The Subgrantee has required and shall require his/her/its subcontractors, who perform work under this Grant Agreement, to certify to the Subgrantee that the subcontractor does not knowingly employ or contract with an unauthorized alien and that the subcontractor has enrolled and is participating in the E-Verify program. The Subgrantee agrees to maintain this certification throughout the duration of the term of a contract with a subcontractor and to provide any and all such certifications to the State promptly upon request.

The State may terminate this grant agreement for default if the Subgrantee fails to cure a breach of this provision no later than thirty (30) days after being notified by the State.

13. Funding Cancellation.

A. As required by Financial Management Circular 3.3 and IC § 5-22-17-5, when the Director of the State Budget Agency makes a written determination that funds are not appropriated or otherwise available to support continuation of performance of this Grant Agreement, it shall be canceled. A determination by the Director of the State Budget Agency that funds are not appropriated or otherwise available to support continuation of performance shall be final and conclusive.

B. If the Grant Agreement is cancelled under this Section, (1) the Subgrantee shall remain responsible for compliance with the requirements in 2 CFR 200.344 (Closeout) and 2 CFR 200.345 (Post-Closeout Adjustments and Continuing Responsibilities), and (2) the Subgrantee shall be entitled to retain ownership of the Project assets, subject to the conditions in 2 CFR 200.311, 200.313, and 200.314.

14. Governing Law. This Grant Agreement shall be governed, construed, and enforced in accordance with the laws of the State of Indiana, without regard to its conflict of laws rules. Suit, if any, must be brought in the State of Indiana or, if applicable, in the venue specified in 47 USC §1702(n).

15. Information Technology Accessibility Standards. Any information technology related products or services purchased, used or maintained through this Grant must be compatible with the principles and goals contained in the Electronic and Information Technology Accessibility Standards adopted by the Architectural and Transportation Barriers Compliance Board under Section 508 of the federal Rehabilitation Act of 1973 (29 U.S.C. §794d), as amended.

16. Insurance. The Subgrantee shall maintain insurance with coverages and in such amount as required by the State in **Paragraph 11** of each **Exhibit** to this Grant Agreement.

17. Nondiscrimination. Pursuant to the Indiana Civil Rights Law, specifically IC § 22-9-1-10, and in keeping with the purposes of the federal Civil Rights Act of 1964, the Age Discrimination in Employment Act, and the Americans with Disabilities Act:

A. The Subgrantee covenants that it shall not discriminate against any employee or applicant for employment relating to this Grant Agreement with respect to the hire, tenure, terms, conditions or privileges of employment or any matter directly or indirectly related to employment, because of the employee's or applicant's race, color, national origin, religion, sex, age, disability, ancestry, status as a veteran, or any other characteristic protected by federal, state, or local law ("Protected Characteristics"). The Subgrantee certifies compliance with applicable federal laws, regulations, and executive orders prohibiting discrimination based on the Protected Characteristics in the provision of services. Breach of this subsection may be regarded as a material breach of this Grant Agreement, including for purposes of Indiana Code § 5-11-5.5-2, but nothing in this section shall be construed to imply or establish an employment relationship between the State and any applicant, subcontractor or employee of the Subgrantee.

B. Subgrantee covenants that it does not and shall not operate any programs or engage in any practices promoting Diversity, Equity, and Inclusion (DEI), or other similar goals, that violate Indiana or Federal Civil Rights Laws by treating a person differently on the basis of race or sex, such as by considering race or sex when making recruitment, hiring, disciplinary, promotion, or employment decisions; requiring employees to participate in training or educational programs that employ racial or sex stereotypes; or attempting to achieve racial or sex balancing in the Subgrantee's workforce. The Parties agree that a breach of this subsection is a material breach of this Contract, including for purposes of Indiana Code § 5-11-5.5-2, but nothing in this section shall be construed to imply or establish an employment relationship between the State and any applicant, subcontractor or employee of the Subgrantee.

18. Notice to Parties. Whenever any notice, statement or other communication is required under this Grant, it will be sent by E-mail or first class U.S. mail service to the following addresses, unless otherwise specifically advised.

A. Notices to the State shall be sent to:

Megan Minor, Chief Broadband Officer
Indiana Broadband Office, IGC-South
302 W. Washington Street, Suite E-203
Indianapolis, IN 46204
E-mail: MeMinor@iot.in.gov

B. Notices to the Subgrantee shall be sent to:

NineStar Connect
Attn: Brad Rennier and George Plisinski
2243 East Main Street
Greenfield, IN 46140
E-mails: brennier@ninstarconnect.com and gplisinski@ninstarconnect.com

As required by IC § 4-13-2-14.8, payments to the Subgrantee shall be made via electronic funds transfer in accordance with instructions filed by the Subgrantee with the Indiana State Comptroller.

19. Order of Precedence; Incorporation by Reference. Any inconsistency or ambiguity in this Grant Agreement shall be resolved by giving precedence in the following order:

- (1) requirements imposed by the [Infrastructure Investment and Jobs Act of 2021, Division F, Title I, Section 60101](#) ("IIJA" - codified at 47 USC § 1702 *et seq.*)⁴ and applicable federal or state law, including those identified in this Section 24, below,
- (2) the [Specific Award Conditions \("SAC"\) incorporated into the State's BEAD Award](#)⁵ ("BEAD Award"),

⁴ At [https://uscode.house.gov/view.xhtml?req=\(title:47%20section:1702%20edition:prelim\)](https://uscode.house.gov/view.xhtml?req=(title:47%20section:1702%20edition:prelim))

- (3) the [General Terms and Conditions for the BEAD Program](#)⁶,
- (4) the [BEAD Restructuring Policy Notice](#) of June 2025 ("RPN")⁷,
- (5) the [BEAD NOFO](#)⁸,
- (6) the [Department of Commerce Standard Terms and Conditions](#) (dated September 22, 2025)⁹ ("DOC ST&C"),
- (7) the [Uniform Guidance Policy Notice](#)¹⁰,
- (8) the Uniform Guidance for Federal Awards - [2 CFR Part 200](#)¹¹,
- (9) all policies set forth in all applicable [Federal Executive Orders](#)¹² currently in legal force and effect, including those issued on or after January 20, 2025, as well as Federal Executive Orders that may be issued after the effective date of this Grant Agreement,
- (10) all other [NTIA BEAD Policy Notices](#)¹³,
- (11) all other [NTIA Guidance and Resources](#)¹⁴ in the BEAD Technical Assistance Hub,
- (12) the latest version of [NTIA's BEAD FAQs](#)¹⁵,
- (13) this Grant Agreement,
- (14) Exhibits, Attachments and Appendixes, attached to this Grant Agreement,
- (15) Indiana's Approved Initial Proposal (Volumes 1 and 2) and Final Proposal, and
- (16) the Grant Application.

All of the foregoing are incorporated fully herein by reference.

20. Public Record. The Subgrantee acknowledges that the State will not treat this Grant Agreement as containing confidential information, and the State will post this Grant Agreement on the transparency portal as required by Executive Order 05-07 and IC § 5-14-3.5-2. Use by the public of the information contained in this Grant Agreement shall not be considered an act of the State.

21. Termination for Cause; Remedies for Breach. Upon the Subgrantee's material breach of this Grant Agreement, the State shall provide written notice to the Subgrantee providing thirty (30) days to cure the breach or commence a cure for the breach if such breach cannot be cured within thirty (30) days. If the breach is not cured within that time period but Subgrantee has made progress towards curing the material breach, then the cure period shall be extended to a date to which the Parties mutually agree. If the breach is not cured within the extended cure period, then the State may impose conditions, including but not limited to additional reporting, more frequent performance testing and withholding of a portion of the payments. Thereafter, if the Subgrantee has not cured the material breach by the extended cure date and the conditions have not cured the breach within the time period established by the Parties, the State may terminate this Grant Agreement in whole or in part.

A. Failure to complete the Project and expend Federal, local and/or private funds in accordance with this Grant Agreement may be considered a material breach, and shall entitle the State to suspend grant payments, and to suspend the Subgrantee's participation in State grant programs until such time as all material breaches are cured to the State's satisfaction.

⁵ At <https://www.in.gov/indianabroadband/files/IBO-BEAD-Specific-Award-Conditions-SAC.pdf>

⁶ At https://broadbandusa.ntia.gov/sites/default/files/2026-02/BEAD_GTCs_Nov_18_2025.pdf

⁷ At <https://www.ntia.gov/sites/default/files/2025-06/bead-restructuring-policy-notice.pdf>

⁸ At <https://broadbandusa.ntia.gov/sites/default/files/2022-05/BEAD%20NOFO.pdf>

⁹ At <https://www.commerce.gov/sites/default/files/2025-09/DOC%20Financial%20Assistance%20General%20Terms%20and%20Conditions%20as%20of%2022%20September%202025%20vF.pdf>

¹⁰ At https://broadbandusa.ntia.gov/sites/default/files/2023-12/BEAD_Policy_Notice_of_Uniform_Guidance_Part_200_Exceptions_Related_Issues.pdf

¹¹ At <https://www.ecfr.gov/current/title-2/subtitle-A/chapter-II/part-200?toc=1>

¹² At <https://www.federalregister.gov/presidential-documents/executive-orders>

¹³ At <https://broadbandusa.ntia.gov/waivers-policies>

¹⁴ At <https://broadbandusa.ntia.gov/technical-assistance-hub>

¹⁵ At https://broadbandusa.ntia.gov/technical-assistance/BEAD_FAQs

B. The expenditure of federal funds other than in conformance with the Project or the Budget may be deemed a material breach. The Subgrantee explicitly covenants that it shall promptly repay to the State all funds not spent in conformance with this Grant Agreement.

C. Remedies. Remedies for material breach will be handled consistent with the authorities set forth in this Section 19 and 2 CFR 200.339. When a determination or decision regarding remedies for material breach is to be made, the State shall make such determination by exercising good faith and reasonable discretion.

(1) General Authority. The State may enforce applicable rules, laws and the terms and conditions of this Grant Agreement by imposing penalties for breach, failure to meet statutory obligations, or wasteful, fraudulent, or abusive expenditure of grant funds.

(2) The State may impose additional award conditions, as described in 2 CFR 200.208, on the Subgrantee as a remedy pursuant to this Section 21. If such additional award conditions are imposed and the Subgrantee fails to cure its breach, then the State may take one or more of the following actions:

(a) Temporarily withhold payments until the Subgrantee takes corrective action.

(b) Disallow costs for all or part of the activity associated with the Subgrantee's noncompliance.

(c) Suspend or terminate the Grant Agreement in part or in its entirety.

(d) Recommend suspension or debarment proceedings be initiated by the Department of Commerce.

(e) Withhold further Award Funds for the Project.

(f) Pursue other legally available remedies.

(3) Clawback. Full or partial forfeiture or recoupment of funds previously disbursed may be sought for cause where the Subgrantee has:

(a) Failed to take corrective action or timely cure any material breach after being duly notified by the State,

(b) Failed to comply with the BEAD Program's specifications¹⁶ set forth herein,

(c) Failed to deploy network infrastructure in accordance with the terms of this Grant Agreement and within the mandated deadlines,

(d) Failed to use grant funds for the agreed upon purpose,

(e) Used grant funds on the prohibited costs listed in Section 6.G(2) of this Grant Agreement or

(f) Demonstrated misfeasance or malfeasance in the use of such funds.

(4) Termination. In the event of breach or Noncompliance¹⁷, the Grant Agreement may be terminated in part or its entirety by the State if the Subgrantee fails to comply with the terms and conditions of the BEAD Award.

(5) NTIA¹⁸ Right to Pursue Clawback. The Parties acknowledge that NTIA may pursue claw back of funds directly from the State if the State fails to ensure Subgrantee accountability to the fullest extent of the law. To the extent NTIA successfully pursues the remedy of a claw back from the State on these grounds, the Subgrantee shall reimburse the State in an amount equal to the claw back.

D. If the Grant Agreement is terminated in part or its entirety under this Section, the Subgrantee shall remain responsible for compliance with the requirements in 2 CFR 200.344 (Closeout) and 2 CFR 200.345 (Post-Closeout Adjustments and Continuing Responsibilities).

¹⁶ In addition to the BEAD Program's specifications listed in this Master BEAD Subgrant Agreement, see Attachments A & C, all Exhibits to this Grant Agreement, and the Federal BEAD Requirements listed in Paragraph 1 of Attachment A.

¹⁷ Per 2 CFR 200.339, noncompliance means a failure to comply with the U.S. Constitution, Federal statutes, regulations, or terms and conditions of the BEAD Award.

¹⁸ The National Telecommunications and Information Administration, U.S. Department of Commerce.

22. Termination for Convenience.

A. By the State. Unless prohibited by a statute or regulation relating to the award of the Grant, this Grant Agreement may be terminated, in whole or in part, by the State whenever, for any reason, the State determines that such termination is in the best interest of the State or the Subaward no longer effectuates the BEAD program goals or Federal agency priorities.

B. Reimbursement.

(1) In the event of termination under this Section 22, the Subgrantee shall be reimbursed for completion of milestone events prior to the effective date of termination.

(2) In the event of termination under this Section 22 by the State under federal action to cancel/terminate the BEAD Program, the Subgrantee shall be reimbursed for completion of milestone events prior to the effective date of termination only if federal funds are made available by the U.S. Department of Commerce for disbursement to the Subgrantee.

(3) The State will not be liable for work on the Project performed after the effective date of termination. In no case shall total payment made to the Subgrantee exceed the original subgrant amount.

C. Termination Notice. The State shall provide written notice of termination to the Subgrantee specifying the effective date, the portion of the federal award to be terminated and the reasons for termination.

D. If the Grant Agreement is terminated in part or its entirety under this Section, the Subgrantee shall remain responsible for compliance with the requirements in 2 CFR 200.344 (Closeout) and 2 CFR 200.345 (Post-Closeout Adjustments and Continuing Responsibilities).

23. Omitted.

24. Federal and State Third-Party Contract Provisions. Since this Grant involves the payment of federal funds, the Subgrantee and, if applicable, its contractors shall comply with the federal provisions attached as **Attachment A** and incorporated fully herein. If the Subgrantee fails to comply with any requirement under Section 60102 of the Infrastructure Act, Attachment A, or the BEAD NOFO, it shall be required to return up to the entire amount of the subgrant to the State, at the discretion of the State or the Assistant Secretary of Commerce for Communications and Information ("Assistant Secretary").

25. Omitted.

26. Definitions. The definitions in the IJJA, BEAD NOFO and 2 CFR Part 200 shall apply to capitalized terms not otherwise defined herein.

27. Indemnification. The Subgrantee agrees to indemnify, defend, and hold harmless the State, its agents, officials, and employees from all third party claims and suits including court costs, attorney's fees, and other expenses caused by any act or omission of the Subgrantee and/or its contractors and subcontractors, if any, in the performance of this Grant Agreement. The State will not provide indemnification to the Subgrantee.

28. Dispute Resolution.

A. Should any disputes arise with respect to this Grant Agreement, the Subgrantee and the State agree to act immediately to resolve such disputes.

B. The Subgrantee agrees that, the existence of a dispute notwithstanding, it will continue without delay to carry out all of its responsibilities under this Grant Agreement that are not affected by the dispute. A dispute involving payment does not preclude performance.

C. Informal Dispute Resolution. The Parties to this Agreement agree that time is of the essence in the resolution of disputes, therefore any and all disputes in relation to the Agreement will

initially be referred to the parties' respective Project Managers, designated in **Paragraph 10** of the relevant Subaward attached as an **Exhibit** to the Agreement, for immediate resolution. Such referral must include a description of the issues and all supporting documentation. The parties must submit the dispute to a senior executive if unable to resolve the dispute within fifteen (15) business days.

D. If the parties are unable to resolve a dispute pertaining to this Agreement after good faith attempts to do so, a dissatisfied party shall submit the dispute to the Commissioner of the Indiana Department of Administration for resolution. The dissatisfied party shall give written notice to the Commissioner and the other party. The notice shall include: (1) a description of the disputed issues, (2) the efforts made to resolve the dispute, and (3) a proposed resolution. The Commissioner shall promptly issue a Notice setting out documents and materials to be submitted to the Commissioner in order to resolve the dispute; the Notice may also afford the parties the opportunity to make presentations and enter into further negotiations. Within thirty (30) business days of the conclusion of the final presentations, the Commissioner shall issue a written decision and furnish it to both parties. The Commissioner's decision shall be the final and conclusive administrative decision unless either party serves on the Commissioner and the other party, within ten (10) business days after receipt of the Commissioner's decision, a written request for reconsideration and modification of the written decision. If the Commissioner does not modify the written decision within thirty (30) business days, either party may take such other action helpful to resolving the dispute, including submitting the dispute to the court with exclusive jurisdiction when challenging a decision made by the Assistant Secretary per 47 USCA §1702(n), or to an Indiana court of competent jurisdiction for all other claims. If the parties accept the Commissioner's decision, it may be memorialized as a written Amendment to this Agreement if appropriate.

E. With the written approval of the Commissioner of the Indiana Department of Administration, the parties may agree to forego the process described in this Subsection 28.D relating to submission of the dispute to the Commissioner.

F. This paragraph shall not be construed to abrogate provisions of IC § 4-6-2-11 in situations where dispute resolution efforts lead to a compromise of claims in favor of the State as described in that statute. In particular, releases or settlement agreements involving releases of legal claims or potential legal claims of the state should be processed consistent with IC § 4-6-2-11, which requires approval of the Governor and Attorney General.

29. Ensuring Timely and Effective Deployment of BEAD Projects. The Grantee, and any agency, instrumentality, or subdivision thereof, agrees not to enforce any law, regulation, executive order, contracting requirement, or other enforceable obligation that directly or indirectly regulates in any way the rates, terms, and conditions of broadband internet service, whether on a retail, wholesale, or network basis, or imposes net neutrality rules, open access, or other utility-style rules on broadband internet service, against the Subgrantee or its affiliates anywhere it provides service within the Grantee's jurisdiction, while that Subgrantee has any subgrant that is still within its period of performance, extended period of performance, or federal interest period. For purposes of this provision, a "net neutrality rule" is any law, order, contracting requirement, or other enforceable obligation by the Grantee that prohibits internet service providers from, among other things, blocking content, throttling speeds, imposing data caps, or engaging in paid prioritization, or that imposes a general conduct or similar standard upon internet service providers.

30. State Boilerplate Affirmation Clause. I swear or affirm under the penalties of perjury that I have not altered, modified, changed or deleted the State's standard contract clauses (as contained in the *most current State of Indiana SCM Template*) in any way except as follows:

Paragraphs 1, 4, 5-6, 8-10, 14, 16, 21, and 23-29— Addition of BEAD Program specific language and deletion of language/provisions that are inapplicable to the BEAD Program.

Non-Collusion, Acceptance

The undersigned attests, subject to the penalties for perjury, that the undersigned is the Subgrantee, or that the undersigned is the properly authorized representative, agent, member or officer of the Subgrantee. Further, to the undersigned's knowledge, neither the undersigned nor any other member, employee, representative, agent or officer of the Subgrantee, directly or indirectly, has entered into or been offered any sum of money or other consideration for the execution of this Grant Agreement other than that which appears upon the face hereof. **Furthermore, if the undersigned has knowledge that a state officer, employee, or special state appointee, as those terms are defined in IC § 4-2-6-1, has a financial interest in the Grant, the Subgrantee attests to compliance with the disclosure requirements in IC § 4-2-6-10.5.**

Agreement to Use Electronic Signatures

I agree, and it is my intent, to sign this Grant Agreement by accessing State of Indiana Supplier Portal using the secure password assigned to me and by electronically submitting this Grant Agreement to the State of Indiana. I understand that my signing and submitting this Grant Agreement in this fashion is the legal equivalent of having placed my handwritten signature on the submitted Grant Agreement and this affirmation. I understand and agree that by electronically signing and submitting this Grant Agreement in this fashion I am affirming to the truth of the information contained therein. I understand that this Grant Agreement will not become binding on the State until it has been approved by the Department of Administration, the State Budget Agency, and the Office of the Attorney General, which approvals will be posted on the Active Contracts Database: <https://secure.in.gov/apps/idoa/contractsearch/>

In Witness Whereof, the Subgrantee and the State have, through their duly authorized representatives, entered into this Grant Agreement. The parties, having read and understood the foregoing terms of this Grant Agreement, do by their respective signatures dated below agree to the terms thereof.

Central Indiana Communications, Inc.

Signed By:
By: *Brad Rennie*
3A067A56D1D240F...

Title: Chief Financial Officer

Date: 7/1/2026 | 12:15 PDT

Indiana Broadband Office

Signed By:
By: *Megan Bailey*
5A3FF1452AC6469...

Title: Chief Broadband Officer

Date: 7/1/2026 | 13:15 PDT

Electronically Approved by: Indiana Office of Technology By: _____ (for) Warren Lenard, Executive Director	Electronically Approved by: Department of Administration By: _____ (for) Brandon Clifton, Commissioner
Electronically Approved by: State Budget Agency By: _____ (for) Chad Ranney, State Budget Director	Electronically Approved as to Form and Legality: Office of the Attorney General By: _____ (for) Theodore E. Rokita, Attorney General

ATTACHMENT A – GENERAL TERMS AND CONDITIONS FOR THE BEAD PROGRAM

1. Award Compliance Requirements, Prioritization and Terminology

Subgrantees must comply with all applicable requirements contained in [47 U.S.C. § 1702](#)¹, the [BEAD NOFO](#)², [2 CFR Part 200](#)³, the [Department of Commerce Standard Terms and Conditions](#) (dated September 22, 2025)⁴, the [General Terms and Conditions for the BEAD Program](#)⁵, and the [Specific Award Conditions incorporated into the IBO's BEAD award](#)⁶. In any case where language among two or more authorities appears inconsistent, the relevant authorities should be read and interpreted in a manner which emphasizes consistency and harmonization across all relevant authorities. Where harmonization is impossible, any inconsistency or ambiguity shall be resolved by giving precedence to the authorities listed Section 19 of the Master BEAD Subgrant Agreement (collectively “Federal BEAD Requirements”).

The definitions in the BEAD NOFO and 2 CFR Part 200 shall apply to capitalized terms not otherwise defined herein. Additionally, as used herein, the terms “Grantee” and “Subgrantee” refer to the recipient or subrecipient of a grant as appropriate and as aligned with the updated Uniform Guidance (dated October 1, 2024) and the BEAD NOFO. The Subgrantee assumes ultimate responsibility for compliance with the requirements of this award.

2. Subgrantee and Contractor Compliance with Applicable Requirements

With the exception of IC 5 -22, the Subgrantee shall comply, and must require its contractors, including lower tier subcontractors, to comply with all applicable Federal, state, and local laws and regulations, and all applicable terms and conditions of this Grant Agreement. The Subgrantee is responsible for ensuring that all contracts, including those necessary for design and construction of facilities, are implemented in compliance with the Terms and Conditions of this Award.

¹ At [https://uscode.house.gov/view.xhtml?req=\(title:47%20section:1702%20edition:prelim\)](https://uscode.house.gov/view.xhtml?req=(title:47%20section:1702%20edition:prelim))

² At <https://broadbandusa.ntia.gov/sites/default/files/2022-05/BEAD%20NOFO.pdf>

³ At <https://www.ecfr.gov/current/title-2/subtitle-A/chapter-II/part-200?toc=1>

⁴ At <https://www.commerce.gov/sites/default/files/2025-09/DOC%20Financial%20Assistance%20General%20Terms%20and%20Conditions%20as%20of%2022%20September%202025%20vF.pdf>

⁵ At https://broadbandusa.ntia.gov/sites/default/files/2026-02/BEAD_GTCs_Nov_18_2025.pdf

⁶ At <https://www.in.gov/indianabroadband/files/IBO-BEAD-Specific-Award-Conditions-SAC.pdf>

3. Contracting with Small and Minority Businesses, Women’s Business Enterprises, and Labor Surplus Area Firms

The Subgrantee must take all necessary affirmative steps (as described in 2 CFR 200.321 and NOFO Section VII.D.7) to assure that minority businesses, women’s business enterprises, and labor surplus area firms are used when possible.

4. Prevention of Waste, Fraud, and Abuse

Consistent with the principles in 2 CFR part 200, at any time(s) during the grant period of performance, the IBO may direct a member or members of Subgrantee’s key personnel to take a Government-provided training on preventing waste, fraud and abuse. Key personnel include those responsible for managing the Grantee’s finances and overseeing any contractors, sub-contractors or Subgrantees (for financial matters and/or general oversight related to the grant).

The Subgrantee shall monitor award activities for common fraud schemes, including but not limited to:

- false claims for materials and labor;
- bribes related to the acquisition of materials and labor;
- product substitution;
- mismarking or mislabeling on products and materials; and
- time and materials overcharging.

The Subgrantee shall establish and widely publicize telephone numbers and email addresses for the State of Indiana’s Office of Inspector General or Subgrantee’s internal ethics office (or comparable entity) for the purpose of reporting waste, fraud or abuse in the Program. The Subgrantee shall produce copies of materials used for such purposed upon request of the Federal Program Officer.

Should a Subgrantee detect any fraud schemes or any other suspicious activity, the Subgrantee must contact the IBO’s Grant Manager and the IBO Fraud Hotline at: BEADGrantMgt@iot.in.gov and IBOFraudHotline@iot.in.gov. Additionally, in accordance with 2 CFR 200.113, an applicant or Subgrantee must disclose, in a timely manner, in writing to the Federal awarding agency or pass-through entity all violations of Federal criminal law involving fraud, bribery, or gratuity violations found in Title 18 of the United States Code or a violation of the civil False Claims Act (31 USC 3729-3733) potentially affecting the Federal award. Subgrantees are required to report certain civil, criminal, or administrative proceedings to SAM.gov. Failure to make required disclosures can result in any of the remedies described in 2 CFR 200.339. (See also 2 CFR Part 180, 31 USC 3321, and 41 USC 2313.)

5. Protection of Whistleblowers

The Department of Commerce Financial Assistance Standard Terms and Conditions are incorporated into this Grant Agreement. Section F.05 of these Terms and Conditions states that each award is subject to the whistleblower protections afforded by 41 USC 4712 (Enhancement of contractor protection from reprisal for disclosure of certain information).

Generally, this law provides that an employee or contractor (including subcontractor and personal services contractors) of a Grantee, Subgrantee, contractor, subcontractor or personal services contractor may not be discharged, demoted, or otherwise discriminated against as a reprisal for disclosing to a person or body information that the employee reasonably believes is evidence of gross mismanagement of a Federal Award, subgrant, or a contract under a Federal Award or subgrant, a gross waste of Federal funds, an abuse of authority relating to a Federal Award or subgrant or contract under a Federal Award or subgrant, a substantial and specific danger to public health or safety, or a violation of law, rule, or regulation related to a Federal Award, subgrant, or contract under a Federal Award or subgrant.

Subgrantee shall inform their employees and contractors in writing of the rights and remedies provided under 41 USC 4712, in the predominant native language of the workforce.

A person that believes they have been the subject of retaliation for protected whistleblowing can contact the Department of Commerce, Office of Inspector General Hotline, as indicated at <https://www.oig.doc.gov/Pages/Hotline.aspx>, or the U.S. Office of Special Counsel, toll free at 1- 800- 872-9855.

6. Inspection and Testing of Materials

The Subgrantee, as applicable, shall ensure that all materials and equipment used in the completion of the work shall be subject to adequate inspection and testing in accordance with accepted standards. Materials of construction, particularly those upon which the strength and durability of any structure may depend, shall be subject to inspection and testing to establish conformance with specifications and suitability for intended uses. The Subgrantee shall ensure that documentation of same is cataloged and retained.

7. Requirements During Construction

During construction, the Subgrantee, as applicable, is responsible for:

- Ensuring that it meets all deadlines in approved plans and specifications;
- Monitoring the progress of grant funded activities;

- Reporting progress;
- Providing for required construction permits and adequate construction inspection;
- Promptly paying costs incurred for grant funded activities;
- Monitoring Subgrantees' compliance with Federal, State, and local requirements; and
- Constructing and maintaining in good condition throughout the construction period a sign or signs, at the site of grant funded activities in a conspicuous place indicating that the Federal Government is participating in the activities.

8. Environmental and Historic Preservation (EHP) Review

The Subgrantee must comply with the requirements of all applicable Federal, State, and local environmental laws, regulations, and standards.

A. EHP Pre-Implementation and Funding Conditions

The Subgrantee must not initiate any grant funded implementation activities—except for the limited permissible activities identified in this Paragraph 8.E below—prior to the following:

1. The completion of any review required under the National Environmental Policy Act of 1969 (42U.S.C. 4321, *et seq.*) (NEPA), and issuance by NTIA and the IBO, as required, of a Categorical Exclusion (Cat Ex) determination, Record of Environmental Consideration (REC), Finding of No Significant Impact (FONSI), or Record of Decision (ROD) (hereinafter “decision documents”) that meets the requirements of NEPA;
2. The completion of reviews required under Section 106 of the National Historic Preservation Act of 1966 (54 U.S.C. 300101, *et seq.*) (NHPA), including any consultations required by Federal law, to include consultations with the State Historic Preservation Office (SHPO), and Federally recognized Native American tribes;
3. The completion of consultations with the U.S. Fish and Wildlife Service (USFWS) or the National Marine Fisheries Service (NMFS), as applicable, under Section 7 of the Endangered Species Act (16 U.S.C. 1531, *et seq.*), and/or consultations with the U.S. Army Corps of Engineers (USACE) under Section 404 of the Clean Water Act (33 U.S.C. 1251, *et seq.*), as applicable; and
4. Demonstration of compliance with all other applicable Federal, State, and local environmental laws and regulations.

B. Subgrantee Compliance with NEPA

NEPA Compliance: To ensure the timely completion of environmental review for all BEAD-funded activities subject to NEPA review, the Subgrantee must:

- not commence implementation and funds will not be disbursed until any necessary environmental review is complete and NTIA has approved any necessary decision document, except for the limited permissible activities identified in this Paragraph 8.E below;
- timely prepare any required NEPA documents and obtain any required permits, and must adhere to any applicable statutory deadlines as described in 42 U.S.C. 4336a(g); and
- provide a milestone schedule identifying specific deadlines and describing how the Subgrantee proposes to meet these timing requirements including, as required, the completion of consultations, the completion of NEPA and Section 106 reviews, and the submission of Environmental Assessments (EAs) or Environmental Impact Statements (EISs).

C. Subgrantee Compliance with NHPA Section 106

NHPA Compliance: To ensure the timely completion of historic preservation review for all BEAD-funded activities, the Subgrantee must adhere to the provisions of the NTIA memorandum to SHPOs, Tribal Historic Preservation Officers (THPOs), and Internet for All (IFA) grant recipients authorizing IFA grant recipients to initiate Section 106 consultation for NTIA funded projects.

D. Grantee Permitting Obligations

To help ensure that Grantee's BEAD projects are carried out in a timely and effective manner, the IBO shall take the following actions, to the extent permissible by law, to streamline permitting processes:

1. Consistent with any relevant legal requirements and authorities, the IBO will establish procedures to ensure that broadband-related permit applications are promptly accepted, and requests are approved or denied within 90 days, including by:
 - a. Assisting state and local authorities in establishing a single, dedicated point of contact, which has knowledge of the application and review processes, for broadband-related permits.
 - b. Providing technical assistance to permitting agencies to ensure sufficient capacity (e.g., Master Agreement and Consultant Reimbursement Agreement templates, surge support for permit processing, etc.)

- c. Providing deference to the construction techniques chosen by BEAD Subgrantees (without seeking to influence those decisions), absent any identified safety concerns.
 - d. Maximizing streamlined processing through permitting by rule; batch processing of substantially similar permit requests; and waiving or expediting duplicative or burdensome broadband permitting requirements where possible.
 - e. Following FCC rules regarding timelines, rates, terms, and conditions for access to municipally owned poles and conduit for broadband projects—including provisions in the FCC’s rules providing for “one-touch make-ready” and “self-help”—and requiring BEAD Subgrantees that own poles (including cooperatives) to comply with FCC rules across their footprint.
2. IBO will seek to minimize state and local permitting-related costs for broadband deployments and ensure (1) permitting fees are a reasonable approximation of the state or local government’s costs, (2) only objectively reasonable costs are factored into those fees, and (3) the fees are no higher than the fees charged to similarly situated competitors in similar situations.
3. IBO will establish Permitting Roundtables⁶ and/or working groups of relevant federal, state, local, and tribal authorities and representatives of impacted industries—including utility pole owners, railroads, communications providers, and BEAD subgrantees—that will:
 - a. Meet regularly to identify and facilitate resolution of any delays or disputes related to deploying BEAD-funded facilities.
 - b. Collect complaints (and supporting information) from Subgrantees that are not timely resolved through this process and escalate such complaints through the appropriate Permitting Roundtable or working group.
4. IBO will track, publicly post, and submit to NTIA, as part of its Semi-Annual Report, information on subgrantee compliance with the NEPA milestone schedules⁷ and data regarding unresolved complaints from Subgrantees, including: (1) issues escalated through the Permitting Roundtable or working group; (2) delays in broadband-related projects that Subgrantees attribute to a state or local prohibition on using its preferred construction techniques; and (3) delays in broadband related projects that Subgrantees attribute to state and/or local authorities failing to follow FCC rules regarding pole attachment timelines, rates, terms, and conditions for

access to municipally owned poles and conduit for broadband projects.⁷

E. Limited Permissible Pre-Implementation Activities

The Subgrantee must ensure that implementation (site preparation, demolition, construction, ground disturbance, fixed installation, or any other implementation activities) does not begin prior to the completion of all EHP requirements as outlined in this Paragraph. The Subgrantee must comply with all conditions placed on the grant funded activities as the result of NEPA or NHPA consultation or processes under other applicable laws— *e.g.*, mitigation requirements, best management practices, or other measures necessary to reduce environmental impacts—and ensure that Subcontractors comply with such conditions as well. The Subgrantee must also provide any information requested by NTIA or the IBO to ensure both initial and ongoing compliance with all requirements described above.

Only if approved by the IBO in writing, may the Subgrantee undertake limited permissible activities under NEPA using award funds prior to the completion of the EHP review process, including the following:

- Pre-construction planning, including collecting information necessary to complete environmental reviews;
- Applications for environmental permits;
- Administrative costs;
- Pre-award applications costs;
- Studies including, but not limited to, Environmental Assessments (EA), wetland delineations, biological assessments, archaeological surveys, and other environmental reviews and analyses;
- Activities supporting consultations required under the NHPA, the Endangered Species Act, and the Clean Water Act; and/or
- Limited, preliminary procurement, including the purchase or lease of equipment, or entering into binding contracts to do so; the purchase of applicable or conditional insurance; and/or funds used to secure land or building leases (including right-of-way easements).

Subgrantees that undertake unauthorized project activities in contravention of this

⁷ Such reports will be shared with the FCC and Congress to determine whether additional funding rescission, enforcement, legislation to modify 47 U.S.C. § 224 to remove the exemption for poles and conduits owned by municipalities and electric cooperatives, and/or other actions are warranted.

Paragraph proceed at their own risk and may face de-obligation of funding.

The Subgrantee shall notify the IBO within 24 hours upon receipt of any Section 106 notices of foreclosure; notices requesting continuing or supplemental consultation received from the SHPO, THPO, or other consulting party or the USFWS or NMFS; or notices of noncompliance received from consulting authorities or regulatory agencies.

Any change to the approved scope of grant funded activities proposed after the completion of environmental and historic preservation review that has the potential for altering the nature or extent of environmental or historic preservation impacts must be brought to the attention of the IBO and will be re-evaluated for compliance with applicable requirements.

Archaeological Resources: Burial sites, human remains, and funerary objects are subject to the requirements of all applicable Federal, Tribal, State, and Local laws and protocols, such as the Native America Graves Protection and Repatriation Act (NAGPRA), in addition to Section 106 of the NHPA. Subgrantees must notify the IBO of inadvertent discoveries and potential impacts to these resources and identify and follow all applicable laws or protocols. If any potential archeological resources or buried human remains are discovered during construction, the Subgrantee must immediately stop work in that area, secure that area, and keep information about the discovery confidential, except to notify the IBO and the interested SHPO. Such construction activities may then only continue with the written approval of the IBO.

9. Scheduling Inspection for Final Acceptance

The Subgrantee shall provide notice of completion for each broadband infrastructure project and other construction activities when all construction has been completed, the professional engineer has conducted its own final inspection, and any deficiencies have been corrected. Scheduling of the final inspection will be coordinated by the IBO. Representatives of the IBO, the architect/engineer and Subgrantee must attend the final inspection for each project.

10. Domestic Preference for Procurements (Build America, Buy America)

Congress passed the Build America, Buy America Act (BABA) on November 15, 2021 as part of the Infrastructure Investment and Jobs Act, Pub. L. 117-58, 135 Stat. 429, 70901-70927. BABA established domestic content procurement preference requirements for Federal financial assistance projects for infrastructure, including the BEAD Program, consistent with Section 70912(2) of the Infrastructure Act. The Subgrantee shall comply

with BABA consistent with applicable legal authorities, such as the Infrastructure Act, Executive Order 14005, 2 CFR Part 184, OMB Memo M-24-02, and the requirements laid out in the final version of the BEAD BABA waiver. All waivers applicable to BEAD, an FAQ, and a BEAD BABA Self Certification list are posted on the Build America, Buy America page maintained by the Department of Commerce Office of Acquisition Management at <https://www.commerce.gov/oam/build-america-buy-america>.

11. Prohibition on Use for Covered Communications Equipment or Services

A Subgrantee or its contractors and subcontractors may not use Agreement Funds (including Matching Funds) to purchase or support any communications equipment or service covered by either the Secure and Trusted Communications Networks Act of 2019 (47 USC 1608) or 2 CFR 200.216 (Prohibition on certain telecommunications and video surveillance services or equipment). By executing this Agreement, subgrantee certifies it (along with its contractors or subcontractors) will not obligate or expend grant funds to: (1) procure or obtain covered telecommunications equipment or services; (2) extend or renew a contract to procure or obtain covered telecommunications equipment or services; or (3) enter into a contract (or extend or renew a contract) to procure or obtain covered telecommunications equipment or services.

12. Prohibition on the Supplantation of Funds

Consistent with 47 U.S.C. § 1702(l), Grant Funds awarded to the Subgrantee under this program shall be used to supplement, and not supplant, the amounts of Federal or non-Federal funds that the IBO would otherwise make available for the purposes for which the grant funds may be used. *See* NOFO V.H.2.

13. Equitable and Nondiscriminatory Use of Funds

The Subgrantee acknowledges and agrees to abide by 47 U.S.C. § 1702(g)(2)(C) to use grant funds in an equitable and nondiscriminatory manner. The Subgrantee's failure to do so may result in cancellation of any subgrant and/or recoupment of funds already disbursed.

14. Network Capabilities

Pursuant to 47 U.S.C. § 1702(g)(1)(A), Subgrantee shall ensure that every Funded Network meets the criteria related to speed and latency and network outages outlined in the NOFO. *See* NOFO IV.C.2.a. and in the [Performance Measures for BEAD Last Mile Networks Policy Notice](#)⁸ (an any future amendments).

⁸ At https://broadbandusa.ntia.gov/sites/default/files/2025-09/Performance_Measures_Policy_Notice.pdf

15. Deployment Deadlines and Benchmarks

Pursuant to 47 U.S.C. § 1702(h)(4)(C), the Subgrantee shall deploy its Funded Networks and begin providing broadband service to each customer that desires broadband service not later than four (4) years after the date on which the Subgrantee receives the subgrant for the applicable network.

16. Deployment and Provision of Service Requirements

Pursuant to 47 U.S.C. § 1702(h)(4)(D), any Funded Network deployment project that involves laying fiber-optic cables or conduit underground or along a roadway must include interspersed conduit access points at regular and short intervals. *See* NOFO IV.C.2.b.ii. Subgrantee shall include the required interspersed conduit access points at regular and short intervals when laying fiber-optic cables or conduit underground or along a roadway.

Consistent with 47 U.S.C. § 1702(h)(4)(E) and 47 U.S.C. § 1702(h)(4)(H), if Subgrantee has been awarded funds for construction of Middle Mile Infrastructure, then Subgrantee shall deploy broadband infrastructure in or through any area required to reach interconnection points or otherwise to ensure the technical feasibility and financial sustainability of a project providing broadband service to an unserved location, underserved location, or eligible community anchor institution. If the Subgrantee, at any time, is no longer able to provide broadband service to the end user locations covered by the subgrant at any time on a retail basis, then remedial action must be taken to ensure continuity of service.

17. Plans

Pursuant to 47 U.S.C. § 1702(h)(4)(B), Subgrantee agrees to offer at least one low-cost broadband service option for eligible subscribers. Eligible subscriber means any household seeking to subscribe to broadband internet service that is eligible for the FCC's Lifeline Program.⁹ To comply with the low-cost plan statutory requirement, Subgrantee must propose a Low-Cost Service Option in its applications for project areas. The low-cost service option must offer speeds of at least 100/20 Mbps and latency performance of no more than 100 milliseconds. The Subgrantee must continue to offer the low-cost broadband service option to eligible subscribers, during the Federal Interest Period or in the case of Low Earth Orbit ("LEO") Subgrantees, a ten-year period of performance. Pursuant to Section 1702(h)(5)(C), NTIA or the IBO may take corrective action, including recoupment of funds from the Subgrantee, for noncompliance with the statutory low-cost plan requirement.

⁹ Lifeline eligibility criteria are defined in 47 CFR §54.409.

18. Access to Service

Pursuant to 47 U.S.C. § 1702(g)(2)(C)(ii), operators of Funded Networks shall provide access to broadband service to each customer served by the project that desires broadband service on terms and conditions that are reasonable and non-discriminatory.

19. Public Notice & Public Awareness

Pursuant to 47 U.S.C. § 1702(h)(4)(F), once the network has been deployed, the Subgrantee shall provide public notice, online and through other means, of that fact to the locations and areas to which broadband service has been provided and share the public notice with the IBO.

Pursuant to 47 U.S.C. § 1702(h)(4)(G), the Subgrantee shall carry out public awareness campaigns in their service areas that are designed to highlight the value and benefits of broadband service in order to increase the adoption of broadband service by consumers.

20. Reserved.

21. Sale Upon Incapacity

Pursuant to 47 U.S.C. § 1702(h)(4)(H), in consultation with NTIA, if the Subgrantee is no longer able to provide broadband service to the locations covered by the subgrant at any time, the Subgrantee shall consult with the NTIA and shall sell the network capacity at a reasonable, wholesale rate on a nondiscriminatory basis to other broadband service providers or public sector entities.

22. Cybersecurity and Supply Chain Risk Management

Pursuant to 47 U.S.C. § 1702(g)(1)(B), a Subgrantee, in carrying out activities using amounts received from the IBO, shall comply with prudent cybersecurity and supply chain risk management practices, as specified by the Assistant Secretary, in consultation with the Director of the National Institute of Standards and Technology and the Federal Communications Commission. Subgrantee attests by entering into this Grant Agreement that:

- The Subgrantee has a cybersecurity risk management plan (the plan) in place that is either:
 - operational, if the prospective Subgrantee is providing service prior to the award of the grant; or
 - ready to be operationalized upon providing service, if the prospective Subgrantee is not yet providing service prior to the grant award;
- The plan reflects the latest version of the NIST Framework for Improving Critical

Infrastructure Cybersecurity (currently Version 1.1) and the standards and controls set forth in Executive Order 14028 and specifies the security and privacy controls being implemented;

- The plan will be reevaluated and updated on a periodic basis and as events warrant; and
- The plan will be submitted to the IBO prior to the allocation of funds. If the Subgrantee makes any substantive changes to the plan, a new version will be submitted to the IBO within 30 days. The IBO will provide the Subgrantee's plan to NTIA upon NTIA's request.

With respect to supply chain risk management (SCRM), Subgrantee further attests that:

- The Subgrantee has a SCRM plan in place that is either:
 - operational, if the Subgrantee is already providing service at the time of the grant; or
 - ready to be operationalized, if the Subgrantee is not yet providing service at the time of grant award;
- The plan is based upon the key practices discussed in the NIST publication NISTIR 8276, Key Practices in Cyber Supply Chain Risk Management: Observations from Industry and related SCRM guidance from NIST, including NIST 800-161, Cybersecurity Supply Chain Risk Management Practices for Systems and Organizations and specifies the supply chain risk management controls being implemented;
- The plan will be reevaluated and updated on a periodic basis and as events warrant; and
- The plan will be submitted to the IBO prior to the allocation of funds. If the Subgrantee makes any substantive changes to the plan, a new version will be submitted to the IBO within 30 days. The IBO will provide the Subgrantee's plan to NTIA upon NTIA's request.

The Subgrantee also must, to the extent the Subgrantee relies in whole or in part on network facilities owned or operated by a third party (e.g., purchases wholesale carriage on such facilities), obtain the above attestations from its network provider with respect to both cybersecurity and supply chain risk management practices. *See* NOFO IV.C.2.c.vi.

23. Prohibition on Profit and Fees

A profit, fee, or other incremental charge above actual cost incurred by a Subgrantee is not an allowable cost under this Program. *See* NOFO V.H.2.b.

24. Prohibition on Use of Grant Funds to Support or Oppose Collective Bargaining

A Subgrantee may not use Grant Funds, whether directly or indirectly, to support or oppose collective bargaining. *See* NOFO V.H.2.c.

25. Subgrantee Integrity and Performance Matters

In accordance with Section 872 of Public Law 110-417, as amended, *see* 41 USC 2313, if the total value of a Subgrantee's currently active grants, cooperative agreements, and procurement contracts from all Federal awarding agencies exceeds \$10,000,000 for any period of time during the period of performance of this Federal Award, then the Subgrantee shall be subject to the requirements specified in [Appendix XII to 2 CFR Part 200](#)¹⁰, for maintaining the currency of information reported to SAM that is made available in the Federal Awardee Performance and Integrity Information System (FAPIIS) about certain civil, criminal, or administrative proceedings involving the Subgrantee. *See* 2 CFR 200.113.

26. Audit Requirements

2 CFR Part 200, Subpart F, adopted by the Department of Commerce through 2 CFR 1327.101, requires any Non-Federal entity that expends Federal Awards of \$1,000,000 or more in the Subgrantee's fiscal year to conduct a single or program-specific audit in accordance with the requirements set out in the Subpart. Subrecipients that are not subject to Subpart F of 2 CFR Part 200 (e.g., commercial entities) that expend \$1,000,000 or more in grant funds during their fiscal year must submit to the IBO either: (i) a financial related audit of each Department of Commerce (DOC) award or subaward in accordance with Generally Accepted Government Auditing Standards; or (ii) a program-specific audit for each award or subaward in accordance with the requirements contained in 2 CFR 200.507. Subgrantees may batch their audit submission to the IBO when allowable and/or required by the IBO. Subgrantees are reminded that the IBO, NTIA, the Department of Commerce Office of Inspector General, or another authorized Federal or state agency may request audit documents or conduct an audit of an award at any time.

27. Federal Funding Accountability and Transparency Act of 2006 (Transparency Act)

- A. In accordance with 2 CFR Part 170, the Subgrantee shall report to the IBO their executive total compensation described in Paragraph 27.B., below.
- B. Reporting of total compensation of Subgrantee's executives. The Subgrantee shall provide to the IBO a report of its five most highly compensated executives for the

¹⁰ At <https://www.ecfr.gov/current/title-2/subtitle-A/chapter-II/part-200/appendix-Appendix%20XII%20to%20Part%20200>

Subgrantee's preceding completed fiscal year, if:

1. The total Federal BEAD funding authorized to date under the subaward equals or exceeds \$30,000;
2. In the Subgrantee's preceding fiscal year, the Subgrantee received:
 - a. 80 percent or more of its annual gross revenues from Federal procurement contracts (and subcontracts) and Federal Awards (and subawards) subject to the Transparency Act; and,
 - b. \$25,000,000 or more in annual gross revenues from Federal procurement contracts (and subcontracts), and Federal Awards (and subawards) subject to the Transparency Act; and
3. The public does not have access to information about the compensation of the executives through periodic reports filed under Section 13(a) or 15(d) of the Securities Exchange Act of 1934 (15 U.S.C. §§ 78m(a), 78o(d)) or Section 6104 of the Internal Revenue Code of 1986 after receiving this subaward. (To determine if the public has access to the compensation information, *see* the U.S. Security and Exchange Commission total compensation filings at <http://www.sec.gov/answers/execomp.htm>).

C. Definitions.

- *Executive* means an officer, managing partner, or any other employee holding a management position.
- *Subaward* has the meaning given in 2 CFR 200.1.
- *Total Compensation* means the cash and noncash dollar value an executive earns during an entity's preceding fiscal year. This includes all items of compensation as prescribed in 17 CFR 229.402(c)(2).

D. The Subgrantee shall furnish their executive total compensation described in this Paragraph 27.B to the IBO before the commencement of this Grant Agreement.

28. Protected and Proprietary Information

The Subgrantee is expected to support Program reviews and evaluations by submitting required financial and performance information and data in an accurate and timely manner, and by cooperation with the Department of Commerce and external program evaluators. In accordance with 2 CFR 200.303(e), Subgrantees must take reasonable measures to safeguard protected personally identifiable information and other confidential or sensitive personal or business information created or obtained in connection with a Department of Commerce financial assistance award. *See also* NOFO IX.B.

29. Subgrantee Reporting

Pursuant to 47 U.S.C. § 1702(j)(2)(A), the Subgrantee shall submit to the IBO a report, at least semiannually, for the duration of the subgrant to track the effectiveness of the use of funds provided. Subgrantees must certify that the information in the report is accurate. Each report shall describe each type of broadband infrastructure project and/or other eligible activities carried out using the subgrant and the duration of the subgrant. *See also* NOFO VII.E.2.

30. Tribal Consent to Deploy on Tribal Land

Consistent with NOFO Sections IV.B.7.a.ii.10 and IV.B.9.b.15, the Subgrantee may not deploy broadband to Unserved Service Projects or Underserved Service Projects that include any locations on Tribal Lands without receiving a Resolution of Consent from each Tribal Government, from the Tribal Council or other governing body, upon whose Tribal Lands the infrastructure will be deployed.

31. Broadband Infrastructure Projects and the Major Purpose Test

As used in this Attachment A, broadband infrastructure “project” carries the same meaning as the term project is used in NOFO Section I.C.(t). For the sake of clarity, broadband infrastructure projects include:

- last-mile broadband deployment projects, as that term is used in Section IV.B.7.a.ii. of the NOFO, with the exception that projects for which the major purpose is training or workforce development are not considered broadband infrastructure projects for the purposes of the exceptions addressed in Paragraph 43, below;
- projects to deploy Middle Mile Infrastructure, as that term is defined in Section I.A.(o) of the NOFO; and
- projects to deploy internet and Wi-Fi infrastructure within a multi-family residential building.

The “major purpose” of a subgrant is a broadband infrastructure project(s) if more than 50% of the estimated total costs (e.g., labor, permitting expenses, equipment, etc.) under the subgrant are necessitated by the broadband infrastructure project(s) activities of the subgrant. NTIA and the IBO retain the authority to review subgrant agreements and revise determinations regarding the major purpose of a subgrant. For purposes of the BEAD Program, LEO Capacity Subgrants shall be considered projects whose major purpose is broadband infrastructure.

32. Encumbrances

Subject to the exception below, Subgrantees must not encumber property without prior disclosure to and approval from the IBO, NTIA and NIST. Subgrantees may not enter into any encumbrances that interfere with the construction, intended use, operation, or maintenance of grant funded property during Federal Interest Period set forth in Paragraph 34.

The following exception applies to subgrants whose major purpose is a broadband infrastructure project. Subgrantees may encumber real property and equipment acquired or improved under such subgrants only after provision of notice to the IBO, NTIA and to the Grants Officer¹¹, and subject to a requirement that the DOC receives either a first priority security interest (preferred) or a shared first priority security interest in the real property and equipment such that, if the real property and equipment were foreclosed upon and liquidated, the DOC would be entitled to receive, on a pari-passu basis with other first position creditors, the portion of the current fair market value of the property that is equal to the DOC's percentage of contribution to the project costs. For example, if the DOC had contributed 50% of the project costs, the DOC would receive, on a pari-passu basis, 50% of the current fair market value of the property when liquidated. NTIA will address the notice requirement for encumbrances in future guidance.

33. Recordation of the Federal Interest in BEAD-Funded Property

A. Useful Life and Compliance with 2 CFR 200.311, 200.313. For the purposes of this Award, the useful life of the real property or equipment acquired or improved using BEAD funds (inclusive of both Federal funds and non-Federal matching funds) shall coincide with the Federal Interest Period as defined in Term 34 below. During the useful life of the BEAD-funded property, the Subgrantee must adhere to the requirements contained in the terms and conditions of the Award, including adherence to the use, management, and disposition requirements set forth in 2 CFR 200.311 or 200.313, as applicable. NTIA will provide additional information concerning the review and approval process for transactions involving BEAD-funded real property and equipment in subsequent guidance. As used in this Paragraph 33 and Paragraph 34, the terms "real property" and "equipment" shall have the meanings given to such terms in 2 C.F.R. 200.1.

B. To document the Federal interest in BEAD-funded real property, the Subgrantee must

¹¹ The National Institute of Standards and Technology (NIST) Grants Officer serves as the Grants Officer for the BEAD program.

prepare and properly record a “Covenant of Purpose, Use and Ownership” (Covenant). The Covenant differs from a traditional mortgage lien in that it does not establish a traditional creditor relationship requiring the periodic repayment of principal and interest to NTIA. Rather, pursuant to the Covenant, the Subgrantee acknowledges that it holds title to the BEAD-funded property in trust for the public purposes of the BEAD financial assistance award and agrees, among other commitments, that it will repay the Federal interest if it disposes of or alienates an interest in the BEAD-funded property, or uses it in a manner inconsistent with the public purposes of the BEAD award, during the useful life of the BEAD-funded property. The Covenant must be properly recorded in the real property records in the jurisdiction in which the real property is located in order to provide public record notice to interested parties that there are certain restrictions on the use and disposition of the BEAD-funded property during its useful life and that NTIA retains an undivided equitable reversionary interest in the BEAD-funded property during the Federal Interest Period. NTIA will provide a suggested sample form to use for the Covenant to record notice of the Federal interest in real property.

- C. UCC-1 Filing & Attorney’s Certification. Pursuant to 2 CFR § 200.316, after acquiring all or any portion of the equipment under this Award, the Subgrantee shall properly file a UCC-1 with the appropriate State office where the equipment will be located in accordance with the State’s Uniform Commercial Code (UCC). This security interest shall be executed in advance of any sale or lease and not later than closeout of the grant or subgrant, as applicable. The UCC filing(s) must include the below or substantively similar language providing public notice of the Federal interest in the equipment acquired with BEAD funding. Also, a clear and accurate inventory of the subject equipment must be attached to and filed with the UCC-1.

The UCC filing must include the below or substantively similar language:

*The Equipment set forth at Attachment A hereto was acquired with funding under a financial assistance award (Award Number) issued by the National Institute of Standards and Technology, U.S. Department of Commerce. As such, the U.S. Department of Commerce retains an undivided equitable reversionary interest (Federal interest) in the Equipment for **[insert number]** years after the end of the year in which the award is closed out in accordance with 2 CFR 200.344.*

In addition, within 15 calendar days following the required UCC filing(s), the Grantee shall provide the Grants Officer with complete and certified copies of the filed UCC forms and attachments for the equipment acquired with NTIA BEAD funding including all subgrants,

along with a certification from legal counsel, licensed by the State within which the filings were made (Attorney's Certification), that the UCC filing was properly executed and filed in accordance with applicable state law. The Attorney's Certification must include the below or substantively similar language:

NIST Award Number: 18-20-B297-3

Pursuant to 28 USC 1746, I hereby certify as follows:

I am legal counsel at _____.

I am licensed to practice law in the State of _____ having been a license holder of said state and in good standing since _____.

Attached hereto is a certified copy of UCC-1 form(s) reflecting that this document was filed in the _____ on _____, 202x, bearing the following filing information [insert filing data, e.g., instrument number, etc.] and consists of _____ recorded pages as certified by the Secretary of State of _____.

I certify that this UCC-1 form(s) has/have been validly executed and properly recorded as noted above.

I certify under the penalty of perjury that the foregoing is true and correct.

Executed on this _____ day of _____.

(Attorney name and title)

(Address and phone number)

In addition, during the estimated useful life of the [type of equipment, e.g. robotic equipment], the Subgrantee is hereby authorized to timely file any necessary UCC-3 continuation statements (or other filings) for the subject equipment consistent with the requirements set forth in this specific award condition. Copies of all filed UCC continuation statements, together with an Attorney's Certification, must be submitted to the IBO and the Grants Officer within 15 calendar days following each such filing. The UCC filing(s) and the accompanying Attorney's Certification(s) must be acceptable in form and in substance to NTIA and the National Institute of Standards and Technology (NIST) Grants Officer.

34. Federal Interest Period

- A. BEAD-Funded Broadband Infrastructure Projects: The Federal interest in all real property or equipment acquired or improved as part of a subgrant for which the major purpose is a broadband infrastructure project will continue for ten years after the year in which that subgrant has been closed out in accordance with 2 CFR 200.344. This Federal interest shall apply regardless of whether the asset is acquired or improved with

Federal funds or non-Federal matching funds. For example, for all subgrants closed out in 2027, regardless of the month, the Federal interest will last until December 31, 2037. The Federal interest described herein applies to BEAD subgrants for which the major purpose of the subgrant, as defined in Paragraph 31 above, is a broadband infrastructure project(s).

- B. The Grants Officer, in consultation with the Program Officer, shall determine the Federal Interest Period for real property or equipment that will be acquired or improved using BEAD funds (inclusive of both Federal funds and non-federal matching funds) and not captured in provision (a) of this Paragraph 34. NTIA will issue further implementation guidance regarding the Federal Interest Period for these BEAD assets.
- C. Per the BEAD Restructuring Policy Notice, NTIA will not take a Federal interest in equipment or property acquired or improved with a LEO Capacity Subgrant. Additionally, the consumer and taxpayer protections set forth in the NOFO apply to the recipients of such subgrants for the duration of the LEO Capacity Subgrant ten-year Federal interest period.

35. Program Income

In the case of subgrants whose major purpose is a broadband infrastructure project, Subgrantees may retain program income without restriction, including retaining program income for profit. This exception does not alter the prohibition in Paragraph 23 above regarding a profit, fee, or other incremental charge above the actual cost incurred by the Subgrantee.

36. Never Contract with the Enemy (2 CFR 200.215)

The Subgrantee shall adhere to the regulations implementing “Never Contract with the Enemy” in 2 CFR Part 183. The regulations in 2 CFR Part 183 affect covered contracts, grants and cooperative agreements that are expected to exceed \$50,000 during the period of performance, are performed outside the United States and its territories, and are in support of a contingency operation in which members of the Armed Forces are actively engaged in hostilities.

37. Network Resilience

The Subgrantee shall incorporate best practices defined by NTIA for ensuring reliability and resilience of broadband infrastructure by establishing risk management plans that account for technology infrastructure reliability and resilience, including from natural disasters (e.g., wildfires, flooding, tornadoes, hurricanes, etc.), as applicable, as well as cybersecurity best practices.

38. Termination

This award may be terminated in part or its entirety for those reasons stated in 2 CFR § 200.340(a). This includes termination “[b]y the Federal agency or pass-through entity pursuant to the terms and conditions of the Federal award, including, to the extent authorized by law, if an award no longer effectuates the program goals or agency priorities.”

39. Trafficking Victims Protection Act (22 USC 7104)

The Subgrantee acknowledges and understands that The Trafficking Victims Protection Act of 2000 authorizes termination of financial assistance provided in this Grant Agreement, without penalty to the Federal Government, if the Subgrantee engages in certain activities related to trafficking in persons. See [2 CFR Part 175](#)¹².

40. Contract Provisions for Non-Federal Entity Contracts under BEAD Award

If the Subgrantee is a Non-Federal Entity as defined by 2 CFR 200.1, then all contracts¹³ made by the Non-Federal Entity¹⁴ Subgrantee under the BEAD award must contain the following provisions, if applicable:

- A. Contracts for more than the simplified acquisition threshold, which is the inflation adjusted amount determined by the Civilian Agency Acquisition Council and the Defense Acquisition Regulations Council (Councils) as authorized by 41 U.S.C. 1908, must address administrative, contractual, or legal remedies in instances where contractors violate or breach contract terms, and provide for such sanctions and penalties as appropriate.
- B. All contracts in excess of \$10,000 must address termination for cause and for convenience by the non–Federal entity including the manner by which it will be effected and the basis for settlement.
- C. Equal Employment Opportunity. Except as otherwise provided under 41 CFR Part 60, and to the extent still applicable and consistent with federal law, all contracts that meet the definition of “federally assisted construction contract” in 41 CFR Part 60–1.3 must include the equal opportunity clause provided under 41 CFR 60–1.4(b), in accordance with Executive Order 11246, “Equal Employment Opportunity” (30 FR 12319, 12935, 3 CFR Part, 1964–1965 Comp., p. 339), as amended by Executive Order 11375, “Amending

¹² At <https://www.ecfr.gov/current/title-2/subtitle-A/chapter-I/part-175>

¹³ See 2 CFR 200.1. *Contract* means, for the purpose of Federal financial assistance, a legal instrument by which a recipient or subrecipient conducts procurement transactions under a Federal award. For additional information on subrecipient and contractor determinations, see [§ 200.331](#).

¹⁴ See 2 CFR 200.1. *Non-Federal Entity* (NFE) means a State, local government, Indian Tribe, Institution of Higher Education (IHE), or nonprofit organization that carries out a Federal award as a recipient or subrecipient.

Executive Order 11246 Relating to Equal Employment Opportunity,” and implementing regulations at 41 CFR part 60, “Office of Federal Contract Compliance Programs, Equal Employment Opportunity, Department of Labor.”

- D. Contract Work Hours and Safety Standards Act (40 U.S.C. 3701–3708). Where applicable, all contracts awarded by the non–Federal entity in excess of \$100,000 that involve the employment of mechanics or laborers must include a provision for compliance with 40 U.S.C. 3702 and 3704, as supplemented by Department of Labor regulations (29 CFR Part 5). Under 40 U.S.C. 3702 of the Act, each contractor must be required to compute the wages of every mechanic and laborer on the basis of a standard work week of 40 hours. Work in excess of the standard work week is permissible provided that the worker is compensated at a rate of not less than one and a half times the basic rate of pay for all hours worked in excess of 40 hours in the work week. The requirements of 40 U.S.C. 3704 are applicable to construction work and provide that no laborer or mechanic must be required to work in surroundings or under working conditions which are unsanitary, hazardous or dangerous. These requirements do not apply to the purchases of supplies or materials or articles ordinarily available on the open market, or contracts for transportation or transmission of intelligence.
- E. Clean Air Act (42 U.S.C. 7401–7671q.) and the Federal Water Pollution Control Act (33 U.S.C. 1251–1387), as amended—Contracts and subgrants of amounts in excess of \$150,000 must contain a provision that requires the non–Federal Award to agree to comply with all applicable standards, orders or regulations issued pursuant to the Clean Air Act (42 U.S.C. 7401–7671q) and the Federal Water Pollution Control Act as amended (33 U.S.C. 1251–1387). Violations must be reported to the Federal awarding agency and the Regional Office of the Environmental Protection Agency (EPA).
- F. Debarment and Suspension (Executive Orders 12549 and 12689)—A contract award (*see* 2 CFR 180.220) must not be made to parties listed on the governmentwide exclusions in the System for Award Management (SAM), in accordance with the OMB guidelines at 2 CFR 180 that implement Executive Orders 12549 (3 CFR part 1986 Comp., p. 189) and 12689 (3 CFR part 1989 Comp., p. 235), “Debarment and Suspension.” SAM Exclusions contains the names of parties debarred, suspended, or otherwise excluded by agencies, as well as parties declared ineligible under statutory or regulatory authority other than Executive Order 12549.
- G. Byrd Anti–Lobbying Amendment (31 U.S.C. 1352)—Contractors that apply or bid for an award exceeding \$100,000 must file the required certification. Each tier certifies to the

tier above that it will not and has not used Federal appropriated funds to pay any person or organization for influencing or attempting to influence an officer or employee of any agency, a member of Congress, officer or employee of Congress, or an employee of a member of Congress in connection with obtaining any Federal contract, grant or any other award covered by 31 U.S.C. 1352. Each tier must also disclose any lobbying with non-Federal funds that takes place in connection with obtaining any Federal award. Such disclosures are forwarded from tier to tier up to the non-Federal award.

41. Compliance with Federal Executive Orders

Incorporated by reference into this BEAD financial assistance award are the policies set forth in all applicable Executive Orders currently in legal force and effect, including Executive Orders issued on or after January 20, 2025. A comprehensive list of Executive Orders may be found at: <https://www.federalregister.gov/presidential-documents/executive-orders>.

By accepting this financial assistance award and expending federal funding thereunder, the Subgrantee agrees to the following conditions:

- A. Compliance with Executive Orders: The Subgrantee agrees to comply with the policies and to further the objectives set forth in all applicable Executive Orders currently in legal effect, including those issued on or after January 20, 2025, as well as Executive Orders that may be issued after the effective date of this award.
- B. Executive Order 14173, 90 FR 8633 (Jan. 21, 2025): The Subgrantee:
 1. Agrees that compliance in all respects with all applicable Federal antidiscrimination laws is material to the government's payment decisions for purposes of Section 3729(b)(4) of Title 31 United States Code;
 2. Certifies to the IBO that it does not operate any programs promoting diversity, equity, and inclusion that violate any applicable Federal antidiscrimination laws; and
 3. Acknowledges that the IBO may require the Subgrantee to submit an annual certification to the IBO that it does not operate any programs promoting diversity, equity, and inclusion that violate any applicable Federal antidiscrimination laws.
- C. Affirmative Duty to Monitor for and to Report Potential Inconsistencies. The Subgrantee must actively monitor its administration of this subaward to ensure that its activities do not violate the requirements of this subaward. At any time during the period of performance of this award, if the Subgrantee believes that any of the activities in its approved scope of work may be inconsistent with the policies outlined in any applicable

Executive Order, the Subgrantee has an affirmative duty to immediately stop work on those potentially inconsistent activities and immediately contact the IBO to determine whether the potentially inconsistent activities may proceed under this award. The performance of activities that violate or that are otherwise inconsistent with requirements under any applicable Executive Order will result in appropriate enforcement action pursuant to 2 CFR 200.339, including the disallowance of costs and possible termination of a portion or all of this award.

42. National Policy Requirements

- A. The Program Fraud Civil Remedies Act (31 U.S.C. § 3801 *et seq.*). The Subgrantee acknowledges and understands that civil penalties may be imposed against persons who make false, fictitious, or fraudulent claims to the Federal Government for money (including money representing grants, loans, or other benefits).
- B. The False Claims Amendments Act of 1986 and the False Statements Accountability Act of 1996 (18 U.S.C. §§ 287 and 1001, respectively). The Subgrantee acknowledges and understands that the making or presenting of any false, fictitious, or fraudulent statement, representation, or claim against the United States may result in imprisonment and fines under Federal law.
- C. The Civil False Claims Act (31 U.S.C. §§ 3729 - 3733). The Subgrantee acknowledges and understands that suits may be brought by the government, or a person on behalf of the government, for false claims made under Federal assistance programs.
- D. The Copeland Anti-Kickback Act (18 U.S.C. § 874). The Subgrantee agrees that it shall comply and ensure that its contractors and subcontractors (pursuant to 40 U.S.C. § 3145) comply with the Copeland Anti-Kickback Act, which prohibits a person or organization engaged in a Federally supported project from enticing an employee working on the project from giving up a part of the employee's compensation under an employment contract.
- E. The Uniform Relocation Assistance and Real Property Acquisition Policies Act of 1970 (42 U.S.C. § 4601 *et seq.*) and implementing regulations issued at 15 CFR Part 11. The Subgrantee shall ensure the fair and equitable treatment of displaced persons or persons whose property is acquired as a result of Federal or Federally-assisted programs. The Subgrantee agrees to apply these requirements to all interests in real property acquired for project purposes regardless of Federal participation in purchases.

- F. To the extent applicable, the Subgrantee acknowledges and agrees that it shall comply with the Hatch Act (5 U.S.C. §§ 1501-1508 and 7321-7326), which limits the political activities of employees or officers of state or local governments whose principal employment activities are funded in whole or in part with Federal funds.
- G. To the extent applicable, the Subgrantee acknowledges and agrees that it shall comply with the provisions of the Fly America Act (49 U.S.C. § 40118). The implementing regulations of the Fly America Act are found at 41 CFR §§ 301-10.131 through 301-10.143.

43. Uniform Guidance Exceptions, Adjustments, and Clarifications Applicable to Fixed Amount Subgrants For Which the Major Purpose of the Subgrant is a Broadband Infrastructure Project(s)

The following Uniform Guidance exceptions, adjustments, and clarifications apply to fixed amount subgrants for which the major purpose of the subgrant is a broadband infrastructure project. Throughout the below discussion on exceptions, adjustments, and clarifications, the phrase “fixed amount subgrant” is used as shorthand to refer to fixed amount subgrants as described in the preceding sentence.

A. Exceptions to 2 CFR Part 200 Fixed Amount Subgrant Requirements (200.333—Fixed Amount Subgrants and 200.201(b)(2)--Use of grant agreements (including fixed amount awards), cooperative agreements, and contracts)

Pursuant to exceptions of 2 CFR 200.333 and 200.201(b)(2) approved by the Office of Management and Budget (“OMB”), the IBO has elected to treat this Award as a fixed amount subgrant. Subgrantees must periodically report their expenses using Generally Accepted Accounting Principles or other standard accounting practices. Subgrantees must also monitor and report to the IBO the relative proportion of costs across key spending areas: professional services (e.g., engineering, environmental and historic preservation permitting, legal expenses, etc.); construction services (e.g., digging trenches, erecting towers, blowing fiber, constructing and improving buildings, etc.); outside plant, towers, and poles (e.g., fiber plan, conduit, towers, poles, emergency power generational equipment, etc.); network and access equipment (e.g., broadband routing equipment, broadband transport equipment, network broadband access equipment, wireless base stations, antennas, etc.); operating equipment (e.g., office furniture and fixtures, work equipment and vehicles, etc.); customer premise equipment; contingency funds; and all other expenses.

Subgrantees shall use subgrant payments only for the reimbursement of the eligible costs in connection with the last-mile broadband deployment projects for which the payment is intended and, if applicable, the eligible costs for non-deployment for which the payment is intended. Ineligible uses of fixed amount subgrant payments include but are not limited to the following:

1. Personal expenses of employees, executives, board members, and contractors, and family members thereof, or any other individuals affiliated with the Subgrantee, including but not limited to personal expenses for housing, such as rent or mortgages, vehicles for personal use and personal travel, including transportation, lodging and meals;
2. Gifts to employees; housing allowances or other forms of mortgage or rent assistance for employees except that a reasonable amount of assistance shall be allowed for work-related temporary or seasonal lodging; cafeterias and dining facilities; food and beverage except that a reasonable amount shall be allowed for work-related travel; entertainment;
3. Expenses associated with: tangible property not logically related or necessary to the broadband infrastructure project or authorized non-deployment use; corporate aircraft, watercraft, and other motor vehicles designed for off-road use except insofar as necessary or reasonable to access portions of the project area not readily accessible by motor vehicles travelling on roads; tangible property used for entertainment purposes; consumer electronics used for personal use; kitchen appliances except as part of work-related temporary or seasonal lodging assistance; artwork and other objects which possess aesthetic value;
4. Political contributions; charitable donations; scholarships; membership fees and dues in clubs and organizations; sponsorships or conferences or community events not logically related or necessary for the intended use of the subgrant; nonproduct-related corporate image advertising; and
5. Penalties or fines for statutory or regulatory violations; penalties or fees for any late payments on debt, loans, or other payments.

The remainder of 2 CFR 200.201 remains unchanged. Payments shall be made on a reimbursement basis in accordance with terms of the Grant Agreement. *See* NOFO Sec. IV.C.1.b. Pursuant to 2 CFR 200.201(b)(3), the Subgrantee must certify in writing to the IBO at the end of the Federal Award that the broadband infrastructure project funded under the subgrant was completed. Accordingly, a Subgrantee receiving a fixed amount subgrant must certify to the IBO that the broadband infrastructure project

was placed into service, as defined in 47 USC 1702(h)(4)(C) for last-mile broadband deployment projects by the end of the Subgrantee's period of performance.

The above notwithstanding, the BEAD Program prohibition on the Subgrantee claiming profit or fees as allowable costs remains unchanged by this exemption. See NOFO Sec. V.H.2.b. Therefore, neither fees above the estimated actual cost that will be incurred by the Subgrantee nor profit shall be considered reasonable costs when determining the reasonable estimate of actual costs (i.e., neither fees nor profits may be included in the estimate of actual costs).

Subgrantees of fixed amount subgrants pursuant to the above exceptions are not required to comply with the Cost Principles set forth in 2 CFR Subpart E. However, all fixed amount subgrants must be based on a reasonable estimate of actual cost.

B. Adjustments to 2 CFR 200.318-320 and 200.324-326—Procurement Standards

Subgrantees of fixed amount subgrants pursuant to the above exceptions are not required to comply with the Procurement Standards set forth in 2 CFR 200.318-320 and 200.324-326. All other Procurement Standards, i.e., 2 CFR 200.317, 200.321-200.323, and 200.327, remain as requirements.

C. Exceptions and Clarifications to 2 CFR 200.313—Equipment

Title to equipment acquired or improved under the fixed amount subgrant vests in the Subgrantee upon acquisition, subject to the following conditions and clarifications that apply for the duration of the Federal Interest Period:

1. Subgrantee must follow their existing commercial practices for managing equipment in the normal course of business and must use inventory controls indicating the applicable Federal interest and loss prevention procedures. This requirement is in lieu of the requirements contained in 2 CFR 200.313(d), pursuant to an exception from OMB. Subgrantees that do not have existing commercial practices for managing equipment in the normal course of business must comply with 2 CFR 200.313(d).
2. Subgrantee must comply with the use and equipment disposition requirements of 2 CFR 200.313(c)(4) and 313(e).
 - a. Subgrantees acquiring replacement equipment under 2 CFR 200.313(c)(4) may treat the equipment to be replaced as "trade-in" even if the Subgrantee elects to retain full ownership and use over equipment. As with trade-ins that involve a third party, the Subgrantee will have to record the fair market

value of the equipment being replaced in its Tangible Personal Property Status Reports to the IBO and DOC to ensure adequate tracking of the Federal percentage of participation in the cost of the grant funded activities. The Subgrantee will also be responsible for tracking the value of the replacement equipment, including both the Federal and non-Federal share.

- b. Subgrantee may sell, lease, or transfer equipment only after (a) securing the agreement of the successor or transferee to comply with these requirements and the acknowledgement of the successor or transferee of the Federal interest in the subject equipment, and (b) obtaining consent to the sale or transfer from NTIA. NTIA will provide additional information concerning the review and approval process for transactions involving BEAD-funded equipment, as well as real property, in subsequent guidance.
- c. Subgrantee must notify the IBO and NTIA upon the filing of a petition under the U.S. Bankruptcy Code, whether voluntary or involuntary, with respect to the Subgrantee or any affiliate that would impact the Subgrantee's ability to perform in accordance with its subgrant.

D. Exception to 2 CFR 200.314--Supplies

Pursuant to an exception approved by OMB, the property standards set forth in 2 CFR 200.314 for supplies shall not apply to fixed amount grants.

E. Exception to 2 CFR 200.315--Intangible Property

Pursuant to an exception approved by OMB, the property standards set forth in 2 CFR 200.315 for intangible property shall not apply to fixed amount grants.

ATTACHMENT B - ANNUAL FINANCIAL REPORT FOR NON- GOVERNMENTAL ENTITIES

Guidelines for filing the annual financial report:

1. Filing an annual financial report called an Entity Annual Report (E-1) is required by IC 5-11-1-4. This is done through Gateway which is an on-line electronic submission process.
 - a. There is no filing fee to do this.
 - b. This is in addition to the similarly titled Business Entity Report required by the Indiana Secretary of State.
 - c. The E-1 electronical submission site is found at <https://gateway.ifionline.org/login.aspx>
 - d. The Gateway User Guide is found at <https://gateway.ifionline.org/userguides/E1guide>
 - e. The State Board of Accounts may request documentation to support the information presented on the E-1.
 - f. Login credentials for filing the E-1 and-additional information can be obtained using the notforprofit@sboa.in.gov email address.
2. A tutorial on completing Form E-1 online is available at https://www.youtube.com/watch?time_continue=87&v=nPpgtPcdUcs
3. Based on the level of government financial assistance received, an audit may be required by IC 5-11-1-9.

ATTACHMENT C – BYRD ANTI-LOBBYING CERTIFICATION

Grant applicants who apply or bid for an award of \$100,000 or more shall file the required certification. Each tier certifies to the tier above that it will not and has not used Federal appropriated funds to pay any person or organization for influencing or attempting to influence an officer or employee of any agency, a Member of Congress, officer or employee of Congress, or an employee of a Member of Congress in connection with obtaining any Federal contract, grant, or any other award covered by 31 U.S.C. § 1352.

Each tier shall also disclose any lobbying with non-Federal funds that takes place in connection with obtaining any Federal Award. Such disclosures are forwarded from tier to tier up to the recipient who in turn will forward the certification(s) to the awarding agency.

APPENDIX A, 44 C.F.R. PART 18 – CERTIFICATION REGARDING LOBBYING


Certification for Contracts, Grants, Loans, and Cooperative Agreements

The undersigned certifies, to the best of his or her knowledge and belief, that:

1. No Federal appropriated funds have been paid or will be paid, by or on behalf of the undersigned, to any person for influencing or attempting to influence an officer or employee of an agency, a Member of Congress, an officer or employee of Congress, or an employee of a Member of Congress in connection with the awarding of any Federal contract, the making of any Federal grant, the making of any Federal loan, the entering into of any cooperative agreement, and the extension, continuation, renewal, amendment, or modification of any Federal contract, grant, loan, or cooperative agreement.
2. If any funds other than Federal appropriated funds have been paid or will be paid to any person for influencing or attempting to influence an officer or employee of any agency, a Member of Congress, an officer or employee of Congress, or an employee of a Member of Congress in connection with this Federal contract, grant, loan, or cooperative agreement, the undersigned shall complete and submit Standard Form-LLL, "Disclosure Form to Report Lobbying," in accordance with its instructions.
3. The undersigned shall require that the language of this certification be included in the award documents for all subawards at all tiers (including subcontracts, subgrants, and contracts under grants, loans, and cooperative agreements) and that all subrecipients shall certify and disclose accordingly.

This certification is a material representation of fact upon which reliance was placed when this transaction was made or entered into. Submission of this certification is a prerequisite for making or entering into this transaction imposed by Section 1352, title 31, U.S. Code. Any person who fails to file the required certification shall be subject to a civil penalty of not less than \$10,000 and not more than \$100,000 for each such failure.

The Subgrantee, **Central Indiana Communications Inc.**, certifies or affirms the truthfulness and accuracy of each statement of its certification and disclosure, if any. In addition, the Subgrantee understands and agrees that the provisions of 31 U.S.C. Chap. 38, Administrative Remedies for False Claims and Statements, apply to this certification and disclosure, if any.

A handwritten signature in black ink, appearing to read "Michael R. Burrow", is written over a horizontal line.

Signature of Subgrantee's Authorized Representative

Michael R. Burrow – President & CEO

Name and Title of Subgrantee's Authorized Representative

1/8/2026

Date



ATTACHMENT D – PROTECTING THE BEAD PROGRAM FROM DEFAULTS CERTIFICATION

The undersigned certifies, to the best of his or her knowledge and belief, that:

1. For the project awards described in each individual Exhibit and corresponding Appendix A to the Master BEAD Subgrant Agreement, **Central Indiana Communications Inc.** and any of its affiliates will not require or accept any additional Federal funds to support a BEAD project¹ during the BEAD subgrant agreement's period of performance, extended period of performance, or federal interest period; and
2. For the project awards described in each individual Exhibit and corresponding Appendix A to the Master BEAD Subgrant Agreement, **Central Indiana Communications Inc.** and any of its affiliates will not accept any additional Federal broadband service subsidies² for the project(s) and/or Broadband Serviceable Location(s) (BSL(s)) to be served by the subgrant during the BEAD subgrant agreement's period of performance, extended period of performance, or federal interest period, other than any such subsidies that were committed prior to the BEAD subgrant agreement. (This includes, but is not limited to, new operating expenses for any BEAD project(s) or BSL(s)).

I certify that the foregoing is true and correct.

Executed on this **4th day of June 2026**.

Brad Rennier

CFO

NineStar Connect

2243 East Main Street

¹ 47 U.S.C. § 1702(a)(2)(K) (defining the term "project" as "an undertaking by a subgrantee under this section to construct and deploy infrastructure for the provision of broadband service").

² For purposes of this prohibition, a "Federal broadband subsidy" is defined as any Federal funds made available to subsidize the provision of broadband service. For example, Federal broadband service subsidies include, but are not limited to, any of the Universal Service Fund (USF) support mechanisms.



Greenfield, IN 46140

P: 317-323-2021

C: 317-967-0996



Exhibit 1 –Subaward Conditions and Statement of Work for Project Area NIN-001

1. General Information.

General Information	
2 CFR 200.332(a)(1) Federal Award Identification.	
(i) Subrecipient name (which must match the name associated with its unique entity identifier);	Central Indiana Communications, Inc. f/k/a NineStar Connect
(ii) Subrecipient's unique entity identifier;	UEI Number or CAGE Code: FCG3GL1YN5N7
(iii) Federal Award Identification Number (FAIN);	18-20-B297; UEI Number: LK34C47QFQC5
(iv) Federal Award Date;	11/15/2022
(v) Subaward Period of Performance Start and End Date;	Four years from Effective Date (“ED”)
(vi) Subaward Budget Period Start and End Date;	Effective date through Four years from ED
(vii) Amount of Federal Funds Obligated by this action by the pass-through entity to the Subrecipient (subaward funds);	\$16,742,798.00
(viii) Total Amount of Federal Funds Obligated to the subrecipient by the pass-through entity including the current obligation (subaward funds);	\$16,742,798.00
(ix) Total Amount of the Federal Award committed to the Subrecipient by the pass-through entity (subaward funds);	\$16,742,798.00
(x) Federal Award project description, as required to be responsive to the Federal Funding Accountability and Transparency Act (FFATA);	This project will utilize a Federal Award to build broadband infrastructure for unserved and underserved locations. Subrecipient will deploy and install broadband to BEAD eligible locations in Appendix B in accordance with the terms and milestones set forth in this Exhibit 1 - Specific Award Conditions for Project Area NIN-001.
(xi) Name of Federal awarding agency, pass-through entity, and contact information for awarding official of the Pass- through entity;	Federal Awarding Agency: United States Department of Commerce National Telecommunications Information Administration Pass-Through Entity: Indiana Broadband Office Pass-Through Entity Contact Information: Megan Minor, Chief Broadband Officer email: MeMinor@iot.in.gov phone: 317-509-4363
(xii) Assistance Listing Number and Title;	Assistance Listing Number and Title: 11.035 – Broadband Equity, Access, and Deployment Program

(xiii) Identification of whether the award is R&D; and	This award does not support research and development (R&D).
(xiv) Indirect cost rate for the Federal Award (including if the de minimis rate is charged per §200.414 Indirect (F&A) costs).	N/A
Match percentage and Match amount	25.00%; \$5,580,932.00
Total Project Cost = (subaward funds + match)	\$22,323,730.00

2. Subaward Amount. The IBO will provide the Subgrantee with subaward funds in the amount of **\$16,742,798.00** (“Subgrant Funds” or “Subaward Amount”) to deliver and maintain broadband to Project Area NIN-001 (“Deployment Project”) in accordance with applicable law and the State and federal conditions applicable to the BEAD Award and this Agreement. *Project Area* means the area designated by the Subgrantee in which Subgrantee will construct a broadband network to provide reliable broadband to residents and businesses listed in **Appendix B of this Exhibit 1**. The Project Area is depicted in the map in **Appendix A of this Exhibit 1**, attached hereto and incorporated herein.

3. Fixed Amount Subaward and Milestone Payment Schedule.

- A. This Subaward is issued as a Fixed Amount Subaward per 2 CFR 200.333. As such, the Subgrantee shall be responsible for all Project costs that exceed the amount of the Subgrant Funds. In the event the available Subgrant Funds are insufficient to satisfy all Project costs, the Subgrantee shall be responsible for fulfilling all of its obligations under the Grant Agreement.
- B. Record Keeping. Although there is no routine monitoring of the actual costs incurred by the Subgrantee under this Subaward, the Subgrantee must keep records of actual costs incurred and abide by the record retention requirements contained in 2 CFR 200.334 through 200.338 as well as the responsibilities of making records available for review during an audit.
- C. The IBO will disburse Subaward Funds after the Subgrantee’s completion and verification of each milestone event detailed in **Appendix D of this Exhibit 1**, attached hereto and incorporated herein. The IBO may, at its discretion, request evidence of actual costs and restrict payment to actual costs after reviewing evidence of costs for any milestone reimbursement made under the Grant Agreement.
- D. Conditions Precedent to First Disbursement. The IBO shall not disburse any subaward funds prior to the Subgrantee’s completion of Environmental and Historic Preservation (“EHP”) reviews, EHP consultations and compliance with applicable environmental laws and regulations as detailed in Paragraph 8.A of Attachment A to the Grant Agreement.

4. Match Details.

- A. The Subgrantee shall provide a match in the amount of **\$5,580,932.50**, which is 25.00% of the Total Project Cost.

- B. The Subgrantee's match (or cost share) toward the Total Project Cost shall be from the following sources¹, and in the amounts and percentages below:
- (1) Central Indiana Communications, Inc. f/k/a NineStar Connect/private funds; cash match at 25.00% for a total match of \$5,580,932.50.
- C. Verification of Match. Upon the completion of a project milestone, the Subgrantee shall verify its match toward the project cost by providing documentation ***along with a legally binding attestation***. The records verifying the match amount must include the source, amount, quantity, time (if applicable), and delivery of each match service.
- (1) Cash Match. Examples of records verifying cash matches include:
 - Bank or financial statement, showing available and expended funding.
 - Receipts from disbursements.
 - (2) In-Kind Match. Examples of records verifying in-kind matches include:
 - For volunteer services where the rate must not exceed fair market value, use federal tools such as the Bureau of Labor Statistics to determine wage rate information. To the extent feasible, record time as an organization would for paid labor, such as timesheets and timecards.
 - For reduced rates from consultants and other individuals, compare current charges against standard or set labor category rates.
 - For facility in-kind matches, verify the amount against current mortgage statements or rental rates.
- D. The Subgrantee agrees to abide by the cost sharing/match requirements of 2 CFR 200.306 by ensuring its matches are:
- (1) Verifiable from the records submitted to the IBO;
 - (2) Not included as contribution for another Federal Award;
 - (3) Necessary and reasonable to accomplish project or program objectives;
 - (4) Allowable under subpart E of CFR 200.306;
 - (5) Not paid by the federal government under another Federal Award, except where the federal statute authorizing a program specifically provides that federal funds made available for such program can be applied to matching or cost sharing requirements of other federal programs. *See* the IIJA provision providing for such exceptions under 47 USC § 1702(h)(3)(B)(iii) and Section III.B.1 of the BEAD NOFO; and
 - (6) In conformance to other provisions of 2 CFR 200.306, as applicable.
- E. The Subgrantee shall retain records associated with its match towards the project cost through the life of the Subaward, grant closeout and records retention period set forth in 2 CFR 200.334 and Section 8.A of the Grant Agreement.

5. Scope of Work.

A. Project Description.

- (1) Grantee must, no later than four (4) years after receiving the Subaward, create a fully-functioning, commercially serviceable broadband network within the Project Area that meets all Project Completion Standards.

¹ Match can be provided from the following sources: the Subgrantee; the Eligible Entity; Philanthropic Organization; Federal Regional Commission or Authority; Unit of Local Government; For-Profit Company; Utility Company; Regional Planning; Government Organization; Non-Profit Organization; Cooperative; or any combination of the above.

- (2) The Subgrantee, in deploying broadband infrastructure, must do the following:
 - a. Acquire such Equipment as is necessary to install, create, and maintain the broadband network, and to construct and install its related facilities²;
 - b. Design, install, construct, test, maintain, and operate its broadband network; and
 - c. Acquire all necessary real property interests or access rights to real property for the purpose of installing its transmission lines.

B. Project Completion Standards. The Subgrantee agrees and warrants that, upon completion of the Project as described in this Paragraph 5.A(1), the broadband network will comply with the following:

- (1) Project Area. The broadband network will provide broadband to the locations listed in **Appendix B of this Exhibit 1** in the area depicted in **Appendix A of this Exhibit 1**.
- (2) Locations Served in the Project Area. The network will service each of the residential and business locations (broadband serviceable location or BSL) listed in **Appendix B of this Exhibit 1**, attached hereto and incorporated herein. The Subgrantee agrees that, upon completion, the network will serve the comprehensive list of Locations (whether residential or business) located within the Project Area at the service speeds specified below. Any modifications must be approved in writing by both parties. A Location is considered “served” if the Subgrantee can initiate service through a routine installation within ten (10) business days of a request with no extraordinary monetary charges or delays attributable to the extension of Subgrantee’s network. The Subgrantee may charge standard installation fees to subscribers on the BEAD-funded network but may not require subscribers to make modifications to their own or surrounding property or charge fees for the same in connection with installation of broadband services funded by this Subaward.
- (3) Network Capabilities. Pursuant to 47 U.S.C. § 1702(g)(1)(A), the Subgrantee shall ensure that every Funded Network meets the criteria related to speed and latency and network outages outlined in the NOFO. See NOFO IV.C.2.a. and in the [Performance Measures for BEAD Last Mile Networks Policy Notice](#)³ (an any future amendments).
 - a. Speed and Latency.
 - i. Broadband networks shall deliver broadband service to each of the Locations served with speeds of not less than one hundred (100) Mbps for downloads and twenty (20) Mbps for uploads. In addition, ninety-five percent (95%) of latency measurements during testing windows must fall at or below one hundred (100) milliseconds round trip time.
 - ii. Connections to Eligible Community Anchor Institutions, as defined in the BEAD NOFO, shall be capable of delivering service at speeds not less than one (1) Gigabit per second for uploads. The Subgrantee shall ensure that such connections can be used to provide business service data.⁴

² Facilities means a place or building used to construct, maintain, or operate a broadband network.

³ At https://broadbandusa.ntia.gov/sites/default/files/2025-09/Performance_Measures_Policy_Notice.pdf

⁴ The term “business data service” refers to the dedicated point-to-point transmission of data at certain guaranteed speeds and service levels using high-capacity connections. See *Business Data Services in an Internet Protocol Environment et al.*, WC Docket No. 16-143 *et al.*, Report and Order, 32 FCC Rcd 3459, 3463 para. 6 (2017).

- iii. Subgrantees must demonstrate continued compliance with these standards by performing speed and latency tests from the subscriber premises of an active subscriber to a remote test server at an end-point consistent with the requirements for a Commission-designated IXP (FCC Designated Internet exchange point).⁵
 - b. Reliability and Resilience. The Subgrantee shall establish risk management plans that account for technology infrastructure reliability and resilience, including safeguards against natural disasters (e.g., wildfires, flooding, tornadoes, hurricanes, etc.), as applicable, as well as cybersecurity and SCRM best practices⁶ that incorporate strategies for mitigating risks associated with natural disasters. The plans should reflect best practices and demonstrate preparedness for physical and digital disruptions.
 - c. Network Outages. The network's outages should not exceed, on average, forty-eight (48) hours over any three hundred sixty-five (365) day period except in the case of natural disasters or other force majeure occurrence. The Subgrantee shall ensure a prospective network is designed to meet this requirement. Developing a comprehensive outage management plan that includes preventive maintenance schedules, metrics for measuring outages, quick response teams for outage resolution, and clear communication channels for informing subscribers about outages and expected restoration times will meet this requirement. As applicable, the Subgrantee shall develop network designs that meet IBO metrics for measuring outages once the network is operational.
- (4) Deployment Requirements.
- a. Deployment Deadline. The Subgrantee must deploy broadband networks and start service to each prospective subscriber that desires it no later than four (4) years after the effective date of this Agreement.
 - b. Conduit Access Points. Any Project that involves laying fiber-optic cables or conduit underground or along a roadway must include interspersed conduit access points at regular and short intervals.
 - c. Covered Purchases. When deploying broadband networks, the Subgrantee may not purchase covered communications equipment⁷ or support the People's Republic of China through purchasing fiber optic cable and optical transmission equipment manufactured there.
- (5) Service Obligations.
- a. Low-Cost Plans. The Subgrantee must offer at least one Low-Cost Broadband Service Option ("LCSO"), as proposed by the Subgrantee and approved by the NTIA. The LCSO must be made available to eligible subscribers⁸ for the useful life of the network asset (i.e., the Federal Interest Period, which is ten (10) years after the year in which the subgrant for a project has been closed out or in the case of LEOs, a ten (10) year period of performance). The NTIA or the IBO may

⁵ See *Performance Measures Reconsideration Order*, 34 FCC Rcd at 10114-16, paras. 17-19.

⁶ See, e.g., National Institute of Standards and Technology Framework for Improving Critical Infrastructure Cybersecurity, *Cybersecurity Supply Chain Risk Management Practices for Systems and Organizations*, NIST 800-161 Rev.1 and *Key Practices in Cyber Supply Chain Risk Management: Observations from Industry*, NIST IR 8276.

⁷ Covered communications equipment or services are defined in section 9 of the Secure and Trusted Communications Networks Act of 2019 (47 U.S.C. 1608).

⁸ Eligible Subscriber means any household seeking to subscribe to broadband internet access service that is eligible for the FCC's Lifeline Program. Lifeline eligibility criteria are defined in 47 CFR 54.409.

take corrective action, including recoupment of Subaward funds from the Subgrantee, for non-compliance with the statutory low-cost plan requirement. The Subgrantee's definition of a LCSO must detail:

- i. All recurring charges to the subscriber, as well as any non-recurring costs or fees to the subscriber;
 - ii. The plan's basic service characteristics (download and upload speeds and latency; the LCSO must be at least 100/20 Mbps and <100ms latency);
 - iii. The plan's price and, as applicable, how the price will change over time;
 - iv. Whether the Subgrantee will define Eligible Subscriber more broadly than the RPN.
- b. Access to Service. The Subgrantee shall provide access to broadband service to each subscriber served by the project that desires broadband service on terms and conditions that are reasonable and non-discriminatory.
 - i. The Subgrantee shall initiate service at standard installation charges within ten (10) business days of a request from any prospective subscriber in the Project Area.
 - ii. For Low Earth orbit (LEO) Projects, the Subgrantee is required to provide all necessary consumer premises equipment (CPE) at no cost as part of the standard installation for each new subscriber at the BEAD-funded Location throughout the period of performance. This obligation is limited to no more than three (3) CPE per Location during the Period of Performance. If the Subgrantee plans to send CPE to the subscriber to self-install or use a third-party installer, the Subgrantee shall ensure the subscriber receive the CPE within ten (10) days.
- c. Use of Funds. The Subgrantee shall use Subaward Funds in an equitable and nondiscriminatory manner. The Subgrantee further acknowledges and agrees that the IBO may recover Subaward Funds and/or terminate the Grant Agreement in the event of the Subgrantee's nonperformance as detailed in Section 21 of the Grant Agreement.
- d. Public Notice.
 - i. Once the broadband network has been deployed, the Subgrantee shall provide public notice, online and through other means, of that fact to the locations and areas to which broadband service has been provided and share the public notice with the IBO; and
 - ii. The Subgrantee shall conduct public awareness campaigns in broadband network service areas to increase broadband adoption by highlighting the value and benefits of broadband internet access.
- e. Cybersecurity and Supply Chain Risk Management. The Subgrantee shall comply with the Cybersecurity and Supply Chain Risk Management (SCRM) requirements detailed in Paragraph 22 of Exhibit A to the Grant Agreement.
- f. Wholesale Rate. If the Subgrantee is no longer able to provide broadband service to the locations covered by the Subaward at any time, the Subgrantee shall sell the network capacity at a reasonable, wholesale rate on a nondiscriminatory basis to other broadband service providers or public sector entities.

6. Reporting.

A. Semiannual Report.

The Subgrantee shall, for the duration of the Subaward, submit to the IBO a semiannual report on a semiannual basis for the periods ending June 30 and December 31. The Semiannual Report must be submitted no later than five (5) days following the end of each reporting period. The Subgrantee must maintain sufficient records to substantiate all information below upon request. Each semiannual report shall:

- (1) Describe each type of project carried out using the Subaward and the duration of the Subaward;
- (2) Include a list of addresses or locations (including the Broadband Serviceable Location Fabric established under 47 U.S.C. 642(b)(1)(B)) that constitute the service locations that will be served by the broadband infrastructure to be constructed;
- (3) Identify new locations served within each project area at the relevant reporting intervals, and service taken (if applicable);
- (4) Identify whether each address or location described is residential, commercial, or a community anchor institution;
- (5) Describe the types of facilities that have been constructed and installed;
- (6) Describe the peak and off-peak actual speeds of the broadband service being offered;
- (7) Describe the maximum advertised speed of the broadband service being offered;
- (8) Describe the non-promotional prices, including any associated fees, charged for different tiers of broadband service being offered;
- (9) Include any other data that would be required to comply with the data and mapping collection standards of the Commission under section 1.7004 of title 47, Code of Federal Regulations, or any successor regulation, for broadband infrastructure projects;
- (10) Include Form SF-425 (Real Property Status Report) that meets the requirements described in DOC ST&Cs, Section A.01 for Real Property Status Reports;
- (11) Describe delays in broadband-related projects that Subgrantee attributes to a state or local prohibition on using its preferred construction technique;
- (12) Describe delays in broadband-related projects that Subgrantee attributes to state and/or local authorities failing to follow FCC rules regarding pole attachment timelines, rates, terms, and conditions for access to municipally owned poles and conduit for broadband projects;
- (13) Federal, State or local permit requests submitted;
- (14) Detail Subgrant Funds and matching funds expended, in a manner consistent with the requirements of Paragraph 52.A of the General Terms and Conditions for the BEAD Program;
- (15) Comply with any other reasonable reporting requirements determined by the IBO or the Assistant Secretary; and
- (16) Certify that the information in the report is accurate.

B. Close-Out Performance Report.

Final Performance Report. The Subgrantee must submit a final Performance Report to the IBO no later than ninety (90) calendar days after the conclusion of the period of performance⁹.

⁹ See Section A.01.b.3 DOC ST&C.

C. Financial Report.

The Subgrantee shall submit to the IBO a Performance Report on a semiannual basis for the periods ending March 31 and September 30. The Financial Report must be submitted no later than fifteen (15) calendar days following the end of each reporting period.

- (1) The Subgrantee shall submit a Form SF-425 (Federal Financial Report) that meets the requirements described in the DOC ST&Cs, Section A.01 for Financial Reports.
- (2) Final Financial Report. The Subgrantee must submit a final Financial Report to the IBO no later than ninety (90) calendar days after the conclusion of the period of performance.

7. Project Monitoring.

A. Monitoring Activities. The IBO will monitor the Subgrantee's overall performance to ensure that the goals and objectives of the Subaward are achieved. Monitoring activities may consist of site visits, desk reviews and performance/financial report reviews.

B. Monitoring Plan. The monitoring plan will consist of:

- (1) Quarterly progress check-in meetings with the Subgrantee;
- (2) Review of Subgrantee's Financial and Performance reports that are required by the NTIA, the Grant Agreement, or any applicable laws and regulations;
- (3) Review of Subgrantee's audit results;
- (4) Site visits, if deemed necessary by the IBO and upon advance written notice to the Subgrantee; and
- (5) Review to ensure Subgrantee's compliance with applicable laws, the terms of the Grant Agreement and BEAD Program requirements.

C. The State may, pursuant to 2 CFR 200.332 and 200.208, change its monitoring plan, procedures or requirements at any time during the term of this Grant Agreement, including, but not limited to placing specific award conditions on this Subaward.

D. Corrective Action and Compliance Oversight. The IBO will take corrective action on all significant developments that negatively affect the Subaward. Significant developments include Single Audit findings related to the Subaward, other audit findings, site visits, and written notifications from a subrecipient of adverse conditions which will impact the Subgrantee's ability to meet the milestones or the objectives of this Subaward. When significant developments negatively impact the Subaward, the Subgrantee shall provide the IBO with information on its plan for corrective action and any assistance needed to resolve the situation.

- (1) Any corrective action plan under this Paragraph 7.D will:
 - i. Identify the specific noncompliance or deficiency;
 - ii. Define clear resolution steps and timelines;
 - iii. Outline documentation required for remediation;
 - iv. Establish consequences for failure to comply, consistent with the enforcement provisions in 2 CFR 200.339.
- (2) The IBO will monitor corrective action plans closely through scheduled follow-ups and additional oversight activities. The Subgrantee will receive guidance and tailored support throughout the process to promote timely resolution and sustained compliance.

- E. Final Inspection. The Subgrantee shall provide notice of completion of the broadband infrastructure project and other construction activities when all construction has been completed, the architect/engineer has conducted its own final inspection, and any deficiencies have been corrected. The IBO will schedule the final inspection. Representatives of the IBO, the architect/engineer and the Subgrantee must attend the final inspection for the project.

8. Project Closeout

- A. Closeout will be conducted on the timelines and in the manner set forth in 2 CFR 200.344.
- B. The Subgrantee shall submit all reports (financial, performance, and other reports required by the Subaward) to the IBO no later than ninety (90) calendar days after the conclusion of the period of performance of the Subaward (or an earlier date as agreed upon by the IBO and Subgrantee).
- C. The Subgrantee must liquidate all financial obligations incurred under this Subaward no later than ninety (90) calendar days after the conclusion of the period of performance of this Subaward (or an earlier date as agreed upon by IBO and Subgrantee).
- D. The Subgrantee must promptly refund any unobligated funds that the IBO paid and that are not authorized to be retained. *See* OMB Circular A-129 and 2 CFR 200.346.
- E. The Subgrantee must account for any “real property” and “equipment,” in each case as defined in 2 CFR 200.1, acquired with Subaward Funds or received from the Federal Government in accordance with 2 CFR 200.310 through 200.313, 200.316 and 200.330.
- F. Certification of Project Completion. The Subgrantee shall certify in writing to the IBO that the project was completed as agreed to in this Exhibit 1 to the Grant Agreement, or identify activities that were not completed, and that all expenditures were incurred in accordance with 2 CFR 200.403. If the required activities are completed in accordance with the terms and conditions of the Federal BEAD Requirements and this Grant Agreement, the Subgrantee is entitled to any unexpended funds.

9. Letter of Credit (“LOC”).

Prior to entering into the Grant Agreement, the Subgrantee shall obtain an irrevocable standby letter of credit, effective no later than the Effective Date of this Agreement, which shall be acceptable in all respects to the IBO and in a value of no less than 25% of the Subaward Amount. In addition, the Subgrantee shall provide the IBO an opinion letter from legal counsel clearly stating that in a proceeding under Title 11 of the United States Code, 11 USC § 101 *et seq.* (“Bankruptcy Code”), the bankruptcy court would not treat the LOC or proceeds of the LOC as a property of the Subgrantee’s bankruptcy estate under Section 541 of the Bankruptcy Code.

10. Project Personnel.

- A. Both IBO and Subgrantee have designated the following persons to serve as Project Manager to support effective communication between the Parties to report on the work’s progress.

- (1) For IBO: IBO Division Director (TBD); IndianaBroadband@iot.in.gov; phone; TBD
- (2) For Subgrantee: George Plisinski; gplisinski@ninstarconnect.com

B. Written notice shall be provided to personnel at the email addresses set forth in this Paragraph 10 in the event of any change in Project Personnel.

11. Insurance.

- A. Subgrantee must comply with the insurance requirements in 2 CFR 200.310. In addition, the Subgrantee and its contractors shall secure and keep in force during the term of the Grant Agreement the following insurance coverages (if applicable) covering the Subgrantee for any and all claims of any nature which may in any manner arise out of or result from Subcontractor's performance under this Grant Agreement.

All insurance required under this Grant Agreement shall apply to the full limits of liability actually maintained or purchased by the Subgrantee and its contractors, including any primary, umbrella, or excess policies. The insurance limits specified in this Agreement are minimum requirements only and shall not be construed to limit, cap, reduce, or otherwise restrict the total limits of insurance available under any applicable policy up to the full limits of the applicable policy, even if those limits exceed the minimum limits required by this Grant Agreement.

No policy provision, endorsement, exclusion, or condition—including any ISO or manuscript endorsement containing language such as “contractual limitation,” “limits,” “most we will pay,” “not broader than required by contract,” “lesser of,” or similar wording—shall operate to limit, reduce, erode, or restrict the coverage or limits available to the State to the minimum limits required by this Grant Agreement or to the amount of insurance required by contract.

The duty to defend, indemnify, and hold harmless the State under this Grant Agreement is independent of and shall not be limited by the insurance requirements contained herein or by the availability of insurance coverage, and the maintenance of insurance required under this Agreement shall not be construed to limit the liability assumed by the Subgrantee.

- (1) Commercial general liability, including contractual coverage, and products or completed operations coverage (if applicable), with minimum liability limits not less than \$700,000 per person and \$5,000,000 per occurrence unless additional coverage is required by the State. The State is to be named as an additional insured on a primary, non-contributory basis for any liability arising directly or indirectly under or in connection with this Grant Agreement.
- (2) Automobile liability for owned, non-owned and hired autos with minimum liability limits not less than \$700,000 per person and \$5,000,000 per occurrence. The State is to be named as an additional insured on a primary, non-contributory basis.
- (3) Errors and Omissions liability with minimum liability limits of \$1,000,000 per claim and in the aggregate. Coverage for the benefit of the State shall continue for a period of two (2) years after the date of service provided under this Grant

Agreement.

- (4) Worker' Compensation insurance as required by state statute.
- (5) Insurance Coverage reasonably sufficient to protect Grant funded property from theft, fire, vandalism, weather damage to materials, equipment, and the project itself during the build.
- (6) Inland Marine Insurance reasonably sufficient to protect equipment acquired with Grant funds.
- (7) Cyber Liability addressing risks associated with electronic transmissions, the internet, networks and informational assets sufficient to satisfy the obligations under the Grant Agreement.

The Subgrantee shall provide proof of such insurance coverage by tendering to the undersigned State representative a certificate of insurance prior to the commencement of this Grant Agreement and proof of workers' compensation coverage meeting all statutory requirements of IC § 22-3-2.

B. The Subgrantee's insurance coverage must meet the following additional requirements:

- (1) The insurer must have a certificate of authority or other appropriate authorization to operate in the state in which the policy was issued.
- (2) Any deductible or self-insured retention amount or other similar obligation under the insurance policies shall be the sole obligation of the Subgrantee.
- (3) The State will be defended, indemnified and held harmless to the full extent of any coverage actually secured by the Subgrantee in excess of the minimum requirements set forth above. The duty to indemnify the State under this Grant Agreement shall not be limited by the insurance required in this Grant Agreement.
- (4) The insurance required in this Grant Agreement, through a policy or endorsement(s), shall include a provision that the policy and endorsements may not be canceled or modified without thirty (30) days' prior written notice to the undersigned State agency.
- (5) The Subgrantee waives and agrees to require their insurer to waive their rights of subrogation against the State of Indiana.

C. Failure to provide insurance as required in this Grant Agreement may be deemed a material breach of contract entitling the State to immediately terminate this Grant Agreement. The Subgrantee shall furnish a certificate of insurance and all endorsements to the State before the commencement of this Grant Agreement.

12. Conditions Precedent to Grant Agreement Execution.

Before the commencement of this Grant Agreement, the Subgrantee shall provide the following documents to the IBO:

- FFATA information from Paragraph 27 of Attachment A to the Grant Agreement;
- Certificate of Insurance and all endorsements;
- Letter of Credit with an opinion letter from legal counsel or Performance Bond¹⁰;
- Cybersecurity Risk Management Plan referenced in Paragraph 22 of Attachment A to the Grant Agreement;

¹⁰ If the Subgrantee is submitting a Performance Bond (PB), then Subgrantee may choose to submit the PB within 60 days of entering into this Grant Agreement as permitted by the NTIA's BEAD Letter of Credit Waiver at https://broadbandusa.ntia.gov/sites/default/files/2026-01/BEAD_LOC_Waiver_Notice_10.23.23_0.pdf

- Supply Chain Risk Management (SCRM) Plan referenced in Paragraph 22 of Attachment A to the Grant Agreement;
- Match details listing the match source, type of match, percentage of Total Project Cost, and dollar amount as required in Paragraph 4.B of this Exhibit 1;
- Appendix A to this Exhibit 1 – Map of Project Area NIN-001;
- Appendix C to this Exhibit 1 – Budget for Project Area NIN-001;
- Appendix E to this Exhibit 1 – Environmental and Historic Preservation (EHP) Milestone Schedule for Project Area NIN-001;
- Appendix F to this Exhibit 1 – Form of Attestation to Accompany Disbursement Request;
- Byrd Anti-Lobbying Certification (Attachment C to the Grant Agreement); and
- Protecting the BEAD Program from Defaults Certification (Attachment D to the Grant Agreement). The NTIA may, at its discretion, publicly publish the signed certifications in Attachment D.

13. Specific Award Conditions – Environmental and Historic Preservation (EHP)/Permitting

A. Completion of Environmental Review.

The Subgrantee must comply with all applicable statutory environmental and historic preservation regulations and identify to the IBO and NTIA when a proposed infrastructure project may have potentially significant effects on the environment. The Subgrantee may not expend any federal BEAD funds other than for the limited permissible activities identified in [General Terms and Conditions for NTIA BEAD Program Funds](#) Section 13.E prior to the following:

- The completion of any review required under the National Environmental Policy Act of 1969 (42 U.S.C. 4321, et seq.) (NEPA), and issuance by NTIA and the Grantee, as required, of a Categorical Exclusion (Cat Ex) determination, Record of Environmental Consideration (REC), Finding of No Significant Impact (FONSI), or Record of Decision (ROD) (hereinafter “decision documents”) that meets the requirements of NEPA;
- The completion of reviews required under Section 106 of the National Historic Preservation Act of 1966 (54 U.S.C. 300101, et seq.) (NHPA), including any consultations required by Federal law, to include consultations with the State Historic Preservation Office (SHPO), and Federally recognized Native American tribes;
- The completion of consultations with the U.S. Fish and Wildlife Service (USFWS) or the National Marine Fisheries Service (NMFS), as applicable, under Section 7 of the Endangered Species Act (16 U.S.C. 1531, et seq.), and/or consultations with the U.S. Army Corps of Engineers (USACE) under Section 404 of the Clean Water Act (33 U.S.C. 1251, et seq.), as applicable; and
- Demonstration of compliance with all other applicable Federal, state, and local environmental laws and regulations.

Project implementation (site preparation, demolition, construction, ground disturbance, or any other project implementation activities) may not begin prior to the completion of the above activities. The Subgrantee must comply with all conditions placed on the grant funded activities as the result of environmental reviews and associated consultations as the result of NEPA or NHPA consultation or processes under other applicable laws — e.g., mitigation requirements, best management practices, or other measures necessary to reduce environmental impacts.

The allowable use of funds prior to beginning project implementation includes, but is not limited to, activities necessary for the completion of the following:

- Pre-construction planning, including collecting information necessary to complete environmental reviews;
- Applications for environmental permits;
- Studies including, but not limited to, Environmental Assessments (EA), wetland delineations, biological assessments, archaeological surveys, and other environmental reviews and analyses;
- Administrative costs;
- Pre-award application costs;
- Activities supporting consultations required under the NHPA, the Endangered Species Act, and the Clean Water Act;
- Limited, preliminary procurement, including the purchase or lease of equipment, or entering into binding contracts to do so; the purchase of applicable or conditional insurance; and/or funds used to secure land or building leases (including right-of-way easements).

If the Subgrantee undertakes unauthorized project activities in contravention of this Section, it proceeds at its own risk and may face de-obligation of funding.

B. Timely Provision of NEPA Documents and Permits.

The Subgrantee shall provide any information requested by the IBO or NTIA to support initial and ongoing compliance with environmental and historic preservation laws and regulations. Once consultation activities have been completed, the IBO will review all documentation and determine sufficiency. Projects with potentially significant impacts to environmental or historic resources may face de-obligation of funding if impacts cannot be mitigated.

The Subgrantee must comply with all conditions placed on the grant funded activities as the result of NEPA or NHPA consultation or processes under other applicable laws—e.g., mitigation requirements, best management practices, or other measures necessary to reduce environmental impacts.

The Subgrantee shall notify the IBO within 24 hours upon receipt of any notices of foreclosure; requests for additional consultation received from the SHPO, THPO, Tribal representative, USFWS, or other consulting party; or notices of noncompliance received from consulting authorities or regulatory agencies.

The Subgrantee must notify the IBO of any change to the approved project scope that has the potential for altering the nature or extent of environmental or cultural resources

impacts. Projects with such potential will be re-evaluated for compliance with applicable regulatory requirements.

C. Milestone Schedule for NEPA and Permitting

Before executing this Grant Agreement, the Subgrantee must provide the IBO a draft milestone schedule identifying environmental review and permitting activities, dependencies, and deadlines and describing how the Subgrantee proposes to meet timing requirements including, as required:

- The completion of any statutorily required reviews and consultations including, but not limited to, Endangered Species Act Section 7 and National Historic Preservation Act Section 106;
- The completion of NEPA, including the submission of Environmental Assessments (EAs) or Environmental Impact Statements (EISs) if anticipated; and
- Anticipated dates for any necessary federal permit applications, including application acceptance and permit decisions.

The IBO may stipulate the format of the NEPA and Permitting milestone schedule and, upon review, request revisions to reflect statutorily driven sequencing requirements.

The Subgrantee shall provide quarterly updates to the IBO on the status of its milestone progress under this Paragraph 13.C.

D. Unanticipated Discoveries.

Burial sites, human remains, and funerary objects are subject to the requirements of all applicable Federal, Tribal, state, and local laws and protocols, such as the Native American Graves Protection and Repatriation Act (NAGPRA), in addition to Section 106 of the NHPA. Subgrantee must notify the IBO and NTIA of inadvertent discoveries and potential impacts to these resources and identify and follow all applicable laws or protocols. Subgrantee should have an archaeologist who meets the Secretary of the Interior's Professional Qualification Standards monitor ground disturbance for grant funded activities proposed in the vicinity of National Register eligible archaeological sites and suspected or known burials. If any potential archeological resources or buried human remains are discovered during construction, the Subgrantee must immediately stop work in that area, secure that area, and keep information about the discovery confidential, except to notify the IBO and NTIA and the interested SHPO, THPO, and potentially affected Tribes. Such construction activities may then only continue with the written approval of NTIA.

14. Deployment Scope Changes and Budget Modification.

All Project scope changes and budget changes¹¹ shall comply with the terms of 2 CFR 200.308, the Deployment Scope Changes SAC for the State of Indiana, the BEAD Program

¹¹ The IBO shall adhere to NTIA's BEAD Scope Change and Budget Modification Guidance for Eligible Entities (https://broadbandusa.ntia.gov/sites/default/files/2026-03/BEAD_Eligible_Entity_Guidance_Scope_Change_and_Budget_Modification.pdf) when approving or seeking scope changes or budget modifications.

General Terms and Conditions, and all project-specific requirements, including but not limited to National Environmental Policy Act (NEPA) and Permitting requirements.

15. Access to Subgrantee's Records.

The Subgrantee acknowledges and agrees that the IBO has the right to collect any information from the Subgrantee or its subcontractors related to budgets, expenses, receipts, financial reports, and deployment milestones at whatever frequency the IBO deems appropriate.

16. Updated NTIA Guidance and Requirements.

The Subgrantee acknowledges and agrees that the IBO retains the right to update provisions of the Grant Agreement to align with updated NTIA guidance and requirements via a written amendment.

17. Survival.

- A. Any provision of this Grant Agreement that would reasonably be expected to be complied with or performed after the expiration or termination of this Grant Agreement shall survive the expiration or termination of this Grant Agreement and continue until the end of the Federal Interest Period.
- B. The Subgrantee acknowledges and agrees that some terms shall remain an ongoing obligation of the Subgrantee through the Federal Interest Period. These ongoing terms include, but are not limited to, the following provisions:
 - Paragraph 17 of Attachment A – Affordability and Low-Cost Plans
 - Paragraph 32 of Attachment A – Encumbrances
 - Paragraph 33 of Attachment A – Recordation of the Federal Interest in BEAD – funded Property
 - Paragraph 43.C of Attachment A – Exceptions and Clarifications to 2 CFR 200.313 - Equipment
 - Paragraph 5.B(1) of Exhibit 1 – Project Area
 - Paragraph 5.B(2) of Exhibit 1 – Locations Served in the Project Area
 - Paragraph 5.B(3) of Exhibit 1 – Network Capabilities
 - Paragraph 5.B(4)b of Exhibit 1 – Conduit Access Points
 - Paragraph 5.B(4)c of Exhibit 1 – Covered Purchases
 - Paragraph 5.B(5)a of Exhibit 1 – Low-Cost Plans
 - Paragraph 5.B(5)b of Exhibit 1 – Access to Service
 - Paragraph 5.B(5)e of Exhibit 1 – Cybersecurity and SCRM
 - Paragraph 5.B(5)f of Exhibit 1 – Wholesale Rate

Appendix A to Exhibit 1 – Map of Project Area NIN-001

Appendix B to Exhibit 1 – List of Locations in Project Area NIN-001

Ninestar Connect NIN-001 Location List

3,353 locations

ID	Location ID	Is CAI	Technology	Upload	Download
993dd4d08b8586481fde4632bed6fb02	1089034331	No	Fiber	10000	10000
67c10d187c5e9568b8e4b6d8cc36b586	1106686704	No	Fiber	10000	10000
1656238e73ae028878ae563472f1b92a	1111406127	No	Fiber	10000	10000
9a984981c40387e572928a67434dabcc	1106683926	No	Fiber	10000	10000
2e7192e078657c91100befee547da5fd	1089059854	No	Fiber	10000	10000
90b01b74216107dc345e4c26c26ee203	1106682480	No	Fiber	10000	10000
700c337eb87b0a768b9e18b4ebc300c8	1106682861	No	Fiber	10000	10000
3e5bfc5b4d058b85c7cb3ae121438fa3	1286905467	No	Fiber	10000	10000
3fae8668c4bfa22305d15fe834e5c28f	1112239106	No	Fiber	10000	10000
1b72ee9557a66db33efcf30cd08d1f78	1106680728	No	Fiber	10000	10000
72d61d0ecf8660df637860d1de86a35d	1106686497	No	Fiber	10000	10000
7c7bd9ced8c022278a7aa9a3cee85449	1106683968	No	Fiber	10000	10000
9a286c20b20d4106d8739972ad862531	1089034242	No	Fiber	10000	10000
0984c13fb06379fff159ab7571a4c9d4	1111411960	No	Fiber	10000	10000
143fa18dd80627d90766f95dc895f926	1286908268	No	Fiber	10000	10000
b620a65d432b4b30801648bd59c504d5	1286907167	No	Fiber	10000	10000
942b93f876ba174bf386509acb32be80	1111413336	No	Fiber	10000	10000
186debb4a5f5402ef91b2ac9095ebaa9	1106683687	No	Fiber	10000	10000
e443bfac5bdc4db29512a6c58747fc7d	1106682918	No	Fiber	10000	10000
da132d303490428829d6c87446c09c62	1106685928	No	Fiber	10000	10000
6197a763344b320eade6aee91dd4e2a	1106682383	No	Fiber	10000	10000
36c919aef151352d9207e10ab43b0442	1112259005	No	Fiber	10000	10000
a816b07ebdc2b032299921735cbb0b19	1111413209	No	Fiber	10000	10000
feaeec488d41546b9200a947a62aca5d	1111421014	No	Fiber	10000	10000
155f3b125181d63c685be33fa8691aa9	1106682522	No	Fiber	10000	10000
f8c5396435c05cba17186bef7972c4f3	1286908133	No	Fiber	10000	10000
31b9f51e11b986d9332c7ea077ad8c0a	1106679128	No	Fiber	10000	10000
aba584e1905a164632c904a36bd7d990	1111412045	No	Fiber	10000	10000
8da735e5585c8d9eeb6aee0149d760e	1286907818	No	Fiber	10000	10000
a4babd4f330096d05344037fb9fdbbf8	1106679782	No	Fiber	10000	10000
199c9cdb2925eac5eb4f159b894f594e	1106680098	No	Fiber	10000	10000
28785af820ac307627d944f84a953d19	1111410388	No	Fiber	10000	10000
55d1f6de6aa48e8ea77658fde33cdcc3	1106682359	No	Fiber	10000	10000
dd0f14a4a6cba7d17052be6cbef090ca	1111413023	No	Fiber	10000	10000
5f2c895e186b9e983514912c61055c19	1106679459	No	Fiber	10000	10000
513473aa4226e5b81c026cf7bd71213b	1111413906	No	Fiber	10000	10000
b20c24b3857af904cbf24be558c5cd6a	1111405912	No	Fiber	10000	10000
6cf2b8fa75436f41d85c1555c6a553fc	1111411979	No	Fiber	10000	10000
64ce26dde5c7b7500a1457ed3d2e7fc9	1106679426	No	Fiber	10000	10000
812a82f996b460d75bb0601bba8c196d	1106687128	No	Fiber	10000	10000
2c1fb6ba9f250f081a4f03f19234cf75	1286914399	No	Fiber	10000	10000
83b0e2b5e942419fa32abfbfb448d782	1106682837	No	Fiber	10000	10000
1cf7053a929d91b0d6f490c1fc7775da	1089055482	No	Fiber	10000	10000
fc3908e95772c5d718c08bb7222d7e8e	1089031238	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
19ec1ffef6baf6bdb1bf0bd6d0ecb615	1106679938	No	Fiber	10000	10000
beef5d9bae7899974d785e0053ea151f	1106679995	No	Fiber	10000	10000
5ba64fb66f3b496a461e61a47cc55379	1111412228	No	Fiber	10000	10000
ddbbbac80c89043d31b4fa427237b5ae	1384581027	No	Fiber	10000	10000
822624875d224f1d5a6b88ed26860e8e	1111412006	No	Fiber	10000	10000
f87ae211bc59381d49900b72cab54a51	1106680125	No	Fiber	10000	10000
61bf298b2b1c8d09aa14d8f5c0bfe8ad	1089059856	No	Fiber	10000	10000
264dbf9dfd9ecbfa3bda762894662b7c	1106680146	No	Fiber	10000	10000
816948574d0300fc5cdbfd872971f8de	1106686933	No	Fiber	10000	10000
114d23d5a90d167deddc06b8af52d0df	1384900437	No	Fiber	10000	10000
52213bcbf275fdae75a9141ec01267a8	1106686048	No	Fiber	10000	10000
94a9c106d43ec73d160a2937b2d1355b	1112239084	No	Fiber	10000	10000
eb0de6bde44721f2454c6ba3537abd97	1089059420	No	Fiber	10000	10000
1438bf78895d0a9fbb98a12adfd2b788	1112257234	No	Fiber	10000	10000
89eafd4fb655ad4c27c96d2a5aa2ff84	1106684107	No	Fiber	10000	10000
66237f693dc9f4f85db2d343d9bee17f	1106682883	No	Fiber	10000	10000
c2249422e15786fd52b214d5b1bfdf97	1286905233	No	Fiber	10000	10000
277a74cc820cb7aaf74c92bdecfc64b	1106686208	No	Fiber	10000	10000
fa689ea88f34f33056005bdfbd16e00	1106684985	No	Fiber	10000	10000
57cbfc9204f315200cd40818ae62b525	1112261290	No	Fiber	10000	10000
6ae9169dd3b94c5f33ca3310366ecf67	1089034560	No	Fiber	10000	10000
19ab6524a3f30b84fbc5626d2b44f6bb	1089059982	No	Fiber	10000	10000
e20da4c47e3b0074dff6dc83a76abba8	1112257573	No	Fiber	10000	10000
6528a1748f5a90c9a5a68e33da4a12ec	1089040449	No	Fiber	10000	10000
42c37fc3a7b66a848acadb03ac1c623	1106684384	No	Fiber	10000	10000
d341508d4ab091ab563987d0f3449c0c	1111412036	No	Fiber	10000	10000
8dacb72c8b37aabda91a7f626115b19d	1112264010	No	Fiber	10000	10000
1aa7094602eb6fe4c1534f90c2d9aedef	1286908907	No	Fiber	10000	10000
dde9ab8a3c64919e211660c7e0ce84dc	1111410799	No	Fiber	10000	10000
e2b53879e9be3f2887a64815d2688a62	1106681642	No	Fiber	10000	10000
5c6fe6a602724ccd65bfb81eb1ef30c4	1106684399	No	Fiber	10000	10000
3c6c4a54edc16c67b83e19875fadb37a	1089034315	No	Fiber	10000	10000
526be7305d7f8da073e90dc79f4a3534	1106682613	No	Fiber	10000	10000
2acc654b28376fb051a10df65fcd22f2	1286913000	No	Fiber	10000	10000
fe0bbc4d8abd1586f1bf4d08b96a788a	1106685553	No	Fiber	10000	10000
40733c1d32bc628057cdb73fca8e645c	1413421455	No	Fiber	10000	10000
2139085cc1c424bd2060166d73266ce1	1106681079	No	Fiber	10000	10000
d9c2af8e891874b59b9c6538df44a1e3	1106686152	No	Fiber	10000	10000
7cace70528963059936d1927058485a8	1089039732	No	Fiber	10000	10000
993209976e718a377eba52d5796c1d6d	1106679524	No	Fiber	10000	10000
10d8c35b91cee3d3f7f010ef0cbdc63c	1106680413	No	Fiber	10000	10000
3dd9f653429ab04ed78a5f5459216142	1286910360	No	Fiber	10000	10000
7b86166b9d844bc0adf6432db1acb5f1	1111412031	No	Fiber	10000	10000
2cda797afabb98d1f61c89ea952a539a	1111413031	No	Fiber	10000	10000
b2041c661062d701d81b3182af0fb65d	1106684879	No	Fiber	10000	10000
8aa3121b9ee8a544f05885a19a86b1da	1106683983	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
2c6cd20830e69f826097c2ce3a74774e	1106681553	No	Fiber	10000	10000
7041c56306a1158c1165303320acea38	1286905577	No	Fiber	10000	10000
953ba2c904c2be87710db7a43f905e93	1286912739	No	Fiber	10000	10000
8955143cdca2aca8e1081fb0dfd8b406	1413429248	No	Fiber	10000	10000
ddb45b8592d7c34ca34d397b068e6e4b	1106684310	No	Fiber	10000	10000
4cef3dde29a69e4fa2952455a31029e3	1106684152	No	Fiber	10000	10000
596dfa11f33c8560df4f5e0451bb63a2	1384900393	No	Fiber	10000	10000
a33542fc95beb0bb4402f8c520269e50	1106684302	No	Fiber	10000	10000
ed6af96e64c08c030b58369d5649de2b	1089056578	No	Fiber	10000	10000
6c2fdc3b11aaf9449bac6ca4d06acbf5	1111414554	No	Fiber	10000	10000
de4e5f4cb11f15ca7836de52009342ce	1106687179	No	Fiber	10000	10000
7383e5b6875712d6622814fd1b38eba7	1106680049	No	Fiber	10000	10000
f828cf5def39c76d49e2d4ab5841e67f	1089039760	No	Fiber	10000	10000
0b571538562b9fa88d339f15038f32f3	1089043844	No	Fiber	10000	10000
c971b1f46f4f06ff4411c296954e6818	1111412253	No	Fiber	10000	10000
d78a524f3079c95d9d5f57e5fb087456	1089059709	No	Fiber	10000	10000
e4941f29f81f2f8fe5c95b98281a74fe	1112239090	No	Fiber	10000	10000
dd144b19d832e7fdd890af438b4dd47e	1106684996	No	Fiber	10000	10000
26f4d4b90ebb034ae0f45b0cbc8180a0	1286909062	No	Fiber	10000	10000
64e57a4635ed1801677d04bff8890e79	1112263144	No	Fiber	10000	10000
08107a86e41d71dcf6f475fd4da0528b	1106681089	No	Fiber	10000	10000
18daf8ae85140e5761b5a02b307976e9	1286905889	No	Fiber	10000	10000
4599f7e92dacbe4922055e85018343cd	1111412155	No	Fiber	10000	10000
1855a1c7c541f851b578f4efcade212c	1106680754	No	Fiber	10000	10000
d7bb05f0190935de33a48afb56a9a85a	1106682556	No	Fiber	10000	10000
de9582105609350589e5fe7bc6f1ff21	1089040418	No	Fiber	10000	10000
8a70d7ef531b2e152a97db3cf4e74490	1106681163	No	Fiber	10000	10000
6ddd618cb6e95cb35332acf5a94bfe20	1089040448	No	Fiber	10000	10000
7874f0f6ac937bec794ef985e6a644f9	1111413197	No	Fiber	10000	10000
3094c1530228c6550dcc740d933c3100	1106682606	No	Fiber	10000	10000
fc93d800f45269f22f5995db351d5ac2	1106683364	No	Fiber	10000	10000
869f93f6dd15c06f5551d2a302ab745f	1106680505	No	Fiber	10000	10000
323f58031f597308cf23bc30d1f4ffc4	1106685856	No	Fiber	10000	10000
06e1c4a227cf7be71628570dd3c38ea5	1111425492	No	Fiber	10000	10000
d1c701cd8aee5e67dfd647ca5baf1ff6	1286908872	No	Fiber	10000	10000
589d2bb7632f94e389bc7c2c1244868d	1106681493	No	Fiber	10000	10000
64562ae7cb15bf30aab521c69b0d7f30	1286914245	No	Fiber	10000	10000
187b26a9fa9cac94d75fdcf8eaca60d9	1111409949	No	Fiber	10000	10000
ccd6c472980ccbca23a80b65deedce9e	1106680021	No	Fiber	10000	10000
0999644789216a24def8284ef7811bde	1106681928	No	Fiber	10000	10000
7b72996b1dd97536fd2ff0ec32c543ca	1106687218	No	Fiber	10000	10000
8a53be2994d2fcb422232033b62cdc83	1106680154	No	Fiber	10000	10000
fb843cd9c8aacadf1193170e6a7f92fec	1106685071	No	Fiber	10000	10000
34688d80ca2b93e43929e5634400e930	1089032095	No	Fiber	10000	10000
0a94e13dc019108b91179cff5fc47fe5	1112258986	No	Fiber	10000	10000
3fd9ed5020855973e1208d88ceb2bc58	1106684210	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
4a908b5628b0de700ba18675f88b0739	1106682055	No	Fiber	10000	10000
5cd1e7978bbfcd009e7ab409a34c9f47	1106683313	No	Fiber	10000	10000
1c365735c0d87c64aaab6ffc04f5a427	1106680554	No	Fiber	10000	10000
bda2137af0c8d8017cc6f92e9d3b89b9	1111412055	No	Fiber	10000	10000
a6998ad121f7aa4b4b8d7291d0dde220	1106682551	No	Fiber	10000	10000
fd69391d5ed34fb689519047f8db8672	1089031964	No	Fiber	10000	10000
0791a049e0e89231ed86cf860c56b8ae	1111412797	No	Fiber	10000	10000
58e518eab65950bce87c15580d605063	1112239086	No	Fiber	10000	10000
047df584fd16ccd4dcd93da759e8f969	1106683533	No	Fiber	10000	10000
a4d5d2d2db9d6d6b4283a053eace86b5	1111411388	No	Fiber	10000	10000
4ab00e9ae2a3fe0a187685f532ab00c2	1413411259	No	Fiber	10000	10000
3d6f09318940e908fe62c8749c2cd245	1286905525	No	Fiber	10000	10000
c151a23c3bcf2b67fd377b5246ffe944	1106686086	No	Fiber	10000	10000
9332db26a5e75f7b634195cc8cbde57e	1106685771	No	Fiber	10000	10000
f0427ec89130e7cb89222f4f403d6fa5	1111411961	No	Fiber	10000	10000
dfd2661899a55ebfd947479093eb70fe	1112239115	No	Fiber	10000	10000
ba828c2ff8895ebd8f6b6796cf0e94c7	1106680873	No	Fiber	10000	10000
67b2ae9bfb700ab6907974530bbfc580	1106684050	No	Fiber	10000	10000
2bcf6dafed85105b484faed1977906f2	1106683247	No	Fiber	10000	10000
1be92579a654f1e587d865bca0bd0ed7	1106684979	No	Fiber	10000	10000
54d8c9e39e8afd9cf2edf6c78ace7bcd	1106684792	No	Fiber	10000	10000
544127def34ab5ee5dccb1cfde8ffe85	1111413211	No	Fiber	10000	10000
7b00666d09b9d9540bb0cedf108f4ce9	1111412038	No	Fiber	10000	10000
71f31d8c23e2ab8bba8b86dd89bcff6f	1089056298	No	Fiber	10000	10000
1460e97bf4f522dbe9e3a16bcc939f93	1106680039	No	Fiber	10000	10000
06e82cdb56498edf9be2822c2155910f	1089031232	No	Fiber	10000	10000
fbcbffbb3431c8271e6e9ebaa0226af7	1111413110	No	Fiber	10000	10000
760794a6fe82a257fede300a318f6cda	1111409946	No	Fiber	10000	10000
23361cf2381064d5f3beb12c1f1debe4	1286908310	No	Fiber	10000	10000
362670d54a095f67c9f55a79dbf4af83	1111414810	No	Fiber	10000	10000
d69819f9a44c0517690033288d989384	1106686410	No	Fiber	10000	10000
150333fa7f10bf7dfe81655c9a6e569	1112243669	No	Fiber	10000	10000
028b984e203642acd534a7a9010785ea	1286906062	No	Fiber	10000	10000
3405162906d1b172d1b64381a41efca9	1106685356	No	Fiber	10000	10000
49863b1574aa0a9b69dcae51c452529c	1089040414	No	Fiber	10000	10000
d811b129d7c53ed5a375d6bc257d0889	1106686918	No	Fiber	10000	10000
a49cc4ca1288eff8e4796f94562245c8	1106683657	No	Fiber	10000	10000
655a3c584abac7282a3a629266f16eaf	1111411840	No	Fiber	10000	10000
b99167767af517d0b683417771d0480f	1106680511	No	Fiber	10000	10000
5611b05fcab446ba7c9c57cb20a6a1b0	1106685261	No	Fiber	10000	10000
7cf0407d52a3214d2705d8ffa671aa86	1286906205	No	Fiber	10000	10000
ee7eae69063e31bc94f64921e5a52a64	1111414585	No	Fiber	10000	10000
f008c8d339c78b3d814991d0f1a1c19b	1111413337	No	Fiber	10000	10000
23f4563404954ad29c07e1c80ae5aa00	1286908288	No	Fiber	10000	10000
e6b5c1a92af0270941c88f75eafadba9	1384586305	No	Fiber	10000	10000
ed1808a6ddf6324ab0aa928658259ca6	1111413232	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
42123d5f5eb7325f4410486859abd4dd	1106684843	No	Fiber	10000	10000
d26a96ed92ec433c8d4bb1c33ac23b48	1286918418	No	Fiber	10000	10000
26ddc0c0fad2f0bf777bc44162be9dd5	1089055477	No	Fiber	10000	10000
c740d73c1d06bfc0bed83a06bc620e5	1286907689	No	Fiber	10000	10000
1493c1a4950ceeb37d393244b2036be5	1089059395	No	Fiber	10000	10000
633ad95453be0bfea72bac3c5b676371	1106686877	No	Fiber	10000	10000
39482e9c351fddda36fafedd1481b2cd	1111419599	No	Fiber	10000	10000
bee331d4bf1005d74dd094598f0432de	1106686790	No	Fiber	10000	10000
5e450c5ceef66aec0ac41051f0317652	1106680168	No	Fiber	10000	10000
fff2d918a5720ba7a32ff9dcf1481cbb	1112235923	No	Fiber	10000	10000
ce8d2fe3ae5a752a5435cb36a2ea7e6d	1111413900	No	Fiber	10000	10000
2f82853830a75aad9f0f24696f129664	1106682914	No	Fiber	10000	10000
1d96660292986a42a284a335b4ca8feb	1106679326	No	Fiber	10000	10000
3b5bde9448f2dff0673f13344b70c78	1106684685	No	Fiber	10000	10000
caa9e584a094047e9b0434a69c13c6f9	1106683099	No	Fiber	10000	10000
0af7d992bc2251c10d832fefa87d205c	1089034828	No	Fiber	10000	10000
87bda2b081763d491831851dbae132a2	1286913080	No	Fiber	10000	10000
2ed5c2ea4cecf771d95de535ba7caa91	1111406335	No	Fiber	10000	10000
5c5ffe20d10385526564938d5ab85b11	1106686494	No	Fiber	10000	10000
1d7f2659cebeb5f76443f4e85b3de6c5	1384687827	No	Fiber	10000	10000
c9e8bc3fea27047cae23c9cb633d26a0	1111413867	No	Fiber	10000	10000
e1560fe3e3c7f719b1ff58e8afea7ed5	1106682742	No	Fiber	10000	10000
8c829a4d9ca87004a7bc1c3d6c19a029	1106685212	No	Fiber	10000	10000
a94593b273c5c648c788260545e3d112	1112257561	No	Fiber	10000	10000
7c26bc9d11fdf3275f716b6d1c605c6	1106684890	No	Fiber	10000	10000
71b04c7c59e750b5148c42ec87700ff6	1286908604	No	Fiber	10000	10000
38f4622d1522aac75a87189484eefb35	1111406286	No	Fiber	10000	10000
12c1d08f4102e152fcf3e21cb790498e	1106682372	No	Fiber	10000	10000
d78c011d82c060d8f1ed8f55493d8d94	1111405924	No	Fiber	10000	10000
24df4910cc4f9d17d9ef21c657ec4364	1111404544	No	Fiber	10000	10000
9c53c2361ad1572e6cda4a52cac99bbc	1106684100	No	Fiber	10000	10000
242ebcd48626d18fd21de9882bf82049	1106686174	No	Fiber	10000	10000
aec4485d4e31f9750dce8e95aab08de	1384901001	No	Fiber	10000	10000
75d2856c7e6f867a2a01ac761d3fa5e6	1089040417	No	Fiber	10000	10000
272fe489d6116b48cb8ee27c648318f4	1106682229	No	Fiber	10000	10000
e89f91b2d6bd58c5a3b45deea46a39e7	1106682126	No	Fiber	10000	10000
b5ff183b33882ee6d06b001a6c862c70	1413411255	No	Fiber	10000	10000
a463fce70c001ee233d557b45e0be2a7	1286904500	No	Fiber	10000	10000
19cf8c4556a3dde75c5df6dfcb37313	1384981291	No	Fiber	10000	10000
6c6ccfa4ef16c887567b64457f065ffc	1089059399	No	Fiber	10000	10000
c28b053ccbd801f5eb9ed4f511b70016	1384901432	No	Fiber	10000	10000
9739ea2cd9922ad82433a12a3561ad4b	1111415051	No	Fiber	10000	10000
c451b36c87d3d79ede89882c17e403bf	1111419612	No	Fiber	10000	10000
eeb7ae13017cc446454c055edc77ff0f	1111405564	No	Fiber	10000	10000
ec8f6e8b7dc1adc49771673f5a8bd7e4	1089059490	No	Fiber	10000	10000
e21ac2dc462dc2b4985c6bad1bc7c24a	1111413030	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
8dcd963455155204f3eb6abc49add8ba	1106685579	No	Fiber	10000	10000
481d4ff7b0b43cb744b0210ae887eb32	1106683055	No	Fiber	10000	10000
5a0f18743436c72d2c89cc24a9d3758a	1089059843	No	Fiber	10000	10000
d11ee39a218d89871cc1a37ea23b9750	1286907363	No	Fiber	10000	10000
318524634f64c793b972d9f3302240c1	1106691247	No	Fiber	10000	10000
49cfd3cf4f1eb6f6ebe13dcd7ff20ea	1111411975	No	Fiber	10000	10000
6932b2be2536eb6d1c03256dc41e9374	1111404919	No	Fiber	10000	10000
83c8bc32ef12de69f5cfef8ccf910276	1111405208	No	Fiber	10000	10000
80e3a5f6ee178ac12c1f09fdc9ba0e4c	1089059226	No	Fiber	10000	10000
9c1e2bb9879b7732562609cdf436b293	1106683496	No	Fiber	10000	10000
0a4c05fef9faf6f0e92da5c8afa5b0ea	1106681192	No	Fiber	10000	10000
19b2a46b70b52e51a0530703dc201958	1106682249	No	Fiber	10000	10000
ab3ddf2d552185a69af08ca27a6ef555	1106686034	No	Fiber	10000	10000
41baeb6a6e27de76aee99bfc8ed383	1112239102	No	Fiber	10000	10000
405056c1e51b3cec4fc51347cc8e2a1b	1111417557	No	Fiber	10000	10000
f4d5942a589236d1816b5749309d2734	1106681222	No	Fiber	10000	10000
c4ff0ab3c7f4505d74ca57040f25261e	1111405200	No	Fiber	10000	10000
f812e88ec5ab66385257a70a6875ed8b	1111420835	No	Fiber	10000	10000
08f20fa5a84746774766b99bcd93580a	1106687052	No	Fiber	10000	10000
924f9c625b400115bba020db95e5c8e2	1112259250	No	Fiber	10000	10000
39d2242f3613184d4b85ef21c34e8e17	1106682060	No	Fiber	10000	10000
0f1b7b185492939160a5da80b84b3957	1111413399	No	Fiber	10000	10000
8e12eca4166bc790ddc7102bf1fab8d0	1111413918	No	Fiber	10000	10000
59468c16f678af5ce45bfc4f85fdad6f	1106685202	No	Fiber	10000	10000
918b60d0b8352380a3aad3ba5a37b8b5	1089040153	No	Fiber	10000	10000
f9c3abf404d85ce0f102b96d64468a74	1106685515	No	Fiber	10000	10000
85ff25d74f589778eae7b5a6ac0f6330	1106683863	No	Fiber	10000	10000
b50432c7c44411d5239fc3d24cf08aa0	1111412032	No	Fiber	10000	10000
678f4e2bc977a948ef943302099ccdef	1111411317	No	Fiber	10000	10000
f3ac7c12d5359aa55c4fe23e6ea4df5d	1106682239	No	Fiber	10000	10000
72fcc5d343a25a7f088fd236cfe1c8a0	1089031951	No	Fiber	10000	10000
f72be728b9613a79b64a27da097b6687	1106679478	No	Fiber	10000	10000
de672b4caf9412af8930130063c40c18	1106683459	No	Fiber	10000	10000
c6add5d279d98f0947b0950f72b969d	1106685643	No	Fiber	10000	10000
2bd86ec5848397117554d50fe9b558fd	1111413231	No	Fiber	10000	10000
2550a37744a8460128309990fab20376	1106679805	No	Fiber	10000	10000
0502dcf97440c3bf8338018ac327b612	1106680924	No	Fiber	10000	10000
1f54d00b68f5202332ce0e383583ae32	1106681240	No	Fiber	10000	10000
d9d5d876ebe462dd63edd455574a9b56	1106686866	No	Fiber	10000	10000
8f6a2856daa9e88382dc57e2c2708434	1111414008	No	Fiber	10000	10000
b5427e34cc6140331e48c28c9c801bf2	1111424490	No	Fiber	10000	10000
6a26a64da8508c1ec132af57166057a7	1106680387	No	Fiber	10000	10000
e97c778cf78bfa891d6e03f0791684c8	1385050344	No	Fiber	10000	10000
498caa0e30c85c893a9576541bafa512	1106682094	No	Fiber	10000	10000
ab9f554ce80663c02af02488de848812	1106681198	No	Fiber	10000	10000
e57363d046cff151ffea7088449a5d7	1106680913	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
b06ac3af4c605d46fc8d368e9f7245a6	1106683729	No	Fiber	10000	10000
2d732dac22b827614aaf30321dfecf0c	1111404580	No	Fiber	10000	10000
1ab37f3552e394701e4938927f8dfa98	1106682954	No	Fiber	10000	10000
3e4338302665dde5536d3b992285d9fa	1111413422	No	Fiber	10000	10000
c4dee452653f434fd0af4459e43363e7	1112263700	No	Fiber	10000	10000
194e513c24949dd96c6185e8f24ab9e4	1286912995	No	Fiber	10000	10000
057146bba4aa41c4ebd160a6cf0af785	1106680689	No	Fiber	10000	10000
3a11466e8de9ba4dbc0c2ccee0a76520	1106686325	No	Fiber	10000	10000
c13ed5b41430d12fa1dbfbc882121f31	1106685183	No	Fiber	10000	10000
7f6177bd440360e3a513cba9512b4f4c	1286910922	No	Fiber	10000	10000
dfe2f2ee737b526521d4b886551f50bb	1106681794	No	Fiber	10000	10000
cd1fcc0b1eef6c4590f41ab563c9c6ca	1106686289	No	Fiber	10000	10000
6210e12b558ca38e5c4307e4f3966c4a	1106680001	No	Fiber	10000	10000
017120480d61698b25bf983654cb7e22	1286908271	No	Fiber	10000	10000
e40cbc2ea7dfd50af064091c4de4e0e4	1106691249	No	Fiber	10000	10000
a02adea43b4ef514eaccd80a4e3ba600	1106685753	No	Fiber	10000	10000
e7492f8c4b1d52e338ec54178231824d	1112237706	No	Fiber	10000	10000
e3b32ab2a2bf7b11c029ca7e2e1ca457	1089059204	No	Fiber	10000	10000
315ed399652d9b88a975cb3cb314aad5	1089032091	No	Fiber	10000	10000
38d650fdc61217fe01fa4c1ff51a5d8e	1111410351	No	Fiber	10000	10000
7ae3ee06b5f361d4721200dc3ec58c36	1106685460	No	Fiber	10000	10000
33f7332def697a4b98cd85c24cffb04d	1286910097	No	Fiber	10000	10000
b2d4f14b32d258e4043206e1556a8287	1286909446	No	Fiber	10000	10000
142b09c51e0c22f4e8e711abfaabdd8	1106683971	No	Fiber	10000	10000
bff4baebf971dde28a9131e6e07c1ad7	1111412548	No	Fiber	10000	10000
f528f46e41eb952169d38af85c31cca6	1106686203	No	Fiber	10000	10000
274c73819611828d7c679ecccdec924e	1111411490	No	Fiber	10000	10000
e9eae4934260a1eaea6088753a0bd9a2	1089059402	No	Fiber	10000	10000
7445198be04d1aa0b86f72a4caf0b1d9	1385048837	No	Fiber	10000	10000
5a12091a343de4f32430713f91f228b8	1106681725	No	Fiber	10000	10000
f908806fa664bd1da8a9a774dd6f46e4	1106680003	No	Fiber	10000	10000
bc6dbf91ed85c7e5f3a48e99c5c25336	1106683785	No	Fiber	10000	10000
b3a933f24a43f033d39abf5bbc333c22	1111406483	No	Fiber	10000	10000
abfc381a18e54831f37973adaf66ba2e	1089034405	No	Fiber	10000	10000
e21c54ff87396bba8345eb4fa52e1988	1106684932	No	Fiber	10000	10000
e3fd9343e7f0b1dda5259642751a2c0d	1106683154	No	Fiber	10000	10000
20f989f6d70c6ec7f82e6d1abca033fa	1106681821	No	Fiber	10000	10000
6f4f5c92c1161d33cc0ce40aee1921a2	1286909392	No	Fiber	10000	10000
8ff2e2026194f66cea526dc2cec3d638	1106681793	No	Fiber	10000	10000
4d0029606460caaad6fc6c01a69951a5	1089033531	No	Fiber	10000	10000
d8f39bed38351bf5d4d0d6f155816c3b	1106687066	No	Fiber	10000	10000
993e62effb7a133a5cc031e8090f05a0	1286911136	No	Fiber	10000	10000
4d2c687ffb5a0e242d801cfa15f7c86d	1106685141	No	Fiber	10000	10000
83f3f9678ae2ddad996d11321e7993fe	1106683034	No	Fiber	10000	10000
592e66f836c4c66bb32266bb20936e91	1089039765	No	Fiber	10000	10000
503a57f1624aa659acce6a6455b1a4769	1106684786	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
7dfe6db48ac488b56d894dabe05f3114	1089059323	No	Fiber	10000	10000
97f9fb0ed448d4bb7c1aa2439e8977ac	1089044886	No	Fiber	10000	10000
bbf809cf32078ec83017e22b78110112	1106685848	No	Fiber	10000	10000
697b91d78daf9487eb71be26431d3151	1089034243	No	Fiber	10000	10000
82f28fba1c34d3db182bb96679e070b4	1106686881	No	Fiber	10000	10000
4617a419be72aedc90eb285673ee7645	1106686008	No	Fiber	10000	10000
7984e94af67fac4ac6ca29f05ccfa08f	1286913444	No	Fiber	10000	10000
aba1cfa272362b443bf8b0e74f6fda2d	1112263657	No	Fiber	10000	10000
8d71ef276c9f0f2a106fa226a5566c60	1106681655	No	Fiber	10000	10000
c799722bd973d5a66d6d8173db8eb4f5	1089059184	No	Fiber	10000	10000
b40d8c52cb31443a6b969a69a78f1258	1384687826	No	Fiber	10000	10000
6ecf008d693ecdc43d40ee1e992255a7	1111413116	No	Fiber	10000	10000
036f49ccc18ef4d6e59e56ead225efeb	1089059198	No	Fiber	10000	10000
438df5e2326fb10c28407252a9d91ca2	1089059326	No	Fiber	10000	10000
43a863875f1a434b8680e82aabe0bac4	1106680733	No	Fiber	10000	10000
067f380e09c3be796ed151d1c57cf84c	1106683153	No	Fiber	10000	10000
ca94ce190ce58d7692084b7ee2fe9b2f	1106685492	No	Fiber	10000	10000
8ea4376deb4dd6c2e55d76932849b18c	1106682251	No	Fiber	10000	10000
96df13fd29c5d04448653fc72015490e	1112236588	No	Fiber	10000	10000
98ba2bea6611308f7e1848b97bc58f19	1089033527	No	Fiber	10000	10000
10bc3ffc14176476c795b98ff932ebd0	1413429267	No	Fiber	10000	10000
94f31b47bc81183681efb654c21ab819	1106684350	No	Fiber	10000	10000
9fe53975dc794b085cda2db792f79329	1106679446	No	Fiber	10000	10000
6c4143cc4ffed37edb4fa551f9dd2c06	1106685782	No	Fiber	10000	10000
ca8df994162102b2ecefe620f93844359	1106679707	No	Fiber	10000	10000
568ade93ffc2a3525a57360c5cdb963f	1089041411	No	Fiber	10000	10000
27c1a6b839c3e9e020a9e2066295cd8f	1089042183	No	Fiber	10000	10000
8598f47a3b639fec7c951b6be1d2f2c3	1089031236	No	Fiber	10000	10000
ce423066bb2ac0f0a2b661f6889ddbcbf	1286905097	No	Fiber	10000	10000
37740f0173bb3445a0c4e43e03e6a2e4	1111427382	No	Fiber	10000	10000
9e9392dce31495be4ff2e2b7ca05cf73	1106686083	No	Fiber	10000	10000
65d6b7bb7caa6e771daf48706a20c2a6	1112236595	No	Fiber	10000	10000
2b7285749c7e244c1e501767c9347493	1089040438	No	Fiber	10000	10000
d6f6c64c86338a806358207a9f790244	1286904970	No	Fiber	10000	10000
b1b0593134a497858744b8c143f45705	1106686946	No	Fiber	10000	10000
0490fd19ae39f77faef1a9ae863c28ea	1106686977	No	Fiber	10000	10000
b291d61ba0e4f174c26cbf067ba9d9d4	1106682678	No	Fiber	10000	10000
9b2532c8c18ed061ca02131bc229015e	1106684116	No	Fiber	10000	10000
a583df2c54b9ac19b65d0d6bdea322d0	1089034363	No	Fiber	10000	10000
1575a15a5055724e8e431630bca507e6	1111405911	No	Fiber	10000	10000
0c806f0fc7af6e9c12e9a4f1f37ba974	1106681584	No	Fiber	10000	10000
397115d996ab125fc337aac7bfacc702	1111412026	No	Fiber	10000	10000
274f91ee9bc4bdcd68bbc66a90f740a4	1111410355	No	Fiber	10000	10000
a13deee34d8b06151f7509ee4fb18696	1286905900	No	Fiber	10000	10000
cf2f024d5270940f2b5194c3894e38de	1106684394	No	Fiber	10000	10000
fbad259317d261ae86f3935732fbedf0	1106685748	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
6294dc2f49a110c839f2e5d8d60b2eed	1089059999	No	Fiber	10000	10000
2dc48a7e7d862279f393d4787710b0df	1106685278	No	Fiber	10000	10000
3f98c55e730d40c468620ba8bb6bf931	1106681559	No	Fiber	10000	10000
61e79068e4e84d6cf149decc670be6e2	1112257339	No	Fiber	10000	10000
f91de2ccdeb58a26e897e1b689e8f5b	1089059712	No	Fiber	10000	10000
8cfd42792f7a714faca825f1fd878aa9	1106683012	No	Fiber	10000	10000
4584c3ca65ec16b9dc4ba79c1e6a530b	1089042262	No	Fiber	10000	10000
f9ca3f31fb3388a568ad2d480886414c	1106685811	No	Fiber	10000	10000
c2a438a6b93637195d5b1aa2303bf238	1106684440	No	Fiber	10000	10000
36943020cc52b7bc9afd3af9717b2fa8	1106679903	No	Fiber	10000	10000
5a3e1aa80e8fdc650350dcc112ade952	1106681050	No	Fiber	10000	10000
f4cc352ca63481708db4eefe00ff1b89	1112253992	No	Fiber	10000	10000
6b8ebd309be277513153fa5fe26f2fc4	1112259025	No	Fiber	10000	10000
08b6444f8cfb04ed2f51fb3bf27136bf	1106685831	No	Fiber	10000	10000
2dd9a43251c2f9d69ef0b7ea3d7da5cc	1111420815	No	Fiber	10000	10000
a42db1d603da3f30514450cae6fa7e2c	1106680663	No	Fiber	10000	10000
702091d5fa4f92a6465fbed7a0b9d878	1286910645	No	Fiber	10000	10000
8a7e465a9b2aa912a174b501d1049f67	1286913928	No	Fiber	10000	10000
ee95689ef1c2ad2c9bfea70fc5e0808a	1106682388	No	Fiber	10000	10000
0fe218cb872a34ae89d07c0abe4ccc25	1106681561	No	Fiber	10000	10000
e31588811113c24a83e858c0546e6b18	1111404554	No	Fiber	10000	10000
977cb367fde43372d929b6ebb6751ba9	1286904607	No	Fiber	10000	10000
48664e27408714a444934d9e450447a1	1106685558	No	Fiber	10000	10000
6aa62f1914716dabaf7953186565fd6d	1112259233	No	Fiber	10000	10000
db81761eefc6a7a89fa4b87a9082f6d3	1106681704	No	Fiber	10000	10000
33997e36ff8acf7a37f767ddd99d02bc	1089034378	No	Fiber	10000	10000
309ee0aa0e5173aff8811e1a6e8b471	1286906011	No	Fiber	10000	10000
8ba916ceed16a52f56533bcb9aa0041c	1106685646	No	Fiber	10000	10000
b87b5e3ea42cdf5160500343005eb0fb	1106686612	No	Fiber	10000	10000
8f9c1219100ee6069f5128074f6e35fb	1089033534	No	Fiber	10000	10000
bdf45a07f425a0f327f25543cc019ad6	1286909610	No	Fiber	10000	10000
3c90214c47bed1383214b7ca629c6b3b	1106683433	No	Fiber	10000	10000
102f6a52cca7b68f6cdf31a2d323bfc7	1106681907	No	Fiber	10000	10000
3a05b1c9d2135d89068388510678984e	1106679345	No	Fiber	10000	10000
afb2b2d1e0c5b586cfb145b09e5f5c4f	1089059218	No	Fiber	10000	10000
7b806d6b56bceee09e37b064e66552e	1089042258	No	Fiber	10000	10000
116dc4c90e3e80dec821ab2aa7a8c7bb	1106684183	No	Fiber	10000	10000
335800cedfb6400e575862eff3ac2ade	1089057376	No	Fiber	10000	10000
58efe35bb82fd890e35aeebed8dbd747	1106686393	No	Fiber	10000	10000
70ab22c2e8ead5c5fa0c6b43d3420f61	1089042940	No	Fiber	10000	10000
b0c0c34c7a0967034d9285388773ecc9	1286911190	No	Fiber	10000	10000
efdfd62fda71062f06c0996b34b05de5	1106684636	No	Fiber	10000	10000
52e022fcd477e2f6a6543882ee384125	1106685119	No	Fiber	10000	10000
38bee38057f501566c135d5deacc30c1	1089039722	No	Fiber	10000	10000
d78a68550f3e78aaf29b18b51fbaa512	1106686306	No	Fiber	10000	10000
2efa5271fdadb3a16ca0a31eeced8a8e5	1106680568	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
87e5585eb51dbf2a8710786368d733ab	1111413195	No	Fiber	10000	10000
94022534f72b6c27e9232a5197b1f255	1106686645	No	Fiber	10000	10000
f2b5d1646d004745008bfa9db720a922	1451746176	No	Fiber	10000	10000
f365a6fce0071e4268b4bd17586d570a	1111413006	No	Fiber	10000	10000
d7fc25f3becd0e393cbea80e5db5d677	1106684864	No	Fiber	10000	10000
d4259ae3cf68cbb95f2827195ea6246a	1106684980	No	Fiber	10000	10000
e1caece033db65137b0d8db770465dd	1111413202	No	Fiber	10000	10000
2eea4bd6d38c883a851de612c98d7cc9	1111420816	No	Fiber	10000	10000
1cdba36268cb1ac9a7f5132beb969d70	1106686784	No	Fiber	10000	10000
487ea80aeec150da23712897e681bf6	1106682694	No	Fiber	10000	10000
94d3c962ce3da39aa7cc5f167c705815	1106684931	No	Fiber	10000	10000
aa05e72c213468bd0b269fb69bd62592	1286908597	No	Fiber	10000	10000
cd8a057c659cc4bf5bba8870cceff6496	1089033532	No	Fiber	10000	10000
368a489b0c7c1717c7b379b4294580e9	1111405887	No	Fiber	10000	10000
df4f97f1c576a7e17c02f8137dd5b775	1106686586	No	Fiber	10000	10000
36934cd5057897029260c7009353a0a8	1106683803	No	Fiber	10000	10000
863eee0057a536a96a79e7d2184cb75d	1106680730	No	Fiber	10000	10000
f8bde1939c94f7389770c7e7288e4fb0	1413421551	No	Fiber	10000	10000
ce5a5bd519422e92f9765cf89962468d	1106683757	No	Fiber	10000	10000
79b5151dd974aefd890572deb1e88f1e	1286918640	No	Fiber	10000	10000
81e2f9f57360d785abbd88a114e57ee3	1106682594	No	Fiber	10000	10000
94b19774fd08e8642318d9dd589c392c	1106686261	No	Fiber	10000	10000
3b045266d69f33530c6d448dab7ef6b9	1106683197	No	Fiber	10000	10000
e04ba41250157c6bc6935982ac940fb8	1106683148	No	Fiber	10000	10000
d8419e645785dd2e6aad073bbfb32c53	1089059321	No	Fiber	10000	10000
123a0c1563f175366e5a4a50d6033408	1112252676	No	Fiber	10000	10000
7ae1944f6f66f3620b015ee27d290354	1106681758	No	Fiber	10000	10000
11ca129d5455de59ac1f96aba521c842	1286911771	No	Fiber	10000	10000
006724d2b77d70fc306434261922e015	1089055535	No	Fiber	10000	10000
c919c39c4a191f5a0dd792ea6d8890de	1106684249	No	Fiber	10000	10000
d950aa2ebb6e9d03b8585215d9aa5aef	1286907773	No	Fiber	10000	10000
85dfc38a7f72b3a77203971214187302	1089034385	No	Fiber	10000	10000
36ab67eec65f820c9f64c291e9f69193	1106680774	No	Fiber	10000	10000
1a2904440ce01178bc5082e9adf39e1a	1286910950	No	Fiber	10000	10000
771d770462f16a09d9c4015e76127724	1029588209	No	Fiber	10000	10000
e682398a8deec381be20c387a934b682	1106686971	No	Fiber	10000	10000
11c915504c11bdcd4fb6b00cf2926c35	1106681275	No	Fiber	10000	10000
cde0a74b078b67a0c8bd86ad7c475d16	1106679650	No	Fiber	10000	10000
91177d92f25ee8e0d42bd9aee3c100f	1111411977	No	Fiber	10000	10000
40a0993f136f17b48194631343d13141	1106683226	No	Fiber	10000	10000
1f578fa5f3cdcd41d603c9b18f9bc0a0	1106683208	No	Fiber	10000	10000
678bd9c84ca355d9143f8ed530cce2c5	1111413082	No	Fiber	10000	10000
136419a80aea5abe2041010c9691cc9b	1112264035	No	Fiber	10000	10000
143a1fc0b2967708b85bea9df27db251	1111413446	No	Fiber	10000	10000
1715e5413565dddddfeee2fcca8f985f4	1106681706	No	Fiber	10000	10000
7b6532f06aee0533ea6c7a7d158374e7	1106683035	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
7296ec0b694247f756f7df0a36bed96e	1106679985	No	Fiber	10000	10000
6fd2d1995fff38f9d5643063a315a5e6	1286912400	No	Fiber	10000	10000
abe7547c6e75b21f6a73586562155bcd	1112237697	No	Fiber	10000	10000
9c4085a6b42c5ba693d78adf3f55e774	1106680063	No	Fiber	10000	10000
9ce8f9f23269bb443c312bf4e5a67c93	1106686901	No	Fiber	10000	10000
b3104344ed2fbdd401cee59a55a69316	1106679532	No	Fiber	10000	10000
0ed865af425936f208404eaba87db166	1106681756	No	Fiber	10000	10000
d86db4c29b52e392cd3e0208205d6960	1089055484	No	Fiber	10000	10000
5cfbd95481ab995232e55ff9e85ae4b8	1089056303	No	Fiber	10000	10000
2a40c364aff29f03648c80c49f92bc20	1111410347	No	Fiber	10000	10000
8bfa4dbb72d101fd8a6a9d7aaa1182d2	1106680148	No	Fiber	10000	10000
12d6fab9fcb3b452ae48a9af2218dc1	1089040433	No	Fiber	10000	10000
08613fa75b92d2ee657aa048151d5c78	1106683664	No	Fiber	10000	10000
3c4fdcc33f227b3b5820fa7d5bc34d4f	1384897904	No	Fiber	10000	10000
7aa0774431dab42335a9a161466fe244	1106680701	No	Fiber	10000	10000
43b96092c2bb101086e666db5c57750b	1089034327	No	Fiber	10000	10000
a3cf9f1c6e569d67814cc6f5b005fa8f	1106686437	No	Fiber	10000	10000
d60c0286bcdabd4bd79173ea8f3ea95d	1111406161	No	Fiber	10000	10000
2b8183828db269c20d71e10d02098059	1106686089	No	Fiber	10000	10000
ce21bf0e90a276c34da179dbb2b34574	1106679569	No	Fiber	10000	10000
aa9387487f32247cf4e3c137b9024a04	1106682741	No	Fiber	10000	10000
30da1114e5c8de0a58a4d531ab1e5e22	1106685510	No	Fiber	10000	10000
1cd60a70167ab81bf021a7ba1626e0e6	1112239092	No	Fiber	10000	10000
8bbe6199104c3387c3609ae0848ec119	1112236610	No	Fiber	10000	10000
b34ad6a1a183be515da346dac76f3c42	1384901433	No	Fiber	10000	10000
94b2ecbcbd21fe542db9b790db8c7573	1089055471	No	Fiber	10000	10000
fd17891a8189a3a247cf629a4fb93d42	1106680712	No	Fiber	10000	10000
19603b077d78f21d3cf5f569de612baf	1089034326	No	Fiber	10000	10000
cd4768dae320c44527476ed0c9f4b474	1106683103	No	Fiber	10000	10000
f72d087340b610da605e319c4510ae4d	1106684551	No	Fiber	10000	10000
6e283aa97a6fc4c3debdff0472b2f9709	1451746351	No	Fiber	10000	10000
29c7acf965a6a306c70f514f00b9a2e5	1112236593	No	Fiber	10000	10000
cb28057b55aa41d005c7d2f7fe1f5e56	1111410813	No	Fiber	10000	10000
9a9ac51188fc7a00d9190690c7d7d492	1384680077	No	Fiber	10000	10000
33af9006b55be99a0663db0885e20c7b	1286909977	No	Fiber	10000	10000
6ae0797fb28db7ee79185e4f3c0e2e3	1106684632	No	Fiber	10000	10000
ad091c29c891cb17899889602714b267	1111406334	No	Fiber	10000	10000
35f6cf2e58d7fe5262028be866ae9b94	1089040445	No	Fiber	10000	10000
61430914bc96cf26dcf4673c45a5ce8d	1106685878	No	Fiber	10000	10000
ee7c67a5edb11d574d9c2ccaa4777d5e	1286907789	No	Fiber	10000	10000
3b2d970f032cea1bfd2b107c7211d591	1089059497	No	Fiber	10000	10000
77668fa33e6b3894f47f95efc7d5838c	1089059422	No	Fiber	10000	10000
0632f47ea77dda45b539fdbec0c883ea8	1106683485	No	Fiber	10000	10000
9ce05265114bc48f6fa76a6ccf3b7d4e	1112236582	No	Fiber	10000	10000
914d03e230b5c8a5170a5b37070e37bf	1111411703	No	Fiber	10000	10000
d80230a027dae3405b0b9fbc4130420c	1106686358	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
31448096251f0ea350e8933d18d58004	1106682156	No	Fiber	10000	10000
1d7c69e50c578303d1fb7e16a696293a	1089042465	No	Fiber	10000	10000
17649b67c5a0a8bd0ba3efa49942d44d	1286910445	No	Fiber	10000	10000
bd21d457f39e66adc30a297f57253efc	1106684429	No	Fiber	10000	10000
51fabf56678a9ca586943cfd34802ed3	1106687226	No	Fiber	10000	10000
676029230bf2d4c9fcf15f17bdfd0869	1413421490	No	Fiber	10000	10000
6eea875621d55e83367468c53f15f5f4	1106679992	No	Fiber	10000	10000
57987ce967aacc5aeed674e99e83ab2	1106682884	No	Fiber	10000	10000
1257214eac0eca0bc20c85ea8964a7ca	1106682572	No	Fiber	10000	10000
f1cb64ad507a2278534a8043af322d66	1089039684	No	Fiber	10000	10000
f487d4db1060188605e74a63701033ce	1286913842	No	Fiber	10000	10000
20559236c4f0b8a145200f57d8e26a98	1286910631	No	Fiber	10000	10000
ac47f52b20ffc0f923465e2a3e1a88a3	1112248311	No	Fiber	10000	10000
be71ac5522767e990bc9d5ab00bfd597	1106681919	No	Fiber	10000	10000
ae9190c4af218c2b3ef631a81ed532c2	1106685873	No	Fiber	10000	10000
ef14c3af6e945768beb94b467f0f7340	1089034328	No	Fiber	10000	10000
0fb3d94fe1e18401df8b6666ef8d9373	1106680099	No	Fiber	10000	10000
f8ff4545acdf71847077a0be4e1f3a86	1089042172	No	Fiber	10000	10000
3e9560ad1f7a457e8b243c41de1e8c03	1089060005	No	Fiber	10000	10000
bb73f114178148f01a5e0f583acc0eef	1111406340	No	Fiber	10000	10000
d417eebcd31fd3d01aed9b0cfa1f964d	1286913654	No	Fiber	10000	10000
f7cd4779f7ceadae5db22503c95ccd1c	1106681250	No	Fiber	10000	10000
7088bbec8c574fa850d630c79d2df28c	1106686235	No	Fiber	10000	10000
f9a5e758635124e44ea3377134b2c1f6	1106685142	No	Fiber	10000	10000
70fcf7000dde3d462e0ee518a0b65e71	1112257347	No	Fiber	10000	10000
518bc985282847217fa7e4828a3124e9	1111411487	No	Fiber	10000	10000
cb5dcbdcdee5116b87df5a8fb4668b46	1106683173	No	Fiber	10000	10000
6e79cc24e67ffd508f39cac17aa3598e	1111405151	No	Fiber	10000	10000
80a13ea61cdef2240bc5a22115bca463	1089059317	No	Fiber	10000	10000
1245962c91266b28ee7ccef4f768a62c	1111411962	No	Fiber	10000	10000
fd8524eebb2318fc7d284f5fcb600ab9	1111411491	No	Fiber	10000	10000
10b17c792a7998bb694ce21dac51ccef	1384900922	No	Fiber	10000	10000
fbcab6428ea0b61eb72f27bbaa098735	1111414783	No	Fiber	10000	10000
48b55b3a0e67d17ac55ddd4fbb46a90	1286917806	No	Fiber	10000	10000
6bfb5559688b8836b1105145596b744f	1106682603	No	Fiber	10000	10000
a50065502524ae368f553a7736e7c72b	1106681356	No	Fiber	10000	10000
9ad8c3a245184036300038eb92590dfb	1106685514	No	Fiber	10000	10000
dbe35ccac9381ab8f298d92a4a49439e	1106684423	No	Fiber	10000	10000
6bd2332129b48e10660188d0c2312873	1106680548	No	Fiber	10000	10000
96200535ca9a926d342be316f77869e9	1106683426	No	Fiber	10000	10000
cbab33184b704fd86ecea773fd2d9fb25	1106684841	No	Fiber	10000	10000
6028f48882b9c2fbb9c7a21606541144	1111409929	No	Fiber	10000	10000
d1c8dbfbd7d24e5eb7c74b8de3e2647	1111405267	No	Fiber	10000	10000
af2f85d2b0448a0840034a6f687a2789	1106686315	No	Fiber	10000	10000
1af998db4b54105f56683b5bb93deba6	1106686724	No	Fiber	10000	10000
ed29185919c5abf398052c40888ed380	1106686001	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
80e0290b4351324d2ef771e53c9c74bf	1286907534	No	Fiber	10000	10000
d3d60cb02ae602e400da069330df6ed8	1413421561	No	Fiber	10000	10000
ad4fc85bcb93baca8eda6482f7c736f6	1286907576	No	Fiber	10000	10000
5493746b8ca0d74 added02bfc2c55dbca5	1106683774	No	Fiber	10000	10000
366b3e42c59dd433e5cfb4a66d6a1867	1106679754	No	Fiber	10000	10000
1e99e9ff0ef7ea426433534633d6d781	1089059096	No	Fiber	10000	10000
0a937114f9d813e6cab06d47b7d9ba45	1106683877	No	Fiber	10000	10000
b30a2d8131a59d8aade459254cfab422	1106681457	No	Fiber	10000	10000
b5afce4cd82990e7716675e18d8a05b7	1106685172	No	Fiber	10000	10000
6ae0fb0387fa341c875b6fd86a629971	1089056295	No	Fiber	10000	10000
0432d02a7981e06f1a97b94de7d91c8e	1286904652	No	Fiber	10000	10000
d636d9d8b679c060f8ce4ab7ec19c707	1106682668	No	Fiber	10000	10000
4cf004cd4f01d9083b72ba4a2b1b8eaa	1089059984	No	Fiber	10000	10000
abc96d70195882b239e2683ecb22a577	1111405886	No	Fiber	10000	10000
b101545ce6053454163188a051be8173	1106680650	No	Fiber	10000	10000
61e176adfa6105dfc63598821d39ef55	1384901515	No	Fiber	10000	10000
acd1685405bc400e1e67fb3fa016c9e4	1106684405	No	Fiber	10000	10000
1693ab5dbd414d7a5c65e75fb65add26	1286904456	No	Fiber	10000	10000
e7b76537528ac008622afd2e4c432a4f	1106686582	No	Fiber	10000	10000
1a96bdb96a064dc82da2e6e7016af133	1089031234	No	Fiber	10000	10000
32ae641959e17c8e6fa86a81087f4f5e	1111411493	No	Fiber	10000	10000
e2886ccab2008425676116a73c7c6829	1413429252	No	Fiber	10000	10000
147870575cd3f2c0b29916edfc27138c	1106681451	No	Fiber	10000	10000
c8b552f6df39f5b30dca6fdf83268847	1112239112	No	Fiber	10000	10000
aba0c7a00623153ce0f9353c3ad7218e	1106685325	No	Fiber	10000	10000
ba470fb1b82e9e92b9e29321139a49c8	1111413278	No	Fiber	10000	10000
9d55c8155ca5511442a0d94f3ba2b28e	1111406012	No	Fiber	10000	10000
2f473ff1fc8ee46911fb70634d1b47f5	1089034785	No	Fiber	10000	10000
b1c5aa9dcd0f7c9a0f3b6fb0d9b98ce8	1111413047	No	Fiber	10000	10000
01de81dfbc290994d8952aea3ec0560f	1089059715	No	Fiber	10000	10000
20337554867e72e864e051efa4d95c43	1106687170	No	Fiber	10000	10000
eeb1ebd63299143092053e07d5a24995	1286908607	No	Fiber	10000	10000
8e5c550381556036b5ef39240cc81d2b	1106682880	No	Fiber	10000	10000
e77480ebac1bc1b64b8e15e10f8c7f92	1089059199	No	Fiber	10000	10000
b5e608d49e9b1939e4b9b90284fbd9ef	1106683887	No	Fiber	10000	10000
7d629ccc36fa9fb128f47bd5a8d0078a	1111413987	No	Fiber	10000	10000
fb40f8d1f9e24666f97739856bd260bb	1106680737	No	Fiber	10000	10000
9edc6188f3ee2bc04eb5a05184b86c4b	1106683566	No	Fiber	10000	10000
8a9b8d61c71eed971067ff31cad8d98c	1106681574	No	Fiber	10000	10000
22322375c7a8bd0338370749922f5ed6	1111405275	No	Fiber	10000	10000
903cf5609e3e37d85822076847ac6109	1111413866	No	Fiber	10000	10000
75cf6756d194ad115ac84ed9890f18c0	1112264013	No	Fiber	10000	10000
aaa2e3df8d428a0cb6c11f4f13b5b31b	1106680716	No	Fiber	10000	10000
59c179a5888cfac9bb369b36ad8f0612	1106684138	No	Fiber	10000	10000
a03623faba2309a4e8bee555fe7f0a84	1106682364	No	Fiber	10000	10000
289a178dc65019b9cff124a50bcc72ff	1106685988	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
4a25d2804ebf37389cbdcfa0783c9c8	1286908390	No	Fiber	10000	10000
635f696ac094355fc0b504bd01005ffc	1106681371	No	Fiber	10000	10000
c2729c2ceebf84f02597ac0f83a00b03	1111414007	No	Fiber	10000	10000
59a36d73ffb2685efaf35c98998caaae	1106685163	No	Fiber	10000	10000
b6a6536d28e50bf73e263a10c874fa33	1106684508	No	Fiber	10000	10000
0f06a004fd4d880b4a4ce532a8140ba1	1106682679	No	Fiber	10000	10000
e125c0c076ed116c161047e7f2962ac5	1106679466	No	Fiber	10000	10000
b8ab2a4e037a0dabf05d871edb5d2b84	1111406346	No	Fiber	10000	10000
b28d5a65d1cac261647fdf065fb12a9f	1106680732	No	Fiber	10000	10000
3ca1950d7370cd2a75da55287d749656	1106686321	No	Fiber	10000	10000
41a82bd7d0e7ba9fbff5a23d06d745f3	1106681898	No	Fiber	10000	10000
926ccd9a34e02124aca4013c7ad81e80	1112237695	No	Fiber	10000	10000
922e0c7cfb3f96b737d9f6f1654dac0b	1106683481	No	Fiber	10000	10000
6ecc7de84507813457c14d62b556cc03	1106680367	No	Fiber	10000	10000
a128c43321d78fdfe3469ca6c6c493a	1089040455	No	Fiber	10000	10000
c17542308498188fbc5375e0a1bc4f74	1106679852	No	Fiber	10000	10000
8cc750fdb6953b54ef86dcfb2dbbd1ac	1112236591	No	Fiber	10000	10000
7d3f1916368daeda5dbcf8e2495115cb	1111420847	No	Fiber	10000	10000
bffb75bf987b54ad87b4304e2e19ff8f	1286909900	No	Fiber	10000	10000
22e5cd7e61fb10565384ce66483ec154	1106679684	No	Fiber	10000	10000
cdc02ec3a368f5a0b8aa3ce606bb4de0	1413421449	No	Fiber	10000	10000
255e4900702a7fa15fad446218a1fd2e	1106680976	No	Fiber	10000	10000
397bcd563fb9409a0f6c648aa2bf2f60	1106681490	No	Fiber	10000	10000
fa3e8d245035b8b94a928bee8f1fc55e	1106679815	No	Fiber	10000	10000
3cb40d03ff86200b0e7e6ad623b274bf	1089039716	No	Fiber	10000	10000
6eca821315d55498ed700922671d362b	1106683137	No	Fiber	10000	10000
5ba392211284283ad02e978e94f905c2	1106680720	No	Fiber	10000	10000
4a952c46682fbd28e47baaf971b7df4c	1106685333	No	Fiber	10000	10000
7dbcd70a082147ae8afa31321cb29b9c	1286909295	No	Fiber	10000	10000
16c408fb75f7d0cdb7f9d19f1a9a7b57	1106683454	No	Fiber	10000	10000
c92f337cc1c14eee83a2c2899abaa4df	1089042274	No	Fiber	10000	10000
3ae1a5d728c7add98ecaacf521c0578c	1089034325	No	Fiber	10000	10000
6a418c0db3295c239e8390847a26329e	1089059342	No	Fiber	10000	10000
3967c1a206e3c4bcbd3b6547bbdc41f4	1106684504	No	Fiber	10000	10000
e59767b6abf900edf59c8551145c0f5f	1112239097	No	Fiber	10000	10000
bb1628858ae542f9ff16ad389c5e8606	1286909141	No	Fiber	10000	10000
fb7e30c0826219d3c838b1f6cc13c79e	1106686429	No	Fiber	10000	10000
f6c8a88714c44f3c4d9aa6fb2a0ce1cc	1089056296	No	Fiber	10000	10000
61c2df8359fca80cabe40858bd1e60a1	1111414609	No	Fiber	10000	10000
9dd58a2b0df78b214539a1599ed7d0ee	1286907630	No	Fiber	10000	10000
5ffce213706a43fca59700e71e6e8983	1286918466	No	Fiber	10000	10000
8298a44e70c4f584b91b9ca656b087fe	1106680101	No	Fiber	10000	10000
497d02168680076f8f7bb7f99f972191	1111405175	No	Fiber	10000	10000
9dd170d8d1d93d1e7c777eb4928849b9	1106680727	No	Fiber	10000	10000
0ab0ad8c10d59e909989a93e4159b090	1106681769	No	Fiber	10000	10000
a3273db5d0a576becf3aae41bd016fdf	1112225508	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
0d99d77e72bf450f4f80c25161ecf0a7	1111405165	No	Fiber	10000	10000
9f536a5229222c3bca727298ab83ae04	1286906013	No	Fiber	10000	10000
12349f96517b22892b6944b7ac1c4786	1089055475	No	Fiber	10000	10000
9df5367eb78597691baaf6b54524d3dd	1106680278	No	Fiber	10000	10000
7f96d8a23c2071bf360d79e451fd2757	1089034563	No	Fiber	10000	10000
b199aa2fdd02bf3ff79a50eb6d7a788b	1106686147	No	Fiber	10000	10000
50c4624571ec5e98b5b2e4d8ebe4d629	1089059398	No	Fiber	10000	10000
c060d01e5ce1194922d8043c5ab58611	1112236592	No	Fiber	10000	10000
4c45c0d90a2dbdcca3ba4fdc197faf3	1111409910	No	Fiber	10000	10000
d8708c4d41a7d1752700d176daac6ce0	1111412508	No	Fiber	10000	10000
fff37766e92e06fe5d1545c703a799bc	1106682953	No	Fiber	10000	10000
597844dbc54aaa2b59c773fec7953fc8	1089060073	No	Fiber	10000	10000
d63781bf417ac192bf23528612e72c33	1111406236	No	Fiber	10000	10000
dcfa97e16986a7220c028a9400410e59	1106683135	No	Fiber	10000	10000
09f4a0780d9d799ec0a479ebbbd77ecc	1106680435	No	Fiber	10000	10000
9031666256053c5c428957193062bc98	1112248300	No	Fiber	10000	10000
ce08a816aa29bdcf2d9660d2704a8fd4	1286910306	No	Fiber	10000	10000
8727d90911683521b815fe84389f8b17	1106684524	No	Fiber	10000	10000
5cf842fb9cb2a04c8df7348b5c04c3fe	1106687086	No	Fiber	10000	10000
1fd17762780f227f4c80b3ad5a3dbaf0	1111406336	No	Fiber	10000	10000
7526cc5f7ee7d2c294bb0ea0446884cb	1089059509	No	Fiber	10000	10000
cb169930ae6b2572bfa94eb4a98b0998	1106685442	No	Fiber	10000	10000
c7adb670f4bfdfc328d1563c5c179d46	1111413361	No	Fiber	10000	10000
f51bf416ea256c053f01f3cce955208b	1112258998	No	Fiber	10000	10000
25cee4ca00cc96afcad008fa8d206e2c	1112257358	No	Fiber	10000	10000
8aea49b76735f2866de47538aa3535af	1286908424	No	Fiber	10000	10000
bb979120036d082312b958ce5158890a	1106681899	No	Fiber	10000	10000
df6e8ee35a1b5d9d361d62f954cb5323	1106690772	No	Fiber	10000	10000
a3fa77a0aea03d127940b8527531d081	1106680598	No	Fiber	10000	10000
d6dc5e6012b418073f40f34933abe583	1286912607	No	Fiber	10000	10000
e4cf011e01d74fe6718c11bd252aef9c	1111404579	No	Fiber	10000	10000
2afea59c83b9b0c6b304221c423fe96c	1106686454	No	Fiber	10000	10000
8c6d57380b84ff386d214441625585c1	1106679576	No	Fiber	10000	10000
bdd9f09342f5dab2f55fdc5dc984cb54	1286905051	No	Fiber	10000	10000
051ef3d0285c40e6ec93bb0b28b71622	1286905394	No	Fiber	10000	10000
8d493288a9931a20c9891bdc8cc7a30f	1286907144	No	Fiber	10000	10000
b2ac10bf564fc7b182fd84263443e3c3	1106679848	No	Fiber	10000	10000
657e894cd9435892896714ddc526f9af	1089039712	No	Fiber	10000	10000
c641740723c7b2d103953eb1d362ab98	1111414786	No	Fiber	10000	10000
bee0ffbe8b2d103fd80e93a9694eaf3b	1106686888	No	Fiber	10000	10000
87e62b4bad9015c2ce896c63106ad166	1089034381	No	Fiber	10000	10000
ec5e37786c2f511303552f6094b9370e	1106683534	No	Fiber	10000	10000
5c15185fcca482354d9f7a29eb6a9e56	1111414003	No	Fiber	10000	10000
e175e2ffbedb450e0606e9b046599d5b	1106685018	No	Fiber	10000	10000
d91b1cd50524059a42a2de25fdebfd2c	1106679365	No	Fiber	10000	10000
5b91101e9df043ea52cce3d2bd842432	1106683399	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
1d37dc03e29e928162d9076d45317335	1106679737	No	Fiber	10000	10000
ace73a36f5f38a593db291c976027abd	1106687201	No	Fiber	10000	10000
5786c1a28088f30945cd907233bd4d91	1111427339	No	Fiber	10000	10000
c0d43fb0f10c53011683de0c22766f6f	1106683181	No	Fiber	10000	10000
7ab9873fd4d38ae656cf1e080c8d30f4	1089031618	No	Fiber	10000	10000
3adb36183796b07890d6ec5ccf821e49	1286909650	No	Fiber	10000	10000
9bd794bf1a9aa936dcdcf57e99029310b	1111411969	No	Fiber	10000	10000
e64dfa3b8ec3328f49167907d5164adc	1111409941	No	Fiber	10000	10000
c85db650561b268db1cc5981e9b12c32	1286904422	No	Fiber	10000	10000
fe4267c8cc625b2f5200ee5aa4afc348	1106683587	No	Fiber	10000	10000
e30540ee26db922f1b985d2ee6c36d6f	1089031631	No	Fiber	10000	10000
bdbca568d8fff6795c15eb8df818d383	1112239107	No	Fiber	10000	10000
5132b4bd66cbc2b192e958981fad5bd0	1089034557	No	Fiber	10000	10000
0c93686e1d3389d4d5cfc4fb40154b0c	1089059850	No	Fiber	10000	10000
047a65cb38e629be7c476c20b779f2b9	1089059227	No	Fiber	10000	10000
e2983545ca9e8854387c27f7664a640a	1106691113	No	Fiber	10000	10000
02cd1a8898e63a66fd87da6ad0980e34	1106684381	No	Fiber	10000	10000
ee6be5f682dbd28382cf2818ba4fa8cb	1106687173	No	Fiber	10000	10000
fe00638e88b9df6d7e9123ec6b6dcc35	1106687000	No	Fiber	10000	10000
608e13985af29255eab0ec7227dc5b58	1106679382	No	Fiber	10000	10000
bfd7d01ad2a0df5414d8d4e45facdac	1112264018	No	Fiber	10000	10000
2e3f85bbb908c29e9a8abc48a84e2982	1106684952	No	Fiber	10000	10000
8c023190647c6c5690e6893f03734a8f	1111417555	No	Fiber	10000	10000
a293d60de59fb004f166e49d26d6b3be	1106682448	No	Fiber	10000	10000
df4ee08e2ad6cfe4e9e02bb73447f970	1106686257	No	Fiber	10000	10000
fd4cf42c261ce63b49676e45398b26b4	1106679795	No	Fiber	10000	10000
f4b1945ba89b733ee39d555462fe6360	1111404578	No	Fiber	10000	10000
60fac8bcfb09cf2fff17401ebc4ad958	1089032093	No	Fiber	10000	10000
0764399e594f1de555a18f43f7ade2a5	1106685004	No	Fiber	10000	10000
b0af3215358a58da18bab542e8b41b88	1111413221	No	Fiber	10000	10000
eea1c91a847da8ef8fc3cc012e959972	1112255147	No	Fiber	10000	10000
7b40b13f42aa0ccf1b82f4b6fdc06c6c	1106684054	No	Fiber	10000	10000
1b961c1508f730cbcd9db46c81c3b267	1089055463	No	Fiber	10000	10000
5cc7c1a6fbb1bc7d97cc933ee89513f0	1089059998	No	Fiber	10000	10000
1599190513a3d393f0d2735ad71f5c27	1111405604	No	Fiber	10000	10000
6e8472e3de8cb472d4714e6e60a77e9d	1112248303	No	Fiber	10000	10000
4b07c6e521c788bceb15954920cb559c	1286909006	No	Fiber	10000	10000
72ca4873627249d1788a7aead5418fde	1089041403	No	Fiber	10000	10000
19bb5125120c34202fed74a867e206cd	1106691246	No	Fiber	10000	10000
b19ac04aee7e407e466e5c7d8ef53fe9	1111412028	No	Fiber	10000	10000
0b10ba05f37d1b280c4264b008ade5dc	1106680321	No	Fiber	10000	10000
a25d6d56e4f1c6dbd939b61ea0923c9e	1111413020	No	Fiber	10000	10000
ad3871356de05bf5c4e3a48831771e41	1106681300	No	Fiber	10000	10000
09fb28a150749b96a0cb2ba372cd89e0	1089057377	No	Fiber	10000	10000
ce426d756ba5918c02267944fec7113e	1111412705	No	Fiber	10000	10000
4a479be566497d71901b805e47f129dc	1089043156	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
b055f6c7c9e2af3f98df73f93bde248	1106686984	No	Fiber	10000	10000
5d63ee20f6d777bf8fbacca89a944ee9	1106679616	No	Fiber	10000	10000
0db5e9b95612746781e49401217ce3bb	1106681497	No	Fiber	10000	10000
7b7917ef86607b5dfb879eb1a3ff1e0f	1286908609	No	Fiber	10000	10000
c28506a36d69da29a5a1cd40b33ecd1d	1106682542	No	Fiber	10000	10000
bf2b6477b023fef95a7921033fff6795	1106679547	No	Fiber	10000	10000
6ab4e0d4c93e36bce7fdfbf86322ee68	1111412223	No	Fiber	10000	10000
3aab61436472c230fb90d7fec0319a13	1106681699	No	Fiber	10000	10000
66325bb09bb3c7cd082357df281fb80b	1106686756	No	Fiber	10000	10000
6814fb55131e697cdf39bcf96bf1f21	1106679959	No	Fiber	10000	10000
861c83ed8939dbdf30d7380fd27dde8b	1286912740	No	Fiber	10000	10000
a9164a583fbaad4d46e88379fec3e96b	1106680160	No	Fiber	10000	10000
268569d8475713c664707556feea95dc	1106681388	No	Fiber	10000	10000
bd7a206a39bf2375662e7b08aad9dd00	1286910270	No	Fiber	10000	10000
6f0cbb64cef67d232675bebc1488637	1286914443	No	Fiber	10000	10000
0991c0e7477fa90e6c524af4383dad88	1089055467	No	Fiber	10000	10000
953854de9ae288e4808e61743bec8aef	1111413220	No	Fiber	10000	10000
cabbfecfa6745e3b36d3e0a47301f561	1089032443	No	Fiber	10000	10000
7232e14a4a8fba89d7da5888fa01758	1112264030	No	Fiber	10000	10000
f3e8b5420b484bc9865f992c7c478b24	1106685578	No	Fiber	10000	10000
fb26c34d44b31873c9a5cf991cf6387d	1286904680	No	Fiber	10000	10000
be175aa3d2110c793f716f1f2ea84a6e	1111405250	No	Fiber	10000	10000
0e81732dc1e56dff004f5e58c9c3682	1089040441	No	Fiber	10000	10000
2914dfe40071cb87d00e5721c0559b66	1286914693	No	Fiber	10000	10000
df509e931fb3584374c832fb4273c7dd	1106679736	No	Fiber	10000	10000
96fd6589a750fe0d4dc22cd586202577	1089060007	No	Fiber	10000	10000
e5d4042584f0874842f665e1bd0fde17	1089042938	No	Fiber	10000	10000
770707c6f65e0bcc93255d2dc1d1a07c	1106680473	No	Fiber	10000	10000
dc016d662a424c5196c5538c7370d54b	1112239083	No	Fiber	10000	10000
a3ac2180f8a3cdc6ec455833a6758763	1089059857	No	Fiber	10000	10000
8528f3f08a1df9ef0676ecd426da240	1106681215	No	Fiber	10000	10000
11475f33224a3b6fe15ed6e475b93bb3	1106682844	No	Fiber	10000	10000
3a03ed65aa2fc51eba53dad2d3814005	1106685854	No	Fiber	10000	10000
28018d7ee93dffeaab57f9e387755db	1111412703	No	Fiber	10000	10000
1833ba5a53b1cee18f81afd5bde351de	1106684575	No	Fiber	10000	10000
5e9d61c4f556cee0456d1ef3f37c8bd5	1384898283	No	Fiber	10000	10000
29a52d11b28cad9a6590f390ac3b77f2	1106686479	No	Fiber	10000	10000
def06421f1aab3fa92e74461d185ac1d	1286911377	No	Fiber	10000	10000
fee802bcea704066e1e6df2d8bd011ef	1286913320	No	Fiber	10000	10000
ad5df140b3f03cda73972f37bc664c97	1286911227	No	Fiber	10000	10000
a60c16c1e6415ddcb6cc8deb653a425e	1089039694	No	Fiber	10000	10000
1bd49569e7fc659bfa04e88127d3b453	1111405185	No	Fiber	10000	10000
e9b447e4c224c66adc779b0a197010f9	1106679904	No	Fiber	10000	10000
0548eed1fc554c49c80394546e26673a	1106684894	No	Fiber	10000	10000
9071e8b5de275fbb68fb12021e689cfb	1106687074	No	Fiber	10000	10000
cf0d3e3f71c6ac1bc984f9ad027b9808	1286912331	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
d93df15bba7a055cc3fdda394b7fc72c	1106684735	No	Fiber	10000	10000
3467c71c5df5e3ce631898a867073ef8	1313751588	No	Fiber	10000	10000
c57ecf311b7b8427be7e4b874424a99a	1089034314	No	Fiber	10000	10000
86af8e6f7557e93d5d7c43719b9262d7	1089057375	No	Fiber	10000	10000
c3aef6a6c66765ee84cc5ac14a79efbe	1089034555	No	Fiber	10000	10000
80b0712f6db57eb9dd1c32576aa96668	1106681020	No	Fiber	10000	10000
6c666fcaa545fb74a04de40a98e41c0b	1111405561	No	Fiber	10000	10000
33c9947ffe54e56c29bf23dcfc7cc1dc	1111413338	No	Fiber	10000	10000
0ae3a5fe83b3b434905edfd2804265f7	1106682248	No	Fiber	10000	10000
3e8fd774c01d59d19371af3d7ec76cb0	1286909786	No	Fiber	10000	10000
f33b3e0da35dce1433dad3c9eadda8c5	1089056297	No	Fiber	10000	10000
b89f01d81f271c994217a84cb9ba0f72	1106685281	No	Fiber	10000	10000
bef4951ad71e9c1eceabbedbe0c3f8f4	1286909387	No	Fiber	10000	10000
cf28fed6bb7080c3dc08bef87c88ca03	1111414563	No	Fiber	10000	10000
1cb53803c6a6ef289360f4969ef4efe3	1089057373	No	Fiber	10000	10000
724931e41abb2d08b1ce2c00b059f66e	1106684493	No	Fiber	10000	10000
774545674b2da23906d7b111061b8da2	1111413904	No	Fiber	10000	10000
820a5005a99f59b1a90dccb07febb45b	1106683216	No	Fiber	10000	10000
b89735f7f5dc93527e7b230121336c23	1111412042	No	Fiber	10000	10000
ff0d42e055698173c4273fccff114904	1111404787	No	Fiber	10000	10000
e6c38bd74df7cd54f782566c165b66e9	1106686371	No	Fiber	10000	10000
675588c7586446e8c64b59718e8cd0a9	1286912860	No	Fiber	10000	10000
c492762bf6b52ba4aab6bf39a2c188ee	1106679766	No	Fiber	10000	10000
3bf5b69fa5d11842b0dbd1f4e8398667	1089039693	No	Fiber	10000	10000
048dcb1dc556384f36691e26d02a1571	1111413119	No	Fiber	10000	10000
72c11aefe61f8e50586fbcfd20007215	1106682684	No	Fiber	10000	10000
655a7cc14e2d4d1e3af451067ac5bfd7	1106681071	No	Fiber	10000	10000
b954f271490aa83649d4a917671a143f	1111410348	No	Fiber	10000	10000
a0f5aaf51502611faac51b368fe388ca	1111413201	No	Fiber	10000	10000
e930f32c693177b553c8714d4e2dfd56	1112253233	No	Fiber	10000	10000
c64b7e20d85d973e4e954255391e772e	1106682648	No	Fiber	10000	10000
10adc783a66fcdca9fd48f31565ab40	1089039723	No	Fiber	10000	10000
bfe854d561b398dae8a91c92715decf2	1106687148	No	Fiber	10000	10000
0dbeeb1866189ba6dc783ecbc85581d9	1111404907	No	Fiber	10000	10000
e181ccf646a2e3247c1697dca68126f6	1111409921	No	Fiber	10000	10000
15c25de692b79b31aabbed6dc8f096b1	1111412791	No	Fiber	10000	10000
1ae9655f3426973617471c36a1543cc4	1106682203	No	Fiber	10000	10000
06ce2245e5199edfd16a8c6878e78725	1111412035	No	Fiber	10000	10000
2e3bc45995ce734e15b8731e95ee51db	1106684606	No	Fiber	10000	10000
b57040a5a027d3b890e22d46355ef874	1112236586	No	Fiber	10000	10000
1fa5088a51ec996be3da5ce0fb94e6f1	1106680184	No	Fiber	10000	10000
7ff9d540182e4f4cedd65db0d5b3bcd	1106686035	No	Fiber	10000	10000
e89267bd73c0a2ca8a5d7e2dd89c28da	1106685867	No	Fiber	10000	10000
d7dca7ccf9013dc37e08faa86627f79e	1413411257	No	Fiber	10000	10000
c2c91c8ac26a9ae275ea403255a818cc	1106680206	No	Fiber	10000	10000
8bdaaca6e1a357b24446d2711675ec43	1106684098	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
30da41cddc109eac7486cff5fb0ea132	1089032444	No	Fiber	10000	10000
beb42225f4e05d98c68bbe1d618c5cc	1106681735	No	Fiber	10000	10000
19eb9f7112f5d6b5f016fc74b120f429	1106683057	No	Fiber	10000	10000
09d3ba53eccceb4b91f0ecb5f51093e0	1286913522	No	Fiber	10000	10000
5f7a10131548deead557eede2b30fb45	1112264017	No	Fiber	10000	10000
e64d9a5bd0836c2bed832eb4a9d136c2	1384991491	No	Fiber	10000	10000
d8b1eee67bf8c27ac2debbdda37c04e	1286904468	No	Fiber	10000	10000
12260e8d443bad5a33678165d27ff21d	1089034450	No	Fiber	10000	10000
4ddbc09409731c85ce92ed240ba9ef45	1111404917	No	Fiber	10000	10000
08c2be49b6a9a2a27939ce6c54f7fec1	1111406181	No	Fiber	10000	10000
c5068a29cca00d30da745d1e717a19ac	1111413200	No	Fiber	10000	10000
fc096acee7370388cee1ab48b1abb87e	1111404537	No	Fiber	10000	10000
388cd67b424d486b768bfef613cc1d99	1106680865	No	Fiber	10000	10000
62ef19673bb58924867b1c909b157d33	1111413277	No	Fiber	10000	10000
7f31fe956c69fdab20f57186ab287125	1106686913	No	Fiber	10000	10000
77dc1133af33c8220e48cd805fbb68f1	1111409943	No	Fiber	10000	10000
2baf69fef3f258b83def1d44118d0fc8	1089039759	No	Fiber	10000	10000
24dde64de3510c6d213f381a85acbf26	1286917817	No	Fiber	10000	10000
f44a88d1aec6464bf2f5c8d5dfa677b	1106682992	No	Fiber	10000	10000
2a0d00fc373694b980fe2b5b516083de	1106682136	No	Fiber	10000	10000
77da56dc8957f421ad89ffe249ea3272	1106681453	No	Fiber	10000	10000
2b2998fea22eac026a8805eabfb4a835	1286914140	No	Fiber	10000	10000
f910c944f71ea12ce680eb9723121c4d	1111411349	No	Fiber	10000	10000
082e59fc68619a24d15d897bc5ebf2e4	1106682987	No	Fiber	10000	10000
ca79d2a651d0aa85dce1d4a9cddd08b3	1286908896	No	Fiber	10000	10000
e0df84819be44fca015495b5aabd899e	1106683443	No	Fiber	10000	10000
bfb991b8c9e45bacf8f6182470eb4997	1286910729	No	Fiber	10000	10000
18c6b2c17f50ba0faff9ee0b8d439429	1106682408	No	Fiber	10000	10000
fef1684f17007937e476b10a71061b7c	1286907707	No	Fiber	10000	10000
4a5160f0042429c57c598ac5cdaa6d5c	1106685366	No	Fiber	10000	10000
228732671e5bb9a8a54ce59f03e10418	1111412047	No	Fiber	10000	10000
0a556c879fddb53a5be20507fae4b075	1106683885	No	Fiber	10000	10000
bf248766420e5d21e05ae2e1d2efa52d	1089043845	No	Fiber	10000	10000
54dc9253e474f4773155ef2e1d21a967	1089033528	No	Fiber	10000	10000
ee7a839d406d29b2f42a8262d9180038	1106683699	No	Fiber	10000	10000
075804bb701e02a1007ae1b2c17aa78e	1384679511	No	Fiber	10000	10000
28f7163ab4d5cff0af012fcdaaef23a3	1089059768	No	Fiber	10000	10000
c84ac2b754f902c17bb9cf5231a5fc30	1111410774	No	Fiber	10000	10000
a9760631b06cb84420cb8111d72c2a2f	1286908920	No	Fiber	10000	10000
34386a1c580263ef9bfff2523da3a54fa	1106685462	No	Fiber	10000	10000
7416d7c9ba0d85da74cfcc97c516c736	1106683389	No	Fiber	10000	10000
b51c988f7aa323a234aba1a19788ef4e	1111415774	No	Fiber	10000	10000
ec15f85434c43f324966f89a93e00999	1106685078	No	Fiber	10000	10000
422d0c89689b4c7c1f74e25c6bf221a	1106681324	No	Fiber	10000	10000
36a5f5e7b45c8f45b93307c1a7d3695f	1106680908	No	Fiber	10000	10000
91e24f1f46b8c4a3668767ad8a067c2e	1089039731	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
c45e649e68dade83e0f231df10cdd3ce	1106680619	No	Fiber	10000	10000
05776b86e93835590b624436fe2e1bf7	1106684017	No	Fiber	10000	10000
06000e6e183eb508abe155384fa248e8	1089055480	No	Fiber	10000	10000
b94e8ed54c6e07c7c3941ac2c525e40b	1111412041	No	Fiber	10000	10000
ddcff73762ba7a36a7ea4910207f2ca	1106687005	No	Fiber	10000	10000
782134cb7bf5dd31e94133e7ed08c4f5	1111411963	No	Fiber	10000	10000
cc23aca0a4993a83c0ee6fc286baacd5	1106683690	No	Fiber	10000	10000
b0560626a83ee1de34724b57328f26c9	1106684719	No	Fiber	10000	10000
5a0de60ed7e232e161ebdbdc9633c50b	1089031239	No	Fiber	10000	10000
5fe1e12fada765fd3088eb16758074e0	1106686510	No	Fiber	10000	10000
01d36b1551f6525a3482b58ce3069f4b	1106685223	No	Fiber	10000	10000
7ce3e5c6d05beee67e33f512a9942b9b	1106683735	No	Fiber	10000	10000
42ee42d538c43c481b621f97df8585aa	1089034376	No	Fiber	10000	10000
98f846f7b4e026dbec140129a82ac817	1111406482	No	Fiber	10000	10000
cb5f42be5a43418c18b5f271b029b8ae	1106680383	No	Fiber	10000	10000
21158571e8f102789bdfba039d821b80	1286918335	No	Fiber	10000	10000
44e9223f63de86fdc1fa42e9f172a583	1089034382	No	Fiber	10000	10000
b7e3dac4d01081bbbbe13531898adad3	1106686559	No	Fiber	10000	10000
891142f0718e2a0ab95fe772c66ab144	1111413434	No	Fiber	10000	10000
6b24e2a806ba467b6796200cfede3a76	1286910822	No	Fiber	10000	10000
2f2b0c332e366222ce43b3a07b0adcee	1089033530	No	Fiber	10000	10000
33c1f84aaf2cc71feb57e1350af26ce7	1089040410	No	Fiber	10000	10000
11bc1ba9aee4b46a7ebeaeb137f429dc	1106681122	No	Fiber	10000	10000
8ff858d83f1a13df4e2bee9f376d1dc9	1106682892	No	Fiber	10000	10000
5268dc41f3859dd3a93a1a59dfc00bc3	1106684186	No	Fiber	10000	10000
7a19fc5f9d437708504f1b4db402643a	1106681543	No	Fiber	10000	10000
5633b2d5d44057a52998740ea093c3dc	1106685666	No	Fiber	10000	10000
f74b074a92649e5152427d46b49d399b	1106687147	No	Fiber	10000	10000
c02509dea79d9d99cb3a97c1c2e6e1b7	1106680340	No	Fiber	10000	10000
eb906035a1a5b6b0cbb57908f87f81d2	1111409913	No	Fiber	10000	10000
009222453e7f80404a96b8bdd3e36738	1106682993	No	Fiber	10000	10000
2f2cf5d1c18d5fd9a00bf4c5a68c3c37	1286906956	No	Fiber	10000	10000
cd257ae13ec7c4759128d5757b3e30d9	1106681750	No	Fiber	10000	10000
ded9df77eda48d3cdf754f806d155c91	1106683290	No	Fiber	10000	10000
e73456084fd17dbeabb97690bfc5f3d	1413429086	No	Fiber	10000	10000
6bdfd0b9db956a2dd71e6f2a6d625855	1089059316	No	Fiber	10000	10000
d2b1777311ae8f4eba7287fa81e6d18b	1111415078	No	Fiber	10000	10000
791ed5f2c2d69d33a1dde9bf9667505a	1111413269	No	Fiber	10000	10000
43bfec5f95d2aefb7ff5a893ff1b8b38	1106685010	No	Fiber	10000	10000
1c262534bef130e4e9c00c7abcc1539e	1106681858	No	Fiber	10000	10000
3f383b553935b55be3e1f098af324fe0	1286908625	No	Fiber	10000	10000
2714454a7b4256549edd66e8eaedfe95	1106684058	No	Fiber	10000	10000
3924131e42aed8d3bd1f58368990bc1f	1106680599	No	Fiber	10000	10000
9c0c79665606f45822ec67b40c50021d	1111411318	No	Fiber	10000	10000
e46b684ed078800d6787829d5e86c7d7	1106682582	No	Fiber	10000	10000
080d4795f3e65bb67416033025dfe4a1	1384899968	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
ca24eb813a43f094260f02b82b154c07	1089040450	No	Fiber	10000	10000
c32f38149b215da2868d5614ace5f6d2	1111410037	No	Fiber	10000	10000
24bcb3565980860fb2b80b93964fb787	1112264007	No	Fiber	10000	10000
2c34a6bafaefe35c59932dc01b1fc951	1106683112	No	Fiber	10000	10000
e75be7b70df7d14c48647091c3f07372	1089055481	No	Fiber	10000	10000
beb3f2c50dd097a53a811252ee5d9bfa	1089041328	No	Fiber	10000	10000
e7b306f8033a4b1a9fac2a8f729eef8d	1106686436	No	Fiber	10000	10000
92aa0e0ccb00e9e3979ac5a917f0c20f	1106685199	No	Fiber	10000	10000
d26bc9a0aafe045a7a7e8d1f16564ff4	1286914236	No	Fiber	10000	10000
e23b6866047868968fc9f9a7d439e695	1286905243	No	Fiber	10000	10000
2406cc5b2e2d678ddec8dc1b398cf942	1106681291	No	Fiber	10000	10000
16ce2a3f4ca528f2c55d7057bff5fd9a	1106681839	No	Fiber	10000	10000
4f03e19c3efa29644aabac99f3d3506b	1106680927	No	Fiber	10000	10000
6f00c27538649cd5e0f4b3c0fcd6ae86	1106683395	No	Fiber	10000	10000
f92a2ff924de1c6cb9df304a8be6487c	1112253231	No	Fiber	10000	10000
842253be9d4e92d79ced6ec0089aea47	1112259232	No	Fiber	10000	10000
feb5389a221a52619cb61a73e86f3d11	1286907124	No	Fiber	10000	10000
f7c10416d4e885ec5c5aac3bb77c88c0	1111410209	No	Fiber	10000	10000
31927084a24adf3554a9d2268254c9d9	1106681528	No	Fiber	10000	10000
4539ef91d1a07d06bc9423386ea9d3c8	1106686404	No	Fiber	10000	10000
335f5675ec47feedafffe23cb8ff0be8	1111410340	No	Fiber	10000	10000
da07146b30a439de7ba4217a9300a68e	1106684354	No	Fiber	10000	10000
473d2fbda17969a161035d454ffb14f1	1111411928	No	Fiber	10000	10000
16aafd13a158664243539f8c1d30fcb3	1451746347	No	Fiber	10000	10000
05f7138b63f588ddb3f481363d5dba4	1111404482	No	Fiber	10000	10000
3234948a68f95bb7c2f63bd581d56ebd	1111411397	No	Fiber	10000	10000
bbccab67f25492affce190c13e5b985c	1106681415	No	Fiber	10000	10000
d73274775c3b4ab333bd70cd40e3ef51	1106684245	No	Fiber	10000	10000
e1f4b22ab8d8bc4683aa07165f8f9074	1111413205	No	Fiber	10000	10000
65e4a3b10b7df930ac9dbd9f742e659e	1106680808	No	Fiber	10000	10000
95517dcc5a58f005dc1c142478bdf6c7	1089041405	No	Fiber	10000	10000
53480b88bc0dc5ec6e8ad4af6c3a4ec7	1286905586	No	Fiber	10000	10000
c8b87dd7fd6b08411ae05d50b9ed35f2	1106679908	No	Fiber	10000	10000
6a2ccf5a86bd3ff1e3cf9b8e7dd0fd6e	1089043149	No	Fiber	10000	10000
89da48f7ab81924a238caac3b7b34f10	1106684893	No	Fiber	10000	10000
5387aa313f6cabf9fe4a48aa7b13c0f4	1106683419	No	Fiber	10000	10000
59a675c1803a046851e9349e66466284	1111404581	No	Fiber	10000	10000
c7624c2c6fb8af232df52dfbaaa673b1	1106685488	No	Fiber	10000	10000
0621fcfebf6ffe6d662f39248e3a25f8	1106681326	No	Fiber	10000	10000
b85f60032001b51e995314e331a9de46	1112239117	No	Fiber	10000	10000
8895c9b2a54b32a3541bb2bc62e850c9	1089032092	No	Fiber	10000	10000
90b90cf7d120a90877847a9d11023909	1089039711	No	Fiber	10000	10000
490ea37bddcaebf905008724e8a340ec	1089040412	No	Fiber	10000	10000
ed3f9cec031f43b7c7dac5f24577a741	1106682000	No	Fiber	10000	10000
6d9537919f8db82b4c4f594613eb84e	1106685440	No	Fiber	10000	10000
fd8c7633c1d3eac4406f1890c0523931	1286908365	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
5f5e2cfc9ce021b628f4988786c8d755	1106686505	No	Fiber	10000	10000
cc27e159d9f8fbce4068fde3dd0c8e06	1313751598	No	Fiber	10000	10000
bd323c8b790334beb3a88c659f154469	1111409936	No	Fiber	10000	10000
18c9f02bb1df3d9b8c74230721f489fb	1089059108	No	Fiber	10000	10000
a70262642f80cfd5c53cd325cf3895a0	1112236587	No	Fiber	10000	10000
d94257e1f19ae512542a298d022af185	1106680005	No	Fiber	10000	10000
43bd18d82ba0a2b63b49d77bfe74f131	1106680330	No	Fiber	10000	10000
4dc24c1eae1fc063bb5e21b24301fdf	1106687030	No	Fiber	10000	10000
71ba0397264fdfb8d691d9aee8062b39	1112263671	No	Fiber	10000	10000
4aa690173c6eb21986f00f2b3ffb343	1106682340	No	Fiber	10000	10000
ff55eef5d4ece4182898c5415f272b9a	1089055461	No	Fiber	10000	10000
c6327426fa28d2a1a1b06762899efa66	1106680920	No	Fiber	10000	10000
afd3ae10d4b480e6be0b69b69c0c20bb	1106685480	No	Fiber	10000	10000
389060568d20833590f8b1b3b7206544	1112261292	No	Fiber	10000	10000
fe04df318bb975ea305a06e848e44f3c	1106680504	No	Fiber	10000	10000
321e0318c5e5caac380f6c4d6b3d4d60	1089059517	No	Fiber	10000	10000
6c7082048a583f43cda24307a4841da7	1089055537	No	Fiber	10000	10000
d0c0bf4d54efe158b1baf7e924f09763	1106681737	No	Fiber	10000	10000
4282588543b6d91ff242cdb27138aef8	1106679896	No	Fiber	10000	10000
6ecd832767fdde18828e31e0fb32983d	1286910692	No	Fiber	10000	10000
6b73c4662f1dc60a50565543d84489f8	1106686468	No	Fiber	10000	10000
464d40b08bc8fbdf7e0898dd2a57346e	1106681157	No	Fiber	10000	10000
eda95afab8b601682167e0273e7bbc30	1089059322	No	Fiber	10000	10000
ae47232448a1690f6b7fc070abf48db3	1106684917	No	Fiber	10000	10000
7e023ef2e36c059f49805cfde58bf90a	1111411393	No	Fiber	10000	10000
aa056ec8a922ad01614714400f3c7d0	1089041295	No	Fiber	10000	10000
e811c280aaf657e9b425972ef73206d0	1111410391	No	Fiber	10000	10000
2b0c256685f5d30f8163820305f241ad	1286906147	No	Fiber	10000	10000
c2e1b6ed1d26317676eb8c4e13b56dc6	1111412795	No	Fiber	10000	10000
e06d8a33bc227b548d9c7d756ad64e4c	1106687121	No	Fiber	10000	10000
a5a0361bc9627b4b4f8e44ad74af4de8	1089059310	No	Fiber	10000	10000
0febe154b723fec7e1dc7617d516ed12	1089056778	No	Fiber	10000	10000
470e302157f6aa2a6384a03bb4a351a9	1286909581	No	Fiber	10000	10000
a410630d900823ecfab2fd880d02c247	1106686378	No	Fiber	10000	10000
dc9a112de29be619e8c50b81c7f11d96	1089039455	No	Fiber	10000	10000
93ee1df5365a31e31063d1b5942d0597	1089059419	No	Fiber	10000	10000
12cee93c883af767cf1dcf04eebf3cea	1286904566	No	Fiber	10000	10000
c89bbd067715a259e6f9aaf9bf685b0f	1286906304	No	Fiber	10000	10000
438879e58e43b44fcbd20ec54a4dbfc5	1106681123	No	Fiber	10000	10000
83d0bb1399bd62519c2f6d398f17c61d	1111413117	No	Fiber	10000	10000
77f18e0904e1672db0abb10a5128b273	1106684043	No	Fiber	10000	10000
d48b768daf783c9014a4e7519a12a8e5	1106685117	No	Fiber	10000	10000
5f4bac0345c0ed63fbc9256feaf8e487	1106679757	No	Fiber	10000	10000
ad96db744224e8839b57c0e20ecdea43	1111413178	No	Fiber	10000	10000
945228f2a6964526c9ac422360978748	1106681264	No	Fiber	10000	10000
646b1768e1d264b91f80ed9334b32a42	1106683709	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
eb3c2437bd6f2f37e2a7614afec2953	1089059312	No	Fiber	10000	10000
334eb1b61b3158c4b69e23e55597ef86	1106684620	No	Fiber	10000	10000
a711b45633e83120499219828481ce62	1106681027	No	Fiber	10000	10000
6511dad1adb86a4052dfd6a7db9685a2	1106685483	No	Fiber	10000	10000
bd3fa8ddfae31636a730c54a9f66a9bb	1106682985	No	Fiber	10000	10000
1a19430d17520332c5c07bdbbc6561c5	1106683536	No	Fiber	10000	10000
9f253151978bcef7da0de24bad2bf9ad	1106679133	No	Fiber	10000	10000
2fe9310a41284245ba4da05500f80673	1111405576	No	Fiber	10000	10000
b308250121e7bca618759a222e08bcd0	1089059977	No	Fiber	10000	10000
a9aa8d5142a6232c17e83020cd3ac0e3	1106680089	No	Fiber	10000	10000
7a93c96286a7b52faadaa52d9c65fb1d	1286912831	No	Fiber	10000	10000
aed5614e0f827873c929f73c0fa830de	1111413007	No	Fiber	10000	10000
bdd230dafa7c4082fab1d41a4512e262	1111410337	No	Fiber	10000	10000
57b79b2613048c0001417befdc16bc50	1106681934	No	Fiber	10000	10000
db9590d2d0e468c1f94520b89cf2b71c	1106682331	No	Fiber	10000	10000
cc464a66585d0a00f9ac31c81e7c3ea2	1384988439	No	Fiber	10000	10000
18608904b4bcb17a7c4b59ca7e82c91a	1106680896	No	Fiber	10000	10000
d4ea0153f2aea967ff5539c1495744c5	1106686212	No	Fiber	10000	10000
cc268bc14c175b4c99ab979bf1b46f36	1111412021	No	Fiber	10000	10000
dac26992f1669a991ce18ac6fb345b7c	1111413199	No	Fiber	10000	10000
e5f46ef53635c9504e2684a7d5e8ab6b	1111413085	No	Fiber	10000	10000
ab89823f36fd0b5cb4507a59a5ca2710	1106682367	No	Fiber	10000	10000
b0a8633340540bb8a3d3ffa39bc671e8	1089059837	No	Fiber	10000	10000
68df215492e0c8df893725ce13ba15a4	1106683622	No	Fiber	10000	10000
9b3add587fc92d1faba684759c469be4	1106686177	No	Fiber	10000	10000
4f726f1267c35eb3135d48cdf0e375b	1106686192	No	Fiber	10000	10000
cf99774ca902f50cc71f8118cb88bcc1	1089034379	No	Fiber	10000	10000
aa3906051ba53b26853a4d95aada3e8a	1286904928	No	Fiber	10000	10000
ba86e2b150fa2d8c52f9f6f2431632dc	1089039691	No	Fiber	10000	10000
a45e142ee5c71179264a492e08586be8	1106680807	No	Fiber	10000	10000
06eefbd3c412f01c5a09be4ed85a679d	1089056294	No	Fiber	10000	10000
295d73fa3b46504ccc2555720af73760	1286907183	No	Fiber	10000	10000
b713948672430735dea95eeac5319e07	1106680307	No	Fiber	10000	10000
acf28d517b7dfbf6e826e09d5fd7dd78	1286913923	No	Fiber	10000	10000
3cd4f0bbd5bfe70e8f0a5c33377479b8	1089059183	No	Fiber	10000	10000
3941044de429fcd13717338d4db6c6be	1106685755	No	Fiber	10000	10000
e17cb4431a972e3312e7e0ab1dbb8976	1106679455	No	Fiber	10000	10000
c87a0af7274fb43432c01bac1023708c	1106680775	No	Fiber	10000	10000
ca7c233a11edd0570ce605d7d2f9a88a	1111413905	No	Fiber	10000	10000
1db8f512e724e881efabc1900135d74d	1106685328	No	Fiber	10000	10000
d56e7247bd928ee2a6820c9e36476eff	1106686390	No	Fiber	10000	10000
24a42a96cf9cdc5d6c1ea95cf251f0e4	1106685101	No	Fiber	10000	10000
1daca9cf93392de838b73a4cf5603c19	1106681045	No	Fiber	10000	10000
e54648dbb123a7914030ed49b0fe7d52	1111410819	No	Fiber	10000	10000
990cb924605a30625963cd0fef77e1a6	1106679761	No	Fiber	10000	10000
7f3a62cc1382d9868735343765c82ec3	1089042944	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
abd1109da13e5a2a579b81dbd542b21f	1089034815	No	Fiber	10000	10000
337d2a179ceda2631acbcc17fb2df5e7	1106680520	No	Fiber	10000	10000
abe10c837df89119b820f2c601f9edc6	1106682085	No	Fiber	10000	10000
9b8a876554c85daa4ca4879d817ba946	1106686929	No	Fiber	10000	10000
acaa71b4ce304f0a87e5f6eb608b617a	1106679353	No	Fiber	10000	10000
b9ffcea3e4eab14713f4d650809d8141	1106683995	No	Fiber	10000	10000
d27466c4067068ef2564f0fc8885c3ac	1111405249	No	Fiber	10000	10000
aa527e6f378c562ae6be6384ba4f9456	1089044888	No	Fiber	10000	10000
72a49ace377eecbf49b7f8cc8ab24e83	1111413996	No	Fiber	10000	10000
65aa91db183e2d40f5611e462efcdacc	1112239111	No	Fiber	10000	10000
2ffa42cb4ea03811fa809f34f2507332	1089055473	No	Fiber	10000	10000
0bd91e826fa31b28d22ff6286815b9f4	1112257377	No	Fiber	10000	10000
3c25be3971c6d5b27e4659e5c37b01bb	1106682020	No	Fiber	10000	10000
841dd35a2c1c1a956d0664972f74abff	1286914267	No	Fiber	10000	10000
813abb7e8ba88f802195dcb270c67cae	1111406121	No	Fiber	10000	10000
d3f7189a965955f702f3c2248cb5c94c	1286905073	No	Fiber	10000	10000
f8dbcb7d969aa8f9eb003124747265b7	1106680766	No	Fiber	10000	10000
d09c21913fb363c998b3a5f65c69ae0f	1286905058	No	Fiber	10000	10000
e3dcbab1a30a204f3395368473b286a4	1111413004	No	Fiber	10000	10000
427bd1588fcd4e85dc8fd86e5db7ade8	1111412033	No	Fiber	10000	10000
2a9ee438be8daefa9fb86efa6fc299a7	1106680565	No	Fiber	10000	10000
34bdb8871adec1f3d7c05da698ae78fa	1089034310	No	Fiber	10000	10000
ce494a08e769641dee3af2b00240da5d	1106686389	No	Fiber	10000	10000
c454dc9d7b80681ad560a600bc1dbd59	1106685624	No	Fiber	10000	10000
371c677af2d0ee086c05d411f05e0a6f	1089040650	No	Fiber	10000	10000
8a0e6c637fce8f5c72762bec331eecf	1111417554	No	Fiber	10000	10000
fe6c61cd79aa025ab64d18ac0673cc22	1111413864	No	Fiber	10000	10000
7d0f589e8be5aed02ab0ac9ff640e386	1111414013	No	Fiber	10000	10000
a4bab931fae4513f88126f40517fc65f	1286914621	No	Fiber	10000	10000
d97924d4a59bd935e8b9999623e9b617	1106683428	No	Fiber	10000	10000
e9045c59a93b2c95f377674a4c160736	1106679488	No	Fiber	10000	10000
e58dbc800dbf9c8fcb298b976b8c1a81	1286910779	No	Fiber	10000	10000
9eeb224d8d95ab06980ee506be9ada46	1106679927	No	Fiber	10000	10000
a8641959d661874e696e2290d0965104	1451746346	No	Fiber	10000	10000
53c088d125523ee14b492e7fd9a97542	1111409924	No	Fiber	10000	10000
a009eda26f498706ac667b0034592b61	1111411459	No	Fiber	10000	10000
99ee78fec457134691b022da1d8d7610	1106679629	No	Fiber	10000	10000
1f59b79b60f3e60c88fe948a8ece03f7	1089059210	No	Fiber	10000	10000
91f6277429e50bf31be2eeefce42f3ed	1111417560	No	Fiber	10000	10000
c68da28b265d092227bb8d8b314901d7	1089034377	No	Fiber	10000	10000
3c04994400cc33169521c91036e75062	1111413895	No	Fiber	10000	10000
852dd9007686cae0de96aa2ed8d45d57	1111413107	No	Fiber	10000	10000
4ae6e61e3522db5e096790f0354c7592	1106679383	No	Fiber	10000	10000
796a1bdc5cd2ca018123df3c0bbfdb72	1106681890	No	Fiber	10000	10000
5f9b528e86dcd333b55fede6f1a3424f	1106686237	No	Fiber	10000	10000
c20cbfd412b48be9010872eec308b7c5	1286905599	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
4937a1c16c5282256743678bd5949353	1106686227	No	Fiber	10000	10000
d0c6f7047626b9e4248589886deca673	1286912004	No	Fiber	10000	10000
f47ff75c89b927fe73ee8fa04eb1829b	1089059328	No	Fiber	10000	10000
accf34f67c5bf17741cb0e800983871b	1111410818	No	Fiber	10000	10000
dbb3c4a7d77a78dca74fd503638b4dbb	1106680707	No	Fiber	10000	10000
2631098947a616b3415e0ab8fd1c7ed4	1089059228	No	Fiber	10000	10000
8e4214dd8ad0baeff667922eeb5aa9a1	1112264009	No	Fiber	10000	10000
1e40caaad2a8fd4eb8c9f8a8841715d4	1111404572	No	Fiber	10000	10000
72daca6d86c7f80402754db5103b0d10	1286910566	No	Fiber	10000	10000
0a3ea9c9f62f292f0fcca4635af40e17	1286904855	No	Fiber	10000	10000
be3fabaec4284d499895fe6435195223	1106681236	No	Fiber	10000	10000
69672298f44c0ecf7d08c6bd76dba9a1	1106679448	No	Fiber	10000	10000
f145beca95872bf70963320fc2d22288	1111414583	No	Fiber	10000	10000
184107d94cc4b8f9217c0b54872fba23	1286910581	No	Fiber	10000	10000
7fb51b37a18b69c7b3ecf810ffad846b	1111413920	No	Fiber	10000	10000
3b5503c134e0e1ac50f0c9b3e1e08a73	1111413022	No	Fiber	10000	10000
991e3c59c14e974866dd40c03716cce5	1106684099	No	Fiber	10000	10000
7c1e7ef7738ee2daade9102e1f2fcfd6	1106683663	No	Fiber	10000	10000
685fbe7de4aaae6280a55d4f176d7511	1112236608	No	Fiber	10000	10000
a6a6b7471da3b1163d86491954e61719	1106681666	No	Fiber	10000	10000
0f411c33d6e5b8b181e96364503d5fc0	1106681270	No	Fiber	10000	10000
2f04b88f6591d4dcb18d49a6794f1e31	1111413207	No	Fiber	10000	10000
3bd0b552da3592e94ff1d42263c1d526	1112257228	No	Fiber	10000	10000
6806140f840abf0f6ae7eb4003318e0e	1089055476	No	Fiber	10000	10000
7daddf2c6d05b9052ef1dbe41d849dc6	1112259235	No	Fiber	10000	10000
c7468cada199e04b081a6fb171a7a70c	1111413919	No	Fiber	10000	10000
02ec4b1dc0ea1dbc3da101723036cb12	1286911989	No	Fiber	10000	10000
e3b8191f22a8249a66934ee38d2e560e	1106681367	No	Fiber	10000	10000
45347f4e5563809e2d0b89b3bc369189	1089059111	No	Fiber	10000	10000
74313cfa7ba6e72132f93bb4d093a6ee	1106680437	No	Fiber	10000	10000
85ca599da8781742f9fcb964e40deb1b	1106680027	No	Fiber	10000	10000
dbc377181126566f501c1b728983fda9	1106681074	No	Fiber	10000	10000
4cd2b28bf732a782d5076536371a5861	1106685642	No	Fiber	10000	10000
2d7282774ee78acac68cbfb911d1e6e5	1111413186	No	Fiber	10000	10000
6652366143668f02f219bbc5524deffa	1106680193	No	Fiber	10000	10000
1b18e64f47767cef228b4558d377a418	1111406188	No	Fiber	10000	10000
c61b2ed37e65295c9daa8a798ad1ebde	1111405147	No	Fiber	10000	10000
a599d0cd8aeade3bdc46a4933573d3f	1111413003	No	Fiber	10000	10000
9aee9d8ffd39b3296fb71fb3e6ca4c71	1106684243	No	Fiber	10000	10000
85067a9309b44303c1d59c7c63d36422	1111412057	No	Fiber	10000	10000
90afaf6fa2a1e5fd6be7624ec023e131	1106682218	No	Fiber	10000	10000
910d0e68aebd5589f451cc740d04b48f	1106682605	No	Fiber	10000	10000
f36ab0066ae296c9e3cf5f7576fee7f2	1384901002	No	Fiber	10000	10000
06b39bc9e07f347d1b067b43301203cb	1106684026	No	Fiber	10000	10000
5cf9efbd0e94783d2b53948dc9c0d59e	1106684503	No	Fiber	10000	10000
6134f848c5dd8ff951493ef830f86f3c	1106682915	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
131caa3f156f47afe58faedba7f8701	1286912459	No	Fiber	10000	10000
279ae2e033dc404874d633793296f9e7	1111406233	No	Fiber	10000	10000
f5a577cafc8b34e5f2abc22b57aa701e	1106682855	No	Fiber	10000	10000
59eb5b8f09667ecdd08240fa09c945c6	1111406182	No	Fiber	10000	10000
2313a07eba6e65fc594e988740d06dba	1106682093	No	Fiber	10000	10000
0bbac423db2d8efa3052434cfe936586	1106686476	No	Fiber	10000	10000
248544e00f25fc6bf1bbc7a192723524	1106682027	No	Fiber	10000	10000
2b32f657e8eb09fce5bacf09146b590c	1111413091	No	Fiber	10000	10000
a43298fa373e6233d9bedbfdbae3d5a8	1106680469	No	Fiber	10000	10000
63aa9dcdbcbbfac39f33b5e42c33643ce	1106679859	No	Fiber	10000	10000
cfc6a846e7cfaab4874566f4ab39ef40	1106683184	No	Fiber	10000	10000
04157c4f174be5cbf9b7e291de0d8f3b	1106679424	No	Fiber	10000	10000
e28cbf0173ed4dc9db34843efc990348	1106686572	No	Fiber	10000	10000
7cd1b2af365e72fab23c982f4290a6dd	1106682834	No	Fiber	10000	10000
d7a01d6dd2677118151f1714c7ccc826	1106680860	No	Fiber	10000	10000
1df811c57a5d7e46c9323315a0402af7	1286907835	No	Fiber	10000	10000
58fd10c1d1c2e1edc63c6c881cf5e7ca	1106680625	No	Fiber	10000	10000
a365971a2d8939201874000b00cb55d0	1385050345	No	Fiber	10000	10000
10f16bd4bca405ce4df1266a445d6390	1106680721	No	Fiber	10000	10000
329bc982a19059f11860c847d9fde75a	1106680911	No	Fiber	10000	10000
998dd5a2d22cc754d2936409a1147c2e	1106683966	No	Fiber	10000	10000
3346f403e183d16db4a89f4e61cbfd39	1089059191	No	Fiber	10000	10000
41ffdd6b3ba18ec716d9a172f458b1fb	1089059852	No	Fiber	10000	10000
66249ccb693c041cc7c55ba2d67f1278	1111405567	No	Fiber	10000	10000
ab7b1c5d82c09a4a8860982c2db870898	1106684198	No	Fiber	10000	10000
e617174cddb944bbfcd08903ebff973	1111405155	No	Fiber	10000	10000
39d2682e913ce565e8307ada7d4b85ce	1106682069	No	Fiber	10000	10000
c743b9ff3cc398c8df0dc69c71b7eb02	1286904451	No	Fiber	10000	10000
96a249488994cc456820b3ae2a89b2db	1106685123	No	Fiber	10000	10000
311a2c2f461840c601226d120ea5a8ca	1111411887	No	Fiber	10000	10000
0745a06028b1dffd73f7d5b05a38c08	1111410387	No	Fiber	10000	10000
81e620db32eb5e0a0128ac2f7166ec60	1111413407	No	Fiber	10000	10000
85b70a367cf371e6191b8fd7d3019c19	1106686636	No	Fiber	10000	10000
b9e5ef8f557a253fbf64b61b2887e927	1413411258	No	Fiber	10000	10000
26c02664a9bd95fe01cff4ecba9a7a5d	1112259023	No	Fiber	10000	10000
29162de1a2e11f92a58d8ae5d2275f62	1106680136	No	Fiber	10000	10000
730366eb2d7079014948dbb9abead617	1106683952	No	Fiber	10000	10000
8f809daaa193dac458644eff79358c67	1106687146	No	Fiber	10000	10000
84f069efd39d56b9b47db823e955a72c	1106682089	No	Fiber	10000	10000
73d202069d62431f74ca2b0d196d7b41	1286905651	No	Fiber	10000	10000
4f60f7060fcc9bcebcdbd9b62d1c3dc2	1286914531	No	Fiber	10000	10000
9077ffe55b599dd68f041e400d47aedf	1106683993	No	Fiber	10000	10000
e1bda9c07321e8f5c06b8bbda9daf9a	1089031231	No	Fiber	10000	10000
510fdb3674d0a6196c78961ba18ead5d	1286909759	No	Fiber	10000	10000
9329d1fe4f8be5cb5402aa682457315a	1106686222	No	Fiber	10000	10000
b11cf4a4547f82b0e5d31457996784ee	1106683978	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
9212cf6239dab2aeecdcdf138ee1ccb8	1286910501	No	Fiber	10000	10000
eead98badbd43a1c98190850d3ee251	1106683767	No	Fiber	10000	10000
4ebd84c29e40e0c6914308087cf7b415	1089039420	No	Fiber	10000	10000
5325a0b212b8ecd711ba6108d00ae460	1089034313	No	Fiber	10000	10000
ab4e72390561735ce59c5589410411ee	1111413012	No	Fiber	10000	10000
1c68978a8000c831dac4358a2c7d82fa	1111411713	No	Fiber	10000	10000
4ffe86bf3267de2bb258064e66add1d4	1106679503	No	Fiber	10000	10000
11cc0edba670819d095458d7780b2e87	1106683796	No	Fiber	10000	10000
45416eac5015a140fec416ec7be37712	1106682276	No	Fiber	10000	10000
285b3d809d7162b25c9bc3380ce3d233	1286906789	No	Fiber	10000	10000
132e1b3b3d056abac9a2b4df7cdad441	1111414004	No	Fiber	10000	10000
5a828773662ffe50ae99bb8b382ce120	1089039766	No	Fiber	10000	10000
d7f64fee7d20463567c3be2779c018d7	1106684118	No	Fiber	10000	10000
3573a4e1afed8dd4d1539c3d8dddba14	1089031241	No	Fiber	10000	10000
a0b39fa0ecc930a2d087e3fd875159e2	1106681463	No	Fiber	10000	10000
d8336df14e2be063875779f9eec19790	1089059206	No	Fiber	10000	10000
35b64f2229f9c3be731e263ad5b49343	1111405880	No	Fiber	10000	10000
702cdbebf6535d071186c759c512c6ce	1106682384	No	Fiber	10000	10000
889d39600f26461717e4cf4909f6ef53	1106684939	No	Fiber	10000	10000
2083500f0305294c3dce2600825cda6b	1089039452	No	Fiber	10000	10000
ca9ba5fa8bd1fcdffbf2f20d7f0a0e	1089040425	No	Fiber	10000	10000
22559d84dfd50adf694af4158267538c	1106685032	No	Fiber	10000	10000
6bc33189f84d326238882667e16e5d32	1106684455	No	Fiber	10000	10000
922f08383a6ceca1e10095daada6e168	1111410392	No	Fiber	10000	10000
9519490a46554d9fa1c048db3aee59fc	1106686438	No	Fiber	10000	10000
2b98a8601ec9fb213e692189f5416e30	1111412524	No	Fiber	10000	10000
54c2e0315061e4f6d15d81c9926f83d8	1106681733	No	Fiber	10000	10000
c39fed346cebcd5f4216e4696272789d	1111404911	No	Fiber	10000	10000
54c060b535426de45c8c1328bca62b09	1106691250	No	Fiber	10000	10000
d271e505702a1c7d022964d0fa432c9a	1111413187	No	Fiber	10000	10000
3e71257ac39cd365e852fc74a0b46987	1111405882	No	Fiber	10000	10000
e67f0a4ec23698d7e737e58f6796c5c9	1106686264	No	Fiber	10000	10000
a858fb348be4f5d8af497b62e30c985d	1286910820	No	Fiber	10000	10000
34f090c3751cf463bb421ad531f360a8	1089034371	No	Fiber	10000	10000
cef459b4baead7d76389ea7636c20411	1089059723	No	Fiber	10000	10000
971b9155c828fafccb2031e5e5a2abe2	1106682879	No	Fiber	10000	10000
4a657345d6143926b4e13d3e860e1cd6	1089034805	No	Fiber	10000	10000
1428e8a60b39ee60755188709763507f	1106683061	No	Fiber	10000	10000
f3e79ed0bdbeef38ca43d10c681cc823	1089059853	No	Fiber	10000	10000
d2e1961d94b9b5a67b3c5330454bfa5d	1106680731	No	Fiber	10000	10000
b5256d3c1bca1fd087a1c9b7c946f488	1286907096	No	Fiber	10000	10000
6c374b157594289b0f18f1fcc3c7ae3d	1112257327	No	Fiber	10000	10000
9374238b7e739f52aba92b210e28f2a0	1089040430	No	Fiber	10000	10000
8a05d9f64db99ffa3b467e4d5f7aeac9	1111411477	No	Fiber	10000	10000
eda34c1fb8122f938c29a8b19fb5885a	1111405560	No	Fiber	10000	10000
ccde538cb19d5f7880bd9a8d46d5effe	1111412226	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
2011c133765436b72a976952637f09d3	1106685164	No	Fiber	10000	10000
777adcd45ea4ac4ac0a42a78e62281de	1111404556	No	Fiber	10000	10000
fb41eb62edf4dbd1640664bf178edb07	1106682615	No	Fiber	10000	10000
59a199d8fe51dd181f361b25ecd4a10b	1089059710	No	Fiber	10000	10000
a1583fd089266eec95c340afe68e8647	1106687001	No	Fiber	10000	10000
0cc29e42fa858cf86f1ac98502aa0e58	1089056577	No	Fiber	10000	10000
c3a51a959686efe976f80e12417e72ff	1106687159	No	Fiber	10000	10000
58e37c7a643e4b27bf11fb3512147298	1111413081	No	Fiber	10000	10000
27ad97152527810e662cc891678f6bc2	1106679492	No	Fiber	10000	10000
21e27177aad593c828ef002f0e2f80fd	1106682264	No	Fiber	10000	10000
9339e4db1b4764e36e4ff76cd6f45e71	1106684960	No	Fiber	10000	10000
2bc062a005a6a55bb5b8b9a565d1fbaf	1106682630	No	Fiber	10000	10000
47c3b1fe4269772409bc8a3e2f742011	1286910091	No	Fiber	10000	10000
7baec0841251e714c800137b02ab7e32	1106686045	No	Fiber	10000	10000
7aa78420f69ffdd679b659372ee4c39a	1106682576	No	Fiber	10000	10000
37c47eb038c01715c1e44682cbc67ef3	1106682123	No	Fiber	10000	10000
9a238a4e3b86fe893b29ccc46e413969	1089059400	No	Fiber	10000	10000
a5c486729a94cfd90538c43b5afa9dcb	1112239085	No	Fiber	10000	10000
944996d49e99368f3436c7d9904d8cf1	1286905676	No	Fiber	10000	10000
5a3cf4505c2fd601125bb85175d5be28	1111412757	No	Fiber	10000	10000
d9292be48b51f64bc2be379e903c16c3	1089031628	No	Fiber	10000	10000
7cdb18bd13be7e7ebca768c015998f38	1106687035	No	Fiber	10000	10000
d93459b378c130dba74880bb8eece6a	1089059474	No	Fiber	10000	10000
4689a80d4634ecea2fa0530c42492aba	1111405877	No	Fiber	10000	10000
18158c3608cce36293e9f9f407161805	1106684516	No	Fiber	10000	10000
4807dc93379b542440a035e420ec8ff8	1089040413	No	Fiber	10000	10000
ac4d02b19d38e5b1548e30c8aff0ce9e	1111410798	No	Fiber	10000	10000
91e1cfa0de83dfa1d83fd9333508a468	1089044887	No	Fiber	10000	10000
51908aceac3e2aa9d4c65f6fe8a95da8	1111413876	No	Fiber	10000	10000
ca995a1414edcc1a5a7bd0ac544e2abf	1286907277	No	Fiber	10000	10000
a5aec52c7fe558b07eb37515293467ea	1106687013	No	Fiber	10000	10000
5756109cc1cc7370f4f224e8f36a951a	1089040415	No	Fiber	10000	10000
f4943d0de43c9cae7e7d9ac8906813fb	1286918465	No	Fiber	10000	10000
ebd2e3d774842a1cc60aa6177f56f0b4	1111405318	No	Fiber	10000	10000
242f339dc0acb831685f42aaa79b9e07	1111405910	No	Fiber	10000	10000
f9e28486812d437b7986b7620ee9cff9	1106684974	No	Fiber	10000	10000
6c1f48cb125aded5abd7a518a7d0cca5	1111413013	No	Fiber	10000	10000
f35c51f0b7a38513d50223f8cfc324f2	1106685769	No	Fiber	10000	10000
26538a88f227d8fb69dacaceb56e6713	1106682090	No	Fiber	10000	10000
a842ca28f292615158626081355b2718	1112239110	No	Fiber	10000	10000
9c41e777ca28f64325fb9012d70d760d	1106681745	No	Fiber	10000	10000
2bb1134ac161489c9c6da8b9481a3911	1106682457	No	Fiber	10000	10000
604feeb1e97da4d4841dfdd0e9fc484	1106682550	No	Fiber	10000	10000
982fd212867acd8f06eddd2a3d85821f	1106682099	No	Fiber	10000	10000
b798b7bd7354549175b25dacdd96bc49	1286909266	No	Fiber	10000	10000
3a5a6152474c62438a358e5f5b6b42a1	1089059851	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
8cbca61292d41bef2eb038393a72dfb8	1111411492	No	Fiber	10000	10000
ef67bba96cbdb14e2a5cb63e3341540	1286911266	No	Fiber	10000	10000
5395f050f742d99457ccd92cf88c5647	1106686959	No	Fiber	10000	10000
e7ee630ada034c576779f2088fbaecf0	1106683604	No	Fiber	10000	10000
2333d87b28c159062e7c9a28de828bc0	1286907308	No	Fiber	10000	10000
2435844bf5d263196661579cc4a40d58	1106686910	No	Fiber	10000	10000
d261ca4d04bdac57613512146a7118f	1111405189	No	Fiber	10000	10000
c0091f29d6a2385ab9a3c34e43e905ae	1089059429	No	Fiber	10000	10000
305b9638a632f033f6b8b00c0fa96f89	1286912736	No	Fiber	10000	10000
c1f887b40ad3c51709a537452b629cd8	1286904629	No	Fiber	10000	10000
0f8ea3620706a092ccc61b58e39d424a	1089056581	No	Fiber	10000	10000
f82853772573707ed7d826cef57f5dd9	1089031246	No	Fiber	10000	10000
3830565d6d976fd3c09bd2d2c5c680da	1286913016	No	Fiber	10000	10000
db3a57fbb906a0b39e7511837584ffdb	1106679352	No	Fiber	10000	10000
c9774f657846b3de112086078c262d60	1106683916	No	Fiber	10000	10000
2e2d6ac2c8674dc798ddb16d2557d64b	1106682863	No	Fiber	10000	10000
d0abe677ae2764d68e63cc7470b20142	1106685191	No	Fiber	10000	10000
9b8568a966af156dc4a1aaafa739375f	1111413903	No	Fiber	10000	10000
37a10c2bf65f024fa5065a2850ba5adf	1089034829	No	Fiber	10000	10000
36cf89227e07f1a97999ba7eb5fc1c2e	1089039429	No	Fiber	10000	10000
a81eab611029aeb9d1d39dfbfbfd014f2	1111405157	No	Fiber	10000	10000
50baa2917fee736bbdb784cf91660df9	1106681883	No	Fiber	10000	10000
ecdc3a017fc5974252af2708fbec3879	1106683758	No	Fiber	10000	10000
9670296ba833447eb2f7a8423e369307	1106679948	No	Fiber	10000	10000
72584d908024e0be7319e56ee48a4d54	1111411322	No	Fiber	10000	10000
5273d4872a67d0874f77c3577e573709	1089031247	No	Fiber	10000	10000
e11fa9dc371a6244956caa758e6d5f6e	1111413001	No	Fiber	10000	10000
7891b844380f87e4c9aacb4cc9ff0d6c	1106685250	No	Fiber	10000	10000
c533ff2ed9f5569e49064e0e3fcd42c3	1106684712	No	Fiber	10000	10000
8c97acc2916c820694b836a2179cdbff	1286905129	No	Fiber	10000	10000
46d24f9aeee965a73234d84fd5c7624c	1106682353	No	Fiber	10000	10000
cd8a61a667f9cce5498cb6d3c909e2ed	1089039748	No	Fiber	10000	10000
c02a59e3e03fdfd0e6b161050e4b2e8f	1106683554	No	Fiber	10000	10000
9d96a39539951e4ff49a150ab6978cec	1106679966	No	Fiber	10000	10000
937164dbcf10eb4964fb3abfb086112f	1106685088	No	Fiber	10000	10000
13ce9efcf92616568aa23a419c9ebaed	1089043171	No	Fiber	10000	10000
8e6bc52ad13da7f6e726f1d3d57bcc38	1111412765	No	Fiber	10000	10000
a5bbbb35c2e96e7a8dec1b5b72392d15	1106683624	No	Fiber	10000	10000
084224a9d69bfb2025a8c3a361f9242f	1286904844	No	Fiber	10000	10000
0198a8cbb3f2666cc8e03d81de6cecf3	1106683805	No	Fiber	10000	10000
7b346e9126295e1b53a809b7c4329e18	1089059364	No	Fiber	10000	10000
c2261d811a67b53e0d754af1da5695d2	1106679741	No	Fiber	10000	10000
12aef68407fc27d83e920c8497328fa3	1286911462	No	Fiber	10000	10000
ab2983724c020f90c2f7f028b2b7eab1	1089031945	No	Fiber	10000	10000
40fad4b03640bc3603a3fd4ee15f5b61	1106684688	No	Fiber	10000	10000
3946def92866bd0833e7c6050f182d66	1106684710	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
ab7b53a11d01f204bd6b8c09b3fb2040	1089031230	No	Fiber	10000	10000
ffd5f9d8f9082bd52d9b35268fc67e67	1106683487	No	Fiber	10000	10000
f8e46880390b07f7bd7468023665e5e4	1106681261	No	Fiber	10000	10000
d76eeb8852301d9aab9b5b7148032836	1106685242	No	Fiber	10000	10000
c3def4d7aff2a98c160ca2e516c22b51	1111406014	No	Fiber	10000	10000
db74a7d6b279c477493e229540eb2702	1089044894	No	Fiber	10000	10000
e443569fa87fd99aa61a124560a32ade	1106683644	No	Fiber	10000	10000
011fd0e95372636fca0cab9fed08cfa5	1089034391	No	Fiber	10000	10000
2e7b9fb3382bd48e53017b885fa10d2f	1111413087	No	Fiber	10000	10000
caac983b978620422602ff024b935d16	1106681843	No	Fiber	10000	10000
82336697f2be66e041fc74b724a9fbd1	1106687231	No	Fiber	10000	10000
75d2160e42929b15175c94fcec78a861	1106685017	No	Fiber	10000	10000
4d6010c95bd269e61481a81594450b89	1111410386	No	Fiber	10000	10000
8e47f94ce9fc18ac6f780f1ccae1bc6a	1286914150	No	Fiber	10000	10000
b32570142d66f4a918465e3f650a73d8	1106683167	No	Fiber	10000	10000
0b69a4b859619e3299eae3c5940e5f4d	1106684286	No	Fiber	10000	10000
336788b4ccea84ad73ea7d2ac26e5d7a	1106683269	No	Fiber	10000	10000
058b12ee5fe51d26eabba8cd1dd792d5	1089059845	No	Fiber	10000	10000
06cf0ac73b93f2bb6d1f9eb767d086a3	1385051662	No	Fiber	10000	10000
252368a79a675904e964e983fecb6950	1111420823	No	Fiber	10000	10000
896c26d9aad3434ed65cfb08a6ebebe3	1286910544	No	Fiber	10000	10000
d959cf272b8cbdd03fc802e3b4419d5	1106685178	No	Fiber	10000	10000
9f9bba8f584b9602daf0f2dd133350db	1384898282	No	Fiber	10000	10000
738a58b20fdd26a96b0782f3c617c8f5	1089059177	No	Fiber	10000	10000
b528455758edfe1db11bf30ede725f06	1106685174	No	Fiber	10000	10000
1d1aa051fabda0340f3134c5ae2c4400	1106684204	No	Fiber	10000	10000
a28f9c3356fde9f5f7e3b8c1f096a1e1	1111415777	No	Fiber	10000	10000
333e76770e6a1b0933eb317530563fcd	1106686425	No	Fiber	10000	10000
7aa3c15345a585d74c8cd0dc784488c7	1106684971	No	Fiber	10000	10000
1478180a850dab96d40b3fd0bf4c638f	1413429139	No	Fiber	10000	10000
7df1d555967be216528ca7286407f188	1286912447	No	Fiber	10000	10000
fb40b8aa81cb598eaeaba8ed2660bf0c6	1089040452	No	Fiber	10000	10000
f001847f2a92ab15a579024de36f3be4	1106685252	No	Fiber	10000	10000
dfc0862164de3668c9f171dec6a47bb5	1106681812	No	Fiber	10000	10000
32583e67b39df628b6f25b733849d07d	1111413011	No	Fiber	10000	10000
c153b8c26d4a0d1a3a50bb789ce18b97	1111407557	No	Fiber	10000	10000
358c8983320cdde5693690867fb2fb07	1106684547	No	Fiber	10000	10000
7ece6eaa9c468360af37961673eb46a4	1106683232	No	Fiber	10000	10000
835860daf46221b674d5ad29c11cc39d	1111417548	No	Fiber	10000	10000
7810d3870791cf9f8d4b048fd540b6ae	1413421516	No	Fiber	10000	10000
40aba0842116b7e5364e373d3749fbac	1286912993	No	Fiber	10000	10000
e21a2b3f82a515322e14a1ff8ffe06e	1106685825	No	Fiber	10000	10000
a2d8cc553c4d01248e21269ff16b0d89	1111414803	No	Fiber	10000	10000
814b629421a461c5a2f5e298dce2fa55	1089059127	No	Fiber	10000	10000
69176ca8e3c55a3a44f2c792727bdc8c	1106685522	No	Fiber	10000	10000
c8ba04b304db6454979f400272fe39fc	1089034323	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
5a8bb41527f687435d556656a21cd2e2	1286914362	No	Fiber	10000	10000
d84ff30f5a85ab7af25f7ad9c30e572f	1089040442	No	Fiber	10000	10000
0322f1b39cefb4c766947203603a74f5	1089042943	No	Fiber	10000	10000
f0c9e14932fbb939c1f52fc8efec414c	1111406228	No	Fiber	10000	10000
c730513f0861b5163036ef4a26431af6	1286910772	No	Fiber	10000	10000
4a88594dfc6d31f3a3a4b94689b43ed6	1089034386	No	Fiber	10000	10000
1e2e6ea45344cfe9a0b760fceb539bb8	1106683990	No	Fiber	10000	10000
2b47daf98c1a4ec2375b1dce5a0067a3	1106684462	No	Fiber	10000	10000
092627b82b938f98cde1c2c5e24f5df6	1089034245	No	Fiber	10000	10000
26c4bfb6556e2160fb0ac1bcb8e09b6e	1111412947	No	Fiber	10000	10000
f949408eb27b998a6c3f4189622d9c32	1089043148	No	Fiber	10000	10000
78851de0af5432c09fc5994102b79103	1106685843	No	Fiber	10000	10000
c26c0a5b8e73a259e234d752a181f7ad	1112239079	No	Fiber	10000	10000
72f6f44bb492d9cfb7bf2e5bda56bac4	1106686496	No	Fiber	10000	10000
461b7ce2ad530342306e39ccc82c0917	1106683400	No	Fiber	10000	10000
59127edeac48c11a608c245e2b46d7e3	1089032088	No	Fiber	10000	10000
c15a626b66752f58361b73ef20bcb0b	1106680710	No	Fiber	10000	10000
deb21e7d0bc684acb9ae4e280c730904	1106682589	No	Fiber	10000	10000
1bd7f58d8de27dc00eaae3288712d53c	1111413230	No	Fiber	10000	10000
4701123b2fe091d304503dbaa7744961	1111411392	No	Fiber	10000	10000
dbf26e3d181900c8669a29a6dd384fc8	1111410817	No	Fiber	10000	10000
2f1be47ed50fbdae0dc971f5bd1527f8	1106681244	No	Fiber	10000	10000
9954c3a8e2add1f70b084c197b7953e	1111411485	No	Fiber	10000	10000
4e3bbc8a4567f7839875b6ed8d419a31	1111420480	No	Fiber	10000	10000
41c05d3924c2c78a03b19176d52453a0	1111413002	No	Fiber	10000	10000
d156cfc46a9cf717a3e696f9461e2a0b	1089040140	No	Fiber	10000	10000
b301421934668152ecd34ca02ade8dda	1111411704	No	Fiber	10000	10000
acff368433533003059e326d52481768	1286913199	No	Fiber	10000	10000
fa5695864fd59b7de240a91ed59e85f1	1089059224	No	Fiber	10000	10000
887aa873bf49a618c5f64dcf651faf6d	1286907956	No	Fiber	10000	10000
ddf9d15e89a9a95d15911045bd64905e	1286904865	No	Fiber	10000	10000
8679a7bc3ec9f4fa47fb814b705b930a	1286912887	No	Fiber	10000	10000
3f4c5edc988a2988bf7f454ea06e52e5	1106682584	No	Fiber	10000	10000
8da8e3f45ca339ce819878ec5b026213	1106685859	No	Fiber	10000	10000
ab61d63757b5a5ce53576ac4b354ca63	1106687167	No	Fiber	10000	10000
0d7c63714753c84870e4c86da7ca61a9	1106681277	No	Fiber	10000	10000
718dffce8c0a43ef0c0975fc4982914f	1106686516	No	Fiber	10000	10000
c4d1e318bdc9698708cb1fc8cdf02ef0	1111413015	No	Fiber	10000	10000
bee568f0036962136426c3e2071c46be	1106685112	No	Fiber	10000	10000
dfa88090c4d3c8e80c3bc625f02901aa	1089031635	No	Fiber	10000	10000
ff839b521fee42ec7e72dec5bef8fe96	1089059344	No	Fiber	10000	10000
85fe9ccceb494050d95ae924a9ba527b	1106681742	No	Fiber	10000	10000
873aa18c19e47a1d5955ff66341b5aee	1106684347	No	Fiber	10000	10000
bf07a04c328c92315eaac74b80211fce	1106686381	No	Fiber	10000	10000
9b27b1283952aafb25154c4fbe80f931	1106684863	No	Fiber	10000	10000
060b9a1a0616e9cc1c8261120f1e7e40	1089059207	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
2fa339aa2480cedff7d43a722121459d	1106680963	No	Fiber	10000	10000
9ad4c5eeb036c2cf0a73b9c8e88890f1	1106687151	No	Fiber	10000	10000
a85d600998d3c85c3eafbab4eb78e7cd	1106681924	No	Fiber	10000	10000
76a1165a273590c19f8c555ac4d8a708	1112257580	No	Fiber	10000	10000
0b1c035812a9aaaa65a6654df7107158	1106684478	No	Fiber	10000	10000
55984f989627b23cea913bf843a77040	1111405572	No	Fiber	10000	10000
8a730bec6d2c649d7d45e69b17182eb6	1286906045	No	Fiber	10000	10000
cbc0edb8f3dc731bc9e9ed859b8e5320	1089037106	No	Fiber	10000	10000
a417d7c031d50b2e27427e0029af8ba8	1089031233	No	Fiber	10000	10000
cb0a1d5d9217edb499548e4afc8991f8	1106684900	No	Fiber	10000	10000
2f80a6c79696783dabe56a38091e3204	1106683532	No	Fiber	10000	10000
efd034032099a782eb25ccf03a58784e	1111412393	No	Fiber	10000	10000
e35cbf220a11efa84fd613a3f7d5b708	1106682063	No	Fiber	10000	10000
a9e71003aed904dde4e4144e20b22445	1106682118	No	Fiber	10000	10000
9d2b045a306652c8b61d221d38ccc354	1286911690	No	Fiber	10000	10000
fc8a8e79d66d7766baed2200d4537378	1106682135	No	Fiber	10000	10000
567a00834bdba808c990f9d9b9696827	1089042451	No	Fiber	10000	10000
77a5e1b39497af5a7cff79d96198ab75	1089059200	No	Fiber	10000	10000
30c45d2632fbf5f8e32e3c514be2bff5	1111412551	No	Fiber	10000	10000
40c9a966556b44052c55fb3afd3ead00	1111413921	No	Fiber	10000	10000
baa4a7eed0d13009a0bdc02b1ec2bed	1089059287	No	Fiber	10000	10000
237e533ea4602788b67177212829d71f	1106680662	No	Fiber	10000	10000
809028e2f1161590164a073e54946ab1	1106682138	No	Fiber	10000	10000
de5eaa794261d20a2ea3b25cc4abc780	1111412034	No	Fiber	10000	10000
ed4441b0856df500754c60421aa37fdf	1106680024	No	Fiber	10000	10000
3d9dc48affe73ea3cb8fe55bdb3e190	1089040431	No	Fiber	10000	10000
b416a33136cfb74feaf647343f601028	1286905201	No	Fiber	10000	10000
c4ae92921ded5481a7658e4b8c7ebf08	1106685863	No	Fiber	10000	10000
61f6c08584b1d4dbbdf378bec50b15b	1111413891	No	Fiber	10000	10000
6030516c781ddfc04f10486a7fe09a24	1106680284	No	Fiber	10000	10000
97eee763c1aa5ccd9c4282fa5d7f9e77	1106680092	No	Fiber	10000	10000
0072fdf197cdad2584f42236326ff595	1112259022	No	Fiber	10000	10000
c2d283b50db2879574d1f0b7c977d50d	1111411419	No	Fiber	10000	10000
85036294f43ed7ae342335784370f3d8	1106684220	No	Fiber	10000	10000
25a5f5e870b85a539d5b9887013c905f	1286914680	No	Fiber	10000	10000
922ab491f93a062b87b8c300ba3d650d	1111412550	No	Fiber	10000	10000
f40c8acdae18b170e6490b0efaff22a6	1286907397	No	Fiber	10000	10000
5d3acd557cc7f87c4bf15f96aeb8caf	1384901004	No	Fiber	10000	10000
ac88cfe3e2b4f3adcceaa843a1833ccb	1106685823	No	Fiber	10000	10000
33ad854dcc5c8c7e1c707ba66a8a945f	1106687198	No	Fiber	10000	10000
c4fc0f6de2e7834fdacdc226fc0fd58	1089034333	No	Fiber	10000	10000
8e78e52092ac28d5bae35b89fdaebe3e	1106681732	No	Fiber	10000	10000
aa754462f9f03be4ac36ecaecd5d895c	1112237726	No	Fiber	10000	10000
ce733c4f14c08ecb7316164794893b09	1112239116	No	Fiber	10000	10000
d92b528efbed485643b5dfef8d35336c	1111412039	No	Fiber	10000	10000
6cf3ff02ac2aa5e203ddf53b8ebd41c6	1106681640	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
c4f99ed27f671c32b7511b4ec8cc2227	1286906257	No	Fiber	10000	10000
477905d459281cf72bd4915e16c07acc	1106686614	No	Fiber	10000	10000
da41ded9e4fccc4e53c04661e5886ff9	1111410390	No	Fiber	10000	10000
77a085ecdb1115cca8ffe3930ed8daa3	1106685014	No	Fiber	10000	10000
4e6cbcd0678ad956d5036cee58253756	1106686111	No	Fiber	10000	10000
f7c32a08ccb0fd32c1600aa65e29d53	1106680364	No	Fiber	10000	10000
718cab7cec56213981bb59c873696d04	1385050343	No	Fiber	10000	10000
c31be822b046f2fceb7860f2ab74102a	1111412056	No	Fiber	10000	10000
b6e2ef5d3597930f5ed683a0de0b6085	1106685389	No	Fiber	10000	10000
e38b24d48a38c612e1aa69d1e67945e0	1111413512	No	Fiber	10000	10000
85ee3e6db26dfa705422ca3c7eebaf44	1106679473	No	Fiber	10000	10000
fc675f5cbe1701fb870c379373276efc	1313751585	No	Fiber	10000	10000
a5db671b2085ce75b561c6d32fd30bd0	1112239100	No	Fiber	10000	10000
7f2029a409ffe4f7d18174c37bb8164b	1111404788	No	Fiber	10000	10000
6d6e7aa02fb357ec843ab4ce11f103b7	1106680481	No	Fiber	10000	10000
712546119c1e84b8710d4676999ecffa	1111410345	No	Fiber	10000	10000
69ee705a8778d5ce926e2c308bcdff4a	1112239101	No	Fiber	10000	10000
456c6c80bd5890c56ba9360d07c66f11	1106687025	No	Fiber	10000	10000
be74d49c1dd4215cc7daa4d73a571dd0	1286906372	No	Fiber	10000	10000
ebd5bf9f694aafd4b271f8f386e850a4	1106687453	No	Fiber	10000	10000
6d53a7c457a4c325abcb088e3c9b91cf	1286907385	No	Fiber	10000	10000
aa8ed164b020a929fe1a39f022b27fe8	1112235921	No	Fiber	10000	10000
559a2b658aad1fe017a734de8002aa9a	1112239121	No	Fiber	10000	10000
659aa658686dc8783fba565236d163db	1106683720	No	Fiber	10000	10000
3856d4ccc09f7312e1bfb6d4875e85e	1106679958	No	Fiber	10000	10000
76c8be6208fd6123f8a9e8a8113a9cb0	1111405154	No	Fiber	10000	10000
af8b68035b56a991bb66bf5b819b6f31	1106680759	No	Fiber	10000	10000
49de536e70c685dc7982cd2631d867cd	1089032761	No	Fiber	10000	10000
d44e675433fbe374a0b94d88a11f7e18	1106684328	No	Fiber	10000	10000
2e4b2d8b28317a58894c65f5995672f6	1111413330	No	Fiber	10000	10000
62bdada172bec3dc35ab7b36a87604b4	1286906129	No	Fiber	10000	10000
e4dfa4d2f023b36bf79bd24b83dc0a68	1286911174	No	Fiber	10000	10000
b348df17c5dd21b612eabaecff9ad0a9	1106684958	No	Fiber	10000	10000
b7c585e73b1c7b43127c22d83c6c8760	1089041408	No	Fiber	10000	10000
99976b79edfb9ee9d222442cca37100c	1089034567	No	Fiber	10000	10000
135eb223956ebd76e6e521cbdded9f43b	1111413215	No	Fiber	10000	10000
ceac4e719a0f0b21b3b933583ae21836	1286905616	No	Fiber	10000	10000
ec647651295773f35c6bb4bf70fa56fe	1112225919	No	Fiber	10000	10000
3788c5f6b4d74124678186a9588855d2	1286907469	No	Fiber	10000	10000
81e210ea6738b5588f41191da630e0f7	1286906922	No	Fiber	10000	10000
f829e2e9b035abcc9bf8087a70db8042	1286910850	No	Fiber	10000	10000
a5e59eedfc02294abe87470652fd0ff2	1111414587	No	Fiber	10000	10000
8d121023d9afe490119cb5789b727f25	1106679359	No	Fiber	10000	10000
f006bc5b66d2601d32cb77fd6458c52c	1106679753	No	Fiber	10000	10000
b14b32601f477b27832c8cc0ee897b5c	1112239094	No	Fiber	10000	10000
6164e5db473c713b2c9fe39dd6957d7c	1286914594	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
c6a5804aa8ac5a5c41a656744e080a1d	1106681459	No	Fiber	10000	10000
c62c658c8abb209acbccce985ab9f507	1089034396	No	Fiber	10000	10000
966fcdbae6c15b585acf2df26079ce07	1286908942	No	Fiber	10000	10000
6dd83565a73d46a3d15e9ee4c6ffc57a	1286913388	No	Fiber	10000	10000
791bb9c8bdeb82fc5eca07bd23a37258	1106684540	No	Fiber	10000	10000
cda999bcf75225aeb6122e23cceba401e	1111414620	No	Fiber	10000	10000
25040782417fcaacc34dccc0f6fa092d	1106683793	No	Fiber	10000	10000
c1cc10304a4f9d7817c181060a0f09dc	1106682337	No	Fiber	10000	10000
ca22f95e2ddb9c70397764b0facb104	1089059217	No	Fiber	10000	10000
530f812a9453d7aa8fde86da0f9d0e68	1286914170	No	Fiber	10000	10000
364db1c64384dd2a0bd5016ffaa75346	1106683355	No	Fiber	10000	10000
9b1f78c8b78cfd4d72a239bf954f9f8f	1106683812	No	Fiber	10000	10000
caccb4a69b89521e27d695e5fc17d398	1106683264	No	Fiber	10000	10000
ad1ca5e94e46b57ad81fd41063dc9782	1111405159	No	Fiber	10000	10000
02e1c7b4ef794cb681abf5d1f0d2597d	1106682379	No	Fiber	10000	10000
a62beb4dcf4c302043069ad5b0380626	1089055459	No	Fiber	10000	10000
c8ef720074f8cc1b004d12d92332c336	1106680358	No	Fiber	10000	10000
9cb7baccee926f9161e8b563622c6d58	1106680097	No	Fiber	10000	10000
76b73469248c77ab9ff487d3f293d71b	1089059417	No	Fiber	10000	10000
7f3a16c2f13a0f41f33a8d40512f1d6c	1286914078	No	Fiber	10000	10000
998d857ff1003792aa533a8ae3b920e2	1106680338	No	Fiber	10000	10000
1cd441a30075a546ab06604b2826ad81	1106679724	No	Fiber	10000	10000
943d8e2f8f0bcdfd52100f2d7c992588	1286904565	No	Fiber	10000	10000
f29d53f7793d15ff2752e6310efac24c	1112239073	No	Fiber	10000	10000
07e3f16957656b234f01207b807f57ae	1286911329	No	Fiber	10000	10000
5300e423b4f298f6964b58e6b9d2b92b	1106680076	No	Fiber	10000	10000
1ea2ee338e35ca7745ef3f8a97cc3b7d	1111415077	No	Fiber	10000	10000
689d64d6c69843efa1838ce5a1988d51	1089034249	No	Fiber	10000	10000
c5e795614a53bdc3de303162cab07824	1106680267	No	Fiber	10000	10000
a70dd6b03968209fc7895104a7a961e0	1106681945	No	Fiber	10000	10000
eccec6e7594311b2ed6758053e85ee1ef	1384901514	No	Fiber	10000	10000
802be495b88102b571bbddb60fae3921	1106679744	No	Fiber	10000	10000
93ca7174fb24a8325343dc8c0a3cc25b	1286907004	No	Fiber	10000	10000
e77ae5c44fccbba6d3106f9a3a47caba	1111409912	No	Fiber	10000	10000
9e3739d46e7544573ad4003c8d516e1f	1089059327	No	Fiber	10000	10000
94266c44bb2696baf995f05937d2ae1c	1089042257	No	Fiber	10000	10000
992679325e1868471fc44636006b80de	1106685895	No	Fiber	10000	10000
288de55ffccbb3365625a87fa764e408	1106686897	No	Fiber	10000	10000
3946d2759bc8dcdcd327bab9bd595f94	1106686870	No	Fiber	10000	10000
931d10dfa25fa99051c3bce82c97749c	1106680422	No	Fiber	10000	10000
ff017c072dd3184d6d2926bada216eb8	1106680408	No	Fiber	10000	10000
d6a28d653e1975fba5ac26df3e129b1d	1286906943	No	Fiber	10000	10000
092df6df0b50a2f06b65401890cfd17a	1106684156	No	Fiber	10000	10000
874aaf3923c666bca5f8ebae1ea83e97	1089059396	No	Fiber	10000	10000
fb43a18be4b5ed1fc16dfc8ab49ad75a	1089031956	No	Fiber	10000	10000
61dee842edf745345c14ac5529b8d36e	1089032782	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
2ce0adebf4b416fb1c63250acf6db1a6	1106682306	No	Fiber	10000	10000
8b0af5c83e6b227f4c32794594cf32c0	1112239071	No	Fiber	10000	10000
6490238f8c4c98f3f4fb9642f456b9c9	1111413048	No	Fiber	10000	10000
3fd18494052b477e78801a64b0cfdeb8	1106683989	No	Fiber	10000	10000
1c136306f245e0e5104573ddfea9558f	1111404561	No	Fiber	10000	10000
b54f5e6d18d79d67f4b86fb40d38800f	1106681571	No	Fiber	10000	10000
4b88acd6d08188f8e417e70dfe9b98a4	1111423877	No	Fiber	10000	10000
0447334763051b15743aa3f02cda402d	1106685319	No	Fiber	10000	10000
641d6c80028102cb31c127aa94d6d3fe	1384899010	No	Fiber	10000	10000
da87c51c16eea121937e06193ee46555	1286912033	No	Fiber	10000	10000
0a648410fef7e831620f932190aad4eb	1106686323	No	Fiber	10000	10000
ed8e305ed88efd7da60b54c173d916f5	1106685189	No	Fiber	10000	10000
18db380838f06b63c70e0f5eb86f1f51	1089060008	No	Fiber	10000	10000
865fc658bd857d6d89558edb21ee0377	1111413049	No	Fiber	10000	10000
348b8d8c70d07dfb17286fdc86934864	1089059225	No	Fiber	10000	10000
8ef9e4af4ed1cd6f28b5ecb747cb006c	1089039714	No	Fiber	10000	10000
e919490f9ff557c7ff4fae9a95aabb34	1089059767	No	Fiber	10000	10000
69c438ce936f1733fd4ca71f8a36469d	1106682817	No	Fiber	10000	10000
c2efea8dde3a4e0cc3a20b4a574c7f5a	1286910491	No	Fiber	10000	10000
e2b195e1e339cc15b31601006c65d21a	1111413032	No	Fiber	10000	10000
ec72b0cb60f9a460f7cf2824eab2e08c	1106682905	No	Fiber	10000	10000
cd71fe9ddc85c5963734430926d2fcb	1106686043	No	Fiber	10000	10000
f48ddcb41387a9e13ebc674425fb7ef5	1112239088	No	Fiber	10000	10000
cf3936dc1ab3a07c64004e2b0aa5183f	1089059421	No	Fiber	10000	10000
cf27a2e15c0b52d57f1e0493d7f5db1b	1106680760	No	Fiber	10000	10000
9beaf3618a7d074a22fc17482e9bf9bb	1286906087	No	Fiber	10000	10000
d7824f843e0692463d2457d2f1373c33	1111413226	No	Fiber	10000	10000
10b7e98ba12297a19cf5e186fd7fef8c	1106681512	No	Fiber	10000	10000
bbb1fff03ee852116a4126a4ba848ac9	1384580614	No	Fiber	10000	10000
8aa11190c54f5a8abb3c30049d8dc828	1106680150	No	Fiber	10000	10000
815d7619b35b07a0f8221d03698707dc	1106686892	No	Fiber	10000	10000
e763dbbb77639ff5ccb09a2366cdc197	1106683866	No	Fiber	10000	10000
e5d5c6b2900798a45893a0c03b434dcd	1106681149	No	Fiber	10000	10000
dd60bcdf8467eb889c49dcc7892af6e5	1384899501	No	Fiber	10000	10000
6ea6a57a3d6e1f904ab5916e6bfc1c5f	1106680030	No	Fiber	10000	10000
4bb8eec2d8d31210efc9d237417d759e	1089034552	No	Fiber	10000	10000
2eae79a619214bb34a1b78faff754de3	1089032675	No	Fiber	10000	10000
5cb7edf2ab77210af632155d0bc3605d	1112257565	No	Fiber	10000	10000
4435d24f068139935c6257e7f469d3f8	1106680839	No	Fiber	10000	10000
390a86f52ac559744a05202941f946ae	1111411978	No	Fiber	10000	10000
1729e9e6b2137ca292b910d6c04f1463	1111405178	No	Fiber	10000	10000
26e3d7d2a93a64e3449b8d75d4d67d31	1286905205	No	Fiber	10000	10000
85917461476a46e99e153e695eb15433	1106679469	No	Fiber	10000	10000
706b5f3364e6cbf79cc97c3338c1b018	1106686534	No	Fiber	10000	10000
5bd8eb29a49c18fb9acb71d85fac49af	1111413213	No	Fiber	10000	10000
5bfb712e3ba54d30c24ca17515e263b3	1089059741	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
82816e8be490b9127afd4b6ec17ca07d	1384898010	No	Fiber	10000	10000
cc5323d6b183eed06155bd039394496e	1106681118	No	Fiber	10000	10000
4055010b5e3cbb9be09cd70861611e9b	1089059194	No	Fiber	10000	10000
9cd149f0e330ec58702d1b19301b7773	1111413281	No	Fiber	10000	10000
9cd4ffdf1be60b7d05b86f07bc1143af	1451746044	No	Fiber	10000	10000
c45602eb95cfa14a2b7386a0b9be39d6	1111413206	No	Fiber	10000	10000
483644b31dedfc24200275d524321a00	1106679386	No	Fiber	10000	10000
5312e3ccc28d4fdc72e2de5632df335f	1089034332	No	Fiber	10000	10000
170191c412860d08b7e41849d96d308e	1286913561	No	Fiber	10000	10000
dd1acfe13319d2caed7bc69944110f71	1286909075	No	Fiber	10000	10000
11c586c11d8067c2e875ad0295441fd4	1106681935	No	Fiber	10000	10000
d1291e9e61636c7d808c8f145684d965	1111404922	No	Fiber	10000	10000
a7f69336cad5b7daa2666f97e25fa198	1089034318	No	Fiber	10000	10000
b4ca2807528d919012fa4d83a8bdda8f	1106686824	No	Fiber	10000	10000
fee266e676adeb1082aaad1ee4ebb57e	1089034366	No	Fiber	10000	10000
7fd1231d9c62e3daa0510875790741fb	1089034404	No	Fiber	10000	10000
0eb889d7aea1dc984434ec27c1965122	1106681087	No	Fiber	10000	10000
b14415f691c23dd0292e4b057d97c663	1106686050	No	Fiber	10000	10000
fafcdcd243acea82e380d2abd3bc05e7	1089032731	No	Fiber	10000	10000
efa9cfda5dc0e7eb1cd8802096ff66ae	1089059839	No	Fiber	10000	10000
621357797de8ac44e0cccfe75e108917	1089059392	No	Fiber	10000	10000
08108bf82e321cf658a3a978a9a10423	1106679976	No	Fiber	10000	10000
d2758226cb79757a48dc0536111ea6c0	1286905134	No	Fiber	10000	10000
fe8fccfe84c3126030dd33475557b8aa	1106682144	No	Fiber	10000	10000
f5e883d583bbd07607f5862441f11665	1384899499	No	Fiber	10000	10000
efcdaa506b6f74976afb484257eb19dc	1111409724	No	Fiber	10000	10000
65e174e704286e63d1eaef4f1e87da8	1106680849	No	Fiber	10000	10000
f0ac0eae82f40e6bb3e6ce3c9f9bade2	1106681904	No	Fiber	10000	10000
886e8c0dedb9489329b13e310d4b070d	1106679981	No	Fiber	10000	10000
3458a2721e70b3882ad4138fd2dcff3e	1106684747	No	Fiber	10000	10000
4ab68b3538dbfe85d0ef8451e39900a3	1111405850	No	Fiber	10000	10000
0c9ba11f2c3cb05aa4856bef6d0d28e6	1106681350	No	Fiber	10000	10000
9e4df9d73272365ed5f049d00d07e7dc	1286907373	No	Fiber	10000	10000
0f5896d3b7827d512d435356be9c8626	1106683518	No	Fiber	10000	10000
41368d959e14940c29e4a95596df35f9	1106680824	No	Fiber	10000	10000
0c8b37d865a0f9849f671e7e317ab99e	1112236589	No	Fiber	10000	10000
4ce3eff667f0c3c5f158b3bbaf0811b9	1106680736	No	Fiber	10000	10000
3dbe69196ff6ab3c0691b2e50f7a6241	1089042919	No	Fiber	10000	10000
80a432fcd542b55d8549060853e00581	1089034317	No	Fiber	10000	10000
7af155296f7f8d73ab6afe500acf56b9	1286906477	No	Fiber	10000	10000
58c744a947dc11428c2dd0116820dad6	1112256277	No	Fiber	10000	10000
ca19de473f549037d7806b449608b31b	1106680912	No	Fiber	10000	10000
1d2bdd6866beeddd9b839e89ca77e85d	1106679125	No	Fiber	10000	10000
7f678f88a3ecb8aed569ef41a82fea7d	1106682575	No	Fiber	10000	10000
dc8dd06cc4d0b7c0b6b41dede7b2b912	1089042277	No	Fiber	10000	10000
f739acba940ebe47b29e2e053b28b3ff	1111413014	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
dbca1af4f85b41540590b9fb3e4ad7a5	1413411256	No	Fiber	10000	10000
2722a11ba47c2153ba098165d0dca563	1106684855	No	Fiber	10000	10000
0c6db57cd1bd2db85d23b0574695ca52	1286911328	No	Fiber	10000	10000
dbc26abf9895ef4de722007b0866ef70	1106681930	No	Fiber	10000	10000
0e5dcd4325aff487e2ab9484b042d91f	1111413272	No	Fiber	10000	10000
bf8dd1531f75b2d8157816566eaba344	1106684344	No	Fiber	10000	10000
d7f0db747b8751f7ad882456fccb2256	1111405596	No	Fiber	10000	10000
addc1003c9c7e86c92459dc897dcf993	1106686723	No	Fiber	10000	10000
44d24c480b9f8887e6aa1a75ebec5517	1286911891	No	Fiber	10000	10000
e1e6e3fa19838b54e664f66cf4f8cb5	1112261288	No	Fiber	10000	10000
2cae7b46d1a6703ec3641c3b1866628c	1106685285	No	Fiber	10000	10000
b7b96bc627f37397e63a18bbfbd401e1	1286913114	No	Fiber	10000	10000
f9c7668bab501d9d767ec0a7c8cb821f	1106680992	No	Fiber	10000	10000
cf04d08d24c80bc9ec47ec4d3ed6a1e7	1089039697	No	Fiber	10000	10000
8bfd55344a596034d39340de395cb38	1089039686	No	Fiber	10000	10000
b1905fd1032382d6e874c7dc4999e6dd	1089031237	No	Fiber	10000	10000
a2c043354fc3b20607bf06766b86d944	1089034283	No	Fiber	10000	10000
2682ebc8bb6a529c2acd33709bba5e86	1106685249	No	Fiber	10000	10000
7a056f7a25781442aca5725f94e78203	1106686268	No	Fiber	10000	10000
77fdbc94ce02d7766ce4c85dae6cb60b	1106682962	No	Fiber	10000	10000
1ca8182830647fc50f879cd3742abef8	1286908865	No	Fiber	10000	10000
d7e29ccfd5f932acbdcb69bb3aa973bd4	1106684300	No	Fiber	10000	10000
717b2e2b55b2dc207162c329920e6eaf	1106681580	No	Fiber	10000	10000
e415616c5d8458dc8144164b5ec6438b	1106684301	No	Fiber	10000	10000
c010cf10e13839b8ae576ffad7507060	1106687065	No	Fiber	10000	10000
c35539a74ff7294fbedaef2d0dd6c9a0	1413407060	No	Fiber	10000	10000
8cd84e3124895e6de83537921498bf41	1286912385	No	Fiber	10000	10000
824e61ee8eeb271a2b19c3c93e3036eb	1286911399	No	Fiber	10000	10000
16cbc006319e17bfc256f76014f01e2	1112225504	No	Fiber	10000	10000
5e31b86cee56d794f2e965e6f1fb6e60	1111410089	No	Fiber	10000	10000
992fdeb3d0d63f88ba6fed73bf5b56a8	1089032097	No	Fiber	10000	10000
e8e42d3101baae369eadbf75bedac3ac	1111409917	No	Fiber	10000	10000
25289d2c5abbcb1409081d9bdf171d99	1286913359	No	Fiber	10000	10000
f9cb950f7e5ce2b862c2f05bc5a99e03	1111406485	No	Fiber	10000	10000
10faa228dcd28b0a0e212d9eed8dff85	1089040426	No	Fiber	10000	10000
cb30ae3d3fd94deef28743549ac8947	1106684509	No	Fiber	10000	10000
f82023d8c4b768fc18b09889ecf662f8	1384899668	No	Fiber	10000	10000
f00dea61f95c1277521abe87a3533fa1	1111405203	No	Fiber	10000	10000
3a5058c61c9c7ad2dad8e2ee543ed79b	1106684226	No	Fiber	10000	10000
513c9fdb6fd099fb6a09a71dd0e36ab6	1413411066	No	Fiber	10000	10000
bc2d27650369863ef947bf9d59a36b3e	1111413275	No	Fiber	10000	10000
950eee21f9575e2c4910d24d808e6973	1106681315	No	Fiber	10000	10000
b8597bf6f05e36c4d01d4fcd7031f09	1111412543	No	Fiber	10000	10000
33f86b7a3a609b428caf8bf031bd9304	1112239082	No	Fiber	10000	10000
ec40e49180a706f09896f38634ea6d13	1106683547	No	Fiber	10000	10000
1c6f7242c4461dcdec267cc42edeea6	1111412037	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
279585defa672f5c6737b6eb576bd039	1106679779	No	Fiber	10000	10000
ddea19927ce4e1b3650409c78d2433d3	1106685013	No	Fiber	10000	10000
cf32566710fd80741d59832a7c96d638	1111411814	No	Fiber	10000	10000
839d90895bc35377795fabeeff8667207	1106681968	No	Fiber	10000	10000
99a855257308b5b7d5f878bedfcc3219	1089059106	No	Fiber	10000	10000
86509b0f86c800dbd571d5207098f069	1111410336	No	Fiber	10000	10000
0bf1247e278d60488614e3b5a50be6c7	1106686286	No	Fiber	10000	10000
1ad2ed67a7fcbfdb4d540ee11362b9da	1106684076	No	Fiber	10000	10000
e0b8f7b7bd0c9b6afd9479086bc71cde	1106681518	No	Fiber	10000	10000
0ffb2c1b54a699189bedc777afc1a781	1089039721	No	Fiber	10000	10000
dece38e0144f4e1f963bbb432925b568	1111413034	No	Fiber	10000	10000
32ed861c8b7f02f39ded4b4d29286eab	1106680452	No	Fiber	10000	10000
55c043d6f956f86b72a97317965b7ec6	1286911007	No	Fiber	10000	10000
96356a5c66ed0680e52081fee090c141	1089040447	No	Fiber	10000	10000
382a91c9ba98fa6e4661a75144a04d09	1106683948	No	Fiber	10000	10000
104042a062dcfcd732ce2c56a8f2df3	1111427338	No	Fiber	10000	10000
00767311129f37f0aea20b887ef97af8	1413421468	No	Fiber	10000	10000
24a175eede5b76db3115da6ae613e861	1089044885	No	Fiber	10000	10000
096266aa87747468b41e5e4b8f66cb97	1111429329	No	Fiber	10000	10000
73b80e8f8a0d8c1ea50a3146130ea64f	1106679388	No	Fiber	10000	10000
f6ceed92c4049b4bdc92d89670894ba1	1089059346	No	Fiber	10000	10000
c6f77dfe16720c22f32c2640f74d3620	1111413024	No	Fiber	10000	10000
2cb172585fdc0d3b054e7f196644bf55	1089034380	No	Fiber	10000	10000
a0fcdd0215634e84b909791918531828	1384679510	No	Fiber	10000	10000
a8d9a318390b970067086f095658cb3e	1106682886	No	Fiber	10000	10000
253e94851c24415a8136a55f5cfa4be4	1111405885	No	Fiber	10000	10000
47b10323ffc1a53cf9d9731aa14f1f0d	1384898257	No	Fiber	10000	10000
9ed163667ae2b522ff397c9c0a6bd4c9	1111412284	No	Fiber	10000	10000
c64cbe193f833976d945f418b95f6ad0	1106682660	No	Fiber	10000	10000
5fbbb8286245356fce8026abd5002eea	1089059772	No	Fiber	10000	10000
88a1bc96444eaf5044a8f7ea3b717aea	1106687181	No	Fiber	10000	10000
1ae17f0370c02294bf32c9d308ded9a3	1111411319	No	Fiber	10000	10000
092274b7c2f0a1783756529399fba5ec	1106682686	No	Fiber	10000	10000
1cd3476da9c28cfed49ed01ad841c20f	1111413525	No	Fiber	10000	10000
1016e7999a3262762dfff4dc46b006d	1106683129	No	Fiber	10000	10000
d1be73f9fa8b6c9bdd3202c397fd62b5	1111412545	No	Fiber	10000	10000
d92b4ecd0d33ac86edf0e815f4deff82	1111412030	No	Fiber	10000	10000
48f359c9b2c3619f89da56680a74e6c2	1106680696	No	Fiber	10000	10000
e45d3523abfa5cc97fe0a8d166b84b0a	1089042234	No	Fiber	10000	10000
9166bee9f2c5affa93d41abb43cc9ede	1106679690	No	Fiber	10000	10000
0674df63a34b49e6d1ed65e54aa978dd	1089055538	No	Fiber	10000	10000
8ca2b2aee9e947a547580bde4be1911c	1106681621	No	Fiber	10000	10000
e7056c1c32fc40c15c3f5f0e24b07e2e	1106682833	No	Fiber	10000	10000
ac570ea7edb66876368faa9db23b4353	1106683549	No	Fiber	10000	10000
0f78600027d346e95e384422312b6733	1106685086	No	Fiber	10000	10000
a0728dc29042297c469649e22c653a96	1089055462	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
ae01af8a5c32bbaf5726f714f0bb8550	1111411462	No	Fiber	10000	10000
a895a375efd09228d179bc6a57ce50d3	1111413429	No	Fiber	10000	10000
f0584e690d937d132ddedc29de5f31d1	1286908612	No	Fiber	10000	10000
194b422a89e84225c3d2fa74a922a2af	1111413235	No	Fiber	10000	10000
0b247421de1e34b5145c9092c3caf82f	1089059487	No	Fiber	10000	10000
939237663a86b88ac017e3ad63233a73	1106680941	No	Fiber	10000	10000
7d39f4bc06d94cf3e996a6b633aea615	1286904485	No	Fiber	10000	10000
3241ef961ea5df2cd5f6c1cb8732b094	1111412544	No	Fiber	10000	10000
54ae3d3f0500671415289b2a06a99178	1106686563	No	Fiber	10000	10000
6c4e2f8bfe3e9c7a14a07adfd5621599	1111419637	No	Fiber	10000	10000
800ee0afbcbdb700232a017d53be57e3	1111413051	No	Fiber	10000	10000
3dd3ff654a9f58d26464a4e2f817380c	1106685799	No	Fiber	10000	10000
a243769034f443f0e98d3400f62c3b34	1106680265	No	Fiber	10000	10000
b8a13a2e29b34b6fd1e36b85e9495cdf	1286914002	No	Fiber	10000	10000
98300a89771bc2afc672c926183f2d52	1106680815	No	Fiber	10000	10000
d522a31d400450d6fe7d4b61c87a4db5	1106686994	No	Fiber	10000	10000
166d4a53c44b371cd9fde0be0ca4d334	1112236585	No	Fiber	10000	10000
e9bed381235a593bec6b9b84d7a9f276	1286904497	No	Fiber	10000	10000
a9512e5e23658b262f207dbe56559b30	1106682028	No	Fiber	10000	10000
89dfbf13238fad54a056bcfab954df33	1286912167	No	Fiber	10000	10000
ccae8d5e629f09afef190760140d4ea2	1106685890	No	Fiber	10000	10000
be92b9408c8c4b6810344d2383172366	1089059990	No	Fiber	10000	10000
5970b5caee0bb0395ea6fddd080428a8	1089059393	No	Fiber	10000	10000
abea623d7078cee3ae5da184052e3dc8	1286915567	No	Fiber	10000	10000
7d7740820c93ac2446d9df122b8e2504	1111413870	No	Fiber	10000	10000
98c8f13085eb6733905ab927f0e3eeaa	1106683654	No	Fiber	10000	10000
4fa65284eb4feef7d137a17e8c2eb9a5	1106681610	No	Fiber	10000	10000
783bad0bbbedf8eb87514bd380774498f	1106686473	No	Fiber	10000	10000
d05d1ae41ecc846a16ae8a3ea7da9eed	1111413121	No	Fiber	10000	10000
97a8167f0694f884371403638e8654bd	1089059208	No	Fiber	10000	10000
2129d7c7f79f756ae3628606031cd8b4	1286904898	No	Fiber	10000	10000
a696447c3749684b1d85b0923f008a59	1089040428	No	Fiber	10000	10000
240ef7f8a61508bc0d35f51a16ab96e7	1106685776	No	Fiber	10000	10000
2f056219f3654a69a294def1860389a3	1111417558	No	Fiber	10000	10000
aa08657ec7cdae6dd79bea3f0390decc	1106682481	No	Fiber	10000	10000
5f44b402c5bfa431a83c5e1435b75691	1106680966	No	Fiber	10000	10000
cc324e5dd4975a4e90c8f05c4784fb6	1106686096	No	Fiber	10000	10000
a3db1e48a776de81d708e8bf2602fb53	1111413989	No	Fiber	10000	10000
72019f2ccfa8628340e297816eb6229d	1106685425	No	Fiber	10000	10000
0c42164fd9532ee1964f6fb5fe55cfd5	1106686854	No	Fiber	10000	10000
5f5ced685641a911304d383a1c124441	1106681771	No	Fiber	10000	10000
5a9816a64f04c548f29ca7d748c652e2	1112259003	No	Fiber	10000	10000
33fc2ae3ad9a0deabf3fbae26bb8387c	1106684471	No	Fiber	10000	10000
c93aef3671a60a51fbf9c7c6a6b1e78b	1106680460	No	Fiber	10000	10000
522137f996f7733df229d3d6d5922c05	1286909357	No	Fiber	10000	10000
6d665af1bb7144d4b382ebc7888def8d	1089059223	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
07455f912cbe7df8660837e12b818be0	1286910979	No	Fiber	10000	10000
ef5b66ebc4d61c69d7206d5d525d2ed8	1106683660	No	Fiber	10000	10000
9f1b209df790b64cb7ecde742fcd5223	1106687097	No	Fiber	10000	10000
a0fb4ebf7007d668fcc70c6d45a0d73b	1106683278	No	Fiber	10000	10000
fb22d7f80b0c58282d2d591cb58a0067	1106682134	No	Fiber	10000	10000
956d0135509cafab5a4112a212aff4ca	1111405881	No	Fiber	10000	10000
36147bd2596d823c0f8f9922f5aea9ed	1111411436	No	Fiber	10000	10000
c35bbe6a4fcd65df4a62e3953ebf375e	1106682025	No	Fiber	10000	10000
9aaa3a9519b10ad6f555158d7607cb13	1286910011	No	Fiber	10000	10000
b59f8e85ed3d04f64ccc026cfef0eb95	1106681485	No	Fiber	10000	10000
6d3934d92f16fae279fa266bed2b7169	1106685151	No	Fiber	10000	10000
324bcb21fc216f9da6e5074179a21c3b	1089039746	No	Fiber	10000	10000
a60cb3cbdce04a68c53193f3011d60c6	1089039482	No	Fiber	10000	10000
82676e533fad23cd4eab90f048b7b4e9	1286910860	No	Fiber	10000	10000
074527a15f33ee7cf765d7d53e719339	1106684693	No	Fiber	10000	10000
319441a76799c719ca0570b9550e965b	1106683698	No	Fiber	10000	10000
ba116cce8f4f2842e0e1551c1a872086	1089040439	No	Fiber	10000	10000
8ad4a321c6d188a4908b4b8a525f2399	1106684943	No	Fiber	10000	10000
51fbc7ec2ff0b013aff4f196c5e5705b	1111423326	No	Fiber	10000	10000
bc8476570107d65c14b5ad9075d3d20e	1111415052	No	Fiber	10000	10000
a94bc34ac85ac4efe61a8a65e862f1d4	1089042456	No	Fiber	10000	10000
5d5cdc9c7aa2514b3b312db750a36ae8	1111405354	No	Fiber	10000	10000
71350f31d3f8395685eb6ff9ee8a4a94	1089059771	No	Fiber	10000	10000
4551c62f4df01ef508d7de24dc07a666	1106686433	No	Fiber	10000	10000
f47a9faaa6b820142fb161065f93c45b	1106683790	No	Fiber	10000	10000
72988756ec7426735f217b18fb601ba9	1089059824	No	Fiber	10000	10000
3336b5749d2bf11d408e1db7c72258ae	1106680294	No	Fiber	10000	10000
4b7b8ed344c755b3873619f5c649a050	1089060000	No	Fiber	10000	10000
e5cb7bc0e3c18958f411fbc13a201a88	1111411534	No	Fiber	10000	10000
d250122c5d832df662f5708a70f153ef	1111405156	No	Fiber	10000	10000
1f6356ec513153078e7a9649254e0bfa	1106683531	No	Fiber	10000	10000
4a51eb0dfdef611be313791f212ae296	1106683193	No	Fiber	10000	10000
29510797d7b675552dcfaecd013bbfd4	1286911861	No	Fiber	10000	10000
42684e815ff4d07ccff294e483eb641c	1089059773	No	Fiber	10000	10000
6e5979ed0ff1635a89bf321995c58494	1112236590	No	Fiber	10000	10000
55c8b260ac00b3161b0c1ca32fb35cf4	1286912422	No	Fiber	10000	10000
0559c973ecb88731a7ba4d02ea2b75ad	1106682643	No	Fiber	10000	10000
8c6e3e7abd657308466d5db77ed821d7	1286907899	No	Fiber	10000	10000
8687dc9af131c3047d4566cdb9050828	1111412707	No	Fiber	10000	10000
1ca173aac3e1a88471547f6fa68d259	1286913184	No	Fiber	10000	10000
279ac138ab2c30424fc7ed3eeb957926	1106683285	No	Fiber	10000	10000
8dada1f375d679b6c216142594a7df92	1112239104	No	Fiber	10000	10000
6936980b8a21ece828165672fe0931c1	1111405891	No	Fiber	10000	10000
9bd29fb87ec02f78c663853d82683a1a	1286904896	No	Fiber	10000	10000
abcd96870929e22b36d3c66d7c54dcc1	1106691244	No	Fiber	10000	10000
71cb615f4f35bbbed1a4d958466d3a1f8	1111405575	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
46648ae8f030b830e2f6129d48390824	1106683296	No	Fiber	10000	10000
8ee492004d4ad3fcc16dfbe193833b7d	1106686065	No	Fiber	10000	10000
20cd7f1995abb5319e7875b1f87c5c60	1106680906	No	Fiber	10000	10000
1913a906b16730c7fccaaca31ce86d1e	1286911221	No	Fiber	10000	10000
15e662b0532be82cd710cac1b23003f5	1112239067	No	Fiber	10000	10000
6a1c52a0a3f3750b057cd358ba9c15e2	1089040432	No	Fiber	10000	10000
819b04be5a181440e8f4b61b7ca6e633	1106681333	No	Fiber	10000	10000
ce60dfb63ddaf79d8391493a208edb29	1106685519	No	Fiber	10000	10000
842767c3972748f41e199909b07f0114	1106682482	No	Fiber	10000	10000
e12c13b03b01dd92ce6b29c55b4b30bb	1286907872	No	Fiber	10000	10000
112233895632eab434396fbc8a38f90	1106679803	No	Fiber	10000	10000
356fabfc123504e3bb038b1734810017	1106684343	No	Fiber	10000	10000
4cf28df4adc6423df35637a02821c6b5	1286904901	No	Fiber	10000	10000
8e0baa4549fdac0ddb1edccfd9a6270c	1106680803	No	Fiber	10000	10000
dd72b603032619bd15d29a584514e305	1106685871	No	Fiber	10000	10000
2f45832ef203a04343cafdb601590230	1111405848	No	Fiber	10000	10000
57b7a4b013f41e3d3b6287514e030ea9	1106680725	No	Fiber	10000	10000
9b677e30b0dee663b3f624bf37da6a6a	1112257346	No	Fiber	10000	10000
b26781fb659ba8109b42ea10a331a26e	1286911810	No	Fiber	10000	10000
ee286a2258dfd4b862bf8ecb385c5b61	1106684957	No	Fiber	10000	10000
f3f5e0d17ba3d7ed9d05857a9527747c	1106679697	No	Fiber	10000	10000
75169ad1ac74e72575c7a6ba3857e761	1106679583	No	Fiber	10000	10000
e04137c26265f0ece100cb84e5a6f4c5	1106684556	No	Fiber	10000	10000
53f032916ce9d38ad6f8f915fb09328b	1111406200	No	Fiber	10000	10000
dcae0832db20d6845ae5dbcd20e3d202	1089032094	No	Fiber	10000	10000
00c33640cbc76b287ef9ef44e008c841	1106684106	No	Fiber	10000	10000
e378453bb21409be9fa4e2491b60b1f7	1111406122	No	Fiber	10000	10000
c313a9d695750753dc67ac0beadbf182	1106686658	No	Fiber	10000	10000
ffd515411de6919596a83d86a2d501ff	1413407106	No	Fiber	10000	10000
09e56634b5200f7d82001ec8d6f8c696	1106684270	No	Fiber	10000	10000
45f180441a38cdba52e9136f48d0919b	1089059717	No	Fiber	10000	10000
d90727ab6673d713e7b0fd6c88cd4434	1286908132	No	Fiber	10000	10000
5278548dd1f82b0c52c67e7cc73d6f0f	1106681532	No	Fiber	10000	10000
0caa61e017851bc29f1965c0f527f290	1286904912	No	Fiber	10000	10000
6d1519d0099d787d1f5c03f309955d15	1111413208	No	Fiber	10000	10000
0a61dba3273b6f926984a955b1690cd7	1112239113	No	Fiber	10000	10000
9991ceaebe89b320d715846b8f05489c	1106684832	No	Fiber	10000	10000
984af9eec1bb5fa3145a6552309f5b15	1089034373	No	Fiber	10000	10000
beeead69857f7b02b9603d7602bb2598	1112239069	No	Fiber	10000	10000
7fe33274521f48f0c0baf30f50f6b1c6	1111406180	No	Fiber	10000	10000
255ffe49c3538f613cc0c2599f73ea30	1106684383	No	Fiber	10000	10000
66153d548d2e05fdefcb2ad67495197a	1106684211	No	Fiber	10000	10000
ff85a5640c61fe14ff680a62c65b32a7	1089032673	No	Fiber	10000	10000
69fc85cc63ecf84322faf7f5cb9f8bdd	1286908962	No	Fiber	10000	10000
869ba325fab45f677ee99897d22fdae0	1106684763	No	Fiber	10000	10000
3d191c61e51891cc4957b5ab19e9ff14	1111404559	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
31f9f0679b80d5d83257c5ead88ce35a	1112239099	No	Fiber	10000	10000
2d15f9da075da7c6037068105b49e9ed	1106681393	No	Fiber	10000	10000
9d14339757fe22c15fe6a95f2417f95b	1106681298	No	Fiber	10000	10000
65437e065c385356372d6fc28e1b18f9	1106685698	No	Fiber	10000	10000
57b21a5bd963e9b2190592ca814e4813	1106680327	No	Fiber	10000	10000
1902c38c43de38e8b165cf6f9a1fd387	1286913550	No	Fiber	10000	10000
255bcf49e30845e2e24fc4c160892940	1089034561	No	Fiber	10000	10000
d2bbd632d5395dcc03eeb84cb4897762	1089042935	No	Fiber	10000	10000
b1ea63f810e9cb2f45ef4db3c8e906b5	1286914677	No	Fiber	10000	10000
cdde1c21a0646e9f756c09406f9df949	1106684166	No	Fiber	10000	10000
c640d90504ae252ae35666056a98dded	1111413216	No	Fiber	10000	10000
2e81cbc6a33b5589c4bac6c2dce24afc	1111413037	No	Fiber	10000	10000
a047dd68fb265427536fb311201ee259	1106680979	No	Fiber	10000	10000
12719048e08ad3c7fe3adc674a854a0d	1089056305	No	Fiber	10000	10000
8f99cc7167fae305dadcc97358b92775f	1111413194	No	Fiber	10000	10000
e0a74f2f583bc170074419caf227dad9	1106687020	No	Fiber	10000	10000
216cf8d5953d52d8d3fe9b2dcfb9a101	1089033533	No	Fiber	10000	10000
e81fe445e45ab83943ffe85aa78f3e7c	1286907923	No	Fiber	10000	10000
337b6c31f3821bcc935464704fd7d43d	1112264029	No	Fiber	10000	10000
5d0606e5726c318095585a74dffda441	1106684187	No	Fiber	10000	10000
aa4bee4623bff787e2488d21c1949ce9	1111413118	No	Fiber	10000	10000
d5bd27a23281420750de0992323a3cba	1286909594	No	Fiber	10000	10000
35ff1d31fa4aa56872ce1c91242742bc	1106686273	No	Fiber	10000	10000
13f0f1fbab627083c66b2314161955bd	1106684377	No	Fiber	10000	10000
712f58655d69768ef87228882cd06566	1089040429	No	Fiber	10000	10000
9369faa458815eb1e7dab8196c40b732	1106684159	No	Fiber	10000	10000
32be9f5654e22e10f4b35355b13d311d	1112239077	No	Fiber	10000	10000
bdbbdea53104e8e94a7870f7bf251b36	1106681817	No	Fiber	10000	10000
95bebed48cb343ae4fdf23932097810d	1106681006	No	Fiber	10000	10000
d8285a68d3cfd733c53ed79a69fcfeef	1111413418	No	Fiber	10000	10000
2aa862153457e7655e72fd782015b2e9	1106682500	No	Fiber	10000	10000
8ceaec8a9318e38f0044b2aa7ca1e128	1112257577	No	Fiber	10000	10000
7fcf8be69778947014564b0939b5f7d2	1106684028	No	Fiber	10000	10000
50a609580a5e712052686a3acc2abfb7	1106680831	No	Fiber	10000	10000
5ab231ab00b3df6d56931df43707f791	1106686269	No	Fiber	10000	10000
9544069400d645691e8ad5ed6cb44158	1286911583	No	Fiber	10000	10000
6042a918a2e33dcdd962f7c8e59473e8	1106684699	No	Fiber	10000	10000
c064be303039f25544bea9aa2b7634af	1111412511	No	Fiber	10000	10000
a6c96ef684735f275b34b147a80c6589	1112237702	No	Fiber	10000	10000
cc5296535e445b31033372a6c659538b	1111405252	No	Fiber	10000	10000
437c5d5858647e95b629908c153dafa7	1106685302	No	Fiber	10000	10000
fa089d7fc356d8c281ae82d027ea826a	1106680653	No	Fiber	10000	10000
eef8352c2f786fe8ef9ffab71a15aa97	1089059708	No	Fiber	10000	10000
f2d2ce7cabfda4204db0d0aa403a8adb	1106682295	No	Fiber	10000	10000
c4eb9381c19e1635906ff855c7ee31c2	1286913469	No	Fiber	10000	10000
2701f4a8bc0e5df9f87fca3d5e5810cc	1106679375	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
10c58da754a96ef415bef8b2d00e9331	1111413274	No	Fiber	10000	10000
250d7a2f525fd0b520149b5c0ee6c8b2	1106679421	No	Fiber	10000	10000
63404ff235661c02e73dc630682fdb48	1089041419	No	Fiber	10000	10000
0f3d42b0f355ae0e858da293581be30d	1111405855	No	Fiber	10000	10000
41ee3236bf7a5582e4f85dd3799c549	1106685405	No	Fiber	10000	10000
f53976ea27d3cf99983ed73c2a9f878f	1286908761	No	Fiber	10000	10000
f59653670be2814728e29a05feec9933	1106685594	No	Fiber	10000	10000
90aff5a999a2c5802dff0790e1733cb	1089033535	No	Fiber	10000	10000
0fb6e30d5d6ecf3cded5404925d58fe3	1089059361	No	Fiber	10000	10000
a949e5888e4f8febaa717e69d404c9eb	1106680588	No	Fiber	10000	10000
a0448a06e8445bcf533062a8666eee8d	1111413101	No	Fiber	10000	10000
c58c8d1e25e39574ed2d9fd4ac382c2c	1111406333	No	Fiber	10000	10000
a7ab9c9fcd39c75ee3c0cb1dea411bb2	1112241819	No	Fiber	10000	10000
bbfe49f9687709a933906416ce68771c	1106684357	No	Fiber	10000	10000
0268ffb6466bb9d0643266d7c2247879	1286912582	No	Fiber	10000	10000
7f18a0a3a387eff03bddfe08ee54c477	1106681936	No	Fiber	10000	10000
a27a2f0f85ea9fd8b557eebcef587399	1111413217	No	Fiber	10000	10000
f588bc5ca503a94fc335d61f5cfe4fac	1286908106	No	Fiber	10000	10000
b73959cce2e129f992b9241ac6bcf871	1089034319	No	Fiber	10000	10000
9f73591e68911c22a4e25a67935cd6ad	1384984039	No	Fiber	10000	10000
2b9f686f87a208725ccccf1e2832a66d	1111406202	No	Fiber	10000	10000
bd816e03459462428be3bc512a436f50	1106687006	No	Fiber	10000	10000
3ae8be8a0cd9dd2bef531f5b4c3297d8	1111413421	No	Fiber	10000	10000
10e9513872f1f8a4e08cdb5880e04b45	1112236579	No	Fiber	10000	10000
786fad30d004c44b1d83ebe8258d9105	1286907912	No	Fiber	10000	10000
a88a347f6e72fdae01808dcb47f94f7b	1112257592	No	Fiber	10000	10000
3064c8be6d21c543e32bfdc91bb09dab	1089056591	No	Fiber	10000	10000
06d004635c71481048e66fe6f9f23710	1111411429	No	Fiber	10000	10000
a440b9c31ddf5b21d3e5390e3a34e17f	1112257362	No	Fiber	10000	10000
939666cff09bff419a60b3e67da20f46	1106686753	No	Fiber	10000	10000
f48800581ee4f15047c5faaaaaee56d9	1106690347	No	Fiber	10000	10000
0f51ce888a52e72fc60b26f21ccfb6be	1106682841	No	Fiber	10000	10000
a7e152220795e64fe0095945559cc8b9	1106686335	No	Fiber	10000	10000
9346470256bafb565a88756df4efa81e	1089059714	No	Fiber	10000	10000
f65bef19b22649f4072128214907d915	1106687015	No	Fiber	10000	10000
3eb1b9963e14f51931a4563d126ab970	1106679804	No	Fiber	10000	10000
516f3aad5e239688684b03e587779d3d	1111404569	No	Fiber	10000	10000
56311d0883b0aa1f3d4b841bd5c0d7be	1112239098	No	Fiber	10000	10000
cb7e8b76c86490e1a03b1d022e29cf5f	1111412020	No	Fiber	10000	10000
d358e3aae850b3de3a37b4c5a76cd94e	1106683070	No	Fiber	10000	10000
cbb3f567dd2ab51b9edc86d711d781e5	1106680933	No	Fiber	10000	10000
e8b41eef6eef0b62e99bd040cb95453a	1106679534	No	Fiber	10000	10000
fa94e908e2e2a0a56a24ddcb1ba8bf6d	1384680076	No	Fiber	10000	10000
c3539763fe34d1347ddd8a8a2861e3ce	1106682845	No	Fiber	10000	10000
3f94910f52dacb5e9b519aeb8e2b733b	1384901426	No	Fiber	10000	10000
82d21cfbe40d1ee0f3951163004a34e3	1111406223	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
eed9e5b836313ac08beb11cffa966775	1089040440	No	Fiber	10000	10000
0ff861c0ef9d46e9c0980e925c8d6e46	1106690934	No	Fiber	10000	10000
9c4bc42c0ab6f1e7ddcf4ca19c77cac7	1413429166	No	Fiber	10000	10000
de47d27f85b155ad305777d3c664f57f	1106682300	No	Fiber	10000	10000
c0c58ee22e1c25cab9919dc60cb819ae	1089042184	No	Fiber	10000	10000
a429fd34b5dcc599ee577a0d26bb6c58	1106680228	No	Fiber	10000	10000
89f82f254ba9c0cc955645867ae6cd00	1106679857	No	Fiber	10000	10000
f72f4de253554f9907421af9d06dbeb4	1313751586	No	Fiber	10000	10000
df5cc3f37382b698bc77ee787bb2f8a7	1106685605	No	Fiber	10000	10000
b20efa671d1e43496b4b12e990940cf4	1089059230	No	Fiber	10000	10000
6df3220bcea11c3b8bfcc7cd5c82cde7	1106685423	No	Fiber	10000	10000
566bb67e23bee5ab4f4a564e97685d42	1106685640	No	Fiber	10000	10000
6114b998d47d9097e8a570b0ff9faab0	1089034247	No	Fiber	10000	10000
3623ecef31f48d86f42a357fe83228b6	1286906802	No	Fiber	10000	10000
4b213cb908230493c9a702ac8a60adc3	1111424513	No	Fiber	10000	10000
568884f1d1763e75d4b16a3872494bad	1286908713	No	Fiber	10000	10000
7a9ff32a17f4f37e6e1b68a9df1dbf4	1106681541	No	Fiber	10000	10000
bd33f41a162eb6152f872dd1152aa03c	1106685750	No	Fiber	10000	10000
d327b1cbe408d559af05c08d5dc654b9	1106679894	No	Fiber	10000	10000
e14b7e2e38a1bd368486ff610a85175	1106679571	No	Fiber	10000	10000
d7eb68b91a17724f49245fa73ea9dd6b	1286905440	No	Fiber	10000	10000
f9bbcab131094a6f9d8ca1f7e7228e49	1286910945	No	Fiber	10000	10000
950866b81b1b12818b488a2c349a9ce2	1286906761	No	Fiber	10000	10000
dca962e1419833ca2144f68bec70ee3f	1089055466	No	Fiber	10000	10000
435d2a6bd33bd4a2dd3fbeca01203803	1106679322	No	Fiber	10000	10000
39ee929a7b71d7d3ba8bcf30481531e3	1106681325	No	Fiber	10000	10000
9906421c1871be68f62beb0275901265	1106686562	No	Fiber	10000	10000
d79508939dc7f44c671ca611a0ffd970	1106682252	No	Fiber	10000	10000
1c65bd7223fbd06bae8c145e3b9d3ddc	1111405188	No	Fiber	10000	10000
c8b23c7a32dcac1777db1b0fb4a2c025	1106683150	No	Fiber	10000	10000
3ff98fa9dcde58e5c484ba00938a1446	1413421520	No	Fiber	10000	10000
845f92c508c48ee821b00b8279cfcc32	1106684842	No	Fiber	10000	10000
1d9fdb2d4dacb67924f504aa7a745d38	1106682083	No	Fiber	10000	10000
0f8c79602210897847c891ccc1d9d2e9	1106679599	No	Fiber	10000	10000
d8d2a34d43a1b16da76cec121b58ea2d	1106679528	No	Fiber	10000	10000
dae076cae7adf209e2b393ff6f4e83190	1106680672	No	Fiber	10000	10000
c05f872d143eb248652e6b3669d23177	1111411981	No	Fiber	10000	10000
069bdb086b7472989b4402bf9b00856a	1106685220	No	Fiber	10000	10000
408529e31f70d57c2baaea4623b4190f	1112264015	No	Fiber	10000	10000
263e8820ae9adaea14e8697b267b6f65	1111413153	No	Fiber	10000	10000
45623d757debcc5f4c8754e1133b7746	1106682564	No	Fiber	10000	10000
fb83cf3c431706f53cf844dce6460b40	1089031611	No	Fiber	10000	10000
6e5a54c9037650afb6253b246190de1d	1106683773	No	Fiber	10000	10000
b0d9837049670d1292e251ce7a38f4be	1106684560	No	Fiber	10000	10000
4103862054f314129929ab5a4d2ce870	1106686934	No	Fiber	10000	10000
eeef337e23e2227fb0dedbb5f260f0ae	1106686085	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
e518668aa5b5a37989093262f2835436	1106679788	No	Fiber	10000	10000
7801226116451de1ee937f081d136f9d	1106685371	No	Fiber	10000	10000
c886c3ce092e403b39795bd55c2f5758	1106681092	No	Fiber	10000	10000
f9d7d9a1d5cc26aaeacd7f200cd043a5	1106682828	No	Fiber	10000	10000
6318291703e41a161da200af7c5d6b6d	1106691251	No	Fiber	10000	10000
0037673bbd1cca68b50ea1adb884fc0a	1111410038	No	Fiber	10000	10000
afcbddec0253e6eb085366f88f8b852d	1384981898	No	Fiber	10000	10000
a914667201254c93fd2295bd7aa520ec	1106686354	No	Fiber	10000	10000
f530e5084d9aff48b78157dabe3edd75	1286913766	No	Fiber	10000	10000
f0bfba1b883f3431cbb8f5bfdcbaa6ea	1106686442	No	Fiber	10000	10000
e8e6aefbee17bece63b25bb7412ebf75	1111406179	No	Fiber	10000	10000
898e4773a3f076a880b4982597cde6ef	1089059205	No	Fiber	10000	10000
32dadec3b49299368658be15efdfa7f1	1286908555	No	Fiber	10000	10000
31ba9f220fe05ec3654a1aee5c85e0a2	1106680040	No	Fiber	10000	10000
1edae3e9c76d7fd65289af568ef213a7	1111413873	No	Fiber	10000	10000
d2b31ca124ac186221d6be308453d988	1106680626	No	Fiber	10000	10000
168795b4b862f13a842d9b5ffdc8ef01	1111404534	No	Fiber	10000	10000
ac5da05dfc40e6da77300bbed854cc67	1106686408	No	Fiber	10000	10000
d36e468ed233ff920b4e8cb798ce7737	1286913637	No	Fiber	10000	10000
2dd62e118379f3cf57ad0488868dc99a	1089039758	No	Fiber	10000	10000
395a69239ad971af53fe27d77436e1f	1111412387	No	Fiber	10000	10000
c90f18b46ea46efb0d19b650e453e123	1089034370	No	Fiber	10000	10000
54392d376c797f26b18cfe300cdfaf975	1106679755	No	Fiber	10000	10000
087a2d6ec8d0f8ec99d2a3c849ea93a1	1106681455	No	Fiber	10000	10000
8a80718eef9752562dc395b22608df18	1286914527	No	Fiber	10000	10000
1cade7a7d969758c3d7c316fea50b710	1111405876	No	Fiber	10000	10000
a282ed50ba91e5e8da02ef19af60deed	1112264014	No	Fiber	10000	10000
5ed0a235f06d4339a0267fa9609ccee3	1106681533	No	Fiber	10000	10000
35b03c62562a4c6ea930f8f418fe21f1	1111404536	No	Fiber	10000	10000
968b5247eac0261ce9e8695c30be19f3	1111405184	No	Fiber	10000	10000
e0f05afa2fcf79b1e43191fa6362c039	1089059105	No	Fiber	10000	10000
7fef18d6be21338e7484cd5a9ee466e3	1106687161	No	Fiber	10000	10000
f7fbac8fa4b35885ef812eb128f842e4	1106686301	No	Fiber	10000	10000
514a86130253d7bebd31b9fee101fad1	1111411959	No	Fiber	10000	10000
ddffd700b25e0a8c6d6b33738cdb1c28	1111413219	No	Fiber	10000	10000
8775d392dc2393ae08e6a8215fa982cf	1106683949	No	Fiber	10000	10000
5eaa393ae9d646a3f9ee86cb8f72333a	1106681521	No	Fiber	10000	10000
d6191e0fa76112c011222c045d795d73	1089039719	No	Fiber	10000	10000
4d00416a52e7a2c3c773a02fa2b1e49d	1106684744	No	Fiber	10000	10000
4de5553fb7f45182351f1f0df691cbe6	1286911091	No	Fiber	10000	10000
37df4af1e4a62af43049fe63fca4e384	1111413026	No	Fiber	10000	10000
01d921a9f760c56d8f60730cbc12ab1a	1089034392	No	Fiber	10000	10000
0e539242da609a0a46013ab1bd6b22bf	1286914201	No	Fiber	10000	10000
5710b7f70765f03b423c636009423b5d	1106685215	No	Fiber	10000	10000
2f1d864e872c4e4d5b1c95862aa9bbd6	1111412625	No	Fiber	10000	10000
884972bf2e4dc547baef8589fcdfcdcb	1106681897	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
ab6af15aac71eae31a25a53afc873213	1106684777	No	Fiber	10000	10000
7a635704f425a8194090c71047f44dfe	1106684468	No	Fiber	10000	10000
d06a7de76625e63bbce677e0cb5c7f14	1111412542	No	Fiber	10000	10000
65c6cf222eb159e6527f5a23fea91925	1106686725	No	Fiber	10000	10000
274b667d0c0b1fea1bb1605113c3f623	1111410096	No	Fiber	10000	10000
90265819bf3d368a3439347e4234f83c	1111412156	No	Fiber	10000	10000
3b633a400452e47a862452e78ff721ca	1106684287	No	Fiber	10000	10000
4275b7a1ec95e1dc9a9e09a967de9cbd	1106686876	No	Fiber	10000	10000
ad4366b0db31222e4fda1cd02d70e4fa	1106686157	No	Fiber	10000	10000
535634f38ae6a3a2c29d0050b3614391	1106686650	No	Fiber	10000	10000
d322e244cd3af3d824bd3ed1b2643b6c	1286913706	No	Fiber	10000	10000
8cd5a7795b1188d0b43479f0f19cdd5a	1106684428	No	Fiber	10000	10000
ce8fab5e75f978497fe7aa09fdad5ff3	1106685342	No	Fiber	10000	10000
9a9f6ab7e4c50578663d9a9eb7cf22ec	1106687112	No	Fiber	10000	10000
519d6a201478fd190b75ccf098983234	1106681101	No	Fiber	10000	10000
d48d72e9670d20d8398d70a4a121b309	1106686075	No	Fiber	10000	10000
989e500c22b2386f02f82861d4f57162	1112239072	No	Fiber	10000	10000
b219a7be165dbeba8461b566b1b53167	1106679873	No	Fiber	10000	10000
de362d7954c45df7cf1e9497e808f866	1106691182	No	Fiber	10000	10000
f96b8f5fa60610d3785b5a6cd2062d83	1106686171	No	Fiber	10000	10000
c563954eecb0c232bbe6148d0b0a3717	1384900929	No	Fiber	10000	10000
c5d19b2fc5faccac93a3f2e6cb746d5	1089032089	No	Fiber	10000	10000
fc08052494f451c131cbb32d8fbdf1e2	1111413279	No	Fiber	10000	10000
284d1040d964eb852e0962184bf84c42	1089040167	No	Fiber	10000	10000
8bf5fcb314000e86e67f0cd0e4171144	1106681969	No	Fiber	10000	10000
94ce6e955673071a878f973ee9ace874	1089059769	No	Fiber	10000	10000
4c0aa73a34d08c337a4e7a37db786fcf	1106680196	No	Fiber	10000	10000
5f5e6ec3578c64619c63afce5eaf9624	1089032780	No	Fiber	10000	10000
138a1e6763cdacf464b859ebe6dd814f	1106680863	No	Fiber	10000	10000
96922da85ec8d74eabdf0cc36321ccb9	1089034783	No	Fiber	10000	10000
f961ff85db0102d48b43da21c8dc1815	1111406347	No	Fiber	10000	10000
34d959fdabdb3b52b8b405106289e9cc	1106683452	No	Fiber	10000	10000
4e5627f84da910782fecdd2f3df873ce5	1111413276	No	Fiber	10000	10000
2b97b895c6c1b86bb97d7c5b81b79ce3	1111406224	No	Fiber	10000	10000
296a6370276f646d51f77ffbe0d4c0aa	1089059997	No	Fiber	10000	10000
28df07b5d254e5d941f37550688f43ef	1111412043	No	Fiber	10000	10000
2a9992af5bd1d4f68ba4eab769114592	1106686807	No	Fiber	10000	10000
dc7f8c07fdfa217f9206f652e6c5fbd0	1286912985	No	Fiber	10000	10000
85c7b5b30c63a96a91c21e190db46555	1106679841	No	Fiber	10000	10000
88b7279b3fd3bb6f3a2da67e81bbf37b	1089032798	No	Fiber	10000	10000
cb860eb499d9fb3ff9d871e04a396cbd	1106684609	No	Fiber	10000	10000
febafbb5e28cf88c50e7313db4755966	1106685253	No	Fiber	10000	10000
f9ddafae726f7a21a91ed27aa7f7150d	1111406019	No	Fiber	10000	10000
60db5add16c095c2ebf6c3e034ecbeca	1286905411	No	Fiber	10000	10000
bb96242c311e9fcf118085836c061e91	1106679358	No	Fiber	10000	10000
5d365b3f1ac5ee55fc26e42f08d18ae9	1106680464	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
c2fb46f127123a5637cfe5e57614490b	1111410764	No	Fiber	10000	10000
03c5830d18c221b5153384a66fae1989	1111412400	No	Fiber	10000	10000
dc04770e7ace8f9b586bbb15dd9e5573	1106681885	No	Fiber	10000	10000
e33d0aafd9d1f948bbae18f07a6cf526	1089059719	No	Fiber	10000	10000
9881ed3b73f56256a523524971cf0ffa	1106685718	No	Fiber	10000	10000
1e8305733d49458d9d5e32950da27503	1286906226	No	Fiber	10000	10000
f895a47ccc22c974e5775ac31fe0254b	1106682588	No	Fiber	10000	10000
b7ea3a41212315f25ca9476e51064800	1089034394	No	Fiber	10000	10000
a1dce535b30f61591f27cf83cacaab5	1112257575	No	Fiber	10000	10000
eea0b99e20c85f84bb53d5ca26f4ed7f	1106680799	No	Fiber	10000	10000
48c927ba1df0f07cd9d21a444141224	1089031617	No	Fiber	10000	10000
f68012fb3f0f59068a5a17c5570c5ca7	1112261294	No	Fiber	10000	10000
9578f4b51aad4e375b74dff06adb5a0	1106680895	No	Fiber	10000	10000
13a3cc62b2c7bb8c578d2e1cfa466cac	1089042253	No	Fiber	10000	10000
1175a94d5249b0cc21c1b5dd507a356d	1106680000	No	Fiber	10000	10000
3863efd139f011cf1e3d0f1e501c1031	1384581917	No	Fiber	10000	10000
c89f3f0ba361d9a6d389f9cc77e68c1	1286909503	No	Fiber	10000	10000
9a2399e94cd285266e48645afe22769d	1089059315	No	Fiber	10000	10000
7f54630035e8114260885a7f518e51b4	1111406162	No	Fiber	10000	10000
51852bf59a6e238bcffc93e5259d6a94	1286905069	No	Fiber	10000	10000
2434e5b9c8a2ee3de08c2e4f464b824c	1106683588	No	Fiber	10000	10000
412f418903531ad3eb8d6e4f0824ebaa	1111412012	No	Fiber	10000	10000
091e5952a4a2802603103fe987107d9d	1106682309	No	Fiber	10000	10000
ba72de1ea78d8369ca095b7af914b980	1089059718	No	Fiber	10000	10000
afe6c5a91a6d4511dff974a955b225e8	1286909969	No	Fiber	10000	10000
cb1f3884cbe6042e9041aef07f3bcee7	1089034387	No	Fiber	10000	10000
2672ed4741d906dbe1632bbd14bafd2f	1106684963	No	Fiber	10000	10000
ae0fdc0f83c614cab11907ed9dd4618e	1111404539	No	Fiber	10000	10000
fb8373075fdf38539ca1634b4006b243	1106683198	No	Fiber	10000	10000
129fd520e746cf171181c4e81dd86a14	1286906108	No	Fiber	10000	10000
ca237bcbb44bd73962d652afeba69c9b	1106682571	No	Fiber	10000	10000
f1fc2571e39835ecef00c6adc4cad07	1089032796	No	Fiber	10000	10000
f3fc69c306c5405a70110bf1f0c30f0e	1106685240	No	Fiber	10000	10000
543cbc5887168c2a9f6b126dad315d01	1089059188	No	Fiber	10000	10000
bf2ccae60e2d15348f48af5e04ea4294	1106684500	No	Fiber	10000	10000
18efaa3e9868ef29c6db457844485700	1111420963	No	Fiber	10000	10000
5f7bb5d0eb745d1c870cc913eaa87105	1106680503	No	Fiber	10000	10000
a4435984a35ce5efe0380cb48744d4ff	1106680025	No	Fiber	10000	10000
8349c71be5492d934d1baadf32b64916	1106685938	No	Fiber	10000	10000
656006f1110cee92b176c30215f13895	1106681103	No	Fiber	10000	10000
4317cfef04ed4e33dc407eba9b0e3677	1111413449	No	Fiber	10000	10000
cbbaca516217c6104f72aaba60a7f23d	1384580780	No	Fiber	10000	10000
e60fcd7e2273ca00053397e1ee52d258	1111410350	No	Fiber	10000	10000
617020c73dd353ee04f6a8a3aa65064e	1106679842	No	Fiber	10000	10000
4959fae2ea3a018cf33205dc7d57aa0d	1089039692	No	Fiber	10000	10000
638d53472efc56371a571bf51badbb0f	1106679834	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
c786887f33b25bd2e0ea647cbb671461	1111417553	No	Fiber	10000	10000
93224371a0ed5689de215f08d277a27c	1089039727	No	Fiber	10000	10000
5ab3f0d6831203f428c784b5a5a1c27f	1106680623	No	Fiber	10000	10000
f03b087143469c3f08a5a6a272bb1c58	1106683836	No	Fiber	10000	10000
eea269ed35e51ae8bfb2b9f1c4375840	1106686033	No	Fiber	10000	10000
ce9bb0b2a02a0e2901ea859a6e37c902	1106680179	No	Fiber	10000	10000
f11f350bcb6a42a727401fbcabc65217	1106679533	No	Fiber	10000	10000
3daa317a1cf76274923dddd70b5d2aec	1106686350	No	Fiber	10000	10000
ad55ab913765ef80f6ec366843f2f243	1089032674	No	Fiber	10000	10000
c461a5fd411faebe2d850acd2dbe7919	1106685802	No	Fiber	10000	10000
f0324d5bc6c357e6b298851ebf27d277	1286913494	No	Fiber	10000	10000
40777e91ae1c62cdcc624d7fde3d368d	1106685344	No	Fiber	10000	10000
41601ea0b044503adcd72505c227cd33	1106679400	No	Fiber	10000	10000
f5aa959b51aeb6b602cdea2a3bbce330	1286914649	No	Fiber	10000	10000
531798915e430105287afe4855c34508	1111413334	No	Fiber	10000	10000
1ab87a15c335abed2e9034f95bf7198a	1106682184	No	Fiber	10000	10000
378ebfb0cf053136be0779dddebc0b90	1106686013	No	Fiber	10000	10000
23b10a4b2affa9da3d1d9a2ff875e36f	1106682656	No	Fiber	10000	10000
44d2fefcf5339b4ea6eaf874907bec67	1106681523	No	Fiber	10000	10000
5566315064ffe7ccf8d535cca89cbbc6	1112259002	No	Fiber	10000	10000
04a16fbe4a3778acd74ea804b7b29485	1111414608	No	Fiber	10000	10000
fded49a1251c8860d83b917dbfa92a75	1089059311	No	Fiber	10000	10000
9047a6bb04b70ce1ffe91ad63c46563e	1089059770	No	Fiber	10000	10000
a64d845ad11973fa0cc4c6b7b59e7e27	1106680735	No	Fiber	10000	10000
49d8197edb790042bcffc1d0ba5bd5eb	1106681183	No	Fiber	10000	10000
57caa0912d3c64566393c127b09cc51d	1089059178	No	Fiber	10000	10000
3ad978cdd4b83da3a1796ad82fa07eda	1111411372	No	Fiber	10000	10000
10d8e1fe92d1c360d7750ea3cf344024	1089059192	No	Fiber	10000	10000
ee6e205afd0bc5661ad107b3ac01b26f	1106683233	No	Fiber	10000	10000
b689ff6d39f65d6e2340f59c64aae20c	1106682220	No	Fiber	10000	10000
05169042105d833982a2b81260805928	1106686627	No	Fiber	10000	10000
c87622b2b5eb81c0a2b81c79445fbf6c	1111411376	No	Fiber	10000	10000
8c43af906624fe71c28e1892812216c7	1106683593	No	Fiber	10000	10000
72ad269dc8ff211910cc7d9142816298	1106680816	No	Fiber	10000	10000
90bd4394643bbbf3a1ef6a583f6eb736	1089059983	No	Fiber	10000	10000
1f898706ed302f32349748c6b0de061c	1106679844	No	Fiber	10000	10000
e9e1232cfb255333fc556621abeb4814	1089055479	No	Fiber	10000	10000
c0d6810c2889341d7344dd9b00f014a8	1111411391	No	Fiber	10000	10000
d4c0acb0234f2b5beaea124ca4f2924e	1106686016	No	Fiber	10000	10000
a385ff80741bab76756df46a90fd3c2c	1111417559	No	Fiber	10000	10000
7628b6b49a53104b2c3b5b5d0bd590c3	1451614607	No	Fiber	10000	10000
2bd56621ff2116c9e3fac5ff10faab95	1112263661	No	Fiber	10000	10000
84bd854ba0ab7673b4a082cd021548a9	1106682035	No	Fiber	10000	10000
d09c88ec75d84f7196b5983ad2952d66	1106680813	No	Fiber	10000	10000
8b518f00aa11d3cf40048266a3f0a1d8	1384898797	No	Fiber	10000	10000
fe947ce24baaba852909895318701822	1106684349	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
d56791200c6a6abb9f993500c7bdfb87	1106684902	No	Fiber	10000	10000
1633588b2064be513ed6a3ba43f24d24	1286912617	No	Fiber	10000	10000
162031654e37a1315cb4d5bbad1be184	1106680559	No	Fiber	10000	10000
f7eecf71532a37065edee79b694afae0	1106681784	No	Fiber	10000	10000
cffd854906ce67634fab92c06db833c8	1106687152	No	Fiber	10000	10000
d4bcdea47d231f76eeb669bccfbc9503	1106686523	No	Fiber	10000	10000
22371f5c5d9e2fdf3343219731fe89c8	1106679580	No	Fiber	10000	10000
cc339eb0c5cec576bcd08b5588266dd6	1089059306	No	Fiber	10000	10000
f8874583e513a6bb7def6f6f535e3ec6	1089042276	No	Fiber	10000	10000
922264e59dd13a6218af4a76609f541e	1106685453	No	Fiber	10000	10000
b993d7bf44d6ee0884296d40d9a79235	1112239125	No	Fiber	10000	10000
a629445ff00182b1223949ecd4e01f2e	1089059766	No	Fiber	10000	10000
2c10360189df9ba2968916e0c9873fa8	1384984411	No	Fiber	10000	10000
3a1a3759a0a7970a5fd3a6481a8a4168	1089059176	No	Fiber	10000	10000
4257be22a2dc116d8d079f486d05c111	1106681399	No	Fiber	10000	10000
217be11a8f54366a8fc4f02aafc346a7	1106683405	No	Fiber	10000	10000
b908056cdc712c30664861b6a6acd2ff	1286914019	No	Fiber	10000	10000
80d4e8ebddf18f99e9462faf3b046d36	1286912156	No	Fiber	10000	10000
00ed58362cc6d26069eb93e32d38f5f8	1106679485	No	Fiber	10000	10000
8b9f8c7e0b0acf6a759461ba5d2b9872	1089060001	No	Fiber	10000	10000
accb9ffd456a1f8d374679137595b162	1106684567	No	Fiber	10000	10000
ee09f52abb9101db1a83ff794e84d51c	1286913214	No	Fiber	10000	10000
efa1f980a8f2bba46f6a81321eb24415	1089034233	No	Fiber	10000	10000
660ea4429d712dc4652ec54722dd9a71	1111410776	No	Fiber	10000	10000
8b225393602b47da9cc7fa3e4902e57e	1089032671	No	Fiber	10000	10000
157c42e3e871e1bd89e0a8bf6b2a38ea	1106686949	No	Fiber	10000	10000
213f2c974e3bfbd69602ce34c5445167	1106685000	No	Fiber	10000	10000
deee8dd893642a686c4d4d9be5259520	1112236583	No	Fiber	10000	10000
61f39508d12c0e0497d0e82f57920d99	1089059213	No	Fiber	10000	10000
e4880a573e95575e8f19c16e2af5fc03	1111412394	No	Fiber	10000	10000
b89477c0682d26915fedde96d7709a3f	1111413009	No	Fiber	10000	10000
6e7746141f9929b279c4815dd947ebb3	1111405566	No	Fiber	10000	10000
d64931b6195dfa8a94af3255972aca93	1106683679	No	Fiber	10000	10000
cb9370112291d0690cd0892f897ac8fe	1089034365	No	Fiber	10000	10000
e127742c379af39b77c658ab06498bf4	1286905557	No	Fiber	10000	10000
7e7b859b51c026c74e0faafb7bc9e9df	1106679893	No	Fiber	10000	10000
f382c33fb6eb6ca267d5492715b88293	1286908043	No	Fiber	10000	10000
319d953fd7e7a31692daf998a4a3ba77	1106682533	No	Fiber	10000	10000
8d043d4c462679447b23388d9d29bbe7	1106685948	No	Fiber	10000	10000
a434251c50d14d916d04e019e4935a89	1089039687	No	Fiber	10000	10000
3408353e8fda94e86a7d607093e865cb	1089031235	No	Fiber	10000	10000
85db9d793055c1d4db977158b02193c0	1106680752	No	Fiber	10000	10000
13b6af04c9ca4139201fbb06286a6725	1111413335	No	Fiber	10000	10000
9ffd8a2104853d7ce1d96c5a778b4bc8	1286908125	No	Fiber	10000	10000
2108871a65521c1cbafed4dafbed55de	1106683849	No	Fiber	10000	10000
bd3a3a39a0791594dd35d86d574a5acc	1111413223	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
5a9f256247d34d94d281e6ca481b767e	1111413045	No	Fiber	10000	10000
df4fce9c624928a9f47dcbcd7cd5ff30	1384901425	No	Fiber	10000	10000
654c3a02e89b1383a037b9b01e7ed1e5	1112257360	No	Fiber	10000	10000
ba92fcfb28ed5555de947e3de857d2ec	1089039726	No	Fiber	10000	10000
efe15c53595085147d7cbca80c02000f	1286909958	No	Fiber	10000	10000
bd102e8303bcd1b3873d607d0385069c	1112259026	No	Fiber	10000	10000
738d685b4ffe7ba973fa979567853b22	1413421522	No	Fiber	10000	10000
a39ff4a63019f118d489c2b1c153a532	1089059358	No	Fiber	10000	10000
c7debfb18139d60dda4bd4c808d15c8a	1089034369	No	Fiber	10000	10000
8239977d2449b12c4a1624093bce0f9b	1089039685	No	Fiber	10000	10000
38346e9b4506b1d44a0fe26661c8a350	1384901206	No	Fiber	10000	10000
afa7b7a2b4f984859211ed8d6e477b8d	1106680461	No	Fiber	10000	10000
d3deec2e083b5f8bb410f73cedd89ae	1089041404	No	Fiber	10000	10000
2b0d508ff0ac5f9974a639ce01f1ff01	1089056569	No	Fiber	10000	10000
ddb05a131dc528cc124e40683d8b3a13	1089034566	No	Fiber	10000	10000
560cbbd5d612539a3d3c0c77e391580a	1111404639	No	Fiber	10000	10000
e3ed8fb01363576df8577c03d7174bf4	1106683860	No	Fiber	10000	10000
37b20c494ca72a849fea02eb78a0206c	1106682866	No	Fiber	10000	10000
2faba63435348d8ce45aa6f3956d9a12	1286905629	No	Fiber	10000	10000
d404cf7da8282c0f185a03d2a9887b0c	1106679573	No	Fiber	10000	10000
035ee830cac33573a0ea7b3dadd99eb5	1106686659	No	Fiber	10000	10000
30665d3e5cf3ffe36ea5041ddfc24363	1106681322	No	Fiber	10000	10000
b481da948379954c01f174e55dee65c2	1106681492	No	Fiber	10000	10000
9737bde5fb25c53e2ede1c7a4b742c10	1106681683	No	Fiber	10000	10000
174399f72b86fdbee591793b6bcd9122	1089056592	No	Fiber	10000	10000
ca0625e3e3a7d950586d4bbded638dc6	1106680821	No	Fiber	10000	10000
70864fb4d5e2ed196de387e21077a224	1111413331	No	Fiber	10000	10000
8cbfad4674ecaac0848c73c36731f54f	1106680550	No	Fiber	10000	10000
a837efad83b17396a5e00ff49444aa05	1106680362	No	Fiber	10000	10000
d72d0e7dea6e5e97039acffa305231dc	1106685230	No	Fiber	10000	10000
9db82a74d44870a24c61381186426139	1111412480	No	Fiber	10000	10000
fe8411840df861854cce5daedd6f6fc1	1111406488	No	Fiber	10000	10000
12f3e8c99e274d17692c59e26f3823bf	1106683175	No	Fiber	10000	10000
61af4414e51196e1818159011476d2dd	1106683027	No	Fiber	10000	10000
da29e4ad30e058e2f2f0ce663982d0bf	1106683190	No	Fiber	10000	10000
042d6a8856293e86b64a66d6cb89f9c7	1106683768	No	Fiber	10000	10000
bd706ef4ca45ec6da86a8c1a41e2d3cc	1089039742	No	Fiber	10000	10000
e573486b859864188389d023ff50ab99	1286913254	No	Fiber	10000	10000
90aadbe1131fbb2f4aa10425cac015e0	1111420837	No	Fiber	10000	10000
e516916b3a521de44f2462bb01d69ae4	1106685923	No	Fiber	10000	10000
0343dbb0be62ce66cb04975f583b8317	1089039764	No	Fiber	10000	10000
8765b32713d40548aabb5441fed9181e	1106684808	No	Fiber	10000	10000
c1d4448b9fa942c502f71ab7b74363ee	1286909272	No	Fiber	10000	10000
0d2e89e559a7ed3f7a7ecc7f0fd4540f	1089059981	No	Fiber	10000	10000
34b1b27ce70b6e73cd53cba9598fe6b1	1286908584	No	Fiber	10000	10000
065de4684217a2d165623659fc59cf4c	1286911819	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
753c6de85dcf606951f15b93acfb841	1106679520	No	Fiber	10000	10000
5fc7d5d2ae78fa9bddfb84f5e28c59c9	1089059185	No	Fiber	10000	10000
4dca534ad36feda1b028a8690ea7587b	1106681086	No	Fiber	10000	10000
698fa95f8cc59ce35a953ac3f6fd3cf	1106680335	No	Fiber	10000	10000
429e0ed25d5f98b231aaf0643281e2ad	1106679712	No	Fiber	10000	10000
9a20236cd2d423c77d9b2756a061992a	1106682877	No	Fiber	10000	10000
e0b7b93ab94a5f14b86c4841ef0e20be	1413421518	No	Fiber	10000	10000
b557a7c835c42db758a23b80bc45f486	1106679538	No	Fiber	10000	10000
2b8203778f7c8f035b0fc88f5217a725	1286904797	No	Fiber	10000	10000
a8e4ff83d178a34530846bf5f1084db5	1089031621	No	Fiber	10000	10000
990b9fc534245b5ab754e52b59526e66	1413429250	No	Fiber	10000	10000
fb32f0a2c8e01e3138f21335c98c667a	1089042228	No	Fiber	10000	10000
bcf8274876cde94dc84421927fa2cb68	1089039690	No	Fiber	10000	10000
1c934c793c4effda55dd31482f9028cf	1106681627	No	Fiber	10000	10000
050bb774027d94203e70dd0165d553a2	1106691253	No	Fiber	10000	10000
a0c8ea04b34a33f61f534bdeccf474b7	1089039743	No	Fiber	10000	10000
f576fbcf475d8dda94dce1c7740e4e99	1106686682	No	Fiber	10000	10000
8ddfbe828b1c4db0ef1105f740fcb644	1111428347	No	Fiber	10000	10000
2391f23d358b953c3a4be67d8ad1818c	1111413225	No	Fiber	10000	10000
8481829e8d509a30c784e48168609c3a	1384901012	No	Fiber	10000	10000
4d0ac4211275c463eb8c31a1420e54fb	1106683638	No	Fiber	10000	10000
9901aaab1201a1fe09c4fac5c7304de4	1286914521	No	Fiber	10000	10000
a4d1dd72b56235c2576eba3a02e58bb0	1106682050	No	Fiber	10000	10000
69dfade96951703c2e55a31ab8072dea	1286914688	No	Fiber	10000	10000
925c2fc88c025f86004d574dd4166564	1106681263	No	Fiber	10000	10000
c75a9bb30e8108e442e3a2fec40073a8	1106682825	No	Fiber	10000	10000
b00c2f298a7360f011d25fd89b098ab3	1106682626	No	Fiber	10000	10000
dcd266faabb84a78e92e530adc99abd6	1106679940	No	Fiber	10000	10000
228fc4f9369fc8c160e7a14375668618	1111414617	No	Fiber	10000	10000
cd63eea1c61939182fe54252b16fdddf	1106684352	No	Fiber	10000	10000
458f1414b7b82345450e7e8ddefab00d	1286914471	No	Fiber	10000	10000
7ff22589bfde4c7eee964b43f50dcbb1	1106680028	No	Fiber	10000	10000
4793e9960f1041e89a223eb5f6290254	1106680242	No	Fiber	10000	10000
1791610f917ff296d43528e6e16ccc35	1106683215	No	Fiber	10000	10000
4d5be74039deb5f4ada020086cb2c5ba	1106679828	No	Fiber	10000	10000
af1d53297b412e65c3de41e1ce5fe1b5	1106684395	No	Fiber	10000	10000
0368edd8fc780e9d7c4cb130ff570a42	1286907435	No	Fiber	10000	10000
28cfe843a1e185e0464b9f2215683ba0	1106684805	No	Fiber	10000	10000
75c12c1cd7540bce1fac3faad666d170	1111410773	No	Fiber	10000	10000
8aa620de8dd231ec22df9590eb4104ff	1111413046	No	Fiber	10000	10000
a6e22195512efd8bece4cebd7fff6bf8	1106686792	No	Fiber	10000	10000
c14c1c965f26f07252e337e8b76dba53	1106682489	No	Fiber	10000	10000
1cfe838baa6d893449d8438d9a0b07c2	1112257369	No	Fiber	10000	10000
495f51704735a596d8d04d9a456601e5	1106686861	No	Fiber	10000	10000
dc3bc5cd7c8fad8f2333838aa49eb534	1111420830	No	Fiber	10000	10000
8d6392f7ab5b1b82c3cb275aa08728a2	1111413214	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
66e19918fab34a67465a71d8405e133f	1286906018	No	Fiber	10000	10000
753c8e5b36a6bc3c00ec1160f1b9d09c	1111405276	No	Fiber	10000	10000
41002e4cc61652adf7f9ec8ae68e760f	1106682173	No	Fiber	10000	10000
6b28a49a2d23342fc8d69f10690639dd	1106684346	No	Fiber	10000	10000
c25a0105507f512a08d3f2471588af77	1106685810	No	Fiber	10000	10000
ae2bd6d7c628bf2984fab89b26674952	1089034397	No	Fiber	10000	10000
eab2ba8ed05197ea8b397f62f80f9a51	1106680764	No	Fiber	10000	10000
02f489ac02c638e89b762a6f7689e907	1089043194	No	Fiber	10000	10000
9f3bfc6fa289c55c8d9d0613920ad0c0	1106684125	No	Fiber	10000	10000
b81691a4bd377c6adca3a17a65894ddc	1286914507	No	Fiber	10000	10000
a9f12e5b9419c063b5a3dace76a3e3bf	1111414562	No	Fiber	10000	10000
12cd2b0ee9b918f932f12b7c567c06a5	1089032767	No	Fiber	10000	10000
f2a5014c2de8b9f41b2ef43e9fd33eca	1112264019	No	Fiber	10000	10000
37b78216e781e3efdd761bb144e9e78b	1384984546	No	Fiber	10000	10000
4dae874536b3c6310b4ec951b58037f9	1106683322	No	Fiber	10000	10000
396a435bbaa63a245901b475a962971f	1111413120	No	Fiber	10000	10000
acb122b45b68c35d75a7799c73e04f7c	1106683263	No	Fiber	10000	10000
42eccd689af35964ab3078fca2270fc2	1106685225	No	Fiber	10000	10000
4061d7ac301ade884c152ead5a04dbb5	1106680386	No	Fiber	10000	10000
15396ba019782e52797b90fb7b3c5e2b	1286914739	No	Fiber	10000	10000
d2b87887c455b1f827f667856e88bff8	1106686593	No	Fiber	10000	10000
f3d7a6c55478e16951a479bf5f821d78	1111406330	No	Fiber	10000	10000
39e8af03a3bbc8d1bc4e0336f507cfda	1286905114	No	Fiber	10000	10000
d1ee845d2459501e530b4e98f9c27586	1112264016	No	Fiber	10000	10000
f4878dbf4e611a23db973587c09e4369	1089059307	No	Fiber	10000	10000
7186d187a82bfca902f1716a431f7963	1106682455	No	Fiber	10000	10000
64dfb3c27637c7aa3bad89377d48bc14	1106682611	No	Fiber	10000	10000
75d1de90e78f8007441f8d4adfdfe58e	1286905451	No	Fiber	10000	10000
87c6f9e06378719ec6d1ac6e5cde5ecb	1111413234	No	Fiber	10000	10000
cbd720fa9d37f2835edd0c35dbf67595	1111411420	No	Fiber	10000	10000
3125d03463c6cad06f3429e7900c0814	1111412011	No	Fiber	10000	10000
de375e2cff35c4716fda1b42a96d5aea	1106684078	No	Fiber	10000	10000
7b05ba23bba52be01787abaf91661216	1106684860	No	Fiber	10000	10000
6321043b8f13fb9128ead261c96fae6	1106685434	No	Fiber	10000	10000
709b5bd813832fcc694386b13e44bf6d	1106686366	No	Fiber	10000	10000
a7d7217fa3e1ed9a8c02f35b29c1b807	1106685062	No	Fiber	10000	10000
bf14d44c0053f05d09bd210c5a84e448	1106680500	No	Fiber	10000	10000
d80396f051bcaae9599a5e7f25c05079	1089059282	No	Fiber	10000	10000
8d83038d155eca60ce22371f22554a85	1112239124	No	Fiber	10000	10000
19ca5998ef29548bfcf8006700ba3894	1106680898	No	Fiber	10000	10000
298dcfbcb10ccd91ec0f2c10f5cfd053e	1106679415	No	Fiber	10000	10000
ae7de05d8ec659c852ecfcec65fb0c66	1106684825	No	Fiber	10000	10000
c9e786625235e88596e708d8f0180e58	1111412227	No	Fiber	10000	10000
af546a6dcb2c0b794c422175c7358f5	1106684981	No	Fiber	10000	10000
8e407ab25890c3c358342a246c2aefd1	1111412391	No	Fiber	10000	10000
f3061b0b90d6e540e20e32937e43b47b	1106680859	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
14db8662e81a68097af2168745e9283b	1112236581	No	Fiber	10000	10000
c653d967e75fd32ea771a8eb1244621e	1106679351	No	Fiber	10000	10000
b181c02aa0f162a5fb1579bebbc9ba45	1286912323	No	Fiber	10000	10000
4d921809e39bdc332337cfdfff309a64	1106680713	No	Fiber	10000	10000
8d13f388e9cce33e38c1d0b931c8576e	1112264008	No	Fiber	10000	10000
2adaa7c50b77d506e998dc90736c8b6e	1111413050	No	Fiber	10000	10000
a8619cca4bfa10c1babf1e98f8c3c58b	1111414568	No	Fiber	10000	10000
8f8566fb66442cd55c05437a64819571	1106679507	No	Fiber	10000	10000
530cf943906681fa5fe7144003a16588	1384981476	No	Fiber	10000	10000
08eeee62aca1db632bb587a4134dd929	1106683550	No	Fiber	10000	10000
5610f2db1f6ccd122d56dfb043501ca1	1111405569	No	Fiber	10000	10000
2d1c70e79df3dd1b4381790f8806f661	1106686649	No	Fiber	10000	10000
9b2b3d2cad8460193c7547b314ebcb1b	1106685777	No	Fiber	10000	10000
c70353b97bd26bbe1fd90f0765e5302d	1112239122	No	Fiber	10000	10000
cb0d0e1d20997c058f020807d768c5fc	1106682732	No	Fiber	10000	10000
2a914d1be3123668ca9860d0e8562a2f	1111430170	No	Fiber	10000	10000
5cd0a6ec79d02db75f21a080e54f5501	1413421562	No	Fiber	10000	10000
c344c87e4376d36c9130779cb1cb6642	1106685512	No	Fiber	10000	10000
7dd705071e6f20ad6633a3ba9256d800	1089041406	No	Fiber	10000	10000
8fff16a0ea6e2d360df93a2b4f5a227d	1106684323	No	Fiber	10000	10000
eb2d8f162fcd1d9f3c96e9db8e2ebe21	1106683303	No	Fiber	10000	10000
2c2a7709cffaa04068693605c41af893	1089039688	No	Fiber	10000	10000
a5a9bc2a76644cf6c41238dfcf55dd82	1106682366	No	Fiber	10000	10000
433f347c7ceaff5b6644dc2290c0d0a9	1111406174	No	Fiber	10000	10000
8c389f355b1e79d39f0cacd1efc37c19	1413421458	No	Fiber	10000	10000
2e220647fc2429250dc0c6d2f81fb29e	1089034393	No	Fiber	10000	10000
54bf64b79e4411fcaeb185c92e7171116	1106684972	No	Fiber	10000	10000
321dd21ea7790f05192f7aea996c0060	1286905140	No	Fiber	10000	10000
ba21fff509869b7cc7f5576d429d4f29	1089059196	No	Fiber	10000	10000
6f6a1e0beb49607c298c10ca3c7b90df	1106683378	No	Fiber	10000	10000
6fbcbcd3cbfcd9692e24e7ebec5c869f	1286910074	No	Fiber	10000	10000
a75c24f05068b20dacc9c3f8e489496	1106681825	No	Fiber	10000	10000
68e5bfdb4070df44b42b9ce185463e4b	1106680233	No	Fiber	10000	10000
68e8bf291189bb94dd2e835c5cbcb67f	1111410540	No	Fiber	10000	10000
36a74572afdd0f6e00fab83d9efb4cf0	1112257578	No	Fiber	10000	10000
d4ccd8be8d7fed538230a28cb5406959	1089059202	No	Fiber	10000	10000
2acc93afbc88b5c370ff9acf908a611c	1106685160	No	Fiber	10000	10000
3ca6fe8fa9162e8f75bef87f736e5196	1286913703	No	Fiber	10000	10000
2d66ddd216e3dfbac44c7332017977d5	1106686958	No	Fiber	10000	10000
d1700d4c0294ab63242b81889c3ad9d3	1413421459	No	Fiber	10000	10000
a5e7429ae4eb62167cf56db104ff6c72	1089034789	No	Fiber	10000	10000
b3d8fe4cf9a0521905a7e9acd5ac9309	1106682084	No	Fiber	10000	10000
4965c157ff2d74e5c28fc14ca3237f0e	1106681808	No	Fiber	10000	10000
3ad100846328a0e27f61ae39ed7b44f3	1089059186	No	Fiber	10000	10000
bade2a6b7720a840c76484aef282427b	1089043160	No	Fiber	10000	10000
da18ca820204011cfc381e5e89869509	1111410815	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
06135fc7a87ca93fe94582891779dc21	1106684180	No	Fiber	10000	10000
6e38d10a9ea03bd799175ac593419cbb	1286907590	No	Fiber	10000	10000
09b4c916fef03da6ba81f69caf6b9acc	1106680562	No	Fiber	10000	10000
be68ebe9a7a8bafa2e10978e40b6833b	1111413005	No	Fiber	10000	10000
cc3bdd6b77a8659215f7b3fe58399e9a	1112257571	No	Fiber	10000	10000
2f55aefc23459f2764875d2b368acf70	1089034839	No	Fiber	10000	10000
137c216c0789a4092d89813b6336dfce	1106686697	No	Fiber	10000	10000
1ed32a28f7aff240c7685c4635c25896	1106680282	No	Fiber	10000	10000
4d162db080472b28469e6cdd02e8bda7	1286914490	No	Fiber	10000	10000
db17c8b94cf8c128a2afc69795f6215	1089039745	No	Fiber	10000	10000
e4749cfd147ee1780f491a10486d367	1089034334	No	Fiber	10000	10000
984739cdf6acd4651149afd1a3907e6a	1111412025	No	Fiber	10000	10000
ae1134fcedaca2bf19638e7b16ff2a5c	1106681437	No	Fiber	10000	10000
bd1c8135cd5cbeac2d71b5df8f19bc12	1112252695	No	Fiber	10000	10000
df0ec578cdb3f857dcde6e8d5135f859	1106683945	No	Fiber	10000	10000
59c2599172109e4de50e77af08d0a77e	1286904522	No	Fiber	10000	10000
d07c25021233e92077f19a08841211c1	1111414785	No	Fiber	10000	10000
09118737dd9dc2191e145c76bf2d9ad4	1106686558	No	Fiber	10000	10000
197e8935f7e11c7c25e0015c88e06f0e	1286910651	No	Fiber	10000	10000
5d0b105458a8b87a15a78706fe4527ec	1106686628	No	Fiber	10000	10000
a5527b33dbeaafbddef3ad28ace87893	1106679154	No	Fiber	10000	10000
18abf7125270604e2e5cd89ee8019935	1112257519	No	Fiber	10000	10000
2e2c6d1dc4aa77c2b938b67ad8d5a2d1	1089059858	No	Fiber	10000	10000
2d79b880ec9cb7c1dabb47cfc4a44f9	1106679886	No	Fiber	10000	10000
1e9e893c3e6c83321624789dcc1ba033	1106686952	No	Fiber	10000	10000
96cafdd258b8061ead7cb11ac1fda9e9	1111413114	No	Fiber	10000	10000
7fae07e55f94a039151dd87778941661	1089039451	No	Fiber	10000	10000
8037280645391bc082faa170f2e3790d	1106688805	No	Fiber	10000	10000
dc5d909963e886940c80b4402817b698	1089032096	No	Fiber	10000	10000
b19f0621b35e71ef445ac4583f55209f	1106680561	No	Fiber	10000	10000
a607ff9696d29af6c5fab4fdb1f62733	1111413993	No	Fiber	10000	10000
dd4e0b8dd08f5488e5698c11e51c9345	1111412048	No	Fiber	10000	10000
d083b3951eed5e81e3f90e0adea19a82	1286906708	No	Fiber	10000	10000
b765c913baba3241146bedb6e3b3d0af	1106680295	No	Fiber	10000	10000
93c55c4e6fb06f2bc085b27df3c53e98	1106680106	No	Fiber	10000	10000
7da9edee5a689e4edf5a86891ea8d5e6	1106679935	No	Fiber	10000	10000
4454f51809cda1435bf3f059d919b834	1089059462	No	Fiber	10000	10000
ee776b4ff40239cc585ff70f1f5adfeb	1106683943	No	Fiber	10000	10000
7abda6d2063b5f34abef55545408b8dc	1106683383	No	Fiber	10000	10000
a742ee0c42522df0bc7f73c34fbbdb3d	1106680449	No	Fiber	10000	10000
4babaaf777ce1d8f3df3943823db9eae	1286911490	No	Fiber	10000	10000
c3726fea7d42571e4a67564d162441e3	1089031242	No	Fiber	10000	10000
f8ebc3236059a320d2846842f8f6b393	1112257562	No	Fiber	10000	10000
5c1f1b78096f07938c97416a6a0d01e8	1286910732	No	Fiber	10000	10000
f326ab7d00bd44424ff8128416f597de	1106682168	No	Fiber	10000	10000
35567933a64f88f1af1c0c8e482568e4	1089059716	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
1244518e75225e45a6f66418cec23dd3	1089059222	No	Fiber	10000	10000
7d1c919f2f7c9619a9d82b2e65d088e9	1106686114	No	Fiber	10000	10000
5e3b80cccb657cff8f7e30fb696a39b4	1106681530	No	Fiber	10000	10000
5d202b0be9cdb8661db2f305910a84e0	1286912700	No	Fiber	10000	10000
9131a1e34a09c464b9f5e1a3882d9daf	1286912727	No	Fiber	10000	10000
11158550c44eef5ab690cc3901566721	1111405977	No	Fiber	10000	10000
ff068362c9991968bb09c1c48f7bc82c	1385048836	No	Fiber	10000	10000
76d3ba7400deb9d28f2c25409e469bdc	1111405594	No	Fiber	10000	10000
13d25aa8bc121cbb06f16a422927301f	1106681798	No	Fiber	10000	10000
4393396eea52fa2d484dc992bb6a9261	1111405565	No	Fiber	10000	10000
a3b788dee2303bd88dbd3b3fc003e1a4	1111412961	No	Fiber	10000	10000
bf14dfd7f6c26c1d77a4759275f293d1	1286914313	No	Fiber	10000	10000
08f874fefa67014e1c02ad79aa7c0fbb	1106681474	No	Fiber	10000	10000
bca6f37bc5b65c9697b88b0660ccddec	1413421543	No	Fiber	10000	10000
f148f65b28ce3277ade2092d37197962	1111413113	No	Fiber	10000	10000
2039fd9fc2b0abb7aa1020580a601c69	1106685879	No	Fiber	10000	10000
89111b2f148124fa840cd31f8228234d	1106683883	No	Fiber	10000	10000
d43a483376a6e70b85590f20898d1129	1384901205	No	Fiber	10000	10000
940dcc5f69d90abff603cfaf297c13dd	1111412706	No	Fiber	10000	10000
714f34c2836fca9625493a65a6622716	1111411807	No	Fiber	10000	10000
49b03e9a30101638c156d0196aef93a4	1106686829	No	Fiber	10000	10000
f72aada32b54db106700a0b749ac143a	1106685307	No	Fiber	10000	10000
b113f208fb4612bb9a7db232255666b7	1111420817	No	Fiber	10000	10000
8d5efbd586db8feed9f447f91a532ad4	1106680875	No	Fiber	10000	10000
b61e52a302a1ae1756e454546981b399	1111420067	No	Fiber	10000	10000
526dc70634e21ab3fcea95306781245a	1106683458	No	Fiber	10000	10000
5ee5272096c19822b2252298b200472c	1111411316	No	Fiber	10000	10000
d46dae46f2b80029c86e04016eb09d57	1106681387	No	Fiber	10000	10000
f67075f1665be8e63b185b20e631a049	1286907295	No	Fiber	10000	10000
8d35ff166bd06a2a0de3b32b25cd2b4f	1089060003	No	Fiber	10000	10000
6627a2b98fad33fbc3da7681f4e22297	1106684355	No	Fiber	10000	10000
887071d595f3efec8bca143e7e50e66c	1111413029	No	Fiber	10000	10000
cd6154f3f56aac0c93d3c25e0a323953	1106686522	No	Fiber	10000	10000
b25b939e9758b0ebbd2ba3bd192283ee	1111412013	No	Fiber	10000	10000
62974bf4bb8070094e7332f0c48544b6	1111412507	No	Fiber	10000	10000
1deeb4c2f362bcec53f050623dbcd081	1111414011	No	Fiber	10000	10000
f88a88116b3c3cea5a1a012275ac1a58	1106680086	No	Fiber	10000	10000
de67019d4698889cf14d337032a02ab8	1106682717	No	Fiber	10000	10000
f8d5a43fd54a37d5aaa35039324498a5	1286905277	No	Fiber	10000	10000
57f4b6c284726303c44e8e1cc5d30eab	1106685968	No	Fiber	10000	10000
0fbbcdc32d8d761fd94071804ca55d8b	1112239105	No	Fiber	10000	10000
a9d16aebdeb8748a66c3744284aa0c4b	1106691245	No	Fiber	10000	10000
f122b8978b284db31155e1033772c3ce	1111417550	No	Fiber	10000	10000
f8ee25c6fd7110373a18f1e88c603748	1106679910	No	Fiber	10000	10000
96c6acb08b50437ffa1952047fa0a112	1106685318	No	Fiber	10000	10000
2f1d6587ab600f2bdf38f2098d062522	1384580615	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
02682b326a19665b61a173da93513ac6	1111414553	No	Fiber	10000	10000
b39d32929b1a7bf5b9823b9ad32d80ca	1106683032	No	Fiber	10000	10000
3efdab65782bb1417eddc4a2d540c4dc	1089034395	No	Fiber	10000	10000
23b9d18bb1c26b88f88811f7c9ed1730	1106681550	No	Fiber	10000	10000
cd2a7e41c49df9ec8c33d3ecf95fa278	1111413445	No	Fiber	10000	10000
cc4843747ca1b281553ebb4a9cc62611	1286904690	No	Fiber	10000	10000
7093d3b5160fb0d1514f880ba5fa9f41	1106682246	No	Fiber	10000	10000
a3c78fc5763b64984d14c87ff5081256	1106686720	No	Fiber	10000	10000
708b558a0798381f9496d4565d315ad4	1106684704	No	Fiber	10000	10000
e54b83fa9ac0a13f7435adefb0911cf4	1112259009	No	Fiber	10000	10000
a9beb00dd3bbd5cbc41295114bdd6d9a	1106682507	No	Fiber	10000	10000
48b135670b4ebd3f87c9e609ac601d64	1286913050	No	Fiber	10000	10000
7d90df6c1f1afa44a30e736018d7bfb0	1106686905	No	Fiber	10000	10000
5aab1a8e0ea4ec47a2a049f4e059e12f	1106686975	No	Fiber	10000	10000
ae943bebb9efcd00f437e2fbc7e3fe8	1106684169	No	Fiber	10000	10000
db4d1ead5262ba189f6fa3fe54d9b481	1106679530	No	Fiber	10000	10000
96883287694d06f5f479634c3d559ab5	1106686002	No	Fiber	10000	10000
b73bc5d7b5e168adf651e7136923fd91	1089034312	No	Fiber	10000	10000
9993aa6f4833fd35ef7df2aee6d97f16	1106681866	No	Fiber	10000	10000
50cb6e9701c820f6196456954f8d5e8a	1286904638	No	Fiber	10000	10000
238e6a105809845cb93c0e07fba8e02a	1106682106	No	Fiber	10000	10000
37cefea8f897f952120076b91eda2d2b	1106679764	No	Fiber	10000	10000
e86a9f474a79bf073bef4d4b191d4fd5	1106679742	No	Fiber	10000	10000
0b29f9805b98f39e91f00fe3622c3af0	1089040437	No	Fiber	10000	10000
dd792fef7f069bb5be0a515d7588b8ad	1111404538	No	Fiber	10000	10000
a74ed20f3a81315243aa8489b6dc4c13	1089031636	No	Fiber	10000	10000
83189d64832c141c24fa81708591d6ad	1106684538	No	Fiber	10000	10000
d89639e07ce68eebe9b027164836b98f	1111412512	No	Fiber	10000	10000
8edd00a9a23a8ac0b788717f59561842	1111405359	No	Fiber	10000	10000
095bdc60f88d6a1e19daea5de9838095	1089059179	No	Fiber	10000	10000
b55573b4e9143b365039917855c510ff	1089034384	No	Fiber	10000	10000
dfab78112c601e8e25fccee147fa28b	1106686610	No	Fiber	10000	10000
29d080dfc1e2e9b890c35ab459b8eee7	1106680829	No	Fiber	10000	10000
d49421b9bb736f86080ddfb1bca1484	1286906443	No	Fiber	10000	10000
ad019b2d793c77c8cfece9e5efbf23e5	1089042222	No	Fiber	10000	10000
cfa75646732db699de22185a2873b335	1106683332	No	Fiber	10000	10000
c474023793a3fa55723ebc6c55193678	1089034324	No	Fiber	10000	10000
862001c0777695ae0883460c6b07454e	1089039447	No	Fiber	10000	10000
38e2d5f33ee5f9cff0b498919f8de9ca	1089042197	No	Fiber	10000	10000
8afe3377b846aa3ed62aef1b79fd48cb	1106679858	No	Fiber	10000	10000
23bb4808f53a351eeeda26ae3b430a79	1106681925	No	Fiber	10000	10000
c555a261ea5633060d2169cac74b2863	1089043150	No	Fiber	10000	10000
71781be282121c76680b8623dcb901de	1106681285	No	Fiber	10000	10000
028df86aa18b5eb4c7c1940d761f8159	1106682789	No	Fiber	10000	10000
6ec1e062f260ae76e4972f1d620661a1	1106683630	No	Fiber	10000	10000
e39717c09848d72c39910fda4a80c8f6	1106679914	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
6d82c55b4e160ef546890e73dc742dc2	1106686527	No	Fiber	10000	10000
9a505517f3a675f5ca85f88b90bdde60	1106686469	No	Fiber	10000	10000
4b0d9424238c9973a2730d70e0e2e7a4	1106679501	No	Fiber	10000	10000
be1964d215ada1d91697528e57a9904f	1106683673	No	Fiber	10000	10000
62f3410fbd4dfa38bdcfb29ae00f1e1d	1106686259	No	Fiber	10000	10000
d7be5f9092e30d6116325ef665077aa1	1089040451	No	Fiber	10000	10000
dffac5b0b82243422d352cb361aaf3a8	1106679675	No	Fiber	10000	10000
000f225018088819f0686d0a97862fd8	1089055470	No	Fiber	10000	10000
fef292588278d4f1383ff76628bbe76f	1111405563	No	Fiber	10000	10000
04dbd17bfc4892a107cb4bd734180526	1089034330	No	Fiber	10000	10000
400abe9308af9cba610c8b7ff8780b7a	1106680556	No	Fiber	10000	10000
af47631448cd25cbe6c4a4f4cb4de63f	1112259024	No	Fiber	10000	10000
c2b6e16854232bda50f6d581ea09989d	1106682254	No	Fiber	10000	10000
91c28f68c725a4445ee8a00e2c0fa0ed	1111411668	No	Fiber	10000	10000
e1691bd0cadf5a2aba062d9b732b0bba	1106682634	No	Fiber	10000	10000
253fda6003233704c2fc64b1656ca9d9	1286911070	No	Fiber	10000	10000
f84ecd3d89b9dea958969ddf4861da4	1112239081	No	Fiber	10000	10000
5fd92457835c635ecb706c4a880d0a0d	1106681156	No	Fiber	10000	10000
5ae3fc459f5f963f4a2b1efa18d8b1f5	1106684331	No	Fiber	10000	10000
b557a36061a6775b3698470637e22434	1106681221	No	Fiber	10000	10000
6caf7c3a2083030c3f9e8316377e72db	1106686455	No	Fiber	10000	10000
f426f5291d2231a44caf0a7e4b678dad	1286912679	No	Fiber	10000	10000
e91b7658e9d1da5d07048bf6660a5827	1106683985	No	Fiber	10000	10000
d8cd3c30935729c845eba3ad89908fc9	1106685433	No	Fiber	10000	10000
d814208a17aa2d6070f22a6d0354fadc	1112236584	No	Fiber	10000	10000
d9a91ebd73a8554c931d25a87f68ae78	1106685695	No	Fiber	10000	10000
3510b93c83629dd061cdcf4a20ea8a16	1106686834	No	Fiber	10000	10000
cb773a274d80989e0f5df1d49a160df0	1089039725	No	Fiber	10000	10000
2d921cdc5fc7dc8b58d0699bed44364b	1106681516	No	Fiber	10000	10000
94ffd9ac774b1eb81cdb4571d04f1117	1111409918	No	Fiber	10000	10000
3fc65fd23ccbc4b09677b3d981c1be2f	1106679891	No	Fiber	10000	10000
581b1eaa71c70c0f04dce0943c4e175e	1286911859	No	Fiber	10000	10000
b179f89983a504687d3806baee5a5be6	1111405160	No	Fiber	10000	10000
c32ed6cea1c000c030e0703214546c05	1106683591	No	Fiber	10000	10000
dad42ca6f70cd778da431798eda1c9fb	1106686779	No	Fiber	10000	10000
65d675b3fd84833dba65d99dd91b3d22	1112237728	No	Fiber	10000	10000
400d74ff37296b4d9e936d4dfc1ff7da	1111411394	No	Fiber	10000	10000
c630a9ff698b869b71178c9fb5aecee8	1089059209	No	Fiber	10000	10000
f5ef382ad9aec2327142ac4bf0c6a8f7	1106686348	No	Fiber	10000	10000
9671e585f48257a764910512231cf15b	1112257257	No	Fiber	10000	10000
a00ee1c2d2f8eb8e9018bc76490383a2	1112257534	No	Fiber	10000	10000
919f176270edd634d91c94722e70198f	1106680533	No	Fiber	10000	10000
b10380c1c9b1104fe3d2d64522aa6685	1106679829	No	Fiber	10000	10000
626b5ac1905701a31a71101d4da13a75	1111405202	No	Fiber	10000	10000
0d1230be5ffc28dd9f02ef46d88ea9cc	1089060072	No	Fiber	10000	10000
018f88f371bda9c76a1d2c9a0985592e	1111412027	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
e3a287cd3a24b5535514289c63f3f319	1106686782	No	Fiber	10000	10000
e4aacdbfde251038442330950003ae2f	1111406184	No	Fiber	10000	10000
4655fd2216ee6b4e71649ba292da9098	1111413286	No	Fiber	10000	10000
5ad4d3c205c8d893d2189d1821693ff3	1286906156	No	Fiber	10000	10000
bb31ed81111788410c9ff8073869d513	1111411373	No	Fiber	10000	10000
8b3329bfa9054d90ef33819a0850dcf4	1106685853	No	Fiber	10000	10000
474cf29bcabbfe3843a96f08dc67fa7	1111406131	No	Fiber	10000	10000
0dbfc113bfb812e650bf362f37e3fc75	1286909838	No	Fiber	10000	10000
7c0a76f6e20aed85dc170ea7edb79358	1286907333	No	Fiber	10000	10000
3102438291822f4b70c47f80df03a9f2	1286911573	No	Fiber	10000	10000
1ad1df8e7b7ae0728e1c48ec25c7ac21	1089059975	No	Fiber	10000	10000
ee40cd6749262ffef518e10aa9376ab1	1413421438	No	Fiber	10000	10000
429ea1a824636816e3382b407e42e4cd	1089059216	No	Fiber	10000	10000
f1a21a8e8769b9a9ea20623901f57028	1089034832	No	Fiber	10000	10000
bef4219cb1e886e8b1f2ab1a248ef163	1111413995	No	Fiber	10000	10000
87402842a44e5c46ce87e42bbb9bf69a	1089059350	No	Fiber	10000	10000
bb1a144820c5a9ed801449746313dcc2	1286911823	No	Fiber	10000	10000
483cabcc8c7b56a61f9d30d362785b01c	1106687058	No	Fiber	10000	10000
3991261bbe35cd7f1e9f5c4e6e6bf767	1286913434	No	Fiber	10000	10000
4390daf9e7bfc0786a74951fda57fa34	1111412029	No	Fiber	10000	10000
a9ff266a9514d073a40ff0cc38e1a263	1111413224	No	Fiber	10000	10000
f499d7c848c4951ce7ec687d3a4faa8a	1089041329	No	Fiber	10000	10000
1c31fa10737c4fb5d22ad08104dfd170	1089056589	No	Fiber	10000	10000
98066441484603a2d0f3f06e0c850ef1	1106680782	No	Fiber	10000	10000
670cb4a95dc8c597d1c3a2a6d34d4cc7	1106686833	No	Fiber	10000	10000
6177c17049fc539e2a3115e5df58f7b8	1106682047	No	Fiber	10000	10000
ff4a38e763b15652155a93c97a24dc2f	1106687234	No	Fiber	10000	10000
43ef2f91a7a8494dfd61694db0f5a638	1111427343	No	Fiber	10000	10000
a64e0e038e7d08dae3116c94b38c08d7	1413411270	No	Fiber	10000	10000
dfbf1e799ca30bd94d661e5576a5439b	1106685216	No	Fiber	10000	10000
a9dd347253ae3d1b20182ae2e8ea740c	1111412075	No	Fiber	10000	10000
3ac88d0265f59732b38e59d5f7257edf	1106679434	No	Fiber	10000	10000
66a2461967076cee635f431e284a2a64	1111413083	No	Fiber	10000	10000
649fd7e8d494a5e275ba27f3ac2ea0f1	1106684967	No	Fiber	10000	10000
e27dc3108a932043be5f366bc4912851	1111414586	No	Fiber	10000	10000
06148310b8c012ac86eb50684dc8ba1f	1286912547	No	Fiber	10000	10000
78a1a4223f3a5cba4df2bebfea0661f0	1106681297	No	Fiber	10000	10000
ef512363b633db909c4f535a02adee4a	1111413397	No	Fiber	10000	10000
e4517456518016fe2f532ebf95cb97d1	1111423325	No	Fiber	10000	10000
6e4374a990fa39c045e8eb28cac5a138	1089031245	No	Fiber	10000	10000
806d21113b5944ff92cf404749d79494	1089040423	No	Fiber	10000	10000
dfc8dcdf4b8478a3033426748608b1ec	1106679355	No	Fiber	10000	10000
70877a2fbe796bfd1d0b049633e9176c	1286905187	No	Fiber	10000	10000
a0cc132f02c1cab4b60ac44121028300	1106686705	No	Fiber	10000	10000
d7be1289d4dda693b32e074749bfbf7a	1111405353	No	Fiber	10000	10000
1baf86b2b5c826fc81b05fed1c3440fa	1286904632	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
3b0dbceec23037366f97416741cdd3a9d	1106686576	No	Fiber	10000	10000
eca84d9a2a61fef3c01c58a4669eb098	1112239080	No	Fiber	10000	10000
b5df3dfab9be5f31207adb342832f83e	1111404519	No	Fiber	10000	10000
45b3a59fa1cd242c74e2324b3b1a1bc8	1089059976	No	Fiber	10000	10000
80c6d942d48743aec9c3970667be1d11	1106680309	No	Fiber	10000	10000
b32e0609345c12122c495e50ba4b50ce	1106684422	No	Fiber	10000	10000
d299dca5c9d8e1f074fb80981814be2c	1089031958	No	Fiber	10000	10000
0f1e972d9f7f6e1eda4041a05940dee	1089043852	No	Fiber	10000	10000
069827d75fd6de8efd14c7513b215c07	1106685676	No	Fiber	10000	10000
0f2d523c2a468d503d57d75526417079	1286909485	No	Fiber	10000	10000
73bbd186e8b4eefcc3835c31cb44c0c3	1089040453	No	Fiber	10000	10000
da1dbdbd6da2de5f22ee60141820748b	1112257576	No	Fiber	10000	10000
0d1bc35a61f9ba4033b36a5c55a34f07	1106679129	No	Fiber	10000	10000
a7fb2b2501085ed1c4493c20b1132b3e	1106684391	No	Fiber	10000	10000
8dea1215ebbe031474aaf4fa3eadc002	1111413008	No	Fiber	10000	10000
4874565d276366b3093001fb144f16fd	1286908001	No	Fiber	10000	10000
3cd20c85282f3235f1a4358ebfdd2ad0	1286914304	No	Fiber	10000	10000
1a446323856cbb1c641c45615e69262d	1089059313	No	Fiber	10000	10000
5c99b00a2462a20f8e41f176b5968a47	1106684940	No	Fiber	10000	10000
1db9406f4fcf1dd2521a208f6d8d8017	1111410341	No	Fiber	10000	10000
d2565f0586f048a281c7fe6c5158007f	1286913859	No	Fiber	10000	10000
c2e79ec56946491403092498a13e873d	1106686357	No	Fiber	10000	10000
f4713a3db0f58a9ee9b878dcb3cb555f	1112237700	No	Fiber	10000	10000
9b73586bae29e3bd1ca4802b4532f00d	1106685294	No	Fiber	10000	10000
86dcbab55f4ad580fb0279a363a00026	1111412637	No	Fiber	10000	10000
64352885cd0467977784dbd5262e0e66	1106689954	No	Fiber	10000	10000
18af2332fe5a175c79cacc5e641d927a	1106684965	No	Fiber	10000	10000
91b292b2e085ae9bf4493f5fb9862c17	1286905252	No	Fiber	10000	10000
85f96130de47b6c958aa0ff28de23c6c	1286907673	No	Fiber	10000	10000
a828947a4ca6a4562f4137526c65ea0a	1106681840	No	Fiber	10000	10000
73546ae3367ee3a7b155475d40934592	1384899500	No	Fiber	10000	10000
ccb5af5f6cf12528a81a3d43b8fa8db8	1106680761	No	Fiber	10000	10000
04fe49519a7099caa7b9809e02b37f10	1089040424	No	Fiber	10000	10000
4f29ac72618c62719395e7ce16496d88	1089059314	No	Fiber	10000	10000
cc3d2724b81e199d2f4604583794b581	1106684258	No	Fiber	10000	10000
210adf891f5c59bad90b54899b1740aa	1106681389	No	Fiber	10000	10000
14ad2ebea7ebe9b1dc0bfdaca0831636	1106680421	No	Fiber	10000	10000
8600d1feb49a32187ee78018b4c3088e	1112257533	No	Fiber	10000	10000
ba344f8bf3b33c187ce1b08d6e654c79	1106682670	No	Fiber	10000	10000
19d8e219e1e3cfc83cdf19cc75e8cd3d	1106679816	No	Fiber	10000	10000
5cb3fa15788cb34733ceb0adb945529e	1089042233	No	Fiber	10000	10000
1011b3c2e4257459cb9eef42548510b4	1106681111	No	Fiber	10000	10000
e76d52ca3b3d902ddcce58739a2a5501	1111413021	No	Fiber	10000	10000
efc1e04fe98668c68c34796e872003ff	1106685336	No	Fiber	10000	10000
8fa344929f27abf3d338d2c140637d30	1089031633	No	Fiber	10000	10000
5014017b52b663fe80b8ff028339442e	1106685839	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
82aadff00ef66e11d358f94dc155ff5a	1286909577	No	Fiber	10000	10000
84bc862683c3bddb56daa16de013c66d	1089060067	No	Fiber	10000	10000
f12bac82247538057d453aa93a2716ba	1111404908	No	Fiber	10000	10000
ea82f537848b522c958aa3ec4a23d06c	1106685917	No	Fiber	10000	10000
e859f0e86ce2223c8ffb706a0aff8698	1089032445	No	Fiber	10000	10000
125bf2b78c76ffa447545285133e4ddd	1286906977	No	Fiber	10000	10000
a216f4b69e8d201ce588a9c7f127f816	1106686124	No	Fiber	10000	10000
2b0280c43012fd50f5d1de75d0eeb2f9	1286911232	No	Fiber	10000	10000
b09a264370daa763a9296f8367971af2	1106681980	No	Fiber	10000	10000
480a92d6e368fc0fbabdfb296ecbf97d	1106680065	No	Fiber	10000	10000
bde7c548377f68c6ba1260130f8e72fb	1111413198	No	Fiber	10000	10000
e45490465e7b262d07b9e7cedd5a61f0	1089031639	No	Fiber	10000	10000
59ee785fbca35e267d5c7be670bd80aa	1106683275	No	Fiber	10000	10000
3ec3b619bd33c97175c5a65c65f39f20	1089031961	No	Fiber	10000	10000
54a0004b1e8b664f4cbcb2e99e34509d	1111405597	No	Fiber	10000	10000
7ed6861e9028d0c8da618f3951becfcf	1106684315	No	Fiber	10000	10000
af60ce71ceb125cb3e5ce3e044ef2db5	1111410767	No	Fiber	10000	10000
164fef99a340f21e9c6bdfc58d408852	1106679394	No	Fiber	10000	10000
69fbef3543eb705a590464b205247bc8	1106682387	No	Fiber	10000	10000
2ca5d7187360d46d120e717e087f3a2a	1106680085	No	Fiber	10000	10000
f63fd3be864cdda5a93dcba0d6e29d77	1089059397	No	Fiber	10000	10000
a02524ed4ae82d1c25e229d18652d893	1106685065	No	Fiber	10000	10000
4a189dd9785551dff19c764616feb1d	1106682195	No	Fiber	10000	10000
5541cd1701c60e6e2b31883afc4a8f98	1106680853	No	Fiber	10000	10000
bc6813e3f5690bdad9ff5ec86fcd5480	1112239078	No	Fiber	10000	10000
a21548c5496adae080f6d64b200dce47	1089034320	No	Fiber	10000	10000
0eedfbdf122d68226ceee945ef4d6108	1106685836	No	Fiber	10000	10000
bd1a51cbced33f665ef7bb42255b1b01	1111411666	No	Fiber	10000	10000
5d226a4b7623dea17428d71833b3f4a4	1106679656	No	Fiber	10000	10000
cd4de131b26363750d2d0d5d3763a79d	1089059107	No	Fiber	10000	10000
aeb077be40bef2009fe55dd68aa187ec	1111406196	No	Fiber	10000	10000
25bea0077960e73dcbef531dd0c96e2d	1089034388	No	Fiber	10000	10000
f6beede78e5e7b1689a5397fa1d40c63	1111413088	No	Fiber	10000	10000
d7c52d8b016dc4631d8871242329a265	1384900930	No	Fiber	10000	10000
01c9ce0b84a8a248e2de4eb6f9962f8f	1089034321	No	Fiber	10000	10000
ef060fe0f6035fabd0890020124457ff	1106680916	No	Fiber	10000	10000
4913d7c112e2aceb8530daf03f9eaff3	1089041412	No	Fiber	10000	10000
9b023c37a85551df752bcd878733a0aa	1106684240	No	Fiber	10000	10000
8ac20677b68c274e2d7fc0cceb1ecb80	1111413869	No	Fiber	10000	10000
aca93a8cd97d1e1246588481401d7d3b	1106681032	No	Fiber	10000	10000
62209f03b96d088fec5f1c1346c0bba6	1106685231	No	Fiber	10000	10000
a12e182d64f8d2ecf08b61c539b1cbb5	1286912395	No	Fiber	10000	10000
eb4facd695c1e80ec6508b20392faa78	1089039757	No	Fiber	10000	10000
d2d2aefa9ded3cdc03f1c2139a8951ad	1106683077	No	Fiber	10000	10000
ec6760889b76338581ffdd90cf1e4aac	1106681585	No	Fiber	10000	10000
0a86e67d07c56efa8a1dc251ab4093ec	1111410339	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
638b25120c11645ffab690d76b6ae717	1111413080	No	Fiber	10000	10000
7df414926e4ce72c57738ae8500dfbcf	1111410812	No	Fiber	10000	10000
144484fe6cfdad0e999ac9fa8de4f718	1111413010	No	Fiber	10000	10000
f0fcac97d04a0ece8911e8978f80d05b	1106685044	No	Fiber	10000	10000
64d85bca6359aa3e475df28c6d733f30	1106686603	No	Fiber	10000	10000
b45a3842c96cd4454669c70fbc8691bf	1384680078	No	Fiber	10000	10000
7822f435814a83976f25f0d4086c9726	1106682614	No	Fiber	10000	10000
27e6f897c0eac4c331b98dc98a842ae	1089059291	No	Fiber	10000	10000
8816cccd3d749271f462364314c98521	1286904737	No	Fiber	10000	10000
d1d176d6127ab176837da39540a80367	1111427588	No	Fiber	10000	10000
0abd3a39fc467f4e1f265441e4d0b1f0	1106685993	No	Fiber	10000	10000
2ce3792062da462d0bf4fd6ae38064c9	1106686583	No	Fiber	10000	10000
455622522ccc241ea94f9b2887bcb3ba	1089059401	No	Fiber	10000	10000
1de4da353b2b3c5bff2d4b07ef90617d	1384899522	No	Fiber	10000	10000
697d10c7822064a066d43e7b825ba287	1286913133	No	Fiber	10000	10000
8f902931de6664a0a388dd6d8a937849	1106681848	No	Fiber	10000	10000
0678dc9f96923b2130e644bf92c62ee9	1286905847	No	Fiber	10000	10000
56fc64dc5820d914a9ab0a90a6cd99d5	1106681176	No	Fiber	10000	10000
24216592645bb481dd18073774dee521	1106686635	No	Fiber	10000	10000
db0b4610c324b7b562f75b6340be8b2f	1089040139	No	Fiber	10000	10000
daa563eda01f42d6825880fc15ea1286	1106686539	No	Fiber	10000	10000
32c6c9ecf4873e87ad2122a3fdee5bb3	1106681213	No	Fiber	10000	10000
1ba63d6a2a28beaca0b5422a36474a86	1106683756	No	Fiber	10000	10000
2054d2fedac30d800ad37dd290696b0e	1111412022	No	Fiber	10000	10000
cc64df52466a3df1040f03f350e03122	1106683059	No	Fiber	10000	10000
e4545e8679d67038df6a24a2802e7deb	1106683080	No	Fiber	10000	10000
476df8520821d3a5bcbf6db57ab7c03f8	1111413189	No	Fiber	10000	10000
d7326e9eef41212bccd13d4620c68489	1106684492	No	Fiber	10000	10000
eb72180d99730530e55b0cb9d512fe38	1089056304	No	Fiber	10000	10000
2077244b791a4dc4f9e7700e70c6c732	1111413190	No	Fiber	10000	10000
2e4ce1818f64d4ba839ea61fbe457723	1106685593	No	Fiber	10000	10000
b496677c4daee57150df73828521b073	1106682604	No	Fiber	10000	10000
3ba96c1a46e894552c74861cdfb323d3	1089042217	No	Fiber	10000	10000
2a7001fdb03b864568ac2682cd915e64	1112255157	No	Fiber	10000	10000
d60e701cba3be20906003dc7002fd55a	1286913518	No	Fiber	10000	10000
97e115b716da2f16fe3fc70312856b78	1106682250	No	Fiber	10000	10000
65c3360cf285cc667a9c1062ec340457	1106681028	No	Fiber	10000	10000
7f1d30d96f4473c10c31d9c141d3d34f	1111411430	No	Fiber	10000	10000
7b00baa51228a06920cdf10b3fc6594a	1089034374	No	Fiber	10000	10000
ecc298cae11f383d322d70eb6d8f323d	1106682639	No	Fiber	10000	10000
e62232c5501ad4800c41eb8117ad221d	1106685708	No	Fiber	10000	10000
295e57ad8131b17621bda4833bd638e9	1111411484	No	Fiber	10000	10000
3e6fd2eeee56b0f615d740b585af816d	1111413191	No	Fiber	10000	10000
6078e7bfd64afe238b12e6003e798820	1106686063	No	Fiber	10000	10000
f4ef5e4f7ae7594c9fc1c151b5891d68	1106682994	No	Fiber	10000	10000
6d38498e91c034d6ac9c89490eee6b4c	1106686144	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
71311d3d14ddf514bd090f238dc0881c	1089042230	No	Fiber	10000	10000
cc595637dbe55b4b1e9bd7e5a7d1b7a5	1106681117	No	Fiber	10000	10000
97e5f95af47745967b03c800919730f7	1111414564	No	Fiber	10000	10000
c8c2cb39b9eabd19103c63f2bdda4809	1106685550	No	Fiber	10000	10000
b7d9790ef97666739c92e9c8338a84ed	1111410385	No	Fiber	10000	10000
bf0e5023559de6bd09c5088fc78fa108	1111413233	No	Fiber	10000	10000
0af23f51e2834d23babf7159b1b42a65	1111411389	No	Fiber	10000	10000
4f21abac11bfa5183feff0f8711fd8bf	1089031965	No	Fiber	10000	10000
2be151230f5b8185ea3be02aae95b043	1106685136	No	Fiber	10000	10000
79b19e122dad80e8f2662bd0b06e3c22	1111413193	No	Fiber	10000	10000
a8aa30ad45aed16e6c0b304d17bbc73b	1106683700	No	Fiber	10000	10000
c1b640e9e8b3e6a8788ab44925e8f0bd	1112253232	No	Fiber	10000	10000
f6ebc1ac3d48bda766333a71b458ed90	1106680468	No	Fiber	10000	10000
f6aa4068769b56c92a38e97eb6dfd44e	1111411888	No	Fiber	10000	10000
d50bd3aa8360459dcd234aecbe94b3bf	1111413218	No	Fiber	10000	10000
89dcee040d46495ce06d46754a8b8600	1106687026	No	Fiber	10000	10000
76b00f42d84c2fcffbc61dea8c5f4550	1111412053	No	Fiber	10000	10000
51e73f29d843012d8db62ec02c61b6f2	1089055474	No	Fiber	10000	10000
ffbd0f4bd1ca57cd82c5bcb23fc41362	1106682763	No	Fiber	10000	10000
2177953877a6d622ec83aa8ba5246936	1286906005	No	Fiber	10000	10000
b28acb6a24194b5c7f9802670e2e943b	1111413897	No	Fiber	10000	10000
8db9e0e6333994b2544383db602846be	1111411390	No	Fiber	10000	10000
955f87c5d37fd29bcdcd634705ba293	1111414802	No	Fiber	10000	10000
6b7f08b4041cbfe2630cc21d3dbd87f0	1106683444	No	Fiber	10000	10000
190f081032db1e5877136a03d9a3f16c	1106686107	No	Fiber	10000	10000
a3fd05a69f4225f161aa1975a19c51fa	1106680480	No	Fiber	10000	10000
677d48b764654b8f75ab31faed2f3940	1111412764	No	Fiber	10000	10000
c1ba91392bb9618fd784a7a9b27d2911	1413421486	No	Fiber	10000	10000
7897f9104bb7479b843a0e96c7a1ff46	1286912346	No	Fiber	10000	10000
b2e661f61d4e10f21ec0e03c39115f68	1111413182	No	Fiber	10000	10000
4465ed6d2de7298bc1214f165b1414ca	1106684836	No	Fiber	10000	10000
f0f1371f9effcf484206d513c3369c29	1106682917	No	Fiber	10000	10000
cd204d53475229bdfff6eaf88b3686ec	1286905230	No	Fiber	10000	10000
01112ce87aa29c3c2295738bbf8d4cdb	1111412225	No	Fiber	10000	10000
f8789cfd6244970aff1603b5f0a1e4c	1089043172	No	Fiber	10000	10000
260e115feb29ce87fa0205aba68f0b68	1106685426	No	Fiber	10000	10000
08b786185eb52201a671f3601b2c6303	1106684941	No	Fiber	10000	10000
816f9c1a5c7f1b15a86d014e33451160	1089040443	No	Fiber	10000	10000
4ea8e40435de69d3339b34109231cb33	1111413036	No	Fiber	10000	10000
bda545e40aa478f013f332d25deae4ba	1106686373	No	Fiber	10000	10000
b52f1a9d6a5f77399aa8446e69c39048	1286912572	No	Fiber	10000	10000
4ff85206e622b26114e3a38d54a7134d	1106680496	No	Fiber	10000	10000
8f0f80b51f1cb0cb5e2dd9cfb9f2753d	1286904938	No	Fiber	10000	10000
05f9eb7481168851981eaaf8be8749f0	1106685613	No	Fiber	10000	10000
e9c67e92188fed422935eb34437803a6	1286914406	No	Fiber	10000	10000
7fe6e7e449e3f754fc140dab0709fe13	1111423879	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
9f5065ad1c8771da75d7cd388158fa6f	1089055523	No	Fiber	10000	10000
a3fb36f60449b50dfd513305bef0b798	1112257365	No	Fiber	10000	10000
f678b306bf176202621e43c6e471ef43	1286908344	No	Fiber	10000	10000
890c14ecd3a3079dd3e761c939cf3f52	1111405161	No	Fiber	10000	10000
a1b2232069e32bea7b06cc954216750a	1106680289	No	Fiber	10000	10000
16fffa18614e50727fbf22a6a87c83a0	1106683179	No	Fiber	10000	10000
60a5c4fa2e9dfa785ac86e05ad9149cc	1286910541	No	Fiber	10000	10000
b8ab88a789972d09554f9b063c983f38	1111405190	No	Fiber	10000	10000
422cee7d3c4f548f3c7cf4945d832e9c	1106684040	No	Fiber	10000	10000
0bb4874be7b138d779583ac1bcff06cf	1111407743	No	Fiber	10000	10000
47347b13693269aeeced4dca5e61a218	1111413204	No	Fiber	10000	10000
8a275873edc601e79a7ea3cfff6083253	1089039717	No	Fiber	10000	10000
1fee9b50d465dd5b475d893d07cc01dc	1111413038	No	Fiber	10000	10000
6fa1f86fd9b63cf50148d77dd8f021e8	1286914631	No	Fiber	10000	10000
641537fbe26afa2213681843c910707d	1106682458	No	Fiber	10000	10000
e43e3c0e45093bc7077ce6072bd863b7	1089032672	No	Fiber	10000	10000
471c014f64800dd23683994a9c6b2fab	1106682310	No	Fiber	10000	10000
6c6e89cce45ce9c82f4e134bede709bd	1106681008	No	Fiber	10000	10000
dd0f9a9c9eb552b60ae719a8df323da8	1089042223	No	Fiber	10000	10000
6dd0afe01e68b5326152a35d52d4b556	1384586306	No	Fiber	10000	10000
096217ae2241b5315dbb67e47d4c27b8	1111413212	No	Fiber	10000	10000
09b53c67b44ac9a708e4f4e515a53535	1106683323	No	Fiber	10000	10000
a0a1483d62f5ec519632f66ecc8cde06	1089040446	No	Fiber	10000	10000
6edbd2201a8bd45eb87e15de89b58cf2	1106680436	No	Fiber	10000	10000
daae958460c108248fa9891c0f6925c1	1111413099	No	Fiber	10000	10000
5ff1798d9b16b6866df4dee0f5953a87	1106686023	No	Fiber	10000	10000
3af61cab2a0218c97255f6db5c67ed40	1111410805	No	Fiber	10000	10000
ab64d9ec53ed3a50aaa84bc5e795f7d9	1106682023	No	Fiber	10000	10000
97dbc2c54a645059e77f3d5dcf2142b1	1106683676	No	Fiber	10000	10000
f942a1455456c2334d6c60255c5c31ee	1286914706	No	Fiber	10000	10000
db7169811a531f86abceb3233b65833a	1089055469	No	Fiber	10000	10000
35fd4625aa225ba574e59443c6ba1af7	1106687088	No	Fiber	10000	10000
db05eb9b58908523ba40f9af80d0e8bb	1106680820	No	Fiber	10000	10000
569ce2e7f697751ab18163616ecca208	1106682145	No	Fiber	10000	10000
af1671b0554753cb946e3129300bea4b	1111405191	No	Fiber	10000	10000
034a3f93840e0c9fed69086e50925a5a	1106679865	No	Fiber	10000	10000
839ce0bc82d999971e22b6cec601cf51	1111413396	No	Fiber	10000	10000
101f21df5760d2bcf0c42e9a0b8cd8e3	1106679563	No	Fiber	10000	10000
f9eb1a9727cd36c70baf4360b188b8de	1286908287	No	Fiber	10000	10000
7d4aa35757b2b3e87945a647c11c0cb3	1111405571	No	Fiber	10000	10000
b07dab82dae45de95414753500b1dddf	1111411410	No	Fiber	10000	10000
34868d32d32356c4cd17b07a39078678	1286912414	No	Fiber	10000	10000
0dfa2f4ddd85a3d69dea85923c6f8f95	1111411937	No	Fiber	10000	10000
ea458ea6f53b9304712a9d5e5923071b	1106681414	No	Fiber	10000	10000
8d4408117a2baacb8c04f127ade378b5	1106684491	No	Fiber	10000	10000
311e54f3790572f0cb8bc77993898034	1111412054	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
3f5d9e4588d8e9da395df459ad160397	1106685201	No	Fiber	10000	10000
00d65168735f5de97b918f564a706f11	1385050346	No	Fiber	10000	10000
20a2f5bff2f60c1769b89d2817f8b78e	1106681831	No	Fiber	10000	10000
1a9eed26c47c92eec769d0d89fa2cb28	1106684431	No	Fiber	10000	10000
b821f88ae17ad57eff81d14684754550	1286907388	No	Fiber	10000	10000
b0de5cbfe3f840bffb3a240567eb1ee	1106682444	No	Fiber	10000	10000
8ab21c278d49049a6dbeee1494c61e9e	1286906506	No	Fiber	10000	10000
d85c4641d9f1dc369b2517fb3f49b36	1112264006	No	Fiber	10000	10000
19f9812800896845028b6c8547415bef	1111411377	No	Fiber	10000	10000
1e2e74154f1df9b3c412c0280d5ae991	1089059201	No	Fiber	10000	10000
468fa0db7ae1cd64ca698b6e33b00c5d	1089039699	No	Fiber	10000	10000
614b18a1fb446eb67c2aac5017c92ade	1106682523	No	Fiber	10000	10000
c1ba387f134f9c531c0fe579d41e48c7	1106682033	No	Fiber	10000	10000
c2b960c430c51fbfd5abfc9fac5e4df7	1106681905	No	Fiber	10000	10000
fcbc6963af8e5c4b6f96b53e4e249979	1111425688	No	Fiber	10000	10000
9b44046862e59f5f582087f7c68302aa	1089060002	No	Fiber	10000	10000
2440107662384aeeec764b0e27d3ece20	1106680960	No	Fiber	10000	10000
0a5a9268a23b49d63b627145f7456603	1111413018	No	Fiber	10000	10000
def8ece7016b6920d5a794e644970429	1112239074	No	Fiber	10000	10000
81290a20fe6a9c7e7952146c6bc73ee3	1106680268	No	Fiber	10000	10000
f8f38b43979ded5541093b8fa80ef0c9	1112239093	No	Fiber	10000	10000
a1a979ef5bdd453ce242e0783bab7d5a	1111412052	No	Fiber	10000	10000
dc86c103d0aecd585786ac43115155f3	1106682727	No	Fiber	10000	10000
12e618ddaa029a71a00cfdb6af46102b	1106681069	No	Fiber	10000	10000
a15b0519ec6db1335b792076d5a5e883	1111414549	No	Fiber	10000	10000
5fec8496235df8aea7df837a5e426f9a	1286907634	No	Fiber	10000	10000
cd8a9a4ee55db977154b4ce0b2908505	1089059117	No	Fiber	10000	10000
0bfe986089d0d69e19be1f6146ce883f	1106687217	No	Fiber	10000	10000
29a0dcb15fd972f8a4edd2aa3624b1f2	1111409945	No	Fiber	10000	10000
08789c5d524d6de25ca0a60b7cf5ecbc	1111413188	No	Fiber	10000	10000
d6c0c5820882481a883aa2996be5e925	1106682114	No	Fiber	10000	10000
6d350818440ed4141bdaf564c00b7d20	1106684246	No	Fiber	10000	10000
e191bea170e3e3db92fec2780d22bd33	1089039737	No	Fiber	10000	10000
48e615e25196402f6a0e9279b8d3e0ea	1111412704	No	Fiber	10000	10000
0cb908a3920899c87acd5a8b15fd09b3	1106687157	No	Fiber	10000	10000
4c244a81c8f6237670c4601c7b73de41	1106682711	No	Fiber	10000	10000
02598f7e5062e9f8f310ff1d6ecbc4a6	1111414626	No	Fiber	10000	10000
2b09a2b6dbe0dc1e16e9853753b74c3c	1106685982	No	Fiber	10000	10000
f04cd514145b8f852c8438d46be85f33	1089040435	No	Fiber	10000	10000
13a968ebd519d2d6f4a36609708019df	1286905454	No	Fiber	10000	10000
9599c56ce1ca11e55fc8039872ca4f6a	1106685665	No	Fiber	10000	10000
4b6c30d55c3930569142944a3f0846f3	1089034830	No	Fiber	10000	10000
1865f62210bc4343bc2fb637f92186c1	1089039761	No	Fiber	10000	10000
625dce5b0959120724e073f60f187780	1286912326	No	Fiber	10000	10000
1a03682045dabdb6031bc44e3ed13495	1106681786	No	Fiber	10000	10000
0f348fe034acee7e5daecfcc5fe9c4ea	1106685348	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
577239e677fba55a581121c894dd0413	1089059115	No	Fiber	10000	10000
9f5dd37dc285a60d8fb7f8ce344783f2	1286907949	No	Fiber	10000	10000
175baf4005b24c496fb08e977c1d8da3	1106684557	No	Fiber	10000	10000
6650df24af050ddc9d896b106af9eb20	1111413332	No	Fiber	10000	10000
2bc949aed8309220f26e555bca9ed3d0	1286911782	No	Fiber	10000	10000
0737e6efb690a1b8aaf9a87dae905acd	1106684311	No	Fiber	10000	10000
da53abef6fab7610cdfc2f611b4bc45d	1106685729	No	Fiber	10000	10000
ad680c80b715f51e81ceea87af3119e5	1112239126	No	Fiber	10000	10000
3871bc4433c88bb0d4ac47bc34860ef5	1112239114	No	Fiber	10000	10000
f53466930c620a30663065b2f1b8702e	1106680103	No	Fiber	10000	10000
bb6ed80883bc7ce7a0605b32055085d6	1106681009	No	Fiber	10000	10000
80c53369e868d1ee5ea22813244eec92	1106686458	No	Fiber	10000	10000
319e9074e5faf70728634638d9c18f2d	1112258989	No	Fiber	10000	10000
abac2eb0e09e1ab10c3d0d1d7c998f8a	1106681775	No	Fiber	10000	10000
0dd2814ed4af183dfa8542ef8521d680	1089032793	No	Fiber	10000	10000
23122b5ef630455b3d0b81859b1af73d	1286913297	No	Fiber	10000	10000
d4e86d6bc53bcf6c0112741ce5109f67	1106685547	No	Fiber	10000	10000
c1111e34d386872551e74fe66681b31c	1106686796	No	Fiber	10000	10000
49e2f95adfcbfd3ef3e12b32fec777b4	1106684881	No	Fiber	10000	10000
8ec81c9de9a0d907d062286c62cdcbecc	1106679897	No	Fiber	10000	10000
4a611fb5d4d06ac1ebe87d51eeb6cd34	1111413115	No	Fiber	10000	10000
7ef3e50e8bb23cb694b7f0c609dd34a0	1106685448	No	Fiber	10000	10000
6b611f2cfe04aa3b96603cd369877e85	1413421541	No	Fiber	10000	10000
7b0fe825bbfc91e32d859f4acc85457f	1106682162	No	Fiber	10000	10000
d5fb8d27bba213a5accb930eac2e2e35	1106681749	No	Fiber	10000	10000
b37aa955d12ce037ae614c84e6c644f7	1106683457	No	Fiber	10000	10000
f770789d8195487d45ab96e6d9782759	1106684008	No	Fiber	10000	10000
732a93b5013dc215fc5f36e9df4c5195	1106681410	No	Fiber	10000	10000
3a8944172ee91697a1e2e7437c3c8128	1106681411	No	Fiber	10000	10000
0a95a8b603cdaf0b4c39899554145d3c	1106686176	No	Fiber	10000	10000
7fb118ba3e1fb8b8e268b2e2eb561935	1089059418	No	Fiber	10000	10000
35596227af55c032aa7edddd1a2faa6c	1112256280	No	Fiber	10000	10000
462a702fe33b4f73e3bf50bed54b5679	1111413222	No	Fiber	10000	10000
5ac74ce010c612ebbf47932170e0118f	1111413016	No	Fiber	10000	10000
990128b623d6fe8bf08d118217d1400f	1106683495	No	Fiber	10000	10000
1f96f7bb62c0759c49d48c44bb4abd5e	1112237699	No	Fiber	10000	10000
ac80cc1439ff2a53f53c064f331aae45	1106682870	No	Fiber	10000	10000
0e5dfd04e64209704fb8121d9bb3369e	1286908564	No	Fiber	10000	10000
a32679d41c5405a85be8067de313fc5d	1106684945	No	Fiber	10000	10000
0d115f57a7d5f531bcd9b6c2129d2aa9	1089034558	No	Fiber	10000	10000
b07c2a93663eb583ff3ec9a966c96c0b	1106685735	No	Fiber	10000	10000
3ceb6be48e3936500bd3a5020ab3c0db	1286905730	No	Fiber	10000	10000
8f2ddc7e918dadd0b6b51c3631c8afb5	1286905683	No	Fiber	10000	10000
9dc2f96d9cdaeca301d86aa4adcf31f7	1451747411	No	Fiber	10000	10000
6b421bb2ce9dc653a9fa161cc1aca02c	1106680539	No	Fiber	10000	10000
9cc81e67ca1ccd771edbca8388078535	1106685601	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
ee3912f54edd7c3a82bb029213383928	1106680957	No	Fiber	10000	10000
285de785bcf0e78bc133ff415ff7f976	1106686778	No	Fiber	10000	10000
e7c4ea786c0ca97c7b2fba40f17c1c2a	1106684402	No	Fiber	10000	10000
fbbeb3ebd9283db0f03687747a05155f	1106682989	No	Fiber	10000	10000
9eb17d20f7d8efb524601b2ae3bd4790	1106686980	No	Fiber	10000	10000
852bd85d921f14fbc893d1208a6cd888	1106685742	No	Fiber	10000	10000
7b42c1539885f4f6b04a7319847739ad	1106687078	No	Fiber	10000	10000
911321df467aa8a891aac3b2981fc6ff	1106686127	No	Fiber	10000	10000
f7616f2f2f36170f7f586469f7165977	1111406337	No	Fiber	10000	10000
876e759cea4107f28d252d8a7c50618d	1286907103	No	Fiber	10000	10000
66c3c1e4df5c346db2e67dc0a3261676	1286912264	No	Fiber	10000	10000
79729c3b3899c0a04f1c2d57762b3349	1112239118	No	Fiber	10000	10000
192e026ed81b7b171266f966c24caece	1112239119	No	Fiber	10000	10000
0882acb604a660a62ac35d9e96d27f4d	1106680012	No	Fiber	10000	10000
74d580afb58b88dc80301fdd55c3cd	1106685106	No	Fiber	10000	10000
58682f624932a431feddbf2551c378b5	1106679335	No	Fiber	10000	10000
19e35d389bbb4a5d565ff9083dda3224	1089059189	No	Fiber	10000	10000
874f4f53edfea4a9d2f69fe0a379ad46	1106683478	No	Fiber	10000	10000
2629089dbc5474df5d765876117f9c74	1286904774	No	Fiber	10000	10000
aa04cd6778d1a74af08953312de9d6d1	1111413095	No	Fiber	10000	10000
ac7d8f9f7f436c60f606f3f41d05d7b8	1106682017	No	Fiber	10000	10000
e3d597573791f8cfc94bcf34846fcc97	1384981292	No	Fiber	10000	10000
8c0a9434206913a376bc2e2a734c0117	1106682007	No	Fiber	10000	10000
c59cec96b2bd226fb124dc4caef5ff76	1106682298	No	Fiber	10000	10000
69ab8eeb30835e0d23a5136413468b84	1112239895	No	Fiber	10000	10000
a8e487b7516f5a6a1a2f79d310491fd4	1111414631	No	Fiber	10000	10000
170f6625b8cb67d392a311995d8c0df0	1089034390	No	Fiber	10000	10000
6adf056603aa07bb0265e115b489d747	1106686232	No	Fiber	10000	10000
7498b271bb0897d19ad6799744368a85	1089041407	No	Fiber	10000	10000
3cdfa83e67ce6a95dfcf5176e5dade43	1111411667	No	Fiber	10000	10000
aded7cbf87345e27e2f7079faacafa7b	1106682039	No	Fiber	10000	10000
423d4ffe32cc18197cb5984b4596272e	1106681174	No	Fiber	10000	10000
3be887e20d0da4e4231e753d52cb4920	1111413086	No	Fiber	10000	10000
08725d7d94e513352345e1ed63af704e	1286908714	No	Fiber	10000	10000
b9ae44975314c8edadcbdbc9938ceae0	1089041418	No	Fiber	10000	10000
6340a46a1080bd3fa5dfc23b2992ce9d	1089060010	No	Fiber	10000	10000
32a643655e3055fb93231581ed59e5aa	1111411489	No	Fiber	10000	10000
deb9be5799ce2f95b382e31ae114f963	1111413196	No	Fiber	10000	10000
037fa9794337087236eaf68668908022	1106679381	No	Fiber	10000	10000
e2d78e29e89e20b34990991f9d7f0762	1286914603	No	Fiber	10000	10000
8042ab2088e41afe7d1a8df393633950	1112264032	No	Fiber	10000	10000
b00f0fb76ece792b154e22b12272be1f	1286910834	No	Fiber	10000	10000
d538b1f4f7563b8e3e8f381872a636ea	1106684924	No	Fiber	10000	10000
2b2354512d2ee317b22ff5c3a922ef9b	1106681635	No	Fiber	10000	10000
299f1cd5a67eff1b21ae777d0f4429de	1089059488	No	Fiber	10000	10000
ee42ba6047fdd5ad7a504360e4286a56	1089055483	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
5fd4240e809b4663e336c97dbdc1faa9	1106686374	No	Fiber	10000	10000
4ea88d749366028f72b8aaf29a57b228	1286911840	No	Fiber	10000	10000
02267fa0a0525a8ad04cbddf849985fc	1111412606	No	Fiber	10000	10000
664adce1937a0eccef359d1cf0046dc6	1111404535	No	Fiber	10000	10000
47ed4f12a6266d2463b3720708071e8e	1106684752	No	Fiber	10000	10000
1bc7d132c433ea2464d3db94cb116f3d	1106684130	No	Fiber	10000	10000
a0c41cee8d1e64fa4774c2bef24d4495	1106679661	No	Fiber	10000	10000
33c18b3e24b5c44a46f5ba441014364e	1089040434	No	Fiber	10000	10000
6aae4273774ff2c153db8bb4b5b43f1f	1106685186	No	Fiber	10000	10000
4db5840b2ea3a4c9cc18e9b95a12c873	1089059348	No	Fiber	10000	10000
8481ce007e7530ad95835cdd5a1565aa	1106681486	No	Fiber	10000	10000
82b8648ca138374e5d6cd553b00e2988	1106682777	No	Fiber	10000	10000
8a06c842e9fb99b335a5032e890117fa	1089034402	No	Fiber	10000	10000
5bf5d2f4a3f8f4491072d08726867325	1106683843	No	Fiber	10000	10000
8f77778e033681ee0d7c9e95d557cd30	1106679963	No	Fiber	10000	10000
113d7858d6f495d98b795492aff2c190	1089043170	No	Fiber	10000	10000
fe51b214f6f2b6b3eb1b243d65a3eb89		Yes	Fiber	10000	10000
bb2eb02ca61a07bdad0a48af687eb665	1106682505	No	Fiber	10000	10000
0d53029278cab6e1278fea641af8dfda	1106679853	No	Fiber	10000	10000
2e6c6a2ebb653d9d587a764b9cb7a6e3	1106683650	No	Fiber	10000	10000
e1865388e8476aaab665541ed36265d6	1111410389	No	Fiber	10000	10000
88911fbf40f06bcaeda7e5710892710a	1089033529	No	Fiber	10000	10000
3f13c980d7a1b779d66651cb618df2a6	1413421540	No	Fiber	10000	10000
317d73c75317b3b969e195f27c0d4f2f	1106680879	No	Fiber	10000	10000
4173d0533c69c02b2521080d6d2c66c8	1384899523	No	Fiber	10000	10000
b7907be1cb7e9371fd4405b0be0d5a30	1286913856	No	Fiber	10000	10000
36509902b8f32e5e7b310af355c2b0e0	1106686667	No	Fiber	10000	10000
26f69c11a19df23fc7a8b7b42f1cbc30	1111409911	No	Fiber	10000	10000
7784b31a8df52aa7cdeabde9a24a5bc4	1106684087	No	Fiber	10000	10000
4b86ba13a62c6e0c46fb5be2560a27a0	1106685162	No	Fiber	10000	10000
5c7286c071eb3fe8684508762366e529	1106684659	No	Fiber	10000	10000
73c847b8df4d0eba1faabe4e2311736c	1089040416	No	Fiber	10000	10000
a17a5a4c867cf227940b8f4971a8c1af	1106684745	No	Fiber	10000	10000
c0540e796f72a82c947b60cf26eecb82	1106681100	No	Fiber	10000	10000
42851014298ff02ecb538f66e2942d5a	1111412010	No	Fiber	10000	10000
b2a5fd4d0e44d5c8bc0bf7cc83cbfa14	1106681368	No	Fiber	10000	10000
99f5f1c76d49a690927584cb6f00c601	1106687047	No	Fiber	10000	10000
f2c34a73d4fcb88d65be2413725d539	1106679637	No	Fiber	10000	10000
84882c82addc89369c3db8e1bfce8ef1	1089059187	No	Fiber	10000	10000
50423da4799fb44814d8cb5c43363662	1106685471	No	Fiber	10000	10000
8115cb33f535f830ce294caa6770b99f	1111427337	No	Fiber	10000	10000
a6051702add6e78f6bbf462153ee363c	1106683555	No	Fiber	10000	10000
53729711ae1c7a362826416c14268a6e	1106679391	No	Fiber	10000	10000
5f6f367e216c4633398c7031e4453759	1111420832	No	Fiber	10000	10000
71b4eb8cfec400e54b94623a24526c8b	1106683516	No	Fiber	10000	10000
e689c3bcab9e5185606a0bc7f6dd15eb	1286911017	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
ca4ba6a711752c0cf8016cc48151d50c	1106682190	No	Fiber	10000	10000
815c3e4bc584cf03800f610522b56da9	1111413368	No	Fiber	10000	10000
33b4ef597fc59a76dce89cef1bca14ec	1106684802	No	Fiber	10000	10000
2f7d6d7c0cc13d941edf73e61596993d	1111406484	No	Fiber	10000	10000
1950b2e28f9a62b2d7c262c72358a2dc	1111413109	No	Fiber	10000	10000
5e4fd445813c581cb81225442205a27e	1106682462	No	Fiber	10000	10000
d0dd524df708e06c1ac7f8b86e651dbe	1089055478	No	Fiber	10000	10000
f192555310f7c93a8e718e7c1f1622d4	1089032850	No	Fiber	10000	10000
7af68c690bdb6d67295e5203cec0d60b	1413421439	No	Fiber	10000	10000
ec3030671b50b8623560bbd0eced9367	1106682857	No	Fiber	10000	10000
8436b17c23a62bb6b43bc5b1dc48c034	1106684512	No	Fiber	10000	10000
fd52d0a3fb348afba385c320f51ed2f4	1089042261	No	Fiber	10000	10000
f81f549c3fd92996b3b99291bca8ad0c	1106681448	No	Fiber	10000	10000
a7c9b100625494f013131a062f8ce527	1384901310	No	Fiber	10000	10000
b808c4db1fbeat556b7ab5460ebdd143	1089043842	No	Fiber	10000	10000
947c63c559eac23e62b58a511c8c47f7	1106686125	No	Fiber	10000	10000
95d78afd5e8be0f8f7a06a1ce82e0cde	1106690130	No	Fiber	10000	10000
a707aa6730a013ddf926ab2ccc80c637	1106685801	No	Fiber	10000	10000
d41b8c8db91108e0aed7ec1463536db1	1106684104	No	Fiber	10000	10000
ae0bf58f9f0b0658e78e21f1ffa20134	1106682974	No	Fiber	10000	10000
a75724a7d6e5205790b4e213bdd39a16	1111413442	No	Fiber	10000	10000
665dc69c6c94833ca86fd6fd61169c7d	1089040419	No	Fiber	10000	10000
6cdd2812ccbb8eafd7963e001e16b971	1089042466	No	Fiber	10000	10000
4d0156156dc23996a88040aeebedf356	1106686339	No	Fiber	10000	10000
ac0baca63e922dee999c5541af5316ba	1089059193	No	Fiber	10000	10000
0fca16292ff18a38d7b601761755681a	1112258977	No	Fiber	10000	10000
634f1706c8d4920457d4eae456567671	1111406185	No	Fiber	10000	10000
1552f95970ed94649f512891e4fb68e6	1286905921	No	Fiber	10000	10000
983707340c569cf09a72d95771ffb5c1	1106679895	No	Fiber	10000	10000
b5f281abffb5d3d5921702608be73f4a	1111408674	No	Fiber	10000	10000
03554fd57ef339a88f6a5d88f14cb6fd	1106686993	No	Fiber	10000	10000
8cd4c0d52f94938d853233eff69a3e43	1106687139	No	Fiber	10000	10000
30ac2de4b9351904381d47d00009111d	1106684576	No	Fiber	10000	10000
8e110ac8e5cacb289a6d51f733a62491	1286909929	No	Fiber	10000	10000
a3d23fcdd033528566cc4a24d65b3e60	1089055529	No	Fiber	10000	10000
6f905ccaa7e7529f4f343cf8b64d80ab	1111413868	No	Fiber	10000	10000
ba22fc683217f044d4549f1cd730cf9f	1106685772	No	Fiber	10000	10000
95a14ac9161150a1dec83d82a57952c	1106681125	No	Fiber	10000	10000
428b0c874af5594c233ce1413724ae50	1089059996	No	Fiber	10000	10000
8b808701637649481b1a5d39754a09f2	1106687007	No	Fiber	10000	10000
07a230c0782b8830a9a9ec799dabb016	1111411421	No	Fiber	10000	10000
583f030730114eb2ff993146dcef2a35	1089059994	No	Fiber	10000	10000
d06e904b9d0b601450ef125d925a2333	1106686600	No	Fiber	10000	10000
709e4bb05407606940518236424eca41	1106685132	No	Fiber	10000	10000
6d27c00334d6643bc79ba0f104c8d14d	1111406175	No	Fiber	10000	10000
430b38628c0663e71864cd99d1cceb14	1089059989	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
db95f68c8098751c4ca0ae89b657682e	1089043142	No	Fiber	10000	10000
0940ad6f18d7b56605011d62e9595fb0	1089059362	No	Fiber	10000	10000
c2f71adccae121ad4596578fad48019b	1089059713	No	Fiber	10000	10000
7feb7280051e23d9dfd8543c5ae16fc	1106683191	No	Fiber	10000	10000
53c54cd594cc0a0d2d85f6873b781ea6	1089034808	No	Fiber	10000	10000
07b85e0c8ae395d1c6764f8ec1c90d81	1111409922	No	Fiber	10000	10000
c3113452e9999ad82303c7753a54151b	1111406345	No	Fiber	10000	10000
52ac998ad8288c57084fb6b420bee20c	1111405920	No	Fiber	10000	10000
7f6f4e7e4495e7418c35b5bbfe2fae01	1286913363	No	Fiber	10000	10000
d12db6e01aead3e14e77d62bfd8cab5c	1106685362	No	Fiber	10000	10000
b3add54450437880ee6cc5ffee8348dd	1106681871	No	Fiber	10000	10000
ced9ab3365abba14729d0e53f464572d	1111412224	No	Fiber	10000	10000
650919198ba0d4f0d249b03e1cf6d608	1106680905	No	Fiber	10000	10000
dc546fda39c4d138e90fe4844a6f5831	1106685682	No	Fiber	10000	10000
1b4dedd422216e34390dd8561b7720b4	1106685849	No	Fiber	10000	10000
b092b3dc7117409972502302bf60a77f	1286913416	No	Fiber	10000	10000
4feee8710b982c0d704573fda69e9709	1106679722	No	Fiber	10000	10000
d1d347eac3064c54c0ba1ae57b631a8b	1106680112	No	Fiber	10000	10000
ebdea73cc95135aee0ad9cfafdc4fbb8	1089040427	No	Fiber	10000	10000
108e2a1589e26b9437fdd31da82c95ba	1111406338	No	Fiber	10000	10000
aa888a29ec22dbf453a07d3d3fe2ef96	1106681278	No	Fiber	10000	10000
3611f45e5b8aff3584e4f224ef28bf39	1111414813	No	Fiber	10000	10000
ebc7f9d737c187bd1aabd99a921ed760	1111412255	No	Fiber	10000	10000
9307326fe893c6b0daa92aa0a80c5952	1286911877	No	Fiber	10000	10000
511c6f58eb3d8c34d39753d5fe7242db	1111412760	No	Fiber	10000	10000
565914019bce584dc87037888a175e6d	1106685196	No	Fiber	10000	10000
453c586a9cb25721b31f8cb5304bcff7	1111413096	No	Fiber	10000	10000
c89c80c47b6534ed699d99ba09df6b4f	1286911959	No	Fiber	10000	10000
57468ab7a3b55bc98db834e669345837	1089034246	No	Fiber	10000	10000
98579027db924d5700d457547178a39b	1106680950	No	Fiber	10000	10000
ab2ea0051ae61348c315e7a265e59e38	1286906405	No	Fiber	10000	10000
e3982054ca1fa089b87e2b7c3c9defde	1106686840	No	Fiber	10000	10000
ddf5660f53ac99e95ceaffb40e88bcd	1286914670	No	Fiber	10000	10000
f43001e40516d3af809f00c6571ae00d	1286906421	No	Fiber	10000	10000
910f75f8b2aef122334d77e4a87ca855	1286908339	No	Fiber	10000	10000
f785aec5b169c8b5efaa9765f42a58b8	1286908571	No	Fiber	10000	10000
8d3dc8904bb40947d009f2b1aced295a	1106682187	No	Fiber	10000	10000
b963ccc46eb44df11e82db9499bed61b	1111411418	No	Fiber	10000	10000
f90e5bac629a71bc52d9ee072eda18b0	1089041402	No	Fiber	10000	10000
44f3d39b7d648a14471573da95c57d4f	1106681860	No	Fiber	10000	10000
2ef10406351135c735585bad4924f385	1112261318	No	Fiber	10000	10000
aff0c73cdf32184018363174e3970801	1112239108	No	Fiber	10000	10000
503bb7806577d1dae3882a2b53c563b2	1286911178	No	Fiber	10000	10000
17ae931530dc7a97a540920899c36c08	1089059283	No	Fiber	10000	10000
ac5ef0a9f7eee0c972b280a726971ffc	1106679720	No	Fiber	10000	10000
508c0ac4c1eaac8e2f8a0a8c5317db18	1111414006	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
6628318ecce8c4dd5b3464dac77ad20c	1106686886	No	Fiber	10000	10000
13bf3d82cdba271a856e3c9a6ace1430	1106681082	No	Fiber	10000	10000
f3c4882c00fb0fbb2dba7f0aee30d507	1106680897	No	Fiber	10000	10000
9dab1dae30f6e840634d75769f3d99c5	1111405176	No	Fiber	10000	10000
711235c0404d50a7f4b8cd646e066809	1106682566	No	Fiber	10000	10000
5bcc0328ecdb2e8be7d4a7710582701f	1286904423	No	Fiber	10000	10000
48a04499beb89d01d0b5391609bb805e	1286908367	No	Fiber	10000	10000
e007d3ac335991c2699c7dbdd2d81ee7	1106682574	No	Fiber	10000	10000
93d9623ea365d58c427f80fcd1a70f09	1106684520	No	Fiber	10000	10000
e0943f11a505bbacdf790c97bb286676	1286910096	No	Fiber	10000	10000
b22a589e86d29047c47ee34c5df96f7d	1106685813	No	Fiber	10000	10000
6f63f94774af0096a2e094bc784e3792	1106686009	No	Fiber	10000	10000
60fbb839356e39e246ec0f61988cbc45	1089031953	No	Fiber	10000	10000
20e784db2a1940dcf77a6035bf28b972	1112236596	No	Fiber	10000	10000
154402ffd74b1e99c26d5f0e5439132d	1106685885	No	Fiber	10000	10000
2bd8ae38525bbb5e98a0cf2ced9204bc	1111413280	No	Fiber	10000	10000
570d6068bb2fde982a06604ed0160be5	1106687124	No	Fiber	10000	10000
01e4eb559c3b8fa31c2b69bd8d4c87c1	1089055485	No	Fiber	10000	10000
c2522e170172e6d7eee9abd96a3ed84e	1111405199	No	Fiber	10000	10000
0b4653c743d4c2b077e9b3d9a3caa2f4	1112257355	No	Fiber	10000	10000
ce7b2a8bb1d6c694f5c14902848fc4b1	1286908576	No	Fiber	10000	10000
e0f3fc63a9e2764e272718192909d232	1111410763	No	Fiber	10000	10000
c30af9ba1374be585505b7d60886009e	1111413530	No	Fiber	10000	10000
9101e04b2bd378c6c7ff0909d3a2ef69	1286908909	No	Fiber	10000	10000
7bd10c9d2bd3fccf9cfd648e5fc6581e	1106684676	No	Fiber	10000	10000
2147c1453838ab76f17e5bb05caf143d	1106684309	No	Fiber	10000	10000
b2415da87f1a077d04306e1ecd53290e	1089039762	No	Fiber	10000	10000
23c07be806e2186345b6301b7feb4c40	1089040152	No	Fiber	10000	10000
ea09edb3619154c611dd16919329187c	1286912684	No	Fiber	10000	10000
7b2792de8995e7e98828dd15192ee240	1111413908	No	Fiber	10000	10000
feca5090bc0ee5d432125c83bfa91f05	1111412509	No	Fiber	10000	10000
bbec0797d65ae1f8ae73878912677abd	1089059341	No	Fiber	10000	10000
27e2cabb57ea82a621e1bbebf64095e0	1089060071	No	Fiber	10000	10000
40bb80fb84e78108abb628ce983b17f0	1111409915	No	Fiber	10000	10000
f3bfa1623897e5192f81083c9e8daedb	1112239103	No	Fiber	10000	10000
c8957988c5404d3863799d7046ff879a	1106685045	No	Fiber	10000	10000
765cf2a9d38b1c3c9a260728e1fe1d59	1111412077	No	Fiber	10000	10000
1284e391076f936d3cab7471c8dd4d87	1106682333	No	Fiber	10000	10000
cc2ccbc7cdd864ffee8f65e69a863199	1089040682	No	Fiber	10000	10000
ac6e7297ea7f723fa67cb6fe7cbae23e	1111405593	No	Fiber	10000	10000
83872f716c5c916be60e09d8a7845b45	1106686536	No	Fiber	10000	10000
629236ad38fc3a4b677f932fc61a7349	1286912899	No	Fiber	10000	10000
1fa1fa95bd5ff107611f3db02efe7981	1106679984	No	Fiber	10000	10000
ef08bb2e599288a3f8f9bf647a0f5171	1106683612	No	Fiber	10000	10000
5019c9f2cad2888527ce82124553802	1106685897	No	Fiber	10000	10000
00ef0b278a081ec468e6a781f65e90c6	1106680329	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
1fc8ba0ec62f8d5030d33814992d972d	1286907659	No	Fiber	10000	10000
9c145aedf4e7e9f8b3e1875777d0e329	1111411486	No	Fiber	10000	10000
a2990f93e0ee756c4aebf1ec1036983e	1106683266	No	Fiber	10000	10000
0f884143d7edc65240018737eb9f03fa	1089034322	No	Fiber	10000	10000
e35bbf8e04b8a39fb7087c89e5550def	1089059428	No	Fiber	10000	10000
17fc62c5318b542a396fee2630fda9eb	1106683268	No	Fiber	10000	10000
f258fd843ced25dd7da2e93b448fc60	1089031248	No	Fiber	10000	10000
cf75a800c123e33403b3c09a52f4c566	1106681752	No	Fiber	10000	10000
caae2dfb76e66d6a821064e6f25d4220	1111413025	No	Fiber	10000	10000
a050bf1c085f9995657dce2294cbae6a	1106681514	No	Fiber	10000	10000
405ebb64ced66bbda27a03aad1954e2c	1111405152	No	Fiber	10000	10000
e43bd3fb78c46b45f0543a04b0a3b4d9	1106685815	No	Fiber	10000	10000
9da2a394e8942e30c902c3c7a265f94e	1111413333	No	Fiber	10000	10000
0eec9cbb3cf07ae9a428175271caf157	1089031615	No	Fiber	10000	10000
af28d2feb3c7fbabf5173349bdc9a1e1	1106683274	No	Fiber	10000	10000
7372e78f95afe8ce04d64b3e9bb00a46	1106686785	No	Fiber	10000	10000
875708da05d485078c185d8ad19e1135	1111410814	No	Fiber	10000	10000
700de8a567a5ea27b7df2974b7e40265	1111405177	No	Fiber	10000	10000
922d855d6a78ac8c6540a6da272ca224	1286904696	No	Fiber	10000	10000
08d095f0b3cabe533ed24e196482096d	1106680161	No	Fiber	10000	10000
ac41598708cd60a54b5b7c163b947c74	1106682325	No	Fiber	10000	10000
731b8c9f61edc57c7af6a6546f2eaa94	1106680495	No	Fiber	10000	10000
ef92a1b496aeae0a98be01e08d0f9bca	1111414794	No	Fiber	10000	10000
48b07308b4097eda8c0d6a3942b08e71	1106681901	No	Fiber	10000	10000
ce5737e4f36a5a2fe2b48d4fe9425bce	1106682278	No	Fiber	10000	10000
2a7aadd856d89c936f0eb9815211ecc3	1106686030	No	Fiber	10000	10000
d206e6c7f1d9d866b9bfa53ec1968396	1111411702	No	Fiber	10000	10000
ae570e3a0bc7b31769e195b0871dc107	1286914285	No	Fiber	10000	10000
3c28b1459d33ebfa65754ade01d5f2eb	1106681353	No	Fiber	10000	10000
408e6507f94ae6d6e70a2e78c3c29c7b	1106681058	No	Fiber	10000	10000
564bdd5c60b8e4aefaf434ea4bf9a00a	1106679790	No	Fiber	10000	10000
9f823110ada37e95c61324677c8b8ccc	1106682495	No	Fiber	10000	10000
a539750a4a4187c9a8207adcbd615040	1286906487	No	Fiber	10000	10000
3e703a032eeeb0379f55f5b237243271	1106685685	No	Fiber	10000	10000
b774fd66c084a5b386ad8e8b984cf42e	1111406176	No	Fiber	10000	10000
565ade7d8891239fffeccc650630c76d	1089056300	No	Fiber	10000	10000
62b27189d7285b358d6e86722f9be900	1286907396	No	Fiber	10000	10000
60a6d8e2f4685d1a77be56653a723a77	1106686585	No	Fiber	10000	10000
8fb53836959b66ace66e2aed0fac32cc	1106683787	No	Fiber	10000	10000
a419aad3d836892fd31e3ed849967286	1089042273	No	Fiber	10000	10000
27bcdbc2fd4f3e2f1c725734560dbcc7	1089041420	No	Fiber	10000	10000
56e02e572c0acb1d2a798f96fd098c82	1106685543	No	Fiber	10000	10000
cdfb4e42b884ddffc1259734b5584fd1	1106683222	No	Fiber	10000	10000
0bd0ac4f68130a45a252986f4a2901fb	1111412546	No	Fiber	10000	10000
f3f542dddfbc03ff0f792d9cd69b26ce	1384898261	No	Fiber	10000	10000
0039978da51c3081fa33ceb0a1d55acd	1112239123	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
46fad0a956d9f1dd47fc74d4720a438d	1106684862	No	Fiber	10000	10000
06ceb5ff2bd38cace0722cf4aa809d8f	1089056576	No	Fiber	10000	10000
0200f3ad444ce866c56d43684d267952	1286911345	No	Fiber	10000	10000
9d6c5b8e936605b3e483316f6ad2cfa9	1111412049	No	Fiber	10000	10000
c6448e7471a7f032dde6af0e963ae080	1111405562	No	Fiber	10000	10000
9460e102a15bc3189c81771336166c65	1106683022	No	Fiber	10000	10000
a5d32cc35468e662d55f137851b8d4f4	1106684442	No	Fiber	10000	10000
0d5ee343d3e64b34a1962f051ae16c57	1286913475	No	Fiber	10000	10000
79417ce7dfb2d728e5da46c29422658e	1111410816	No	Fiber	10000	10000
e569098ca63ab5e90700d3a8f50693f4	1106682358	No	Fiber	10000	10000
43f510cb59aa71b9cb8fa575e0c23db8	1106681337	No	Fiber	10000	10000
c2f82c96aac76229b6e729745eadb90	1106684274	No	Fiber	10000	10000
a5727b4bbd63dbceee2d736dbdb8bc038	1089042455	No	Fiber	10000	10000
c26cc3c9e006b16c4ea75b208d04e2ea	1286914754	No	Fiber	10000	10000
2b1317f4013ae274427a081f38271665	1089039428	No	Fiber	10000	10000
52d9cb3bbeae37a4ffb00a176faef480	1106681508	No	Fiber	10000	10000
fcdd3fb089bf902c337d5d13fe1581af	1106685588	No	Fiber	10000	10000
eb1ff7c28ff5a51eec6ad8968e5924ea	1089040456	No	Fiber	10000	10000
f33cf4666ca6eb460f0f52b0601721fe	1384901446	No	Fiber	10000	10000
26cf743782c2d054f4eebcc2b2c1f062	1112239109	No	Fiber	10000	10000
b5654c3a06972df3d2cde73c920619c9	1106681679	No	Fiber	10000	10000
7424408591d7db22959bf72b8a31dd55	1106682682	No	Fiber	10000	10000
b6d749f78055abab8bfc94cbc368687e	1089039720	No	Fiber	10000	10000
7bd56133a113cc8b345f67326591c940	1286907911	No	Fiber	10000	10000
54cec53b3422bf6dcada5ca0a90251a0	1286910933	No	Fiber	10000	10000
1a86206c88bf166ca57f4fb433cdebe35	1111412050	No	Fiber	10000	10000
fa5b90ef7751ab3f5f4cbd3106165cc3	1089040454	No	Fiber	10000	10000
230983be65df2975b900a5e5fa1eb84d	1089034241	No	Fiber	10000	10000
37cfb37b2a7a835036be7c2cfd6143ee	1106682362	No	Fiber	10000	10000
1db1005241371ce3642bdafce1c95912	1089034389	No	Fiber	10000	10000
a8ea23459b30052feb05065689feaf5b	1112263143	No	Fiber	10000	10000
266bb00883e8e696c62439a78d20fafa	1286906614	No	Fiber	10000	10000
779c5ee19f105be79f1e561c152ef6d5	1106681671	No	Fiber	10000	10000
67a840f369bc3dc31114f5e5d4342b89	1106684766	No	Fiber	10000	10000
f3c5696bc12c8642037b0a25e90d69de	1106680288	No	Fiber	10000	10000
9a4f857201d9026ae07cd88954a6f40e	1089039710	No	Fiber	10000	10000
18f918c78154dac51f7c4aec793fd746	1286911635	No	Fiber	10000	10000
893795f53321fe71cd5370e28f991c2c	1089034309	No	Fiber	10000	10000
1d4a89e3fd731a534471a00d40a17e10	1089034372	No	Fiber	10000	10000
14a7a4ef3088124667119082ec70cbfe	1089060006	No	Fiber	10000	10000
d9a235db3a14af2f81c3e3eb831068e2	1106686443	No	Fiber	10000	10000
d8bcc80b00573eb47f4fb1d47479c9ae	1089059355	No	Fiber	10000	10000
bbe1881d753690635783037847362bd2	1286912606	No	Fiber	10000	10000
bdc756d1ba64543e8762999c8b036b8c	1089056302	No	Fiber	10000	10000
df8e0996fda489ab67cc159c59b7f03b	1112241831	No	Fiber	10000	10000
96695d5039ab65b0d37986104e13b4aa	1106685270	No	Fiber	10000	10000

ID	Location ID	Is CAI	Technology	Upload	Download
9bbee6f2213471da70f92b7523baf22d	1089034316	No	Fiber	10000	10000
4b1707c2f42da21f173509e08b5e9488	1106684314	No	Fiber	10000	10000
a3d78112e5371753c1c560c28c3fb2fc	1089059097	No	Fiber	10000	10000
24c033409e9f1de102ea57c8d5c4079f	1106680698	No	Fiber	10000	10000
db06c6f3caab4cd0213ba4820bf585f4	1106680745	No	Fiber	10000	10000
60be93bda49d9b188ab9c6b19000793b	1111412014	No	Fiber	10000	10000
876970ca3379415a824c35959f240096	1106684093	No	Fiber	10000	10000
798adfb4fb038b361942da308ba0609	1384900928	No	Fiber	10000	10000
763613fb0a6aa78a10160606b963b07c	1089059356	No	Fiber	10000	10000
337c476ecbe8307c855c693d37171423	1112258987	No	Fiber	10000	10000
25895d438fe9b307857992da56a960c2	1106686178	No	Fiber	10000	10000
bc81180a0d3b03bb579895ae4b012b85	1286904665	No	Fiber	10000	10000
5a5b763dd3b62bef3ab2d6d17f2f6e2c	1111424521	No	Fiber	10000	10000
d4574b7a4199ffaff88b8b38ab9d2bdf	1089034375	No	Fiber	10000	10000
f69e3b48c3322da5dc9709ccc4339a1f	1106682082	No	Fiber	10000	10000
459e0e3f7522832ed2006faf51cb42c4	1106679780	No	Fiber	10000	10000
981fe472ad71c8d13b863e57a9776704	1286905153	No	Fiber	10000	10000
8b41baf505ed7c966b0a23dfce9c9b21	1111413270	No	Fiber	10000	10000
de6f7f368cf4b7096f938335be586b8a	1111405207	No	Fiber	10000	10000
d02fd844175a2dff72c6e3261d617953	1112239095	No	Fiber	10000	10000
03e6c4ae69c64be9da25a07f617b871b	1106686590	No	Fiber	10000	10000
adc1f5dd776212a50b3f78894ad59983	1111417375	No	Fiber	10000	10000
e72fbc4b2781b1e9c91d9ffa77524246	1106681182	No	Fiber	10000	10000
8f6ce7e4cc90543c00cc6d1433a1b30c	1106684421	No	Fiber	10000	10000
51c5021a92a56b095917eac9a0f63ebe	1089059195	No	Fiber	10000	10000
c7596f9c4f8e85ff8183e7ed1e61ef6f	1089034811	No	Fiber	10000	10000
2755cb280430c6ba6c1c0f9e4011d725	1089039696	No	Fiber	10000	10000
f452d8cde7c489161a8a01fbe224aceb	1089032787	No	Fiber	10000	10000
c96a5bb99a27eb5eeaa1f36ee05b98e1	1385049878	No	Fiber	10000	10000
afdcacc676ca3090a912066d55ce6de1	1112239076	No	Fiber	10000	10000
8b147ec7f38ffe2e21b5b78cec63626e	1089040672	No	Fiber	10000	10000
211a4bee28d98b22313580fcca93da09	1286911459	No	Fiber	10000	10000
d2c41be64898ea9cf6fc49bd016b1217	1111404575	No	Fiber	10000	10000
9a2ebe716eb20c90935c1db3abca8155	1106686795	No	Fiber	10000	10000
99ad0b15f38264abc8d9954f4a9d346	1111411470	No	Fiber	10000	10000
ed5e011d182e3b9b6231c51c3f7ad89e	1089056299	No	Fiber	10000	10000
13d777f692910be21fbd392ce281356a	1106683029	No	Fiber	10000	10000
5a29cad3a51d06dc39fd4169d22e29f5	1384581916	No	Fiber	10000	10000
23402f61aff26fcb640392e50e9ffc43	1089031942	No	Fiber	10000	10000
091b4fcfc18d7339250fae54037ede62	1286918087	No	Fiber	10000	10000
a77b919e2981c041c3ebd31d2b8111ef	1106680357	No	Fiber	10000	10000
726d57bf5c2e844744b7aa1744d7b492	1111413180	No	Fiber	10000	10000
a314b951a207eebac696115ef5d58c48	1089059324	No	Fiber	10000	10000

Appendix C to Exhibit 1 – Budget for Project Area NIN-001

Cost Item	Description	Category	Total Cost	Grant Funds Requested	Match Funds
Y2 counties Fayette & Rush Contingency Funds	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Contingency Funds	\$0.00	\$0.00	\$0.00
Y1 counties Henry & Shelby, Professional Services	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Professional Services	\$29,849.99	\$22,387.99	\$7,462.00
Y1 counties Henry & Shelby, Construction Services	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Construction Services	\$2,763,386.17	\$2,072,539.63	\$690,846.54
Y1 counties Henry & Shelby, Outside Plant, Towers, and Poles	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Outside Plant, Towers, and Poles	\$2,032,550.92	\$1,524,413.19	\$508,137.73
Y1 counties Henry & Shelby, Network and Access Equipment	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Network and Access Equipment	\$264,845.40	\$198,634.05	\$66,211.35
Y4 counties Henry & Shelby Construction Services	Rush 1 ,Shelby 5 ,Shelby Year 4	Construction Services	\$2,738,202.23	\$2,053,651.67	\$684,550.56
Y4 counties Henry & Shelby Outside Plant, Towers, and Poles	Rush 1 ,Shelby 5 ,Shelby Year 4	Outside Plant, Towers, and Poles	\$2,032,550.92	\$1,524,413.19	\$508,137.73
Y1 counties Henry & Shelby, Operating Equipment	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Operating Equipment	\$0.00	\$0.00	\$0.00

Cost Item	Description	Category	Total Cost	Grant Funds Requested	Match Funds
Y1 counties Henry & Shelby, Customer Premise Equipment (CPE)	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Customer Premise Equipment (CPE)	\$502,320.80	\$376,740.60	\$125,580.20
Y1 counties Henry & Shelby, Contingency Funds	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Contingency Funds	\$0.00	\$0.00	\$0.00
Y1 counties Henry & Shelby, Other Allowable Costs	Hancock 1 ,Henry 1 ,Henry 10 ,Henry 11 ,Henry 12 ,Henry 2 ,Henry 3 ,Henry 4 ,Henry 5 ,Henry 6 ,Henry 7 ,Henry 8 ,Henry 9 ,Shelby 1 ,Shelby 2 ,Shelby 3 ,Shelby 4	Other Allowable Costs	\$0.00	\$0.00	\$0.00
Y2 counties Fayette & Rush Professional Services	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Professional Services	\$27,200.00	\$20,400.00	\$6,800.00
Y2 counties Fayette & Rush Construction Services	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Construction Services	\$2,758,386.17	\$2,068,789.63	\$689,596.54
Y2 counties Fayette & Rush Outside Plant, Towers, and Poles	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Outside Plant, Towers, and Poles	\$2,032,550.92	\$1,524,413.19	\$508,137.73
Y2 counties Fayette & Rush Network and Access Equipment	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Network and Access Equipment	\$264,864.24	\$198,648.18	\$66,216.06
Y2 counties Fayette & Rush Operating Equipment	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Operating Equipment	\$0.00	\$0.00	\$0.00

Cost Item	Description	Category	Total Cost	Grant Funds Requested	Match Funds
Y2 counties Fayette & Rush Customer Premise Equipment (CPE)	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Customer Premise Equipment (CPE)	\$502,352.75	\$376,764.56	\$125,588.19
Y2 counties Fayette & Rush Other Allowable Costs	Fayette 1 ,Rush 2 ,Rush 3 ,Rush 8	Other Allowable Costs	\$0.00	\$0.00	\$0.00
Y4 counties Henry & Shelby Professional Services	Rush 1 ,Shelby 5 ,Shelby Year 4	Professional Services	\$27,200.00	\$20,400.00	\$6,800.00
Y3 counties Gwynnville & Rush Professional Services	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Professional Services	\$27,200.00	\$20,400.00	\$6,800.00
Y3 counties Gwynnville & Rush Other Allowable Costs	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Other Allowable Costs	\$0.00	\$0.00	\$0.00
Y3 counties Gwynnville & Rush Operating Equipment	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Operating Equipment	\$0.00	\$0.00	\$0.00
Y3 counties Gwynnville & Rush Customer Premise Equipment (CPE)	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Customer Premise Equipment (CPE)	\$502,320.80	\$376,740.60	\$125,580.20
Y4 counties Henry & Shelby Network and Access Equipment	Rush 1 ,Shelby 5 ,Shelby Year 4	Network and Access Equipment	\$264,845.40	\$198,634.05	\$66,211.35
Y3 counties Gwynnville & Rush Contingency Funds	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Contingency Funds	\$0.00	\$0.00	\$0.00

Cost Item	Description	Category	Total Cost	Grant Funds Requested	Match Funds
Y4 counties Henry & Shelby Other Allowable Costs	Rush 1 ,Shelby 5 ,Shelby Year 4	Other Allowable Costs	\$0.00	\$0.00	\$0.00
Y3 counties Gwynnville & Rush Construction Services	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Construction Services	\$2,753,386.17	\$2,065,039.63	\$688,346.54
Y3 counties Gwynnville & Rush Outside Plant, Towers, and Poles	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Outside Plant, Towers, and Poles	\$2,032,550.92	\$1,524,413.19	\$508,137.73
Y3 counties Gwynnville & Rush Network and Access Equipment	Gwynnville 1 ,Rush 5 ,Rush 6a ,Rush 6b ,Rush 6c ,Rush 7 AN ,Rush 7 AS	Network and Access Equipment	\$264,845.40	\$198,634.05	\$66,211.35
Y4 counties Henry & Shelby Operating Equipment	Rush 1 ,Shelby 5 ,Shelby Year 4	Operating Equipment	\$0.00	\$0.00	\$0.00
Y4 counties Henry & Shelby Customer Premise Equipment (CPE)	Rush 1 ,Shelby 5 ,Shelby Year 4	Customer Premise Equipment (CPE)	\$502,320.80	\$376,740.60	\$125,580.20
Y4 counties Henry & Shelby Contingency Funds	Rush 1 ,Shelby 5 ,Shelby Year 4	Contingency Funds	\$0.00	\$0.00	\$0.00

Appendix D to Exhibit 1 –Reimbursement Schedule for Project Area NIN-001

Milestones Subgrantee must submit a reimbursement request no less than every 6 months	Disbursement (% of Subaward) ... Match Contribution (% of Total Match Pledged)	Cumulative Disbursement (% of Subaward) ... Match Contribution (% of Total Match Pledged)
0.5. Full execution of the Grant Agreement. AND Subgrantee provides documentation verifying expenditure of approximately 5% of total match pledged.	5% ... 5%	5% ... 5%
1. Complete EHP Reviews and demonstrate compliance with all applicable environmental laws: - Complete any and all review(s) required under the National Environmental Policy Act of 1969 (42U.S.C. 4321, et seq.) (NEPA), and issuance by NTIA and the IBO, as required, of a Categorical Exclusion (Cat Ex) determination, Record of Environmental Consideration (REC), Finding of No Significant Impact (FONSI), or Record of Decision (ROD) (hereinafter “decision documents”) that meets the requirements of NEPA; - Complete reviews required under Section 106 of the National Historic Preservation Act of 1966 (54 U.S.C. 300101, et seq.) (NHPA), including any consultations required by Federal law, to include consultations with the State Historic Preservation Office (SHPO), and Federally recognized Native American tribes; - Complete consultations with the U.S. Fish and Wildlife Service (USFWS) or the National Marine Fisheries Service (NMFS), as applicable, under Section 7 of the Endangered Species Act (16 U.S.C. 1531, et seq.), and/or consultations with the U.S. Army Corps of Engineers (USACE) under Section 404 of the Clean Water Act (33 U.S.C. 1251, et seq.), as applicable; and - Demonstrate compliance with all other applicable Federal, state, and local environmental laws and regulations; AND Subgrantee provides documentation verifying expenditure of approximately 5% additional contribution of total match pledged.	5% ... 5%	10% ... 10%

Milestones Subgrantee must submit a reimbursement request no less than every 6 months	Disbursement (% of Subaward) ... Match Contribution (% of Total Match Pledged)	Cumulative Disbursement (% of Subaward) ... Match Contribution (% of Total Match Pledged)
2. Complete a high-level design for the Project so that Subgrantee can apply for necessary permits. AND Subgrantee provides documentation verifying expenditure of approximately 15% additional contribution of total match pledged.	15% ... 15%	25% ... 25%
3. Serve 10% of Project Locations. AND Subgrantee provides documentation verifying expenditure of approximately 10% additional contribution of total match pledged.	10% ... 10%	35% ... 35%
4. Serve 35% of Project Locations. AND Subgrantee provides documentation verifying expenditure of approximately 15% additional contribution of total match pledged.	15% ... 15%	50% ... 50%
5. Serve 50% of Project Locations. AND Subgrantee provides documentation verifying expenditure of approximately 15% additional contribution of total match pledged.	15% ... 15%	65% ... 65%
6. Serve 65% of Project Locations. AND Subgrantee provides documentation verifying expenditure of approximately 10% additional contribution of total match pledged.	10% ... 10%	75% ... 75%
7. Serve 90% of Project Locations. AND Subgrantee provides documentation verifying expenditure of approximately 15% additional contribution of total match pledged.	15% ... 15%	90% ... 90%
8. Serve 100% of Project Locations. Complete Final Inspection and Project Closeout requirements. AND Subgrantee provides documentation verifying expenditure of remaining 10% of total match pledged.	10% ... 10%	100% ... 100%

**Appendix E to Exhibit 1 – Environmental and Historic Preservation (EHP)
Milestone Schedule for Project Area NIN-001**

NineStar Connect

Environmental and Historic Preservation BEAD Milestone Schedule

Task	Description	Comments	Assigned To	Progress	Start	End
EHP.01	EHP Initiation and Data Collection					
EHP.01.01	Collect all project information (scope of work, maps, ground disturbance details, photos, structure age, permits)	Utilize current GIS mapping plans and submissions for upload and review for potential items to address in more detail	NSC	0%	1/15/2026	2/6/2026
EHP.01.02	Conduct initial EHP screening and form completion needs Internal	Verify all documentation is collected for review and input can overlap with step 1 above	NSC	0%	1/25/2026	2/6/2026
EHP.01.03	Engage environmental consultants across all NEPA requirements, inclusive of ESA section 7, Section 106 tribal, and wetlands and other permits as deemed relevant for this project	dependencies on scheduling and meeting can take time	Various	0%	1/31/2026	2/7/2026
EHP.01.04	Finalize design inputs for NEPA specialists needs	Add any additional items missed for input	NSC	0%	2/9/2026	2/12/2026
EHP.01.05	NEPA create ESAPTT NEPA record for project	NEPA specialist	NEPA specialist	0%	2/14/2026	2/21/2026
EHP.02	Agency Review and Consultation					
EHP.02.01	Meet with individual permitting agencies	dependencies on scheduling and meeting can take time	Various	0%	2/21/2026	2/28/2026
EHP.02.02	Submit EHP screening package to funding agency EHP staff as required by permitting agency		NSC	0%	3/2/2026	3/9/2026
EHP.02.03	Agencies accept and review and determination of compliance needs (broken out for reference below if applicable and defined as a need)	dependencies on scheduling and meeting can take time	Agencies	0%	3/11/2026	3/25/2026
EHP.02.04	Consult with State Historic Preservation Office (SHPO) and/or Tribal Historic Preservation Office (THPO)	dependencies on scheduling and meeting can take time	Agencies	0%	3/11/2026	3/25/2026
EHP.02.05	Consult with natural resource agencies (e.g., US Fish & Wildlife Service, US Army Corps of Engineers) for threatened/endangered species or work in water bodies	dependencies on scheduling and meeting can take time	Agencies	0%	3/11/2026	3/25/2026

Task	Description	Comments	Assigned To	Progress	Start	End
EHP.02.06	NEPA specialist working concurrently with agencies above to follow up/mitigate actions as identified, inclusive of groups above.	dependent on NEPA	NEPA specialist	0%	3/11/2026	3/30/2026
EHP.03	Mitigation and Documentation (done concurrently with NEPA/Agencies above)					
EHP.03.01	Incorporate mitigation measures (if required by agencies) into project plan to avoid or minimize adverse effects	Internal allow time to address and scope	NSC	0%	4/2/2026	4/9/2026
EHP.03.02	Submit NEPA Documents to SBO/TBO NEPA Specialist		NSC	0%	4/12/2026	4/15/2026
EHP.03.03	NEPA specialist prepares, supervises, or reviews documents and drafts NEPA decision Memo in ESAPTT	can take time dependent on agencies	NEPA specialist	0%	4/18/2026	4/23/2026
EHP.04	Final Approvals and Implementation					
EHP.04.01	NTIA reviews documentation	can take time dependent on agencies	NTIA	0%	4/26/2026	5/6/2026
EHP.04.02	Allow time for Q&A; follow up	can take time dependent on agencies	Various	0%	5/9/2026	5/12/2026
EHP.04.03	Receive final NTIA approval and Issuance of final memo clearance/approval from the funding agency	can take time dependent on agencies	NTIA	0%	5/15/2026	5/20/2026
EHP.04.04	Permitting agencies review and completes the review process	can take time dependent on agencies	Permit Agencies	0%	5/23/2026	5/28/2026
EHP.04.05	Permits issued	can take time dependent on agencies	Permit Agencies	0%	5/31/2026	6/5/2026
EHP.04.06	Obtain any relevant other state, federal and local permits as needed	can take time dependent on agencies	State/Fed/Local	0%	6/8/2026	6/15/2026
EHP.04.07	Project implementation and release of funding		NTIA	0%	6/18/2026	6/25/2026
EHP.04.08	Start construction/ground-disturbing activities		NSC	0%	6/28/2026	6/30/2026

Appendix F to Exhibit 1 – Form of Attestation to Accompany Disbursement Request

I, [Officer Name], in my capacity as the [Title] of [Subgrantee], and not personally, hereby certify that the information regarding the matching funds provided by [Subgrantee] in connection with [Subgrantee]'s BEAD subaward provided herewith is complete and accurate, to the best of my knowledge.

[Officer Name]

[Title], [Subgrantee]

[Date]