

# Work Order Invoice



WIESE USA  
1435 WOODSON ROAD  
ST LOUIS MO 63132

OCT 23 2017

INVOICE NO. 60295158	
INVOICE DATE 10-20-17	BRANCH NO. 060
CUSTOMER NO. 2884405	WORK ORDER NO. 104785
PLEASE REMIT ALL PAYMENTS TO:	
REMIT TO: WIESE USA P.O. BOX 60106 ST. LOUIS, MISSOURI 63160	

SHIPPED/SERVICE ADDRESS:

RYOBI DIE CASTING  
525 INDUSTRIAL PARK DR  
SHELBYVILLE IN 46176

RYOBI DIE CASTING  
525 INDUSTRIAL PARK DR  
SHELBYVILLE IN 46176

17-11-59

CUSTOMER PO NO.	JOB NUMBER	TERMS	DUE DATE	ORDER DATE	CUSTOMER CONTACT
264297		NET 30 DAYS	11-19-17	10-11-17	TIM
SEG# 001	Model: DOCK	Equip ID: 2769N	Cust ID: 2769N		
Mfr: DOC	S/N: 2769N	Meter: 0			
REMOVE / REPLACE					
10/11/2017- RUN DROP TEST ON 5 FIRE DOOR.					
DOORS 28,30,A6- DROP TESTED - PASSED ALL - COMPLETE					
HAZMAT DOOR- UNABLE TO PASS DUE TO SEVERAL DAMAGED SLAT, MISSING WIND LOCKS, OPERATOR OVERHEATING- SUGGEST REPLACEMENT					
DOOR D26- UNABLE TO PASS DROP TEST DUE TO SEIZED HAMMER AND SPRING PLATE, ALSO ALL SASH CHAIN NOT CONNECTED, AND RUSTED OFF OF LINKS. SUGGEST EITHER REPLACEMENT OR ALL NEW CHAIN, S HOOKS, LINKS, AND TURNBUCKLE, ALONG WITH HAMMER AND SPRING WHEEL.					
HAZMAT DOOR - 12 X12 OHD W/ OHD 115, 1PH OPERATOR EXPLOSION PROOF.					
D26- 12 X 11 6" OHD W,115, 1PH OP NONE EXPLOSION PROOF.					
Total parts	0.00	Total labor	750.00	Total misc	0.00
				Total Labor	750.00
				Total for segment	750.00
				IN SALES TAX	0.00



**SAVE TIME AND MONEY WITH OUR FREE E-BILLING SERVICE**  
Choose from three easy ways to receive your invoices: email, fax or Invoice Gateway, our secure online site. With Invoice Gateway, you are notified by email when new invoices are posted. You can search, sort, view, print, download and pay your bills on this site. With email and fax delivery, your invoices are sent once per day and you get an exact replica of your paper bill.  
Contact WieseUSA at ARsupport@wieseusa.com and get setup today!

T. Dravet 10/23

**PAY THIS AMOUNT** 750.00



RYOBI DIE CASTING  
525 INDUSTRIAL PARK DR

SHELBYVILLE, IN 46176

Branch 060

Workorder 104785

Unit 2769N  
(cust) 2769N

10/11/2017 4:55:25 PM

Mfr DOC Model DOCK

Serial Number 2769N

Meter 0

Additional Meters

LEVELERS CHECKLIST

<input type="checkbox"/>	PM'S COMPLETE
<input type="checkbox"/>	SAFETY CHECKS PASSED
<input type="checkbox"/>	OPERATIONAL CHECKS PASSED
<input type="checkbox"/>	REPAIR NEEDED/FOUND
<input type="checkbox"/>	ELEC COMPONENTS FUNCTION OK
<input type="checkbox"/>	DAMAGE EXISTS
<input type="checkbox"/>	ENVIRONMENTAL ISSUES

DOORS CHECKLIST

<input type="checkbox"/>	PM'S COMPLETE
<input checked="" type="checkbox"/>	SAFETY CHECKS PASSED
<input checked="" type="checkbox"/>	OPERATIONAL CHECKS PASSED
<input checked="" type="checkbox"/>	REPAIR NEEDED/FOUND
<input type="checkbox"/>	ELEC COMPONENTS FUNCTION OK
<input type="checkbox"/>	DAMAGE EXISTS
<input type="checkbox"/>	ENVIRONMENTAL ISSUES

RESTRAINTS CHECKLIST

<input type="checkbox"/>	PM'S COMPLETE
<input type="checkbox"/>	SAFETY CHECKS PASSED
<input type="checkbox"/>	OPERATIONAL CHECKS PASSED
<input type="checkbox"/>	REPAIR NEEDED/FOUND
<input type="checkbox"/>	ELEC COMPONENTS FUNCTION OK
<input type="checkbox"/>	DAMAGE EXISTS

ACCESSORIES CHECKLIST

<input type="checkbox"/>	WHEEL CHOCKS
<input type="checkbox"/>	SEALS/SHELTERS
<input type="checkbox"/>	BUMPERS
<input type="checkbox"/>	LIGHTS
<input type="checkbox"/>	FALL PROTECTION

Seg 000 Gen

Seg 001 Gen

Qty	Parts Used	Work Description
		10/11/2017- RUN DROP TEST ON 5 FIRE DOOR.
		DOORS 28,30,A6- DROP TESTED - PASSED ALL - COMPLETE
		HAZMAT DOOR- UNABLE TO PASS DUE TO SEVERAL DAMAGED SLAT, MISSING WIND LOCKS, OPERATOR OVERHEATING- SUGGEST REPLACEMENT
		DOOR D26- UNABLE TO PASS DROP TEST DUE TO SEIZED HAMMER AND SPRING PLATE, ALSO ALL SASH CHAIN NOT CONNECTED, AND RUSTED OFF OF LINKS. SUGGEST EITHER REPLACEMENT OR ALL NEW CHAIN, S HOOKS, LINKS, AND TURNBUCKLE, ALONG WITH HAMMER AND SPRING WHEEL.
		HAZMAT DOOR - 12 X12 OHD W/ OHD 115, 1PH OPERATOR EXPLOSION PROOF.
		D26- 12 X 11 6" OHD W, 115, 1PH OP NONE EXPLOSION PROOF.


Seg 002 Gen

Seg 003 Gen


Seg 004 Gen

Co: RYOBI DIE CASTING Br: 060 WO: 104785 Date: 10/11/2017 4:55:25 PM  
Qty Parts Used Work Description

Seg 004 Gen	
Seg 005 Gen	
Seg 098 Gen TRAVEL CHARGE	
Seg 099 Gen	

<input checked="" type="checkbox"/> OK	<input checked="" type="checkbox"/> Active	Authorized Signature	TIM
<input type="checkbox"/> A	<input type="checkbox"/> Adjustments Made		
<input type="checkbox"/> O	<input type="checkbox"/> Repair Needed		
<input type="checkbox"/> R	<input type="checkbox"/> Repair Made		
<input type="checkbox"/> NA	<input type="checkbox"/> Not Applicable		

Thank You for your business; your technician was:  
**KAYS, PATRICK**  
 Phone (317) 241-8600  
 Cust PO 264297














MAXIMUM STORAGE

RESTRICTED AREA AUTHORIZED PERSONNEL ONLY

RESTRICTED AREA FOR PERSONAL USE ONLY





