

Company		Mine
Gibson County Coal		Gibson South Mine
Inspection Date:	Wednesday, January 20, 2021	
Areas Inspected:	Underground Areas - Unit 1, Unit 1 Belts, Unit 1 Primaries, Unit 1 Secondaries	
Findings / Law(s) Violated:	75.323(b), 75.330(c)	
Corrective Actions Taken:	Hazards have been addressed by management and corrected.	
Recommendation(s):	None noted	

Inspection Date:	Tuesday, February 23, 2021	
Areas Inspected:	Underground Areas - Belts & Headers: 1st Main, 2nd Main, 3rd Main; Secondaries: 1st Main, 2nd Main, 3rd Main; Bottom areas	
Findings / Law(s) Violated:	No violatins noted	
Corrective Actions Taken:		
Recommendation(s):	Lable portable chemical containers as to the contents.	

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
Peabody Midwest Mining		Francisco Mine
Inspection Date:	Wednesday, January 20, 2021	
Areas Inspected:	Surface Facilities Area - plant and facilities, shop, belts, traffic flow, tunnels, stackers	
Findings / Law(s) Violated:	77.1109(a), 77.1110	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company	Mine
---------	------

Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Thursday, March 11, 2021	
Areas Inspected:	Underground areas- M1, M2, M3 Belts and Drives, M1, M2, M3 Primary escapeways	
Findings / Law(s) Violated:	No violations noted	
Corrective Actions Taken:		
Recommendation(s):	None noted	

Company		Mine
Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Thursday, February 11, 2021	
Areas Inspected:	Underground Areas - Belts: M12 1st L, S2A; Unit @; Primaries: S2A, M12 1st L	
Findings / Law(s) Violated:	No violations noted	
Corrective Actions Taken:		
Recommendation(s):	None noted	

Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Corrective Actions Taken:	
Recommendation(s):	