County Washington Route SR 60 over South Fork Blue River Des. No. 1700173

# FHWA-Indiana Environmental Document CATEGORICAL EXCLUSION / ENVIRONMENTAL ASSESSMENT FORM GENERAL PROJECT INFORMATION

		GENERAL PROJI	ECT INFORMATION	
Road I	No./County:	State Road (SR) 60	/ Washington County	
Design	nation Number:	1700173		
After co	t Description/Termini: mpleting this form, I conclude t approve if Level 4 CE):			River, 0.42 mile west of SR 335 ategorical Exclusion (FHWA must
X				a for Categorical Exclusion Manual rironmental Scoping Manager)
				a for Categorical Exclusion Manual (Environmental Services Division)
	Categorical Exclusion, Louder Level 4 - table 1, CE Level			a for Categorical Exclusion Manual FHWA
	Environmental Assessment is necessary to determine the			litional research and documentation ories: ES, FHWA
	o release for public involvement or s		ES Signature	SM of the district in which the project is  Date
	e for Public Involvement	Date 03.31 15:58:50		
ESM In		ate	ES Initials	Date
	cation of Public Involvemen	Office of Public I		
		-	t and all other environmenta	al requirements have been satisfied.
INDOT	`ES/District Env. Reviewer \$	Signature:		Date:
Name a	and Organization of CE/EA F	reparer: Susan	Castle, Metric Environme	ental, LLC

		Indiana	a Department of Transportation	on	
County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173
		ires some level of p	- PUBLIC INVOLVEMEN  ublic involvement, providing for early and coic involvement should be commensurate with	ontinuous opportunities	throughout the
P. *J		~~		Yes	No
	1 0	historic bridge pr	ocessed under the Historic Bridges PA*?		X
	No, then: Opportunity for a Pu	blic Hearing Requ	ired?	X	
*A ]		ired for all historic	bridges processed under the Historic Bridges	ges Programmatic Agre	ement between
			ties (legal notices, letters to affected proper gs, newspaper articles, etc.) have occurred for		(i.e. notice of
Remark	2015 notifying t	hem about the pro	d to potentially affected property owners ject and that individuals responsible for copy of the Notice of Entry letter is included.	land surveying and fie	eld activities
	Transportation ( an opportunity to local publication	(INDOT) Public II o submit commen o contingent upon	nimum requirements described in the <i>nvolvement Manual</i> which requires the pt and/or request a public hearing. Thereft the release of this document for public in the requirements are fulfilled.	project sponsor to offe fore, a legal notice will	r the public appear in a
	Controversy on Enverse project involve subs		ands y concerning community and/or natural re	esource impacts?	es No
Remark	s: At this time, the resources.	ere is no substanti	al public controversy concerning impac	ts to the community of	or to natural
<u>F</u>	<u> Part II - Gener</u>	<u>al Project Io</u>	lentification, Description, a	nd Design Infor	mation
Sponsor of	the Project:	INDOT		INDOT District: Sey	ymour
Local Nam	e of the Facility:	SR 60 over S	outh Fork Blue River	-	
Funding So	ource (mark all that app	oly): Federal	X State X Local Other*	*	
*If other is	selected, please indenti	ify the funding sourc	ee:		
PURPOS	E AND NEED:				
			ll address. The solution to the traffic problem	should NOT be discussed	d in this
The need the most cracking i cracking i	recent Bridge Inspe n the copings, crack	e to the deteriorate ction Report, date ing and delaminal cracking through	ing conditions of the SR 60 bridge over ed July 2, 2019, the bridge is showing tion, and spalls with exposed rebar in a out the bituminous pavement; and a 1 ft.	signs of deterioration few spots of the side	on including walk; minor
piers; min the spandi stems and of pier #2.	or cracking in the arcrel walls at piers #2 minor scour on the arc. The deck, wearing s	ches and arch ring and #3. The sub- nose of pier #2. The surface and supers	nd spalling with exposed rebar at all four s and efflorescence in all three spans and structure has cracking and scaling with ehere is moderate drift around pier #3 and tructure are in fair condition with a rating of 9. Overall the bridge is in fair to satisfa	cracking, scaling, and fflorescence on the property as small amount on the gof 5 out of 9 and the	d spalling in ier caps and e north side
This is	page 2 of 22	Project name:	Bridge Replacement Project	Date: Ma	rch 10, 2020

County	Washington	Route	SR 60 over South Fork Blue River	r <u> </u>	Des. No.	1700173
		is to provide a sufficient ally adequate at the proj	nt structure in order to perpetuate ect location.	vehicular tra	ffic over South	Fork Blue
PROJEC'	T DESCRIPTIO	ON (PREFERRED ALT	ΓERNATIVE):			
County:	Washington	<u> </u>	Municipality:	New Pekin		
Limits of l	Proposed Work:	pavement and appro structure for a total	SR 60 will extend up to 85 ft. east ximately 693 ft. south and 583 of 1,276 ft. (0.24 mile). This incuction and maintenance of traffic.	ft. north of the	he center of th	ne existing
Total Wor	k Length:	0.24 Mile(s)	Total Work Area:	4.5	Acre(s)	
If yes, who	en did the FHWA	grant a conditional app	Justification Study (IMS/IJS) req roval for this project? EA document must be submitted to the		Yes¹  Date:  request for final	No X approval of
alternative. roadway defit Project Le INDOT, w Bridge Ne approxima Specifical	Include a discussion ocation with funding from o. 060-88-03069 ately 0.42 mile with project is 1	on of logical termini. Disc e issues.  In the Federal Highway A b, (NBI 021480) that of evest of SR 335 in Pier located in Sections 25 ar	Administration (FHWA), intends carries SR 60 over South Fork ree Township, Washington Cound 30, Township 1 North, Range 4 of Survey topographic quadrangles	to proceed w Blue River nty, Indiana ( 4 East as illust	ith a bridge pro The project Appendix B, trated on the Po	oject, State is located page B-1).
The bridge measuring The bridge structure he exposed re Level 2 de Bridge Inv.  SR 60 is cobordered be area. An un	s 50 ft. The bridge e is skewed at an has spread footing ebar, spalling, and ocument. The bridge ventory Report (Massified as a Run by shoulders that underground telep	e roadway width curb-to angle of 15 degrees to gs, no piles and is set on d efflorescence as descri- dge is not load posted and Mead and Hunt 2010) and ral Principal Arterial roa are 4 ft4 inches wide hone line is located alor	ch bridge, built in 1937. The bridge, curb is 28 ft 3 inches and the the left of the waterway. The bridge rock. The structure is showing signified in the Purpose and Need second is open to all vehicles. This bridge is not eligible for listing on the 1 dway that provides a two-lane cross. The posted speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit is 45 mag the east side of SR 60 and a burget in the second speed limit in the second speed limit is 45 mag the east side of SR 60 and a burget in	deck out-to-o dge deck was gns of deterio tion of this Ca dge is not liste National Regis oss-section win liles per hour ried water line	ut width is 35 resurfaced in ration includin ategorical Excludion the <i>Indian</i> ster of Historic th 12 ft. wide to (mph) within the is located along.	ft 1 inch. 2007. The g cracking, usion (CE) na Historic Places.  ravel lanes the project ng the west
sanitary se located in commercia	ewer line in the so the southeast qual retail. The sou	outhwest quadrant. One a uadrant. Land use on the	ines are located in the northeast quadside ditch (RSD) is located in the north end of the bridge cross e crossing is more rural in natural.	the northeast	quadrant and of residential,	one RSD is with some
The prefer stressed codegrees to	oncrete bulb-tee the left. The br	beam bridge with a total ridge cross-section will	structure with a three-span (58 ft al length of 192.6 ft., a clear roa provide a 12 ft. wide travel land itions will be installed along the	dway width of bordered by	of 30 ft., and s a 3 ft. should	skew of 15 der in each

Date:

March 10, 2020

Bridge Replacement Project

This is page 3 of 22

Project name:

County Washington Route SR 60 over South Fork Blue River Des. No. 1700173

The project will require approximately 0.80 acre of new permanent right-of-way, and 0.30 acre of temporary right-of-way for construction access. The project will result in approximately 135 linear ft. of stream impacts for the placement of scour protection and construction of substrate. Design plans are provided in Appendix B, pages B-19 to B-25. The contract letting is currently scheduled for December 2021. Construction is anticipated to begin in early 2022 and last approximately one year.

### **Maintenance of Traffic**

Traffic will be maintained on SR 60 for the duration of construction and a detour will not be required. The maintenance of traffic (MOT) plan for this project will require phased construction with a temporary traffic signal. Additional details are provided in the MOT section of this document.

### **Logical Termini and Independent Utility**

The project termini are logical because they encompass the minimum amount of roadwork and disturbance to incorporate the new structure into the existing conditions. The project has independent utility because the improvements will provide a benefit to the community even if no additional transportation improvements are planned for the project area.

The preferred alternative will meet the stated purpose and need of the project by providing a sufficient structure to perpetuate vehicular traffic on SR 60 over South Fork Blue River. Specifically, the preferred alternative is expected to provide a structure rating of 9 out of 9, hydraulically adequate, and a service life of approximately 75 years before the need for any required maintenance.

### **OTHER ALTERNATIVES CONSIDERED:**

Describe all discarded alternatives, including the Do-Nothing Alternative and an explanation of why each discarded alternative was not selected.

### Alternative 1: Three-Span Steel Beam Bridge

Alternative 1 would consist of installation of a three-span steel beam bridge that would be 182 ft. in length by 36 ft. in width. Weathering steel is assumed for this alternative to reduce the life cycle maintenance costs compared with painted steel. Alternative 1 would meet the stated purpose and need of the project by addressing the deteriorated condition of the existing bridge such that it would perpetuate vehicular traffic at the crossing of South Fork Blue River; however, the estimated construction cost of Alternative 1 is \$2,410,000.00 which is approximately 17% more expensive than the preferred alternative. Although this is a feasible alternative, due to the increased cost, it was decided that this alternative was not a prudent use of funds and was discarded from further consideration.

### **Alternative 2: Do-Nothing**

The do-nothing alternative would allow the existing structure to remain in its current deteriorating state. Although no additional cost would be incurred by this alternate, the structure would continue to deteriorate and may eventually be posted with a limited load limit which would restrict larger vehicles such as semitrucks, fire trucks and school buses. The do-nothing alternative is feasible but, it does not meet the purpose and need of the project. Furthermore, it would not be prudent to allow the structure to continue to deteriorate; therefore, this alternative was discarded from further consideration.

### The Do Nothing Alternative is not feasible, prudent or practicable because (Mark all that apply):

It	would	d not	correct	existing	capacity	deficiencies;
----	-------	-------	---------	----------	----------	---------------

It would not correct existing safety hazards;

It would not correct the existing roadway geometric deficiencies;

It would not correct existing deteriorated conditions and maintenance problems; or

It would result in serious impacts to the motoring public and general welfare of the economy.

Other (Describe)

# ROADWAY CHARACTER:

Functional Classification: SR 60 - Rural Principal Arterial

Current ADT: 7,408 VPD (2022) Design Year ADT: 7,492 VPD (2042)

Design Hour Volume (DHV): 836 Truck Percentage (%) 7.9
Designed Speed (mph): 60 Legal Speed (mph): 45

This is page 4 of 22 Project name: Bridge Replacement Project Date: March 10, 2020

 $\mathbf{X}$ 

County	Washington	Route	Route SR 60 over South Fork Blue River			Des. No.	1700173	
		Existi	ng		Proposed			
Number o		2			2			
Type of L		12 ft. trave	l lanes		12 ft. travel lan	es		
Pavement		28 – 33.8 ft.		30	ft.			
Shoulder V		2-4.4 ft.		3	ft. ft.			
Median W Sidewalk		N/A ft.		N/A N/A	ft.			
Sidewalk	widii.	IN/A II.		1 <b>N</b> / <i>F</i> <b>A</b>	] It.			
Setting:		Urban	Suburban	X	Rural			
Topograpl	hv:	X Level	Rolling		Hilly			
F - <i>O</i> F -					<i>y</i>			
If the propos	ed action has multip	le roadways, this secti	on should be fi	lled out for e	each roadway.			
DECICN	CRITERIA FOR	DDIDCES.						
DESIGN	CRITERIA FOR	DRIDGES:						
Structure/	NRI Number(s):	#060-88-03069/NB	I #021480	Suffic	ciency Rating:	50.2 Brid	dae Inspection	Report 7/2/2019
Siructure/.	rvbi rvainoci(s).	#000-00-03007/1 <b>\L</b>	1 #021400	Suiii	nency Rainig.		ource of Information	
						(raamg, se		
		Existing		Pro	posed			
Bridge Ty	pe:	Concrete A	Arch	Concre	ete Bulb-Tee B	eam		
Number o	f Spans:	3			3			
	estrictions:	N/A ton		N/A	ton			
Height Re		N/A ft.		N/A	ft.			
	urb Width:	28.3 ft.		30	ft.			
	Outside Width:	35.1 ft.		35	ft.			
Shoulder '		2 ft.		4	ft.			
Length of	Channel Work:		L	135	ft.			
Daga	wiba buidaas and s	tmietuves: provide s	nacifia locatio	an informa	tion for amall at	miotumos		
Remarks:		tructures; provide s 88-03069 is a three					Fach span is	50 ft and
Kemarks.		des a clear roadway						
		small structures are				es to the re	it over the wa	iei way. 10
				FJ -				
						Yes	No	N/A
		tated or replaced as				X		
		le bridges or small str				each structur	·e.	
MAINTE	NANCE OF TRA	AFFIC (MOT) DUI	RING CONS	TRUCTIC	<u> </u>			
		10					Yes	No
	orary bridge propos							X
	rary roadway prop			1 0/1		1 \		X
		use of a detour or re			escribe in remai	rks)	N/	X
		For access by local tr					X	
		for through-traffic do accommodate any	•		ectivale		X	<del>                                     </del>
		stantially change the				rion?	A	X
		stantiany change the sy associated with the				1011;		X
15 01010 50	Continui Conti O V CI	.s, associated with t	proposed r		1.101.			

This is page 5 of 22 Project name: Bridge Replacement Project Date: March 10, 2020

		marana Bej		r i ransportatio	· <del>-</del>	
County _	Washington	Route S	R 60 over South	Fork Blue River	Des. No.	170017
Remarks:	Traffic will be may while construction bridge to control of John Street, Grove construction; how provided in Apper	aintained on SR 60 for aintained by diverting by takes place on the other directional access for each extreet, and Poplar Streever, the entrance froudix B, pages B-21 to Borrestrictions will pose a next services); however a completion.	ooth northboun r half. A tempo ch direction of et. The entranc m John Street -22.	d and southbound tra rary traffic signal wil ravel. Access will like to Sunoco from SR will be maintained.	affic onto half of the ll be required at each tely be restricted to S 60 will likely be clo The MOT design and motorists (includ	e structure, end of the ER 60 from sed during sheets are ing school
STIMAT	ED PROJECT CO	ST AND SCHEDULE	•			
Engineerin			ay: <u>\$85,000.00</u>	(2021) Const.	ruction:\$ <u>3,684,689.0</u>	00 (2022)
C	d Start Date of Const		22 – December	This	Des is covered in a b	
If yes, Name of Location	ect in an MPO Area?  MPO  of Project in TIP incorporation by refe					
RIGHT O	F WAY:					
				Am	ount (acres)	
	Land Us	e Impacts		Permanent	Tempor	ary
esidential				0.00	0.03	
ommercia				0.05	0.27	
gricultura	11			0.61	0.00	
orest Vetlands			-	0.14	0.00	
ther:				0.00	0.00	
			TOTAL	0.80	0.30	
existing and	The project required of commercial latestream crossing.	mporary right-of-way and be discussed. Any advantal definition of the discussed.  The approximately 0.80 and, 0.61 acre of agricus a staging, and regrading	acre of perman	ent right-of-way (RO 0.14 acre of woodely 0.30 acre of ten	W) of which 0.05 acd riparian land adjace operators ROW for co	there impact.  ere consists cent to the construction
		land and 0.27 acre of co	ommercial land		•	

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173

In addition, there is no legally recorded right-of-way on file with the Washington County Recorder's Office for a portion of the project area. Therefore, it will be necessary for INDOT to re-acquire and properly record the additional permanent right-of-way necessary to complete this project. Approximately 0.06 acre of residential land, 0.21 acre of commercial land, 0.31 acre of forested land, and 0.72 acre of agricultural land will be re-acquired, for a total of 1.30 acres. Please refer to Appendix B, page B-24.

The existing ROW is typically edge of pavement to 12 ft. east of SR 60 and edge of pavement to 36 ft. west of SR 60. The maximum proposed ROW will extend approximately 60 ft. to the east and 24 ft. to the west from the edge of existing pavement (Appendix B, page B-24).

If the scope of work or permanent or temporary ROW amounts change, the INDOT Environmental Services Division (ESD) and the INDOT District Environmental Section will be contacted immediately.

### Part III – Identification and Evaluation of Impacts of the Proposed Action

# SECTION A – ECOLOGICAL RESOURCES Presence Yes No Streams, Rivers, Watercourses & Jurisdictional Ditches Federal Wild and Scenic Rivers State Natural, Scenic or Recreational Rivers Nationwide Rivers Inventory (NRI) listed Outstanding Rivers List for Indiana Navigable Waterways Presence X X X X Impacts Yes No Yes No Outstanding Rivers Outstanding Rivers Inventory (NRI) listed Outstanding Rivers List for Indiana Navigable Waterways

### Remarks:

Based on a desktop review, a site visit on August 7, 2019 by Metric Environmental, the 2015 aerial map of the project area (Appendix B, page B-3), and the water resources map in the Red Flag Investigation (RFI) report (Appendix E, page E-8), there are 22 streams, rivers, watercourses, or jurisdictional ditches located within the 0.5 mile search radius. There is one river present within the project area.

A Waters of the U.S. Determination / Wetland Delineation Report was approved on November 12, 2019 by INDOT Ecology and Waterway Permitting Office (Appendix F, page F-29). Please refer to Appendix F, pages F-1 to F-28 for the Waters of the U.S. Determination / Wetland Delineation Report. It was determined that one stream, South Fork Blue River, is present within the project limits. The U.S. Army Corps of Engineers (USACE) makes all final determinations regarding jurisdiction.

South Fork Blue River intersects the project area (Appendix F, page F-11). South Fork Blue River flows southwest into the Blue River, a Section 10 Traditional Navigable Water (TNW). Therefore, South Fork Blue River should be considered a jurisdictional Water of the U.S. South Fork Blue River is associated with a solid blue line on the USGS topographic map, indicating it is perennial. South Fork Blue River is classified by the National Wetland Inventory (NWI) as a Riverine, Lower Perennial, Unconsolidated Bottom, Permanently Flooded (R2UBH) wetland. The Ordinary High Water Mark (OHWM) was an average of 42 ft. wide and 1 ft. deep within the project study limits. The stream substrate consisted of boulder slabs, cobble, gravel, and silt. Overhanging vegetation and undercut banks were the in-stream cover present. No sinuosity was observed, and water velocity was moderate. Aquatic organisms, fish and frogs, were found in the stream. According to USGS *Indiana StreamStats*, the drainage area upstream of South Fork Blue River is 41.97 square miles. Based on qualitative analysis, South Fork Blue River is an average quality resource.

This project will install approximately 330 tons of riprap over 570 square yards of geotextiles around the north and south abutments of the new bridge for scour protection. Approximately 135 linear ft. of stream will be impacted by the placement of the erosion control measures (Appendix B, pages B-24 to B-26). No stream mitigation will be required as the impacts are less than 300 linear ft. and 0.10 acre.

This is page 7 of 22	Project name:	Bridge Replacement Project	Date:	March 10, 2020

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173

Two roadside ditches (RSD) were identified within the project study limits (Appendix F, page F-11). RSD 1 is located in the northeast quadrant and RSD 2 is located in the southeast quadrant. These features did have cut channels as they got closer to South Fork Blue River, possibly due to the field and road runoff; however, in areas where there was no debris accumulation, there was predominantly upland vegetation present within the ditch. No OHWM was observed in either of these features, so they are likely non-jurisdictional.

Early coordination letters were sent to Indiana Department of Natural Resources, Division of Fish & Wildlife (INDR-DFW), U.S. Army Corps of Engineers (USACE), and Indiana Department of Environmental Management (IDEM) on September 6, 2019 (Appendix C, pages C-1 to C-3). The USACE did not respond to the early coordination letter. IDNR-DFW stated this proposal will require the formal approval for construction in a floodway pursuant to the Flood Control Act, IC 14-28-1, unless it qualifies for a bridge exemption. This project is located within an incorporated area; therefore, the bridge exemption does not apply. A construction in a floodway permit will be required. The IDNR-DFW also responded with recommendations to avoid and minimize impacts to fish, wildlife, and botanical resources to the greatest extent possible and compensate for impacts including bank stabilization, minimizing the use of riprap in the stream and methods for riprap placement, minimizing in-channel disturbance, and avoiding work in the waterway from April 1 through June 30 (Appendix C, pages C-4 to C-6). IDEM's automatic response letter, dated September 9, 2019, includes recommendations to obtain the appropriate USACE 404 and IDEM 401 permits and to avoid impacts to water resources to the fullest extent (Appendix C, pages C-7 to C-13). All applicable IDNR-DFW recommendations are included in the Environmental Commitments section of this CE document.

	Presenc	<u>e</u>	<u>In</u>	npa	cts
Other Surface Waters			Yes		No
Reservoirs				i	
Lakes	X				X
Farm Ponds					
Detention Basins					
Storm Water Management Facilities					
Other:					

Remarks:

Based on a desktop review, a site visit on August 7, 2019 by Metric Environmental the 2015 aerial map of the project area (Appendix B, page B-3), and the water resources map in the RFI report (Appendix E, page E-8), there are four lakes located within the 0.5 mile search radius. There are no other surface waters present within or adjacent to the project area.

A Waters of the U.S. Determination / Wetland Delineation Report was approved on November 12, 2019 by INDOT Ecology and Waterway Permitting Office (Appendix F, page F-29). Please refer to Appendix F, pages F-1 to F-28 for the Waters of the U.S. Determination / Wetland Delineation Report. It was determined that there are no other surface waters present within the project limits. The USACE makes all final determinations regarding jurisdiction.

IDNR-DFW responded on October 3, 2019; however, their response did not include recommendations specific to other surface waters (Appendix C, pages C-4 to C-6). IDEM's automatic response letter, dated September 9, 2019, includes a recommendation that impacts to other water resources be avoided to the fullest extent (Appendix C, pages C-7 to C-13).

This is page 8 of 22	Project name:	Bridge Replacement Project	Date:	March 10, 2020

County	Washington	Route	SR 60 ove	r South Fork Blue River	Des.	No. 1700173		
Wetlands				Presence X	Impacts Yes	<u>s</u> No X		
Total wetl	and area: 0	acre(s)	Total wetla	and area impacted:	0 acre(s)	)		
(If a determ	nination has not been m	nade for non-is	olated/isolated	wetlands, fill in the to	otal wetland area imp	pacted above.)		
Wetland N	No. Classificatio	n Total	Size (Acres)	Impacted Acres	Comments			
N/A	N/A		N/A	N/A	N/A			
			<u>Docum</u>	<u>ientation</u>	ES Appro	oval Dates		
Wetland Do Wetland Do USACE Iso Mitigation	olated Waters Determin Plan			X	November 12,			
would resu Substa Substa Unique Substa	Improvements that will not result in any wetland impacts are not practicable because such avoidance would result in (Mark all that apply and explain):  Substantial adverse impacts to adjacent homes, business or other improved properties; Substantially increased project costs; Unique engineering, traffic, maintenance, or safety problems; Substantial adverse social, economic, or environmental impacts, or The project not meeting the identified needs.							
Measures to Remarks:	data/Mapper.html), (Appendix B page If the 0.5 mile search impacts are expected  A Waters of the U.S. INDOT Ecology an pages F-1 to F-28 fo that there are no w jurisdiction.  IDNR-DFW respon specific to wetlands 2019, includes reco	f the National a site visit on B-2), and the F radius. No will.  S. Determination of Waterway For the Waters of etlands within ded on Octob (Appendix C, mmendations of the site of the si	Wetlands Inverton August 7, 20 RFI report (Appretlands are proported of the U.S. Detector of the U.S. Detector of the pages C-4 to County that a consultant of the U.S. Detector of the U.S. Detector of the pages C-4 to County the U.S. Detector of the U.S. Detector of the pages C-4 to County the U.S. Detector of the U.S. Det	ntory (NWI) online made to be discussed in the latery (NWI) online made to the later than the la	apper (https://www.nmental, the USGS even (11) wetlands ent to the project as approved on Nove e F-29). Please references all final determines edid not include the response letter, de whether the project	topographic map are located within area, therefore, no ember 12, 2019 by the to Appendix F, It was determined inations regarding recommendations lated September 9, but will abut, or lie		
<b>Terrestria</b> Unique or	<b>l Habitat</b> High Quality Habitat			<u>Presence</u> X	Yes X	Impacts No		
Use the remo	arks box to identify eac	h type of habit	at and the acre	s impacted (i.e. foresi	ted, grassland, farml	'and, lawn, etc).		
This is p	age 9 of 22	Project name:	Bridge R	eplacement Project	Date:	March 10, 2020		

		maiama	Department of	rransport	ation		
County	Washington	Route	SR 60 over South	Fork Blue River		Des. No.	1700173
Remarks:	project area (Appen The dominant vege stratum; eastern bla	adix B, page B-station located wack walnut ( <i>Jug</i> eed ( <i>Ambrosia t</i> )	visit on August 7, 203), there are fourteen within the project are dans nigra) and black rifida), japanese hop	types of terres a is silver map ck cherry ( <i>Pru</i>	strial habitats ble ( <i>Acer sac</i> nus serotine)	within the procharinum) from the sap	oject area. n the tree ling/shrub
	The project will result in approximately 1.17 acres of tree clearing, 0.50 acre of agriculture land disturbance and 0.50 acre of grass disturbance to replace the bridge and widen the roadway for maintenance of traffic Mitigation will not be required.						
	terrestrial habitat. R mitigated at a minir replacement should	ecommendation mum 2:1 ratio; be at a 1:1 ratio	tober 3, 2019 with s include impacts to if less than one acre based on area; revege included in the	non-wetland for of non-wetland getating; and mi	rest of one (1 d forest is read inimizing tree	) acre or more moved in a rur e clearing. All	should be ral setting, applicable
	nigh incidences of anin r for animal movement					er areas appea	r to be the
	proposed project locate rst features located wit		-		_	Yes X	No X
If yes,	will the project impact	any of these ka	rst features?				
	arks box to identify any October 13, 1993)	y karst features	within the project are	ea. (Karst inves	stigation mus	t comply with t	he Karst
Remarks:	Based on a desktop the October 13, 199 (Appendix B, page within or adjacent to (IGS) did not indicates responded that geol- mineral resources in and no active or aba	3 Memorandum B-2), and the R to the project at that karst fe ogical hazards include moderate andoned mineral	ect is located inside of Understanding (N LFI report (Appendix rea. In the early co atures exist in the p include a high liquefa is potential bedrock re- resources extraction immunicated with the	MOU). According E, page E-8), ordination resproject area (Apaction potential esource and lown sites are located	ing to the top there are no onse, the Independix C, pa and 1% ann w potential sa ed within 0.5	o map of the property karst features diana Geologic ages C-14 to Cual chance floor and and gravel mile of the property was considered.	roject area identified ral Survey 2-16). IGS od hazard; resource; oject area.
				<u>P1</u>	<u>resence</u>	<u>Im</u>	<u>pacts</u>
Within t Any crit Federal	d or Endangered Spe the known range of any tical habitat identified species found in project ecies found in project	y federal species within project an ct area (based up	rea oon informal consulta		X	Yes	No X
Is Section	on 7 formal consultatio	on required for the	nis action?	Yes	No X		

Bridge Replacement Project

Date:

March 10, 2020

Project name:

This is page 10 of 22

		Indian	a Department of	Transportatio	'n	
County	Washington	Route	SR 60 over South Fo	•	Des. No.	1700173
Remarks:	Based on a desktop review and the RFI report (Appendix E, page E-4), completed by Metric Environmental on October 8, 2019, the IDNR Washington County Endangered, Threatened and Rare (ETR) Species List has been checked and is included in (Appendix E, pages E-10 to E-13). The highlighted species on the list reflect the federal and state identified ETR species located within the county. According to the IDNR-DFW early coordination response letter dated October 3, 2019 (Appendix C, page C-4), the Natural Heritage Program's Database has been checked. To date, no plant or animal species listed as state or federally threatened, endangered, or rare have been reported to occur in the project vicinity.  Project information was submitted through the USFWS's Information for Planning and Consultation (IPaC) portal, and an official species list was generated (Appendix C, pages C-17 to C-22). The project is within range of the federally endangered Indiana bat ( <i>Myotis sodalis</i> ) and the federally threatened northern longeared bat (NLEB) ( <i>Myotis septentrionalis</i> ). No additional species were found within or adjacent to the project area other than the Indiana bat and northern long-eared bat.					
:						
	northern long-ea Railroad Adminis key was complete "May Affect/Not verified the effect C, pages C-23 to it was concluded	tred bat (NLEB), tration (FRA), Fe ed on December Likely to Adve finding on Dece C-37). No resport they concur with	ge-wide Programmatic dated May 2016 (rederal Transit Administrall, 2019, and based on the India mber 11, 2019 and requise was received from Uthe finding. Avoidance amental Commitments is	rised February 20 ation (FTA), and U the responses pro na bat and/or the nested USFWS's rISFWS within the and Minimization	oll8), between FHWA USFWS. An effect deta vided, the project wa NLEB. INDOT reversive of the finding 14-day review period; Measures (AMMs) ar	A, Federal ermination s found to iewed and (Appendix therefore,
	Species Act, as a	mended. If new	consultation on this pro information on endang will be contacted for co	gered species at the		
SECTION	N B – OTHER RESO	OURCES				
Wellhe Public Reside	Water Resources ead Protection Area Water System(s) ntial Well(s) Water Protection Are	22(c)		Presence X	Yes No	

	<u>Presence</u>	<u>Impacts</u>	
Orinking Water Resources		Yes	No
Wellhead Protection Area			
Public Water System(s)	X		X
Residential Well(s)			
Source Water Protection Area(s)			
Sole Source Aquifer (SSA)			
If a SSA is present, answer the following:			
	Yes	No	
Is the Project in the St. Joseph Aquifer System?			
Is the FHWA/EPA SSA MOU Applicable?			
Initial Groundwater Assessment Required?			
Detailed Groundwater Assessment Required?			

Remarks:

The project is located in Washington County, which is not located within the area of the St. Joseph Sole Source Aquifer, the only legally designated sole source aquifer in the state of Indiana. Therefore, the FHWA/EPA Sole Source Aquifer Memorandum of Understanding (MOU) is not applicable to this project. Therefore, a detailed groundwater assessment is not needed and no impacts are expected.

The Indiana Department of Environmental Management's Wellhead Proximity Determinator website (<a href="http://www.in.gov/idem/cleanwater/pages/wellhead/">http://www.in.gov/idem/cleanwater/pages/wellhead/</a>) was accessed on December 20, 2019 by Metric Environmental. This project is not located within a Wellhead Protection Area or Source Water Area. No impacts are expected.

This is page 11 of 22	Project name:	Bridge Replacement Project	Date:	March 10, 2020

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173

The Indiana Department of Natural Resources Water Well Record Database website (<a href="https://www.in.gov/dnr/water/3595.htm">https://www.in.gov/dnr/water/3595.htm</a>) was accessed on September 25, 2019 by Metric Environmental. No wells are located near this project. Therefore, no impacts are expected.

Based on a desktop review of the INDOT MS4 website (<a href="https://entapps.indot.in.gov/MS4/">https://entapps.indot.in.gov/MS4/</a>) by Metric Environmental on August 16, 2019, and the RFI report; this project is not located in an Urban Area Boundary location. No impacts are expected.

Based on a desktop review, a site visit on August 7, 2019 by Metric Environmental, the 2015 aerial map of the project area (Appendix B, page B-3), this project is located where there is a public water system. The public water system will not be affected because this project does not include excavation to repair or replace the public water system. An early coordination letter was sent on July 11, 2019 to the New Pekin Municipal Utilities (Appendix C, pages C-38 to C-39). No response was received.

<u>.r</u>		<u>1</u>	<u>Impacts</u>	
Flood Plains		Yes	<b>;</b>	No
Longitudinal Encroachment	X	X		
Transverse Encroachment				
Project located within a regulated floodplain	X	X		
Homes located in floodplain within 1000' up/downstream from project	X			X

Discuss impacts according to classification system described in the "Procedural Manual for Preparing Environmental Studies".

Remarks:

Based on a desktop review of The Indiana Department of Natural Resources Indiana Floodway Information Portal website (<a href="http://dnrmaps.dnr.in.gov/appsphp/fdms/">http://dnrmaps.dnr.in.gov/appsphp/fdms/</a>) by Metric Environmental on September 25, 2019 and the RFI report; this project is located in a regulatory floodplain as determined from approved IDNR floodplain maps (Appendix F, page F-10). An early coordination letter was sent on March 4, 2020, to the local Floodplain Administrator. On March 6, 2020, the Floodplain Administrator stated in a phone conversation with a staff member from Metric Environmental that he has no comments regarding this project.

This project qualifies as a Category 4 per the current INDOT CE Manual, which includes projects involving replacement of existing drainage structures on essentially the same alignment. Category 4 states "no homes are located within the base floodplain within 1,000 ft. upstream and twelve homes are located within the base floodplain within 1,000 ft. downstream. The proposed structure will have an effective capacity such that backwater surface elevations are not expected to substantially increase. As a result, there will be no substantial adverse impacts on natural and beneficial floodplain values; there will be no substantial change in flood risks; and there will be no substantial increase in potential for interruption or termination of emergency service or emergency evacuation routes; therefore, it has been determined that this encroachment is not substantial. A hydraulic design study that addresses various structure size alternatives will be completed during the preliminary design phase. A summary of this study will be included with the Field Check Plans."

	<u>Presence</u>	<u>Impacts</u>
Farmland		Yes No
Agricultural Lands	X	X
Prime Farmland (per NRCS)	X	X
Total Points (from Section VII of CPA-106/AD-1006*	92	
*If 160 or greater, see CE Manual for guidance.		

See CE Manual for guidance to determine which NRCS form is appropriate for your project.

This is page 12 of 22	Project name:	Bridge Replacement Project	Date:	March 10, 2020

County					
_	Washington Route	SR 60 ove	er South Fork Blue River	Des. No.	1700173
Remarks:	Based on a desktop review, a the project area (Appendix B Farmland Protection Policy A Resources Conservation Servi requesting their response to the with NRCS resulted in a scothreshold score for significant Since this project score is less important farmland will result document will be investigated.  Since design has progressed, 1 on the NRCS-CPA-106 Form. maintenance of traffic.	page B-3), the proct. An early coordices (NRCS). On Ine early coordination of 92 on the Not impacts to farmles than the threshold from this project, without reevaluation. 10 acres of farmla	roject will convert 0.50 acre ination letter was sent on Sep December 20, 2019 Metric sent on letter sent to them on Sep IRCS-CPA-106 Form (Appearand that result in the consideration of the properties of the primary	of farmland as definatember 6, 2019, to to the a follow-up e-main ptember 6, 2019. Condix C, page C-41). Ideration of alternative me, unique, statewide ose previously discussion.	hed by the he Natural I to NRCS pordination NRCS's res is 160. e, or local ssed in this defined
OE CET CT	O CHIEFIDA PROCES	20			
SECTION	C – CULTURAL RESOURCE	2.O			
· ·	cts PA Clearance	egory Type B 12  Cligible and/or List Passauras Pressau			N/A
esults of R	kesearcn	Resource Presen	<u>u</u>		
Archaeology IRHP Build IRHP Distr IRHP Bridg	dings/Site(s) rict(s)				
roject Effe	ect				
lo Historic	Properties Affected	No Adverse Effect	Adverse Effect		
ocumenta <sup>1</sup>	tion (mark all that apply)	Documentation Prepared	ES/FHWA Approval Date(s)	SHPO Approval D	ata(s)
Iistoric Proparchaeologio Archaeologio Archaeologio Archaeologio Archaeologio	perties Short Report perty Report cal Records Check/ Review cal Phase Ia Survey Report cal Phase Ic Survey Report cal Phase II Investigation Report cal Phase III Data Recovery ility and Effect Determination	X	September 25, 2019	Approvat De	

Date:

March 10, 2020

Bridge Replacement Project

Project name:

This is page 13 of 22

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173
					_
			including a detailed summary of the	-	_

categories outlined in the remarks box. The completion of the Section 106 process requires that a Legal Notice be published in local newspapers. Please indicate the publication date, name of paper(s) and the comment period deadline. Likewise include any further Section 106 work which must be completed at a later date, such as mitigation or deep trenching.

Remarks:

On September 25, 2019 the INDOT Cultural Resource Office (CRO) determined that this project falls within the guidelines of Category A, Type 9 and Category B, Type 12 under the Minor Projects Programmatic Agreement, (Appendix D, pages D-1 to D-4). Category A-9 includes installation, repair, or replacement of erosion control measures along roadways, waterways and bridge piers within previously disturbed soils. Category B-12 type projects includes the replacement, widening, or raising the elevation of the superstructure on existing bridges, and bridge replacement projects (when both the superstructure and substructure are removed).

An Archaeological Phase 1a short report was prepared by Metric Environmental personnel who meet the Secretary of the Interior's Professional Qualification Standards as per 36 CFR Part 61, dated September 6, 2019. The records check identified no previously recorded sites within or adjacent to the project area but determined that a portion of the current project area was previously examined. To account for any future design changes, an area larger than the anticipated project construction footprint was surveyed. Approximately 6.2 acres of land was examined through visual walkover survey, 5m interval pedestrian transects, one shovel test probe, and five soil cores. The northern half of the project area was found to contain either disturbed or eroded soils. The agricultural fields in the southern half were investigated through close interval pedestrian transects. No archaeological sites were identified, and no further work was recommended. No further consultation is required. This completes the Section 106 process and the responsibilities of the FHWA under Section 106 have been fulfilled.

SECTION D – SECTION 4(f) RESOURCES/ SECT	TION 6(f) RESOURCES		
Section 4(f) Involvement (mark all that apply)	Dwagowaa	Uso	
Parks & Other Recreational Land	<u>Presence</u>	<u>Use</u> Yes No	
Publicly owned park			
Publicly owned recreation area			
Other (school, state/national forest, bikeway, etc.)			
	Evaluations		
	<b>Prepared</b>	EHW/A	
Programmatic Section 4(f)*		<u>FHWA</u> Approval date	
"De minimis" Impact*		Approvaruate	
Individual Section 4(f)			
(-)			
	<b>Presence</b>	<u>Use</u>	
Wildlife & Waterfowl Refuges		Yes No	
National Wildlife Refuge			
National Natural Landmark			
State Wildlife Area			
State Nature Preserve			
	<b>Evaluations</b>		
	<b>Prepared</b>		
Dun		FHWA	
Programmatic Section 4(f)* "De minimis" Impact*		Approval date	
Individual Section 4(f)			
marviduai Section 4(1)			
		_	
This is page 14 of 22 Project name:	Bridge Replacement Project	Date:	March 10, 2020

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173
			Presence	Use	
	Properties		Yes	No No	
Sites	eligible and/or listed of	on the NRHP			
			<b>Evaluations</b>		
			<u>Prepared</u>	211XX/ A	
P	rogrammatic Section 4	4(f)*		<u>FHWA</u> proval date	
	De minimis" Impact*				
	ndividual Section 4(f)				
*FHWA app discussed be		tal document also serv	ves as approval of any Section 4f Programi	natic and/or De minimis	evaluation(s)
Discuss Pr	ogrammatic Section 16	f) and "do minimis"	Section 4(f) impacts in the remarks l	oor helow Individual	Section 1(f)
documentat	ion must be separate D	raft and Final docum	ents. For further discussions on Progran	ımatic, "de minimis" a	nd Individual
	evaluations please ref that satisfy the requirem		l Manual for the Preparation of Enviror	imental Studies". Disc	uss proposed
Remarks:	Section 4(f) of th	e U.S. Department	of Transportation Act of 1966 prohib		
			nsportation facilities unless there is no cly owned parks, recreation areas, w		
			rties. Lands subject to this law are cons		
	D4 414-		it an Armant 7, 2010 has Matria Essaina		:-1 6
			it on August 7, 2019 by Metric Envirc 3), and the Red Flag Investigation (RF		
	there is one 4(f)	resource located wi	thin the 0.5 mile search radius. The	re are no Section 4(f	) resources
	Section 4(f) is exp		ea. Therefore, no impact to any reso	urces afforded protec	tion under
Section 6	(f) Involvement		<u>Presence</u>	Use	
Section 6	(f) Proporty		Yes	No	
Section 0	o(f) Property				
•			ements of Section 6(f). Discuss any Sec		
Remarks:			tion Fund Act of 1965 established the to preserve, develop, and assure acc		
	resources. Section	of this Act pr	rohibits conversion of lands purchase	d with LWCF monies	s to a non-
			perties on the Land and Water Conserveyealed a total of three properties in V		
	page I-1). None of	of these properties ar	e located within or adjacent to the proj	ect area. Therefore, th	1 1
	no impacts to any	resources encumber	ed by 6(f) funds as a result of this project	ect.	
GE GELO	NE ALO III				
SECTIO	N E – Air Quality				
<u>Ai</u>	<u>r Quality</u>				
(	Conformity Status of	the Project	Yes	No	
Is	s the project in an air c	•	nt or maintenance area?	X	
I	f YES, then: Is the project in the	most current MPO	ΓΙ <b>D</b> ?		
	Is the project exemp		111;		
	If the project is NO	T exempt from conf	•	- —— - ——	
	2 0	the Transportation I llysis required (CO/I	• • •		
	18 a not spot and	nysis required (CO/I	11/1):		
This is	s page 15 of 22	Project name:	Bridge Replacement Project	Date: Ma	rch 10, 2020

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173
Τ	-1 - CMCAT A 1:	: 10			
Lev	rel of MSAT Analysis re	quirea?			
Lev	rel 1a X Level 1b	Level 2	Level 3 Level 4 Level 4	evel 5	
Remarks:	This project is incl	uded in the F	iscal Year (FY) 2018-2021 and 2020	-2024 Statewide Trans	portation
			endix H, pages H-1 to H-3).		
			ton County, which is currently in attain		ollutants
	according to http conformity procedur		/idem/airquality/files/nonattainment_co	unty_list.pdf. Therefo	ore, the
			and the second s		
			g as a categorical exclusion (Group 1		
			onformity rule under 40 CFR 93.126, and	nd as such, a Mobile So	ource Air
	Toxics analysis is no	n required.			
SECTION	F - NOISE				
Noise				Yes	No
Is a noise ar	nalysis required in accord	dance with FH	WA regulations and INDOT's traffic no	ise policy?	X
15 4 110156 41	iary ord required in accord		Triogulations and It is of a traine no	ise poney.	
		No Y	es/ Date		
ES Review	of Noise Analysis	110 1	es/ Date		
ES Review	of I (olse I lifely sis				
Remarks:	This project is a Type	III project In	accordance with 23 CFR 772 and the cu	rrent Indiana Donartmo	ent of
Kemarks.			<i>Procedure</i> , this action does not require		
			<b>1</b>		
SECTION	G – COMMUNITY IM	IPACTS			
D 1 10				***	<b>N</b> Y
	Community & Neighbor		ional development patterns for the area?	Yes	No
			ets to community cohesion?	X	X
			ets to local tax base or property values?		X
			nts (festivals, fairs, etc.)?		X
	mmunity have an approv			X	
			munity's transition plan?		
Does the pro	oject comply with the tra	ansition plan? (	explain in the remarks box)	X	
Remarks:			e impact to local mobility, access, p		
			project. However, during construction, l. There will be no permanent adverse		
			permanent impacts to the community of		
			ntified as a result from the project.	onesion, local tax base,	property
			FJ		
			ng construction. In accordance with the		
			ractor will be responsible for contacting		
			ne start of construction. Notification and		
	Manal on Uniform Tra		be in accordance with current INDOT	Standard Specifications	and the
	ivianai on Omioim Ita	THE COILIOI DO	. vices (IVIO I CD).		
ant : :	nge 16 of 22 Pr	roject name:	Bridge Replacement Project	Date: March	n 30, 2020

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173				
	on December 23 Park Street, New	The Indiana Association of Fairs website (www.indianafestivals.org) was reviewed by Metric Environmental on December 23, 2019. There is one event scheduled July 3 and 4, 2020 at the Pekin Park, located at 340 Park Street, New Pekin, IN 47165. This project will not impact community events, such as festivals or fairs due to the project area will remain open during construction activities.							
	Housing and Ur	ban Development (	ironmental sent an early coordination pack (HUD) requesting comments from their are ciated with this project (Appendix C, pages of the coordination of the coordination pack (European C).	ea of expertise reg	arding any				
	December 2019. amended within	There are no exist the vicinity of this	s an American with Disabilities Act (ADA ing sidewalks or other pedestrian walkway project, and there are no sidewalks or other . This project will not contribute to any barr	s which will be de pedestrian walkway	estroyed or ys that will				
	and Cumulative Im roposed action resul		rect or cumulative impacts?	Yes	No X				
Remarks:	distance, but are effects related to impacts affect th	still reasonably for induced changes in e environment, wh	are caused by the action and are later in eseeable. Indirect effects may include grown the pattern of land use, population density ich result from the incremental impact of the eable future actions regardless of what agen	or the inducing effects of the contract of the	s and other Cumulative ed to other				
	significant effect distance. In add patterns of land systems, including result from the inforeseeable future.	ts identified which ition, there have buse, population deng ecosystems. No neremental impactore actions. This pro-	have been identified as a result of this are caused by the action and are later in een no significant effects identified which noity or growth rate, or related effects on a significant impacts on the environment have of the proposed action when added to other opect will improve the road and bridge contany substantial negative impacts.	n time or farther remay induce chan ir and water or other been identified past, present, and	emoved in ges in the her natural which will reasonably				
Will the p private uti	lities, emergency sea and bicycle facilities	rvices, religious ins	acts on health and educational facilities, pub titutions, airports, public transportation or e maintenance of traffic will affect public fac		No X				
Remarks:	the project area facilities located	(Appendix B, page within the 0.5 mil	isit on August 7, 2019 by Metric Environm B-3), and the RFI report (Appendix E, pa e search radius. There are no public facilities will be maintained during construction	ge E-7) there are ties within or adjace	five public cent to the				
			et sponsor to notify school corporations and that would block or limit access.	d emergency service	ees at least				
During the Does the p If YES, th Are	any EJ populations l	e project were EJ issanalysis?  ocated within the p	sues identified?	Yes X	No X				
During the Does the p If YES, th Are	nental Justice (EJ) e development of the project require an EJ en: any EJ populations I	(Presidential EO 12 project were EJ is analysis?	898) sues identified?	X	X				

Bridge Replacement Project

Date:

March 10, 2020

Project name:

This is page 17 of 22

County washington Route SK of over South Fork Blue River Des. No. 170	County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173
---	--------	------------	-------	----------------------------------	----------	---------

Remarks:

Under FHWA Order 6640.23A, FHWA and the project sponsor, as a recipient of funding from FHWA, are responsible to ensure that their programs, policies, and activities do not have a disproportionately high and adverse effect on minority or low-income populations. Per the current INDOT Categorical Exclusion Manual, an Environmental Justice (EJ) Analysis is required for any project that has two or more relocations or 0.5 acre of additional permanent right-of-way. The project will require 1.89 acres of permanent right-of-way. Therefore, an EJ Analysis is required.

Potential EJ impacts are detected by locating minority and low-income populations relative to a reference population to determine if populations of EJ concern exists and whether there could be disproportionately high and adverse impacts to them. The reference population may be a county, city or town and is called the community of comparison (COC). In this project, the COC is Washington County. The community that overlaps the project area is called the affected community (AC). In this project, the AC is Census Tract 9677. An AC has a population of concern for EJ if the population is more than 50% minority or low-income or if the low-income or minority population is 125% of the COC. Data from the 2017 American Community Survey [ACS] 5-year estimates was obtained from the US Census Bureau Website https://factfinder.census.gov/ on December 23, 2019 by Metric Environmental. The data collected for minority and low-income populations within the AC are summarized in the below table.

	COC – Washington County	AC-1 - Census Tract 9677, Washington County, Indiana)
Percent Minority	3.09%	4.03%
125% of COC	3.86%	AC < 125% COC
EJ Population of Concern		Yes
Percent Low-Income	13.26%	12.57%
125% of COC	16.58%	AC < 125% COC
EJ Population of Concern		No

<sup>\*</sup>Refer to the INDOT EJ guidance for calculating percentages

AC-1, Census Tract 9677 has a percent minority of 4.03% which is below 50% and is above the 125% COC threshold. Therefore, AC-1 is a minority population of EJ concern.

AC-1, Census Tract 9677 has a percent low-income of 12.57% which is below 50% and is below the 125% COC threshold. Therefore, AC-1 does not contain low-income populations of EJ concern.

Conclusion –The drive that is located within the temporary r/w, in the northeast quadrant of the project area, 540 SR 60, will not be impacted by this project. It will remain accessible to the owner/occupant and will also be available for the contractor's use to access the grass area adjacent west for regrading purposes. If the scope of work occurring on the property located at 540 SR 60 changes, INDOT ESD will be contacted immediately.

INDOT ESD has reviewed the project information along with the EJ Analysis for the above referenced project. The project will require right-of-way, require no relocations, will not disrupt community cohesion or create a physical barrier. The maintenance of traffic for the project will provide minor inconvenience during construction for both EJ and non EJ populations. With the information provided, INDOT ESD does not consider the impacts associated with this project as causing a disproportionately high and adverse effect on minority and/or low income populations of EJ concern relative to non EJ populations in accordance with the provisions of Executive Order 12898 and FHWA Order 6640.23a. No further EJ Analysis is required.

The census data sheets, map, and calculations can be found in Appendix (I).

This is page 18 of 22	Project name:	Bridge Replacement Project	Date:	March 10, 2020	

			•	
County	Washington	Route	SR 60 over South Fork Blue River	Des. No. <u>1700173</u>
Relocat	ion of People, Busi	nesses or Farms		Yes No
Will the	proposed action res	sult in the relocation of	people, businesses or farms?	X
		urvey (BIS) required?	1 1 /	X
		cation Study (CSRS) re	equired?	X
		ination been initiated f		X
Number	of relocations:	Residences: 0	Businesses: 0 Farms: 0	Other: 0
If a RIS o	r CSRS is required	discuss the results in	the remarks hor	
<i>IJ u bis o</i> Remark			or farms will take place as a result of this	s project.
	110 1010 0011011		, or restrict with their process or their	s prejecti
SECTION	ON H – HAZARD	OUS MATERIALS &	REGULATED SUBSTANCES	
			<b>Document</b>	estion
Hazard	ous Materials & R	egulated Substances		<u>atton</u>
	g Investigation	· ·	X	
		Assessment (Phase I I		
		e Assessment (Phase II	ESA)	
Design/S	Specifications for R	emediation required?		
		No. 3	Yes/ Date	
ES Rev	iew of Investigatio		Yes/ October 8, 2019	
Lo Rev	iew of investigatio	113	1 63/ 0 610 61 0, 2017	
Include a	summary of finding	rs for each investigatio	n.	
Remark	s: Based on a re	view of GIS and availa	ble public records, an RFI was completed	d on October 8, 2019 by Metric
			E-1 to E-13). Three underground storag	
			and no sites are located within the proje	
			the project area that will impact the pr	
			ets are expected because the most recen	
			o violations or suspected or reported le	
	Further invest	igation for hazardous i	naterial concerns is not required at this tin	ne.
SECTION	ON I – PERMITS	CHECKLIST		
Dormite	(mark all that appl	)	Likely Required	
1 CI IIIICS	(mark an mat appi	y)	Likely Required	
		(404/Section10 Perm	it)	
	Individual Permit (			
	Nationwide Permit			
	Regional General P		X	
	Pre-Construction N	otification (PCN)		
	Other			
	Wetland Mitigation	-		
	Stream Mitigation 1	equired		
IDEM				
	Section 401 WQC		X	
	Isolated Wetlands of	letermination		
	Rule 5		X	
	Other		<u> </u>	
	Wetland Mitigation	-	<u> </u>	
	Stream Mitigation i	required		
This	is page 19 of 22	Project name:	Bridge Replacement Project	Date: March 30, 2020
11113	p-5- 17 01 44	- roject manne.	21.050 1.001.001.01.01.01.000	

County	Washington	Route	SR 60 over South Fork Blue River	_ Des. No.	1700173
IDNR					
	Construction in a Flood	way	X		
	Navigable Waterway Pe	ermit			
	Lake Preservation Perm	nit			
	Other				
	Mitigation Required				
US Coa	st Guard Section 9 Bri	dge Permit			

Remarks:

An IDEM Section 401 RGP and a USACE 404 RGP are anticipated to be required to remove and replace the existing structure and install the riprap. Final decisions regarding the type of permits will be made by USACE and IDEM.

A National Pollutant Discharge Elimination System (NPDES) General Permit for Erosion Control (Rule 5) will be required, as greater than 1 acre of land will be disturbed. Prior to the initiation of construction, it will be the responsibility of the contractor to submit the Notice of Intent to IDEM regarding the intent to operate the proposed construction project in a manner consistent with the rule.

This project will require the formal approval from IDNR Division of Water for construction in a floodway (CIF).

Applicable recommendations provided by IDNR-DFW are included in the Environmental Commitments section of this document. If permits are found to be necessary, the conditions of the permit will be requirements of the project and will supersede these recommendations.

It is the responsibility of the project sponsor to identify and obtain all required permits.

### SECTION J- ENVIRONMENTAL COMMITMENTS

Others (Please discuss in the remarks box below)

The following information should be provided below: List all commitments, name of agency/organization requesting the commitment(s), and indicating which are firm and which are for further consideration. The commitments should be numbered.

Remarks:

### Firm:

- If the scope of work or permanent or temporary right-of-way amounts change, INDOT ESD and the INDOT District Environmental Section will be contacted immediately. (INDOT ESD and INDOT District)
- 2. It is the responsibility of the project sponsor to notify school corporations and emergency services at least two weeks prior to any construction activity that would block or limit access. (INDOT ESD)
- 3. USFWS Bridge/Structure Assessment shall take place no earlier than two (2) years prior to the start of construction. If construction will begin after August 26, 2021, an inspection of the structure by a qualified individual, must be performed. Inspection of the structure should check for presence of bats/bat indicators and/or presence of birds. The results of the inspection must indicate no signs of bats or birds. If signs of bats or birds are documented during this inspection, the INDOT District Environmental Manager must be contacted immediately. (INDOT ESD)
- 4. General AMM 1: Ensure all operators, employees, and contractors working in areas of known or presumed bat habitat are aware of all FHWAQ/FRA/FTA (Transportation Agencies) environmental commitments, including all applicable AMMs. (USFWS)
- 5. Hibernacula AMM 1: For projects located within karst areas, on-site personnel will use best management practices, secondary containment measures, or other standard spill prevention and countermeasures to avoid impacts to possible hibernacula. Where practicable, a 300 foot buffer will be employed to separate fueling areas and other major containment risk activities from caves, sinkholes, losing streams, and springs in karst topography. (USFWS)
- 6. Lighting AMM 1: Direct lighting away from suitable habitat during the active season. (USFWS)

	Removal AMM 1: Ments) to avoid tree re	Iodify all phases/aspects of the premoval. (USFWS)	oject (e.g., temp	orary work areas,
Γhis is page 20 of 22	Project name:	Bridge Replacement Project	Date:	March 30, 2020
		Form Version: June 2013 Attachment 2		

County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173
Journey	** usiiiii <u>~</u> toii	Route	Sit of over South I olk Blue Itivel	DC3. 1 10.	1/001/5

- 8. Tree Removal AMM 2: Apply time of year restrictions for tree removal when bats are not likely to be present, or limit tree—removal to 10 or fewer trees per project at any time of year within 100 ft. of existing road/rail surface and **outside of documented** roosting/foraging habitat or travel corridors; visual emergence survey must be conducted with no bats observed. (USFWS)
- 9. Tree Removal AMM 3: Ensure tree removal is limited to that specified in project plans and ensure that contractors understand clearing limits and how they are marked in the field (e.g., install bright colored flagging/fencing prior to any tree clearing to ensure contractors stay within clearing limits) (USFWS)
- 10. Tree Removal AMM 4: Do not remove **documented** Indiana bat or NLEB roosts that are still suitable for roosting, or trees within 0.25 mile of roosts, or **documented** foraging habitat any time of year. (USFWS)

### For Further Consideration:

- 11. Do not construct any temporary runarounds, access bridges, causeways, cofferdams, diversions, or pumparounds. (IDNR-DFW)
- 12. Do not cut any trees suitable for Indiana bat or Northern Long-eared bat roosting (greater than 5 inches dbh, living or dead, with loose hanging bark, or with cracks, crevices, or cavities) from April 1 through September 30. (IDNR-DFW)
- 13. Do not excavate in the low flow area except for the placement of piers, foundations, and riprap, or removal of the old structure. (IDNR-DFW)
- 14. Use minimum average 6 inch graded riprap stone extended below the normal water level to provide habitat for aquatic organisms in the voids. (IDNR-DFW)
- 15. Impacts to non-wetland forest of one (1) acre or more should be mitigated at a minimum 2:1 ratio. If less than one acre of non-wetland forest is removed in a rural setting, replacement should be at a 1:1 ratio based on area. Impacts to non-wetland forest under one (1) acre in an urban setting should be mitigated by planting five trees, at least 2 inches in diameter-at-breast height (dbh), for each tree which is removed that is 10 inches dbh or greater (5:1 mitigation based on the number of large trees). (IDNR-DFW)
- 16. The new, replacement, or rehabbed structure should not create conditions that are less favorable for wildlife passage under the structure compared to the current conditions. (IDNR-DFW)
- 17. Riprap must not be placed in the active thalweg channel or placed in the streambed in a manner that precludes fish or aquatic organism passage (riprap must not be placed above the existing streambed elevation). Riprap may be used only at the toe of the sideslopes up to the ordinary high water mark (OHWM). The banks above the OHWM must be restored, stabilized, and revegetated using geotextiles and a mixture of grasses, sedges, wildflowers, shrubs, and trees native to the area and specifically for stream bank/floodway stabilization purposes as soon as possible upon completion. (IDNR-DFW)

Remarks:

	County	Washington	Route	SR 60 over South Fork Blue River	Des. No.	1700173
--	--------	------------	-------	----------------------------------	----------	---------

### **SECTION K- EARLY COORDINATION**

Please list the date coordination was sent and all agencies that were contacted as a part of the development of this Environmental Study. Also, include the date of their response or indicate that no response was received. INDOT and FHWA are automatically considered early coordination participants and should only be listed if a response is received.

Remarks:

Agency	<b>Coordination Sent</b>	Response Received
U.S. Fish & Wildlife Service	September 6, 2019	None Received
Indiana Department of Natural Resources	September 6, 2019	October 3, 2019
US Department of HUD	September 6, 2019	None Received
National Parks Service	September 6, 2019	None Received
IDEM Proposed Roadway Construction Projects	September 6, 2019	September 9,2019
Washington County Surveyor	September 6, 2019	None Received
Washington County Highway Department	September 6, 2019	None Received
Washington County Commissioner-District 1	September 6, 2019	None Received
Washington County Commissioner-District 2	September 6, 2019	None Received
Washington County Commissioner-District 3	September 6, 2019	None Received
Washington County Council- District 1	September 6, 2019	None Received
Washington County Council- District 2	September 6, 2019	None Received
Washington County Council- District 3	September 6, 2019	None Received
Washington County Council- District 4	September 6, 2019	None Received
Pierce-Polk Townships Volunteer Fire Department	September 6, 2019	None Received
Natural Resources Conservation Service	September 6, 2019 and	December 30, 2019
	December 20, 2019	
United States Army Corps of Engineers	September 6, 2019	None Received
Indiana Geological Survey	September 6, 2019	Automatic Response
Wellhead Proximity Determinator	September 6, 2019	Automatic Response
Floodway Administrator	March 4, 2020	March 6, 2020
		(telephone)

### **APPENDICES**

APPENDIX A: INDOT Supporting Documentation	
Threshold Chart	A-1
ADDENDIV D. Cyonhias	
APPENDIX B: Graphics     Location Map	D 1
USGS Topographic Map	
2015 Aerial Photograph	
Photograph Location Map	
<ul><li>Site Photographs</li><li>Bridge Plans</li></ul>	
APPENDIX C: Early Coordination	
Sample Early Coordination letter; September 6. 2019	
• IDNR-DFW response; October 3, 2019	
<ul> <li>IDEM Proposed Roadway Construction Projects Letter; Signed September 9, 2019</li> </ul>	
IGS response; September 6, 2019	
USFWS official species list; December 11, 2019	
USFWS Concurrence Verification Letter; December 11, 2019	
Letter to New Pekin Utilities; July 11, 2019	
NRCS response; December 30, 2019	C-41
APPENDIX D: Section 106 of the National Historic Preservation Act	
Minor Projects PA Project Assessment Form; September 25, 2019	D-1
- 14mor 110feets 171110feet 7155essment 1 6rm, 5eptember 25, 2617	
APPENDIX E: Red Flag and Hazardous Materials	
Red Flag Investigation; Signed by INDOT SAM August 28, 2018	E-1
APPENDIX F: Water Resources	
Waters Determination Report; May 3, 2018	F-1
NRCS Soil Survey, NWI, and Floodplain Map	F-10
Sampling Points Map	F-11
Wetland Determination Data Forms	
Preliminary Jurisdictional Determination Form	F-25
INDOT Waters Report Approval E-mail; November 12, 2019	
APPENDIX G: Public Involvement	
	C 1
Notice of Survey letter; October 13, 2017	G-1
APPENDIX H: Air Quality	
Amendment #18-02, FY 2018-2021 STIP	H-1
• FY 2018-2021 STIP	H-2
• FY 2020-2024 STIP	Н-3
APPENDIX I: Additional Studies	
LWCF Detailed Listing of Grants Grouped by County, Washington County	T 1
American Fact Finder Map  Calculations	1-0

# **APPENDIX A: INDOT Supporting Documentation**

### **Categorical Exclusion Level Thresholds**

	PCE	Level 1	Level 2	Level 3	Level 4 <sup>1</sup>
Section 106	Falls within guidelines of Minor Projects PA	"No Historic Properties Affected"	"No Adverse Effect"	-	"Adverse Effect" Or Historic Bridge involvement <sup>2</sup>
Stream Impacts	No construction in waterways or water bodies	< 300 linear feet of stream impacts	≥ 300 linear feet of stream impacts	-	Individual 404 Permit
Wetland Impacts	No adverse impacts to wetlands	< 0.1 acre	-	< 1 acre	≥ 1 acre
Right-of-way <sup>3</sup>	Property acquisition for preservation only or none	< 0.5 acre	≥ 0.5 acre	-	-
Relocations	None None	-	-	< 5	≥ 5
Threatened/Endangered Species (Species Specific Programmatic for Indiana bat & northern long eared bat)	"No Effect", "Not likely to Adversely Affect" (Without AMMs <sup>4</sup> or with AMMs required for all projects <sup>5</sup> )	"Not likely to Adversely Affect" (With any other AMMs)	-	"Likely to Adversely Affect"	Project does not fall under Species Specific Programmatic
Threatened/Endangered Species (Any other species)	Falls within guidelines of USFWS 2013 Interim Policy	"No Effect", ""Not likely to Adversely Affect"	-	-	"Likely to Adversely Affect"
Environmental Justice	No disproportionately high and adverse impacts	-	-	-	Potential <sup>6</sup>
Sole Source Aquifer	Detailed Assessment Not Required	-	-	-	Detailed Assessment
Floodplain	No Substantial Impacts	-	-	-	Substantial Impacts
Coastal Zone Consistency	Consistent	-	-	-	Not Consistent
National Wild and Scenic	Not Present	-	-	-	Present
River New Alignment	None				Ansy
Section 4(f) Impacts	None	-	-	<u> </u>	Any Any
Section 6(f) Impacts	None	-	-	-	Any
Added Through Lane	None	_	-	_	Any
Permanent Traffic Alteration	None	-	-	-	Any
Coast Guard Permit	None	-	-	-	Any
Noise Analysis Required	No	-	-	-	Yes
Air Quality Analysis Required	No	=	-	-	Yes <sup>7</sup>
Approval Level	Concurrence by INDOT District				
• District Env. Supervisor	Environmental or	Yes	Yes	Yes	Yes
<ul> <li>Env. Services Division</li> </ul>	Environmental			Yes	Yes
• FHWA	Services				Yes

<sup>&</sup>lt;sup>1</sup>Coordinate with INDOT Environmental Services. INDOT will then coordinate with the appropriate FHWA Environmental Specialist.

<sup>&</sup>lt;sup>2</sup>Any involvement with a bridge processed under the Historic Bridge Programmatic Agreement.

<sup>&</sup>lt;sup>3</sup>Permanent and/or temporary right-of-way.


<sup>&</sup>lt;sup>4</sup>AMMs = Avoidance and Mitigation Measures.

<sup>&</sup>lt;sup>5</sup>AMMs determined by the IPAC decision key to be needed that are listed in the USFWS *User's Guide for the Range-wide Programmatic Consultation* for Indiana bat and Northern long-eared bat as "required for all projects". Potential for causing a disproportionately high and adverse impact.

<sup>&</sup>lt;sup>7</sup>Hot Spot Analysis and/or MSAT Quantitative Emission Analysis.


<sup>\*</sup>Substantial public or agency controversy may require a higher-level NEPA document.

# **APPENDIX B: Graphics**



Location Map
Bridge Replacement
SR 60 over South Fork Blue River,
Approximately 0.42 mile West of SR 335
Pierce Township, Washington County, Indiana
Des. No. 1700173
Metric Project No. 18-0022-3


All locations approximate




USGS Topographic Map
Bridge Replacement
SR 60 over South Fork Blue River,
~Approximately 0.42 mile West of SR 335
Pierce Township, Washington County, Indiana
Des. No. 1700173
Metric Project No. 18-0022-3

Note: All locations are approximate
Base map:
2010 Palmyra, IN and
2010 Salem, IN
7.5 Minute Quadrangle






F. IZU 10/10-00ZE - ПИТВ - MFF T/ T/ THI HUIT - UIT-CAIINH - DBII/YER ADIBS/NAPU/16/1886 2 - ON 09 0781 GOUIT FUIN UI HIB DIBE MYBI/EXHIDIS/EC/EQ 12 사람이 아니는 이 10 전에 되었다.




2015 Aerial Photograph
Bridge Replacement
SR 60 over South Fork Blue River,
Approximately 0.42 mile West of SR 335
Pierce Township, Washington County, Indiana
Des. No. 1700173
Metric Project No. 18-0022-3

Note: All locations are approximate

B-3





Stream

Culvert Opening

Sampling Points (SP)


- Roadside Ditch (RSD)

- - Culvert

Photograph Location Map SR 60 over South Fork Blue River Bridge Project Pierce Township, Washington County, Indiana Des. No. 1700173

Metric Project No. 18-0022-3 Map Date: 8/5/2019 Map Author: Zachary Root All locations approximate

Source: Indiana Spatial Data Portal (2016)





Exh. 5



1. View of S.R. 60 Right-of-Way (ROW), from the project study limits (PSL), looking southeast.



3. View of drain, looking southeast.



2. View of S.R. 60 ROW from the PSL, looking southeast.



4. View of S.R. 60 ROW, looking north.



SR 60 over South Fork Blue River

Pierce Township, Washington County, Indiana Des. No. 1700173 Bridge Project



5. View of S.R. 60 ROW and RSD 1, looking southeast.



7. View of RSD 1, looking southeast.



6. View of RSD 1, looking northwest.



8. View from Culvert 1, looking southeast.



SITE PHOTOGRAPHS—8/7/2019 SR 60 over South Fork Blue River

Bridge Project Pierce Township, Washington County, Indiana Des. No. 1700173




9. View of Culvert 1, looking northwest.



 $11. \ \ View\ of\ South\ Fork\ of\ the\ Blue\ River,\ looking\ southwest (downstream).$ 



 $10. \ \mbox{View}$  of northern bank of South Fork of the Blue River, looking southwest.



 $12. \ \mbox{\sc View}$  of southern bank South Fork of the Blue River, looking southwest .

# SITE PHOTOGRAPHS—8/7/2019

SR 60 over South Fork Blue River Bridge Project Pierce Township, Washington County, Indiana Des. No. 1700173

METAIC



13. View of South Fork of Blue River from the PSL, looking northeast (upstream).



15. View of RSD 2, looking northwest.



14. View of South Fork of the Blue River and RSD 2, looking northeast.



16. View of RSD 2, looking southeast.



SITE PHOTOGRAPHS—8/7/2019 SR 60 over South Fork Blue River

Bridge Project

Pierce Township, Washington County, Indiana Des. No. 1700173



17. View of RSD 2, looking southeast.



19. View of S.R. 60 ROW, looking northeast.



18. View of S.R. 60 ROW and RSD 2, looking northwest.



20. View of S.R. 60 ROW, looking southeast.



SITE PHOTOGRAPHS—8/7/2019 SR 60 over South Fork Blue River

Bridge Project Pierce Township, Washington County, Indiana Des. No. 1700173



21. View of S.R. 60 ROW, looking north.



23. View of S.R. 60 ROW from the PSL, looking northwest.



22. View of S.R. 60 ROW, looking northeast.



24. View of S.R. 60 ROW from the PSL, looking northwest.



Bridge Project
Pierce Township, Washington County, Indiana
Des. No. 1700173

METAIC



25. View of S.R. 60 ROW, looking south.



27. View of the south bank of South Fork Blue River, looking east.



26. View of S.R. 60 ROW, looking northwest.



28. View of South Fork of Blue River, looking northeast (upstream).



SITE PHOTOGRAPHS—8/7/2019 SR 60 over South Fork Blue River



29. View of the north bank of South Fork of Blue River, looking northeast.



 $31.\ \mbox{View}$  of the south bank of South Fork of Blue River, looking south.



30. View of South Fork of Blue River from PSL, looking southwest (downstream).



32. View of South Fork of Blue River, looking southwest (downstream).



SR 60 over South Fork Blue River

Bridge Project

Pierce Township, Washington County, Indiana Des. No. 1700173





33. View of the north bank of South Fork of Blue River, looking west.



35. View of the South Fork of Blue River, looking northeast (upstream).



34. View of the north bank of the South Fork of Blue River, looking north.



36. View of the south bank of the South Fork of Blue River, looking east.



SR 60 over South Fork Blue River Bridge Project

Pierce Township, Washington County, Indiana Des. No. 1700173





37. View of S.R. 60 ROW, looking southeast.



39. View of SP-1, soil profile.



38. View of S.R. 60 ROW, looking northwest.



40. View of SP-1, looking north.



SITE PHOTOGRAPHS—8/7/2019 SR 60 over South Fork Blue River




41. View of SP-1, looking southeast.



43. View of SP-2, looking northwest.



42. View of SP-2, soil profile.



44. View of SP-2, looking southeast.





45. View of SP-3, soil profile.



47. View of SP-3, looking northwest.




46. View of SP-3, looking southwest.



48. View of SP-4, soil profile.



SITE PHOTOGRAPHS—8/7/2019 SR 60 over South Fork Blue River



49. View of SP-4, looking southeast.



51. View of SP-5, soil profile.



50. View of SP-4, looking northeast.



52. View of SP-5, looking southeast.








53. View of SP-5, looking southwest.


SITE PHOTOGRAPHS—8/7/2019
SR 60 over South Fork Blue River
Bridge Project
Pierce Township, Washington County, Indiana
Des. No. 1700173


STRUCTURE	TYPE	SPAN AND SKEW	OVER
060-88-10268	CONTINUOUS PRESTRESSED CONCRETE 36X49 BULB-TEE BEAM	3 SPANS: 58'-0", 75'-0", 58'-0" SKEW: 15°00'00" RT.	SOUTH FORK BLUE RIVER


	KIN PROJECT INFORMATION	
DESIGNATION	DESCRIPTION	
1700173	SR 60 OVER SOUTH FORK BLUE RIVER LEAD DES	S
1701449	SR 60 OVER MONEYS BRANCH	


		EXISTING GROUND (TYP.) -
		30'-0" CLEAR ZC











# **APPENDIX C:** Early Coordination



September 6, 2019

Sample Early Coordination Letter

{See Attached List}

Re: Des. No.: 1700173, Bridge Project over South Fork of Blue River on SR 60, 0.42 Mile West of SR 335, Washington County.

Dear Agency:

The Indiana Department of Transportation (INDOT) and Federal Highway Administration (FHWA) intends to proceed with a project involving the aforementioned bridge project in Washington County. This letter is part of the early coordination phase of the environmental review process. We are requesting comments from your area of expertise regarding any possible environmental effects associated with this project. **Please use the above designation number and description in your reply**. We will incorporate your comments into a study of the project's environmental impacts.

This project is located on SR 60, over South Fork of Blue River, approximately 0.42 mile west of SR 335 at reference post (RP) 42+62, in Washington County, Indiana. This section of SR 60 is classified as a Rural Principal Arterial. A typical cross section of SR 60 consists of one 12 feet wide through-lane adjoined by 2 feet wide asphalt shoulder provided in each direction. Two feet wide sidewalk and curb are provided along both sides of the bridge. The posted speed limit on SR 60 is 45 mph.

The existing structure (No. 060-88-03069, NBI No. 021480) is a three-span (50'-0", 50'-0", 50'-0") concrete arch bridge, with a structure length of 193 feet and a clear roadway width of 28 feet. The structure was constructed in 1937. There have been no known rehabilitations. The need for this project is evidenced by the deteriorating condition of the existing structure. In the most recent Bridge Inspection Report, dated July 2, 2019, INDOT noted cracking in the copings. The superstructure exhibited minor cracking in the parapet walls, and cracking, delamination, and spalling with exposed rebar in the sidewalk underside. The substructure exhibited some cracking and scaling with efflorescence on the pier caps and stems. The structure was given a sufficiency rating of 59 out of 100 possible points.

The preferred alternative is to replace the existing bridge. The proposed replacement structure will be three-spans (58′-0″, 75′-0″, 58′-0″) with a structure length of 191 feet, a clear roadway width of 32 feet, and skewed 15 degrees left. The approach roadway will have guardrails and concrete bridge railing transition. It is believed that up to 2 acres of right-of-way may be required for this project; however, the exact amount and locations have not been determined. Channel clearing will be required. SR 60 will be shifted approximately 18 feet upstream (east) from the existing alignment to accommodate maintenance of traffic. A single lane of traffic will be maintained during construction utilizing a temporary signal. Access will likely be restricted to SR 60 from John Street, Grove Street, and Poplar Street. The entrance to Sunoco from SR 60 will likely be closed, but the entrance from John Street will be maintained.

Land use in the vicinity of the project is a mix of residential, commercial, and agricultural. There is an underground telephone line running parallel to SR 60 on the east side of the roadway. There is an underground water line running parallel to SR 60 on the west side of the roadway. There are underground fiber optic and stormwater lines in the northeast quadrant of the project. There is a sanitary sewer line in the southwest quadrant of the project. Utility Coordination is being conducted by the HNTB Corporation.

Metric Environmental, LLC (Metric) will perform waters and wetlands determinations to identify any ecological resources that may be present. This project qualifies for the application of the USFWS range-wide programmatic

informal consultation for the Indiana bat and northern long-eared bat and project information will be submitted through USFW's Information for Planning and Consultation (IPaC) separately. This project appears to fall under Category B-10 (erosion control measures in undisturbed areas) and Category B-12 (bridge replacement) of the Programmatic Agreement (PA) among the Federal Highway Administration (FHWA), the INDOT, the Advisory Council on Historic Preservation (ACHP), and the Indiana State Historic Preservation Officer (Indiana SHPO) regarding the implementation of the Federal Aid Highway Program in the State of Indiana (MPPA). Metric will coordinate with the INDOT Cultural Resources Office (CRO) and Indiana SHPO for review and concurrence.

Should we not receive your response within thirty (30) calendar days from the date of this letter, it will be assumed that your agency believes that there will be no adverse effects incurred as a result of the proposed project. However, should you find that an extension to the response time is necessary, a reasonable amount may be granted upon request. If you have any questions regarding this matter, please contact Irish L. Jones, Environmental Scientist, Metric Environmental, LLC at 317.608.2740, Irishj@MetricEnv.com, or 6971 Hillsdale Court, Indianapolis, Indiana 46250 or Brad Williamson, Project Manager, INDOT Seymour District, at Bwilliamson@indot.in.gov or 812.524.3971. Thank you in advance for your input.

Sincerely,

Irish L. Jones Environmental Scientist

Metric Environmental, LLC

cc: File No. 18-0022-3

Angela Pearl, PE, Apearl@HNTB.com, HNTB Corporation
Brad Williamson, Project Manager, Bwilliamson@indot.in.gov INDOT Seymour District

Attachments: Location Map, USGS Topographic Map, 2015 Aerial Photograph, NRCS Soils Map, NRCS Soils Map Legend, National Wetlands Inventory Map, Flood Insurance Rate Map

The Attachments were intentionally omitted. Please refer to Appendix B and Appendix F in the CE document.



## The following agencies received Early Coordination Letters:

Field Supervisor
U.S. Fish and Wildlife Service
Bloomington Indiana Field Office
{robin mcwilliams@fws.gov}

Federal Highway Administration {Michelle.Allen@dot.gov} {Erica.Tait@dot.gov}

Indiana Department of Transportation Office of Public Involvement {rclark@indot.in.gov} {mwright@indot.in.gov}

United States Department of Housing and Urban Development {Paul.J.Lehmann@hud.gov}

INDOT Seymour District

{<u>Ddye@indot.in.gov}</u> {<u>Bwilliamson@indot.in.gov}</u>

Office of Utilities and Railroads {mjett@indot.in.gov}

Ecology and Waterway Permitting Office {ilandry@indot.in.gov}

National Parks Service Midwest Regional Office {Hector\_Santiago@nps.gov}

Indiana Department of Natural Resources Division of Fish and Wildlife {environmentalreview@dnr.in.gov}

Indiana Department of Environmental Management
Proposed Roadway Construction Projects {http://www.in.gov/idem/5284.htm}

Washington County— Surveyor Diana Green {digreen@washingtoncounty.in.gov}

Washington County Highway Department {rvoyles@co.Washington.in.us}

Washington County Commissioners
Phillip Marshall – President (District 1)
{dlcomm@washingtoncounty.in.gov}
Todd Ewen (District 2)
{d2comm@washingtoncounty.in.gov}
Rick Roberts (District 3)
{d3comm@washingtoncounty.in.gov}

Washington County Council
Ben Bowling
{dlcouncil@ washingtoncounty.in.gov}
John Revels
{d2council@ washingtoncounty.in.gov}
Preston Shell
{d3council@ washingtoncounty.in.gov}
Karen Wischmeler

{d4council@ washingtoncounty.in.gov}

Pierce-Polk Townships Volunteer Fire Department

Natural Resources Conservation Service {Rick.Neilson@in.usda.gov}

{piercepolk@mymail.coop}

United States Army Corps of Engineers {Gregory.A.McKay@usace.army.mil}

Indiana Geological Survey {https://igs.indiana.edu/eAssessment/}

Wellhead Proximity Determinator {www.in.gov/idem/cleanwater/pages/wellhead}

# State of Indiana DEPARTMENT OF NATURAL RESOURCES Division of Fish and Wildlife

## Early Coordination/Environmental Assessment

DNR #:

ER-21806

Request Received: September 6, 2019

Requestor:

Metric Environmental Irish L Jones 6971 Hillsdale Court

Indianapolis, IN 46250

Project:

SR 60 bridge (#060-88-03069) replacement over South Fork Blue River, about 0.42

mile west of SR 335 at RP 42+62; Des #1700173

County/Site info:

Washington

The Indiana Department of Natural Resources has reviewed the above referenced project per your request. Our agency offers the following comments for your information and in accordance with the National Environmental Policy Act of 1969.

If our agency has regulatory jurisdiction over the project, the recommendations contained in this letter may become requirements of any permit issued. If we do not have permitting authority, all recommendations are voluntary.

**Regulatory Assessment:** 

This proposal will require the formal approval of our agency for construction in a floodway pursuant to the Flood Control Act (IC 14-28-1), unless it qualifies for a bridge exemption (see enclosure). Please include a copy of this letter with the permit application if the project does not meet the bridge exemption criteria.

Natural Heritage Database:

The Natural Heritage Program's data have been checked.

To date, no plant or animal species listed as state or federally threatened, endangered,

or rare have been reported to occur in the project vicinity.

Fish & Wildlife Comments:

Avoid and minimize impacts to fish, wildlife, and botanical resources to the greatest extent possible, and compensate for impacts. The following are recommendations that address potential impacts identified in the proposed project area:

1) Bank Stabilization & Wildlife Passage:

The new, replacement, or rehabbed structure, and any bank stabilization under the structure, should not create conditions that are less favorable for wildlife passage under the structure compared to current conditions. A level area of natural ground under the structure is ideal for wildlife passage. If channel clearing will result in a flat bench area above the normal water level under the structure, this area should allow wildlife passage and should remain free of riprap and other similar materials that can impair wildlife passage.

Minimize the use of riprap and use alternative erosion protection materials whenever possible. Riprap must not be placed in the active thalweg channel or placed in the streambed in a manner that precludes fish or aquatic organism passage (riprap must not be placed above the existing streambed elevation). Where riprap must be used, we recommend placing only enough riprap to provide stream bank toe protection, such as from the toe of the bank up to the ordinary high water mark (OHWM). The banks above the OHWM must be restored, stabilized, and revegetated using geotextiles and a mixture of grasses, sedges, wildflowers, shrubs, and trees native to the area and specifically for stream bank/floodway stabilization purposes as soon as possible upon completion.

While hard armoring alone (e.g. riprap or glacial stone) may be needed in certain instances, soft armoring and bioengineering techniques should be considered first. In

Attachments:

A - Bridge Exemption Criteria

## State of Indiana DEPARTMENT OF NATURAL RESOURCES Division of Fish and Wildlife

## Early Coordination/Environmental Assessment

many instances, one or more methods are necessary to increase the likelihood of vegetation establishment. Combining vegetation with most bank stabilization methods can provide additional bank protection and help reduce impacts upon fish and wildlife. If hard armoring is needed, wildlife passage can be facilitated by using a smooth-surfaced armoring material instead of riprap, such as articulated concrete block mats, fabric-formed concrete mats, or other similar smooth-surfaced material.

Information about bioengineering techniques can be found at http://www.in.gov/legislative/iac/20120404-IR-312120154NRA.xml.pdf. Also, the following is a USDA/NRCS document that outlines many different bioengineering techniques for streambank stabilization: http://directives.sc.egov.usda.gov/17553.wba.

#### 2) Riparian Habitat:

We recommend a mitigation plan be developed (and submitted with the permit application, if required) for any unavoidable habitat impacts that will occur. The DNR's Floodway Habitat Mitigation guidelines (and plant lists) can be found online at: http://www.in.gov/legislative/iac/20190130-IR-312190041NRA.xml.pdf.

Impacts to non-wetland forest of one (1) acre or more should be mitigated at a minimum 2:1 ratio. If less than one acre of non-wetland forest is removed in a rural setting, replacement should be at a 1:1 ratio based on area. Impacts to non-wetland forest under one (1) acre in an urban setting should be mitigated by planting five trees, at least 2 inches in diameter-at-breast height (dbh), for each tree which is removed that is 10" dbh or greater (5:1 mitigation based on the number of large trees).

The mitigation site should be located in the floodway, downstream of the one (1) square mile drainage area of that stream (or another stream within the 8-digit HUC, preferably as close to the impact site as possible) and adjacent to existing forested riparian habitat.

The additional measures listed below should be implemented to avoid, minimize, or compensate for impacts to fish, wildlife, and botanical resources:

- 1. Revegetate all bare and disturbed areas in the floodway with a mixture of native grasses, sedges, wildflowers, and also native hardwood trees and shrubs if any woody plants are disturbed during construction as soon as possible upon completion. Do not use any varieties of Tall Fescue or other non-native plants, including prohibited invasive species (see 312 IAC 18-3-25).
- Minimize and contain within the project limits inchannel disturbance and the clearing of trees and brush.
- 3. Do not work in the waterway from April 1 through June 30 without the prior written approval of the Division of Fish and Wildlife.
- 4. Do not cut any trees suitable for Indiana bat or Northern Long-eared bat roosting (greater than 5 inches dbh, living or dead, with loose hanging bark, or with cracks, crevices, or cavities) from April 1 through September 30.
- 5. Do not excavate in the low flow area except for the placement of piers, foundations, and riprap, or removal of the old structure.
- 6. Do not construct any temporary runarounds/access bridges, causeways, cofferdams, diversions, or pumparounds.
- 7. Use minimum average 6 inch graded riprap stone extended below the normal water level to provide habitat for aquatic organisms in the voids.
- 8. Plant native hardwood trees along the top of the bank and right-of-way to replace the vegetation destroyed during construction.
- 9. Post "Do Not Mow or Spray" signs along the right-of-way.
- 10. Appropriately designed measures for controlling erosion and sediment must be implemented to prevent sediment from entering the stream or leaving the construction site; maintain these measures until construction is complete and all disturbed areas are

Attachments:

A - Bridge Exemption Criteria

# State of Indiana DEPARTMENT OF NATURAL RESOURCES Division of Fish and Wildlife

## Early Coordination/Environmental Assessment

stabilized.

11. Seed and protect all disturbed streambanks and slopes not protected by other methods that are 3:1 or steeper with erosion control blankets that are heavy-duty, biodegradable, and net free or that use loose-woven / Leno-woven netting to minimize the entrapment and snaring of small-bodied wildlife such as snakes and turtles (follow manufacturer's recommendations for selection and installation); seed and apply mulch on all other disturbed areas.

### **Contact Staff:**

Christie L. Stanifer, Environ. Coordinator, Fish & Wildlife Our agency appreciates this opportunity to be of service. Please contact the above staff member at (317) 232-4080 if we can be of further assistance.

Date: October 3, 2019

Christie L. Stanifer Environ. Coordinator

Division of Fish and Wildlife



## Indiana Department of Environmental Management

We Protect Hoosiers and Our Environment.

100 North Senate Avenue - Indianapolis, IN 46204 (800) 451-6027 - (317) 232-8603 - www.idem.IN.gov

INDOT Seymour District Brad Williamson 185 Agrico Lane Seymour , IN 47274 Date Metric Environmental Irish L Jones 6971 Hillsdale Ct. Indianapolis, IN 4625

To Engineers and Consultants Proposing Roadway Construction Projects:

RE: The existing structure (No. 060-88-03069, NBI No. 021480) is a three-span (50'-0", 50'-0", 50'-0") concrete arch bridge, with a structure length of 193 feet and a clear roadway width of 28 feet. The superstructure exhibited minor cracking in the parapet walls, and cracking, delamination, and spalling with exposed rebar in the sidewalk underside. The substructure exhibited some cracking and scaling with efflorescence on the pier caps and stems. The preferred alternative is to replace the existing bridge. The proposed replacement structure will be three-spans (58'-0", 75'-0", 58'-0") with a structure length of 191 feet, a clear roadway width of 32 feet, and skewed 15 degrees left. The approach roadway will have guardrails and concrete bridge railing transition. It is believed that up to 2 acres of right-ofway may be required for this project; however, the exact amount and locations have not been determined. Channel clearing will be required. SR 60 will be shifted approximately 18 feet upstream (east) from the existing alignment to accommodate maintenance of traffic.

This letter from the Indiana Department of Environmental Management (IDEM) serves as a standardized response to enquiries inviting IDEM comments on roadway construction, reconstruction, or other improvement projects within existing roadway corridors when the proposed scope of the project is beneath the threshold requiring a formal National Environmental Policy Act-mandated Environmental Assessment or Environmental Impact Statement. As the letter attempts to address all roadway-related environmental topics of potential concern, it is possible that not every topic addressed in the letter will be applicable to your particular roadway project.

For additional information on specific roadway-related topics of interest, please visit the appropriate Web pages cited below, many of which provide contact information for persons within the various program areas who can answer questions not fully addressed in this letter. Also please be mindful that some environmental requirements may be subject to change and so each person intending to include a copy of this letter in their project documentation packet is advised to download the most recently revised version of the letter; found at: http://www.in.gov/idem/5283.htm (http://www.in.gov/idem/5283.htm).

To ensure that all environmentally-related issues are adequately addressed, IDEM recommends that you read this letter in its entirety, and consider each of the following issues as you move forward with the planning of your proposed roadway construction, reconstruction, or improvement project:

## WATER AND BIOTIC QUALITY

1. Section 404 of the Clean Water Act requires that you obtain a permit from the U.S. Army Corps of Engineers (USACE) before discharging dredged or fill materials into any wetlands or other waters, such as rivers,

lakes, streams, and ditches. Other activities regulated include the relocation, channelization, widening, or other such alteration of a stream, and the mechanical clearing (use of heavy construction equipment) of wetlands. Thus, as a project owner or sponsor, it is your responsibility to ensure that no wetlands are disturbed without the proper permit. Although you may initially refer to the U.S. Fish and Wildlife Service National Wetland Inventory maps as a means of identifying potential areas of concern, please be mindful that those maps do not depict jurisdictional wetlands regulated by the USACE or the Department of Environmental Management. A valid jurisdictional wetlands determination can only be made by the USACE, using the 1987 Wetland Delineation Manual.

USACE recommends that you have a consultant check to determine whether your project will abut, or lie within, a wetland area. To view a list of consultants that have requested to be included on a list posted by the USACE on their Web site, see USACE Permits and Public Notices (http://www.lrl.usace.army.mil/orf/default.asp) (http://www.lrl.usace.army.mil/orf/default.asp) (http://www.lrl.usace.army.mil/orf/default.asp)) and then click on "Information" from the menu on the right-hand side of that page. Their "Consultant List" is the fourth entry down on the "Information" page. Please note that the USACE posts all consultants that request to appear on the list, and that inclusion of any particular consultant on the list does not represent an endorsement of that consultant by the USACE, or by IDEM.

Much of northern Indiana (Newton, Lake, Porter, LaPorte, St. Joseph, Elkhart, LaGrange, Steuben, and Dekalb counties; large portions of Jasper, Starke, Marshall, Noble, Allen, and Adams counties; and lesser portions of Benton, White, Pulaski, Kosciusko, and Wells counties) is served by the USACE District Office in Detroit (313-226-6812). The central and southern portions of the state (large portions of Benton, White, Pulaski, Kosciosko, and Wells counties; smaller portions of Jasper, Starke, Marshall, Noble, Allen, and Adams counties; and all other Indiana counties located in north-central, central, and southern Indiana) are served by the USACE Louisville District Office (502-315-6733).

Additional information on contacting these U.S. Army Corps of Engineers (USACE) District Offices, government agencies with jurisdiction over wetlands, and other water quality issues, can be found at http://www.in.gov/idem/4396.htm (http://www.in.gov/idem/4396.htm). IDEM recommends that impacts to wetlands and other water resources be avoided to the fullest extent.

- 2. In the event a Section 404 wetlands permit is required from the USACE, you also must obtain a Section 401 Water Quality Certification from the IDEM Office of Water Quality Wetlands Program. To learn more about the Wetlands Program, visit: http://www.in.gov/idem/4384.htm (http://www.in.gov/idem/4384.htm).
- 3. If the USACE determines that a wetland or other water body is isolated and not subject to Clean Water Act regulation, it is still regulated by the state of Indiana. A State Isolated Wetland permit from IDEM's Office of Water Quality (OWQ) is required for any activity that results in the discharge of dredged or fill materials into isolated wetlands. To learn more about isolated wetlands, contact the OWQ Wetlands Program at 317-233-8488.
- 4. If your project will involve over a 0.5 acre of wetland impact, stream relocation, or other large-scale alterations to water bodies such as the creation of a dam or a water diversion, you should seek additional input from the OWQ Wetlands Program staff. Consult the Web at: http://www.in.gov/idem/4384.htm (http://www.in.gov/idem/4384.htm) for the appropriate staff contact to further discuss your project.
- 5. Work within the one-hundred year floodway of a given water body is regulated by the Department of Natural Resources, Division of Water. The Division issues permits for activities regulated under the follow statutes:
  - IC 14-26-2 Lakes Preservation Act 312 IAC 11
  - IC 14-26-5 Lowering of Ten Acre Lakes Act No related code

- IC 14-28-1 Flood Control Act 310 IAC 6-1
- IC 14-29-1 Navigable Waterways Act 312 IAC 6
- o IC 14-29-3 Sand and Gravel Permits Act 312 IAC 6
- IC 14-29-4 Construction of Channels Act No related code

For information on these Indiana (statutory) Code and Indiana Administrative Code citations, see the DNR Web site at: http://www.in.gov/dnr/water/9451.htm (http://www.in.gov/dnr/water/9451.htm) . Contact the DNR Division of Water at 317-232-4160 for further information.

The physical disturbance of the stream and riparian vegetation, especially large trees overhanging any affected water bodies should be limited to only that which is absolutely necessary to complete the project. The shade provided by the large overhanging trees helps maintain proper stream temperatures and dissolved oxygen for aquatic life.

- 6. For projects involving construction activity (which includes clearing, grading, excavation and other land disturbing activities) that result in the disturbance of one (1), or more, acres of total land area, contact the Office of Water Quality Watershed Planning Branch (317/233-1864) regarding the need for of a Rule 5 Storm Water Runoff Permit. Visit the following Web page
  - http://www.in.gov/idem/4902.htm (http://www.in.gov/idem/4902.htm)

To obtain, and operate under, a Rule 5 permit you will first need to develop a Construction Plan (http://www.in.gov/idem/4917.htm#constreq (http://www.in.gov/idem/4917.htm#constreq)), and as described in 327 IAC 15-5-6.5 (http://www.in.gov/legislative/iac/T03270/A00150 [PDF] (http://www.in.gov/legislative/iac/T03270/A00150.PDF), pages 16 through 19). Before you may apply for a Rule 5 Permit, or begin construction, you must submit your Construction Plan to your county Soil and Water Conservation District (SWCD) (http://www.in.gov/isda/soil/contacts/map.html (http://www.in.gov/isda/soil/contacts/map.html)).

Upon receipt of the construction plan, personnel of the SWCD or the Indiana Department of Environmental Management will review the plan to determine if it meets the requirements of 327 IAC 15-5. Plans that are deemed deficient will require re-submittal. If the plan is sufficient you will be notified and instructed to submit the verification to IDEM as part of the Rule 5 Notice of Intent (NOI) submittal. Once construction begins, staff of the SWCD or Indiana Department of Environmental Management will perform inspections of activities at the site for compliance with the regulation.

Please be mindful that approximately 149 Municipal Separate Storm Sewer System (MS4) areas are now being established by various local governmental entities throughout the state as part of the implementation of Phase II federal storm water requirements. All of these MS4 areas will eventually take responsibility for Construction Plan review, inspection, and enforcement. As these MS4 areas obtain program approval from IDEM, they will be added to a list of MS4 areas posted on the IDEM Website at: http://www.in.gov/idem/4900.htm (http://www.in.gov/idem/4900.htm).

If your project is located in an IDEM-approved MS4 area, please contact the local MS4 program about meeting their storm water requirements. Once the MS4 approves the plan, the NOI can be submitted to IDEM.

Regardless of the size of your project, or which agency you work with to meet storm water requirements, IDEM recommends that appropriate structures and techniques be utilized both during the construction phase, and after completion of the project, to minimize the impacts associated with storm water runoff. The use of appropriate planning and site development and appropriate storm water quality measures are recommended to prevent soil from leaving the construction site during active land disturbance and for post

construction water quality concerns. Information and assistance regarding storm water related to construction activities are available from the Soil and Water Conservation District (SWCD) offices in each county or from IDEM.

- 7. For projects involving impacts to fish and botanical resources, contact the Department of Natural Resources Division of Fish and Wildlife (317/232-4080) for addition project input.
- 8. For projects involving water main construction, water main extensions, and new public water supplies, contact the Office of Water Quality Drinking Water Branch (317-308-3299) regarding the need for permits.
- 9. For projects involving effluent discharges to waters of the State of Indiana, contact the Office of Water Quality Permits Branch (317-233-0468) regarding the need for a National Pollutant Discharge Elimination System (NPDES) permit.
- For projects involving the construction of wastewater facilities and sewer lines, contact the Office of Water Quality - Permits Branch (317-232-8675) regarding the need for permits.

## **AIR QUALITY**

The above-noted project should be designed to minimize any impact on ambient air quality in, or near, the project area. The project must comply with all federal and state air pollution regulations. Consideration should be given to the following:

1. Regarding open burning, and disposing of organic debris generated by land clearing activities; some types of open burning are allowed (http://www.in.gov/idem/4148.htm (http://www.in.gov/idem/4148.htm)) under specific conditions. You also can seek an open burning variance from IDEM.

However, IDEM generally recommends that you take vegetative wastes to a registered yard waste composting facility or that the waste be chipped or shredded with composting on site (you must register with IDEM if more than 2,000 pounds is to be composted; contact 317/232-0066). The finished compost can then be used as a mulch or soil amendment. You also may bury any vegetative wastes (such as leaves, twigs, branches, limbs, tree trunks and stumps) onsite, although burying large quantities of such material can lead to subsidence problems, later on.

Reasonable precautions must be taken to minimize fugitive dust emissions from construction and demolition activities. For example, wetting the area with water, constructing wind barriers, or treating dusty areas with chemical stabilizers (such as calcium chloride or several other commercial products). Dirt tracked onto paved roads from unpaved areas should be minimized.

Additionally, if construction or demolition is conducted in a wooded area where blackbirds have roosted or abandoned buildings or building sections in which pigeons or bats have roosted for 3-5 years precautionary measures should be taken to avoid an outbreak of histoplasmosis. This disease is caused by the fungus Histoplasma capsulatum, which stems from bird or bat droppings that have accumulated in one area for 3-5 years. The spores from this fungus become airborne when the area is disturbed and can cause infections over an entire community downwind of the site. The area should be wetted down prior to cleanup or demolition of the project site. For more detailed information on histoplasmosis prevention and control, please contact the Acute Disease Control Division of the Indiana State Department of Health at (317) 233-7272.

2. The U.S. EPA and the Surgeon General recommend that people not have long-term exposure to radon at levels above 4 pCi/L. (For a county-by-county map of predicted radon levels in Indiana, visit: http://www.in.gov/idem/4145.htm (http://www.in.gov/idem/4145.htm).)

The U.S. EPA further recommends that all homes (and apartments within three stories of ground level) be tested for radon. If in-home radon levels are determined to be 4 pCi/L, or higher, EPA recommends a follow-up test. If the second test confirms that radon levels are 4 pCi/L, or higher, EPA recommends the installation of radon-reduction measures. (For a list of qualified radon testers and radon mitigation (or reduction) specialists visit: http://www.in.gov/isdh/regsvcs/radhealth/pdfs/radon\_testers\_mitigators\_list.pdf (http://www.in.gov/isdh/regsvcs/radhealth/pdfs/radon\_testers\_mitigators\_list.pdf).) It also is recommended that radon reduction measures be built into all new homes, particularly in areas like Indiana that have moderate to high predicted radon levels.

To learn more about radon, radon risks, and ways to reduce exposure visit: http://www.in.gov/isdh/regsvcs/radhealth/radon.htm (http://www.in.gov/isdh/regsvcs/radhealth/radon.htm), http://www.in.gov/idem/4145.htm (http://www.in.gov/idem/4145.htm), or http://www.epa.gov/radon/index.html (http://www.epa.gov/radon/index.html).

3. With respect to asbestos removal: all facilities slated for renovation or demolition (except residential buildings that have (4) four or fewer dwelling units and which will not be used for commercial purposes) must be inspected by an Indiana-licensed asbestos inspector prior to the commencement of any renovation or demolition activities. If regulated asbestos-containing material (RACM) that may become airborne is found, any subsequent demolition, renovation, or asbestos removal activities must be performed in accordance with the proper notification and emission control requirements.

If no asbestos is found where a renovation activity will occur, or if the renovation involves removal of less than 260 linear feet of RACM off of pipes, less than 160 square feet of RACM off of other facility components, or less than 35 cubic feet of RACM off of all facility components, the owner or operator of the project does not need to notify IDEM before beginning the renovation activity.

For questions on asbestos demolition and renovation activities, you can also call IDEM's Lead/Asbestos section at 1-888-574-8150.

However, in all cases where a demolition activity will occur (even if no asbestos is found), the owner or operator must still notify IDEM 10 working days prior to the demolition, using the form found at http://www.in.gov/icpr/webfile/formsdiv/44593.pdf (http://www.in.gov/icpr/webfile/formsdiv/44593.pdf).

Anyone submitting a renovation/demolition notification form will be billed a notification fee based upon the amount of friable asbestos containing material to be removed or demolished. Projects that involve the removal of more than 2,600 linear feet of friable asbestos containing materials on pipes, or 1,600 square feet or 400 cubic feet of friable asbestos containing material on other facility components, will be billed a fee of \$150 per project; projects below these amounts will be billed a fee of \$50 per project. All notification remitters will be billed on a quarterly basis.

For more information about IDEM policy regarding asbestos removal and disposal, visit: http://www.in.gov/idem/4983.htm (http://www.in.gov/idem/4983.htm).

4. With respect to lead-based paint removal: IDEM encourages all efforts to minimize human exposure to lead-based paint chips and dust. IDEM is particularly concerned that young children exposed to lead can suffer from learning disabilities. Although lead-based paint abatement efforts are not mandatory, any abatement that is conducted within housing built before January 1, 1978, or a child-occupied facility is required to comply with all lead-based paint work practice standards, licensing and notification requirements. For more information about lead-based paint removal visit: http://www.in.gov/isdh/19131.htm (http://www.in.gov/isdh/19131.htm).

- 5. Ensure that asphalt paving plants are permitted and operate properly. The use of cutback asphalt, or asphalt emulsion containing more than seven percent (7%) oil distillate, is prohibited during the months April through October. See 326 IAC 8-5-2, Asphalt Paving Rule (http://www.ai.org/legislative/iac/T03260/A00080.PDF (http://www.ai.org/legislative/iac/T03260/A00080.PDF)).
- 6. If your project involves the construction of a new source of air emissions or the modification of an existing source of air emissions or air pollution control equipment, it will need to be reviewed by the IDEM Office of Air Quality (OAQ). A registration or permit may be required under 326 IAC 2 (View at: www.ai.org/legislative/iac/t03260/a00020.pdf (http://www.ai.org/legislative/iac/t03260/a00020.pdf).) New sources that use or emit hazardous air pollutants may be subject to Section 112 of the Clean Air Act and corresponding state air regulations governing hazardous air pollutants.
- 7. For more information on air permits visit: http://www.in.gov/idem/4223.htm (http://www.in.gov/idem/4223.htm), or to initiate the IDEM air permitting process, please contact the Office of Air Quality Permit Reviewer of the Day at (317) 233-0178 or OAMPROD atdem.state.in.us.

## LAND QUALITY

In order to maintain compliance with all applicable laws regarding contamination and/or proper waste disposal, IDEM recommends that:

- 1. If the site is found to contain any areas used to dispose of solid or hazardous waste, you need to contact the Office of Land Quality (OLQ)at 317-308-3103.
- 2. All solid wastes generated by the project, or removed from the project site, need to be taken to a properly permitted solid waste processing or disposal facility. For more information, visit http://www.in.gov/idem/4998.htm (http://www.in.gov/idem/4998.htm).
- 3. If any contaminated soils are discovered during this project, they may be subject to disposal as hazardous waste. Please contact the OLQ at 317-308-3103 to obtain information on proper disposal procedures.
- 4. If PCBs are found at this site, please contact the Industrial Waste Section of OLQ at 317-308-3103 for information regarding management of any PCB wastes from this site.
- 5. If there are any asbestos disposal issues related to this site, please contact the Industrial Waste Section of OLQ at 317-308-3103 for information regarding the management of asbestos wastes (Asbestos removal is addressed above, under Air Quality).
- 6. If the project involves the installation or removal of an underground storage tank, or involves contamination from an underground storage tank, you must contact the IDEM Underground Storage Tank program at 317/308-3039. See: http://www.in.gov/idem/4999.htm (http://www.in.gov/idem/4999.htm).

## FINAL REMARKS

Should you need to obtain any environmental permits in association with this proposed project, please be mindful that IC 13-15-8 requires that you notify all adjoining property owners and/or occupants within ten days your submittal of each permit application. However, if you are seeking multiple permits, you can still meet the notification requirement with a single notice if all required permit applications are submitted with the same ten day period.

Should the scope of the proposed project be expanded to the extent that a National Environmental Policy Act Environmental Assessment (EA) or Environmental Impact Statement (EIS) is required, IDEM will actively participate in any early interagency coordination review of the project.

Meanwhile, please note that this letter does not constitute a permit, license, endorsement or any other form of approval on the part of the Indiana Department of Environmental Management regarding any project for which a copy of this letter is used. Also note that is it the responsibility of the project engineer or consultant using this letter to ensure that the most current draft of this document, which is located at http://www.in.gov/idem/5284.htm (http://www.in.gov/idem/5284.htm), is used.

## Signature(s) of the Applicant

I acknowledge that the following proposed roadway project will be financed in part, or in whole, by public monies.

## **Project Description**

The existing structure (No. 060-88-03069, NBI No. 021480) is a three-span (50'-0", 50'-0", 50'-0") concrete arch bridge, with a structure length of 193 feet and a clear roadway width of 28 feet. The superstructure exhibited minor cracking in the parapet walls, and cracking, delamination, and spalling with exposed rebar in the sidewalk underside. The substructure exhibited some cracking and scaling with efflorescence on the pier caps and stems. The preferred alternative is to replace the existing bridge. The proposed replacement structure will be three-spans (58'-0", 75'-0", 58'-0") with a structure length of 191 feet, a clear roadway width of 32 feet, and skewed 15 degrees left. The approach roadway will have guardrails and concrete bridge railing transition. It is believed that up to 2 acres of right-ofway may be required for this project; however, the exact amount and locations have not been determined. Channel clearing will be required. SR 60 will be shifted approximately 18 feet upstream (east) from the existing alignment to accommodate maintenance of traffic.

With my signature, I do hereby affirm that I have read the letter from the Indiana Department of Environment that appears directly above. In addition, I understand that in order to complete that project in which I am interested, with a minimum of impact to the environment, I must consider all the issues addressed in the aforementioned letter, and further, that I must obtain any required permits.

Date: 9/9/2019

Signature of the INDOT

Project Engineer or Other Responsible Agent

Brad Williamson

Brad Williamson

Date: 9/9/2019

Signature of the

For Hire Consultant

Irish L Jones





## **Organization and Project Information**

**Project ID:** 18-0022 T3 Des. ID: 1700173

**Project Title:** Bridge Replacement Name of Organization: Metric Environmental

Requested by: Irish Jones

## **Environmental Assessment Report**

## 1. Geological Hazards:

- High liquefaction potential
- 1% Annual Chance Flood Hazard

### 2. Mineral Resources:

 Bedrock Resource: Moderate Potential Sand and Gravel Resource: Low Potential

### 3. Active or abandoned mineral resources extraction sites:

None documented in the area

\*All map layers from Indiana Map (maps.indiana.edu)

#### **DISCLAIMER:**

This document was compiled by Indiana University, Indiana Geological Survey, using data believed to be accurate; however, a degree of error is inherent in all data. This product is distributed "AS-IS" without warranties of any kind, either expressed or implied, including but not limited to warranties of suitability to a particular purpose or use. No attempt has been made in either the design or production of these data and document to define the limits or jurisdiction of any federal, state, or local government. The data used to assemble this document are intended for use only at the published scale of the source data or smaller (see the metadata links below) and are for reference purposes only. They are not to be construed as a legal document or survey instrument. A detailed on-the-ground survey and historical analysis of a single site may differ from these data and this document.


This information was furnished by Indiana Geological Survey

Address: 420 N. Walnut St., Bloomington, IN 47404

Email: IGSEnvir@indiana.edu

Phone: 812 855-7428 Date: September 06, 2019







## Metadata:

- https://maps.indiana.edu/metadata/Geology/Seismic Earthquake Liquefaction Potential.html
- https://maps.indiana.edu/metadata/Geology/Industrial Minerals Sand Gravel Resources.html
- https://maps.indiana.edu/metadata/Hydrology/Floodplains\_FIRM.html
- https://maps.indiana.edu/metadata/Geology/Bedrock Geology.html



## United States Department of the Interior

### FISH AND WILDLIFE SERVICE

Indiana Ecological Services Field Office 620 South Walker Street Bloomington, IN 47403-2121

Phone: (812) 334-4261 Fax: (812) 334-4273

http://www.fws.gov/midwest/Endangered/section7/s7process/step1.html



In Reply Refer To: December 11, 2019

Consultation Code: 03E12000-2020-SLI-0353

Event Code: 03E12000-2020-E-01803

Project Name: Des. No. 1700173, State Road (SR) 60 over South Fork Blue River, Bridge

Replacement

Subject: Updated list of threatened and endangered species that may occur in your proposed

project location, and/or may be affected by your proposed project

## To Whom It May Concern:

The attached species list identifies any federally threatened, endangered, proposed and candidate species that may occur within the boundary of your proposed project or may be affected by your proposed project. The list also includes designated critical habitat if present within your proposed project area or affected by your project. This list is provided to you as the initial step of the consultation process required under section 7(c) of the Endangered Species Act, also referred to as Section 7 Consultation.

Section 7 of the Endangered Species Act of 1973 requires that actions authorized, funded, or carried out by Federal agencies not jeopardize federally threatened or endangered species or adversely modify designated critical habitat. To fulfill this mandate, Federal agencies (or their designated non-federal representative) must consult with the Service if they determine their project "may affect" listed species or critical habitat.

Under 50 CFR 402.12(e) (the regulations that implement Section 7 of the Endangered Species Act) the accuracy of this species list should be verified after 90 days. This verification can be completed formally or informally. You may verify the list by visiting the ECOS-IPaC website <a href="http://ecos.fws.gov/ipac/">http://ecos.fws.gov/ipac/</a> at regular intervals during project planning and implementation and completing the same process you used to receive the attached list. As an alternative, you may contact this Ecological Services Field Office for updates.

Please use the species list provided and visit the U.S. Fish and Wildlife Service's Region 3 Section 7 Technical Assistance website at - <a href="http://www.fws.gov/midwest/endangered/section7/s7process/index.html">http://www.fws.gov/midwest/endangered/section7/s7process/index.html</a>. This website contains step-by-step instructions which will help you

determine if your project will have an adverse effect on listed species and will help lead you through the Section 7 process.

For all wind energy projects and projects that include installing towers that use guy wires or are over 200 feet in height, please contact this field office directly for assistance, even if no federally listed plants, animals or critical habitat are present within your proposed project or may be affected by your proposed project.

Although no longer protected under the Endangered Species Act, be aware that bald eagles are protected under the Bald and Golden Eagle Protection Act (16 U.S.C. 668 *et seq.*) and Migratory Bird Treaty Act (16 U.S.C. 703 *et seq*), as are golden eagles. Projects affecting these species may require measures to avoid harming eagles or may require a permit. If your project is near an eagle nest or winter roost area, see our Eagle Permits website at <a href="http://www.fws.gov/midwest/midwestbird/EaglePermits/index.html">http://www.fws.gov/midwest/midwestbird/EaglePermits/index.html</a> to help you determine if you can avoid impacting eagles or if a permit may be necessary.

We appreciate your concern for threatened and endangered species. Please include the Consultation Tracking Number in the header of this letter with any request for consultation or correspondence about your project that you submit to our office.

### Attachment(s):

Official Species List

## **Official Species List**

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

**Indiana Ecological Services Field Office** 620 South Walker Street Bloomington, IN 47403-2121 (812) 334-4261

## **Project Summary**

Consultation Code: 03E12000-2020-SLI-0353

Event Code: 03E12000-2020-E-01803

Project Name: Des. No. 1700173, State Road (SR) 60 over South Fork Blue River,

Bridge Replacement

Project Type: TRANSPORTATION

Project Description: Indiana Department of Transportation (INDOT), with funding from

Federal Highway Administration (FHWA), intends to proceed with a bridge replacement project, bridge #060-88-03069, National Bridge Inventory (NBI) #021480, carrying SR 60 over South Fork Blue River, approximately 0.42 mile west of SR 335, New Pekin, Washington County,

Indiana.

The preferred alternative is to replace the existing three span reinforced concrete arch bridge with a three-span (58 feet, 75 feet, 58 feet) continuous composite pre-stressed concrete bulb-tee beam bridge for a total length of 192.6 feet, a clear roadway width of 30 feet, and skewed 15 degrees left. The bridge will consist of a 12-foot-wide through lane with a 3-foot-wide shoulder provided in each direction. The project will extend approximately 695 feet south and 585 feet north of the center of the existing structure for a total of 1,280 feet. From east and west, construction will vary up to 55 feet from the existing edge of pavement. Channel clearing will be required. This project is located in a rural area. Suitable summer habitat does exist near the project area. Thirteen trees, Silver Maple, Box Elder, and/or Sycamore are currently planned to be removed winter of 2021, 0 to 100 feet from the existing roadway in the northeast quadrant of the project area. No mitigation will be required. More than 0.5 acre of new permanent right-of-way will be necessary for the completion of this project. Temporary lighting may be required. No new permanent lighting will be necessary. The letting date is currently December 8, 2021. Construction is anticipated to take place from winter 2021 to fall 2022.


Based on consultation with INDOT Seymour District, August 13, 2019, a review of the U.S. Fish and Wildlife Service (USFWS) database did not indicate the presence of endangered bat species in or within 0.5 mile of the project area.

A qualified staff member from Metric Environmental conducted an

inspection of the bridge on August 26, 2019. No evidence of bats was observed.

### **Project Location:**

Approximate location of the project can be viewed in Google Maps: <a href="https://www.google.com/maps/place/38.499357454262935N86.01313497645017W">https://www.google.com/maps/place/38.499357454262935N86.01313497645017W</a>



Counties: Washington, IN

# **Endangered Species Act Species**

There is a total of 2 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species. Note that 1 of these species should be considered only under certain conditions.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries<sup>1</sup>, as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

1. <u>NOAA Fisheries</u>, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

### **Mammals**

NAME STATUS

#### Indiana Bat *Myotis sodalis*

Endangered

There is **final** critical habitat for this species. Your location is outside the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/5949

Species survey guidelines:

https://ecos.fws.gov/ipac/guideline/survey/population/1/office/31440.pdf

#### Northern Long-eared Bat *Myotis septentrionalis*

Threatened

No critical habitat has been designated for this species.

This species only needs to be considered under the following conditions:

 Incidental take of the NLEB is not prohibited here. Federal agencies may consult using the 4(d) rule streamlined process. Transportation projects may consult using the programmatic process. See www.fws.gov/midwest/endangered/mammals/nleb/index.html

Species profile: https://ecos.fws.gov/ecp/species/9045

#### **Critical habitats**

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.



# United States Department of the Interior

#### FISH AND WILDLIFE SERVICE

Indiana Ecological Services Field Office 620 South Walker Street Bloomington, IN 47403-2121

Phone: (812) 334-4261 Fax: (812) 334-4273

http://www.fws.gov/midwest/Endangered/section7/s7process/step1.html



In Reply Refer To: December 11, 2019

Consultation Code: 03E12000-2020-I-0353 Event Code: 03E12000-2020-E-01808

Project Name: Des. No. 1700173, State Road (SR) 60 over South Fork Blue River, Bridge

Replacement

Subject: Concurrence verification letter for the 'Des. No. 1700173, State Road (SR) 60 over

South Fork Blue River, Bridge Replacement' project under the revised February 5, 2018, FHWA, FRA, FTA Programmatic Biological Opinion for Transportation Projects within the Range of the Indiana Bat and Northern Long-eared Bat.

To whom it may concern:

The U.S. Fish and Wildlife Service (Service) has received your request to verify that the **Des. No. 1700173, State Road (SR) 60 over South Fork Blue River, Bridge Replacement** (Proposed Action) may rely on the concurrence provided in the February 5, 2018, FHWA, FRA, FTA Programmatic Biological Opinion for Transportation Projects within the Range of the Indiana Bat and Northern Long-eared Bat (PBO) to satisfy requirements under Section 7(a)(2) of the Endangered Species Act of 1973 (ESA) (87 Stat. 884, as amended; 16 U.S.C 1531 *et seq.*).

Based on the information you provided (Project Description shown below), you have determined that the Proposed Action is within the scope and adheres to the criteria of the PBO, including the adoption of applicable avoidance and minimization measures, and may affect, but is <u>not likely to adversely affect</u> (NLAA) the endangered Indiana bat (*Myotis sodalis*) and/or the threatened Northern long-eared bat (*Myotis septentrionalis*).

The Service has 14 calendar days to notify the lead Federal action agency or designated non-federal representative if we determine that the Proposed Action does not meet the criteria for a NLAA determination under the PBO. If we do <u>not</u> notify the lead Federal action agency or designated non-federal representative within that timeframe, you may proceed with the Proposed Action under the terms of the NLAA concurrence provided in the PBO. This verification period allows Service Field Offices to apply local knowledge to implementation of the PBO, as we may identify a small subset of actions having impacts that were unanticipated. In such instances,

Service Field Offices may request additional information that is necessary to verify inclusion of the proposed action under the PBO.

**For Proposed Actions that include bridge/structure removal, replacement, and/or maintenance activities:** If your initial bridge/structure assessments failed to detect Indiana bats, but you later detect bats during construction, please submit the Post Assessment Discovery of Bats at Bridge/Structure Form (User Guide Appendix E) to this Service Office. In these instances, potential incidental take of Indiana bats may be exempted provided that the take is reported to the Service.

If the Proposed Action is modified, or new information reveals that it may affect the Indiana bat and/or Northern long-eared bat in a manner or to an extent not considered in the PBO, further review to conclude the requirements of ESA Section 7(a)(2) may be required. If the Proposed Action may affect any other federally-listed or proposed species, and/or any designated critical habitat, additional consultation between the lead Federal action agency and this Service Office is required. If the proposed action has the potential to take bald or golden eagles, additional coordination with the Service under the Bald and Golden Eagle Protection Act may also be required. In either of these circumstances, please contact this Service Office.

# **Project Description**

The following project name and description was collected in IPaC as part of the endangered species review process.

#### Name

Des. No. 1700173, State Road (SR) 60 over South Fork Blue River, Bridge Replacement

#### **Description**

Indiana Department of Transportation (INDOT), with funding from Federal Highway Administration (FHWA), intends to proceed with a bridge replacement project, bridge #060-88-03069, National Bridge Inventory (NBI) #021480, carrying SR 60 over South Fork Blue River, approximately 0.42 mile west of SR 335, New Pekin, Washington County, Indiana.

The preferred alternative is to replace the existing three span reinforced concrete arch bridge with a three-span (58 feet, 75 feet, 58 feet) continuous composite pre-stressed concrete bulbtee beam bridge for a total length of 192.6 feet, a clear roadway width of 30 feet, and skewed 15 degrees left. The bridge will consist of a 12-foot-wide through lane with a 3-foot-wide shoulder provided in each direction. The project will extend approximately 695 feet south and 585 feet north of the center of the existing structure for a total of 1,280 feet. From east and west, construction will vary up to 55 feet from the existing edge of pavement. Channel clearing will be required. This project is located in a rural area. Suitable summer habitat does exist near the project area. Thirteen trees, Silver Maple, Box Elder, and/or Sycamore are currently planned to be removed winter of 2021, 0 to 100 feet from the existing roadway in the northeast quadrant of the project area. No mitigation will be required. More than 0.5 acre of new permanent right-of-way will be necessary for the completion of this project. Temporary lighting may be required. No new permanent lighting will be necessary. The letting date is currently December 8, 2021. Construction is anticipated to take place from winter 2021 to fall 2022.

Based on consultation with INDOT Seymour District, August 13, 2019, a review of the U.S. Fish and Wildlife Service (USFWS) database did not indicate the presence of endangered bat species in or within 0.5 mile of the project area.

A qualified staff member from Metric Environmental conducted an inspection of the bridge on August 26, 2019. No evidence of bats was observed.

# **Determination Key Result**

Based on your answers provided, this project(s) may affect, but is not likely to adversely affect the endangered Indiana bat and/or the threatened Northern long-eared bat, therefore, consultation with the U.S. Fish and Wildlife Service pursuant to Section 7(a)(2) of the Endangered Species Act of 1973 (ESA) (87 Stat. 884, as amended 16 U.S.C. 1531 *et seq.*) is required. However, also based on your answers provided, this project may rely on the concurrence provided in the revised February 5, 2018, FHWA, FRA, FTA Programmatic Biological Opinion for Transportation Projects within the Range of the Indiana Bat and Northern Long-eared Bat.

# **Qualification Interview**

- 1. Is the project within the range of the Indiana bat<sup>[1]</sup>?
  - [1] See Indiana bat species profile

Automatically answered

Yes

- 2. Is the project within the range of the Northern long-eared bat<sup>[1]</sup>?
  - [1] See Northern long-eared bat species profile

Automatically answered

Yes

- 3. Which Federal Agency is the lead for the action?
  - A) Federal Highway Administration (FHWA)
- 4. Are *all* project activities limited to non-construction<sup>[1]</sup> activities only? (examples of non-construction activities include: bridge/abandoned structure assessments, surveys, planning and technical studies, property inspections, and property sales)
  - [1] Construction refers to activities involving ground disturbance, percussive noise, and/or lighting. No
- 5. Does the project include *any* activities that are **greater than** 300 feet from existing road/rail surfaces<sup>[1]</sup>?
  - [1] Road surface is defined as the actively used [e.g. motorized vehicles] driving surface and shoulders [may be pavement, gravel, etc.] and rail surface is defined as the edge of the actively used rail ballast.

No

- 6. Does the project include *any* activities **within** 0.5 miles of a known Indiana bat and/or NLEB hibernaculum<sup>[1]</sup>?
  - [1] For the purpose of this consultation, a hibernaculum is a site, most often a cave or mine, where bats hibernate during the winter (see suitable habitat), but could also include bridges and structures if bats are found to be hibernating there during the winter.

No

7. Is the project located **within** a karst area?

Yes

- 8. Will the project include *any* type of activity that could impact a **known** hibernaculum<sup>[1]</sup>, or impact a karst feature (e.g., sinkhole, losing stream, or spring) that could result in effects to a **known** hibernaculum?
  - [1] For the purpose of this consultation, a hibernaculum is a site, most often a cave or mine, where bats hibernate during the winter (see suitable habitat), but could also include bridges and structures if bats are found to be hibernating there during the winter.

No

- 9. Is there *any* suitable<sup>[1]</sup> summer habitat for Indiana Bat or NLEB **within** the project action area<sup>[2]</sup>? (includes any trees suitable for maternity, roosting, foraging, or travelling habitat)
  - [1] See the Service's summer survey guidance for our current definitions of suitable habitat.
  - [2] The action area is defined as all areas to be affected directly or indirectly by the Federal action and not merely the immediate area involved in the action (50 CFR Section 402.02). Further clarification is provided by the national consultation FAQs.

Yes

- 10. Will the project remove *any* suitable summer habitat<sup>[1]</sup> and/or remove/trim any existing trees **within** suitable summer habitat?
  - [1] See the Service's <u>summer survey guidance</u> for our current definitions of suitable habitat.

Yes

11. Will the project clear more than 20 acres of suitable habitat per 5-mile section of road/rail? *No* 

- 12. Have presence/probable absence (P/A) summer surveys<sup>[1][2]</sup> been conducted<sup>[3][4]</sup> **within** the suitable habitat located within your project action area?
  - [1] See the Service's <u>summer survey guidance</u> for our current definitions of suitable habitat.
  - [2] Presence/probable absence summer surveys conducted within the fall swarming/spring emergence home range of a documented Indiana bat hibernaculum (contact local Service Field Office for appropriate distance from hibernacula) that result in a negative finding requires additional consultation with the local Service Field Office to determine if clearing of forested habitat is appropriate and/or if seasonal clearing restrictions are needed to avoid and minimize potential adverse effects on fall swarming and spring emerging Indiana bats.
  - [3] For projects within the range of either the Indiana bat or NLEB in which suitable habitat is present, and no bat surveys have been conducted, the transportation agency will assume presence of the appropriate species. This assumption of presence should be based upon the presence of suitable habitat and the capability of bats to occupy it because of their mobility.
  - [4] Negative presence/probable absence survey results obtained using the <u>summer survey guidance</u> are valid for a minimum of two years from the completion of the survey unless new information (e.g., other nearby surveys) suggest otherwise.

No

- 13. Does the project include activities within documented Indiana bat habitat<sup>[1][2]</sup>?
  - [1] Documented roosting or foraging habitat for the purposes of this consultation, we are considering documented habitat as that where Indiana bats and/or NLEB have actually been captured and tracked using (1) radio telemetry to roosts; (2) radio telemetry biangulation/triangulation to estimate foraging areas; or (3) foraging areas with repeated use documented using acoustics. Documented roosting habitat is also considered as suitable summer habitat within 0.25 miles of documented roosts.)
  - [2] For the purposes of this key, we are considering documented corridors as that where Indiana bats and/or NLEB have actually been captured and tracked to using (1) radio telemetry; or (2) treed corridors located directly between documented roosting and foraging habitat.

No

14. Will the removal or trimming of habitat or trees occur **within** suitable but **undocumented Indiana bat** roosting/foraging habitat or travel corridors?

Yes

- 15. What time of year will the removal or trimming of habitat or trees **within** suitable but **undocumented Indiana bat** roosting/foraging habitat or travel corridors occur<sup>[1]</sup>?
  - [1] Coordinate with the local Service Field Office for appropriate dates.
  - B) During the inactive season
- 16. Does the project include activities within documented NLEB habitat<sup>[1][2]</sup>?
  - [1] Documented roosting or foraging habitat for the purposes of this consultation, we are considering documented habitat as that where Indiana bats and/or NLEB have actually been captured and tracked using (1) radio telemetry to roosts; (2) radio telemetry biangulation/triangulation to estimate foraging areas; or (3) foraging areas with repeated use documented using acoustics. Documented roosting habitat is also considered as suitable summer habitat within 0.25 miles of documented roosts.)
  - [2] For the purposes of this key, we are considering documented corridors as that where Indiana bats and/or NLEB have actually been captured and tracked to using (1) radio telemetry; or (2) treed corridors located directly between documented roosting and foraging habitat.

No

17. Will the removal or trimming of habitat or trees occur **within** suitable but **undocumented NLEB** roosting/foraging habitat or travel corridors?

Yes

- 18. What time of year will the removal or trimming of habitat or trees **within** suitable but **undocumented NLEB** roosting/foraging habitat or travel corridors occur?
  - B) During the inactive season
- 19. Will *any* tree trimming or removal occur **within** 100 feet of existing road/rail surfaces? *Yes*
- 20. Will the tree removal alter *any* **documented** Indiana bat or NLEB roosts and/or alter any surrounding summer habitat **within** 0.25 mile of a documented roost?

  No
- 21. Will *any* tree trimming or removal occur **between** 100-300 feet of existing road/rail surfaces?

No

22. Are *all* trees that are being removed clearly demarcated? *Yes* 

23. Will the removal of habitat or the removal/trimming of trees include installing new or replacing existing **permanent** lighting?

No

24. Does the project include wetland or stream protection activities associated with compensatory wetland mitigation?

No

25. Does the project include slash pile burning?

No

- 26. Does the project include *any* bridge removal, replacement, and/or maintenance activities (e.g., any bridge repair, retrofit, maintenance, and/or rehabilitation work)? *Yes*
- 27. Is there *any* suitable habitat<sup>[1]</sup> for Indiana bat or NLEB **within** 1,000 feet of the bridge? (includes any trees suitable for maternity, roosting, foraging, or travelling habitat)
  - [1] See the Service's current <u>summer survey guidance</u> for our current definitions of suitable habitat. *Yes*
- 28. Has a bridge assessment<sup>[1]</sup> been conducted **within** the last 24 months<sup>[2]</sup> to determine if the bridge is being used by bats?
  - [1] See <u>User Guide Appendix D</u> for bridge/structure assessment guidance
  - [2] Assessments must be completed no more than 2 years prior to conducting any work below the deck surface on all bridges that meet the physical characteristics described in the Programmatic Consultation, regardless of whether assessments have been conducted in the past. Due to the transitory nature of bat use, a negative result in one year does not guarantee that bats will not use that bridge/structure in subsequent years.

Yes

#### SUBMITTED DOCUMENTS

Des. No. 1700173 AppDBridgeStructureAssessmentFormJune2016 - CS - 9-27-19.pdf <a href="https://ecos.fws.gov/ipac/project/3KKX5PQG5BFJDAHXO5QJZZ3WDM/">https://ecos.fws.gov/ipac/project/</a>
 3KKX5PQG5BFJDAHXO5QJZZ3WDM/
 projectDocuments/19356906

29. Did the bridge assessment detect *any* signs of Indiana bats and/or NLEBs roosting in/under the bridge (bats, guano, etc.)<sup>[1]</sup>?

[1] If bridge assessment detects signs of *any* species of bats, coordination with the local FWS office is needed to identify potential threatened or endangered bat species. Additional studies may be undertaken to try to identify which bat species may be utilizing the bridge prior to allowing *any* work to proceed.

Note: There is a small chance bridge assessments for bat occupancy do not detect bats. Should a small number of bats be observed roosting on a bridge just prior to or during construction, such that take is likely to occur or does occur in the form of harassment, injury or death, the PBO requires the action agency to report the take. Report all unanticipated take within 2 working days of the incident to the USFWS. Construction activities may continue without delay provided the take is reported to the USFWS and is limited to 5 bats per project.

No

30. Will the bridge removal, replacement, and/or maintenance activities include installing new or replacing existing **permanent** lighting?

No

31. Does the project include the removal, replacement, and/or maintenance of *any* structure other than a bridge? (e.g., rest areas, offices, sheds, outbuildings, barns, parking garages, etc.)

No

- 32. Will the project involve the use of **temporary** lighting *during* the active season? *Yes*
- 33. Is there *any* suitable habitat **within** 1,000 feet of the location(s) where **temporary** lighting will be used?

Yes

34. Will the project install new or replace existing **permanent** lighting? *No* 

35. Does the project include percussives or other activities (**not including tree removal/ trimming or bridge/structure work**) that will increase noise levels above existing traffic/background levels?

No

36. Are *all* project activities that are **not associated with** habitat removal, tree removal/ trimming, bridge and/or structure activities, temporary or permanent lighting, or use of percussives, limited to actions that DO NOT cause any additional stressors to the bat species?

Examples: lining roadways, unlighted signage, rail road crossing signals, signal lighting, and minor road repair such as asphalt fill of potholes, etc.

Yes

- 37. Will the project raise the road profile **above the tree canopy**? *No*
- 38. Are the project activities that are not associated with habitat removal, tree removal/ trimming, bridge and/or structure activities, temporary or permanent lighting, or use of percussives consistent with a No Effect determination in this key?

#### Automatically answered

Yes, other project activities are limited to actions that DO NOT cause any additional stressors to the bat species as described in the BA/BO

39. Is the habitat removal portion of this project consistent with a Not Likely to Adversely Affect determination in this key?

#### Automatically answered

Yes, because the tree removal/trimming that occurs outside of the Indiana bat's active season occurs greater than 0.5 miles from the nearest hibernaculum, is less than 100 feet from the existing road/rail surface, includes clear demarcation of the trees that are to be removed, and does not alter documented roosts and/or surrounding summer habitat within 0.25 miles of a documented roost.

40. Is the habitat removal portion of this project consistent with a Not Likely to Adversely Affect determination in this key?

#### Automatically answered

Yes, because the tree removal/trimming that occurs outside of the NLEB's active season occurs greater than 0.5 miles from the nearest hibernaculum, is less than 100 feet from the existing road/rail surface, includes clear demarcation of the trees that are to be removed, and does not alter documented roosts and/or surrounding summer habitat within 0.25 miles of a documented roost.

41. Is the bridge removal, replacement, or maintenance activities portion of this project consistent with a No Effect determination in this key?

#### Automatically answered

*Yes, because the bridge has been assessed using the criteria documented in the BA and no signs of bats were detected* 

#### 42. General AMM 1

Will the project ensure *all* operators, employees, and contractors working in areas of known or presumed bat habitat are aware of *all* FHWA/FRA/FTA (Transportation Agencies) environmental commitments, including all applicable Avoidance and Minimization Measures?

Yes

#### 43. Hibernacula AMM 1

Will the project ensure that on-site personnel will use best management practices<sup>[1]</sup>, secondary containment measures, or other standard spill prevention and countermeasures to avoid impacts to possible hibernacula?

[1] Coordinate with the appropriate Service Field Office on recommended best management practices for karst in your state.

Yes

#### 44. Hibernacula AMM 1

Will the project ensure that, where practicable, a 300 foot buffer will be employed to separate fueling areas and other major containment risk activities from caves, sinkholes, losing streams, and springs in karst topography?

Yes

#### 45. Tree Removal AMM 1

Can *all* phases/aspects of the project (e.g., temporary work areas, alignments) be modified, to the extent practicable, to avoid tree removal<sup>[1]</sup> in excess of what is required to implement the project safely?

Note: Tree Removal AMM 1 is a minimization measure, the full implementation of which may not always be practicable. Projects may still be NLAA as long as Tree Removal AMMs 2, 3, and 4 are implemented and LAA as long as Tree Removal AMMs 3, 5, 6, and 7 are implemented.

[1] The word "trees" as used in the AMMs refers to trees that are suitable habitat for each species within their range. See the USFWS' current summer survey guidance for our latest definitions of suitable habitat.

Yes

#### 46. Tree Removal AMM 3

Can tree removal be limited to that specified in project plans and ensure that contractors understand clearing limits and how they are marked in the field (e.g., install bright colored flagging/fencing prior to any tree clearing to ensure contractors stay within clearing limits)?

Yes

#### 47. Tree Removal AMM 4

Can the project avoid cutting down/removal of *all* (1) **documented**<sup>[1]</sup> Indiana bat or NLEB roosts<sup>[2]</sup> (that are still suitable for roosting), (2) trees **within** 0.25 miles of roosts, and (3) documented foraging habitat any time of year?

- [1] The word documented means habitat where bats have actually been captured and/or tracked.
- [2] Documented roosting or foraging habitat for the purposes of this consultation, we are considering documented habitat as that where Indiana bats and/or NLEB have actually been captured and tracked using (1) radio telemetry to roosts; (2) radio telemetry biangulation/triangulation to estimate foraging areas; or (3) foraging areas with repeated use documented using acoustics. Documented roosting habitat is also considered as suitable summer habitat within 0.25 miles of documented roosts.)

Yes

#### 48. Lighting AMM 1

Will *all* **temporary** lighting be directed away from suitable habitat during the active season?

Yes

# **Project Questionnaire**

1. Have you made a No Effect determination for *all* other species indicated on the FWS IPaC generated species list?

N/A

2. Have you made a May Affect determination for *any* other species on the FWS IPaC generated species list?

N/A

- 3. How many acres<sup>[1]</sup> of trees are proposed for removal between 0-100 feet of the existing road/rail surface?
  - [1] If described as number of trees, multiply by 0.09 to convert to acreage and enter that number.

1.17

4. Please describe the proposed bridge work:

Replace the existing three span reinforced concrete arch bridge with a three-span (58 feet, 75 feet, 58 feet) continuous composite pre-stressed concrete bulb-tee beam bridge for a total length of 192.6 feet, a clear roadway width of 30 feet, and skewed 15 degrees left.

5. Please state the timing of all proposed bridge work:

Winter 2021 to Fall 2022

6. Please enter the date of the bridge assessment:

August 26, 2019

# **Avoidance And Minimization Measures (AMMs)**

This determination key result includes the committment to implement the following Avoidance and Minimization Measures (AMMs):

#### **GENERAL AMM 1**

Ensure all operators, employees, and contractors working in areas of known or presumed bat habitat are aware of all FHWA/FRA/FTA (Transportation Agencies) environmental commitments, including all applicable AMMs.

#### **HIBERNACULA AMM 1**

For projects located within karst areas, on-site personnel will use best management practices, secondary containment measures, or other standard spill prevention and countermeasures to avoid impacts to possible hibernacula. Where practicable, a 300 foot buffer will be employed to separate fueling areas and other major containment risk activities from caves, sinkholes, losing streams, and springs in karst topography.

#### **LIGHTING AMM 1**

Direct temporary lighting away from suitable habitat during the active season.

#### TREE REMOVAL AMM 1

Modify all phases/aspects of the project (e.g., temporary work areas, alignments) to avoid tree removal.

#### TREE REMOVAL AMM 2

Apply time of year restrictions for tree removal when bats are not likely to be present, or limit tree removal to 10 or fewer trees per project at any time of year within 100 feet of existing road/rail surface and **outside of documented** roosting/foraging habitat or travel corridors; visual emergence survey must be conducted with <u>no bats observed</u>.

#### TREE REMOVAL AMM 3

Ensure tree removal is limited to that specified in project plans and ensure that contractors understand clearing limits and how they are marked in the field (e.g., install bright colored flagging/fencing prior to any tree clearing to ensure contractors stay within clearing limits).

#### TREE REMOVAL AMM 4

Do not remove **documented** Indiana bat or NLEB roosts that are still suitable for roosting, or trees within 0.25 miles of roosts, or **documented** foraging habitat any time of year.

# Determination Key Description: FHWA, FRA, FTA Programmatic Consultation For Transportation Projects Affecting NLEB Or Indiana Bat

This key was last updated in IPaC on December 02, 2019. Keys are subject to periodic revision.

This decision key is intended for projects/activities funded or authorized by the Federal Highway Administration (FHWA), Federal Railroad Administration (FRA), and/or Federal Transit Administration (FTA), which may require consultation with the U.S. Fish and Wildlife Service (Service) under Section 7 of the Endangered Species Act (ESA) for the endangered **Indiana bat** (*Myotis sodalis*) and the threatened **Northern long-eared bat** (NLEB) (*Myotis septentrionalis*).

This decision key should <u>only</u> be used to verify project applicability with the Service's <u>February 5, 2018, FHWA, FRA, FTA Programmatic Biological Opinion for Transportation Projects</u>. The programmatic biological opinion covers limited transportation activities that may affect either bat species, and addresses situations that are both likely and not likely to adversely affect either bat species. This decision key will assist in identifying the effect of a specific project/activity and applicability of the programmatic consultation. The programmatic biological opinion is <u>not</u> intended to cover all types of transportation actions. Activities outside the scope of the programmatic biological opinion, or that may affect ESA-listed species other than the Indiana bat or NLEB, or any designated critical habitat, may require additional ESA Section 7 consultation.

111 Monument Circle Suite 1200 Indianapolis, IN 46204 Telephone (317) 636-4682 Facsimile (317) 917-5211 www.hntb.com



Revised 08/08/2017

07/11/2019

Gary Nale New Pekin Municipal Utilities 75 S Mill St. Pekin, IN 47165

Subject: Initial Notice of Proposed Improvement Project Des. No. 1700173

Dear Gary;

Our firm has been assigned the task of utility coordination for the project referenced above by the Indiana Department of Transportation. In accordance with 105 IAC 13-3-1(c), this letter serves as your initial notice of the proposed improvement project Des. No. 1700173 on SR 60 in Washington County, Indiana.

In accordance with 105 IAC 13-3-1(c), the following information is provided. The dates listed in items (4) and (5) below are the currently scheduled dates.

(1) Name or route number: SR 60

(2) Geographical limits: 0.42 miles W of SR 335 over S Fork Blue River, 42+62,

42+62

(3) General description of work: Br Repl, Comp. Cont. Conc. Construction

(4) Date approved work plan will 01/1/2021

be needed:

(5) Ready for contracts date: 09/29/2021

(6) Name of designer and Angela Pearl - HNTB

contact information: 111 Monument Circle Suite 1200, Indianapolis, IN 46204

Telephone: (317) 636-4682

(7) Major or minor project: Minor

In accordance with 105 IAC 13-3-1(d), within 30 days after receiving the initial notice, the utility shall respond in writing with a:

- (1) Description of the type and location of its facilities within the geographical limits of the proposed improvement project; or
- (2) If the utility has determined to the best of their abilities that they do not have facilities within the geographical limits of the improvement project; complete, sign, and return Page 1 of the attached Work Plan.

Additionally, please provide us the name, telephone number, postal address and email address of the person selected as your designated contact for this project to expedite future communications. We will contact Indiana 811 and request locates for this project prior to our survey. If you would prefer to provide us location information by some other means please contact this office to discuss.

111 Monument Circle Suite 1200 Indianapolis, IN 46204 Telephone (317) 636-4682 Facsimile (317) 917-5211 www.hntb.com



Revised 08/08/2017

Please send your response to Doug Garvin, HNTB, 111 Monument Circle Suite 1200, Indianapolis, IN 46204, telephone: 317-917-5263, <a href="mailto:dgarvin@hntb.com">dgarvin@hntb.com</a>. Thank you for your attention to these matters.

Sincerely;

Doug Garvin Utility Coordinator

Cc: File



December 30, 2019

Irish L. Jones Metric Environmental 6971 Hillsdale Court Indianapolis, Indiana 46250

Dear Mr. Jones:

The proposed project to make bridge improvements along State Road 60 over the South Fork of Blue River in Washington County, Indiana (Des No 1700173), as referred to in your letter received September 6, 2019, will cause a conversion of prime farmland.

The attached packet of information is for your use in completing Parts VI and VII of the AD-1006. After completion, the federal funding agency needs to forward one copy to NRCS for our records.

If you need additional information, please contact John Allen at 317-295-5859.

Sincerely,

JERRY RAYNOR State Conservationist

Enclosures





NRCS-CPA-106

(Rev. 1-91)

# FARMLAND CONVERSION IMPACT RATING FOR CORRIDOR TYPE PROJECTS

PART I (To be completed by Federal Agency)			3. Date of Land Evaluation Request 12/20/19 4. Sheet 1 of 1					
1. Name of Project DES1700173_SR 60 over South Fork of Blue			5. Feder	5. Federal Agency Involved Indiana Department of Transportation				
2. Type of Project Bridge Replacement			6. County and State Washington County, Indiana					
PART II (To be completed by NRCS)			Date Request Received by NRCS 9/6/19			Person Completing Form  JRA		
3. Does the corridor contain prime, unique statewide or local important farmland (If no, the FPPA does not apply - Do not complete additional parts of this forr		•		YES V NO U		Acres Irrigated		
5. Major Crop(s)	·	6. Farmable Land		nment Jurisdiction		7. Amount of Farmland As Defined in FPPA		
Corn		Acres: 276,		% 84		Acres: 136,204 % 41		
Name Of Land Evaluation System U     LESA	sed	9. Name of Local	Site Asse	12/30/19				
PART III (To be completed by Fe	deral Agency)			Alternativ		dor For S idor 2	Segment : Corridor 3	Corridor 4
A. Total Acres To Be Converted Dire	ctly			1.10				
B. Total Acres To Be Converted India	rectly, Or To Receive S	Services						
C. Total Acres In Corridor				1.10	0.00		0.00	0.00
PART IV (To be completed by N	RCS) Land Evaluati	on Information						
A. Total Acres Prime And Unique Fa	armland			1.10				
B. Total Acres Statewide And Local	Important Farmland			0.00				
C. Percentage Of Farmland in Cour	nty Or Local Govt. Uni	t To Be Converted		<0.001				
D. Percentage Of Farmland in Govt.	Jurisdiction With Same	or Higher Relativ	∕e Value	86.0				
PART V (To be completed by NRCS value of Farmland to Be Serviced of	,		Relative	69				
PART VI (To be completed by Fed	•	T'	laximum	03				
Assessment Criteria (These criteria	• • • • • • • • • • • • • • • • • • • •		Points					
1. Area in Nonurban Use			15	8				
2. Perimeter in Nonurban Use			10	4				
3. Percent Of Corridor Being Far	med		20	1				
4. Protection Provided By State	And Local Government	:	20	0				
5. Size of Present Farm Unit Cor	npared To Average		10	5				
6. Creation Of Nonfarmable Farm	nland		25	0				
7. Availablility Of Farm Support S	Services		5	5				
8. On-Farm Investments			20	0				
9. Effects Of Conversion On Far			25	0				
10. Compatibility With Existing Ag	gricultural Use		10	0				
TOTAL CORRIDOR ASSESSME	ENT POINTS		160	23	0		0	0
PART VII (To be completed by Fe	deral Agency)							
Relative Value Of Farmland (From	Part V)		100	69				
Total Corridor Assessment (From I assessment)	Part VI above or a loca	I site	160	23	0		0	0
TOTAL POINTS (Total of above	2 lines)		260	92	0		0	0
1. Corridor Selected:	2. Total Acres of Farn		. Date Of	Selection:	4. Was	A Local Si	te Assessment Use	d?
Α	Converted by Proje	ect:						
	1.10 Ac.					YES [	NO 🗸	
5. Reason For Selection:		I						
The need for this proposed South Fork of Blue River. T function and safety of the to	he purpose of thi	s project is to	addres	s the deteriora	ting co	nditions	before operati	
Signature of Person Completing this Part:  Irish L Jones				DATE <b>12/20/19</b>				
NOTE: Complete a form for ea	ach seament with r	more than one	Alternat	o Corridor				

# APPENDIX D: Section 106 of the National Historic Preservation Act

Date: 9/25/2019

**Project Designation Number:** 1700173

**Route Number: SR 60** 

**Project Description:** Bridge Replacement over S. Fork Blue River, 0.42 miles west of SR 335

Indiana Department of Transportation (INDOT) and Federal Highway Administration (FHWA) propose to utilize federal funds for a bridge project. The project is located on State Road (SR) 60, approximately 0.42 mile west of SR 335. Specifically, this project is located at the intersection of Sections 25 and 30, Township 1 North, Range 4 East on the Salem, Indiana and Palmyra, Indiana 7.5-minute United States Geological Survey (USGS) topographic quadrangles. The existing structure (No. 060-88-03069, NBI No. 021480) is a three-span (50'-0", 50'-0", 50'-0") concrete arch bridge, with a structure length of 193 feet and a clear roadway width of 28 feet. The structure was constructed in 1937. There have been no known rehabilitations. The bridge is listed as "Not Eligible" for the National Register of Historic Places on the Indiana Historic Bridge Inventory. The need for this project is evidenced by the deteriorating condition of the existing structure. In the most recent Bridge Inspection Report, dated July 2, 2019, INDOT noted cracking in the copings. The superstructure exhibited minor cracking in the parapet walls, and cracking, delamination, and spalling with exposed rebar in the sidewalk underside. The substructure exhibited some cracking and scaling with efflorescence on the pier caps and stems. The structure was given a sufficiency rating of 59 out of 100 possible points.

The preferred alternative is to replace the existing bridge. The proposed replacement structure will be three-spans (58'-0", 75'-0", 58'-0") with a structure length of 191 feet, a clear roadway width of 32 feet, and skewed 15 degrees left. The approach roadway will have guardrails and concrete bridge railing transition. It is believed that up to 2 acres of right-of-way may be required for this project; however, the exact amount and locations have not been determined. Channel clearing will be required. SR 60 will be shifted approximately 18 feet upstream (east) from the existing alignment to accommodate maintenance of traffic. A single lane of traffic will be maintained during construction utilizing a temporary signal. The survey area is irregularly shaped approximately 424.0 m (1,391.1 ft) along SR 60 and 78.3 m (256.9 ft) wide at the widest and encompasses 2.5 ha (6.2 ac).

Feature crossed (if applicable): South Fork of Blue River

**Township:** Pierce, and Polk Townships

City/County: New Pekin, Washington County

#### Information reviewed (please check all that apply):

General project location map	USGS map 🛛 Aerial photograph 🖂
Written description of project area	General project area photos
Previously completed archaeology reports	
Previously completed historic property reports	
Soil survey data Bridge	inspection information

**Other (please specify)**: Bridge Inspection Application System (BIAS); Indiana Historic Bridge Inventory; Indiana State Historic Architectural and Archaeological Research Database (SHAARD); Indiana Buildings, Bridges, and Cemeteries Map website; *Washington County Interim Report*; online street-view imagery; ArcMap GIS, Washington County GIS website, MPPA application (including maps and photographs) sent by Metric Environmental dated September 6<sup>th</sup>, 2019 and on file at INDOT CRO.

Snell, Samuel P.

2019 Phase Ia Archaeological Survey for the SR 60 over South Fork of the Blue River Project (Des. No. 1700173), New Perkin, Pierce, and Polk Townships, Washington County, Indiana. Report on file, Indiana Department of Transportation, Cultural Resources Office, Indianapolis, In.

#### **Results of the Records Review for Above-Ground Resources:**

With regard to above-ground resources, an INDOT Cultural Resources historian who meets the Secretary of the Interior's Professional Qualification Standards as per 36 CFR Part 61 performed a desktop review, checking the Indiana Register of Historic Sites and Structures (State Register) and National Register of Historic Places (National Register) lists for Washington County. No listed resources are located near the project area.

The Indiana Historic Sites and Structures Inventory (IHSSI) and National Register information for Washington County are available in the Indiana State Historic Architectural and Archaeological Research Database (SHAARD) and the Indiana Historic Buildings, Bridges, and Cemeteries Map (IHBBCM). The *Washington County Interim Report* (2008; New Pekin Scattered Sites) of the Indiana Historic Sites and Structures Inventory (IHSSI) was also consulted. An INDOT-CRO historian reviewed the SHAARD Online Map and checked it against the Interim Report hard-copy maps.

According to the IHSSI rating system, generally properties rated "contributing" do not possess the level of historical or architectural significance necessary to be considered individually National Register-eligible, although they would contribute to a historic district. If they retain material integrity, properties rated "notable" might possess the necessary level of significance after further research. Properties rated "outstanding" usually possess the necessary level of significance to be considered National Register eligible, if they retain material integrity.

One (1) IHSSI documented properties rated higher than "Contributing" is located within 0.25 mile of the project area:

• IHSSI# 175-567-41040, House, 510 E Main St., c. 1945, Minimal Traditional, "Notable"

The INDOT CRO historian reviewed structures adjacent to the project area utilizing online aerial, streetview photography, and the Washington County GIS website (accessed via https://washingtonin.wthgis.com). The project area is located in a small town setting with adjacent aboveground resources consisting of early twentieth to early twenty-first century commercial and residential buildings. None of the structures appear to possess the age, significance or integrity required to be considered NRHP eligible. One (1) "Notable" property (IHSSI# 175-567-41040, 510 E Main St.) documented in SHAARD is located within 0.25 miles of the project area. However, this property is obscured from the project viewshed by distance, buildings, and vegetation. Therefore, IHSSI# 175-567-41040 is not considered adjacent to the projected area.

The most recent inspection report (C. Everman; 7/2/2019) from the Bridge Inspection Application System (BIAS) was referenced to review the bridge. The subject structure (Bridge #060-88-03069, NBI No. 021480) was constructed in 1937 and is a three-span 193 foot long concrete arch bridge that carries SR 60 over the South Fork of Blue River. The subject bridge is documented in SHAARD (HB-2873) with a "Contributing" rating, however the Indiana Historic Bridge Inventory (M & H Architecture, Inc., 2009) lists the bridge as "Non Historic" (Vol. 2; Section 2, pg.1060) and is therefore not eligible for inclusion in the National Register of Historic Places.

Based on the available information, as summarized above, no above-ground concerns exist.

#### **Archaeology Report Author/Date:**

Samuel P. Snell/September 6, 2019

#### **Summary of Archaeology Investigation Results:**

An archaeological records check and Phase Ia field reconnaissance (Snell 2019) were conducted by Metric personnel who meet the Secretary of the Interior's Professional Qualification Standards as per 36 CFR Part 61. The records check identified no previously recorded sites within or adjacent to the project area but determined that a portion of the current project area was previously examined. To account for any future design changes, an area larger than the anticipated project construction footprint was surveyed. Approximately 6.2 acres of land was examined through visual walkover survey, 5m interval pedestrian transects, one shovel test prove, and five soil cores. The northern half of the project area was found to contain either disturbed or eroded soils. The agricultural fields in the southern half were investigated through close interval pedestrian transects. No archaeological sites were identified and no further work was recommended. The report has been reviewed by INDOT Cultural Resources personnel who meet the Secretary of the Interior's Professional Qualification Standards as per 36 CFR Part 61. It is our opinion that the report is acceptable, and we concur with the evaluations and recommendations made by Snell (September 6, 2019). Therefore, there are no archaeological concerns.

Does the project appear to fall under the Minor Projects PA? yes	🛛 no	
--	------	--

If yes, please specify category and number (applicable conditions are highlighted):

- A-9. Installation, repair, or replacement of erosion control measures along roadways, waterways and bridge piers within previously disturbed soils.
- B-12. Replacement, widening, or raising the elevation of the superstructure on existing bridges, and bridge replacement projects (when both the superstructure and substructure are removed), under the following conditions [BOTH Condition A, which pertains to Archaeological Resources, and Condition B, which pertains to Above-Ground Resources, must be satisfied]:

#### **Condition A (Archaeological Resources)**

One of the two conditions listed below must be met (EITHER Condition i or Condition ii must be satisfied):

- i. Work occurs in previously disturbed soils; OR
- ii. Work occurs in undisturbed soils and an archaeological investigation conducted by the applicant and reviewed by INDOT Cultural Resources Office determines that no National Register-listed or potentially National Register-eligible archaeological resources are present within the project area. If the archaeological investigation locates National Register-listed or potentially National Register-eligible archaeological resources, then full Section 106 review will be required. Copies of any archaeological reports prepared for the project will be provided to the DHPA and any archaeological site form information will be entered directly into the SHAARD by the applicant. The archaeological reports will also be available for viewing (by Tribes only) on INSCOPE.

#### **Condition B (Above-Ground Resources)**

The conditions listed below must be met (BOTH Condition i and Condition ii must be satisfied)

- Work does not occur adjacent to or within a National Register-listed or National Register-eligible district or individual above-ground resource; *AND*
- ii. With regard to the subject bridge, at least one of the conditions listed below is satisfied (AT LEAST one of the conditions a, b or c, must be fulfilled):
  - a. The latest Historic Bridge Inventory identified the bridge as non-historic (see <a href="http://www.in.gov/indot/2531.htm">http://www.in.gov/indot/2531.htm</a>);
  - b. The bridge was built after 1945, and is a common type as defined in Section V. of the *Program Comment Issued for Streamlining Section 106 Review for Actions Affecting Post-1945 Concrete and Steel Bridges* issued by the Advisory Council on Historic Preservation on November 2, 2012 for so long as that Program Comment remains in effect AND the considerations listed in Section IV of the Program Comment do not apply;
- c. The bridge is part of the Interstate system and was determined not eligible for the National Register under the Section 106 Exemption Regarding Effects to the Interstate Highway System adopted by the Advisory Council on Historic Preservation on March 10, 2005, for so long as that Exemption remains in effect.

**Additional comments:** If any archaeological artifacts or human remains are uncovered during construction, demolition, or earthmoving activities, construction in the immediate area of the find will be stopped, and the INDOT Cultural Resources Office and the Division of Historic Preservation and Archaeology will be notified immediately.

#### INDOT Cultural Resources staff reviewer(s): Clint Kelly and Shaun Miller

\*\*\*Be sure to attach this form to the National Environmental Policy Act documentation for this project. Also, the NEPA documentation shall reference and include the description of the specific stipulation in the PA that qualifies the project as exempt from further Section 106 review.

# **APPENDIX E:**Red Flag and Hazardous Materials



## INDIANA DEPARTMENT OF TRANSPORTATION

100 North Senate Avenue Room N642 Indianapolis, Indiana 46204 PHONE: (317) 232-5113 FAX: (317) 233-4929 Eric Holcomb, Governor Joe McGuinness, Commissioner

Date: October 8, 2019

To: Site Assessment & Management

Environmental Policy Office - Environmental Services Division

Indiana Department of Transportation 100 N Senate Avenue, Room N642

Indianapolis, IN 46204

From: Kennita Jones

Metric Environmental 6971 Hillsdale Court Indianapolis, Indiana KennitaJ@metricenv.com

Re: RED FLAG INVESTIGATION

DES #: 1700173, State Project

Bridge Replacement, Existing INDOT Bridge No. 060-88-03069

State Road (SR) 60 over South Fork Blue River New Pekin, Washington County, Indiana

#### PROJECT DESCRIPTION

Brief Description of Project: Indiana Department of Transportation (INDOT) and Federal Highway Administration (FHWA) propose to utilize federal funds for a bridge replacement project. The project is located on SR 60 over South Fork Blue River in New Pekin, Washington County, Indiana. The existing structure, INDOT Bridge No. 060-88-03069, is a three-span, 193 ft. long concrete arch bridge with a 28 ft. clear roadway width and 2 ft. wide sidewalk with curb liner in both directions. According to the abbreviated engineer's report dated June 27, 2019, the existing bridge is in fair condition. The sidewalk and curb liner exhibit cracks, delamination, spalls, and exposed reinforcing steel, the existing arches exhibit minor cracking and efflorescence in all three spans and construction joints. There is cracking, scaling, and spalling in the south spandrel wall at piers 2 and 3 and on the north side of pier 2. The preferred alternative is to replace the existing bridge. The proposed replacement structure will be three-spans (58'-0", 75'-0", 58'-0") with a structure length of 191 feet, a clear roadway width of 32 feet, and skewed 15 degrees left. The approach roadway will have guardrails and concrete bridge railing transition. It is believed that up to 2 acres of right-of-way may be required for this project; however, the exact amount and locations have not been determined. Channel clearing will be required. SR 60 will be shifted approximately 18 feet upstream (east) from the existing alignment to accommodate maintenance of traffic. A single lane of traffic will be maintained during construction utilizing a temporary signal. Access will likely be restricted to SR 60 from John Street, Grove Street, and Poplar Street. The entrance to Sunoco from SR 60 will likely be closed, but the entrance from John Street will be maintained. The purpose of this project is to address the substandard condition of the existing bridge. The replacement structure for this project will be a three-span concrete bulb-tee beam structure. The current letting date for the project is scheduled for December of 2021.

Bridge and/or Culvert Project: Yes ⊠ No □ Structure # <u>060-88-03069</u>
If this is a bridge project, is the bridge Historical? Yes $\square$ No $\boxtimes$ , Select $\square$ Non-Select $\square$
(Note: If the project involves a historical bridge, please include the bridge information in the Recommendations
Section of the report).
Proposed right of way: Temporary $\boxtimes$ # Acres $\underline{}$ > 0.5 Permanent $\boxtimes$ # Acres $\underline{}$ > 0.5 Not Applicable $\square$
Type of excavation: Excavation will occur at a depth of approximately 19 feet for the removal of the existing structure.
Maintenance of traffic: A single lane of traffic across the bridge will be maintained during construction. Temporary
signals will be used to alert drivers. Access will likely be restricted to SR 60 from John Street, Grove Street, and Poplar
Street. The entrance to Sunoco from SR 60 will likely be closed, but the entrance from John Street will be maintained.
Work in waterway: Yes $oxtimes$ No $oxtimes$ Below ordinary high water mark: Yes $oxtimes$ No $oxtimes$
State Project: ⊠ LPA: □
Any other factors influencing recommendations: N/A

#### **INFRASTRUCTURE TABLE AND SUMMARY**

Infrastructure Indicate the number of items of concern found within the 0.5 mile search radius. If there are no items, please indicate N/A:				
Religious Facilities	5*	Recreational Facilities	1	
Airports <sup>1</sup>	N/A	Pipelines	N/A	
Cemeteries	N/A	Railroads	1	
Hospitals	N/A	Trails	N/A	
Schools	N/A	Managed Lands	N/A	

<sup>&</sup>lt;sup>1</sup>In order to complete the required airport review, a review of public airports within 3.8 miles (20,000 feet) is required.

<u>Religious Facilities</u>: Although not mapped on the Indiana GIO database, five (5) religious facilities are located within the 0.5-mile search radius. The nearest feature, Merrill Bright Tabernacle-God is located approximately 0.16-mile northeast of the project area at 173 East Main Street. No impact is expected.

<u>Recreational Facilities</u>: One (1) recreational facility is located within the 0.5-mile search radius. The feature is located approximately 0.23-mile northwest of the project area. No impact is expected.

<u>Railroads</u>: One (1) railroad segment is located within the 0.5-mile search radius. The segment is located approximately 0.07-mile east of the project area. No impact is expected.

#### WATER RESOURCES TABLE AND SUMMARY

Water Resources			
Indicate the number of items of	concern found wit	hin the 0.5 mile search radius. If the	ere are no items,
please indicate N/A:			
NWI - Points	N/A	Canal Routes - Historic	N/A
Karst Springs	N/A	NWI - Wetlands	11
Canal Structures – Historic	N/A	Lakes	4
NPS NRI Listed	N/A	Floodplain - DFIRM	1
NWI-Lines	11	Cave Entrance Density	N/A
IDEM 303d Listed Streams and Lakes (Impaired)	N/A	Sinkhole Areas	N/A
Rivers and Streams	22	Sinking-Stream Basins	N/A

www.in.gov/dot/

<u>NWI – Lines</u>: Eleven (11) NWI – Line segments are located within the 0.5-mile search radius. One segment is located within the project area. A Waters of the US Report will be prepared and coordination with INDOT ES Ecology and Waterway Permitting will occur.

<u>Rivers and Streams</u>: Twenty-two (22) river and stream segments are located within the 0.5-mile search radius. One segment is located within the project area. A Waters of the US Report will be prepared and coordination with INDOT ES Ecology and Waterway Permitting will occur.

<u>NWI – Wetlands</u>: Eleven (11) NWI – Wetlands are located within the 0.5-mile search radius. One wetland is located approximately 0.35-mile west of the project area. No impact is expected.

<u>Lakes</u>: Four (4) lake features are located within the 0.5-mile search radius. The nearest feature is located approximately 0.45-mile west of the project area. No impact is expected.

<u>Floodplain – DFIRM</u>: One (1) floodplain polygon is located within the 0.5-mile search radius. The project area is located within a floodplain polygon. Coordination with INDOT ES Ecology and Waterway Permitting will occur.

#### **URBANIZED AREA BOUNDARY SUMMARY**

N/A

#### MINING AND MINERAL EXPLORATION TABLE AND SUMMARY

Mining/Mineral Exploration					
Indicate the number of items of concern found within the 0.5 mile search radius. If there are no items,					
please indicate N/A:					
Petroleum Wells	N/A	Mineral Resources	N/A		
Mines – Surface	N/A	Mines – Underground	N/A		

Explanation: No Mining/Mineral Exploration resources were identified within the 0.5-mile search radius.

#### HAZARDOUS MATERIAL CONCERNS TABLE AND SUMMARY

Hazardous Material Concerns

Indicate the number of items of conc please indicate N/A:	ern found wit	hin the 0.5 mile search radius. If there	are no items,
Superfund	N/A	Manufactured Gas Plant Sites	N/A
RCRA Generator/ TSD	N/A	Open Dump Waste Sites	N/A
RCRA Corrective Action Sites	N/A	Restricted Waste Sites	N/A
State Cleanup Sites	N/A	Waste Transfer Stations	N/A
Septage Waste Sites	N/A	Tire Waste Sites	N/A
Underground Storage Tank (UST) Sites	3*	Confined Feeding Operations (CFO)	N/A
Voluntary Remediation Program	N/A	Brownfields	N/A
Construction Demolition Waste	N/A	Institutional Controls	N/A
Solid Waste Landfill N/A		NPDES Facilities	N/A
Infectious/Medical Waste Sites	N/A	NPDES Pipe Locations	N/A
Leaking Underground Storage (LUST) Sites	N/A	Notice of Contamination Sites	N/A

www.in.gov/dot/ **An Equal Opportunity Employer**  <u>Underground Storage (UST) Site</u>: Although not included in the GIO database, three (3) UST sites are located within the 0.5-mile search radius. The closest feature is an unmapped Robert McCarty Sunoco (AI ID#: 59124, FID#: 15537) which adjoins the project area to the west at 545 E SR 60. The most recent Underground Storage Tank Inspection Report (document #: 80414456) dated January 30, 2017, identified one (1) 8,000 gallon gasoline UST and one (1) 10,000 gallon gasoline UST registered for use at the site. The USTs are fiberglass and were installed at the facility in 1991. No violations were identified during the January 2017 inspection. No impact is expected.

Phillips 66, E. Main Street and Blue River Road, #019076 (AI ID#: 58840, Regulatory ID#: 7669) was formerly the site of a gas station. According to the IDEM Virtual File Cabinet (VFC), Phillips 66 is located in Salem, Indiana; however, the intersection of Main Street and Blue River does not exist in Salem. Therefore, it appears that this site is mapped correctly. According to the IDEM VFC, Phillips 66 operated a gas station at the site pre-1985. In 1986, three gasoline tanks and one used oil tank, all temporarily out of use, were reported to be on-site. On May 2, 2017 IDEM informed the owner, via letter, that an inspector with the IDEM UST Section would be conducting an inspection at the facility within the next 30 to 45 days. On August 21, 2017, the property owner sent a letter to IDEM UST Section indicating that he bought the property on April 15, 1985 and approximately May or June 1985 the tank or tanks were removed, the hole was filled with limestone gravel, and paved over for parking. This contradicts the tank certification form dated April 3, 1986. No other correspondence is located in the VFC pertaining to this site. No impact is expected.

#### **ECOLOGICAL INFORMATION SUMMARY**

The Washington County listing of the Indiana Natural Heritage Data Center information on endangered, threatened, or rare (ETR) species and high quality natural communities is attached with ETR species highlighted. A preliminary review of the Indiana Natural Heritage Database by INDOT Environmental Services did not indicate the presence of ETR species within the 0.5 mile search radius. Coordination with USFWS and IDNR will occur.

A review of the USFWS database did not indicate the presence of endangered bat species in or within 0.5-mile of the project area. The northern project area is located in a residential and commercial and the southern project area is surrounded by farm fields. The July 2, 2019 inspection report for Bridge #060-88-03069 states that no evidence of bats was seen or heard under the bridge. The range-wide programmatic consultation for the Indiana Bat and Northern Longeared Bat will be completed according to "Using the USFWS's IPaC System for Listed Bat Consultation for INDOT Projects'.

An inquiry using the USFWS Information for Planning and Consulting (IPaC) website did not indicated that the presence of the federal endangered species, the Rusty Patched Bumble Bee, in or within 0.5-mile of the projects area. No impact is expected.

#### RECOMMENDATIONS SECTION

Include recommendations from each section. If there are no recommendations, please indicate N/A:

INFRASTRUCTURE: N/A

WATER RESOURCES: The presence of following water resources will require the preparation of a Waters of the US Report and coordination with INDOT ES Ecology and Waterway Permitting:

- One (1) NWI Line segment flows through the project area.
- One (1) stream segment, South Fork of Blue River, flows through the project area.
- The project area is located within a floodplain (Coordination Only).

www.in.gov/dot/ **An Equal Opportunity Employer**  URBANIZED AREA BOUNDARY: N/A

MINING/MINERAL EXPLORATION: N/A

HAZMAT CONCERNS: N/A

ECOLOGICAL INFORMATION: Coordination with USFWS and IDNR will occur. The range-wide programmatic consultation for the Indiana Bat and Northern Long-eared Bat will be completed according to "Using the USFWS's IPaC System for Listed Bat Consultation for INDOT Projects"

(Signature)

INDOT Environmental Services concurrence:

| Digitally signed by Ronald Bales | Bales | Digitally signed by Ronald Bales

Prepared by: Kennita Jones Project Manager Metric Environmental

#### **Graphics:**

A map for each report section with a 0.5 mile search radius buffer around all project area(s) showing all items identified as possible items of concern is attached. If there is not a section map included, please change the YES to N/A:

SITE LOCATION: YES

**INFRASTRUCTURE: YES** 

WATER RESOURCES: YES


URBANIZED AREA BOUNDARY: N/A

MINING/MINERAL EXPLORATION: N/A

**HAZMAT CONCERNS: YES** 

www.in.gov/dot/ **An Equal Opportunity Employer** 

# Red Flag Investigation - Site Location SR 60 over South Fork Blue River (Bridge No. 060-88-03069) Des. No. 1700173, Bridge Replacement Washington County, Indiana



Sources: 0.3 0.15 0 0.3

Non Orthophotography


Data - Obtained from the State of Indiana Geographical Information Office Library
Orthophotography - Obtained from Indiana Map Framework Data (www.indianamap.org)


Map Projection: UTM Zone 16 N Map Datum: NAD83
This map is intended to serve as an aid in graph

This map is intended to serve as an aid in graphic representation only. This information is not warranted for accuracy or other purposes.

PALMYRA QUADRANGLE INDIANA 7.5 MINUTE SERIES (TOPOGRAPHIC)


# Red Flag Investigation - Infrastructure SR 60 over South Fork Blue River (Bridge No. 060-88-03069) Des. No. 1700173 , Bridge Replacement Washington County, Indiana







# Red Flag Investigation - Water Resources SR 60 over South Fork Blue River (Bridge No. 060-88-03069) Des. No. 1700173, Bridge Replacement Washington County, Indiana



# Red Flag Investigation - Hazardous Material Concerns SR 60 over South Fork Blue River (Bridge No. 060-88-03069) Des. No. 1700173, Bridge Replacement Washington County, Indiana





0.15 0.075 0.15

<u>Non Orthophotography</u> **Data** - Obtained from the State of Indiana Geographical Information Office Library

## **Indiana County Endangered, Threatened and Rare Species List**

County: Washington

Species Name		Common Name FEE		STATE	GRANK	SRANK
Platyhelminthes (Flatworms)					C4	62
Sphalloplana weingartneri		Weingartner's Cave Flatworm		WL	G4	S3
Diplopoda						
Conotyla bollmani		Bollman's Cave Milliped		WL	G5	S3
Pseudotremia indianae		Blue River Cave Milliped		WL	G4	S4
Crustacean: Malacostraca					G.4	
Crangonyx packardi		Packard's Cave Amphipod		WL	G4	S3
Miktoniscus barri		Barr's Terrestrial Isopod		WL	G2G4	SNR
Orconectes inermis inermis		A Troglobitic Crayfish		WL	G5T4	S3
Crustacean: Copepoda <mark>Diacyclops jeanneli</mark>		Jeannel's Cave Copepod		ST	G3G4	S2
Crustacean: Ostracoda						
Dactylocythere susanae		An Ostracod		WL	G2G4	S3
<mark>seudocandona jeanneli</mark>		Jeannel's Cave Ostracod		SE	G2	<b>S1</b>
Sagittocythere barri		Barr's Commensal Cave Ostracod		WL	G5	S3S4
Mollusk: Bivalvia (Mussels)						
Cyprogenia stegaria		Eastern Fanshell Pearlymussel	LE	SE	G1Q	<u>S1</u>
<mark>pioblasma torulosa</mark>		Tubercled Blossom	LE	SX	GX	SX
usconaia subrotunda		Longsolid	C	SX	G3	SX
ampsilis fasciola		Wavyrayed Lampmussel		SSC	G5	S3
igumia recta		Black Sandshell			G4G5	S2
Obovaria subrotunda		Round Hickorynut	C	SE	G4	S1
P <mark>leurobema clava</mark>		Clubshell	LE	SE	G1G2	<b>S</b> 1
leurobema rubrum		Pyramid Pigtoe		SX	G2G3	SX
Ptychobranchus fasciolaris		Kidneyshell		SSC	G4G5	S2
Simpsonaias ambigua		Salamander Mussel	C	SSC	G3	S2
'illosa lienosa		Little Spectaclecase		SSC	G5	S3
Mollusk: Gastropoda						
Carychium riparium		Floodplain Thorn			G2	SNR
Zonitoides kirbyi		Shadow Gloss			G2	SNR
Ellipluran: Collembola						
Arrhopalites ater		Black Medusa Cave Springtail		ST	G2	S2
rrhopalites benitus		A Springtail		WL	G1	S1
<mark>rrhopalites lewisi</mark>		Lewis' Cave Springtail		ST	GNR	S2
olsomia prima		Primitive Springtail		WL	GNR	S4
olsomides americanus		Small Springtail		SE	GNR	S1
lypogastrura horrida		Bristly Springtail		WL	GNR	SNR
sotoma anglicana		A Springtail		WL	GNR	SNR
sotoma caeruleatra		Blue Springtail		WL	GNR	SNR
ndiana Natural Heritage Data Center Division of Nature Preserves Indiana Department of Natural Resources This data is not the result of comprehensive county Surveys.	Fed: State: GRANK: SRANK:	LE = Endangered; LT = Threatened; C = candid SE = state endangered; ST = state threatened; SF SX = state extirpated; SG = state significant; WI Global Heritage Rank: G1 = critically imperiled globally; G4 = widespread and abundant globall; globally; G? = unranked; GX = extinct; Q = unc State Heritage Rank: S1 = critically imperiled in G4 = widespread and abundant in state but with	L = state rare; SSC L = watch list globally; G2 = ir y but with long to ertain rank; T = t state; S2 = imper	C = state specie  mperiled globall  erm concerns; G  taxonomic subu  riled in state; S3	s of special conce y; G3 = rare or ur 5 = widespread an nit rank 3 = rare or uncom	ncommon nd abundant mon in state;

unranked

state; SX = state extirpated; B = breeding status; S? = unranked; SNR = unranked; SNA = nonbreeding status

## Indiana County Endangered, Threatened and Rare Species List County: Washington

Species Name		Common Name FED		STATE	GRANK	SRANK	
Isotoma nigrifrons		Dark Springtail		WL	GNR	SNR	
Isotoma nixoni		Nixon's Springtail		WL	GNR	SNR	
sotoma torildae				WL	GNR	SNR	
Onychiurus casus		Fallen Springtail		WL	GNR	S4	
Onychiurus reluctus		A Springtail		WL	GNR	S4	
Pseudosinella collina		Hilly Springtail		SR	GNR	S2?	
Pseudosinella fonsa		Fountain Cave Springtail		ST	G3G4	S2	
Sinella alata		Springtail		WL	G5	S4	
Sinella cavernarum		A Springtail		WL	G5	S3	
nsect: Coleoptera (Beetles)							
Aleochara lucifuga		Rove beetle		WL	GNR	S4	
<mark>lecrophilus pettiti</mark>		A Carrion Beetle		ST	GNR	S1?	
Pseudanophthalmus stricticollis		Marengo Cave Ground Beetle		WL	G4	S3	
Pseudanophthalmus tenuis		Cave Beetle		WL	G4	S4	
Pseudanophthalmus youngi		Young's cave ground beetle		SR	G3G4	S2	
nsect: Lepidoptera (Butterflies & Moths) Erynnis martialis		Mottled Duskywing		WL	G3	S3	
		Mothed Basky wing		2			
Arachnida Bathyphantes weyeri		A Cave Spider			G4	SNR	
Cicurina arcuata		A Cave Spider  A Funnel-web Weaver			G5	S1	
desperochernes mirabilis		Southeastern Cave Pseudoscorpion		WL	G5	S4	
eptochthonius packardi		Packard's Cave Pseudoscorpion		SE	G2G3	<u>S2</u>	
Fish							
Amblyopsis hoosieri		Hoosier cavefish	C	SE	G2	S1	
Etheostoma maculatum		Spotted Darter		SSC	G2G3	S2S3	
Etheostoma variatum		Variegate Darter		SE	G5	S1	
lotropis ariommus		Popeye Shiner			G3	SX	
Amphibian							
Acris blanchardi		Blanchard's Cricket Frog		SSC	G5	S4	
<mark>Cryptobranchus alleganiensis alleganiens</mark>	sis	Eastern Hellbender	$\mathbf{C}$	SE	G3G4T3T4	S1	
lecturus maculosus		Common mudpuppy		SSC	G5	S2	
Reptile							
C <mark>lonophis kirtlandii</mark>		Kirtland's Snake		SE	G2	S2	
Nerodia erythrogaster neglecta		Copperbelly Water Snake	PS:LT	SE	G5T3	S2	
Opheodrys aestivus		Rough Green Snake		SSC	G5	S3	
errapene carolina carolina		Eastern Box Turtle		SSC	G5T5	S3	
Bird							
Aimophila aestivalis		Bachman's Sparrow			G3	SXB	
Indiana Natural Heritage Data Center	Fed:	LE = Endangered; LT = Threatened; C = candida					
Division of Nature Preserves Indiana Department of Natural Resources	State:	SE = state endangered; ST = state threatened; SF SX = state extirpated; SG = state significant; WI		= state species	s of special concern:		
This data is not the result of comprehensive county	GRANK:	Global Heritage Rank: G1 = critically imperiled	globally; G2 = imp				
surveys.		globally; G4 = widespread and abundant globally globally; G? = unranked; GX = extinct; Q = unc	_			abundant	
	SRANK:	State Heritage Rank: $S1 =$ critically imperiled in				n in state;	
		G4 = widespread and abundant in state but with state: SX = state extirpated: B = breeding status:	_				

unranked

state; SX = state extirpated; B = breeding status; S? = unranked; SNR = unranked; SNA = nonbreeding status

## **Indiana County Endangered, Threatened and Rare Species List**

County: Washington

Species Name Common Name		Common Name	FED	STATE	GRANK	SRANK
Ammodramus henslowii		Henslow's Sparrow		SE	G4	S3B
Cistothorus platensis		Sedge Wren		SE	G5	S3B
Haliaeetus leucocephalus		Bald Eagle		SSC	G5	S2
Helmitheros vermivorus		Worm-eating Warbler		SSC	G5	S3B
Setophaga cerulea		Cerulean Warbler		SE	G4	S3B
Setophaga citrina		Hooded Warbler		SSC	G5	S3B
Tyto alba		Barn Owl		SE	G5	S2
Mammal Corynorhinus rafinesquii		Rafinesque's Big-eared Bat		SSC	G3G4	SH
Myotis austroriparius		Southeastern Bat		SSC	G4	SH
Myotis lucifugus		Little Brown Bat	C	SE	G3	S2
Myotis septentrionalis		Northern Long Eared Bat	LT	SE	G1G2	S2S3
Myotis sodalis		Indiana Bat	LE	SE	G2	S1
Perimyotis subflavus		Tricolored Bat		SE	G2G3	S2S3
Sorex hoyi		Pygmy Shrew		SSC	G5	S2
Taxidea taxus		American Badger		SSC	G5	S2
Vascular Plant						
Aconitum uncinatum		Blue Monkshood		SE	G4	S1
Bacopa rotundifolia		Roundleaf Water-hyssop		ST	G5	S2
Calamagrostis porteri ssp. insperata		Reed Bent Grass		SE	G4T3	S1
Carex straminea		Straw Sedge		ST	G5	S2
Chelone obliqua var. speciosa		Rose Turtlehead		WL	G4T3	S3
Crataegus iracunda		Illinois Hawthorn		SE	GNR	S1
Cuscuta cuspidata		Cusp Dodder		SE	G5	S1
Diervilla Ionicera		Northern Bush-honeysuckle		WL	G5	S3
Eleocharis bifida		Glades spikerush		SE	G3G4	S1
Hexalectris spicata		Crested Coralroot		SR	G5	<b>S3</b>
Juncus secundus		Secund Rush		SE	G5?	S1
Lathyrus venosus		Smooth Veiny Pea		SE	G5	S1
Linum sulcatum		Grooved Yellow Flax		SR	G5	<b>S3</b>
Magnolia acuminata		Cucumber Magnolia		SE	G5	S1
Matelea obliqua		Angle Pod		SR	G4?	<b>S3</b>
Oenothera triloba		Stemless Evening-primrose		SX	G4	SX
Ophioglossum engelmannii		Limestone Adder's-tongue		SR	G5	<b>S3</b>
Pachysandra procumbens		Allegheny Spurge		SE	G4G5	S1
Penstemon deamii		Deam Beardtongue		ST	G1	S2
Pleopeltis polypodioides		Resurrection Fern		WL	G5	S3
Polygala incarnata		Pink Milkwort		SE	G5	S1
Schoenoplectiella purshiana		Weakstalk Bulrush		SR	G4G5	S3
Silene regia		Royal Catchfly		SE	G3	S1
Indiana Natural Heritage Data Center Division of Nature Preserves Indiana Department of Natural Resources This data is not the result of comprehensive county surveys.	Fed: State: GRANK: SRANK:	LE = Endangered; LT = Threatened; C = candi SE = state endangered; ST = state threatened; S SX = state extirpated; SG = state significant; W Global Heritage Rank: G1 = critically imperiled globally; G4 = widespread and abundant global globally; G? = unranked; GX = extinct; Q = ur State Heritage Rank: S1 = critically imperiled in G4 = widespread and abundant in state but with	R = state rare; SSC L = watch list d globally; G2 = ir lly but with long te acertain rank; T = t n state; S2 = imper	C = state species  nperiled globall  erm concerns; G  axonomic subu  riled in state; S3	s of special conce y; G3 = rare or ur 5 = widespread an nit rank 8 = rare or uncom	acommon nd abundant non in state;
		G4 = widespread and abundant in state but with state: SX = state extirpated: B = breeding status	-			

unranked

state; SX = state extirpated; B = breeding status; S? = unranked; SNR = unranked; SNA = nonbreeding status

Page 4 of 4 05/09/2019

## Indiana County Endangered, Threatened and Rare Species List

County: Washington

Species Name	Common Name	FED	STATE	GRANK	SRANK
Thalictrum pubescens	Tall Meadowrue		SR	G5	S3
Tragia cordata	Heart-leaved Noseburn		WL	G4	S3
Waldsteinia fragarioides	Barren Strawberry		SR	G5	S3
Woodwardia areolata	Netted Chainfern			G5	<b>S3</b>
High Quality Natural Community Barrens - bedrock limestone	Limestone Glade		SG	G4	S2S3
Barrens - bedrock siltstone	Siltstone Glade		SG	G2	S2
Barrens - chert	Chert Barrens		SG	G2	S1
Forest - upland dry-mesic Highland Rim	Highland Rim Dry-mesic Upland Forest		SG	GNR	S3
Forest - upland mesic Highland Rim	Highland Rim Mesic Upland Forest		SG	GNR	S3
Primary - cave aquatic	Aquatic Cave		SG	GNR	SNR
Primary - cave terrestrial	Terrestrial Cave		SG	GNR	SNR
Primary - cliff limestone	Limestone Cliff		SG	GU	S1

Indiana Natural Heritage Data Center Division of Nature Preserves Indiana Department of Natural Resources This data is not the result of comprehensive county surveys.

Fed: LE = Endangered; LT = Threatened; C = candidate; PDL = proposed for delisting

SE = state endangered; ST = state threatened; SR = state rare; SSC = state species of special concern;

 $SX = state \ extirpated; \ SG = state \ significant; \ WL = watch \ list$ 

GRANK: Global Heritage Rank: G1 = critically imperiled globally; G2 = imperiled globally; G3 = rare or uncommon

globally; G4 = widespread and abundant globally but with long term concerns; G5 = widespread and abundant

globally; G? = unranked; GX = extinct; Q = uncertain rank; T = taxonomic subunit rank

SRANK: State Heritage Rank: S1 = critically imperiled in state; S2 = imperiled in state; S3 = rare or uncommon in state;  $G4 = wide spread \ and \ abundant \ in \ state \ but \ with \ long \ term \ concern; \ SG = state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ in \ state \ significant; \ SH = historical \ state \ significant; \ SH = historical \ state \ significant; \ SH = historical \ state \ state \ significant; \ SH = historical \ state \ state$ 

state; SX = state extirpated; B = breeding status; S? = unranked; SNR = unranked; SNA = nonbreeding status

unranked

State:

# **APPENDIX F:**Water Resources

## WATERS DETERMINATION REPORT

# S.R. 60 OVER SOUTH FORK OF THE BLUE RIVER BRIDGE PROJECT DES. NO. 1700173 PIERCE AND POLK TOWNSHIP, WASHINGTON COUNTY, INDIANA

**Prepared for:** HNTB Corporation

November 4, 2019



**Metric Environmental, LLC** 

**Complex Environment. Creative Solutions.** 

6971 Hillsdale Court Indianapolis, IN 46256 Telephone: 317.207.4286 www.metricenv.com

## **Contents**

Date of Waters Field Investigation	1
Location	
National Wetlands Inventory (NWI) Information	
Karst Feature Information	
USGS National Hydrography Dataset (NHD) Information	
FEMA Flood Insurance Rate Map (FIRM)	2
Soils	2
Attached Documents	
Project Description	2
Field Reconnaissance	2
Wetlands	3
Sampling Points	3
Roadside Ditches	<del>(</del>
Conclusion	6
Acknowledgements	7



F-2



## WATERS OF THE U.S. DETERMINATION REPORT S.R. 60 over the South Fork of the Blue River Bridge Project

Pierce and Polk Township, Washington County, Indiana Des. No. 1700173

Prepared By: Zachary Root, Metric Environmental, LLC November 4, 2019

**Date of Waters Field Investigation:** August 7, 2019

## Location:

Section 25 & 30; Township 1 North; Range 4 & 5 East

Palmyra, IN 7.5 minute U.S.G.S. Topographic Quadrangles (Exhibit 2)

Pierce and Polk Township, Washington County, Indiana

12-Digit HUC Watershed: 051401040602

Latitude: 38.4994645 Longitude: -86.0131954

## **National Wetlands Inventory (NWI) Information:**

One mapped NWI polygon is located within the project study limits (PSL), listed in the table below. The NWI mapped polygon is associated with the South Fork of the Blue River. The NWI map is provided as **Exhibit 3**.

Symbol	Wetland Type	Location within PSL	Corresponding Feature
R2UBH	Riverine, Lower Perennial, Unconsolidated Bottom, Permanently Flooded	Central	South Fork Blue River


## **Karst Feature Information:**

No mapped karst features were found within 0.5 mi. of the PSL during the desktop review.

## **USGS National Hydrography Dataset (NHD) Information:**

Three mapped NHD flowlines are located within the PSL, listed by occurrence from east to west within the PSL in the table below. The NHD map is provided in **Exhibit 3**.

Corresponding Feature	NHD Flowline Classification	Photo Nos.	USGS Blue line
South Fork of Blue River	Artificial Path	10-14, 27-36	Yes
Culvert 1, RSD 1, Honeycomb Drain	Canal/Ditch	3, 5-9	No
RSD 2	Stream/River	14-18	No



Des. No. 1700173

Pierce and Polk Township, Washington County, Indiana

Metric Project No. 18-0022-3



## **FEMA Flood Insurance Rate Map (FIRM):**

One mapped floodplain, the floodplain of the South Fork of Blue River, covers the majority of the PSL. This area is identified as Zone A, an area subject to inundation by the 1 percent annual chance of flood. The FIRM map for this area is provided as **Exhibit 3**.

## Soils:

According to the Natural Resources Conservation Service (NRCS) Soil Survey Geographic (SSURGO) Database for Washington County, Indiana, the PSL contained three mapped soil units, listed in the table below. The NRCS soil survey map is provided as **Exhibit 3**.

Symbol	Map unit name	Hydric Rating
Ва	Bartle silt loam, 0 to 2 percent slopes	Hydric (3%)
Cu	Cuba silt loam, frequently flooded	Hydric (3%)
Sf	Stendal silt loam, 0 to 2 percent slopes, frequently flooded, brief duration	Hydric (2%)

## **Attached Documents:**

Maps of the project area (Exhibits 1-4)
Photo Location Map (Exhibit 5)
Site Photographs
Wetland Determination Data Form(s)
Preliminary Jurisdictional Determination Form

## **Project Description:**

The proposed project (Des. No. 1700173) includes replacement of the existing bridge (INDOT Bridge No. 060-88-03069) with a three-spans bridge (58 ft., 75 ft., 58 ft.) with a total structure length of 192.6 ft., a clear roadway width of 32 ft., and skewed 15 degrees left. The approach roadway will have guardrails and concrete bridge railing transition. Channel clearing will be required. SR 60 will be shifted approximately 18 ft. upstream (east) from the existing alignment to accommodate existing bridge removal and maintenance of traffic.

## **Field Reconnaissance:**

The wetland determination field visit was conducted on August 7, 2019 by Zachary Root of Metric Environmental, LLC. The PSL consists of the area that has the potential to be impacted, based on the provided design scenario. This area was evaluated for the presence of wetlands and Waters of the United States. This investigation was conducted in accordance with the 1987 U.S. Army Corps of Engineers (USACE) Wetland Delineation Manual and the April 2012 Eastern Mountains and Piedmont Region (version 2.0) Manual.

A Location Map showing the project location is provided as **Exhibit 1**. The proposed project is located in the southeastern tip of Washington County, Indiana, on S.R. 60 approximately 0.42 mi. west of S.R. 335. The PSL extended from the center of the structure along S.R. 60 to the northwest

S.R. 60 over South Fork of the Blue River

Bridge Project Des. No. 1700173

Pierce and Polk Township, Washington County, Indiana

Metric Project No. 18-0022-3



approximately 650 ft. and to the southeast 740 ft. The PSL extends from 50 ft. to 120 ft. perpendicular to S.R. 60. An aerial map of sampling points and water features is provided as **Exhibit 4**. A photo location map is provided as **Exhibit 5** and site photographs are attached.

The site was investigated for evidence of hydrophytic vegetation, hydric soil, and wetland hydrology to determine if the project impacts wetlands and other Waters of U.S. The sampling point (SP) locations were chosen in possible wetland areas within the PSL. The upland areas consisted of deciduous forest, agricultural field, and residential lawn. Upland areas where sampling points were not taken, were investigated and determined to be upland due to upward sloping topography and presence of dominant upland vegetation. Five sampling points were taken and identified as SP-1, SP-2, SP-3, SP-4, and SP-5. The sampling points, recorded on the USACE Wetland Determination Data Forms and shown on **Exhibit 4**, provided the following information:

# Sampling Plot Data Summary Table S.R. 60 over South Fork of the Blue River Bridge Project Pierce and Polk Township, Washington County, Indiana Des. No. 1700173

Plot #	Photo #s	Lat/Long	Hydrophytic Vegetation	Hydric Soils	Wetland Hydrology	Within Wetland
SP-1	39-41	38.49937 -86.01301	Yes	No	Yes	No
SP-2	42-44	38.49808 -86.01217	No	No	Yes	No
SP-3	45-47	38.49917 -86.01321	Yes	No	No	No
SP-4	48-50	38.49941 -86.01336	Yes	No	No	No
SP-5	51-53	38.49971 -86.01311	No	No	No	No

## Wetlands:

No wetlands were observed within the PSL.

## **Sampling Points:**

Five sampling points were taken in areas where wetlands were suspected but did not meet the three wetland criteria. A description of this sampling points is included below.

## Sampling Point 1 (SP-1)

SP-1 was located east of S.R. 60, within the floodplain on a terrace south of the South Fork of the Blue River. The dominant vegetation at this sampling point was silver maple (*Acer saccharinum*, FACW) in the tree stratum; great ragweed (*Ambrosia trifida*, FAC) and reed canary grass (*Phalaris* 

S.R. 60 over South Fork of the Blue River

Bridge Project Des. No. 1700173

Pierce and Polk Township, Washington County, Indiana

Metric Project No. 18-0022-3 Page **3** of **7** 



arundinacea, FACW) and Japanese hops (Humulus japonicus, FACU) in the herb stratum. This plot passes the dominance test for hydrophytic vegetation as 67 percent of dominant species are FAC or wetter. To a depth of 20 inches, the soil in the test pit was a silty clay loam. From 0 to 20 in., the soil exhibited a matrix color of 10YR 5/3 (100 percent). This did not meet the criteria for hydric soil. One primary indicator of wetland hydrology, drift deposits (B3), and two secondary indicators of wetland hydrology, drainage patterns (B10) and FAC-Neutral test (D5), were observed. Since the hydric soil was not met, this area did not qualify as a wetland.

## Sampling Point 2 (SP-2)

SP-2 was located east of S.R. 60, within a likely manmade concave depression in agricultural field south of South Fork Blue River. The dominant vegetation at this sampling point was soybean (Glycine max, NI) and wild cucumber (Echinocystis lobata, FACU) in the herb stratum. This did not meet any of the criteria for hydrophytic vegetation. To a depth of 20 inches, the soil in the test pit was silty clay loam. From 0 to 20 in., the soil exhibited a matrix color of 10YR 5/3 (90 percent) with faint redox concentrations of 10YR 4/4 (10 percent) in the matrix. This did not meet the criteria for hydric soil. Three secondary indicators; surface soil cracks (B6), drainage patterns (B10) and stunted or stressed plants (D1) were observed. Historical aerial imagery shows stunted or stressed plants were present two of the last eight years of imaging. This indicates infrequent flooding for short durations in the area surrounding the sampling point. However, due to the lack of hydrophytic vegetation and hydric soils, it is not likely this area receives the frequency or duration of flooding to warrant a farmed wetland. Since the hydrophytic vegetation and hydric soil were not met, this area did not qualify as a wetland.

## Sampling Point 3 (SP-3)

SP-3 was located west of S.R. 60, within the floodplain on a terrace south of the South Fork of the Blue River. The dominant vegetation at this sampling point was silver maple (Acer saccharinum, FACW) in the tree stratum, reed canary grass (Phalaris arundinacea, FACW) and great ragweed (Ambrosia trifida, FAC), and Japanese hops (Humulus japonicus, FACU) in the herb stratum. This plot passes the dominance test for hydrophytic vegetation as 75 percent of dominant species are FAC or wetter. To a depth of 20 in., the soils in the test pit was a silty clay loam. From 0 to 20 in., the soil exhibited a matrix color of 10YR 4/3 (100 percent). This did not meet the criteria for hydric soil. One secondary indicators of wetland hydrology, geomorphic position (D2), was observed. Since hydric soil and wetland hydrology were not met, this area did not qualify as a wetland.

## Sampling Point 4 (SP-4)

SP-4 was located west of S.R. 60, within the floodplain on a terrace north of the South Fork of the Blue River. The dominant vegetation at this sampling point was boxelder (Acer negundo, FAC) and American elm (Ulmus Americana, FACW) in the sapling/shrub stratum and great ragweed (Ambrosia trifida, FAC), American hog-peanut (Amphicarpaea bracteate, FAC), and Johnson grass (Sorghum halepense, FACU) in the herb stratum. This plot passes the dominance test for hydrophytic vegetation as 80 percent of dominant species are FAC or wetter. To a depth of 20

S.R. 60 over South Fork of the Blue River **Bridge Project** Des. No. 1700173 Pierce and Polk Township, Washington County, Indiana

Metric Project No. 18-0022-3



in., the soils in the test pit was a silty clay loam. From 0 to 20 in., the soil exhibited a matrix color of 10YR 4/3 (100 percent). This did not meet the criteria for hydric soil. One secondary indicator of wetland hydrology, geomorphic position (D2), was observed. Since the hydric soil and wetland hydrology were not met, this area did not qualify as a wetland.

## Sampling Point 5 (SP-5)

SP-5 was located east of S.R. 60, on the top of a slope within the floodplain north of the South Fork of the Blue River. SP-5 was taken within the mapped R2UBH wetland. The dominant vegetation at this sampling point was silver maple (*Acer saccharinum*, FACW) in the tree stratum, black walnut (*Juglans nigra*, FACU) and black cherry (*Prunus serotina*, FACU) in the sapling/shrub stratum, and ground ivy (*Glechoma hederacea*, FACU) in the herb stratum. This did not meet any of the criteria for hydrophytic vegetation. To a depth of 20 in., the soils in the test pit were a silty clay loam. From 0 to 20 in., the soil exhibited a matrix color of 10YR 5/4 (100 percent). This did not meet the criteria for hydric soil. No indicators of wetland hydrology were observed. Since none of the three wetland criteria were met, this area did not qualify as a wetland.

## **Streams:**

One stream, South Fork of the Blue River, was observed within the PSL during the field reconnaissance. Descriptions of the stream is provided below.

# Stream Summary Table S.R. 60 over South Fork of the Blue River Bridge Project Pierce and Polk Township, Washington County, Indiana Des. No. 1700173

Stream Name	Photos	Lat/Long	OHWM Width	OHWM Depth	USGS Blue- line	Riffles Pools	Quality	Likely Water of the U.S.	Substrate	Potential Stream Impact
			ft.	ft.				0.5.		ft.
South Fork of the Blue River	10-14, 27-36	38.499421 -86.013179	42	1	Yes (Perennial)	Yes	Average	Yes	Boulder slabs, Cobble, Gravel, and Silt	265

## **South Fork of the Blue River (265 LFT)**

The South Fork of the Blue River flows from northeast to southwest and is approximately 265 linear feet in length (0.256 ac.) within the PSL. The South Fork of the Blue River flows southwest into the Blue River, a Section 10 Traditional Navigable Water (TNW). Therefore, the South Fork of the Blue River should be considered a jurisdictional Water of the U.S. The South Fork of the Blue River is associated with a solid blue line on the USGS topographic map, indicating it is perennial. The South Fork of the Blue River was classified by the NWI as a Riverine, Lower

S.R. 60 over South Fork of the Blue River

Bridge Project Des. No. 1700173

Pierce and Polk Township, Washington County, Indiana

Metric Project No. 18-0022-3

Page **5** of **7** 

Perennial, Unconsolidated Bottom, Permanently Flooded (R2UBH) wetland. The Ordinary High Water Mark (OHWM) was an average of 42 ft wide and 1 ft. deep within the PSL. All OHWM measurements were taken outside the influence of the structure. The stream substrate consisted of boulder slabs, cobble, gravel, and silt. Overhanging vegetation and undercut banks were the in-stream cover present. Wetland fringe and drift deposits were observed along the stream throughout the PSL but the wetland areas were determined to be within the bank full elevation of the stream. Vegetation dominating the banks of the stream were silver maple (Acer saccharinum), Sycamore (Platanus occidentalis), reed canary grass (Phalaris arundinacea), spotted touch-me-not (Impatiens capensis), great ragweed (Ambrosia trifida), and Japanese hops (Humulus japonicus). No sinuosity was observed, and water velocity was moderate. Aquatic organisms, fish and frogs, were found in the stream. According to USGS Indiana StreamStats, the drainage area upstream of the South Fork of the Blue River at the PSL is 41.971 square miles. Based on qualitative analysis, South Fork of the Blue River is an average quality resource.

## **Roadside Ditches:**


Two roadside ditches were identified within the PSL. RSD 1 was located in the northeast quadrant and RSD 2 was located in the southeast quadrant of the PSL. These features did have incised channels as they got closer to South Fork Blue River, possibly due to the field and road runoff volumes. However, in areas where there was not debris, there was dominantly upland vegetation present within the incised ditch. Therefore, frequency and periods of inundation were not enough to deter vegetation growth. Therefore, no OHWM was observed in these features, so they are likely non-jurisdictional.


## **Culverts and Drains:**

One culvert and one drain were identified within the PSL. Culvert 1 was a corrugated metal pipe (CMP). The drain likely aids in roadside drainage and stormwater conveyance during storm or significant flood events. Culvert 1 is a continuation of RSD 1, carrying runoff/stormwater downhill to South Fork Blue River. These culverts did not carry jurisdictional waters due to a lack of an OHWM, bed and bank, and lack of a significant nexus to any jurisdictional Waters of the U.S. Locations of these culverts are shown on **Exhibits 4, Exhibit 5**, and the attached photosheet.

## **Conclusion:**

One stream, the South Fork of the Blue River, totaling 265 linear feet (0.256 ac.), was identified within the PSL. These waterways are likely Waters of the U.S. Every effort should be taken to avoid and minimize impacts to the waterway and wetlands. If impacts are necessary, then mitigation may be required. The INDOT Environmental Services Division should be contacted immediately if impacts will occur. The final determination of jurisdictional waters is ultimately made by the U.S. Army Corps of Engineers. This report is our best judgement based on the guidelines set forth by the Corps.







## **Acknowledgements:**

This waters determination has been prepared based on the best available information, interpreted in light of the investigator's training, experience and professional judgement in conformance with the 1987 Corps of engineers Wetlands Delineation Manual, the appropriate regional supplement, the USACE Jurisdictional Determination Form Instructional Guidebook, and other appropriate agency guidelines.

Metric Environmental Staff	Position	Contributing Effort	Signature/Date
Amy Noel Smith	Natural Resources Project Manager II	Project Manager, Field Data Collection	any Noclesmith
Alex Gray	Natural Resources Project Manager I	QAQC	Alex M. Gray 11/4/19
Zachary Root	Environmental Scientist 2	Field Data Collection, Report Preparation	January Proot

To conserve space, photographs and duplicate exhibits have been intentionally omitted from this document. Please refer to Appendix B in the CE document.







Exhibit 3 - NWI, FIRM, NHD, NRCS Soil Map S.R. 60 over South Fork of The Blue River Bridge Project

Pierce & Polk Township, Washington County, IN


Des. No. 1700173


Metric Project No. 18-0022-3 Map Date: 8/5/2019 Map Author: Zachary Root Source: Indiana Spatial Data Portal (2016)





Exh. 3





Stream

Culvert/Drain

300

Sampling Points (SP)

-- Roadside Ditch (RSD)

- - Culvert

Exhibit 4 - Waters Delineation Map S.R. 60 over South Fork of The Blue River Bridge Project Pierce & Polk Township, Washington County, IN

Des. No. 1700173

Metric Project No. 18-0022-3 Map Date: 8/5/2019 Map Author: Zachary Root

All locations approximate

Source: Indiana Spatial Data Portal (2016)





Exh. 4

## WETLAND DETERMINATION DATA FORM -- Eastern Mountains and Piedmont Region

Project/Site:	S.R. 60 over So	uth Fork of The Blue Rive	r (Des 17001)	<u>(3)</u>	ity/County: New Pekin/Was	nington	Sampi	
Applicant/Owner:	INDOT					State: IN	Sampli	
nvestigator(s):	Zachary Root				Section, Township	, Range: S 25, 1 N, 3 E		
_andform (hillslop	e, terrace, etc.):	Terrace		Local relief (cond	ave, convex, none):	none		
Subregion (LRR o	or MLRA):	LRR L Lat:		38.49937	Long:	-86.01301	Datum:	
Soil Map Unit Nar	me: Cuba	silt loam (3% hydric)				NWI classifica	ation:	
•	-	on the site typical for this t	ime of vear?		Yes X No	(If no, explain in Remarks	s.)	
Are Vegetation	No , Soil	No , or Hydrology	•	ignificantly disturbed?		al Circumstances" present?	Υ	
Are Vegetation				aturally problematic?		explain any answers in Remai		
· ·					,	•	iks.)	
SUMMARY O	F FINDINGS -	- Attach site map s	nowing sa	impling point loc	ations, transects, im	portant features, etc.		
Hydrophytic Vege	tation Present?	Yes	<u> </u>	No	Is the Sampled Area			
Hydric Soil Presei		Yes		No X	within a Wetland?	Yes		
Wetland Hydrolog	y Present?	Yes	<u> </u>	No				
Remarks: Sampling Point 1								
HYDROLOG	<u> </u>							
Wetland Hydrol		one is required: check all	that apply)				9	
Filliary maic	Surface Water (	•	шаг арріу)		True Aquatic Pla	nte (R14)	<u>s</u>	
-	High Water Tab			_	Hydrogen Sulfide			
-	Saturation (A3)			_		pheres on Living Roots (C3)		
	Water Marks (B	1)		_	Presence of Red	= ' '		
	Sediment Depo	•			Recent Iron Reduction in Tilled Soils (C			
X	<ul> <li>Drift Deposits (E)</li> </ul>			_	Thin Muck Surfa			
,	Algal Mat or Cru	·		_		, ,		
	Iron Deposits (E							
	Inundation Visib	le on Aerial Imagery (B7)						
	— Water-Stained I	_eaves (B9)						
	Aquatic Fauna (	(B13)						
	_							
Field Observation	ons:							
Surface Wate	er Present?		Yes	No X E	Depth (inches):			
Water Table I	Present?		Yes		Depth (inches):			
0 ( " D	esent?		Yes	No X E	Depth (inches):	Wetland Hydrol	logy Pres	
Saturation Pro								
(includes cap	illary fringe)							
(includes cap		auge, monitoring well, ae	rial photos, pr	evious inspections), if a	available:			
(includes cap		auge, monitoring well, ae	rial photos, pr	evious inspections), if a	available:			

VEGETATION Use scientific names of plants.					Ja	mpiing	Point:
	Absolute	Dominant	Indicator				
ree Stratum (Plot size: 30' radius )	% Cover	Species?	Status	Dominance Test	worksheet:		
1. Acer saccharinum	25%	Yes	FACW				
2				Number of Domina	ant Species		
3.				That Are OBL, FA	CW, or FAC:		2
4							
5.				Total Number of D	ominant		
6.				Species Across Al	l Strata:		3
7.							
	25% =	Total Cover		Percent of Domina	ant Species		
50% of total cover: 13%	20% of to	otal cover:	5%	That Are OBL, FA	CW, or FAC:		67%
Sapling/Shrub Stratum (Plot size: 15' radius )							
1				Provolence Index	workshoot		
2				Prevalence Index	worksneet:		
3				T-1-10/ 0	ovor ct.		Marildhallar Issan
4				Total % C			Multiply by:
5				That Are OBL, FAC	CW, or FAC:	- ,	
F00/ - 51-1-1 00/		Total Cover	00/	OBL species		_ x1 =	
50% of total cover: 0%	20% of to	otal cover:	0%	FACW species	75%	_ x2 =	1.5
<u>Herb Stratum</u> (Plot size: <u>5' radius</u> )				FAC species	50%	_ x3 =	1.5
1. Ambrosia trifida	50%	Yes	FAC	FACU species	110%	_ x4 =	4.4
2. Phalaris arundinacea	30%	No	FACW	UPL species		_ x5 =	
3. Impatiens capensis	20%	No	FACW	Column Totals:	2.35	_(A)	7.4
4. Phytolacca americana	20%	No	FACU				
5. Glechoma hederacea	20%	No	FACU	Prevale	nce Index = B/A	\ =	3.15
6. Humulus japonicus	70%	Yes	FACU_				
7.							
8.				Hydrophytic Veg	etation Indicat	ors:	
9.							
0.				1-Rapid 1	est for Hydrop	nytic Veg	etation
1.				X 2-Domina	nce Test is >5	0%	
	210% =	Total Cover		3-Prevale	nce Index is ≤3	3.0 <sup>1</sup>	
50% of total cover: 105%	20% of to		42%	4-Morpho	logical Adaptat	ions¹ (Pr	ovide support
Noody Vine Stratum (Plot size: 30' radius )				data in B	emarks or on a	congrate	o choot)
1					atic Hydrophytic		
1					alic i iyaropiiyii	vegetai	ion (Explain,
2				<sup>1</sup> Indicators of hydri	o soil and well	and budge	alogy must
3.				-		-	
4				be present, unless	aisturbea or p	robiemat	IC.
5							
6				1			
<b>FOO</b> ( 5) ( )		Total Cover	001	Hydrophytic			
50% of total cover: 0%	20% of to	otal cover:	0%	Vegetation			
				Present?	Yes X	_ No	

Color (moist)   %   Color (moist)   %   Type   Loc   Texture   Remarks	Depth	Matrix		Re	dox Features				
<sup>1</sup> Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains. <sup>2</sup> Location: PL=Pore Lining, M=Matrix.  Hydric Soil Indicators:	(inches)	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>	Texture	Remarks
Hydric Soil Indicators:  Histosol (A1)  Dark Surface (S7)  Polyvalue Below Surface (S8) (MLRA 147, 148)  Black Histic (A3)  Hydrogen Sulfide (A4)  Stratified Layers (A5)  Depleted Matrix (F3)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148)  MLRA 147, 148)  Bandy Gleyed Matrix (S4)  Sandy Redox (S5)  Depleted Matrix (S6)  MLRA 136, 122)  Piedmont Floodplain Soils (F19)  Wery Shallow Dark Surface (TF12)  Depleted Dark Surface (F7)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N, MLRA 136)  Sandy Gleyed Matrix (S4)  Depleted Matrix (F3)  MLRA 136, 122)  Sandy Redox (S5)  Piedmon Floodplain Soils (F19) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Wetland hydrology must be present, unless disturbed or problematic  Restrictive Layer (if observed):  Type:	0-20	10YR 5/3	100					SiCL	
Histosol (A1)  Histosol (A2)  Histosol (A3)  Histosol (A3)  Histosol (A4)  Black Histic (A3)  Hydrogen Sulfide (A4)  Stratified Layers (A5)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Bandy Mucky Mineral (S1) (LRR N, MLRA 147, 148)  MLRA 147, 148)  Bandy Redox (S5)  Depleted Dark Surface (F13) (MLRA 136, 122)  Sandy Redox (S5)  Demont Floodplain Soils (F19)  MLRA 147, 148)  Piedmont Floodplain Soils (F19)  Muck (A10) (LRR N)  Redox Dark Surface (F6)  Very Shallow Dark Surface (TF12)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N, MLRA 136)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Piedmon Floodplain Soils (F19) (MLRA 136, 122)  Pindicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic  Restrictive Layer (if observed):  Type:						<u> </u>			
New Control of Problematic Hydric Soils 1:  Histosol (A1)  Histic Epipedon (A2)  Black Histic (A3)  Hydrogen Sulfide (A4)  Stratified Layers (A5)  Depleted Below Dark Surface (B6)  Bandy Mucky Mineral (S1) (LRR N, MLRA 147, 148)  Sandy Redox (S5)  Sandy Redox (S5)  Stripped Matrix (S6)  Description  Des									
Histosol (A1)  Dark Surface (S7)  Polyvalue Below Surface (S8) (MLRA 147, 148)  Black Histic (A3)  Hydrogen Sulfide (A4)  Stratified Layers (A5)  Depleted Matrix (F3)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Bandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Dark Surface (S9) (MLRA 147, 148)  Loamy Gleyed Matrix (F2)  Depleted Matrix (F3)  MLRA 136, 147)  Very Shallow Dark Surface (TF12)  Other (Explain in Remarks)  Piedmont Floodplain Soils (F19)  (MLRA 136, 147)  Very Shallow Dark Surface (TF12)  Other (Explain in Remarks)  MLRA 136)  Umbric Surface (F13) (MLRA 136, 122)  Sandy Redox (S5)  Stripped Matrix (S6)  Red Parent Material (F21) (MLRA 147)  Restrictive Layer (if observed):  Type:	<sup>1</sup> Type: C=Cor	ncentration, D=Depleti	on, RM=Red	uced Matrix, MS=Maske	d Sand Grain	s. <sup>2</sup> Locatio	on: PL=Po	re Lining, M=Matrix.	
Histic Epipedon (A2)  Black Histic (A3)  Hydrogen Sulfide (A4)  Stratified Layers (A5)  Depleted Matrix (F2)  Depleted Below Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S4)  Stripped Matrix (S6)  Polyvalue Below Surface (S8) (MLRA 147, 148)  Coast Prairie Redox (A16)  (MLRA 147, 148)  (MLRA 147, 148)  Piedmont Floodplain Soils (F19)  Piedmont Floodplain Soils (F19)  (MLRA 136, 147)  Very Shallow Dark Surface (TF12)  Other (Explain in Remarks)  Thick Dark Surface (A12)  Redox Depressions (F8)  Iron-Manganese masses (F12) (LRR N,  MLRA 136, 122)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 136, 122)  Sandy Redox (S5)  Stripped Matrix (S4)  Stripped Matrix (S6)  Red Parent Material (F21) (MLRA 127, 147)  Piedmon Floodplain Soils (F19) (MLRA 127, 147)  wetland hydrology must be present, unless disturbed or problematic	ydric Soil Inc	dicators:					Indica	ators for Problemat	tic Hydric Soils <sup>3</sup> :
Black Histic (A3) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F19)  Stratified Layers (A5) Depleted Matrix (F3) MLRA 136, 147)  2 cm Muck (A10) (LRR N) Piedmont Floodplain Soils (F19)  MLRA 136, 147) Very Shallow Dark Surface (TF12) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148) Sandy Gleyed Matrix (S4) Sandy Redox (S5) Stripped Matrix (S6)  MERA 147, 148) MLRA 136, MLRA 136, MLRA 136, MLRA 136, MLRA 148) MLRA 148) MLRA 148) MLRA 147, 148) MLRA 148) MLRA 148) MERA 147, 148) MLRA 148) MLRA 148) MERA 147, 148) MLRA 148) MIRA 149, MIRA 147, 148) MIRA 148, MIRA 147, 148) MIRA 147, 148 MIRA 147, 148 MI	Histosol (	(A1)							
Hydrogen Sulfide (A4)  Stratified Layers (A5)  2 cm Muck (A10) (LRR N)  Depleted Matrix (F3)  Redox Dark Surface (F6)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Loamy Gleyed Matrix (F2)  Depleted Matrix (F2)  Redox Dark Surface (F6)  Depleted Dark Surface (F7)  Redox Depressions (F8)  Iron-Manganese masses (F12) (LRR N,  MLRA 136, 122)  Piedmont Floodplain Soils (F19)  (MLRA 136, 147)  Very Shallow Dark Surface (TF12)  Other (Explain in Remarks)  Mthan 136, 142)  Jumbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Wetland hydrology must be present, unless disturbed or problematic  Restrictive Layer (if observed):  Type:		. , ,							` '
Stratified Layers (A5)  2 cm Muck (A10) (LRR N)  Depleted Matrix (F3)  Redox Dark Surface (F6)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Redox Dark Surface (F7)  Depleted Dark Surface (F7)  Redox Depressions (F8)  Iron-Manganese masses (F12) (LRR N,  MLRA 136)  Umbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Stripped Matrix (S6)  Red Parent Material (F21) (MLRA 127, 147)  Restrictive Layer (if observed):  Type:		` '					48)	•	
2 cm Muck (A10) (LRR N)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Stripped Matrix (S6)  Stripped Matrix (S6)  Redox Dark Surface (F6)  Depleted Dark Surface (F7)  Redox Depressions (F8)  Iron-Manganese masses (F12) (LRR N,  MLRA 136)  Umbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Red Parent Material (F21) (MLRA 127, 147)  Restrictive Layer (if observed):  Type:		, ,			,	)			. , ,
Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Stripped Matrix (S6)  Depleted Dark Surface (F7)  Redox Depressions (F8)  Iron-Manganese masses (F12) (LRR N,  MLRA 136)  Umbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Red Parent Material (F21) (MLRA 127, 147)  Restrictive Layer (if observed):  Type:		• , ,						•	•
Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Red Parent Material (F21) (MLRA 127, 147)  Restrictive Layer (if observed):  Type:  Redox Depressions (F8)  Iron-Manganese masses (F12) (LRR N,  MLRA 136)  Umbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  wetland hydrology must be present,  unless disturbed or problematic					` '				, ,
Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  MERA 136)  Piedmon Floodplain Soils (F19) (MLRA 127, 147)  Red Parent Material (F21) (MLRA 127, 147)  Restrictive Layer (if observed):  Type:			A11)	Depleted Da	ark Surface (F	7)		Other (Expla	ain in Remarks)
MLRA 147, 148) Sandy Gleyed Matrix (S4) Sandy Redox (S5) Stripped Matrix (S6)  Restrictive Layer (if observed): Type:  MLRA 136) Umbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148) Red Parent Material (F21) (MLRA 127, 147)  wetland hydrology must be present, unless disturbed or problematic		, ,		Redox Depr	essions (F8)				
Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Piedmon Floodplain Soils (F19) (MLRA 148)  Red Parent Material (F21) (MLRA 127, 147)  Restrictive Layer (if observed):  Type:			R N,			(F12) <b>(LRR</b> I	N,		
Sandy Redox (S5) Stripped Matrix (S6) Piedmon Floodplain Soils (F19) (MLRA 148) Red Parent Material (F21) (MLRA 127, 147)  Piedmon Floodplain Soils (F19) (MLRA 127, 147)  Restrictive Layer (if observed): Type:		<u>.</u>			•			•	
Stripped Matrix (S6)  Red Parent Material (F21) (MLRA 127, 147)  unless disturbed or problematic  Restrictive Layer (if observed):  Type:		• , ,			, , ,		•		
Restrictive Layer (if observed):  Type:		` '					•	• •	•
Type:	Stripped I	Matrix (S6)		Red Parent N	Material (F21)	(MLRA 127	, 147)	unless disturbed	or problematic
	Restrictive La	yer (if observed):							
Depth (inches): Hydric Soil Present? Yes N	Type:								
	Depth (inc	ches):					Hydric	Soil Present?	Yes N

## **WETLAND DETERMINATION DATA FORM -- Eastern Mountains and Piedmont Region**

Applicant/Owner: Investigator(s): Landform (hillslope Subregion (LRR or Soil Map Unit Nam	Zachary I	Root							State: IN	Sampling I
Landform (hillslope Subregion (LRR or Soil Map Unit Nam		Root								
Subregion (LRR or Soil Map Unit Nam							Sectio	n, Township,	, Range: S 25, 1 N, 3 E	
Soil Map Unit Nam		etc.):		Agricultural F	-ield	Local relief (co	ncave, convex, n	ione):	None	S
·	MLRA):		LRR L	Lat	:	<del>-</del> 38.49808		Long:	-86.01217	Datum:
·	e:	Cubas	silt loam (	3% hydric)					NWI classific	ation:
Are climatic / hydro				typical for this	s time of vea	ar?	Yes X	No	(If no, explain in Remark	:s.)
Are Vegetation	No			, or Hydrolog	•	significantly disturbed			al Circumstances" present?	Yes
Are Vegetation		, Soil		, or Hydrolog , or Hydrolog		naturally problemation			explain any answers in Rema	
G		•		•	·	_		•	·	ai No. <i>)</i>
			Attach	Site map s	snowing	sampling point lo			portant features, etc.	
Hydrophytic Vegeta		ent?		Yes		No X	Is the Sam	-		
Hydric Soil Present				Yes		No X	within a W	etland?	Yes	No
Wetland Hydrology	Present?			Yes	X	No				
Sampling Point 2										
<b>HYDROLOG</b>	<u> </u>									
Wetland Hydrolo	gy Indicat	ors:								
Primary Indicat	ors (minin	num of o	one is req	uired: check a	all that apply	)				Seco
Surfa	ice Water	(A1)				_	True	Aquatic Pla	nts (B14)	X
High	Water Tal	ole (A2)				<del>-</del>	Hydı	rogen Sulfide	e Odor (C1)	
Satui	ation (A3)					_		-	oheres on Living Roots (C3)	X
	r Marks (E					-			uced Iron (C4)	
	ment Depo		2)			-			uction in Tilled Soils (C6)	
	Deposits (					-	Thin	Muck Surface	ce (C7)	
	Mat or Cr	•	)							
	Deposits (I			(DZ)						X
inunc	lation Visib									
	- water-s - Aquatic I		.eaves (B	9)						
	Aquatic	auna (	ь 10)							
Field Observation	ns:									
Surface Water	Present?				Yes	No X	Depth (inches):			
Water Table P	resent?				Yes	No X	Depth (inches):			
Saturation Pres	sent?				Yes	No X	Depth (inches):		Wetland Hydro	logy Presen
(includes capill	, ,									
Describe Recorde	ed Data (st	ream g	auge, mo	nitoring well, a	aerial photos	s, previous inspections)	, if available:			
Remarks:										
	ed or stres	sed nla	nts obser	ved during the	e site visit k	istorical aerial imagery	shows soil satur	ation presen	t two of the last eight years o	f imaging pro

**VEGETATION -- Use scientific names of plants.** Sampling Point: Absolute Dominant Indicator Tree Stratum (Plot size: 30' radius % Cover Species? Status **Dominance Test worksheet: Number of Dominant Species** That Are OBL, FACW, or FAC: 0 **Total Number of Dominant** Species Across All Strata: = Total Cover Percent of Dominant Species 50% of total cover: 0% 20% of total cover: That Are OBL, FACW, or FAC: 0% Sapling/Shrub Stratum (Plot size: 15' radius ) Prevalence Index worksheet: Total % Cover of: Multiply by That Are OBL, FACW, or FAC: = Total Cover OBL species x1 =0% 50% of total cover: 20% of total cover: 0% **FACW** species x2 = 5' radius ) Herb Stratum (Plot size: FAC species x3 = 4.4 1. Glycine max FACU species 100% FACU x4 = 2. Echinocystis lobata 10% FACU **UPL** species x5 = Column Totals: 4.4 (A) Prevalence Index = B/A = 4.00 8. **Hydrophytic Vegetation Indicators:** 1-Rapid Test for Hydrophytic Vegetation 10. 2-Dominance Test is >50% 11. 3-Prevalence Index is ≤3.01 110% = Total Cover 50% of total cover: 55% 20% of total cover: 22% 4-Morphological Adaptations<sup>1</sup> (Provide suppo 30' radius ) Woody Vine Stratum (Plot size: data in Remarks or on a separate sheet) Problematic Hydrophytic Vegetation<sup>1</sup> (Explai <sup>1</sup>Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

0%

0%

= Total Cover

0%

20% of total cover:

Hydrophytic

Vegetation Present?

No X

Remarks: (Include photo numbers here or on a separate sheet.)

50% of total cover:

Depth	Matrix		Re	dox Features				
(inches)	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>	Texture	Remarks
0-20	10YR 5/3	90	10YR 4/4	10	С	М	SiCl	Faint Redox Features
							· —— —	
							· ——	
T C=C		DM-Dad	used Matrix, MC-Macks	d Count Cunin	21 224	DID-	no Lining Manual	
ydric Soil I	oncentration, D=Depleti	on, Rivi=Rea	uced Matrix, MS=Maske	a Sand Grain	s. Localic		re Lining, M=Matrix ators for Problema	
Histoso			Dark Surfac	o (S7)		maic		(A10) <b>(MLRA 147)</b>
	Epipedon (A2)			elow Surface	(S8) (MI RA	147 148)		ie Redox (A16)
	listic (A3)			iurface (S9) <b>(I</b>			(MLRA 14	, ,
	en Sulfide (A4)			red Matrix (F2		-10)	· ·	loodplain Soils (F19)
	ed Layers (A5)		Depleted M		,		(MLRA 1	
	luck (A10) <b>(LRR N)</b>			Surface (F6)			•	w Dark Surface (TF12)
	ed Below Dark Surface (	Δ11)		ark Surface (F	·7)			lain in Remarks)
	Park Surface (A12)	, (11)		ressions (F8)	' /		Outlot (EXP	iam in reomane)
	Mucky Mineral (S1) <b>(LR</b>	RN		nese masses	(F12) <b>(I RR I</b>	N		
	A 147, 148)	,	MLRA 13		(· ··=) (=·····	••,		
	Gleyed Matrix (S4)			face (F13) <b>(M</b> l	RA 136, 12	2)	<sup>3</sup> Indicators of hyd	drophytic vegetation and
	Redox (S5)			odplain Soils		•	•	gy must be present,
	d Matrix (S6)			Material (F21)		•	•	d or problematic
estrictive L	ayer (if observed):							
Type:			<u>-</u>					
Danth /:	nches):					Hydric	Soil Present?	Yes No

## **WETLAND DETERMINATION DATA FORM -- Eastern Mountains and Piedmont Region**

Project/Site:	S.R. 60	over Sou	uth Fork c	of The Blue	e River (	Des 17	00173)		City/Count	y: <u>Ne</u> ۱	w Pekin/W	ashington		Sampling
Applicant/Owner:	INDOT												State: IN	Sampling
Investigator(s):	Zachary	Root								Se	ection, Tov	vnship, Rang	e: S 25, 1 N, 3 E	
Landform (hillslope	e, terrace,	etc.):		Dep	ression			Local relie	f (concave,	conve	x, none):	-	Concave	s S
Subregion (LRR or	· MLRA):		LRR L		Lat:			38.49912			Long:	-86	.01327	Datum:
Soil Map Unit Nam	•	Cuba	silt loam (	3% hydric	:)								NWI classif	ication:
Are climatic / hydro						e of vea	ar?		Yes	X	No	(If no.	explain in Rema	rks.)
Are Vegetation	•	, Soil		, or Hydro		No		antly disturbe					ances" present?	Yes
Are Vegetation		_, Soil		, or Hydro		No	_	y problemati					y answers in Ren	
-		<b>-</b>		•	_					tron	`			,
SUMMARY OF			Attach		ıp snov	wing	sampiir	ig point ic				-	eatures, etc.	
Hydrophytic Veget		ent?		Yes _	Х		No_				pled Area	1		
Hydric Soil Presen				Yes_			No_	<u>X</u>	withi	n a W	etland?		Yes	No
Wetland Hydrology	/ Present?			Yes _			No_	<u> </u>						
Remarks: Sampling Point 3														
<b>HYDROLOG</b>	Y													
Wetland Hydrolo	gy Indica	tors:												
Primary Indica	tors (minir	num of o	one is req	uired: che	ck all tha	at apply	<b>/</b> )							Seco
	ace Water									_		Plants (B14)		
	Water Ta									-	-	ide Odor (C1		
	ration (A3)									_		-	Living Roots (C3)	
	er Marks (I									_		educed Iron (		
	ment Depo		<u>2)</u>							-			lled Soils (C6)	
	Deposits (									- I nin	Muck Sur	race (C7)		
	Mat or Ci		)											
	Deposits ( dation Visi		orial Ima	gon/(P7)										
			.eaves (B											
-	Aquatic			13)										
	- Aquatio	i auna (	D10)											
Field Observation	ne:													
Surface Water					V	'es		No X	Depth (inc	hae).				
Water Table P						es —	_	No X	Depth (inc					
Saturation Pre						es —	_	No X	Depth (inc				Wetland Hydr	ology Presen
(includes capil		)				_	_	<u>/</u>						c.eg,ccc
Describe Recorde			auge, mo	nitoring we	ell, aerial	photos	s, previou	s inspections	), if availabl	e:				
	•			-										
Remarks:														

**VEGETATION -- Use scientific names of plants.** 

Sampling Point:

	Absolute	Dominant	Indicator		
Tree Stratum (Plot size: 30' radius )	% Cover	Species?	Status	Dominance Test worksheet:	
1. Acer saccharinum	25%	Yes	FACW		
2				Number of Dominant Species	
3				That Are OBL, FACW, or FAC:	3
4					
5				Total Number of Dominant	
6.				Species Across All Strata:	4
7					
		= Total Cover		Percent of Dominant Species	
50% of total cover: 13%	<u>6</u> 20% of	total cover:	5%	That Are OBL, FACW, or FAC:	75%
Sapling/Shrub Stratum (Plot size: 15' radius )					
1.					
2.	<u> </u>			Prevalence Index worksheet:	
3.					
4.	<u> </u>			Total % Cover of:	Multiply
5.				That Are OBL, FACW, or FAC:	
	0%	= Total Cover		OBL species	x1 =
50% of total cover: 0%	20% of	total cover:	0%	FACW species 75%	x2 = 1
Herb Stratum (Plot size: 5' radius )				FAC species 70%	x3 = 2
1. Phalaris arundinacea	50%	Yes	FACW	FACU species 80%	$x4 = \frac{2}{3}$
Ambrosia trifida	50%	Yes	FAC	UPL species UPL species	- x4 =3 x5 =
Convolvulus equitans	20%	No	FACU	Column Totals: 2.25	(A) 6
4. Humulus japonicus	60%	Yes	FACU	Column Totals. 2.23	,(A) <u> </u>
5. Echinocystis lobata	20%	No	FAC	Prevalence Index = B/A	= 3.02
6.	20 /6		FAC	Frevalence index – B/A	
7					
γ. Q	_	· <del></del>		Hydrophytic Vegetation Indicato	re.
9.		·		Trydrophytic vegetation indicate	13.
10.		·		1-Rapid Test for Hydroph	vtic Vegetation
11.				X 2-Dominance Test is >50°	
· · · · · · · · · · · · · · · · · · ·	200%	= Total Cover		3-Prevalence Index is ≤3.	
50% of total cover: 100		total cover:	40%	4-Morphological Adaptation	
	70 2070 01	total cover.		<del></del>	
Woody Vine Stratum (Plot size: 30' radius )				data in Remarks or on a	. ,
1	_			Problematic Hydrophytic	vegetation (Exp
2	_			1 Indicators of budris soil and watter	ad budualagu maria
3				<sup>1</sup> Indicators of hydric soil and wetlar	
4				be present, unless disturbed or pro	blematic.
5					
6		- Total C		Usadra mbastia	
FOO/ of total covers		= Total Cover	00/	Hydrophytic	
50% of total cover: 0%		total cover:	0%	Vegetation	
				Present? Yes X	No
1					

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL			e:			Sampling Point: SI
Profile Description: (Describe to the depth			ntirm the a	ibsence of i	ndicators.)	
Depth Matrix (inches) Color (moist) %		edox Features %	Type <sup>1</sup>	Loc <sup>2</sup>	Toyturo	Domorko
	Color (moist)		туре	LOC	Texture	Remarks
0-20 10YR 4/3 100	_				SiCL	
	- '		_			
<sup>1</sup> Type: C=Concentration, D=Depletion, RM=	Reduced Matrix, MS=Mask	ed Sand Grains.	<sup>2</sup> Locatio	n: PL=Pore	Lining, M=Matrix.	
Hydric Soil Indicators:				Indicat	ors for Problematic	: Hydric Soils <sup>3</sup> :
Histosol (A1)	Dark Surface	` '			2 cm Muck	(A10) <b>(MLRA 147)</b>
Histic Epipedon (A2)	Polyvalue E	Below Surface (S	88) <b>(MLRA</b>	147, 148)	Coast Prairi	e Redox (A16)
Black Histic (A3)	Thin Dark S	Surface (S9) <b>(ML</b>	.RA 147, 1	48)	(MLRA 14	I7, 148)
Hydrogen Sulfide (A4)	Loamy Gley	ed Matrix (F2)			Piedmont F	loodplain Soils (F19)
Stratified Layers (A5)	Depleted M	atrix (F3)			(MLRA 13	36, 147)
2 cm Muck (A10) (LRR N)		Surface (F6)			Very Shallo	w Dark Surface (TF12)
Depleted Below Dark Surface (A11)		ark Surface (F7	)		Other (Exp	lain in Remarks)
Thick Dark Surface (A12)	<del></del> ·	ressions (F8)				
Sandy Mucky Mineral (S1) (LRR N,		nese masses (F	12) <b>(LRR</b> I	N,		
MLRA 147, 148)	MLRA 1	•			3	
Sandy Gleyed Matrix (S4)		face (F13) (MLF		-		Irophytic vegetation and
Sandy Redox (S5)		oodplain Soils (F				gy must be present,
Stripped Matrix (S6)	Red Parent	Material (F21) (	VILRA 127	, 147)	unless disturbed	d or problematic
Restrictive Layer (if observed):						
Туре:						
Depth (inches):				Hydric S	oil Present?	Yes No
Remarks:						

## **WETLAND DETERMINATION DATA FORM -- Eastern Mountains and Piedmont Region**

Project/Site:	S.R. 60	over Sou	ıth Fork o	f The Blue	River (De	es 1700	173)		City/C	County:	New	/ Pekin/W	ashington			Sampling
Applicant/Owner:	INDOT													State:	IN	Sampling
Investigator(s):	Zachary	Root								Se	ection	n, Townsh	ip, Range	: S 25, 1 N	, 3 E	
Landform (hillslop	e, terrace,	etc.):		Terra	ace		Lo	cal relief (c	oncave	e, conve	ex, no	one):		nor	ne	
Subregion (LRR o	or MLRA):		LRR L		Lat:			38.49941				Long:		-86.01336		Datum:
Soil Map Unit Nar	ne:	Cuba	silt loam (	3% hydric	) —							-		NV	VI classific	cation:
Are climatic / hydr						of vear?	)			Yes	Х	No	(lf ı	no, explain	in Remark	ks.)
Are Vegetation	•	, Soil		, or Hydro		•		ntly disturbe	ed?	_		-		nstances" ¡		Yes
Are Vegetation	No	, Soil		or Hydro				problemati						any answe		
SUMMARY O				-						ne tr						J110.)
			Attacii			ilig sa		y point ic					-	t reature	:5, etc.	
Hydrophytic Vege		sent?		Yes _	X		No_					oled Area	1	,	<b>/</b>	N
Hydric Soil Preser Wetland Hydrolog		2		Yes Yes			No_ No	X	·	within	a vve	etland?		`	/es	<u> </u>
Remarks:	19 1 1000111	•														
Sampling Point 4																
HYDROLOG	·V															
Wetland Hydrolo		tore:														
Primary Indica			one is rea	uired: che	ck all that	apply)										Sec
	face Water		3110 10 109	anoa. ono	or an trac	арріј)					True	Aguatic F	Plants (B14	1)		_ =
	n Water Ta												ide Odor (			-
	uration (A3										-	-		on Living R	oots (C3)	
Wat	er Marks (	(B1)									Prese	ence of R	educed Iro	on (C4)		
Sed	iment Dep	osits (B2	2)								Rece	nt Iron Re	eduction in	Tilled Soil	s (C6)	
Drift	Deposits	(B3)									Thin	Muck Sur	face (C7)			
Alga	al Mat or C	rust (B4)	)													
	Deposits															
Inur	ndation Vis			, ,												
·	_		.eaves (B	9)												
	_ Aquatic	: Fauna (	B13)													
Field Observation	ns:															
Surface Wate	r Present?	•			Ye	es		No X	Deptl	h (inche	es):					
Water Table F	Present?				Ye	s		No X	Deptl	h (inche	es):					
Saturation Pre	esent?				Ye	es		No X	Deptl	h (inche	es):			Wetla	and Hydro	logy Prese
(includes capi																
Describe Record	led Data (s	stream ga	auge, mo	nitoring we	ell, aerial p	photos, p	orevious	inspections	s), if ava	ailable:						·
Remarks:																
10																
ĺ																

## WETLAND DETERMINATION DATA FORM -- Eastern Mountains and Piedmont Region

Project/Site:	S.R. 60 over South Fork of	The Blue River (Des 1700	)173)	City/Coun	nty: New Pekin/Wash	nington	Sampling Date: 8/7/2019
Applicant/Owner:	INDOT					State: IN	Sampling Point: SP-5
Investigator(s):	Zachary Root				Section, Township, I	Range: S 25, 1 N, 4 E	
Landform (hillslope	e, terrace, etc.):	Top of Hillslope	Local r	elief (concave, co	nvex, none):	Convex	Slope (%): 0
Subregion (LRR o	or MLRA): LRR	R L Lat:	38.4	49971	Long:	-86.01311	Datum: NAD 83
Soil Map Unit Nan	me: Cuba silt loam (3	3% hydric)				NWI classifica	ation: None
Are climatic / hydr	rologic conditions on the site t	typical for this time of year	?	Ye	s X No	(If no, explain in Remarks	s.)
Are Vegetation	No , Soil	No , or Hydrology	No significantly of			Circumstances" present?	Yes X No
Are Vegetation	No , Soil	No , or Hydrology	No naturally prob		(If needed, e	explain any answers in Remar	
SUMMARY O	F FINDINGS Attach s				ects. important	features, etc.	
Hydrophytic Veget		Yes	No X		he Sampled Area	100	
Hydric Soil Preser		Yes	No X		hin a Wetland?	Yes	No x
Wetland Hydrolog		Yes	No X	_			
Remarks:	<u> </u>			_			
Upland Sampling							
HYDROLOG							
Wetland Hydrold	<b>ogy Indicators:</b> ators (minimum of one is requi						Cacandary Indicators (minimum c
	ators (minimum of one is requi face Water (A1)	red: спеск ан тлат арріу)			True Aquatic Plan	nte (R14)	Secondary Indicators (minimum c Surface Soil Cracks (B6)
	h Water Table (A2)				Hydrogen Sulfide		Sparsely Vegetated Concave Surface (B8)
	uration (A3)					heres on Living Roots (C3)	Drainage Patterns (B10)
	ter Marks (B1)				Presence of Redu		Moss Trim Lines (B16)
	liment Deposits (B2)				_	uction in Tilled Soils (C6)	Dry-Season Water Table (C2)
	t Deposits (B3)				_ Thin Muck Surface	e (C7)	Crayfish Burrows (C8)
	al Mat or Crust (B4) Deposits (B5)						Saturation Visible on Aerial Imagery (C9) Stunted or Stressed Plants (D1)
	ndation Visible on Aerial Image	erv (B7)					Geomorphic Position (D2)
	ter-Stained Leaves (B9)	J. J					Shallow Aquitard (D3)
	atic Fauna (B13)						Microtopographix Relief (D4)
							FAC-Neutral Test (D5)
Field Observation	one:						
Surface Wate		Υ	'es No	o X Depth (in	iches):		
Water Table F				o X Depth (in			
Saturation Pre	esent?	Y		o X Depth (in		Wetland Hydrolo	logy Present? Yes No x
(includes capi		<del> </del>					
Describe Record	ded Data (stream gauge, moni	itoring well, aerial photos,	previous inspections),	if available:			
Remarks:							

US Army Corps of Engineers

Absolute	Dominant	Indicator	
% Cover	Species?	Status	Dominance Test worksheet:
30%	Yes	FACW	
			Number of Dominant Species
			That Are OBL, FACW, or FAC: 1 (A)
			Total Number of Dominant
			Species Across All Strata: 4 (B)
			(-,
30%	= Total Cover		Percent of Dominant Species
		6%	That Are OBL, FACW, or FAC: 25% (A/B)
20 /0 01 0	otal cover.	0 70	That Ale Obl., I AGW, Of I AG. (A/b)
10%	Yes	FACU	Prevalence Index worksheet:
			Total % Cover of: Multiply by:
			That Are OBL, FACW, or FAC:  A/B
20%	= Total Cover		OBL species x1 =
20% of t	otal cover:	4%	FACW species 30% x2 = 0.6
	•		FAC species 30% x3 = 0.9
700/	Voc	EACH	
			FACU species 110% x4 = 4.4  UPL species x5 =
			Column Totals: <u>1.70</u> (A) <u>5.9</u> (B)
10%	No	FAC	
			Prevalence Index = B/A = 3.47
			Hydrophytic Vegetation Indicators:
			1-Rapid Test for Hydrophytic Vegetation
			2-Dominance Test is >50%
120%	= Total Cover		3-Prevalence Index is ≤3.0 <sup>1</sup>
20% of t	otal cover:	24%	4-Morphological Adaptations <sup>1</sup> (Provide supporting
	•	J	data in Remarks or on a separate sheet)
			Problematic Hydrophytic Vegetation <sup>1</sup> (Explain)
			<sup>1</sup> Indicators of hydric soil and wetland hydrology must
			be present, unless disturbed or problematic.
		00/	Hydrophytic
20% of t	otal cover:	0%	Vegetation
			Present? Yes No X
	30% 30% 20% of 1 10% 20% 20% of 1 70% 20% 10% 20% 20% 10%  120% 20% of 1	Species?   Yes	% Cover         Species?         Status           30%         Yes         FACW           30%         = Total Cover         6%           20% of total cover:         6%         FACU           10%         Yes         FACU           10%         Yes         FACU           20%         Total Cover:         4%           70%         Yes         FACU           20%         No         FAC           10%         No         FAC           10%         No         FAC           20% of total cover:         24%

e: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.    e: C=Concentration, D=Depletion, RM=Reduced Matrix (S)	pth	Matrix		0 1 2 2	Redox Features	<b>-</b> 1	. ,	<b>-</b> .		
e: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.      Cosil Indicators   Indicators for Problematic Hydric Soils	ches)	Color (moist)		Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>	Texture	Remarks	
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)	0-20	10YR 5/4	100					SiCL		
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)								<u> </u>		
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)	<del></del> , ,									
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Indicators: Indicators: Indicators for Problematic Hydric Soils <sup>3</sup> : Histosol (A1)										
Histosol (A1)  Dark Surface (S7)  Polyvalue Below Surface (S8) (MLRA 147, 148)  Black Histic (A3)  Thin Dark Surface (S9) (MLRA 147, 148)  Hydrogen Sulfide (A4)  Stratified Layers (A5)  Depleted Matrix (F3)  Depleted Below Dark Surface (F6)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Sandy Redox (S5)  Stripped Matrix (S6)  Depleted Dark Surface (F13) (MLRA 136, 122)  Piedmont Floodplain Soils (F19)  (MLRA 136, 147)  Very Shallow Dark Surface (TF12)  Other (Explain in Remarks)  Thick Dark Surface (A12)  Redox Depressions (F8)  Iron-Manganese masses (F12) (LRR N, MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Sandy Redox (S5)  Stripped Matrix (S6)  Red Parent Material (F21) (MLRA 127, 147)  Trictive Layer (if observed):  Type:  Depth (inches):  Hydric Soil Present?  Yes No x			tion, RM=Redu	iced Matrix, MS=M	asked Sand Grains	s. <sup>2</sup> Locatio				
Histic Epipedon (A2)  Black Histic (A3)  Thin Dark Surface (S9) (MLRA 147, 148)  Hydrogen Sulfide (A4)  Stratified Layers (A5)  2 cm Muck (A10) (LRR N)  Depleted Matrix (F3)  Depleted Dark Surface (F6)  Stratified Leyer (A12)  Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Sandy Redox (S5)  Sandy Redox (S5)  Piedmont Floodplain Soils (F19)  Wery Shallow Dark Surface (TF12)  Other (Explain in Remarks)  MLRA 136,  Umbric Surface (F12) (LRR N, MLRA 136, 122)  Piedmont Floodplain Soils (F19)  Wery Shallow Dark Surface (TF12)  Other (Explain in Remarks)  Other (Explain in Remarks)  MLRA 136,  Umbric Surface (F13) (MLRA 136, 122)  Piedmont Floodplain Soils (F19) (MLRA 148)  Wetland hydrology must be present, unless disturbed or problematic  Fictive Layer (if observed):  Type:  Depth (inches):  Hydric Soil Present?  Yes No x	ic Soil II	ndicators:					Indic	ators for Problem	atic Hydric Soils <sup>3</sup> :	
Black Histic (A3) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F19) Stratified Layers (A5) Depleted Matrix (F3) MLRA 136, 147) Perpleted Below Dark Surface (A11) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148) MLRA 147, 148) MLRA 147, 148) Sandy Gleyed Matrix (S4) Sandy Redox (S5) Stripped Matrix (S6) Depleted Dark Surface (F13) (MLRA 136, 122) Piedmont Floodplain Soils (F19) (MLRA 148) Wetland hydrology must be present, unless disturbed or problematic  Hydric Soil Present? Yes No x	Histoso	I (A1)		Dark Su	ırface (S7)			2 cm Muck	(A10) <b>(MLRA 147)</b>	
Hydrogen Sulfide (A4)  Loamy Gleyed Matrix (F2)  Depleted Matrix (F3)  Redox Dark Surface (F6)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Stripped Matrix (S6)  Depleted Dark Surface (F13) (MLRA 136, 122)  Piedmont Floodplain Soils (F19)  Wery Shallow Dark Surface (TF12)  Other (Explain in Remarks)  Piedmont Floodplain Soils (F19)  Wery Shallow Dark Surface (TF12)  Depleted Dark Surface (F7)  Other (Explain in Remarks)  MLRA 147, 148)  MLRA 136,  Umbric Surface (F12) (LRR N,  MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Wetland hydrology must be present,  wetland hydrology must be present,  unless disturbed or problematic  Pictive Layer (if observed):  Type:  Depth (inches):  Hydric Soil Present?  Yes  No  x	Histic E	pipedon (A2)		Polyvalı	ue Below Surface (	S8) <b>(MLRA</b>	147, 148)	Coast Prairi	e Redox (A16)	
Stratified Layers (A5)  Depleted Matrix (F3)  Redox Dark Surface (F6)  Depleted Below Dark Surface (A11)  Thick Dark Surface (A12)  Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Depleted Dark Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  wetland hydrology must be present,  Red Parent Material (F21) (MLRA 127, 147)  Depth (inches):  Hydric Soil Present?  Yes No x	Black H	listic (A3)		Thin Da	rk Surface (S9) <b>(M</b>	LRA 147, 14	<b>4</b> 8)	(MLRA 14	7, 148)	
2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Very Shallow Dark Surface (TF12) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148) Sandy Gleyed Matrix (S4) Sandy Redox (S5) Stripped Matrix (S6)  Depleted Dark Surface (F7) Redox Depressions (F8) Iron-Manganese masses (F12) (LRR N, MLRA 136) Umbric Surface (F13) (MLRA 136, 122) Piedmon Floodplain Soils (F19) (MLRA 148) Wetland hydrology must be present, Red Parent Material (F21) (MLRA 127, 147) Unless disturbed or problematic  Prictive Layer (if observed): Type: Depth (inches): Hydric Soil Present? Yes No x	Hydroge	en Sulfide (A4)		Loamy	Gleyed Matrix (F2)			Piedmont FI	oodplain Soils (F19)	
2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Very Shallow Dark Surface (TF12) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148) Sandy Gleyed Matrix (S4) Sandy Redox (S5) Stripped Matrix (S6)  Depleted Dark Surface (F7) Redox Depressions (F8) Iron-Manganese masses (F12) (LRR N, MLRA 136) Umbric Surface (F13) (MLRA 136, 122) Piedmon Floodplain Soils (F19) (MLRA 148) Wetland hydrology must be present, Red Parent Material (F21) (MLRA 127, 147) Unless disturbed or problematic  Prictive Layer (if observed): Type: Depth (inches): Hydric Soil Present? Yes No x	Stratifie	d Layers (A5)		Deplete	d Matrix (F3)			(MLRA 13	6, 147)	
Thick Dark Surface (A12) Sandy Mucky Mineral (S1) (LRR N, MLRA 147, 148) Sandy Gleyed Matrix (S4) Sandy Redox (S5) Stripped Matrix (S6)  Trictive Layer (if observed):  Type: Depth (inches):  Redox Depressions (F8) Iron-Manganese masses (F12) (LRR N, MLRA 136) Iron-Manganese masses (F12) (MLRA 136, 122) Iron-Manganese masses (F12) (MLRA 148) Iron-Manganese ma	2 cm Mi	uck (A10) (LRR N)		Redox I	Dark Surface (F6)			Very Shallov	w Dark Surface (TF12)	
Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Mineral (F12) (Mineral 136, 122)  Piedmon Floodplain Soils (F19) (Mineral 148)  Red Parent Material (F21) (Mineral 147, 147)  Mineral 136,  Umbric Surface (F13) (Mineral 136, 122)  Piedmon Floodplain Soils (F19) (Mineral 148)  Wetland hydrology must be present,  unless disturbed or problematic  Mineral (F21) (Mineral 147, 147)  Mineral 136,  Wetland hydrology must be present,  unless disturbed or problematic  Mineral (F21) (Mineral 148)  Mineral 136,  Wetland hydrology must be present,  unless disturbed or problematic  Mineral 136,  Wetland hydrology must be present,  unless disturbed or problematic  Mineral 136,  Minera	Deplete	d Below Dark Surface	(A11)	Deplete	d Dark Surface (F7	<b>'</b> )		Other (Expl	ain in Remarks)	
Sandy Mucky Mineral (S1) (LRR N,  MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Mineral (F12) (Mineral 136, 122)  Piedmon Floodplain Soils (F19) (Mineral 148)  Red Parent Material (F21) (Mineral 147, 147)  Mineral 136,  Umbric Surface (F13) (Mineral 136, 122)  Piedmon Floodplain Soils (F19) (Mineral 148)  Wetland hydrology must be present,  unless disturbed or problematic  Mineral (F21) (Mineral 147, 147)  Mineral 136,  Wetland hydrology must be present,  unless disturbed or problematic  Mineral (F21) (Mineral 148)  Mineral 136,  Wetland hydrology must be present,  unless disturbed or problematic  Mineral 136,  Wetland hydrology must be present,  unless disturbed or problematic  Mineral 136,  Minera	Thick D	ark Surface (A12)		Redox I	Depressions (F8)					
MLRA 147, 148)  Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  MLRA 136,  Umbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  Red Parent Material (F21) (MLRA 127, 147)  Wetland hydrology must be present,  unless disturbed or problematic  rictive Layer (if observed):  Type:  Depth (inches):  Hydric Soil Present?  Yes No x			RR N,			F12) <b>(LRR N</b>	١,			
Sandy Gleyed Matrix (S4)  Sandy Redox (S5)  Stripped Matrix (S6)  Piedmon Floodplain Soils (F19) (MLRA 148)  Red Parent Material (F21) (MLRA 127, 147)  Prictive Layer (if observed):  Type:  Depth (inches):  Umbric Surface (F13) (MLRA 136, 122)  Piedmon Floodplain Soils (F19) (MLRA 148)  wetland hydrology must be present, unless disturbed or problematic  Wetland hydrology must be present, unless disturbed or problematic						, ,				
Sandy Redox (S5)						RA 136, 122	2)	<sup>3</sup> Indicators of hvd	rophytic vegetation and	d
Stripped Matrix (S6) Red Parent Material (F21) (MLRA 127, 147) unless disturbed or problematic  rictive Layer (if observed):  Type:  Depth (inches): Hydric Soil Present? Yes No x								-		
Trictive Layer (if observed):  Type:  Depth (inches):	•									
Type:         Hydric Soil Present?         Yes         No         x		, ,			,	•	•		•	
Type:         Hydric Soil Present?         Yes         No         x	trictivo I	aver (if observed):								
Depth (inches): Hydric Soil Present? Yes No x		ayer (ii observeu).								
		nchoe):					Hydric	Sail Brasant?	Vos	No v
rks:	Deptil (ii	inches).					пуштс	Son Fresent?		NO
	arks:									
	arks:									
	arks:									
	arks:									
	arks:									
	arks:									
	rks:									
	rks:									
	rks:									
	rks:									
	rks:									
	rks:									
	rks:									
	rrks:									
	rks:									
	rks:									
	rks:									
	rks:									
	rks:									
	rrks:									
	arks:									
	arks:									
	arks:									
	arks:									
	arks:									
	arks:									
	arks:									

## Appendix 2 - PRELIMINARY JURISDICTIONAL DETERMINATION (PJD) FORM

## **BACKGROUND INFORMATION**

A. REPORT COMPLETION DATE FOR PJD: November 4, 2019

## **B. NAME AND ADDRESS OF PERSON REQUESTING PJD:**

Zachary Root Metric Environmental, LLC 6971 Hillsdale Court Indianapolis, IN 46250 317-350-4896 zacharyr@metricenv.com

C. DISTRICT OFFICE, FILE NAME, AND NUMBER:

## D. PROJECT LOCATION(S) AND BACKGROUND INFORMATION:

The proposed project (Des. No. 1700173) includes the replacement of the existing bridge (INDOT Bridge No. 060-88-03069) with a three-spans bridge (58'-0", 75'-0", 58'-0") with a total structure length of 192.6 feet, a clear roadway width of 32 feet, and skewed 15 degrees left. The approach roadway will have guardrails and concrete bridge railing transition. Channel clearing will be required. SR 60 will be shifted approximately 18 feet upstream (east) from the existing alignment to accommodate existing bridge removal and maintenance of traffic.

## (USE THE TABLE BELOW TO DOCUMENT MULTIPLE AQUATIC RESOURCES AND/OR AQUATIC RESOURCES AT DIFFERENT SITES)

State: IN County/parish/borough: Washington County City: New Pekin

Center coordinates of site (lat/long in degree decimal format):

Lat.: 38.4994645° Long.: -86.0131954°

Universal Transverse Mercator: 16 S 586048.90 E 4261695.37 N

Name of nearest waterbody. South Fork of the Blue River

Ε.	REVIEW PERFORMED FOR SITE EVALUATION (CHECK ALL THAT APPLY):
	Office (Desk) Determination. Date:
	☐ Field Determination. Date(s):

## TABLE OF AQUATIC RESOURCES IN REVIEW AREA WHICH "MAY BE" SUBJECT TO REGULATORY JURISDICTION.

Site number	Latitude (decimal degrees)	Longitude (decimal degrees)	Estimated amount of aquatic resource in review area (acreage and linear feet, if applicable)	Type of aquatic resource (i.e., wetland vs. non-wetland waters)	Geographic authority to which the aquatic resource "may be" subject (i.e., Section 404 or Section 10/404)
South Fork of the Blue River	39.499421	-86.013179	265 LFT (0.256 ac)	Non-Wetland Waters	Section 404

- 1) The Corps of Engineers believes that there may be jurisdictional aquatic resources in the review area, and the requestor of this PJD is hereby advised of his or her option to request and obtain an approved JD (AJD) for that review area based on an informed decision after having discussed the various types of JDs and their characteristics and circumstances when they may be appropriate.
- 2) In any circumstance where a permit applicant obtains an individual permit, or a Nationwide General Permit (NWP) or other general permit verification requiring "preconstruction notification" (PCN), or requests verification for a non-reporting NWP or other general permit, and the permit applicant has not requested an AJD for the activity, the permit applicant is hereby made aware that: (1) the permit applicant has elected to seek a permit authorization based on a PJD, which does not make an official determination of jurisdictional aquatic resources; (2) the applicant has the option to request an AJD before accepting the terms and conditions of the permit authorization, and that basing a permit authorization on an AJD could possibly result in less compensatory mitigation being required or different special conditions; (3) the applicant has the right to request an individual permit rather than accepting the terms and conditions of the NWP or other general permit authorization; (4) the applicant can accept a permit authorization and thereby agree to comply with all the terms and conditions of that permit, including whatever mitigation requirements the Corps has determined to be necessary: (5) undertaking any activity in reliance upon the subject permit authorization without requesting an AJD constitutes the applicant's acceptance of the use of the PJD; (6) accepting a permit authorization (e.g., signing a proffered individual permit) or undertaking any activity in reliance on any form of Corps permit authorization based on a PJD constitutes agreement that all aguatic resources in the review area affected in any way by that activity will be treated as jurisdictional, and waives any challenge to such jurisdiction in any administrative or judicial compliance or enforcement action, or in any administrative appeal or in any Federal court; and (7) whether the applicant elects to use either an AJD or a PJD, the JD will be processed as soon as practicable. Further, an AJD, a proffered individual permit (and all terms and conditions contained therein), or individual permit denial can be administratively appealed pursuant to 33 C.F.R. Part 331. If, during an administrative appeal, it becomes appropriate to make an official determination whether geographic jurisdiction exists over aquatic resources in the review area, or to provide an official delineation of jurisdictional aquatic resources in the review area, the Corps will provide an AJD to accomplish that result, as soon as is practicable. This PJD finds that there "may be" waters of the U.S. and/or that there "may be" navigable waters of the U.S. on the subject review area, and identifies all aquatic features in the review area that could be affected by the proposed activity, based on the following information:

## SUPPORTING DATA. Data reviewed for PJD (check all that apply)

Checked items should be included in subject file. Appropriately reference sources

below where indicated for all checked items: Maps, plans, plots or plat submitted by or on behalf of the PJD requestor: ■ Map:\_\_\_\_\_ Dated 8/5/2019 Data sheets prepared/submitted by or on behalf of the PJD requestor. Office concurs with data sheets/delineation report. Office does not concur with data sheets/delineation report. Rationale:\_\_\_ Data sheets prepared by the Corps: Corps navigable waters' study: U.S. Geological Survey Hydrologic Atlas: USGS NHD data. ■ USGS 8 and 12 digit HUC maps. U.S. Geological Survey map(s). Cite scale & quad name: Palmyra, IN 7.5 min, 1980 Natural Resources Conservation Service Soil Survey. Citation: <u>SSURGO Washington County</u> National wetlands inventory map(s). Cite name: <a href="http://www.fws.gov/wetlands/">http://www.fws.gov/wetlands/</a> State/local wetland inventory map(s):\_\_\_\_\_ FEMA/FIRM maps: https://msc.fema.gov 100-year Floodplain Elevation is: .(National Geodetic Vertical Datum of 1929) Photographs: Aerial (Name & Date): Indiana Aerial Photograph, 2016 Other (Name & Date): Site Photographs, 8/7/2019 Previous determination(s). File no. and date of response letter:\_\_\_\_\_ Other information (please specify): IMPORTANT NOTE: The information recorded on this form has not necessarily been verified by the Corps and should not be relied upon for later jurisdictional determinations. 11/4/2019 Signature and date of Regulatory staff member person requesting PJD completing PJD (REQUIRED, unless obtaining the signature is impracticable)1

<sup>&</sup>lt;sup>1</sup> Districts may establish timeframes for requestor to return signed PJD forms. If the requestor does not respond within the established time frame, the district may presume concurrence and no additional follow up is necessary prior to finalizing an action.

F-28

## Susan Castle

Subject: FW: APPROVED: WOTUS Report, Des 1700173 SR 60 Bridge Rplcmnt., 0.42 miles W of SR 335

over S Fork Blue River, Washington Co

Attachments: Permit Determination Questionnaire V4 11\_7\_2019.docx; Extract from 11-12-2019 Approved

WOTUS Rpt 1700173.pdf

From: Sperry, Steve

Sent: Tuesday, November 12, 2019 10:31 AM

To: Zachary Root <zacharyr@metricenv.com>; Williamson, Brad <BWILLIAMSON@indot.IN.gov>

Cc: Rehder, Crystal <CRehder@indot.IN.gov>; Alex Gray <alexg@metricenv.com>; mkeusch@hntb.com

Subject: APPROVED: WOTUS Report, Des 1700173 SR 60 Bridge Rplcmnt., 0.42 miles W of SR 335 over S Fork Blue River,

Washington Co

Zachary,

Thank you for submitting the waters report for the above referenced project.

## Brad

An extract from the 11/4/2019 WOTUS report is attached. It was approved by this Office on 11/12/2019. The full report can be found in ProjectWise through this link: Approved WOTUS Rpt 1700173 SR60 SF Blue R Washington Co 11-12-2019.pdf It is the responsibility of the Project Manager to forward a copy of this report to the Project Designer.

The information in this report should be used by the Project Designer to determine if waters of the U.S. will be impacted by the project. Avoidance and minimization of impacts must occur before mitigation will be considered. If mitigation is required, the Project Manager or Project Designer must coordinate with the Ecology and Waterway Permitting Office to discuss how adequate compensatory mitigation will be provided.

This email serves as notice that the Project Designer is to complete the standard Permit Determination Questionnaire (refer to attached) as soon as all required information is obtained. It will need to be submitted to Steve Sperry so that a permit determination can be made.

The Project Manager should notify the Ecology and Waterway Permitting Office if there is any change to the project footprint presented in this report. Such changes may require additional fieldwork and submittal of an updated waters report covering areas not previously investigated. This report is only valid for a period of five years from the date of earliest fieldwork. If the report expires prior to waterway permit application submittal, additional fieldwork and a revised waters report will be required.

This waters report will not be sent to the United States Army Corps of Engineers (USACE) or the Indiana Department of Environmental Management (IDEM) until the waterways permit applications are submitted to these agencies.

Thanks

Steve

**Stephen C. Sperry** 

**Ecology and Permits Coordinator** 

Multidistrict East Team Division of Environmental Services IGCN Room 642 100 N. Senate Ave. Indianapolis, IN 46204

Office: (317) 232-5206 Email: ssperry@indot.in.gov







# **APPENDIX G:** Public Involvement



## NOTICE OF SURVEY

March 19, 2015

RE:

S.R. 60 Bridge Replacement Washington County, Indiana

## Dear Property Owner:

Our information indicates that you own or occupy property near this proposed highway project. Our employees will be doing a survey of the project area in the near future. It may be necessary for them to come onto your property to complete this work. This is allowed by law by Indiana Code IC 8-23-7-26. They will show you their identification, if you are available, before coming onto your property. If you have sold this property, or it is occupied by someone else, please let us know the name and address of the new owner or current occupant so we can contact them about the survey.

At this stage we generally do not know what effect, if any, our project may eventually have on your property. If we determine later that your property is involved, we will contact you with additional information.

The survey work will include mapping the location of features such as trees, buildings, fences and drives, and obtaining ground elevations. The survey work may also include the identification and mapping of wetlands, archaeological investigations (which may include excavation of small shovel test probes), and various other environmental studies. The survey is needed for the proper planning and design of this highway project. Please be assured of our sincere desire to cause you as little inconvenience as possible during this survey. If any problems do occur, please contact our field crew or contact me at the phone number or address shown herein.

Sincerely,

VS Engineering, Inc.

Andrew B. McClelland, P.S.

ldo B. Wellilla

Project Surveyor

317-293-3542, x-178

Des. No. 1700173

## **APPENDIX H: Air Quality**



**Indiana Division** 

July 31, 2017

575 N. Pennsylvania St, Room 254 Indianapolis, IN 46204 317-226-7475 317-226-7341

In Reply Refer To: HDA-IN

Mr. Trevor Mills Deputy Commissioner Engineering and Asset Management 100 North Senate Avenue Indianapolis, IN 46204

Dear Mr. Mills:

We have completed our review of INDOT's Amendment #18-02 to the FY 2018-2021 Indiana Statewide Transportation Improvement Program (STIP) dated July 26, 2017. FHWA approves it for inclusion into the STIP.

Should you have any questions regarding this approval please contact Joyce Newland at 317-226-5353 or e-mail at joyce.newland@dot.gov.

Sincerely,

JOYCE E

NEWLAND

DN: c=US, o=U.S. Government, ou=DOT FHWAIndianapolisIN, ou=FHWA FHWAIndianapolisIN, cn=JOYCE NEWLAND

Date: 2017.07.31 11:19:18-04:00'

For: Mayela Sosa

**Division Administrator** 

Enclosure

ecc: Michael McNeil, INDOT

Indiana Department of Transportation (INDOT)
State Preservation and Local Initiated Projects FY 2018 - 2021

ונו	state Preservation and Local	and Loc		ited Projects F Y ZU	ts F											
S	SPONSOR	CONTR	STIP	CONTR   STIP   ROUTE   WC	WORK TYPE	LOCATION	DISTRICT	MILES	FEDERAL	Estimated	PROGRAM	PHASE	FEDERAL	MATCH	2018	
		ACT#/	NAME						CATEGORY	Cost left to						
		LEAD								Complete						
		DES								Project*						

servation	and Loc	Illiane	u riojet	I			- 1			I							
SPONSOR	CONTR ACT # / LEAD DES	STIP	ROUTE	ROUTE WORK TYPE	LOCATION	DISTRICT MIL	MILES FEDE	FEDERAL Estimate CATEGORY Cost left Complet Project*	Estimated Cost left to Complete Project*	PROGRAM	PHASE	FEDERAL	МАТСН	2018	2019	2020	2021
Washington County																	
	1593084	A 02	SR 39	Bridge Deck Overlay	0.08 mile S of SR 256 over Cammie-Thomas Ditch	Seymour	0 STP		\$693,109.00 Bridge Constru	Bridge Construction	S S	\$554,487.20	\$138,621.80			\$693,109.00	
	ర	mments: /	Amend CN	Comments: Amend CN phase in FY 2020 to the current STIP. No MPO.	current STIP. No MPO.					•		Ī					
	34558 / 1173265	A 02	IR 1006	Bridge Rehabilitation Or Repair	Bridge 105 on Becks Mil Road in Washington County	Seymour	0 STP		\$440,000.00 Local Bridge Program	Local Bridge Program	S	\$354,913.40	\$0.00	(\$706,400.00)	\$351,486.60		
								_	10 Fu.	100% Local Funds	S	\$0.00	-\$88,728.35	(\$176,600.00)	\$87,871.65		
	<u>8</u>	mments: /	Amend FY	18-21 STIP. Remove CN	Comments: Amend FY18-21 STIP. Remove CN funding from FY18. Add CN funding to FY19. This is a rural local project. No MPO.	g to FY19. This is a rural loc.	al project.	No MPO.	-	-		-					
, -	40433 / 1700168	A 02	SR 56	Br Repl, Conc. Beam Construction	00.20 mile W of SR 135 at Brock Creek	Seymour	0 STP		,636,375.00 Bri	\$1,636,375.00 Bridge Consulting	H	\$160,000.00	\$40,000.00	\$200,000.00			
	S	mments: /	Amend PE	Comments: Amend PE phase in FY 2018 to current STIP. No MPO.	ent STIP. No MPO.					-		-			-		
* [	40453 / 1700173	A 02	SR 60	Br Repl, Comp. Cont. Conc. Construction	00.42 miles W of SR 335 over S Fork Blue River	Seymour	0 STP		,260,138.00 Bri	\$3,260,138.00 Bridge Consulting	Ħ.	\$200,000.00	\$50,000.00	\$250,000.00			
	ర	mments: /	Amend PE	Comments: Amend PE phase in FY 2018 to current STIP. No MPO	ent STIP. No MPO.									_			
, -	40488 / 1701503	A 02	SR 256	Replace Superstructure	01.20 mile E of SR 39 at Muscatatuck River Overflow	Seymour	0 STP		,329,762.00 Bri	\$1,329,762.00 Bridge Consulting	Ⅱ	\$140,000.00	\$35,000.00	\$175,000.00			
	ి	mments: 4	Amend PE	Comments: Amend PE phase in FY 2018 to the current STIP. No MPO.	Surrent STIP. No MPO.												

2019: \$439,358.25 2018: -\$258,000.00 Match :\$174,893.45 Washington County Total Federal: \$699,573.80

2021:

2020: \$693,109.00

\*Estimated Costs left to Complete Project column is for costs that may extend beyond the four years of a STIP. This column is not fiscally constrained and is for information purposes.

Report Created:7/26/2017 12:10:15PM

Page 72 of 75

Indiana Department of Transportation (INDOT) State Preservation and Local Initiated Projects FY 2020 - 2024

orare i lesei variori alla Eocal Illinarea i lojects i	SIG L		200	707 707								
SPONSOR	CONTR ACT#/ LEAD	STIP	ROUTE	WORK TYPE	LOCATION	DISTRICT	MILES	FEDERAL	Estimated Cost left to Complete	PROGRAM	PHASE	FEDERAL
	DES								Project*			
Washington County Washington County	y 34558 /	Init.	IR 1006	Bridge Rehabilitation	Bridge 105 on Becks Mill Road	Seymour	0	0 STPBG		Local Bridge	CN	\$1,016,400.00
	1173265			Or Repair	over Mill Creek in Washington County					Program		
										Local Funds	N	\$0.00
Washington County	34558 / 1173265	M 02	IR 1006	Bridge Rehabilitation Or Repair	Bridge 105 on Becks Mill Road over Mill Creek in Washington County	Seymour	<u>s</u> 0	STBG	\$1,143,721.92	Local Bridge Program	N O	\$120,000.00
										Local Funds	ON	\$0.00
Comments:Adding CN	funds in the	amount	of \$150,00	Comments:Adding CN funds in the amount of \$150,000 for FY 2020. No MPO.								
Washington County	38186 / 1500216	Init.	VA VARI	VA VARI Bridge Inspections	Countywide Bridge Inspection and Inventory Program for Cycle Years 2018-2021	Seymour	S 0	0 STPBG		Local Bridge Program	PE	\$118,439.20
										Local Funds	ЬE	\$0.00
Indiana Department of Transportation	38602 / 1401870	Init.	SR 160	Small Structure Replacement	Over Unnamed Tributary of Springle Creek, 8.0 miles W of US 31	Seymour	<u>s</u> 0	STPBG		Bridge Construction	N O	\$159,373.60
Indiana Department of Transportation	39905 / 1600873	Init.	SR 56	Pavement Replacement, Small Town	0.09 miles E of W Jct of SR 60 to .08 miles E of SR 135 (High St)	Seymour	1.45 STPBG	TPBG		Road ROW	RW	\$569,640.80
										Road Construction	N	\$5,286,760.00
										District Other Construction	N O	\$280,000.00
										Bridge ROW	RW	\$60,000.00
										Bridge Construction	N	\$1,137,891.20
Indiana Department of Transportation	40057 / 1601989	Init.	SR 135	Bridge Painting	3.76 miles S of SR 235 over Muscatatuck River	Seymour	<u>s</u> 0	STPBG		Bridge Consulting	PE	\$92,000.00
										Bridge Construction	N O	\$769,835.20
Indiana Department of Transportation	40410 / 1700009	lnit.	SR 56	Small Structure Pipe Lining	5.46 miles E of SR 135	Seymour	0	0 STPBG		Bridge ROW	RW	\$24,000.00

## **APPENDIX I: Additional Studies**

### United States Department of the Interior National Park Service Land & Water Conservation Fund

# Detailed Listing of Grants Grouped by County

Today's Date: 12/6/2017	,

Page: 41

Grant ID & Element	Type	Grant Element Title	Grant Sponsor	Amount	Status	Date Approved	Exp. Date	Cong. District
WA	WARRICK							
82 - XXX	C	NEWBURGH PARK AND SWIMMING POOL	NEWBURGH PARK BOARD	\$111,076.39	C	3/24/1971	6/30/1973	∞
383 - XXX	D	AMAX ATHLETIC FIELD	NEWBURGH PARK BOARD	\$50,000.00	C	2/13/1981	12/31/1985	∞
			WARRICK County Total:	\$161,076.39		County Count:	2	
WA	WASHINGTON	ON						
186 - XXX	C	CHRISTIAN CHURCH PLAYGROUND	SALEM PARK BOARD	\$10,728.00	C	1/16/1975	12/31/1977	6
316 - XXX	D	D/SALEM COMMUNITY PARK	SALEM PARK BOARD	\$34,206.83	C	7/6/1978	12/31/1980	6
536 - XXX	D	DELANEY CREEK PARK IMPROVEMENTS	WASHINGTON COUNTY PARK BOARD	\$120,934.00	C	3/19/2003	12/31/2008	6
			WASHINGTON County Total:	\$165,868.83		County Count:	3	
WA	WAYNE							
325 - XXX	A	WHITEWATER VALLEY GORGE PARK	RICHMOND PARK BOARD	\$137,736.00	C	12/15/1978	12/31/1981	2
356 - XXX	D	GLEN MILLER PARK LAKE	RICHMOND PARK BOARD	\$84,086.98	O	4/13/1979	12/31/1983	2
462 - XXX	Q	SPRINGWOOD LAKE PARK RENOVATION	RICHMOND PARK BOARD	\$100,000.00	C	2/11/1988	12/31/1992	2
			WAYNE County Total:	\$321,822.98		County Count:	3	



B03002

### HISPANIC OR LATINO ORIGIN BY RACE

Universe: Total population 2013-2017 American Community Survey 5-Year Estimates

Supporting documentation on code lists, subject definitions, data accuracy, and statistical testing can be found on the American Community Survey website in the Technical Documentation section.

Sample size and data quality measures (including coverage rates, allocation rates, and response rates) can be found on the American Community Survey website in the Methodology section.

Although the American Community Survey (ACS) produces population, demographic and housing unit estimates, it is the Census Bureau's Population Estimates Program that produces and disseminates the official estimates of the population for the nation, states, counties, cities, and towns and estimates of housing units for states and counties.

	Washington Co	unty, Indiana	Census Tract 967 County, I	,
	Estimate	Margin of Error	Estimate	Margin of Error
Total:	27,807	****	6,743	+/-406
Not Hispanic or Latino:	27,444	****	6,541	+/-381
White alone	26,948	+/-22	6,471	+/-389
Black or African American alone	25	+/-25	0	+/-16
American Indian and Alaska Native alone	89	+/-110	14	+/-25
Asian alone	48	+/-36	0	+/-16
Native Hawaiian and Other Pacific Islander alone	0	+/-21	0	+/-16
Some other race alone	17	+/-22	3	+/-12
Two or more races:	317	+/-104	53	+/-63
Two races including Some other race	0	+/-21	0	+/-16
Two races excluding Some other race, and three or more races	317	+/-104	53	+/-63
Hispanic or Latino:	363	****	202	+/-99
White alone	358	+/-10	202	+/-99
Black or African American alone	0	+/-21	0	+/-16
American Indian and Alaska Native alone	0	+/-21	0	+/-16
Asian alone	0	+/-21	0	+/-16
Native Hawaiian and Other Pacific Islander alone	0	+/-21	0	+/-16
Some other race alone	5	+/-10	0	+/-16
Two or more races:	0	+/-21	0	+/-16
Two races including Some other race	0	+/-21	0	+/-16
Two races excluding Some other race, and three or more races	0	+/-21	0	+/-16

Data are based on a sample and are subject to sampling variability. The degree of uncertainty for an estimate arising from sampling variability is represented through the use of a margin of error. The value shown here is the 90 percent margin of error. The margin of error can be interpreted roughly as providing a 90 percent probability that the interval defined by the estimate minus the margin of error and the estimate plus the margin of error (the lower and upper confidence bounds) contains the true value. In addition to sampling variability, the ACS estimates are subject to nonsampling error (for a discussion of nonsampling variability, see Accuracy of the Data). The effect of nonsampling error is not represented in these tables.

While the 2013-2017 American Community Survey (ACS) data generally reflect the February 2013 Office of Management and Budget (OMB) definitions of metropolitan and micropolitan statistical areas; in certain instances the names, codes, and boundaries of the principal cities shown in ACS tables may differ from the OMB definitions due to differences in the effective dates of the geographic entities.

Estimates of urban and rural populations, housing units, and characteristics reflect boundaries of urban areas defined based on Census 2010 data. As a result, data for urban and rural areas from the ACS do not necessarily reflect the results of ongoing urbanization.

Source: U.S. Census Bureau, 2013-2017 American Community Survey 5-Year Estimates

### Explanation of Symbols:

- 1. An '\*\*' entry in the margin of error column indicates that either no sample observations or too few sample observations were available to compute a standard error and thus the margin of error. A statistical test is not appropriate.
- 2. An '-' entry in the estimate column indicates that either no sample observations or too few sample observations were available to compute an estimate, or a ratio of medians cannot be calculated because one or both of the median estimates falls in the lowest interval or upper interval of an open-ended distribution.
  - 3. An '-' following a median estimate means the median falls in the lowest interval of an open-ended distribution.
  - 4. An '+' following a median estimate means the median falls in the upper interval of an open-ended distribution.
- 5. An '\*\*\*' entry in the margin of error column indicates that the median falls in the lowest interval or upper interval of an open-ended distribution. A statistical test is not appropriate.
  - 6. An '\*\*\*\*\* entry in the margin of error column indicates that the estimate is controlled. A statistical test for sampling variability is not appropriate.
- 7. An 'N' entry in the estimate and margin of error columns indicates that data for this geographic area cannot be displayed because the number of sample cases is too small.
  - 8. An '(X)' means that the estimate is not applicable or not available.



B17001

### POVERTY STATUS IN THE PAST 12 MONTHS BY SEX BY AGE

Universe: Population for whom poverty status is determined 2013-2017 American Community Survey 5-Year Estimates

Supporting documentation on code lists, subject definitions, data accuracy, and statistical testing can be found on the American Community Survey website in the Technical Documentation section.

Sample size and data quality measures (including coverage rates, allocation rates, and response rates) can be found on the American Community Survey website in the Methodology section.

Although the American Community Survey (ACS) produces population, demographic and housing unit estimates, it is the Census Bureau's Population Estimates Program that produces and disseminates the official estimates of the population for the nation, states, counties, cities, and towns and estimates of housing units for states and counties.

	Washington Co	unty, Indiana	Census Tract 967 County, I	
	Estimate	Margin of Error	Estimate	Margin of Error
Total:	27,478	+/-119	6,732	+/-404
Income in the past 12 months below poverty level:	3,644	+/-665	846	+/-297
Male:	1,623	+/-327	363	+/-163
Under 5 years	188	+/-73	40	+/-36
5 years	60	+/-59	39	+/-57
6 to 11 years	192	+/-77	16	+/-26
12 to 14 years	131	+/-81	3	+/-5
15 years	43	+/-53	0	+/-16
16 and 17 years	36	+/-30	0	+/-16
18 to 24 years	157	+/-65	19	+/-23
25 to 34 years	168	+/-76	25	+/-24
35 to 44 years	120	+/-81	28	+/-40
45 to 54 years	207	+/-85	84	+/-69
55 to 64 years	205	+/-96	83	+/-64
65 to 74 years	81	+/-41	24	+/-26
75 years and over	35	+/-29	2	+/-4
Female:	2,021	+/-398	483	+/-179
Under 5 years	152	+/-72	23	+/-28
5 years	6	+/-11	0	+/-16
6 to 11 years	160	+/-69	27	+/-24
12 to 14 years	89	+/-60	3	+/-6
15 years	37	+/-44	37	+/-44
16 and 17 years	51	+/-38	8	+/-12
18 to 24 years	298	+/-128	70	+/-56
25 to 34 years	236	+/-96	65	+/-48
35 to 44 years	299	+/-101	30	+/-33
45 to 54 years	211	+/-76	65	+/-41
55 to 64 years	208	+/-87	97	+/-73
65 to 74 years	149	+/-60	45	+/-36
75 years and over	125	+/-53	13	+/-16
Income in the past 12 months at or above poverty level:	23,834	+/-694	5,886	+/-416
Male:	11,982	+/-376	3,106	+/-273
Under 5 years	589	+/-74	156	+/-90

	Washington Co	unty, Indiana	Census Tract 967 County, I	
	Estimate	Margin of Error	Estimate	Margin of Error
5 years	53	+/-39	8	+/-10
6 to 11 years	927	+/-149	248	+/-81
12 to 14 years	456	+/-118	39	+/-39
15 years	242	+/-94	16	+/-15
16 and 17 years	285	+/-91	27	+/-25
18 to 24 years	1,008	+/-68	339	+/-90
25 to 34 years	1,348	+/-83	202	+/-82
35 to 44 years	1,649	+/-96	556	+/-145
45 to 54 years	1,839	+/-110	484	+/-109
55 to 64 years	1,752	+/-112	626	+/-118
65 to 74 years	1,150	+/-43	319	+/-74
75 years and over	684	+/-55	86	+/-40
Female:	11,852	+/-390	2,780	+/-291
Under 5 years	632	+/-75	207	+/-90
5 years	154	+/-76	61	+/-53
6 to 11 years	736	+/-126	126	+/-76
12 to 14 years	719	+/-126	163	+/-83
15 years	211	+/-83	33	+/-35
16 and 17 years	315	+/-74	63	+/-43
18 to 24 years	725	+/-129	110	+/-73
25 to 34 years	1,261	+/-97	254	+/-87
35 to 44 years	1,382	+/-104	356	+/-114
45 to 54 years	1,831	+/-75	543	+/-130
55 to 64 years	1,830	+/-74	423	+/-107
65 to 74 years	1,244	+/-74	286	+/-78
75 years and over	812	+/-72	155	+/-64

Data are based on a sample and are subject to sampling variability. The degree of uncertainty for an estimate arising from sampling variability is represented through the use of a margin of error. The value shown here is the 90 percent margin of error. The margin of error can be interpreted roughly as providing a 90 percent probability that the interval defined by the estimate minus the margin of error and the estimate plus the margin of error (the lower and upper confidence bounds) contains the true value. In addition to sampling variability, the ACS estimates are subject to nonsampling error (for a discussion of nonsampling variability, see Accuracy of the Data). The effect of nonsampling error is not represented in these tables.

While the 2013-2017 American Community Survey (ACS) data generally reflect the February 2013 Office of Management and Budget (OMB) definitions of metropolitan and micropolitan statistical areas; in certain instances the names, codes, and boundaries of the principal cities shown in ACS tables may differ from the OMB definitions due to differences in the effective dates of the geographic entities.

Estimates of urban and rural populations, housing units, and characteristics reflect boundaries of urban areas defined based on Census 2010 data. As a result, data for urban and rural areas from the ACS do not necessarily reflect the results of ongoing urbanization.


Source: U.S. Census Bureau, 2013-2017 American Community Survey 5-Year Estimates

### Explanation of Symbols:

- 1. An '\*\*' entry in the margin of error column indicates that either no sample observations or too few sample observations were available to compute a standard error and thus the margin of error. A statistical test is not appropriate.
- 2. An '-' entry in the estimate column indicates that either no sample observations or too few sample observations were available to compute an estimate, or a ratio of medians cannot be calculated because one or both of the median estimates falls in the lowest interval or upper interval of an open-ended distribution.
  - 3. An '-' following a median estimate means the median falls in the lowest interval of an open-ended distribution.
  - 4. An '+' following a median estimate means the median falls in the upper interval of an open-ended distribution.
- 5. An '\*\*\*' entry in the margin of error column indicates that the median falls in the lowest interval or upper interval of an open-ended distribution. A statistical test is not appropriate.
  - 6. An '\*\*\*\*\* entry in the margin of error column indicates that the estimate is controlled. A statistical test for sampling variability is not appropriate.
- 7. An 'N' entry in the estimate and margin of error columns indicates that data for this geographic area cannot be displayed because the number of sample cases is too small.
  - 8. An '(X)' means that the estimate is not applicable or not available.

MISSOURI

KENTUCKY VIRGINIA VIRGINIA



LegendYour SelectionsSelection Results2018 BoundariesNo Legend□ County Washington□ Census Tract 9677

Environmen	Environmental Justice Analysis, 2017 American Community Survey 5-Year Estimates		
Des. No. 170	No. 1700173, SR 60 over South Fork Blue River, New Pekin, Indiana	၁၀၁	AC-1
		Washington County Indiana	Census Tract 9677 Washington County Indiana
	LOW-INCOME		
B17001001	Population for whom poverty status is determined: Total	27,478	6,732
B17001002	Population for whom poverty status is determined: Income in 2017 below poverty level	3,644	846
	Percent Low-Income (Income in 2017 below poverty level/Total population)	13.26%	12.57%
	125 Percent of COC (125 x COC Percent Low-Income)	16.58%	AC <125% COC
	Potential Low-Income EJ Impact?		No
	MINORITY		
B03002001	Total Population: Total	27,807	6,743
B03002002	Total Population: Not Hispanic or Latino	27,444	6,541
B03002003	Total Population: Not Hispanic or Latino; White alone	26,948	6,471
B03002004	Total Population: Not Hispanic or Latino; Black or African American alone	25	0
B03002005	Total Population: Not Hispanic or Latino; American Indian and Alaska Native alone	68	14
B03002006	Total Population: Not Hispanic or Latino; Asian alone	48	0
B03002007	Total Population: Not Hispanic or Latino; Native Hawaiin and Other Pacific Islander alone	0	0
B03002008	Total Population: Not Hispanic or Latino; Some other race alone	17	3
B03002009	Total Population: Not Hispanic or Latino; Two or more races	317	53
B03002010	Total Population: Hispanic or Latino	363	202
B03002011	Total Population: Hispanic or Latino; White alone	358	202
B03002012	Total Population: Hispanic or Latino; Black or African American alone	0	0
B03002013	Total Population: Hispanic or Latino; American Indian and Alaska Native alone	0	0
B03002014	Total Population: Hispanic or Latino; Asian alone	0	0
B03002015	Total Population: Hispanic or Latino; Native Hawaiian and Other Pacific Islander alone	0	0
B03002016	Total Population: Hispanic or Latino; Some other race alone	9	0
B03002017	Total Population: Hispanic or Latino; Two or more races	0	0
	Number Non-white/minority (B03002001 - B03002003)	828	272
	Percent Non-white/Minority (Total population - white alone)/Total population	3.09%	4.03%
	125 Percent of COC (125 x COC Percent Non-white/Minority)	3.86%	AC <125% COC
	Potential Minority EJ Impact?		Yes