



**INTEGRAL CAPS AT SLAB SUPERSTRUCTURE  
(Section Through Interior Bent)**

**Figure 62-3H**