12 7 86

Computer blocking view so I cant take picture another was spreading Debris? Waste? Garbage?

Couch, carpets, foam, Cushions

N

N

W

W

Tires no cover

N

Mud on Rd at Rd 2 going to 41

N

Mud on Road R 2 to 3T R 41

N

Mud on Rd R 2 going to 41

N

Bruce Dilch

LUMBER

S

W

pump. Hoses

N

(E)

Bruce Dilch

4X8 SHEET [illegible] BARD [illegible]

2X2' H-[illegible] FOAM

S

W

[illegible] going to [illegible] [illegible] N-W - [illegible]
of N-W End of new cell

N

W

12-26

12 7 96

[illegible] Fetch

FOG

Carpetta, Cushion

3 PICTURES SOUTH OF RT 2

S

N

W

W

N

R.R. WEST

No cover

Pump hoses going to RR Dutch penetration of lines?

N

N

Pallet - see page RR

N

Steel Barrel, tree stumps, [illegible] cover seepage
grade of ground, east to west to Rail Road
new cell
is this penetration of liner?

(4)

N

RR

seepage, pallet, hole dug out
for water and pump

(3)

new cell, penetration of liner?

N

No ground cover Set 9:00

N

no cover [illegible] on C/D for 2 weeks

N

steel Barrel seepage stumps

N

Tires, Erosion,
No 6 in cover Saturday, 8:30-9:00

RR

W

Paper stumps, Barrel ... lots of carboard

N

... cell little cover in background

N

W

Mattress in Debris "poor cover in background
Plastic Bags, cardboard

N

Tire in Dump

d

No 6 in fill over 2/D
Plastic
paper

N

Tire in R.R. Ditch from Dump

w