WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-476c | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Sambucus canadensis*	10	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	30	Y	FACW
2.	*Urtica dioica*	20	Y	FAC
3.	*Solidago canadensis*	2	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	52		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	40	x 2 =	80
FAC spp.	20	x 3 =	60
FACU spp.	2	x 4 =	8
UPL spp.	0	x 5 =	0
Total	62 (A)		148 (B)

Prevalence Index = B/A = ***2.387***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	J. Currie
Soil Unit:	Gilford fine sandy loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☑, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/03/11
County:	Lake
State:	Indiana
Wetland ID:	W-476c
Sample Point:	2u
Community ID:	Upland
Section:	5
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Portions of soil profile are sandy and therefore naturally problematic.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: n/a	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Gilford fine sandy loam — Series Drainage Class: poorly

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Type	Location	Texture (e.g. clay, sand, loam)
0	14	1	10YR 2/1	100	-- --	--	--	--	Sandy Loam
14	24	2	10YR 4/1	90	10YR 4/6	10	C	M	Sandy Clay Loam
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☑ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]

- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: While soils are hydric, the absence of wetland hydrology and vegetation supports an upland determination.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-476c | Sample Point **2u**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*ROSA MULTIFLORA*	5	Y	FACU
2.	*Juniperus virginiana*	5	Y	FACU
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*POA PRATENSIS*	55	Y	FAC
2.	*CIRSIUM ARVENSE*	20	Y	FACU
3.	*Solidago canadensis*	10	N	FACU
4.	*Solidago gigantea*	10	N	FACW
5.	*GLECHOMA HEDERACEA*	5	N	FACU
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	10	x 2 =	20
FAC spp.	55	x 3 =	165
FACU spp.	45	x 4 =	180
UPL spp.	0	x 5 =	0
Total	110 (A)		365 (B)

Prevalence Index = B/A = ***3.318***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	J. Currie
Soil Unit:	Milford silt loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/03/11
County:	Lake
State:	Indiana
Wetland ID:	W-476d
Sample Point:	1u
Community ID:	Upland
Section:	5
Township:	36 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ Yes ☑ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes ☑ No	Depth: n/a	(in.)
Saturation Present?	☐ Yes ☑ No	Depth: n/a	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Milford silt loam — Series Drainage Class: poorly drained

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	3/2	100	--	--	--	--	--	Sandy Clay Loam
6	12	2	10YR	4/3	95	10YR	4/6	5	C	M	Sandy Clay Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-476d | Sample Point: 1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*ROSA MULTIFLORA*	5	Y	FACU
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	5		

Herb Stratum (Plot size: 2 meter radius)

1.	*Aster firmus*	40	Y	FACW
2.	*DACTYLIS GLOMERATA*	40	Y	FACU
3.	*Solidago canadensis*	20	N	FACU
4.	*Daucus carota*	2	N	UPL
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	102		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***33.3%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	40	x 2 =	80
FAC spp.	0	x 3 =	0
FACU spp.	65	x 4 =	260
UPL spp.	2	x 5 =	10
Total	107 (A)		350 (B)

Prevalence Index = B/A = ***3.271***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	J. Currie
Soil Unit:	Milford silt loam, outwash	NWI/WWI Classification:	PEMA
Landform:	Depression	Local Relief:	Concave
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/03/11
County:	Lake
State:	Indiana
Wetland ID:	W-476d
Sample Point:	1w
Community ID:	PEM
Section:	5
Township:	36 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☑ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: n/a	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Milford silt loam, outwash — Series Drainage Class: poorly drained

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	10	1	10YR 4/1	70	10YR 4/6	30	C	M	Sandy Clay Loam
10	16	2	10YR 2/1	90	10YR 3/6	10	C	PL	Clay Loam
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: Buried A horizon.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-476d | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Solidago gigantea*	50	Y	FACW
2.	*Aster firmus*	20	Y	FACW
3.	*Cyperus esculentus*	10	N	FACW
4.	*Carex sp.*	10	N	--
5.	*Polygonum lapathifolium*	10	N	FACW
6	*Juncus sp.*	2	N	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	102		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	90	x 2 =	180
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	90 (A)		180 (B)

Prevalence Index = B/A = ***2.000***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Rensselaer loam, sandy substratum	NWI/WWI Classification:	PEMC
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Lake
State:	Indiana
Wetland ID:	W-477a
Sample Point:	1u
Community ID:	Upland
Section:	4
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: 1ft above wetland point in an ag field

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Rensselaer loam, sandy substratum Series Drainage Class: poorly drained or very poorly

Taxonomy (Subgroup): Typic Argiaquolls Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	%	Mottles Color (Moist)	Mottles	%	Type	Location	Texture (e.g. clay, sand, loam)
0	7	1	10YR	2/1	--	--	--	--	--	--	Sandy Loam
7	16	2	10YR	4/1	98	10YR	4/3	2	C	M	Sandy Clay Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☑ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-477a | Sample Point: 1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*ZEA MAYS*	95	Y	UPL
2.	*Veronica peregrina*	5	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	5	x 2 =	10
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	95	x 5 =	475
Total	100 (A)		485 (B)

Prevalence Index = B/A = ***4.850***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

Healthy corn, no water stress. Disturbed from ag use. Although wetland soils present, hydrology and vegetation support upland determination.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Stantec

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Rensselaer loam, sandy substratum	NWI/WWI Classification:	PEMC
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Lake
State:	Indiana
Wetland ID:	W-477a
Sample Point:	1w
Community ID:	PEM
Section:	4
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Depressional area in ag field, not planted.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:
- ☐ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 4	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Standing water in some areas, but not where the sample point was taken.

SOILS

Map Unit Name: Rensselaer loam, sandy substratum Series Drainage Class: poorly drained or very poorly

Taxonomy (Subgroup): Typic Argiaquolls Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	1	N	2.5/0	98	2.5Y	4/3	2	C	M	Silt Loam
8	16	2	2.5Y	4/1	98	10YR	4/3	2	C	M	Sandy Clay Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☑ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☑ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-477a | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Cyperus esculentus*	60	Y	FACW
2.	*Xanthium strumarium*	15	N	FAC
3.	*Ranunculus sceleratus*	10	N	OBL
4.	*Panicum dichotomiflorum*	5	N	FACW
5.	*Setaria faberi*	5	N	FACU
6	*RUMEX CRISPUS*	2	N	FAC
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	97		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	10	x 1 =	10
FACW spp.	65	x 2 =	130
FAC spp.	17	x 3 =	51
FACU spp.	5	x 4 =	20
UPL spp.	0	x 5 =	0
Total	97 (A)		211 (B)

Prevalence Index = B/A = ***2.175***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Alida loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11		
County:	Lake		
State:	Indiana		
Wetland ID:	W-477a		
Sample Point:	2u		
Community ID:	Upland		
Section:	4		
Township:	35 N		
Range:	7	Dir:	W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: 1-2 ft above wetland point in an ag field

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Alida loam — Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aquollic Hapludalfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR 2/1	--	--	--	--	--	Silt loam
12	16	2	10YR 5/2	98	10YR 5/8	2	C	M	Sandy Clay Loam
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-477a	Sample Point	2u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*ZEA MAYS*	90	Y	UPL
2.	*Veronica peregrina*	2	N	FACW
3.	*XANTHIUM STRUMARIUM*	5	N	FAC
4.	*Cerastium arvense*	2	N	FACU
5.	*Panicum dichotomiflorum*	2	N	FACW
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	101		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	4	x 2 =	8
FAC spp.	5	x 3 =	15
FACU spp.	2	x 4 =	8
UPL spp.	90	x 5 =	450
Total	101 (A)		481 (B)

Prevalence Index = B/A = ***4.762***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

Healthy corn in this location. No signs of water stress.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Stantec

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Tracy loam, 2 to 6 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/18/12
County:	Lake
State:	Indiana
Wetland ID:	W-477b
Sample Point:	1u
Community ID:	upland
Section:	4
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Pasture area upgradient of wetland.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Tracy loam, 2 to 6 percent slopes — Series Drainage Class: well

Taxonomy (Subgroup): Ultic Hapludalfs — Field Observations Confirm Mapped Type? ☐ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	13	1	10YR	3/2	100	--	--	--	--	--	sandy clay loam
13	18	2	10YR	4/2	80	10YR	5/8	20	C	M	clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-477b	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*TRIFOLIUM PRATENSE*	35	Y	FACU
2.	*DACTYLIS GLOMERATA*	40	Y	FACU
3.	*TARAXACUM OFFICINALE*	5	N	FACU
4.	*DAUCUS CAROTA*	10	N	UPL
5.	*PLANTAGO LANCEOLATA*	5	N	FAC
6	*FESTUCA ARUNDINACEA*	10	N	FACU
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	105		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	5	x 3 =	15
FACU spp.	90	x 4 =	360
UPL spp.	10	x 5 =	50
Total	105 (A)		425 (B)

Prevalence Index = B/A = ***4.048***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Adrian muck	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/18/12
County:	Lake
State:	Indiana
Wetland ID:	W-477b
Sample Point:	1w
Community ID:	EM1
Section:	4
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Sample point in emergent wetland adjacent to open pond.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☑ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 2	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Adrian muck — Series Drainage Class: very poorly

Taxonomy (Subgroup): Terric Haplosaprists — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	4	1	10YR	3/1	100	--	--	--	--	--	mucky silt loam
4	18	2	N	2.5/0	100	--	--	--	--	--	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☑ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☑ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-477b	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	95	Y	FACW
2.	*Impatiens capensis*	5	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	100	x 2 =	200
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	100 (A)		200 (B)

Prevalence Index = B/A = ***2.000***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Dominated by invasive reed canary grass.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Tracy sandy loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478a
Sample Point:	1u
Community ID:	Upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Tracy sandy loam — Series Drainage Class: well drained

Taxonomy (Subgroup): Ultic Hapludalfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	Matrix %	Mottles Color (Moist)	Mottles	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	4/1	100	--	--	--	--	--	Silt Loam
6	13	2	10YR	3/1	100	--	--	--	--	--	Silt Loam
13	20	3	10YR	4/1	95	2.5Y	5/6	5	C	M	Silt Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-478a | Sample Point **1u**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Prunus pumila*	20	Y	NI
2.	*Morus alba*	15	Y	FAC
3.	*Fraxinus pennsylvanica*	10	Y	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	45		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer saccharinum*	10	Y	FACW
2.	*Lonicera x bella*	5	Y	FACU
3.	*Morus alba*	5	Y	FAC
4.	*rubus occidentalis*	5	Y	UPL
5.	*Prunus virginiana*	5	Y	FAC
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	30		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	20	Y	FACW
2.	*DAUCUS CAROTA*	15	Y	UPL
3.	*Aster pilosus*	10	Y	FACU
4.	*Equisetum arvense*	10	Y	FAC
5.	*CIRSIUM ARVENSE*	10	Y	FACU
6	*FESTUCA ARUNDINACEA*	5	N	FACU
7.	*SETARIA FABERI*	5	N	FACU
8.	*Conyza canadensis*	5	N	FAC
9.	*Solidago canadensis*	5	N	FACU
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	85		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 7 (A)

Total Number of Dominant Species Across All Strata: 13 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***53.8%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	40	x 2 =	80
FAC spp.	40	x 3 =	120
FACU spp.	40	x 4 =	160
UPL spp.	40	x 5 =	200
Total	160 (A)		560 (B)

Prevalence Index = B/A = ***3.500***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

Mixture of wetland and upland vegetation and although vegetation meets one hydrophytic criteria, lack of hydrology and hydric soils supports upland determination.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Tracy sandy loam	NWI/WWI Classification:	PEMF
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478a
Sample Point:	1w
Community ID:	PEM/PSS
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 14	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Although the soils are not quite hydric, the overwhelming evidence for wetland hydrology and hydrophytic vegetation in conjunction with professional judgement supports a determination of wetland at this location.

SOILS

Map Unit Name: Tracy sandy loam — Series Drainage Class: well drained
Taxonomy (Subgroup): Ultic Hapludalfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	Matrix %	Mottles Color (Moist)	Mottles	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	1	10YR	3/1	100	--	--	--	--	--	Silty Clay Loam
8	14	2	10YR	2/1	100	--	--	--	--	--	Silt Loam
14	20	3	10YR	2/1	95	10YR	3/3	5	C	M	Silt Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: Sand seams in C horizon, 10YR 3/2. This is close to F6 redox dark surface.

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478a	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Fraxinus pennsylvanica*	10	Y	FACW
2.	*Salix nigra*	5	Y	OBL
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Salix sp.*	5	Y	--
2.	*Sambucus canadensis*	5	Y	FACW
3.	*Acer rubrum*	5	Y	FAC
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	100	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 5 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***83.3%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	5	x 1 =	5
FACW spp.	115	x 2 =	230
FAC spp.	5	x 3 =	15
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	125 (A)		250 (B)

Prevalence Index = B/A = ***2.000***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

Although the soils are not quite hydric, the overwhelming evidence for wetland hydrology and hydrophytic vegetation in conjunction with professional judgement supports a determination of wetland at this location.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Milford silty clay loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478b
Sample Point:	1u
Community ID:	Upland
Section:	3
Township:	35 N
Range:	7 Dir: W

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ Yes ☑ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes ☑ No	Depth: N/A	(in.)
Saturation Present?	☐ Yes ☑ No	Depth: N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Milford silty clay loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	Matrix %	Mottles Color (Moist)	Mottles	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	16	1	10YR	3/1	100	--	--	--	--	--	Silt Loam
16	20	2	2.5Y	5/2	90	2.5YR	5/4	10	C	M	Silty Clay Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478b	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*FESTUCA ARUNDINACEA*	70	Y	FACU
2.	*TRIFOLIUM PRATENSE*	20	Y	FACU
3.	*POA PRATENSIS*	10	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	10	x 3 =	30
FACU spp.	90	x 4 =	360
UPL spp.	0	x 5 =	0
Total	100 (A)		390 (B)

Prevalence Index = B/A = ***3.900***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Milford silty clay loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478b
Sample Point:	1w
Community ID:	PFO
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☑ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☑ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 10	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: In addition to saturation, two other primary indicators support presence of wetland hydrology.

SOILS

Map Unit Name: Milford silty clay loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	2	1	2.5Y	2/0	100	--	--	--	--	--	Silt Loam
2	8	2	2.5Y	4/2	80	7.5YR	3/4	20	C	M	Silt Loam
8	16	3	2.5Y	2/6	80	2.5Y	6/2	20	C	M	Silt Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☑ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-478b | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Populus deltoides*	90	Y	FAC
2.	*Salix amygdaloides*	10	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	100		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Salix amygdaloides*	10	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	10		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	5	Y	FACW
2.	*Ranunculus abortivus*	1	Y	FACW
3.	*Aster lateriflorus*	1	Y	FACW
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	7		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 5 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	27	x 2 =	54
FAC spp.	90	x 3 =	270
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	117 (A)		324 (B)

Prevalence Index = B/A = ***2.769***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Milford silty clay loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Lake
State:	Indiana
Wetland ID:	W-478c
Sample Point:	1u
Community ID:	Upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 15	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Saturation in pit at 15"

SOILS

Map Unit Name: Milford silty clay loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR	3/1	100	--	--	--	--	--	Silty Loam
12	17	2	10YR	4/1	100	--	--	--	--	--	Silty Clay Loam
17	20	3	2.5YR	5/2	90	2.5Y	5/4	10	C	M	Silty Clay
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478c	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*FESTUCA ARUNDINACEA*	70	Y	FACU
2.	*TRIFOLIUM PRATENSE*	20	Y	FACU
3.	*POA PRATENSIS*	10	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	10	x 3 =	30
FACU spp.	90	x 4 =	360
UPL spp.	0	x 5 =	0
Total	100 (A)		390 (B)

Prevalence Index = B/A = ***3.900***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

Hay field

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Milford silty clay loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Date:	11/08/11
County:	Lake
State:	Indiana
Wetland ID:	W-478c
Sample Point:	1w
Community ID:	PEM
Section:	3
Township:	35 N
Range:	7 Dir: W

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:
- ☑ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☑ Yes	☐ No	Depth: 2	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 0	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Hydric soil criteria very close to being positive, based on overwhelming evidence of wetland hydrology and vegetation, combined with professional judgement, a determination of wetland is supported at this location.

SOILS

Map Unit Name: Milford silty clay loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	18	1	10YR	3/1	100	--	--	--	--	--	Silty Clay Loam
18	20	2	2.5YR	5/1	80	2.5YR	4/4	20	C	M	Silty Clay
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: This very close to A12 indicator.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-478c | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	95	Y	FACW
2.	*POA PRATENSIS*	5	N	FAC
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	95	x 2 =	190
FAC spp.	5	x 3 =	15
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	100 (A)		205 (B)

Prevalence Index = B/A = ***2.050***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

Hay field

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Whitaker loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Lake
State:	Indiana
Wetland ID:	W-478c
Sample Point:	2u
Community ID:	Upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present?	☐ Yes ☑ No	Hydric Soils Present?	☐ Yes ☑ No
Wetland Hydrology Present?	☐ Yes ☑ No	Is This Sampling Point Within A Wetland?	☐ Yes ☑ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes ☑ No	Depth: N/A	(in.)
Saturation Present?	☐ Yes ☑ No	Depth: N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Whitaker loam — Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Aeric Endoaqualfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	16	1	10YR	3/1	100	--	--	--	--	--	Silty Clay Loam
16	20	2	2.5YR	5/2	90	5YR	3/4	10	C	M	Sitly Clay Loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478c	Sample Point	2u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*FESTUCA ARUNDINACEA*	70	Y	FACU
2.	*TRIFOLIUM PRATENSE*	20	Y	FACU
3.	*POA PRATENSIS*	5	N	FAC
4.	*Aster firmus*	5	N	FACW
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	5	x 2 =	10
FAC spp.	5	x 3 =	15
FACU spp.	90	x 4 =	360
UPL spp.	0	x 5 =	0
Total	100 (A)		385 (B)

Prevalence Index = B/A = ***3.850***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

Hay field

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Whitaker loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478d
Sample Point:	1u
Community ID:	Upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Point approximately 1ft higher than wetland point

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☑ Yes	☐ No	Depth: 1	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Historically farmed area, rutting from equipment holds water. Rain was falling during sampling causing accumulation of surface water - this does not constitute wetland hydrology at this time.

SOILS

Map Unit Name: Whitaker loam — Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Aeric Endoaqualfs — Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	13	1	10YR 2/1	--	--	--	--	--	Silt Loam
13	16	2	2.5Y 4/3	98	10YR 5/6	5	C	M	Silty Clay Loam
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☐

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Indiana Line 6B | Wetland ID: W-478d | Sample Point: 1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*FESTUCA ARUNDINACEA*	95	Y	FACU
2.	*TRIFOLIUM PRATENSE*	5	N	FACU
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	100	x 4 =	400
UPL spp.	0	x 5 =	0
Total	100 (A)		400 (B)

Prevalence Index = B/A = ***4.000***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

Precipitation during field work not indicative of wetland hydrologic conditions.

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Stantec

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Milford silty clay loam	NWI/WWI Classification:	--
Landform:	Depression	Local Relief:	Concave
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478d
Sample Point:	1w
Community ID:	PEM
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Soils are close to hydric and based on overwhelming evidence of wetland hydrology and hydrdophytic vegetation, combined with professional judgement, a determination of wetland is supported at this location.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:
- ☑ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☑ Yes	☐ No	Depth: 4	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 0	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Depressional area

SOILS

Map Unit Name: Milford silty clay loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	11	1	10YR 2/1	--	--	--	--	--	Silt Loam
11	16	2	2.5Y 3/1	95	10YR 5/8	5	C	M	Silty Clay Loam
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: Close to F6 and A11 indicators.

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478d	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	100	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	100	x 2 =	200
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	100 (A)		200 (B)

Prevalence Index = B/A = ***2.000***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Whitaker loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478e
Sample Point:	1u
Community ID:	Upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 17	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Old ag field

SOILS

Map Unit Name: Whitaker loam — Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Aeric Endoaqualfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	%	Mottles Color (Moist)	Mottles	%	Type	Location	Texture (e.g. clay, sand, loam)
0	18	1	10YR	3/1	--	--	--	--	--	--	Silt Loam
18	21	2	2.5Y	4/2	90	2.5YR	5/4	10	C	M	Silty Clay
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478e	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*FESTUCA ARUNDINACEA*	60	Y	FACU
2.	*TRIFOLIUM PRATENSE*	40	Y	FACU
3.	*PHLEUM PRATENSE*	10	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	110		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	110	x 4 =	440
UPL spp.	0	x 5 =	0
Total	110 (A)		440 (B)

Prevalence Index = B/A = ***4.000***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Milford silty clay loam	NWI/WWI Classification:	--
Landform:	Depression	Local Relief:	Concave
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478e
Sample Point:	1w
Community ID:	PEM
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☑ Yes ☐ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☐

Primary:
- ☑ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☑ Yes	☐ No	Depth: 1	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 8	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Depression in hay field. Surface water due to recent rain. Soils are close to hydric and based on overwhelming evidence of wetland hydrology and hydrophytic vegetation, combined with professional judgement, a determination of wetland is supported at this location.

SOILS

Map Unit Name: Milford silty clay loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	15	1	10YR 3/1	--	--	--	--	--	Silt Clay
15	20	2	2.5Y 4/2	90	2.5Y 5/6	10	C	M	Silty Clay
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: Very close to indicator A12.

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478e	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	100	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	100	x 2 =	200
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	100 (A)		200 (B)

Prevalence Index = B/A = ***2.000***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	B. Kuykendall	Investigator #2:	A. Binkowski
Soil Unit:	Whitaker loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/08/11
County:	Porter
State:	Indiana
Wetland ID:	W-478e
Sample Point:	2u
Community ID:	Upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present): ☑

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: N/A	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Old ag field

SOILS

Map Unit Name: Whitaker loam — Series Drainage Class: somewhat poorly drained

Taxonomy (Subgroup): Aeric Endoaqualfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	1	10YR 3/2	--	--	--	--	--	Silt Loam
8	10	2	2.5Y 5/3	--	--	--	--	--	Silty Clay Loam
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present): ☑

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-478e	Sample Point	2u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*FESTUCA ARUNDINACEA*	80	Y	FACU
2.	*TRIFOLIUM PRATENSE*	10	N	FACU
3.	*POA PRATENSIS*	5	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	95		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	5	x 3 =	15
FACU spp.	90	x 4 =	360
UPL spp.	0	x 5 =	0
Total	95 (A)		375 (B)

Prevalence Index = B/A = ***3.947***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

--

Stantec

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Whitaker loam	NWI/WWI Classification:	--
Landform:	Slope	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-478f
Sample Point:	1u
Community ID:	upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Sample point midslope in mesic woodland.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	n/a	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	>18	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	>18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Whitaker loam — Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Endoaqualfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	Matrix %	Mottles Color (Moist)	Mottles	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	10	1	10YR	2/2	100	--	--	--	--	--	silty clay loam
10	18	2	10YR	3/2	90	10YR	3/6	10	C	M	clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-478f	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Celtis occidentalis*	30	Y	FAC
2.	*Acer saccharum*	40	Y	FACU
3.	*Ulmus americana*	10	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	80		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer saccharum*	40	Y	FACU
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	40		

Herb Stratum (Plot size: 2 meter radius)

1.	*Asarum canadense*	20	Y	NI
2.	*Galium aparine*	20	Y	FACU
3.	*Parthenocissus quinquefolia*	5	N	FAC
4.	*Hydrophyllum virginianum*	3	N	FACW
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	48		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***20.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	13	x 2 =	26
FAC spp.	35	x 3 =	105
FACU spp.	100	x 4 =	400
UPL spp.	20	x 5 =	100
Total	168 (A)		631 (B)

Prevalence Index = B/A = ***3.756***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

Stantec

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Suman silt loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-478f
Sample Point:	1w
Community ID:	EM1
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Sample point within floodplain-like setting, lower area, water likely moves through in spring and high precipation events.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 14	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Check precipitation records, potentially dry season water table near creek.

SOILS

Map Unit Name: Suman silt loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Fluvaquentic Endoaquolls — Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	14	1	10YR	2/1	100	--	--	--	--	--	clay loam
14	20	2	10YR	4/2	80	7.5YR	4/6	20	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☑ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-478f	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Lindera benzoin*	15	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	15		

Herb Stratum (Plot size: 2 meter radius)

1.	*PHALARIS ARUNDINACEA*	30	Y	FACW
2.	*Urtica dioica*	10	N	FAC
3.	*Geranium maculatum*	10	N	FACU
4.	*Trillium recurvatum*	2	N	FACU
5.	*ARCTIUM MINUS*	5	N	UPL
6	*Hydrophyllum virginianum*	60	Y	FACW
7.	*Sambucus canadensis*	3	N	FACW
8.	*Carex sp.*	3	N	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	123		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	108	x 2 =	216
FAC spp.	10	x 3 =	30
FACU spp.	12	x 4 =	48
UPL spp.	5	x 5 =	25
Total	135 (A)		319 (B)

Prevalence Index = B/A = ***2.363***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

--

Stantec

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Suman silt loam	NWI/WWI Classification:	--
Landform:	Slope	Local Relief:	--
Slope (%):	5	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-478g
Sample Point:	1u
Community ID:	upland
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Mid slope above wetland in mesic woodland

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks:

SOILS

Map Unit Name: Suman silt loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Fluvaquentic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	Matrix %	Mottles Color (Moist)	Mottles	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	3/3	100	--	--	--	--	--	fine sandy clay loam
6	18	2	10YR	4/3	95	10YR	4/6	5	C	M	sandy clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Line 6B Phase 2 Replacement Project | Wetland ID: W-478g | Sample Point: 1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Prunus serotina*	10	N	FACU
2.	*Acer saccharum*	50	Y	FACU
3.	*Tilia americana*	20	Y	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	80		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer saccharum*	40	Y	FACU
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	40		

Herb Stratum (Plot size: 2 meter radius)

1.	*Galium aparine*	80	Y	FACU
2.	*Parthenocissus quinquefolia*	5	N	FAC
3.	*Cardamine concatenata*	10	N	FACU
4.	*Smilacina racemosa*	5	N	FACU
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	5	x 3 =	15
FACU spp.	215	x 4 =	860
UPL spp.	0	x 5 =	0
Total	220 (A)		875 (B)

Prevalence Index = B/A = ***3.977***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Stantec

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Suman silt loam	NWI/WWI Classification:	PFO1A
Landform:	Floodplain	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-478g
Sample Point:	1w
Community ID:	FO1
Section:	3
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Sample point adjacent to stream within woodland.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☑ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 6	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 0	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Suman silt loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Fluvaquentic Endoaquolls — Field Observations Confirm Mapped Type? ☐ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	8	1	10YR	3/1	80	7.5YR	4/6	20	C	M, PL	Silty clay loam
8	18	2	10YR	5/2	70	7.5YR	4/6	30	C	M	clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☑ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]

- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Line 6B Phase 2 Replacement Project | Wetland ID: W-478g | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Tilia americana*	50	Y	FACU
2.	*Ulmus americana*	25	Y	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	75		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Lindera benzoin*	30	Y	FACW
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	30		

Herb Stratum (Plot size: 2 meter radius)

1.	*Toxicodendron rydbergii*	15	Y	FAC
2.	*Glyceria striata*	10	N	OBL
3.	*Hydrophyllum virginianum*	15	Y	FACW
4.	*Carex sp.*	5	N	NI
5.	*PHALARIS ARUNDINACEA*	10	N	FACW
6	*Impatiens capensis*	5	N	FACW
7.	*Ranunculus hispidus var. nitidus*	15	Y	FACW
8.	*ROSA MULTIFLORA*	1	N	FACU
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	76		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 5 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***83.3%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	10	x 1 =	10
FACW spp.	100	x 2 =	200
FAC spp.	15	x 3 =	45
FACU spp.	51	x 4 =	204
UPL spp.	5	x 5 =	25
Total	181 (A)		484 (B)

Prevalence Index = B/A = ***2.674***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Invasive reed canary grass present.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Kraszewski	Investigator #2:	D. Tersteeg
Soil Unit:	Haskins loam, 0 to 2 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-479b
Sample Point:	1u
Community ID:	upland
Section:	2
Township:	35 N
Range:	7 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Upgradient from wetland in open field in transmission right of way, adjacent to landfill mound.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	n/a	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	>18	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	>18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: --

SOILS

Map Unit Name: Haskins loam, 0 to 2 percent slopes Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	10	1	10YR	4/3	100	--	--	--	--	--	sandy clay loam
10	18	2	10YR	4/3	70	10YR	5/8	30	C	M	clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM

Northcentral and Northeast Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-479b	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Festuca sp.*	90	Y	UPL
2.	*TRIFOLIUM PRATENSE*	5	N	FACU
3.	*TARAXACUM OFFICINALE*	3	N	FACU
4.	*DAUCUS CAROTA*	5	N	UPL
5.	*CIRSIUM VULGARE*	5	N	FACU
6.	*DIPSACUS FULLONUM SUBSP. SYL*	2	N	NI
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	110		

Herb Stratum (Plot size: 2 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	0		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	13	x 4 =	52
UPL spp.	97	x 5 =	485
Total	110 (A)		537 (B)

Prevalence Index = B/A = ***4.882***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Stantec

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Haskins loam, 0 to 2 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-479b
Sample Point:	1w
Community ID:	EM1
Section:	2
Township:	35 N
Range:	7 W --

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Wet meadow within transmission right of way. Receives artificial surface water from nearby landfill.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B15 - Marl Deposits
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ Other (Explain)

Secondary:
- ☑ B6 - Surface Soil Cracks
- ☑ B10 - Drainage Patterns
- ☐ B16 - Moss Trim Lines
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D3 - Shallow Aquitard
- ☐ D4 - Microtopographic Relief
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Hummockly sedge clumps with bare ground with surface cracks in between.

SOILS

Map Unit Name: Haskins loam, 0 to 2 percent slopes Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	3/1	80	10YR	4/6	20	C	M	clay loam
6	18	2	10YR	4/2	70	7.5YR	4/6	30	C	M	clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ S7 - Dark Surface (**LRR R, MLRA 149B**)
- ☐ S8 - Polyvalue Below Surface (**LRR R, MLRA 149B**)
- ☐ S9 - Thin Dark Surface (**LRR R, MLRA 149B**)
- ☐ F1 - Loamy Muck Mineral (**LRR K, L**)
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A10 - 2 cm Muck (**LRR K, L, MLRA149B**)
- ☐ A16 - Coast Prairie Redox (**LRR K, L, R**)
- ☐ S3 - 5cm Mucky Peat of Peat (**LRR K, L, R**)
- ☐ S7 - Dark Surface (**LRR K, L**)
- ☐ S8 - Polyvalue Below Surface (**LRR K, L**)
- ☐ S9 - Thin Dark Surface (**LRR K, L**)
- ☐ F12 - Iron-Manganese Masses (**LRR K, L, R**)
- ☐ F19 - Piedmont Floodplain Soils (**MLRA 149B**)
- ☐ TA6 - Mesic Spodic (**MLRA 144A, 145, 149B**)
- ☐ TF2 - Red Parent Material
- ☐ TF12 - Very Shallow Dark Surface
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Northcentral and Northeast Region

Project/Site: Line 6B Phase 2 Replacement Project | Wetland ID: W-479b | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Carex cristatella*	40	Y	FACW
2.	*PHALARIS ARUNDINACEA*	10	N	FACW
3.	*POA PRATENSIS*	10	N	FAC
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	60		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	50	x 2 =	100
FAC spp.	10	x 3 =	30
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	60 (A)		130 (B)

Prevalence Index = B/A = ***2.167***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Patchy bare ground. Invasive reed canary grass present.

Additional Remarks:

Wetland fringe to artificial ditch bordering landfill.

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	D. Tersteeg	Investigator #2:	S. Kraszewski
Soil Unit:	Houghton muck, ponded	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-481a
Sample Point:	1u
Community ID:	upland
Section:	31
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Sample point within hayfield. Healthy rye.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	na	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	>24	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	>24	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Houghton muck, ponded — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Haplosaprists — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	%	Mottles Color (Moist)	Mottles	%	Type	Location	Texture (e.g. clay, sand, loam)
0	20	1	10YR	2/2	100	--	--	--	--	--	silty clay loam
20	24	2	10YR	2/1	100	--	--	--	--	--	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-481a	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Elymus sp.*	70	Y	--
2.	*LAMIUM AMPLEXICAULE*	10	N	NI
3.	*Lepidium virginicum*	5	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	85		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	5	x 4 =	20
UPL spp.	10	x 5 =	50
Total	15 (A)		70 (B)

Prevalence Index = B/A = ***4.667***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: Field planted rye.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Kraszewski	Investigator #2:	D. Tersteeg
Soil Unit:	Houghton muck, ponded	NWI/WWI Classification:	--
Landform:	depression	Local Relief:	concave
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-418a
Sample Point:	**1w**
Community ID:	EM1
Section:	31
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Depressional basin within agricultural field. Area was not farmed in 2011.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☑ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☑ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☑ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☑ Yes	☐ No	Depth: 12	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 5	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: n/a

Remarks: --

SOILS

Map Unit Name: Houghton muck, ponded — Series Drainage Class: very poorly

Taxonomy (Subgroup): Typic Haplosaprists — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	5	1	10YR	2/1	100	--	--	--	--	--	mucky silt loam
5	10	2	10YR	2/1	100	--	--	--	--	--	silt loam
10	16	3	10YR	2/1	100	--	--	--	--	--	loam
16	20	4	10YR	3/1	100	--	--	--	--	--	silt loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☑ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: Third layer is buried historic surface horizon. Plant debris(cattail) found within layer.

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-418a	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*ECHINOCHLOA CRUSGALLI*	40	Y	FACW
2.	*Bidens frondosus*	5	N	FACW
3.	*Eleocharis sp.*	10	N	FACW
4.	*RUMEX CRISPUS*	3	N	FAC
5.	*Ludwigia palustris*	5	N	OBL
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	63		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	5	x 1 =	5
FACW spp.	55	x 2 =	110
FAC spp.	3	x 3 =	9
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	63 (A)		124 (B)

Prevalence Index = B/A = ***1.968***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	J. Delmedico	Investigator #2:	S. Carlson
Soil Unit:	Morley silt loam, 18 to 30 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	Slope
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/18/12
County:	Porter
State:	Indiana
Wetland ID:	W-482a
Sample Point:	**1u**
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ **Yes** ☑ **No**

Remarks: Upland vegetation, no hydrology. Some mottles in soil.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	n/a	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	>24	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	>24	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: On an approx. 9% slope, no hydrology

SOILS

Map Unit Name: Morley silt loam, 18 to 30 percent slopes Series Drainage Class: moderately well

Taxonomy (Subgroup): Oxyaquic Hapludalfs Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR	4/3	100	--	--	--	--	--	silt loam
12	18+	2	10YR	4/3	95	7.5YR	3/4	5	C	M	silt loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: Soils show signs of disturbance

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482a	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*CORONILLA VARIA*	80	Y	NI
2.	*CIRSIUM ARVENSE*	15	N	FACU
3.	*POA PRATENSIS*	10	N	FAC
4.	*DACTYLIS GLOMERATA*	5	N	FACU
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	110		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	10	x 3 =	30
FACU spp.	20	x 4 =	80
UPL spp.	80	x 5 =	400
Total	110 (A)		510 (B)

Prevalence Index = B/A = ***4.636***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: Teasle and yellow rocket also present.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Carlson	Investigator #2:	J. Delmedico
Soil Unit:	Fluvaquents	NWI/WWI Classification:	PEM/SS1C
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-482a
Sample Point:	**1w**
Community ID:	SS1
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks:

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☑ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Fluvaquents — Series Drainage Class: n/a

Taxonomy (Subgroup): n/a — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	4	1	10YR	3/1	80	7.5YR	4/6	15	C	M	silty clay loam
0	4	1	10YR	3/1	60	10YR	3/4	5	C	M	silty clay loam
4	18	2	10YR	4/2	80	7.5YR	4/6	20	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site: Line 6B Phase 2 Replacement Project | Wetland ID: W-482a | Sample Point: 1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Salix amygdaloides*	20	Y	FACW
2.	*Salix nigra*	15	Y	OBL
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	35		

Herb Stratum (Plot size: 2 meter radius)

1.	*Phragmites australis*	90	Y	FACW
2.	*PHALARIS ARUNDINACEA*	10	N	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	15	x 1 =	15
FACW spp.	120	x 2 =	240
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	135 (A)		255 (B)

Prevalence Index = B/A = ***1.889***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☐ No Morphological Adaptations (Explain) *
- ☐ Yes ☐ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Dominated by invasive common reed with invasive reed canary grass also present.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Carlson	Investigator #2:	J. Delmedico
Soil Unit:	Morley silt loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☑, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-482b
Sample Point:	1u
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Sample point taken within right-of-way.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Morley silt loam — Series Drainage Class: moderately well

Taxonomy (Subgroup): Oxyaquic Hapludalfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	14	1	10YR	3/1	95	10YR	4/6	5	C	M	silty clay loam
14	18	1	10YR	3/3	90	7.5YR	4/6	5	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: Point taken within existing ROW; soils have likely been disturbed / graded. Despite the presence of hydric soils, the absence of wetland hydrology and vegetation supports an upland determination.

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482b	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Solidago canadensis*	25	Y	FACU
2.	*BARBAREA VULGARIS*	25	Y	FAC
3.	*Taraxacum officinale*	25	Y	FACU
4.	*DIPSACUS FULLONUM SUBSP. SYL*	20	Y	NI
5.	*Rubus idaeus var. strigosus*	5	N	FACW
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***25.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	5	x 2 =	10
FAC spp.	25	x 3 =	75
FACU spp.	50	x 4 =	200
UPL spp.	20	x 5 =	100
Total	100 (A)		385 (B)

Prevalence Index = B/A = ***3.850***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Carlson	Investigator #2:	J. Delmedico
Soil Unit:	Morley silt loam	NWI/WWI Classification:	--
Landform:	Depression	Local Relief:	Concave
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-482b
Sample Point:	**1w**
Community ID:	EM1
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks:

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: Wetland located in small depression. Evidence of inundation.

SOILS

Map Unit Name: Morley silt loam — Series Drainage Class: moderately well

Taxonomy (Subgroup): Oxyaquic Hapludalfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	3/1	90	10YR	3/4	5	--	--	silty clay loam
0	6	1	--	--	--	7.5YR	4/6	5	--	--	silty clay loam
6	18+	2	10YR	5/1	95	7.5YR	4/6	5	--	--	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☑ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482b	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Eleocharis erythropoda*	70	Y	OBL
2.	*Scirpus atrocinctus*	30	Y	OBL
3.	*PHALARIS ARUNDINACEA*	10	N	FACW
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	110		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	100	x 1 =	100
FACW spp.	10	x 2 =	20
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	110 (A)		120 (B)

Prevalence Index = B/A = ***1.091***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Invasive reed canary grass present.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Carlson	Investigator #2:	J. Delmedico
Soil Unit:	Blount silt loam, 0 to 3 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/18/12
County:	Porter
State:	Indiana
Wetland ID:	W-482c
Sample Point:	1u
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks:

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Blount silt loam, 0 to 3 percent slopes Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	2	1	10YR 3/2	100	-- --	--	--	--	silty clay loam
2	18	2	10YR 4/1	100	-- --	--	--	--	silty clay loam
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--
--	--	--	-- --	--	-- --	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482c	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*POA PRATENSIS*	50	Y	FAC
2.	*Solidago canadensis*	20	Y	FACU
3.	*BARBAREA VULGARIS*	5	N	FAC
4.	*TRIFOLIUM REPENS*	10	N	FACU
5.	*Aster spp.*	10	N	--
6	*BROMUS INERMIS*	10	N	UPL
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	105		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***50.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	55	x 3 =	165
FACU spp.	30	x 4 =	120
UPL spp.	10	x 5 =	50
Total	95 (A)		335 (B)

Prevalence Index = B/A = ***3.526***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Carlson	Investigator #2:	J. Delmedico
Soil Unit:	Blount silt loam, 0 to 3 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/18/12
County:	Porter
State:	Indiana
Wetland ID:	W-482c
Sample Point:	1w
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ Yes ☐ No

Remarks: Area has been disturbed by previous construction

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☑ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: 18	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 12	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Blount silt loam, 0 to 3 percent slopes Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix %	Mottles Color (Moist)	Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	2	1	10YR 3/2	95	7.5YR 4/6	5	C	M	silty clay loam
2	18+	2	10YR 4/2	80	7.5YR 4/6	20	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482c	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Eleocharis erythropoda*	80	Y	OBL
2.	*PHALARIS ARUNDINACEA*	30	Y	FACW
3.	*Asclepias incarnata*	20	N	OBL
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	130		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	100	x 1 =	100
FACW spp.	30	x 2 =	60
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	130 (A)		160 (B)

Prevalence Index = B/A = ***1.231***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Invasive reed canary grass is a dominant.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	S. Carlson	Investigator #2:	J. Delmedico
Soil Unit:	Blount silt loam, 0 to 3 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/18/12
County:	Porter
State:	Indiana
Wetland ID:	W-482c
Sample Point:	**2u**
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☐ **Yes** ☑ **No**

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: n/a

Remarks: --

SOILS

Map Unit Name: Blount silt loam, 0 to 3 percent slopes Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	4	1	10YR	4/1	100	--	--	--	--	--	silty clay loam
4	18+	2	10YR	4/1	90	7.5YR	3/4	10	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: Despite the presence of hydric soils, the absence of wetland hydrology and vegetation supports an upland determination.

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482c	Sample Point	2u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*DIPSACUS FULLONUM SUBSP. SYL*	30	Y	NI
2.	*CORONILLA VARIA*	40	Y	NI
3.	*TARAXACUM OFFICINALE*	20	Y	FACU
4.	*Asclepias syriaca*	5	N	UPL
5.	*Aster spp.*	3	N	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	98		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	20	x 4 =	80
UPL spp.	75	x 5 =	375
Total	95 (A)		455 (B)

Prevalence Index = B/A = ***4.789***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	J. Delmedico	Investigator #2:	S. Carlson
Soil Unit:	Blount silt loam, 0 to 3 percent slopes	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-482d
Sample Point:	1u
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks:

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Blount silt loam, 0 to 3 percent slopes Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	%	Mottles Color (Moist)	Mottles	%	Type	Location	Texture (e.g. clay, sand, loam)
0	4	1	10YR	3/2	100	--	--	--	--	--	silty clay loam
4	18+	2	10YR	4/1	98	10YR	3/4	2	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: While hydric soils were observed, the absence of wetland hydrology and vegetation supports an upland determination.

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482d	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*DIPSACUS FULLONUM SUBSP. SYL*	70	Y	NI
2.	*LOTUS CORNICULATA*	10	N	FAC
3.	*BARBAREA VULGARIS*	10	N	FAC
4.	*PLANTAGO MAJOR*	10	N	FAC
5.	*Asclepias incarnata*	5	N	OBL
6	*Aster sp.*	5	N	--
7.	*Galium aparine*	5	N	FACU
8.	*TRIFOLIUM REPENS*	30	Y	FACU
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	145		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Remarks: --

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	5	x 1 =	5
FACW spp.	0	x 2 =	0
FAC spp.	30	x 3 =	90
FACU spp.	35	x 4 =	140
UPL spp.	70	x 5 =	350
Total	140 (A)		585 (B)

Prevalence Index = B/A = ***4.179***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	J. Delmedico	Investigator #2:	S. Carlson
Soil Unit:	Blount silt loam, 0 to 3 percent	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-482d
Sample Point:	**1w**
Community ID:	EM1
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks:

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☑ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Blount silt loam, 0 to 3 percent — Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
1	6	1	10YR	3/1	95	10YR	3/4	5	C	M	silty clay loam
6	18+	2	10YR	3/2	85	10YR	3/4	15	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482d	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Asclepias incarnata*	20	Y	OBL
2.	*PHALARIS ARUNDINACEA*	80	Y	FACW
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	100		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	20	x 1 =	20
FACW spp.	80	x 2 =	160
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	100 (A)		180 (B)

Prevalence Index = B/A = ***1.800***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Dominated by invasive reed canary grass.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	J. Delmedico	Investigator #2:	S. Carlson
Soil Unit:	Blount silt loam, 0 to 3 percent	NWI/WWI Classification:	-
Landform:	-	Local Relief:	-
Slope (%):	-	Latitude: -	Longitude: - Datum: -

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-482e
Sample Point:	1u
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Soils disturbed within pipeline right-of-way.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: n/a

Remarks: --

SOILS

Map Unit Name: Blount silt loam, 0 to 3 percent — Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	%	Mottles Color (Moist)	Mottles	%	Type	Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	3/2	100	--	--	--	--	--	silty clay loam
6	18+	2	10YR	4/2	90	7.5YR	3/4	10	C	M	silty clay loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: While soils are hydric, the absence of wetland hydrology and vegetation supports an upland determination.

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482e	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--		--
2.	--			--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*TRIFOLIUM REPENS*	40	Y	FACU
2.	*Aster spp.*	20	Y	--
3.	*DIPSACUS FULLONUM SUBSP. SYL*	10	N	NI
4.	*TARAXACUM OFFICINALE*	10	N	FACU
5.	*Asclepias syriaca*	10	N	UPL
6	*SETARIA FABERI*	5	N	FACU
7.	*PLANTAGO MAJOR*	5	N	FAC
8.	*CORONILLA VARIA*	10	N	NI
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	110		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	5	x 3 =	15
FACU spp.	55	x 4 =	220
UPL spp.	30	x 5 =	150
Total	90 (A)		385 (B)

Prevalence Index = B/A = ***4.278***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Approx. 50% bare soil.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	J. Delmedico	Investigator #2:	S. Carlson
Soil Unit:	Blount silt loam, 0 to 3 percent	NWI/WWI Classification:	-
Landform:	-	Local Relief:	-
Slope (%):	-	Latitude: -	Longitude: - Datum: -

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-482e
Sample Point:	1w
Community ID:	EM1
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: --

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☑ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☑ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: n/a

Remarks: --

SOILS

Map Unit Name: Blount silt loam, 0 to 3 percent — Series Drainage Class: somewhat poorly

Taxonomy (Subgroup): Aeric Epiaqualfs — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	2	1	10YR	3/1	90	10YR	3/4	10	C	M	silty clay loam
2	18	2	10YR	3/2	80	10YR	3/4	20	C	M	silty clay
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☑ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-482e	Sample Point	1w

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--		--
2.	--			--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Eleocharis erythropoda*	30	Y	OBL
2.	*TYPHA ANGUSTIFOLIA*	20	Y	OBL
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	50		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	50	x 1 =	50
FACW spp.	0	x 2 =	0
FAC spp.	0	x 3 =	0
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	50 (A)		50 (B)

Prevalence Index = B/A = ***1.000***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Approx. 50% bare soil.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	J. Delmedico	Investigator #2:	S. Carlson
Soil Unit:	Wallkill silt loam	NWI/WWI Classification:	--
Landform:	--	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-483a1
Sample Point:	1u
Community ID:	upland
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Mowed lawn of park.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: >18	(in.)
Saturation Present?	☐ Yes	☑ No	Depth: >18	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Wallkill silt loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Fluvaquentic Humaquepts — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)	Matrix	%	Mottles Color (Moist)	Mottles	%	Type	Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR	3/2	100	--	--	--	--	--	silt loam
12	18+	2	10YR	3/2	95	10YR	4/6	5	C	M	silt loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Wetland ID:	W-483a1	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*POA PRATENSIS*	70	Y	FAC
2.	*GLECHOMA HEDERACEA*	10	N	FACU
3.	*TARAXACUM OFFICINALE*	5	N	FACU
4.	*PLANTAGO MAJOR*	5	N	FAC
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	90		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 1 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	0	x 2 =	0
FAC spp.	75	x 3 =	225
FACU spp.	15	x 4 =	60
UPL spp.	0	x 5 =	0
Total	90 (A)		285 (B)

Prevalence Index = B/A = ***3.167***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Vegetation is dominated by mowed FAC Kentucky bluegrass. The absence of wetland hydrology and soils support an upland determination.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Line 6B Phase 2 Replacement Project	Stantec Project #:	193701660
Applicant:	Enbridge		
Investigator #1:	J. Delmedico	Investigator #2:	S. Carlson
Soil Unit:	Wallkill silt loam	NWI/WWI Classification:	--
Landform:	Floodplain	Local Relief:	--
Slope (%):	--	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☑ Yes ☐ No

Are Vegetation ☐ , Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐ , Soil ☐, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	04/19/12
County:	Porter
State:	Indiana
Wetland ID:	W-483a1
Sample Point:	**1w**
Community ID:	EM1
Section:	32
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☑ Yes ☐ No
Wetland Hydrology Present? ☑ Yes ☐ No
Hydric Soils Present? ☑ Yes ☐ No
Is This Sampling Point Within A Wetland? ☑ **Yes** ☐ **No**

Remarks: Small flood plain of S-483b

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☐):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☑ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☑ D2 - Geomorphic Position
- ☑ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes	☑ No	Depth: n/a	(in.)
Water Table Present?	☐ Yes	☑ No	Depth: 18	(in.)
Saturation Present?	☑ Yes	☐ No	Depth: 12	(in.)

Wetland Hydrology Present? ☑ Yes ☐ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: na

Remarks: --

SOILS

Map Unit Name: Wallkill silt loam — Series Drainage Class: very poorly

Taxonomy (Subgroup): Fluvaquentic Humaquepts — Field Observations Confirm Mapped Type? ☑ Yes ☐ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	6	1	10YR	3/2	100	--	--	--	--	--	silt loam
6	12	2	10YR	3/2	90	10YR	4/6	10	C	M	silt loam
12	18	3	10YR	4/1	95	10YR	4/6	5	C	M	silt loam
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☐):

- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☑ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☑ Yes ☐ No

Remarks: --

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site: Line 6B Phase 2 Replacement Project | Wetland ID: W-483a1 | Sample Point **1w**

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	0		

Herb Stratum (Plot size: 2 meter radius)

1.	*Carex stricta*	70	Y	OBL
2.	*Urtica dioica*	10	N	FAC
3.	*Impatiens pallida*	15	N	FACW
4.	*PHALARIS ARUNDINACEA*	30	Y	FACW
5.	--	--	--	--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	125		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***100.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	70	x 1 =	70
FACW spp.	45	x 2 =	90
FAC spp.	10	x 3 =	30
FACU spp.	0	x 4 =	0
UPL spp.	0	x 5 =	0
Total	125 (A)		190 (B)

Prevalence Index = B/A = ***1.520***

Hydrophytic Vegetation Indicators:

- ☑ Yes ☐ No Rapid Test for Hydrophytic Vegetation
- ☑ Yes ☐ No Dominance Test is > 50%
- ☑ Yes ☐ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☑ Yes ☐ No

Remarks: Dominants include invasive reed canary grass.

Additional Remarks:

--

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Indiana Line 6B	Stantec Project #:	193701313
Applicant:	Enbridge		
Investigator #1:	E. Parker	Investigator #2:	H. Stoffs
Soil Unit:	Fluvaquents	NWI/WWI Classification:	--
Landform:	Hillslope	Local Relief:	--
Slope (%):	6-8	Latitude: --	Longitude: -- Datum: --

Are climatic/hydrologic conditions on the site typical for this time of year? (If no, explain in remarks) ☐ Yes ☑ No

Are Vegetation ☐, Soil ☐, or Hydrology ☐ significantly disturbed?
Are Vegetation ☐, Soil ☑, or Hydrology ☐ naturally problematic?

Are normal circumstances present? ☑ Yes ☐ No

Date:	11/09/11
County:	Porter
State:	Indiana
Wetland ID:	W-483a
Sample Point:	1u
Community ID:	Upland
Section:	28
Township:	36 N
Range:	6 Dir: W

SUMMARY OF FINDINGS

Hydrophytic Vegetation Present? ☐ Yes ☑ No
Wetland Hydrology Present? ☐ Yes ☑ No
Hydric Soils Present? ☐ Yes ☑ No
Is This Sampling Point Within A Wetland? ☐ Yes ☑ No

Remarks: Recent heavy rain. Soils are sandy and therefore naturally problematic.

HYDROLOGY

Wetland Hydrology Indicators (Check here if indicators are not present ☑):

Primary:
- ☐ A1 - Surface Water
- ☐ A2 - High Water Table
- ☐ A3 - Saturation
- ☐ B1 - Water Marks
- ☐ B2 - Sediment Deposits
- ☐ B3 - Drift Deposits
- ☐ B4 - Algal Mat or Crust
- ☐ B5 - Iron Deposits
- ☐ B7 - Inundation Visible on Aerial Imagery
- ☐ B8 - Sparsely Vegetated Concave Surface
- ☐ B9 - Water-Stained Leaves
- ☐ B13 - Aquatic Fauna
- ☐ B14 - True Aquatic Plants
- ☐ C1 - Hydrogen Sulfide Odor
- ☐ C3 - Oxidized Rhizospheres on Living Roots
- ☐ C4 - Presence of Reduced Iron
- ☐ C6 - Recent Iron Reduction in Tilled Soils
- ☐ C7 - Thin Muck Surface
- ☐ D9 - Gauge or Well Data
- ☐ Other (Explain)

Secondary:
- ☐ B6 - Surface Soil Cracks
- ☐ B10 - Drainage Patterns
- ☐ C2 - Dry-Season Water Table
- ☐ C8 - Crayfish Burrows
- ☐ C9 - Saturation Visible on Aerial Imagery
- ☐ D1 - Stunted or Stressed Plants
- ☐ D2 - Geomorphic Position
- ☐ D5 - FAC-Neutral Test

Field Observations:

Surface Water Present?	☐ Yes ☑ No	Depth:	N/A	(in.)
Water Table Present?	☐ Yes ☑ No	Depth:	N/A	(in.)
Saturation Present?	☐ Yes ☑ No	Depth:	N/A	(in.)

Wetland Hydrology Present? ☐ Yes ☑ No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available: N/A

Remarks: Well drained upland forest soil

SOILS

Map Unit Name: Fluvaquents — Series Drainage Class: poorly to somewhat poorly

Taxonomy (Subgroup): NA — Field Observations Confirm Mapped Type? ☐ Yes ☑ No

Profile Description (Describe to the depth needed to document the indicator or confirm the absence of indicators.) (Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered/Coated Sand Grains; Locaiton: PL=Pore Lining, M=Matrix)

Top Depth	Bottom Depth	Horizon	Matrix Color (Moist)		Matrix %	Mottles Color (Moist)		Mottles %	Mottles Type	Mottles Location	Texture (e.g. clay, sand, loam)
0	12	1	10YR	3/2	100	--	--	--	--	--	Sandy Loam
12	20	2	10YR	5/3	90	10YR	4/4	10	C	M	Loamy Sand
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--
--	--	--	--	--	--	--	--	--	--	--	--

NRCS Hydric Soil Field Indicators (check here if indicators are not present ☑):
- ☐ A1- Histosol
- ☐ A2 - Histic Epipedon
- ☐ A3 - Black Histic
- ☐ A4 - Hydrogen Sulfide
- ☐ A5 - Stratified Layers
- ☐ A10 - 2 cm Muck
- ☐ A11 - Depleted Below Dark Surface
- ☐ A12 - Thick Dark Surface
- ☐ S1 - Sandy Muck Mineral
- ☐ S3 - 5 cm Mucky Peat or Peat
- ☐ S4 - Sandy Gleyed Matrix
- ☐ S5 - Sandy Redox
- ☐ S6 - Stripped Matrix
- ☐ F1 - Loamy Muck Mineral
- ☐ F2 - Loamy Gleyed Matrix
- ☐ F3 - Depleted Matrix
- ☐ F6 - Redox Dark Surface
- ☐ F7 - Depleted Dark Surface
- ☐ F8 - Redox Depressions

Indicators for Problematic Soils [1]
- ☐ A16 - Coast Prairie Redox
- ☐ F12 - Iron-Manganese Masses
- ☐ Other (Explain in Remarks)

[1] Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (If Observed) Type: N/A Depth: N/A

Hydric Soil Present? ☐ Yes ☑ No

Remarks: Well drained upland forest soil

WETLAND DETERMINATION DATA FORM
Midwest Region

Project/Site:	Indiana Line 6B	Wetland ID:	W-483a	Sample Point	1u

VEGETATION (Species identified in all uppercase are non-native species.)

Tree Stratum (Plot size: 10 meter radius)

	Species Name	% Cover	Dominant	Ind.Status
1.	*Acer saccharum*	70	Y	FACU
2.	*Prunus serotina*	20	Y	FACU
3.	*Fraxinus americana*	5	N	FACU
4.	--	--	--	--
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	95		

Sapling/Shrub Stratum (Plot size: 5 meter radius)

1.	*Acer saccharum*	25	Y	FACU
2.	*ROSA MULTIFLORA*	5	N	FACU
3.	*RHAMNUS CATHARTICA*	5	N	FACU
4.	*Lindera benzoin*	2	N	FACW
5.	--	--	--	--
6.	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
	Total Cover =	37		

Herb Stratum (Plot size: 2 meter radius)

1.	*RHAMNUS CATHARTICA*	10	Y	FACU
2.	*Sedum ternatum*	10	Y	NI
3.	*Carex grisea*	2	N	NI
4.	*Smilax hispida*	2	N	FAC
5.	--	--		--
6	--	--	--	--
7.	--	--	--	--
8.	--	--	--	--
9.	--	--	--	--
10.	--	--	--	--
11.	--	--	--	--
12.	--	--	--	--
13.	--	--	--	--
14.	--	--	--	--
15.	--	--	--	--
	Total Cover =	24		

Woody Vine Stratum (Plot size: 10 meter radius)

1.	--	--	--	--
2.	--	--	--	--
3.	--	--	--	--
5.	--	--	--	--
4.	--	--	--	--
	Total Cover =	0		

Dominance Test Worksheet

Number of Dominant Species that are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: ***0.0%*** (A/B)

Prevalence Index Worksheet

Total % Cover of:		Multiply by:	
OBL spp.	0	x 1 =	0
FACW spp.	2	x 2 =	4
FAC spp.	2	x 3 =	6
FACU spp.	140	x 4 =	560
UPL spp.	12	x 5 =	60
Total	156 (A)		630 (B)

Prevalence Index = B/A = ***4.038***

Hydrophytic Vegetation Indicators:

- ☐ Yes ☑ No Rapid Test for Hydrophytic Vegetation
- ☐ Yes ☑ No Dominance Test is > 50%
- ☐ Yes ☑ No Prevalence Index is ≤ 3.0 *
- ☐ Yes ☑ No Morphological Adaptations (Explain) *
- ☐ Yes ☑ No Problem Hydrophytic Vegetation (Explain) *

* Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Definitions of Vegetation Strata:

Tree - Woody plants 3 in. (7.6cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/Shrub - Woody plants less than 3 in. DBH and greater than 3.28 ft. tall.

Herb - All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft. tall.

Woody Vines - All woody vines greater than 3.28 ft. in height.

Hydrophytic Vegetation Present ☐ Yes ☑ No

Remarks: --

Additional Remarks:

--