

**Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects
IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report**

Observation Dates:	02/24/14 thru 03/01/14
IEM Name:	Eric Sorenson
Waterbody Identification Number(s):	S-495-A1, S-485-B,
Wetland Identification Number(s):	W-485-X, W-492-A, W-491-B, W-486-B
Enbridge Land Tract Identification Number(s):	N-619-8, N-627-3, N-625-4, N-624-1, N-620-9
County(s): St.Joseph, LaPorte, Porter	Porter and LaPorte
<p>02/24/14: Off E.1100N. rd. testing work continues at Sta.#1502+24, Tract n-626-6. Just outside of wetland W-485-X crews have completed the anomaly dig. Cleanup continues as of now. All ECD'S are in compliance at this location. Snow melt is occurring throughout the ROW. 02/25/14: South West of DNR stream crossing S-495-A1 Reynolds Creek the contractor is potholing a line. The contractor environmental crew has made requested repairs to the silt at this stream crossing. The crew also removed used de-watering filter bag from this location. 02/26/14: The contractor has completed the required repair to the silt fence and ECD'S at the stream crossing S-485-B, N-619-8. Also the contractor is doing an anomaly dig in the upland area near this location. Trash and construction debris has been removed from the wetland and waterbody area. 02/27/14: The contractor has installed mats through the wetland W-491-B for access to the upland area. ECD'S at DNR stream crossing S-491-A Sand Creek at tract N-624-1 are in working order. Repairs have been made to the ECD'S wetland W-492-A at tract number N-625-4. 02/28/14: Performed storm water inspections throughout the ROW. No environmental concerns. 03/01/14: The contractor will be installing sheet pylon in order to perform a dig at wetland W-486-B Tract N-620-9. Repairs are being made to ECD'S at wetland and waterbody locations throughout the ROW.</p>	



sta#1500+00_MP493.5_breaking down equipment_NE



sta#1058+00_MP485.1_removing mats and cleanup_N



sta#1575+00_MP495.0_S-495-A1_ECD repairs_SW12



sta#1575+00_MP495.0_S-495-A1_ECD repairs_SW



sta#1147+00_MP486.8_W-486-B_location of anomaly dig_W



