Eurofins TestAmerica Knoxville Laboratory
Main Building - Figure 2

Emergency Contact List

Associate	Area	Ext	Phone
Lewis Osborne	Comp. Off.	381	
	Emerg. Coord.		(Cell) 719-0305
	EH&S Coor.		
Chris Rigell	Lab. Mgr.	311	(Cell)984-6896
Melissa Davidson	Dioxin	371	(Cell)776-8925
Kevin McGee	QA Mgr.	309	(Cell) 850-7266
Anya Barlozhetskaya	GC/MS	384	(Cell)566-7335
David McNeil	Prep	374	(Cell)406-3876
Howard Marshal	IT	337	(Cell)712-9300
Donna Wilburn	Inorganics	364	(Cell)661-2056
Director, EH&S, QA			
Ray Frederici	(708) 925-2564		

Safety Equipment Location

- E Fire Extingiusher
- A Fire Alarm or Siren
- + First Aid Kit
- S Safety Shower
- W Eye Wash Station
- K Emergency Spill Kit
- L Emergency Lighting - Wired
- P Emergency Lighting - Portable

Eurofins TestAmerica Knoxville Laboratory
Building 2 - Dioxin Lab - Figure 2

Emergency Contact List

Associate	Area	Ext	Phone	
Lewis Osborne	Comp. Off.	381		
	Emerg. Coord.		(Cell) 719-0305	
	EH&S Coor.			
Chris Rigell	Lab. Mgr.	311	(Cell)	984-6896
Melissa Davidson	Dioxin	371	(Cell) 776-8925	
Kevin McGee	QA Mgr.	309	(Cell) 850-7266	
Anya Barlozhetskaya	GC/MS	384	(Cell)566-7335	
David McNeil	Prep	374	(Cell) 406-3876	
Howard Marshal	IT	337	(Cell) 712-9300	
Donna Wilburn	Inorganics	364	(Cell) 661-2056	
Director, EH&S, QA				
Ray Frederici	(708) 925-2564			

Safety Equipment Location

- E — Fire Extingiusher
- A — Fire Alarm or Siren
- + — First Aid Kit
- S — Safety Shower
- W — Eye Wash Station
- K — Emergency Spill Kit
- L — Emergency Lighting - Wired
- P — Emergency Lighting - Portable