

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/08/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155698	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 , 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 08/03/2012
NAME OF PROVIDER OR SUPPLIER BETHANY POINTE HEALTH CAMPUS			STREET ADDRESS, CITY, STATE, ZIP CODE 1707 BETHANY RD ANDERSON, IN 46012		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 06/08/12 and a Quality Assurance Walk-thru Survey were conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 08/03/12</p> <p>Facility Number: 011045 Provider Number: 155698 AIM Number: 200380790</p> <p>Surveyor: Phillip Komsiski, Life Safety Specialist</p> <p>At this PSR survey, Bethany Pointe Health Campus was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire, and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The original portion of the facility built in 1999, building 01, consists of everything except 600 wing was surveyed with Chapter 19, Existing Health Care Occupancies.</p> <p>The one story facility was determined to be Type V(111) construction and fully sprinklered building. The facility was surveyed as two separate buildings due to the construction dates of the two sections of the building. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and hard wired smoke detectors in all resident sleeping rooms. The facility has a capacity of 74 and had a census of 69 at the time of this survey.</p>	{K 000}			
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE			TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/08/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155698	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 , 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 08/03/2012
NAME OF PROVIDER OR SUPPLIER BETHANY POINTE HEALTH CAMPUS			STREET ADDRESS, CITY, STATE, ZIP CODE 1707 BETHANY RD ANDERSON, IN 46012		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 1	{K 000}			
	The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage.				
	All areas where the residents have customary access were sprinklered and all areas providing facility services were sprinklered.				
	Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 08/07/12.				
{K 000}	INITIAL COMMENTS	{K 000}			
	A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 06/08/12 and a Quality Assurance Walk-thru Survey were conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).				
	Surveyor: Phillip Komsiski, Life Safety Specialist				
	Survey Date: 08/03/12				
	Facility Number: 011045 Provider Number: 155698 AIM Number: 200380790				
	At this PSR survey, Bethany Pointe Health Campus was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire, and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The 600 wing with 20 residents was surveyed with Chapter 18, New Health Care Occupancies.				

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/08/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155698	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 , 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 08/03/2012
NAME OF PROVIDER OR SUPPLIER BETHANY POINTE HEALTH CAMPUS			STREET ADDRESS, CITY, STATE, ZIP CODE 1707 BETHANY RD ANDERSON, IN 46012		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>Continued From page 2</p> <p>The one story facility was determined to be Type V(111) construction and fully sprinklered building. The facility was surveyed as two separate buildings due to the construction dates of the two sections of the building. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and hard wired smoke detectors in all resident sleeping rooms. The facility has a capacity of 74 and had a census of 69 at the time of this survey.</p> <p>The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage.</p> <p>All areas where the residents have customary access were sprinklered and all areas providing facility services were sprinklered.</p>	{K 000}			