

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 000539	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 09/28/2012
NAME OF PROVIDER OR SUPPLIER PARKVIEW HAVEN		STREET ADDRESS, CITY, STATE, ZIP CODE 101 CONSTITUTION DR FRANCESVILLE, IN 47946		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	<p>INITIAL COMMENTS</p> <p>A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of Health.</p> <p>Survey Date: 09/28/12</p> <p>Facility Number: 000539 Provider Number: 155746 AIM Number: 100267280</p> <p>Surveyor: Robert Sutton, Life Safety Code Specialist Trainee</p> <p>At this Quality Assurance Walk-thru survey, Parkview Haven was found in compliance with 410 IAC 16.2-3.1-19(ff).</p> <p>This facility located on one wing of a one story building determined to be of Type III (211) construction was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and areas open to the corridors with hard wired smoke detectors in the resident rooms. The facility has a capacity of 48 and had a census of 37 at the time of this visit.</p> <p>The facility was in compliance with state law in regard to sprinkler coverage and smoke detector coverage.</p> <p>All areas where residents have customary access were sprinklered and all areas providing facility services were sprinklered, except one detached shed used for facility storage.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 10/02/12.</p>	K 000		

Indiana State Department of Health

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE