

NO

LOCATE

TICKET

PROVIDED



Pipeline Safety Division Investigation Report

Investigation regarding: Miller Pipeline

UPPAC Database Record ID: 1171

Investigator: Howard Friend

Report Date: 04/30/2012

Damage Date: 08/25/2010 10:25:54 AM

Damage Address: 403 Rodney St

City: Brownsburg

County: Hendricks

The Parties

Excavator: **Miller Pipeline**

Contact: Ralph Miller, Vice President

Address: 8850 Crawfordsville Rd, Indianapolis, In 46234

Telephone: 317-293-0278

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Miller Pipeline

UPPAC Database Record ID: 1171

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$23

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1008171400

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Natural Gas

Synopsis: A steel natural gas service was damaged during efforts to retire it prior to installing a new plastic service.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 03/26/2012. Tree roots had grown around the service, and attempts to pull some of the roots out of the way with the backhoe caused the service to break at a coupling.

Conclusion: Excavator failed to expose the service sufficiently to determine the extent of restrictions from the tree roots prior to attempting to remove them.

Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.

Miller Pipeline currently has 2 reports of damages in the record, between 08/25/2010 10:25:54 AM and 03/16/2011 11:31:03 AM.



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

RECEIVED

MAR 20 2012

INDIANA UTILITY
REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 03-16-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Miller Pipeline

Business address (number and street): 8850 Crawfordsville Rd.

City, State, and ZIP code: Indianapolis, IN 46234

Telephone number (area code): 317-295-6417

Fax number (area code): 317-295-6418

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Natural Gas

Date and Location of Damage

Date of damage (month, day, year): 8-25-2010

County: Hendricks

City: Brownsburg

Street address (number and street, city, state, and ZIP code):
403 Rodney Street, Brownsburg, IN

Nearest intersection: Unknown

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours): 1

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 23.1

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1008171400

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: Miller Pipeline. USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Unknown/Other

Type of markings used: Paint

If other, please specify: None

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? Yes

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: Other

Additional Comments

1.25" steel service severed while attempting to remove tree roots. Service was spotted but roots twisted around service.

FACILITIES DAMAGE REPORT GAS

Vectren Corporation
Form 3112 (Rev. 10/04)

- Indiana Gas
- Sigeco
- Vectren Energy Delivery of Ohio

Task No.: 103.0510

Capital / O&M (circle one)

FDS00013093

TIME: 11:25 AM PM

DATE OF DAMAGE: 8/25/10

Cost Center No.: 5953

DAMAGE SITE ADDRESS: 405 E Rodney

LOT #: _____ CITY: Braunsbury

FACILITIES DAMAGED

- MAIN
- SERVICE
- REGULATOR STATION
- FARM TAP
- RESIDENTIAL METER
- METER INDUSTRIAL/COMMERCIAL
- OTHER

- SIZE(S)
- 0.50 INCH
 - 0.75 INCH
 - 1.00 INCH
 - 2.00 INCH
 - 4.00 INCH
 - 6.00 INCH
 - OTHER 1.25"

TYPE OF MATERIAL

- PLASTIC
- STEEL
- CAST IRON
- OTHER

DAMAGE TYPE

- SEVERED
- NOT CUT
- PUNCTURE
- SIZE _____ X _____

PRESSURE

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 60 PSIG
- 6 WC
- OTHER 10 PSI

PROTECTION IN PLACE

- RAIL
- POST
- NONE
- N/A

LEAK REPORT

583719

- ONE-WAY FEED
- TWO-WAY FEED

DURATION OF ESCAPING GAS

MINUTES 10

- EFV ACTIVATED YES NO

DAMAGED BY

- CONTRACTOR
- MUNICIPALITY/UTILITY
- VEHICULAR ACCIDENT
- COMPANY CREW
- UNKNOWN
- PROPERTY OWNER/TENANT
- OTHER

TYPE OF CONSTRUCTION

- SEWER/DRAIN
- WATER
- ELECTRIC
- TELEPHONE
- CEMENT/PAVING
- TV CABLE
- FENCING
- FOOTERS
- OTHER A Service Replacement

WORKING FOR

- CITY
- STATE
- PROPERTY OWNER
- OTHER

NAME Vectren

TYPE OF EQUIPMENT

- BACKHOE
- TRACKHOE
- PLOW
- TRENCHER
- BULLDOZER
- POSTHOLE DIGGERS
- BORE
- AUGER
- STAKE/SHOVEL
- OTHER

DAMAGING PARTY

- DID NOT REQUEST LOCATES
- DID NOT HAND DIG
- USED EXPIRED LOCATES
- OTHER Had Service spotted while digging

NUMBER OF CUSTOMERS

AFFECTED: 1

root around service pulled

TOTAL HOURS SERVICE

WAS OFF:

Service up

INVOICE: YES NO

DAMAGING PARTY

NAME: Miller Pipe Line

ADDRESS: _____

CITY/STATE/ZIP: _____

PREPARED BY: Robt Hage

DATE: 8-25-10

VISUAL OBSERVATION AT DAMAGE SITE

- LOCATE NOT APPLICABLE (Above Ground Damage Only)
- FACILITIES PROPERLY MARKED
- MARKING METHODS: CONVENTIONAL OFFSET
- FLAGS PAINT STAKES WHISKERS
- LOCATE MARKINGS FADED: YES NO
- WRONG ADDRESS REQUESTED
- FACILITIES IMPROPERLY LOCATED
- QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
- INACCURATE MAPS/CARDS
- BROKEN OR NO TRACER WIRE (PLASTIC)
- INSULATION PREVENTING ACCURATE LOCATE
- LOCATOR ERROR
- QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
- INCOMPLETE LOCATE
- MARKINGS OFF BY _____ (FEET/INCHES)
- INAPPROPRIATE SITE MARKINGS
- NO LOCATE PERFORMED
- FAILURE TO FOLLOW POLICY
- WRONG ADDRESS LOCATED

OBSERVATION BY: _____

NAME OF LOCATOR: _____

- COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

NOTIFICATION AND OTHER DETAILS OF LOCATE

LOCATE TICKET #: 608 171 400

DATE: 8-17-10

TIME: 8:00

- REGULAR REQUEST
- EMERGENCY REQUEST

- LOCATE COMPANY NOTIFIED

CONTACT NAME: Rich Riggs

TIME CALLED: 9:45

TIME LOCATOR ARRIVED AT SITE: 10:50

COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES:

- YES
- NO

CONTRACTOR REPAIRS

- CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
- CONTRACTOR REPAIRED DAMAGE

NAME OF CONTRACTOR: _____

OF REGULAR HOURS _____

OF OVERTIME HOURS _____

CREW TYPE _____

MATERIALS OR ROAD WORK

- METER WAS REPLACED _____ (STORES CODE)
- REGULATOR WAS REPLACED _____ (STORES CODE)
- TEMPORARY ASPHALT REPAIR _____ (SQ. FT.)
- PERMANENT ASPHALT REPAIR _____ (SQ. FT.)

PARTY TO INVOICE

NAME: _____

ADDRESS: _____

CITY/STATE/ZIP: _____

REVIEWED BY: Alexander

DATE: 8-27-10

NORMAL, NOTICE

Ticket : 1008171400 Date: 08/17/2010 Time: 12:12 Oper: SARAH.HEMINGER Chan:000

State: IN Cnty: HENDRICKS Twp: LINCOLN
Cityname: BROWNSBURG Inside: Y Near: N
Subdivision:

Address : 403
Street : RODNEY ST
Cross 1 : GRANT ST Within 1/4 mile: Y
Location: PAINT AND FLAG ENTIRE PROPERTY OF 403 405 407 409 AND 411 RODNEY ST
AND BOTH SIDE OF RODNEY ST
***Boring Where = RODNEY ST
:
Grids : 3950A8623C 3950A8623B

Work type : REPLACE GAS SERVICE
Done for : VECTREN
Start date: 08/19/2010 Time: 12:30 Hours notice: 48/48 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
Duration : 6 DAY Depth: 3FT TO 4FT

Company : MILLER PIPE LINE Type: CONT
Co addr : 8850 CRAWFORDSVILLE RD
City : INDIANAPOLIS State: IN Zip: 46234
Caller : SARAH HEMINGER Phone: (317)295-6417
Contact : JOSH Phone:
BestTime:
Mobile : (317)407-3651
Fax : (317)295-6418


Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? NO
:

Submitted date: 08/17/2010 Time: 12:12
Members: CV ID0002 ID2020 ID4471 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
BROWNSBURG, TOWN OF	SEWER & WATER
COMCAST CABLEVISION - INDIANAPOLIS	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
VECTREN - DANVILLE	GAS

[View Map](#)

[Close Map](#)



Service Order Status

Monday, March 5, 2012

Enter Service Order Number:

4528941



Banner Instance: CS03PROD CS01PROD CS02PROD
Order Number: N4528941
Order Type: LEAK
Order Status: Completed

Customer: 600596773 - ROBINSON BETTY S
Prem: 5125158 - 405 E RODNEY ST

Technician: 3562 - Cordray, Mark

Order Dates and Times

Need Date: 8/25/2010 10:39:00 AM
Time Created: 8/25/2010 10:37:15 AM
Time Dispatched: 8/25/2010 10:37:15 AM
Time In Route: 8/25/2010 10:38:24 AM
Time On-Site: 8/25/2010 10:45:07 AM
Tech Complete: 8/25/2010 11:00:48 AM
Time Closed: 8/25/2010 11:00:48 AM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current ReadStatus

Old Meter: 0837 Active
New Meter:

Completion Notes

THIS WAS MILLER PIPELINE DOING A SERVICE REPLACEMENT, INSPECTOR RICK RIGGS ONSITE WILL TAKE CARE OF PAPERWORK, LEFT OK, MCORDRAY

Request Notes

HIT LINE NOT BLOWING PER JEANNETTE W/ 811...JOSH W/MILLER PIPELINEONSITE..CONT 502-376-9087...XST: GRANT ST..LINES LOC 1008171400..DIGGING FRONT OF PROPERTY

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	8/25/2010 10:38:09 AM	Cordray, Mark
AsnAssignmentEnRoute_evt	8/25/2010 10:38:24 AM	Cordray, Mark
AsnAssignmentOnSite_evt	8/25/2010 10:45:07 AM	Cordray, Mark
OrdOrderComplete_evt	8/25/2010 11:00:48 AM	Cordray, Mark

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

Ticket Portal Production

Ticket Text Photos

Ticket Text

From: att-tickets@tickets.translore.com
Sent: Wednesday, August 25, 2010 10:28 AM
To: onecall7+in-att@smptickets.com
Subject: ATT Translore - 1008251217

ATTIN Seq: 672 Transmitted: Wed Aug 25 09:27:46 CDT 2010

SBCIN 00672 IUPPSa 08/25/2010 10:25:56 1008251217-00A EMER DAMG GRID

DAMAGE DAMAGE

Ticket : 1008251217 Date: 08/25/2010 Time: 10:24 Oper: JREED Chan:001

State: IN Cnty: HENDRICKS Twp: LINCOLN
Cityname: BROWNSBURG Inside: Y Near: N
Subdivision:

Address : 403
Street : RODNEY ST
Cross 1 : GRANT ST Within 1/4 mile: Y
Location: PAINT AND FLAG ENTIRE PROPERTY OF 403 405 407 409 AND 411 RODNEY ST AND BOTH SIDE OF RODNEY ST
***Boring Where = RODNEY ST

Grids : 3950A8623C 3950A8623B
Boundary: n 39.847496 s 39.846317 w -86.392525 e -86.388718

Work type : REPLACE GAS SERVICE
Done for : VECTREN
Start date: 08/25/2010 Time: 10:24 Hours notice: 0/0 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y
Duration : 6 DAY Depth: 3FT TO 4FT

Company : MILLER PIPE LINE Type: CONT
Co addr : 8850 CRAWFORDSVILLE RD
City : INDIANAPOLIS State: IN Zip: 46234
Caller : SARAH HEMINGER Phone: (317)295-6417 Contact : JOSH Phone:
BestTime:
Mobile : (502)376-9083
Fax : (317)295-6418

Remarks : All tickets are taken and processed on Eastern Daylight Time PER RICK RIGGS-- HIT VECTREN GAS LINE IN FRONT OF 405 RODNEY ST-- GAS NOT BLOWING-- CREW ON SITE--CALLED UTILITY- PREVIOUS TICKET NUM 1008171400 Will you be white-lining the dig site area? NO

Submitted date: 08/25/2010 Time: 10:24
Members: CV ID0002 ID2020 ID4471 ID9999 SBCIN SM
!!! Locate the following : DUKE !!!







STATE OF INDIANA



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

February 24, 2012

Miller Pipeline
8850 Crawfordsville Road
Indianapolis, IN 46234

Subject: Notice of Preliminary Determination of Violation

Date of Event: 8/25/2010

Event Location: 403 Rodney St, Brownsburg, Hendricks County

Excavator: Miller Pipeline

Facility Owner: Vecten

Pipeline Safety Division Case No. 1171

To Whom It May Concern:

On behalf of the Indiana Utility Regulatory Commission ("IURC"), I am writing to inform you that information has been filed with our Pipeline Safety Division regarding an alleged violation of Indiana Code chapter 8-1-26, the Indiana Damage to Underground Facilities Act ("the Act"). You are receiving this letter because you have been identified as the Respondent Excavator.

The purpose of this Act is to promote excavation and pipeline safety and to reduce imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Based upon the information received, the Pipeline Safety Division is commencing an investigation into the event concerning you or your business. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

If you believe there are other parties or witnesses with relevant information for the Pipeline Safety Division to consider in its investigation, we request that you *immediately* provide their name, address, telephone number and email address *in writing* to the Pipeline Safety Division. Because the investigation should be completed within sixty (60) days, any delay in providing additional persons to be contacted may result in the investigation being concluded without this additional source of information.

Please forward any documentation to the following address or you may scan the materials and send them electronically. Be sure to include your assigned Pipeline Safety Division Case Number on all communications. Please add your Case Number and denote "INITIAL DOCUMENTS - EXCAVATOR" at the top of your materials or in the subject heading of your email.

Mail: Pipeline Safety Division – Case No. 1171
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 E
Indianapolis, IN 46204

Email: PipelineDamageCase@urc.in.gov

Included with this letter are the following documents: a *Summary of Procedures and Respondent's Rights* to assist in answering your questions; and an *Information Request* enclosure to assist in providing pertinent information regarding this investigation.

Should you have procedural or legal questions regarding the Advisory Committee or the IURC, please contact DeAnna L. Poon, Advisor to the Advisory Committee and Assistant General Counsel at the IURC, at (317) 232-6735. Should you have questions regarding the pipeline damage identified above, or our investigation, please contact me at (317) 232-2718. Thank you for your assistance.

Sincerely,



William Boyd
Director Pipeline Safety Division

Enclosures: Summary of Procedures and Respondent's Rights
Information Request

Information Request

Pipeline Safety Division Indiana Utility Regulatory Commission

Case No. 1171

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: *MILLER PIPELINE*

Responsible Party Personal Name: *CHARLES BEASLEY*

Title (if any): *FOREMAN*

Address: *8850 Crawfordsville Rd.*

City, State Zip: *Indianapolis, IN 46234*

Preferred Telephone: *317 293 0278*

Cell Phone Number:

Email Address: *info@millerpipeline.com*

Facility Information:

Business Name: *Vectren*

Responsible Party Personal Name: *Darlene Kulhanek*

Title (if any): *Mgr. of Facilities Damages*

Address: *One Vectren Square*

City, State, Zip: *Evansville, IN 47702*

Preferred Telephone: *812 491 4227*

Cell Phone Number:

Email Address: *dKulhanek@vectren.com*

Locator Service Information:

Business Name: *Indiana 811 - USIC*

Responsible Party Personal Name:

Title (if any):

Address:

City, State Zip:

Preferred Telephone:

Cell Phone Number:

Email Address:

Other (Witness, Police, Fire, Other) Information:

Personal Contact: Richard Riggs
Business/Organization Name: Vedren
Title (if any) Inspector
Address:
City, State, Zip:
Preferred Telephone:
Cell Phone Number:
Email Address:

Howard Friend
IURC
Howard was on site.

Utility Line Impact:

Location of Damage:
Address: 403 ROONEY
City, State Zip: BROWNSBURG IN
Nearest Intersection: GRANT ST

Product Type (circle one):

- Natural Gas
- Liquid Pipeline
- Unknown/Other

Facility Type (circle one):

- Distribution
- Gathering
- Service/Drop
- Transmission
- Unknown/Other

Size (Diameter/etc.): 3/4"

Pressure (PSIG/Inches): 50

Interruption in Service: Yes No

Number of Customers Affected: 1

Evacuation: Yes No If yes, How Many Evacuated? —

Repair Cost (if known): \$ unknown

Cause of Damage Information:

Type of Equipment (circle one):

Auger

Backhoe/Trackhoe

Boring /Drilling

Directional Drilling

Explosives

Farm Equipment

Grader/Scraper

Hand Tools

Milling Equipment

Probing Device

Trencher

Vacuum Equipment

Unknown/Other

Type of Work Performed (circle one):

Agriculture

Cable TV

Curb/Sidewalk

Bldg. Construction

Bldg. Demolition

Drainage

Driveway

Electric

Engineering/Surveying

Fencing

Grading

Irrigation

Landscaping

Liquid Pipeline

Milling

Natural Gas

Pole

Public Transit Authority

Railroad Maintenance

Road Work

Sewer (Sanitary/Storm)

Site Development

Steam

Storm Drain/Culvert

Street Light

Telecommunications

Traffic Signal

Traffic Sign

Water

Waterway Improvement

Unknown/Other

Release of Product: Yes No

Ignition and/or Fire: Yes / No

Excavator Notify 811: Yes / No

Locate Information:

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1008171400

Locate Marks Visible: Yes No

Locate Marks Correct: Yes No

Excavator "White Lined": Yes / No

Maps Used to Mark Facilities: Yes / No

Was Locate Provided within Two (2) Working Days Yes / No

Operator Employees On-site during Excavation: Yes / No

Incident Impact Information:

Number of Outpatient Treated: 0

Number of Inpatient Treated: 0

Number of Fatalities: 0

Fire Department Response: Yes / No

Police Department Response: Yes / No

Ambulance Response: Yes / No

Additional Information/Comments:

We were digging to expose $\frac{3}{4}$ " steel service in order to replace it with a new polyethylene service. There were very dense tree roots all around service and as we pulled on roots it broke a metal screw coupling on service.

YOUR PIPELINE SAFETY DIVISION CASE NO. 1171

YOUR FULL NAME: Ralph Miller

FULL NAME OF BUSINESS/ENTITY (if applicable): Miller Pipeline

YOUR BUSINESS TITLE (if applicable): VP HR

ADDRESS: 8850 Crawfordsville Rd.

CITY: Indianapolis STATE: IN ZIP CODE: 46234

YOUR TELEPHONE NUMBER: (317) 293 - 0278 SECOND NO. (317) 439 1076

YOUR EMAIL ADDRESS: ralph.miller@millerpipeline.com

TODAY'S DATE: March 20, 2012

YOUR SIGNATURE: Ralph Miller TITLE (if any) VP HR

Please return your Narrative Statement and Answers to the above questions to:

**Pipeline Safety Division – Case No. 1171
Indiana Utility Regulatory Commission
101 West Washington Street, # 1500E
Indianapolis, IN 46204**

Or scan document(s) and Email to:

PipelineDamageCase@urc.in.gov

NORMAL NOTICE JOB EXTENSION

Ticket : 1009010576 Date: 09/01/2010 Time: 09:29 Oper: SARAH.HEMINGER Chan:000
 Old Tkt: 1008171400 Date: 08/17/2010 Time: 12:12 Oper: SARAH.HEMINGER Rev: 00A

State: IN Cnty: HENDRICKS Twp: LINCOLN
 Cityname: BROWNSBURG Inside: Y Near: N
 Subdivision:

Address : 403
 Street : RODNEY ST
 Cross 1 : GRANT ST Within 1/4 mile: Y
 Location: PAINT AND FLAG ENTIRE PROPERTY OF 403 405 407 409 AND 411 RODNEY ST
 AND BOTH SIDE OF RODNEY ST
 ***Boring Where = RODNEY ST

Grids : 3950A8623C 3950A8623B

Work type : REPLACE GAS SERVICE
 Done for : VECTREN
 Start date: 09/03/2010 Time: 09:45 Hours notice: 48/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
 Duration : 6 DAY Depth: 3FT TO 4FT

Company : MILLER PIPE LINE Type: CONT
 Co addr : 8850 CRAWFORDSVILLE RD
 City : INDIANAPOLIS State: IN Zip: 46234
 Caller : SARAH HEMINGER Phone: (317)295-6417
 Contact : JOSH Phone:
 BestTime:
 Mobile : (317)407-3651
 Fax : (317)295-6418

Remarks : All tickets are taken and processed on Eastern Daylight Time
 NEED ALL UTILITIES TO RETURN AND REMARK PREVIOUS TICKET 1008171400
 Will you be white-lining the dig site area? NO


Submitted date: 09/01/2010 Time: 09:29
 Members: CV ID0002 ID2020 ID4471 ID9999 SBCIN SM

8-25 CB
8-26 CB
8-30 CB
8-27 CB
9-1 CB
All done 9/21 W.K.

Member Name Facility Types

9-21
9:45

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
BROWNSBURG, TOWN OF	SEWER & WATER
COMCAST CABLEVISION - INDIANAPOLIS	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
VECTREN - DANVILLE	GAS



Miller Pipeline Corp.

FORM MPC-PD-3502

FOR OFFICE USE:		
RO <input type="checkbox"/>	NCUN <input type="checkbox"/>	CUN <input type="checkbox"/>
CUI <input type="checkbox"/>	PDN <input type="checkbox"/>	PDI <input type="checkbox"/>

PROPERTY DAMAGE/PUBLIC INJURY FORM

1510 gas construction
Property/Facility Owner or Person Injured VECTREN 31758

Site Location/Address 403 RODNEY ST City/State BROWNSBURG INDIANA

Date of damage 8-25-10 Was damaged utility/property owner notified of damage? Yes No

UTILITY DAMAGE Was it: Live Abandoned

Type: Gas Water Telephone cable Telephone fiberoptic Telephone drop Cable TV

Electrical primary Electrical secondary Sewer Other _____

PROPERTY DAMAGE Type: Sidewalk Curb Driveway Trees Street Lawn Sewer Shrubs Sprinkler

Electrical Water Other _____ Home interior Home exterior

Were photographs taken and attached to PD form? Yes No

What damaged property? Backhoe Trackhoe Trencher Directional bore Holehog Concrete saw

Jackhammer Hand excavation Other _____

What happened to cause damage or injury? Be specific: include equipment/tools involved, circumstances, process of events, etc.
DIGGING TO EXPOSE 3/4" STL SERVICE - LOTS OF TREE ROOTS PULLED UP ROOTS W/BACKHOE & SERVICE ABOVE ROOTS - RESULTING IN SERVICE BREAKING AT SCREW COUPLING - WE FOUND THE CURB VALVE, SHUT DOWN THE SERVICE - SERVICE WAS REPLACED WITH NEW PLASTIC SAME DAY

Person causing damage (print) CHARLIE BEASLEY Foreman/Supervisor (print) CHARLIE BEASLEY

Division: IN Const. OH Const. Utility 95

Area: AL FL IN KY KS MD MS N.CA NJ OH S.CA TX Other _____

Technology: Alabama Alagasko Cinery Citizens Columbia Engineering EX Fab Shop Garage Griners IN Gas IWC LG&E Mgf. MS Valley Office Shipping VacRig Vectren Weko Xpandit Other _____

Were locates requested? Yes No Were locates done? Yes No - LOCATES BY MILLER PIPELINE

Name of locate company (if known) MILLER PIPELINE

Date located 8-25-10 Locate reference # _____

Did digging begin prior to locates? Yes No Was facility hand exposed prior to locates? Yes No

Utility markings: Flags Paint None Other _____ Were marks legible? Yes No

Were all locates accurate and all cables marked? Yes No If no, how much were locates off? _____ ft. _____ inches

If locate marks were off, were photographs taken? Yes No Were locates expired? Yes No

Recommendation of Manager/Supervisor: WITNESSES - RICHARDS RIGGS (VECTREN INSPECTOR) PHILLIP IRWIN (MILLER LABOR) JEREMY HOWARD (MILLER LABOR) HOWARD FRIEND (IWC) WAS ON SITE

Report completed by (print): D ROOSE / IN Danville (Noblesville) Vectren Date: 3/5/12

File #