



## Pipeline Safety Division Investigation Report

### Investigation regarding: York Construction

UPPAC Database Record ID: 1180

Investigator: Chuck Weindorf

Report Date: 03/21/2012

Damage Date: 8/26/2010 2:28:44 PM

Damage Address: E 106th St

City: Carmel

County: Hamilton

### The Parties

Excavator: **York Construction**

Contact: Jason York

Address: P.o. Box 3216, Muncie, In 47307

Telephone: 765-760-9806

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

## **Investigation regarding: York Construction**

UPPAC Database Record ID: 1180

### **Damage Impact**

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1243

### **Excavator Activities/Cause of damage information:**

Excavator request locates: Yes    Indiana 811 ticket Number: 1008050861

Type of Equipment: Auger

Type of work performed: Water

**Synopsis:** Excavator severed a natural gas service line with a trackhoe.

**Findings:** Reported by Indiana 811, initial notice was delivered and signed for on 12/7/2011, however the excavator failed to respond. Excavator requested locates on 08/5/2010 and damaged the natural gas line 21 days later.

**Conclusion:** There was a failure to provide notice of excavation prior to construction due to the fact the original locate had expired.

**Violation: IC 8-1-26-16(g) Failure to provide notice of excavation.**

**York Construction** currently has three (3) reports of damages in the record, between 4/12/2010 6:09:26 PM and 8/26/2010 2:28:44 PM.

Ticket ID: Version: 00 Notice ID: IUPPS2010080500893  
Taken Time: 08/05/2010 10:12  
NoticeType: Normal Notice

Case ID 1180

NORMAL NOTICE

Ticket : 1008050861 Date: 08/05/2010 Time: 10:12 Oper: DSEGO Chan:087

State: IN Cnty: HAMILTON Twp: CLAY  
Cityname: CARMEL Inside: Y Near: N  
Subdivision:

Address :  
Street : E 106TH ST  
Cross 1 : HOLADAY DR Within 1/4 mile: Y  
Location: LOCATE FROM THE ABOVE INTERSECTION GOING EAST FOR APROXIMATLEY 1100  
FEET ON THE SOUTH SIDE OF E 106TH ST---LOCATING 75 FEET SOUTH INTO THE PROPERTY  
FOR THE ENTIRE DISTANCE

:  
Grids : 3956C8606B 3956B8606B 3956C8606A 3956B8606A 3956C8607D  
Grids : 3956B8607D

Work type : WATER LINE  
Done for : CITY OF CARMEL  
Start date: 08/09/2010 Time: 10:30 Hours notice: 96/048 Priority: NORM  
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
Duration : 2 MONTHS Depth: 10 FEET

Company : YORK CONSTRUCTION Type: CONT  
Co addr : P.O. BOX 3216  
City : MUNCIE State: IN Zip: 47307  
Caller : JASON YORK Phone: (765)284-9501  
Contact : JASON YORK - CELL Phone:  
BestTime:  
Mobile : (765)760-9806  
Fax : (765)287-9675

Remarks : All tickets are taken and processed on Eastern Daylight Time  
Will you be white-lining the dig site area? NO  
:

Submitted date: 08/05/2010 Time: 10:12  
Members: ID0002 ID0103 ID0660 ID1501 ID2400 ID5555 ID9200 ID9999 SBCIN SM

Service Area: ID0002 (DUKE ENERGY / FORMERLY CINERGY)  
Contact: Carl Shepherd  
Ph: (513)287-3188 Emerg Ph: Alt Ph:

Service Area: ID0103 (VECTREN - NOBLESVILLE #1)  
Contact: Darlene Jarboe  
Ph: Emerg Ph: Alt Ph:

Service Area: ID0660 (COMCAST NORTHEAST (NOBLESVILLE))  
Contact: DALE LAMBERT  
Ph: (765)646-9113 x9109 Emerg Ph: Alt Ph:

Service Area: ID1501 (CITIZENS WATER / FORMERLY VEOLIA WATER)  
Contact: SHAWN WEEKS  
Ph: (317)263-6435 Emerg Ph: Alt Ph:


Service Area: ID2400 (CARMEL UTILITIES)  
Contact: TERRY KRUESKAMP  
Ph: (317)571-2565 Emerg Ph: Alt Ph:

Service Area: ID5555 (INDIANAPOLIS POWER & LIGHT COMPANY)  
Contact: \*  
Ph: (317)261-8111 Emerg Ph: Alt Ph:

Service Area: ID9200 (CLAY TOWNSHIP REGIONAL WASTE DISTRICT)  
Contact: SHAWN PAPS  
Ph: (317)844-9200 Emerg Ph: Alt Ph:

Service Area: ID9999 (BRIGHT HOUSE NETWORKS INDIANAPOLIS)  
Contact: JEFF FARMER  
Ph: (317)632-9077 x263 Emerg Ph: Alt Ph:

# STATE OF INDIANA



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

September 20, 2011

Ms. Darlene Kulhanek  
Vectren  
1 N Main Street  
Evansville, IN 47702

RECEIVED

SEP 23 2011

INDIANA UTILITY  
REGULATORY COMMISSION

Subject: Investigation Request for Information

Date of Event: 8/26/2010

Event Location: E 106th Street, Carmel

Facility Owner: Vectren

Excavator: York Construction

Other Party: N/A

Pipeline Division Case No. 1180

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation,**

maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.

Please promptly provide your information to: Pipeline Safety Division – Case No. 1180, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Also, please include the Investigation Number referenced above on your materials. In the alternative, if you would prefer to scan the materials and send them electronically, please send the documents to: [PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov).

Although you are not a formal party in this investigation, please treat this request for information seriously, because the potential civil penalties for violations include: a potential civil fine up to \$10,000.00; mandatory education and training for employees regarding pipeline safety; a required development plan to avoid future violations; or a warning letter for certain homeowner/tenants who are first time offenders. Consequently, your input will assist the Pipeline Division with its determination and may have a substantial impact on the case.

After the investigation is completed, the Pipeline Division will prepare an Investigation Report with findings and forward it to the Underground Plant Protection Advisory Committee (“Advisory Committee”). This is a statutory committee, comprised of excavators, facility operators, investor and municipal utilities, the 811 Association and facility locate marking companies, whose role is to evaluate the Pipeline Division’s findings and make a recommendation for a civil penalty. In the event there is disagreement regarding the Advisory Committee’s recommendation to the Commission, parties are entitled to request a hearing before the full Commission. If there is a violation, the Indiana Utility Regulatory Commission (“Commission”) will impose the penalty. Any fines imposed are statutorily required to be spent funding the Commission’s training and educational programming to promote excavation and pipeline safety.

Thank you for your *prompt* assistance in providing written information to the Pipeline Division regarding the previously referenced incident. Any information received after the deadlines will not be considered in the investigation, will be unavailable to the Advisory Committee and will result in a lack of full information being made available; hence, your participation is vital to serving the interests of justice and enhancing the public’s safety. In an effort to assist you, please find an enclosure entitled “Information Request.” Should you have procedural or legal questions regarding the Underground Plant Protection Advisory Committee or the Indiana Utility Regulatory Commission, please contact David L. Welch, Assistant General Counsel, at (317) 234-4715. Should you have questions regarding the pipeline damage identified above, or our investigation, please contact me at (317) 232-2718. Thank you for your assistance.

Sincerely,



William Boyd  
Director, Pipeline Safety Division

Enclosure: Information Request

## Information Request

Pipeline Safety Division  
Indiana Utility Regulatory Commission

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: **York Construction**

Responsible Party Personal Name: **Jason York**

Title (if any): **Owner?**

Address: **6700 W. Isangel Rd.**

City, State Zip: **Muncie, IN 47304**

Preferred Telephone: **765-760-9806**

Cell Phone Number:

Email Address:

Facility Information:

Business Name: **Vectren Energy**

Responsible Party Personal Name: **Darlene Kulhanek**

Title (if any): **Manager Facilities Damages**

City, State, Zip **Evansville, IN 47711**

Address: **1 Main Street**

Preferred Telephone: **812-491-4227**

Cell Phone Number: **812-568-5235**

Email Address: **Dkulhanek@vectren.com**

Locator Service Information:

Business Name: **USIC Inc.**

Responsible Party Personal Name: **Morgan Thompson**

Title (if any): **Claims Coordinator**

Address: **9045 N. River Rd., Suite 300**

City, State Zip: **Indianapolis, IN 46240**

Preferred Telephone: **317-575-7800x109**

Cell Phone Number:

Email Address: **morganthompson@usicinc.com**

Other (Witness, Police, Fire, Othea-) Information: N/A

Personal Contact: Business/Organization Name: N/A

Title (if any)

Address:

City, State, Zip Preferred Telephone:

Cell Phone Number:

Email Address:

Utility Line Impact:

Product Type (circle one):

Natural Gas

Liquid Pipeline

Unknown/Other

Facility Type (circle one):

Distribution

Gathering

Service/Drop

Transmission

Unknown/Other

Size (Diameter/etc.): 1/2"

Pressure (PSIG/Inches): 60 PSIG

Interruption in Service: Yes / No

Number of Customers Affected: 1

Evacuation: Yes / No If yes, How Many Evacuated? 0

Repair Cost (if known): \$ 1242.98

Cause of Damage Information:

Type of Equipment (circle one):

Auger

Backhoe/Trackhoe

Boring /Drilling

Directional Drilling

Explosives

Farm Equipment

Grader/Scraper

Hand Tools

Milling Equipment

Probing Device

Trencher

Vacuum Equipment

Unknown/Other

Type of Work Performed (circle one):

- Agriculture Cable
- TV Curb/Sidewalk
- Bldg. Construction
- Bldg. Demolition
- Drainage
- Driveway Electric
- Engineering/Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Natural Gas
- Pole
- Public Transit Authority
- Railroad Maintenance
- Road Work
- Sewer (Sanitary/Storm)
- Site Development
- Steam
- Storm Drain/Culvert
- Street Light
- Telecommunications
- Traffic Signal
- Traffic Sign
- Water
- Waterway Improvement
- Unknown/Other

Release of Product: Yes / No

Ignition and/or Fire: Yes / No

Excavator Notify 811: Yes / No

Locate Information:

Excavator Request Locate: Yes / No

Indiana 811 Locate Ticket Number: 1008050861


Locate Marks Visible: Yes / No

Locate Marks Correct: Yes / No

Excavator "White Lined": Yes / No

Maps Used to Mark Facilities: Yes / No





VECTREN  
Live Smart

Energy Delivery

P.O. Box 209

Evansville, Indiana 47702-0209

September 22, 2011

VIA CERTIFIED MAIL; RETURN RECEIPT REQUESTED

York Construction  
6700 W Isangel Rd  
Muncie, IN 47304

RE: Damage to Natural Gas facilities located at 2033 E 106<sup>th</sup> St, Carmel, Indiana

Dear Sir or Madam:

It has been brought to my attention that your company has damaged natural gas facilities owned by Vectren Energy Delivery of Indiana, Inc. at 2033 E 106<sup>th</sup> St, Carmel, Indiana on or about August 26, 2010. In doing so, York Construction failed to comply with Indiana Code Section 8-1-26-20 which provides that York Construction should have planned the excavation or demolition to avoid damage to or minimize interference with underground facilities in and near the construction area. Furthermore, York Construction failed to maintain a two foot clearance between Vectren Energy Delivery of Indiana Inc.'s facilities, as marked by its locating agent, and the cutting edge or point of York Construction's mechanized equipment and failed to expose Vectren Energy Delivery of Indiana, Inc.'s underground facility by the use of hand excavation, air cutting or vacuum excavation.

As a result of your violation of the foregoing statutes, Vectren Energy Delivery of Indiana, Inc. has incurred a pecuniary loss in the amount of \$1242.98. Indiana Code Section 8-1-26-22 provides that in the event that an operator suffers pecuniary loss as a result of the violation of these statutes, the operator may recover in a civil action an amount equal to the operator's actual damage to the facility, the costs of the action, and a reasonable attorney's fee. Furthermore, the operator may recover punitive damages up to three (3) times the operator's actual damage.


Vectren Energy Delivery of Indiana, Inc. would like to avoid litigation and therefore demands that you immediately pay to Vectren Energy Delivery of Indiana, Inc. the amount of \$1242.98 in order to cover the actual damages sustained by Vectren Energy Delivery of Indiana, Inc. as a result of your actions. In the event that Vectren Energy Delivery of Indiana, Inc. does not receive payment in full within ten (10) days of the date of this letter, Vectren Energy Delivery of Indiana, Inc. will have no choice but to pursue all of its rights and remedies in a court of law. In the event that Vectren Energy Delivery of Indiana, Inc. is required to take legal action against you, it will seek reimbursement for all of the items allowable under Indiana Code Section 8-1-26-22 as detailed above, in addition to any other remedies available in law or equity.

I urge you to give this matter your immediate attention. Payments may be mailed to Vectren Energy Delivery of Indiana, Inc., P. O. Box 209, Evansville, Indiana 47702. In the alternative, please contact Ms. Darlene Kulhanek at 812-491-4227 to make payment arrangements.

Sincerely,

Joshua Claybourn  
Corporate Counsel

cc: Ms. Darlene Kulhanek, Manager Facilities Damage




2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

NOW DUE  
FINAL  
\$1,242.98

YORK CONSTRUCTION  
6700 W ISANGEL RD  
MUNCIE, IN 47304

Type: GAS  
Invoice: FDS0013099  
BillToID: 29147  
Billing Date: 1/3/2011  
Date of Loss: 8/26/2010  
5830 103.0510

Please return this portion with your remittance.



Mail Payment To: VECTREN ENERGY DELIVERY OF INDIANA - NORTH  
Vectren Utilities Holding Group, Inc.  
1239 Reliable Parkway  
Chicago, IL 60686-0012  
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5  
Risk Management/Claims Department

NOW DUE  
FINAL  
\$1,242.98

YORK CONSTRUCTION  
6700 W ISANGEL RD  
MUNCIE, IN 47304

Type: GAS  
Invoice: FDS0013099  
BillToID: 29147  
Billing Date: 1/3/2011  
Date of Loss: 8/26/2010

**Invoice For Costs to Repair and Reconstruct Damaged Property**

Address: 2033 E 106TH STREET, CARMEL

1/2" PLASTIC SERVICE SEVERED BY TRACKHOE. NOT HAND EXPOSED.

Material:	\$98.76
Company Labor:	\$238.64
Contract Labor:	\$875.91
Transportation/Equipment:	\$27.33
Misc:	\$0.00
Gas Loss:	\$2.34
Adjustments:	\$0.00
Payments:	\$0.00
<b>Total:</b>	<b>\$1,242.98</b>

5830 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Task No.: 103.0510

Capital / O&M (circle one)

FDS-0013099

Vectren Corporation

Form 3112 (Rev. 10/04)

Indiana Gas

Sigeco

Vectren Energy Delivery of Ohio

TIME: 2:45 AM/PM

DATE OF DAMAGE: 8/26/10

Cost Center No.: 5830

DAMAGE SITE ADDRESS: 2033 E. 106th St

LOT #: CITY: Carmel

FACILITIES DAMAGED

- MAIN
SERVICE
REGULATOR STATION
FARM TAP
RESIDENTIAL METER
METER INDUSTRIAL/COMMERCIAL
OTHER

- SIZE(S)
0.50 INCH
0.75 INCH
1.00 INCH
2.00 INCH
4.00 INCH
6.00 INCH
OTHER

TYPE OF MATERIAL

- PLASTIC
STEEL
CAST IRON
OTHER

DAMAGE TYPE

- SEVERED
NOT CUT
PUNCTURE
SIZE 1/2" x 1/2"

PRESSURE

- 25 PSIG
40 PSIG
50 PSIG
60 PSIG
6 WC
OTHER

PROTECTION IN PLACE

- RAIL
POST
NONE
N/A

LEAK REPORT

# 636559

DURATION OF ESCAPING GAS

MINUTES 5min

- ONE-WAY FEED
TWO-WAY FEED

EFV ACTIVATED YES NO

DAMAGED BY

- CONTRACTOR
MUNICIPALITY/UTILITY
VEHICULAR ACCIDENT
COMPANY CREW
UNKNOWN
PROPERTY OWNER/TENANT
OTHER

TYPE OF CONSTRUCTION

- SEWER/DRAIN
WATER
ELECTRIC
TELEPHONE
CEMENT/PAVING
TV CABLE
FENCING
FOOTERS
OTHER

WORKING FOR

- CITY
STATE
PROPERTY OWNER
OTHER

NAME City of CARMEL

TYPE OF EQUIPMENT

- BACKHOE
TRACKHOE
PLOW
TRENCHER
BULLDOZER
POSTHOLE DIGGERS
BORE
AUGER
STAKE/SHOVEL
OTHER

DAMAGING PARTY

- DID NOT REQUEST LOCATES
DID NOT HAND DIG
USED EXPIRED LOCATES
OTHER

NUMBER OF CUSTOMERS AFFECTED: 1

TOTAL HOURS SERVICE WAS OFF: 2 1/2 hrs

INVOICE: YES NO

DAMAGING PARTY

NAME: YORK Construction

ADDRESS: 6700 W. ISANGEL Rd.

CITY/STATE/ZIP: MUNCIE, IN - 47304

PREPARED BY: KEVIN RUSSELL DATE: 8-26-10

Damaged by trackhoe operator. Line was properly marked. Did not spot service.

VISUAL OBSERVATION AT DAMAGE SITE

- LOCATE NOT APPLICABLE
FACILITIES PROPERLY MARKED
MARKING METHODS: CONVENTIONAL, OFFSET, FLAGS, PAINT, STAKES, WHISKERS
LOCATE MARKINGS FADED: YES NO
WRONG ADDRESS REQUESTED
FACILITIES IMPROPERLY LOCATED
QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
INACCURATE MAPS/CARDS
BROKEN OR NO TRACER WIRE
INSULATION PREVENTING ACCURATE LOCATE
LOCATOR ERROR
QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
INCOMPLETE LOCATE
MARKINGS OFF BY
INAPPROPRIATE SITE MARKINGS
NO LOCATE PERFORMED
FAILURE TO FOLLOW POLICY
WRONG ADDRESS LOCATED

OBSERVATION BY:

NAME OF LOCATOR:

- COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

NOTIFICATION AND OTHER DETAILS OF LOCATE

LOCATE TICKET #: 1008261975

DATE: TIME: AM/PM

- REGULAR REQUEST
EMERGENCY REQUEST

LOCATE COMPANY NOTIFIED

CONTACT NAME:

TIME CALLED: AM/PM

TIME LOCATOR ARRIVED AT SITE: AM/PM

COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES:

- YES NO

CONTRACTOR REPAIRS

- CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
CONTRACTOR REPAIRED DAMAGE

NAME OF CONTRACTOR: MPL - M. Setty

# OF REGULAR HOURS 2.5

# OF OVERTIME HOURS

CREW TYPE 4-MSH

MATERIALS OR ROAD WORK

- METER WAS REPLACED
REGULATOR WAS REPLACED
TEMPORARY ASPHALT REPAIR
PERMANENT ASPHALT REPAIR

PARTY TO INVOICE

NAME: Same

ADDRESS:

CITY/STATE/ZIP:

REVIEWED BY FIELD SUPERVISOR: R. M... DATE: 8-27-10

Tuesday, September 14, 2010

# Service Order Status

**Enter Service Order Number:**

4530447



**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD  
**Order Number:** N4530447  
**Order Type:** INVE  
**Order Status:** Completed

**Customer:** 600425666 - BEA MARY A  
**Prem:** 5508746 - 2033 E 106TH ST

**Technician:** 2912 - Russell, Kevin

**Order Dates and Times**

**Need Date:** 8/26/2010 2:49:00 PM  
**Time Created:** 8/26/2010 2:36:50 PM  
**Time Dispatched:** 8/26/2010 2:36:50 PM  
**Time In Route:** 8/26/2010 2:53:36 PM  
**Time On-Site:** 8/26/2010 3:05:49 PM  
**Tech Complete:** 8/26/2010 4:22:22 PM  
**Time Closed:** 8/26/2010 4:22:22 PM

**Events Performed/Completion Code**

IVEG - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:**  
**New Meter:**

**Completion Notes**

CONTRACTOR SEVERED 0.500PL.GAS SERVICE WITH TRACKHOE WHILE INSTALLING NEW WTR.MA  
 IN FOR THE CITY OF CARMEL.LINE WAS MADE SAFE AT 3:05PM.CO.CONTRACTOR [MPL] IS O  
 N SITE TO COMPLETE REPAIRS.

**Request Notes**

08/26/10 CUT LINE NOT SURE IF STILL BLOWING PER LISA WITH 811--PETS?? MTR O/SACCESSIBLE MTR#0310176  
 XST HOLIDAY--HIT BY YORK CONSTRUCTION POC JASON YORK #765-760-9806 DIG REF #1008261978--CREW ONSITE

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	8/26/2010 2:47:37 PM	Russell, Kevin
AsnAssignmentEnRoute_evt	8/26/2010 2:53:36 PM	Russell, Kevin
AsnAssignmentOnSite_evt	8/26/2010 3:05:49 PM	Russell, Kevin
OrdOrderComplete_evt	8/26/2010 4:22:22 PM	Russell, Kevin

NOTE: The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

DAMAGE DAMAGE

Ticket : 1008261978 Date: 08/26/2010 Time: 14:26 Oper: LWORTON Chan:025

State: IN Cnty: HAMILTON Twp: CLAY  
 Cityname: CARMEL Inside: Y Near: N  
 Subdivision:

Address :

Street : E 106TH ST  
 Cross 1 : HOLADAY DR Within 1/4 mile: Y  
 Location: LOCATE FROM THE ABOVE INTERSECTION GOING EAST FOR APROXIMATLEY 1100 FEET ON THE SOUTH SIDE OF E 106TH ST---LOCATING 75 FEET SOUTH INTO THE PROPERTY FOR THE ENTIRE DISTANCE

Grids : 3956C8606B 3956B8606B 3956C8606A 3956B8606A 3956C8607D  
 Grids : 3956B8607D

Work type : WATER LINE  
 Done for : CITY OF CARMEL  
 Start date: 08/26/2010 Time: 14:27 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y  
 Duration : 2 MONTHS Depth: 10 FEET

Company : YORK CONSTRUCTION Type: CONT  
 Co addr : P.O. BOX 3216  
 City : MUNCIE State: IN Zip: 47307  
 Caller : CHRIS FISHER Phone: (765)284-9501  
 Contact : JASON YORK - CELL Phone:  
 BestTime:  
 Mobile : (765)760-9806  
 Fax : (765)287-9675

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 PER CHRIS: HAS HIT A VECTREN GAS LINE AT 2033 E 106TH ST---LINE IS NOT BLOWING---ADVISED TO CALL 911 AND VECTREN---CREW IS ON SITE---PREVIOUS TICKET #1008050861---THANK YOU

Will you be white-lining the dig site area? NO

Submitted date: 08/26/2010 Time: 14:26

Members: ID0002 ID0103 ID0660 ID1501 ID2400 ID5555 ID9200 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CARMEL UTILITIES	
CLAY TOWNSHIP REGIONAL WASTE DISTRICT	SEWER
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
INDIANAPOLIS POWER & LIGHT COMPANY	ELECTRIC
VECTREN - NOBLESVILLE #1	GAS
VEOLIA WATER INDIANAPOLIS	WATER

[View Map](#) | [Close Map](#)

NORMAL NOTICE

Ticket : 1008050861 Date: 08/05/2010 Time: 10:12 Oper: DSEGO Chan:087

State: IN Cnty: HAMILTON Twp: CLAY  
 Cityname: CARMEL Inside: Y Near: N  
 Subdivision:

Address :  
 Street : E 106TH ST  
 Cross 1 : HOLADAY DR Within 1/4 mile: Y  
 Location: LOCATE FROM THE ABOVE INTERSECTION GOING EAST FOR APROXIMATLEY 1100 FEET ON THE SOUTH SIDE OF E 106TH ST---LOCATING 75 FEET SOUTH INTO THE PROPERTY FOR THE ENTIRE DISTANCE

Grids : 3956C8606B 3956B8606B 3956C8606A 3956B8606A 3956C8607D  
 Grids : 3956B8607D

Work type : WATER LINE  
 Done for : CITY OF CARMEL  
 Start date: 08/09/2010 Time: 10:30 Hours notice: 96/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
 Duration : 2 MONTHS Depth: 10 FEET

Company : YORK CONSTRUCTION Type: CONT  
 Co addr : P.O. BOX 3216  
 City : MUNCIE State: IN Zip: 47307  
 Caller : JASON YORK Phone: (765)284-9501  
 Contact : JASON YORK - CELL Phone:  
 BestTime:  
 Mobile : (765)760-9806  
 Fax : (765)287-9675

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 Will you be white-lining the dig site area? NO

Submitted date: 08/05/2010 Time: 10:12  
 Members: ID0002 ID0103 ID0660 ID1501 ID2400 ID5555 ID9200 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CARMEL UTILITIES	
CLAY TOWNSHIP REGIONAL WASTE DISTRICT SEWER	
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
INDIANAPOLIS POWER & LIGHT COMPANY	ELECTRIC
VECTREN - NOBLESVILLE #1	GAS
VEOLIA WATER INDIANAPOLIS	WATER

[View Map](#)

[Close Map](#)

NO  
EXCAVATOR  
RESPONSE  
PROVIDED