



Pipeline Safety Division Investigation Report

Investigation regarding: **Lineal Contracting**

UPPAC Database Record ID: 1252

Investigator: Howard Friend

Telephone: 317-232-2717

Report Date: 01/23/2012

Damage Date: 09/17/2010

Damage Address: W Cedar Bluff Rd

City: Harrodsburg

County: Monroe

The Parties

Excavator: **Lineal Contracting**

Contact: Brian Busick

Address: 2922 Mitchell Road, Bedford, In 47421

Telephone: (812) 277-0477

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Lineal Contracting

UPPAC Database Record ID: 1252

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$590

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1008172801

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Telecommunications

Synopsis: Damage to a natural gas service occurred during installation of a fiber optic cable.

Findings: Reported by Indiana 811; excavator signed for initial notice on 09/23/2011 but has not submitted a response. Damage occurred 31 days after ticket date.

Conclusion: There was a failure to provide notice of excavation, as the ticket was allowed to lapse prior to the damage.

Violation: IC 8-1-26-16(g): Failure to provide notice of excavation.

Lineal Contracting currently has 11 reports of damages in the record, between 08/25/2009 and 10/11/2011.

Ticket ID: Version: 00 Notice ID: IUPPS2010081702893
Taken Time: 08/17/2010 21:34
NoticeType: Normal Notice

Case ID 1252

NORMAL NOTICE

Ticket : 1008172801 Date: 08/17/2010 Time: 21:34 Oper: NBOYD Chan:002

State: IN Cnty: MONROE Twp: CLEAR CREEK
Cityname: HARRODSBURG Inside: Y Near: N
Subdivision:

Address :
Street : W CEDAR BLUFF RD
Cross 1 : S OLD IN RT 37 Within 1/4 mile: Y
Location: STARTING AT THE INTERSECTION LOCATE THE NORTH SIDE OF CEDAR BLUFF ROAD
GOING WEST FOR 1500 FEET
***Boring Where = DRIVEWAY
:
Grids : 3902C8632C 3902B8632C 3902C8632B 3902B8632B 3902C8632A
Grids : 3902B8632A

Work type : INSTALL FIBEROPTIC CABLE
Done for : SMITHVILLE TELEPHONE
Start date: 08/20/2010 Time: 07:00 Hours notice: 57/048 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
Duration : 2 WEEKS Depth: 3 FEET

Company : LINEAL CONTRACTING Type: CONT
Co addr : 2922 MITCHELL ROAD
City : BEDFORD State: IN Zip: 47421
Caller : BRIAN BUSICK Phone: (812)277-0477
Contact : BRIAN BUSICK - CELL Phone:
BestTime:
Mobile : (812)521-3474

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? YES
:

Submitted date: 08/17/2010 Time: 21:34
Members: ID0002 ID1443 ID2067 ID3147 ID6752 ID8060 SM

Service Area: ID0002 (DUKE ENERGY / FORMERLY CINERGY)
Contact: Carl Shepherd
Ph: (513)287-3188 Emerg Ph: Alt Ph:

Service Area: ID1443 (VECTREN - BLOOMINGTON)
Contact: Darlene Jarboe
Ph: Emerg Ph: Alt Ph:


Service Area: ID2067 (UTILITIES DIST. OF WESTERN INDIANA REMC)
Contact: BRIAN SPARKS
Ph: (812)384-4446 Emerg Ph: Alt Ph:

Service Area: ID3147 (COMCAST CENTRAL (BLOOMINGTON))
Contact: BRAD
Ph: (812)332-0131 x321 Emerg Ph: Alt Ph:

Service Area: ID6752 (SOUTHERN MONROE WATER CORP)
Contact: SAM WELLMAN
Ph: (812)824-7220 Emerg Ph: Alt Ph:

Service Area: ID8060 (SMITHVILLE TELEPHONE COMPANY, INC)
Contact:
Ph: Emerg Ph: Alt Ph:

STATE OF INDIANA



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

September 20, 2011

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 9/17/2010

Event Location: W Cedar Bluff Rd., Harrodsburg

Facility Owner: Vectren

Excavator: Lineal Contracting

Other Party: N/A

Pipeline Division Case No. 1252

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation,**

RECEIVED

SEP 23 2011

INDIANA UTILITY
REGULATORY COMMISSION

maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.

Please promptly provide your information to: Pipeline Safety Division – Case No. 1252, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Also, please include the Investigation Number referenced above on your materials. In the alternative, if you would prefer to scan the materials and send them electronically, please send the documents to: *PipelineDamageCase@urc.in.gov*.

Although you are not a formal party in this investigation, please treat this request for information seriously, because the potential civil penalties for violations include: a potential civil fine up to \$10,000.00; mandatory education and training for employees regarding pipeline safety; a required development plan to avoid future violations; or a warning letter for certain homeowner/tenants who are first time offenders. Consequently, your input will assist the Pipeline Division with its determination and may have a substantial impact on the case.

After the investigation is completed, the Pipeline Division will prepare an Investigation Report with findings and forward it to the Underground Plant Protection Advisory Committee (“Advisory Committee”). This is a statutory committee, comprised of excavators, facility operators, investor and municipal utilities, the 811 Association and facility locate marking companies, whose role is to evaluate the Pipeline Division’s findings and make a recommendation for a civil penalty. In the event there is disagreement regarding the Advisory Committee’s recommendation to the Commission, parties are entitled to request a hearing before the full Commission. If there is a violation, the Indiana Utility Regulatory Commission (“Commission”) will impose the penalty. Any fines imposed are statutorily required to be spent funding the Commission’s training and educational programming to promote excavation and pipeline safety.

Thank you for your *prompt* assistance in providing written information to the Pipeline Division regarding the previously referenced incident. Any information received after the deadlines will not be considered in the investigation, will be unavailable to the Advisory Committee and will result in a lack of full information being made available; hence, your participation is vital to serving the interests of justice and enhancing the public’s safety. In an effort to assist you, please find an enclosure entitled “Information Request.” Should you have procedural or legal questions regarding the Underground Plant Protection Advisory Committee or the Indiana Utility Regulatory Commission, please contact David L. Welch, Assistant General Counsel, at (317) 234-4715. Should you have questions regarding the pipeline damage identified above, or our investigation, please contact me at (317) 232-2718. Thank you for your assistance.

Sincerely,



William Boyd
Director, Pipeline Safety Division

Enclosure: Information Request

Information Request

Pipeline Safety Division
Indiana Utility Regulatory Commission

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: **Lineal Contracting**

Responsible Party Personal Name: **Brian Busick**

Title (if any): **Unknown**

Address: **2922 Mitchell Rd.**

City, State Zip: **Bedford, IN 47421**

Preferred Telephone: **812-521-3474**

Cell Phone Number:

Email Address:

Facility Information:

Business Name: **Vectren Energy**

Responsible Party Personal Name: **Darlene Kulhanek**

Title (if any): **Manager Facilities Damages**

City, State, Zip **Evansville, IN 47711**

Address: **1 Main Street**

Preferred Telephone: **812-491-4227**

Cell Phone Number: **812-568-5235**

Email Address: **Dkulhanek@vectren.com**

Locator Service Information:

Business Name: **USIC Inc.**

Responsible Party Personal Name: **Tim Sanders**

Title (if any): **Southern Indiana District Manager**

Address: **3818 E Morgan Avenue**

City, State Zip: **Evansville, IN 47715**

Preferred Telephone: **812-479-9236**

Cell Phone Number:

Email Address: **timsanders@usicinc.com**

Other (Witness, Police, Fire, Othea) Information: Fire
Personal Contact: Business/Organization Name: N/A

Title (if any)

Address:

City, State, Zip

Preferred Telephone:

Cell Phone Number:

Email Address:

Utility Line Impact:

Product Type (circle one):

Natural Gas

Liquid Pipeline

Unknown/Other

Facility Type (circle one):

Distribution

Gathering

Service/Drop

Transmission

Unknown/Other

Size (Diameter/etc.): 1/2"

Pressure (PSIG/Inches): 60 psig

Interruption in Service: Yes / No

Number of Customers Affected: 1

Evacuation: Yes / No If yes, How Many Evacuated? 0

Repair Cost (if known): \$ 589.94

Cause of Damage Information:

Type of Equipment (circle one):

Auger

Backhoe/Trackhoe

Boring /Drilling

Directional Drilling

Explosives

Farm Equipment

Grader/Scraper

Hand Tools

Milling Equipment

Probing Device

Trencher

Vacuum Equipment

Unknown/Other

Type of Work Performed (circle one):

- Agriculture Cable
- TV Curb/Sidewalk
- Bldg. Construction
- Bldg. Demolition
- Drainage
- Driveway Electric
- Engineering/Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Natural Gas
- Pole
- Public Transit Authority
- Railroad Maintenance
- Road Work
- Sewer (Sanitary/Storm)
- Site Development
- Steam
- Storm Drain/Culvert
- Street Light
- Telecommunications
- Traffic Signal
- Traffic Sign
- Water
- Waterway Improvement
- Unknown/Other

Release of Product: Yes / No

Ignition and/or Fire: Yes / No

Excavator Notify 811: Yes / No ?

Locate Information:

Excavator Request Locate: Yes / No ?


Indiana 811 Locate Ticket Number: 0

Locate Marks Visible: Yes / No

Locate Marks Correct: Yes / No

Excavator "White Lined": Yes / No ?

Maps Used to Mark Facilities: Yes / No ?




2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

NOW DUE
FINAL
\$589.94

LINEAL CONTRACTING
2922 MITCHELL ROAD,
BEDFORD, IN 47421

Type: GAS
Invoice: FDS0013267
BillToID: 29274
Billing Date: 2/25/2011
Date of Loss: 9/17/2010
5924 103.0510

Please return this portion with your remittance.



Mail Payment To: VECTREN ENERGY DELIVERY OF INDIANA - NORTH
Vectren Utilities Holding Group, Inc.
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE
FINAL
\$589.94

LINEAL CONTRACTING
2922 MITCHELL ROAD,
BEDFORD, IN 47421

Type: GAS
Invoice: FDS0013267
BillToID: 29274
Billing Date: 2/25/2011
Date of Loss: 9/17/2010

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 500 W CEDAR BLUFF RD, BLOOMINGTON
1/2" PLASTIC SERVICE DAMAGED BY TRACKHOE. NOT HAND EXPOSED.

Material:	\$38.53
Company Labor:	\$515.41
Contract Labor:	\$0.00
Transportation/Equipment:	\$36.00
Misc:	\$0.00
Gas Loss:	\$0.00
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$589.94

5924 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Vectren Corporation
Form 3112 (Rev. 10/04)
 Indiana Gas
 Sigeco
 Vectren Energy Delivery of Ohio

Task No.: 103,0510

Capital / O&M (circle one)

FDS0013267

TIME: 5:45 AM/PM

DATE OF DAMAGE: 9, 17, 2010

Cost Center No.: 5924

DAMAGE SITE ADDRESS: 500 W Cedar Bluff Road

LOT #: _____ CITY: Bloomington

FACILITIES DAMAGED

- MAIN
- SERVICE
- REGULATOR STATION
- FARM TAP
- RESIDENTIAL METER
- METER INDUSTRIAL/COMMERCIAL
- OTHER

- SIZE(S)
- 0.50 INCH
 - 0.75 INCH
 - 1.00 INCH
 - 2.00 INCH
 - 4.00 INCH
 - 6.00 INCH
 - OTHER
- 0.660

TYPE OF MATERIAL

- PLASTIC
- STEEL
- CAST IRON
- OTHER

DAMAGE TYPE

- SEVERED
- NOT CUT
- PUNCTURE
- SIZE 1/2 X 16"

PRESSURE

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 60 PSIG
- 6 WC
- OTHER

PROTECTION IN PLACE

- RAIL
- POST
- NONE
- N/A

LEAK REPORT

621568

DURATION OF ESCAPING GAS

MINUTES 1

- ONE-WAY FEED
- TWO-WAY FEED

EFV ACTIVATED YES NO

DAMAGED BY

- CONTRACTOR
- MUNICIPALITY/UTILITY
- VEHICULAR ACCIDENT
- COMPANY CREW
- UNKNOWN
- PROPERTY OWNER/TENANT
- OTHER

TYPE OF CONSTRUCTION

- SEWER/DRAIN
- WATER
- ELECTRIC
- TELEPHONE
- CEMENT/PAVING
- TV CABLE
- FENCING
- FOOTERS
- OTHER

WORKING FOR

- CITY
- STATE
- PROPERTY OWNER

NAME SMITHVILLE Telephone Co

TYPE OF EQUIPMENT

- BACKHOE
- TRACKHOE
- PLOW
- TRENCHER
- BULLDOZER
- POSTHOLE DIGGERS
- BORE
- AUGER
- STAKE/SHOVEL
- OTHER

DAMAGING PARTY

- DID NOT REQUEST LOCATES
- DID NOT HAND DIG
- USED EXPIRED LOCATES
- OTHER

NUMBER OF CUSTOMERS AFFECTED: 1

TOTAL HOURS SERVICE WAS OFF: 3

INVOICE: YES NO

DAMAGING PARTY

NAME: Lineal Contracting # (812) 279-0477

ADDRESS: 2922 Mitchell Road

CITY/STATE/ZIP: Bedford IN 47421

PREPARED BY: M. Swafford DATE: 9-17-2010

VISUAL OBSERVATION AT DAMAGE SITE

- LOCATE NOT APPLICABLE (Above Ground Damage Only)
- FACILITIES PROPERLY MARKED
 - MARKING METHODS: CONVENTIONAL OFFSET
 - FLAGS PAINT STAKES WHISKERS
- LOCATE MARKINGS FADED: YES NO
- WRONG ADDRESS REQUESTED
- FACILITIES IMPROPERLY LOCATED
- QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
- INACCURATE MAPS/CARDS
- BROKEN OR NO TRACER WIRE (PLASTIC)
- INSULATION PREVENTING ACCURATE LOCATE
- LOCATOR ERROR
- QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
- INCOMPLETE LOCATE
- MARKINGS OFF BY 18" (FEET/INCHES)
- INAPPROPRIATE SITE MARKINGS
- NO LOCATE PERFORMED
- FAILURE TO FOLLOW POLICY
- WRONG ADDRESS LOCATED

OBSERVATION BY: M. SWAFFORD

NAME OF LOCATOR: _____

- COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

NOTIFICATION AND OTHER DETAILS OF LOCATE

- LOCATE TICKET #: _____
- DATE: _____ TIME: _____ AM/PM
 - REGULAR REQUEST
 - EMERGENCY REQUEST
- LOCATE COMPANY NOTIFIED
- CONTACT NAME: _____
- TIME CALLED: _____ AM/PM
- TIME LOCATOR ARRIVED AT SITE: _____ AM/PM
- COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES:
 - YES
 - NO

CONTRACTOR REPAIRS

- CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
- CONTRACTOR REPAIRED DAMAGE

NAME OF CONTRACTOR: _____

OF REGULAR HOURS: _____

OF OVERTIME HOURS: _____

CREW TYPE: _____

MATERIALS OR ROAD WORK

- METER WAS REPLACED _____ (STORES CODE)
- REGULATOR WAS REPLACED _____ (STORES CODE)
- TEMPORARY ASPHALT REPAIR _____ (SQ. FT.)
- PERMANENT ASPHALT REPAIR _____ (SQ. FT.)

PARTY TO INVOICE

NAME: Lineal

ADDRESS: _____

CITY/STATE/ZIP: _____

REVIEWED BY FIELD SUPERVISOR: Randa Powers DATE: 9/22/10

INCLUDE ANY OBSERVATIONS ON BACK OF FORM

Submitted 9/20

Service Order Status

Thursday, September 22, 2011

Enter Service Order Number:

4553038



Banner Instance: CS03PROD CS01PROD CS02PROD
Order Number: N4553038
Order Type: LEAK
Order Status: Completed

Customer: 600220812 - WILLIS KENNETH R
Prem: 5409548 - 500 W CEDAR BLUFF RD

Technician: 2921 - Swafford, Mike

Order Dates and Times

Need Date: 9/17/2010 6:43:00 PM
Time Created: 9/17/2010 5:28:17 PM
Time Dispatched: 9/17/2010 5:28:17 PM
Time In Route: 9/17/2010 6:38:02 PM
Time On-Site: 9/17/2010 6:38:05 PM
Tech Complete: 9/17/2010 7:31:30 PM
Time Closed: 9/17/2010 7:31:30 PM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current ReadStatus

Old Meter: 6119 Active
New Meter:

Completion Notes

CREW REPAIRED HALF INCH LINE...TESTED PIPING NEG...INSIDE CHECK OK-RE.LIT W/HEAT
 ER ,FURN AND RANGE..

Request Notes

9-17-10 PER CONTACTOR-BRIAN BUSICK-HIT LINE. GAS NOT BLOWING. LOC#?812-521-3474. CREW ONSITE. 50 FT FROM HOME. XST. OLD ST RD HWY 37.AVAIL FOR ACCSS.

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	9/17/2010 5:30:24 PM	Swafford, Mike
AsnAssignmentEnRoute_evt	9/17/2010 6:38:02 PM	Swafford, Mike
AsnAssignmentOnSite_evt	9/17/2010 6:38:05 PM	Swafford, Mike
OrdOrderComplete_evt	9/17/2010 7:31:30 PM	Swafford, Mike

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

Ticket Text

From: irth@iupps.org
Sent: Tuesday, August 17, 2010 9:44 PM
To: onecall7+indy-iupps@smptickets.com
Subject: IUPPS ID1443 2010/08/17 #02769 1008172801-00A NORM NEW

ID1443 02769 IUPPSa 08/17/2010 21:44:27 1008172801-00A NORM NEW GRID

NORMAL NOTICE

Ticket : 1008172801 Date: 08/17/2010 Time: 21:34 Oper: NBOYD Chan:002

State: IN Cnty: MONROE Twp: CLEAR CREEK
Cityname: HARRODSBURG Inside: Y Near: N
Subdivision:

Address :

Street : W CEDAR BLUFF RD

Cross 1 : S OLD IN RT 37 Within 1/4 mile: Y

Location: STARTING AT THE INTERSECTION LOCATE THE NORTH SIDE OF CEDAR BLUFF ROAD GOING WEST FOR 1500 FEET ***Boring Where = DRIVEWAY

:

Grids : 3902C8632C 3902B8632C 3902C8632B 3902B8632B 3902C8632A

Grids : 3902B8632A

Boundary: n 39.042706 s 39.041607 w -86.549927 e -86.540474

Work type : INSTALL FIBEROPTIC CABLE

Done for : SMITHVILLE TELEPHONE

Start date: 08/20/2010 Time: 07:00 Hours notice: 57/48 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N

Duration : 2 WEEKS Depth: 3 FEET

Company : LINEAL CONTRACTING Type: CONT Co addr : 2922 MITCHELL ROAD

City : BEDFORD State: IN Zip: 47421

Caller : BRIAN BUSICK Phone: (812)277-0477 Contact : BRIAN BUSICK - CELL Phone:

BestTime:

Mobile : (812)521-3474

Remarks : All tickets are taken and processed on Eastern Daylight Time Will you be white-lining the dig site area? YES

:

Submitted date: 08/17/2010 Time: 21:34

Members: ID0002 ID1443 ID2067 ID3147 ID6752 ID8060 SM

Fact Based Investigation Report

NOTIFICATION ID: 01220100917003

DISTRICT: Southern IN

DAMAGE DATE: 9/17/2010 3:06:00 PM

NOTIFICATION DATE: 9/17/2010 3:12:03 PM

NOTIFIED BY: BRIAN BUSICK One Call Center

DAMAGE ADDRESS: W CEDAR BLUFF RD HARRODSBURG

CITY: CLEAR CREEK ST: IN ZIP:

DAMAGED CUSTOMER: VECTREN

INVESTIGATION DATE: 09/17/2010

FROM: 15:30:00

TO: 16:10:00

EXCAVATOR INVOLVED: LINEAL CONSTRUCTION

TYPE OF EXCAVATION: Install Fiber

ORIG. LOCATE REQ.: 1008172801

START DATE/TIME: 8/19/2010 2:30:00 PM

TYPE OF TICKET: Routine

LOCATE REQ. INFO N/A:

DIG UP/DAMAGE REQ.: 1009171854

START DATE/TIME: 9/17/2010 3:10:00 PM

PICTURES TAKEN BY: Herbert Cook

DATE/TIME: 9/17/2010 3:45:00 PM

PHOTOGRAPHY TYPE: Digital

FRAME #: 1-12

INVESTIGATOR EMP#: 125277

INVESTIGATOR NAME: Herbert Cook

BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED? No

Fact Based Investigation Customer Information

NOTIFICATION ID: 01220100917003

SELECT A CUSTOMER: VECTREN

CUSTOMER #: (optional)

FACILITY DESCRIPTION: LOWPROF

FACILITY ID: service

LOCATOR NAME & EMP #: Cook Herbert - 125277

LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:

Facility Marked Accurately

Other:

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):

Visual, Facility Exposed At Time Of Investigation

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

Contractor hit marked gas service.

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

NA

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

NA

LIST ANY OTHER INDIVIDUALS ON SITE:

NA

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? Yes

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? Yes

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? Yes

EXTENT OF FACILITY DAMAGE Severed

REPLACEMENT FOOTAGE 40 feet

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No

WHAT CONTRACTOR EQUIPMENT WAS USED? None

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? Yes

IF YES, PLEASE LIST RECORD #(S) Service Card





2010/09/17




1/19/07





2010/09/17










2010/09/17





2010/09/17



NO
EXCAVATOR
RESPONSE
PROVIDED