



Pipeline Safety Division Investigation Report

Investigation regarding: **Glidden Fence**

UPPAC Database Record ID: 1297

Investigator: Howard Friend

Telephone: 317-232-2717

Report Date: 01/05/2012

Damage Date: 10/26/2010

Damage Address: 411 E 126th St

City: Carmel

County: Hamilton

The Parties

Excavator: **Glidden Fence**

Contact: W. T. Glidden, Sr., President

Address: 17808 Springmill Road, Westfield, In 46074

Telephone: (317) 867-5140

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Glidden Fence

UPPAC Database Record ID: 1297

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$549

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1009240518

Type of Equipment: Auger

Type of work performed: Fencing

Synopsis: A 1” natural gas service was damaged during while excavating fence post holes for a pad for “electric gate operator”.

Findings: Reported by Indiana 811; excavator response received 09/29/2011. Excavator was working on a locate request that had been called in by another company. Glidden Fence Co. had made their own request for earlier work but that locate ticket had expired.

Conclusion: By working off of an expired locate request, excavator failed to provide notice of excavation.

Violation: IC 8-1-26-16(g): Failure to provide notice of excavation.

Glidden Fence currently has 3 reports of damages in the record between 10/26/2010 and 09/12/2011.

NO

LOCATE

TICKET

PROVIDED

STATE OF INDIANA



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

September 20, 2011

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 10/26/2010

Event Location: 411 E 126th St., Carmel

Facility Owner: Vectren

Excavator: Glidden Fence

Other Party: N/A

Pipeline Division Case No. 1297

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation,**

RECEIVED

SEP 23 2011

INDIANA UTILITY
REGULATORY COMMISSION

maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.

Please promptly provide your information to: Pipeline Safety Division – Case No. 1297, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Also, please include the Investigation Number referenced above on your materials. In the alternative, if you would prefer to scan the materials and send them electronically, please send the documents to: *PipelineDamageCase@urc.in.gov*.

Although you are not a formal party in this investigation, please treat this request for information seriously, because the potential civil penalties for violations include: a potential civil fine up to \$10,000.00; mandatory education and training for employees regarding pipeline safety; a required development plan to avoid future violations; or a warning letter for certain homeowner/tenants who are first time offenders. Consequently, your input will assist the Pipeline Division with its determination and may have a substantial impact on the case.

After the investigation is completed, the Pipeline Division will prepare an Investigation Report with findings and forward it to the Underground Plant Protection Advisory Committee (“Advisory Committee”). This is a statutory committee, comprised of excavators, facility operators, investor and municipal utilities, the 811 Association and facility locate marking companies, whose role is to evaluate the Pipeline Division’s findings and make a recommendation for a civil penalty. In the event there is disagreement regarding the Advisory Committee’s recommendation to the Commission, parties are entitled to request a hearing before the full Commission. If there is a violation, the Indiana Utility Regulatory Commission (“Commission”) will impose the penalty. Any fines imposed are statutorily required to be spent funding the Commission’s training and educational programming to promote excavation and pipeline safety.

Thank you for your *prompt* assistance in providing written information to the Pipeline Division regarding the previously referenced incident. Any information received after the deadlines will not be considered in the investigation, will be unavailable to the Advisory Committee and will result in a lack of full information being made available; hence, your participation is vital to serving the interests of justice and enhancing the public’s safety. In an effort to assist you, please find an enclosure entitled “Information Request.” Should you have procedural or legal questions regarding the Underground Plant Protection Advisory Committee or the Indiana Utility Regulatory Commission, please contact David L. Welch, Assistant General Counsel, at (317) 234-4715. Should you have questions regarding the pipeline damage identified above, or our investigation, please contact me at (317) 232-2718. Thank you for your assistance.

Sincerely,



William Boyd
Director, Pipeline Safety Division

Enclosure: Information Request

Information Request

Pipeline Safety Division
Indiana Utility Regulatory Commission

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: **Glidden Fence Inc**

Responsible Party Personal Name: **Wendy**

Title (if any): **Unknown**

Address: **17808 Spring Mill Rd.**

City, State Zip: **Westfield, IN 46074**

Preferred Telephone: **317-379-0178**

Cell Phone Number:

Email Address:

Facility Information:

Business Name: **Vectren Energy**

Responsible Party Personal Name: **Darlene Kulhanek**

Title (if any): **Manager Facilities Damages**

City, State, Zip **Evansville, IN 47711**

Address: **1 Main Street**

Preferred Telephone: **812-491-4227**

Cell Phone Number: **812-568-5235**

Email Address: **Dkulhanek@vectren.com**

Locator Senrice Information:

Business Name: **USIC Inc.**

Responsible Patty Personal Name: **Morgan Thompson**

Title (if any): **Claims Coordinator**

Address: **9045 N. River Rd., Suite 300**

City, State Zip: **Indianapolis, IN 46240**

Preferred Telephone: **317-575-7800x109**

Cell Phone Number:

Email Address: **morganthompson@usicinc.com**

Other (Witness, Police, Fire, Othea) Information: N/A
Personal Contact: Business/Organization Name: N/A

Title (if any)

Address:

City, State, Zip Preferred Telephone:

Cell Phone Number:

Email Address:

Utility Line Impact:

Product Type (circle one):

- Natural Gas
- Liquid Pipeline
- Unknown/Other

Facility Type (circle one):

- Distribution
- Gathering
- Service/Drop
- Transmission
- Unknown/Other

Size (Diameter/etc.): 1"

Pressure (PSIG/Inches): 60 PSIG

Interruption in Service: Yes / No

Number of Customers Affected: 1

Evacuation: Yes / No If yes, How Many Evacuated? 0

Repair Cost (if known): \$ 548.56

Cause of Damage Information:

Type of Equipment (circle one):

- Auger
- Backhoe/Trackhoe
- Boring /Drilling
- Directional Drilling
- Explosives
- Farm Equipment
- Grader/Scraper
- Hand Tools
- Milling Equipment
- Probing Device
- Trencher
- Vacuum Equipment
- Unknown/Other

Type of Work Performed (circle one):

- Agriculture Cable
- TV Curb/Sidewalk
- Bldg. Construction
- Bldg. Demolition
- Drainage
- Driveway Electric
- Engineering/Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Natural Gas
- Pole
- Public Transit Authority
- Railroad Maintenance
- Road Work
- Sewer (Sanitary/Storm)
- Site Development
- Steam
- Storm Drain/Culvert
- Street Light
- Telecommunications
- Traffic Signal
- Traffic Sign
- Water
- Waterway Improvement
- Unknown/Other

Release of Product: Yes / No

Ignition and/or Fire: Yes / No

Excavator Notify 811: Yes / No ?

Locate Information:

Excavator Request Locate: Yes / No

Indiana 811 Locate Ticket Number: 1009240518

Locate Marks Visible: Yes / No

Locate Marks Correct: Yes / No

Excavator "White Lined": Yes / No

Maps Used to Mark Facilities: Yes / No ?

Was Locate Provided within Two (2) Working Days: Yes / No

Operator Employees On-site during Excavation: Yes / No

Incident Impact Information:

Number of Outpatient Treated: _____ 0

Number of Inpatient Treated: _____ 0

Number of Fatalities: _____ 0

Fire Department Response: Yes / No


Police Department Response: Yes / No

Ambulance Response: Yes / No

Additional Information/Comments: _____

1" plastic service severed by auger. No valid locate and not hand exposed.

Multiple horizontal lines for additional information or comments.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

NOW DUE


\$548.56

PAID

GLIDDEN FENCE INC
17808 SPRING MILL ROAD,
WESTFIELD, IN 46074

Type: GAS
Invoice: FDS0013530
BillToID: 29483
Billing Date: 1/19/2011
Date of Loss: 10/26/2010
5830 103.0510

Please return this portion with your remittance.



Mail Payment To: VECTREN ENERGY DELIVERY OF INDIANA - NORTH
Vectren Utilities Holding Group, Inc.
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE

\$548.56

GLIDDEN FENCE INC
17808 SPRING MILL ROAD,
WESTFIELD, IN 46074

Type: GAS
Invoice: FDS0013530
BillToID: 29483
Billing Date: 1/19/2011
Date of Loss: 10/26/2010

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 411 E 126TH STREET, CARMEL

1" PLASTIC SERVICE SEVERED BY AUGER. NO VALID LOCATE AND NOT HAND EXPOSED.

Material:	\$65.54
Company Labor:	\$325.78
Contract Labor:	\$0.00
Transportation/Equipment:	\$38.90
Misc:	\$0.00
Gas Loss:	\$118.34
Adjustments:	\$0.00
Payments:	\$0.00
<hr/> Total:	\$548.56

5830 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Vectren Corporation

Form 3112 (Rev. 10/04)

Indiana Gas

Sigeco

Vectren Energy Delivery of Ohio

Task No.: 103.0510

Capital / O&M (circle one)

FDS 0013530

TIME: 12:30 AM/PM

DATE OF DAMAGE: 10,26,10

EMERGS. Cost Center No.: 5830

DAMAGE SITE ADDRESS: 411 E. 126th LOCATE # 101 026 1456

LOT #: _____ CITY: CARMEL

FACILITIES DAMAGED

- MAIN
- SERVICE
- REGULATOR STATION
- FARM TAP
- RESIDENTIAL METER
- METER INDUSTRIAL/COMMERICAL
- OTHER _____

- SIZE(S)
- 0.50 INCH
 - 0.75 INCH
 - 1.00 INCH
 - 2.00 INCH
 - 4.00 INCH
 - 6.00 INCH
 - OTHER _____

TYPE OF MATERIAL

- PLASTIC
- STEEL
- CAST IRON
- OTHER _____

DAMAGE TYPE

- SEVERED
- NOT CUT
- PUNCTURE
- SIZE 1 X 1

PRESSURE

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 60 PSIG
- 6 WC
- OTHER _____

PROTECTION IN PLACE

- RAIL
- POST
- NONE
- N/A

LEAK REPORT

585835

DURATION OF ESCAPING GAS

MINUTES 35

ONE-WAY FEED

TWO-WAY FEED

DAMAGED BY

- CONTRACTOR
- MUNICIPALITY/UTILITY
- VEHICULAR ACCIDENT
- COMPANY CREW
- UNKNOWN
- PROPERTY OWNER/TENANT
- OTHER _____

TYPE OF CONSTRUCTION

- SEWER/DRAIN
- WATER
- ELECTRIC
- TELEPHONE
- CEMENT/PAVING
- TV CABLE
- FENCING
- FOOTERS
- OTHER _____

WORKING FOR

- CITY
- STATE
- PROPERTY OWNER
- OTHER _____

NAME _____

TYPE OF EQUIPMENT

- BACKHOE
- TRACKHOE
- PLOW
- TRENCHER
- BULLDOZER
- POSTHOLE DIGGERS
- BORE
- AUGER
- STAKE/SHOVEL
- OTHER _____

DAMAGING PARTY

- DID NOT REQUEST LOCATES
- DID NOT HAND DIG
- USED EXPIRED LOCATES
- OTHER _____

NUMBER OF CUSTOMERS AFFECTED: 1

TOTAL HOURS SERVICE WAS OFF: _____

INVOICE: YES NO

DAMAGING PARTY

NAME: Glidden Fence Co.

ADDRESS: P.O. Box 481

CITY/STATE/ZIP: Westfield IN. 46074

PREPARED BY: David Endicott DATE: 10/26/10

VISUAL OBSERVATION AT DAMAGE SITE

- LOCATE NOT APPLICABLE (Above Ground Damage Only)
- FACILITIES PROPERLY MARKED
- MARKING METHODS: CONVENTIONAL OFFSET
- FLAGS PAINT STAKES WHISKERS
- LOCATE MARKINGS FADED: YES NO
- WRONG ADDRESS REQUESTED
- FACILITIES IMPROPERLY LOCATED
- QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
- INACCURATE MAPS/CARDS
- BROKEN OR NO TRACER WIRE (PLASTIC)
- INSULATION PREVENTING ACCURATE LOCATE
- LOCATOR ERROR
- QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
- INCOMPLETE LOCATE
- MARKINGS OFF BY _____ (FEET/INCHES)
- INAPPROPRIATE SITE MARKINGS
- NO LOCATE PERFORMED
- FAILURE TO FOLLOW POLICY
- WRONG ADDRESS LOCATED

OBSERVATION BY: D. Endicott

NAME OF LOCATOR: _____

COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

NOTIFICATION AND OTHER DETAILS OF LOCATE

LOCATE TICKET #: 10 0924 0518 EXPIRED

DATE: _____ TIME: _____ AM/PM

REGULAR REQUEST EMERGENCY REQUEST

LOCATE COMPANY NOTIFIED

CONTACT NAME: _____

TIME CALLED: _____ AM/PM

TIME LOCATOR ARRIVED AT SITE: _____ AM/PM

COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES:

YES NO

CONTRACTOR REPAIRS

CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE

CONTRACTOR REPAIRED DAMAGE

NAME OF CONTRACTOR: _____

OF REGULAR HOURS _____

OF OVERTIME HOURS _____

CREW TYPE _____

MATERIALS OR ROAD WORK

METER WAS REPLACED _____ (STORES CODE)

REGULATOR WAS REPLACED _____ (STORES CODE)

TEMPORARY ASPHALT REPAIR _____ (SQ. FT.)

PERMANENT ASPHALT REPAIR _____ (SQ. FT.)

PARTY TO INVOICE

NAME: _____

ADDRESS: _____

CITY/STATE/ZIP: _____

REVIEWED BY FIELD SUPERVISOR: RJ Mathew DATE: 10-28-10

Friday, November 5, 2010

Service Order Status

Enter Service Order Number:

4604217



Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: N4604217

Order Type: LEAK

Order Status: Completed

Customer: 620916929 - BALIFF REBECCA A

Prem: 5453549 - 411 E 126TH ST

Technician: 2245 - Endicott, David

Order Dates and Times

Need Date: 10/26/2010 11:59:00 AM
Time Created: 10/26/2010 11:44:31 AM
Time Dispatched: 10/26/2010 11:44:31 AM
Time In Route: 10/26/2010 11:45:07 AM
Time On-Site: 10/26/2010 11:59:44 AM
Tech Complete: 10/26/2010 1:12:37 PM
Time Closed: 10/26/2010 1:12:37 PM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current Read Status

Old Meter: 1021 Inactive

New Meter:

Completion Notes

MADE SAFE---CO CREW ONSITE

Request Notes

WENDY GLIDDEN WITH GLIDDEN FENCE COMPANY CALLED TO REPORT THEY HAVE CUTAN LINE THAT IS BLOWING. XST RANGELINE CREW ONSITE // ONSITE CONTACT TED TURNE379-0178

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	10/26/2010 11:44:52 AM	Endicott, David
AsnAssignmentEnRoute_evt	10/26/2010 11:45:07 AM	Endicott, David
AsnAssignmentOnSite_evt	10/26/2010 11:59:44 AM	Endicott, David
OrdOrderComplete_evt	10/26/2010 1:12:37 PM	Endicott, David

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

NORMAL NOTICE

Ticket #: 1009240518 Date: 09/24/2010 Time: 08:44 Oper: CODOM Chan:016

State: IN Cnty: HAMILTON Twp: CLAY
 Cityname: CARMEL Inside: Y Near: N
 Subdivision:

Address : 411
 Street : E 126TH ST
 Cross 1 : S RANGELINE RD Within 1/4 mile: Y
 Location: LOCATE THE ENTIRE PROPERTY

Grids : 3958D8607D 3958C8607D 3958D8607C 3958C8607C

Work type : INSTALL FENCE
 Done for : REBECCA BALIFF
 Start date: 09/28/2010 Time: 09:00 Hours notice: 96/048 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 1 DAY Depth: .3 FEET

Company : GLIDDEN FENCE Type: CONT
 Co addr : 17808 SPRINGMILL ROAD
 City : WESTFIELD State: IN Zip: 46074
 Caller : WENDY GLIDDEN Phone: (317)867-5140
 Contact : WENDY GLIDDEN OFFICE Phone:
 BestTime:
 Mobile : (317)867-5140
 Email : MIKEWENDYPLUS3@AOL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? NO

Submitted date: 09/24/2010 Time: 08:44
 Members: ID0002 ID0103 ID0660 ID2400 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CARMEL UTILITIES	
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
VECTREN - NOBLESVILLE #1	GAS

[View Map](#) [Close Map](#)

13530
~~13530~~

Fact Based Investigation Report

NOTIFICATION ID: 01120101026004 DISTRICT: Central IN
DAMAGE DATE: 10/26/2010 11:32:00 AM NOTIFICATION DATE: 10/26/2010 11:41:03 AM
NOTIFIED BY: WENDY GLIDDEN One Call Center
DAMAGE ADDRESS: 411 E 126TH ST CARMEL
CITY: CLAY ST: IN ZIP:

DAMAGED CUSTOMER: VECTREN

INVESTIGATION DATE: 10/26/2010
FROM: 11:45:00 TO: 12:45:00

EXCAVATOR INVOLVED: GLIDDEN FENCE
TYPE OF EXCAVATION: electric pad install

ORIG. LOCATE REQ.: 1009240518 START DATE/TIME: 9/28/2010 9:00:00 AM
TYPE OF TICKET: Routine LOCATE REQ. INFO N/A:

DIG UP/DAMAGE REQ.: 1010261157 START DATE/TIME: 10/26/2010 11:00:00 AM

PICTURES TAKEN BY: John Roe DATE/TIME: 10/26/2010 12:00:00 PM
PHOTOGRAPHY TYPE: Digital FRAME #:

INVESTIGATOR EMP#: 121583 INVESTIGATOR NAME: John Roe
BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED? No

Fact Based Investigation Customer Information

NOTIFICATION ID: 01120101026004
SELECT A CUSTOMER: VECTREN
CUSTOMER #: (optional)

FACILITY DESCRIPTION: LOWPROF FACILITY ID: Gas Service
LOCATOR NAME & EMP #: Roe John - 121583
LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:
Facility Marked Accurately,
Old Request,
Relocate Needed

Other:

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):

Visual, Facility Exposed At Time Of Investigation

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

Locate is past due, right at a month old. However, when kicking leaves around found old marks on the service.

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

David E. Vectren

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

Ted, Glidden fence, didn't realize it was there, they should have recalled the ticket prior to him being there.

LIST ANY OTHER INDIVIDUALS ON SITE:

Carmel fire dept

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? Yes

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? No

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? Yes

EXTENT OF FACILITY DAMAGE sliced

REPLACEMENT FOOTAGE 4'

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No na

WHAT CONTRACTOR EQUIPMENT WAS USED? na

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? Yes

IF YES, PLEASE LIST RECORD #(S) service record

MISCELLANEOUS CASH RECEIPT

(PLEASE ATTACH A COPY OF ALL CHECKS TO THIS FORM AND
USE PAPER CLIPS/DO NOT STAPLE CHECKS TO FORM)

PROCESS ROUTING FOR ALL VECTREN COMPANIES INCLUDING UTILITIES
AND NON REGULATED SUBSIDIARIES: SEND COMPLETED FORM,
ORIGINAL CHECK AND COPY OF CHECK TO REBECCA MINEAR IN
FINANCIAL ACCOUNTING, BRAUN BUILDING, EVANSVILLE. RETAIN COPY
OF CHECK AND FORM FOR YOUR RECORDS. PLEASE INCLUDE PROPER
ACCOUNTING SO RECEIPT MAY BE CREDITED ACCURATELY. PLEASE
INCLUDE YOUR PHONE NUMBER SO THE RECEIPT MAY BE EASILY
RESEARCHED BY THE FINANCIAL ACCOUNTING GROUP.

Activity Date: **1/25/2011**
12:00:00 AM

Your Name, not your initials (employee): **Pam Barber**

Your Phone Number (employee): **812-491-4734**

Party Check Received From (Check Payor):

Address of Check Writer (Check Payor):

BATCH1-GLIDDEN FENCE CO INC

Check Number **23641**

Amount of Check **\$548.56**

Utility/Company Name **VECTREN ENERGY DELIVERY OF INDIANA - NORTH**

Task Number **103.0510**

Job Number **FDS0013530**

Date Printed: 1/27/2011

Transaction Information G-6628350 CHI-861239 2011/01/25

[Back to Table of Contents](#)

Transaction Level Details

Env Num	3	Envelope	G-6628350
Transaction	G-6628350	Lockbox	CHI-861239
Date	2011/01/25	Time	17:00
Batch	1	Batch Item	3
Check	3	Amount	\$548.56
ABA/RT	074905380	Account Num	00085383
Check Num	023641		

Envelope and Check Image

GLIDDEN FENCE CO., INC. (317) 844-5657 (317) 896-3941 P.O. BOX 481 WESTFIELD, IN 46074		EXPLANATION #FDSC0013530	AMOUNT 23641	71-538/749 23641
PAY AMOUNT OF \$ 548.56	Five Hundred Forty-Eight and 56/100 XX		DOLLARS CHECK NUMBER 23641	CHECK AMOUNT \$ 548.56
DATE 1-21-11	TO THE ORDER OF Vectren Energy of Ind.-North	DESCRIPTION wire loss	GLIDDEN FENCE CO., INC.	
COMMUNITY BANK Serving the Ten Most Major Counties		BY: <i>W. J. Glidden</i>		
⑈023641⑈ ⑆074905380⑆ 0008⑈538⑈3⑈				


YOUR ADDRESS P.O. Box 481 Westfield, IN 46074	INDIANAPOLIS IN 462 12 JAN 2011 PM 5 T	
Vectren Utilities Holding Group, Inc. 1239 Reliable Parkway Chicago, IL 60686-0012		
60686+0012		

Transaction Level Keyed Data

Remitter Name : GLIDDEN FENCE CO INC Check Date : 2011/01/21

Invoice Level Keyed Data

Invoice Number	Reference Number
FDS0013530	29483

 2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH	NOW DUE \$548.56
GLIDDEN FENCE INC 17808 SPRING MILL ROAD, WESTFIELD, IN 46074	Type: GAS Invoice: FDS0013530 BillToID: 29483 Billing Date: 1/19/2011 Date of Loss: 10/26/2010 5830 103.0510
<small>Please return this portion with your remittance.</small>	

Pipeline DamageCase@urc.in.gov Information Request

Case No. 1297

**Pipeline Safety Division
Indiana Utility Regulatory Commission**

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: *GLIDDEN Fence Co., Inc.*

Responsible Party Personal Name: *W. T. Glidden, Sr.*

Title (if any): *President*

Address: *17808 Springmill Road*

City, State Zip: *Westfield, In. 46074*

Preferred Telephone: *317-~~867~~867-5140 Contractor phone#*

Cell Phone Number: *317-695-3400*

Email Address: *wtg51@aol.com*

Facility Information:

Business Name: *Vectren Energy Delivery of INDIANA - North*

Responsible Party Personal Name:

Title (if any):

City, State, Zip

Address:

Preferred Telephone:

Cell Phone Number:

Email Address:

Locator Service Information:

Business Name:

Responsible Party Personal Name:

Title (if any):

Address:

City, State Zip:

Preferred Telephone:

Cell Phone Number:

Email Address:

Other (Witness, Police, Fire, Other) Information:

Personal Contact:

Business/Organization Name:

Title (if any)

Address:

City, State, Zip

Preferred Telephone:

Cell Phone Number:

Email Address:

Utility Line Impact:

Product Type (circle one):

Natural Gas

Liquid Pipeline

Unknown/Other

Facility Type (circle one):

Distribution

Gathering

Service/Drop

Transmission

Unknown/Other

Size (Diameter/etc.): 1"

Pressure (PSIG/Inches): _____

Interruption in Service: Yes / No

Number of Customers Affected: one

Evacuation: Yes No If yes, How Many Evacuated? _____

Repair Cost (if known): \$ 548.56

Cause of Damage Information:

Type of Equipment (circle one):

Auger

Backhoe/Trackhoe

Boring /Drilling

Directional Drilling

Explosives

Farm Equipment

Grader/Scraper

Hand Tools

Milling Equipment

Probing Device

Trencher

Vacuum Equipment

Unknown/Other

Type of Work Performed (circle one):

- Agriculture
- Cable TV
- Curb/Sidewalk
- Bldg. Construction
- Bldg. Demolition
- Drainage
- Driveway
- Electric
- Engineering/Surveying
- Fencing**
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Natural Gas
- Pole
- Public Transit Authority
- Railroad Maintenance
- Road Work
- Sewer (Sanitary/Storm)
- Site Development
- Steam
- Storm Drain/Culvert
- Street Light
- Telecommunications
- Traffic Signal
- Traffic Sign
- Water
- Waterway Improvement
- Unknown/Other

— PAD FOR ELECTRIC GATE OPERATOR

- Release of Product: Yes / No
- Ignition and/or Fire: Yes / No
- Excavator Notify 811: Yes / No

Locate Information:

- Excavator Request Locate: Yes / No
- Indiana 811 Locate Ticket Number: 10-0924-0518 e' 10-1022-1736
- Locate Marks Visible: Yes / No
- Locate Marks Correct: Yes / No
- Excavator "White Lined": Yes / No
- Maps Used to Mark Facilities: Yes / No

Was Locate Provided within Two (2) Working Days: Yes/No

Operator Employees On-site during Excavation: Yes/No

Incident Impact Information:

Number of Outpatient Treated: 0

Number of Inpatient Treated: 0

Number of Fatalities: 0

Fire Department Response: Yes/No

Police Department Response: Yes/No

Ambulance Response: Yes/No

Additional Information/Comments: Glidden Fence Co, Inc. co-mingled with Ashpaugh Electric, Inc. (317) 896-2605 on phase II of this contract.

First locate request #10-0924-0518 was for setting fence posts and was completed 10-6-2010 without incident.

Second locate request #10-1022-1736 was called in by Ashpaugh Electric, Inc. for electric hard wire to fence lines where electric gate was to be located.

Glidden Fence Co, Inc. crew hit gas line on 10-26-10 excavating pad for operator. Respondent immediately notified 811 & fire department.

Vestren responded with repair crew and repaired 1" line which respondent had excavated @ 21" depth to allow for quick repair.

Glidden fence crew moved operator pad location to the south to avoid gas line and finished pad installation.

G.F.I. (respondent) paid for repairs upon receiving repair invoice - copy enclosed.

Glidden fence Co, Inc. has been in business for 35 years at same location & with same phone #. Glidden fence Co, Inc. calls at least one thousand locates every year and tries to comply with all rules & regulations.

Sincerely
W. J. Glidden, President

9.29.2011



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

Case No. 1297

NOW DUE

\$548.56

GLIDDEN FENCE INC
17808 SPRING MILL ROAD,
WESTFIELD, IN 46074

Type: GAS
Invoice: FDS0013530
BillToID: 29483
Billing Date: 1/19/2011
Date of Loss: 10/26/2010
5830 103.0510

RECORD OF PAYMENT OR
EMPLOYEE PAY STATEMENT

FDS0013530

PAY PERIOD FROM _____ TO _____
RATE OF PAY _____

Five Hundred Forty-Eight and 56/100 XX

DATE	TO THE ORDER OF	GROSS	INCOME TAX	SOC. SEC.	STATE TAX	CHECK NUMBER	NET AMOUNT	T W
11-11	Vectren Energy of Ind.-North					23641	548.56	
		DESCRIPTION						

W. J. Glidden
NON NEGOTIABLE

SHIELD GUARD BUSINESS SYSTEMS, INC.
Form No. DUP NCR 14

Material:	\$65.54
Company Labor:	\$325.78
Contract Labor:	\$0.00
Transportation/Equipment:	\$38.90
Misc:	\$0.00
Gas Loss:	\$118.34
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$548.56

5830 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.