



Pipeline Safety Division Investigation Report

Investigation regarding: **Dan Cristiani Excavating**

UPPAC Database Record ID: 1810

Investigator: Howard Friend

Report Date: 04/30/2012

Damage Date: 03/28/2011 10:47:47 AM

Damage Address: 2519 Coopers Ln

City: Jeffersonville

County: Clark

The Parties

Excavator: **Dan Cristiani Excavating**

Contact: Barton R O'leary, Safety Director

Address: 1221 Old Highway 31 East, Clarksville, In 47129

Telephone: (812) 282-9866

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Dan Cristiani Excavating

UPPAC Database Record ID: 1810

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$779

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1103180495

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Sewer (Sanitary/Storm)

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 02/13/2012. Excavator was removing street asphalt for sewer excavation when gas service was damaged. The service was directly under the asphalt; excavator submitted that there was no possibility of exposing the service. Excavator failed to maintain required clearance from the gas service.

Conclusion: Excavator failed to maintain the required clearance with mechanized equipment.

Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.

Dan Cristiani Excavating currently has 6 reports of damages in the record, between 03/28/2011 10:47:47 AM and 03/13/2012 10:55:49 AM.

NO

LOCATE


TICKET

PROVIDED



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION



Submitted to IURC-Pipeline Safety on: 02-17-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Dan Cristiani Excavating

Business address (*number and street*): 1221 Old Hwy 31 E,

City, State, and ZIP code: Clarksville, IN 47129

Telephone number (*area code*): 812-282-9866

Fax number (*area code*): 812-282-9908

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Sewer (Sanitary/Storm)

Date and Location of Damage

Date of damage (month, day, year): 3-28-2011

County: Clark

City: Sellersburg

Street address (number and street, city, state, and ZIP code):
2519 Coopers Lane, Sellersburg, IN

Nearest intersection: Unknown

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours): 2

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 778.7

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1103180495

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Other

If other, please specify: None

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes


Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

Additional Comments

3/4" steel service severed by trackhoe. Not hand exposed.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

PAID


NOW DUE

\$778.70

DAN CHRISTIANI EXCAVATING
1221 OLD HIGHWAY 31
CLARKSVILLE, IN 47129

Type: GAS
Invoice: FDS0014067
BillToID: 30035
Billing Date: 6/2/2011
Date of Loss: 3/28/2011
5920 103.0510

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holding Corp.
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

DAN CHRISTIANI EXCAVATING
1221 OLD HIGHWAY 31
CLARKSVILLE, IN 47129

Type: GAS
Invoice: FDS0014067
BillToID: 30035
Billing Date: 6/2/2011
Date of Loss: 3/28/2011

NOW DUE

\$778.70

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 2519 COPPERS LANE, SELLERSBURG

1" STEEL SERVICE DAMAGED BY TRACKHOE. NOT HAND EXPOSED.

Material:	\$44.36
Company Labor:	\$101.49
Contract Labor:	\$481.88
Transportation/Equipment:	\$16.96
Misc:	\$0.00
Gas Loss:	\$134.01
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$778.70

5920 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Vectren Corporation
Form 3112 (Rev. 10/04)

- Indiana Gas
- Sigeco
- Vectren Energy Delivery of Ohio

Task No.: 00103

Capital / O&M (circle one)

FDS 0014067

TIME: 1145 (AM/PM)

DATE OF DAMAGE: 3/28/11

Cost Center No.: 5921

DAMAGE SITE ADDRESS: 2519 Coopers LN

LOT #: _____ CITY: Sellersburg

FACILITIES DAMAGED

- MAIN
- SERVICE
- REGULATOR STATION
- FARM TAP
- RESIDENTIAL METER
- METER INDUSTRIAL/COMMERCIAL
- OTHER

- SIZE(S)
- 0.50 INCH
 - 0.75 INCH
 - 1.00 INCH
 - 2.00 INCH
 - 4.00 INCH
 - 6.00 INCH
 - OTHER

TYPE OF MATERIAL

- PLASTIC
- STEEL
- CAST IRON
- OTHER

DAMAGE TYPE

- SEVERED
- NOT CUT
- PUNCTURE
- SIZE 3/8" X 3/8"
1/2" X 1/2"

PRESSURE

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 60 PSIG
- 6 WC
- OTHER

PROTECTION IN PLACE

- RAIL
- POST
- NONE
- N/A

LEAK REPORT

- # 619408
- ONE-WAY FEED
- TWO-WAY FEED

DURATION OF ESCAPING GAS

- MINUTES 1 hour
- EFV ACTIVATED YES NO

DAMAGED BY

- CONTRACTOR
- MUNICIPALITY/UTILITY
- VEHICULAR ACCIDENT
- COMPANY CREW
- UNKNOWN
- PROPERTY OWNER/TENANT
- OTHER

TYPE OF CONSTRUCTION

- SEWER/DRAIN
- WATER
- ELECTRIC
- TELEPHONE
- CEMENT/PAVING
- TV CABLE
- FENCING
- FOOTERS
- OTHER

WORKING FOR

- CITY
- STATE
- PROPERTY OWNER
- OTHER

TYPE OF EQUIPMENT

- BACKHOE
- TRACKHOE
- PLOW
- TRENCHER
- BULLDOZER
- POSTHOLE DIGGERS
- BORE
- AUGER
- STAKE/SHOVEL
- OTHER

DAMAGING PARTY

- DID NOT REQUEST LOCATES
- DID NOT HAND DIG
- USED EXPIRED LOCATES
- OTHER

NUMBER OF CUSTOMERS AFFECTED: 1

TOTAL HOURS SERVICE WAS OFF: _____

INVOICE: YES NO

DAMAGING PARTY

NAME: Dan Christiani excavating

ADDRESS: 1221 Old Hwy 31

CITY/STATE/ZIP: Clarksville, IN 47129

PREPARED BY: Kevin Vissing DATE: 3-28-11

VISUAL OBSERVATION AT DAMAGE SITE

- LOCATE NOT APPLICABLE (Above Ground Damage Only)
- FACILITIES PROPERLY MARKED
- MARKING METHODS: CONVENTIONAL OFFSET
- FLAGS PAINT STAKES WHISKERS
- LOCATE MARKINGS FADED: YES NO
- WRONG ADDRESS REQUESTED
- FACILITIES IMPROPERLY LOCATED
- QUALIFIED LOCATOR COULD NOT HAVE ACCURATELY LOCATED
- INACCURATE MAPS/CARDS
- BROKEN OR NO TRACER WIRE (PLASTIC)
- INSULATION PREVENTING ACCURATE LOCATE
- LOCATOR ERROR
- QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
- INCOMPLETE LOCATE
- MARKINGS OFF BY _____ (FEET/INCHES)
- INAPPROPRIATE SITE MARKINGS
- NO LOCATE PERFORMED
- FAILURE TO FOLLOW POLICY
- WRONG ADDRESS LOCATED

OBSERVATION BY: Kevin Vissing

NAME OF LOCATOR: _____

- COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

NOTIFICATION AND OTHER DETAILS OF LOCATE

- LOCATE TICKET #: 1103180495
- DATE: 3-18-11 TIME: _____ AM/PM
- REGULAR REQUEST EMERGENCY REQUEST
- LOCATE COMPANY NOTIFIED
- CONTACT NAME: _____
- TIME CALLED: _____ AM/PM
- TIME LOCATOR ARRIVED AT SITE: _____ AM/PM
- COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES: YES NO

CONTRACTOR REPAIRS

- CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
- CONTRACTOR REPAIRED DAMAGE

NAME OF CONTRACTOR: _____

OF REGULAR HOURS: _____

OF OVERTIME HOURS: _____

CREW TYPE: _____

MATERIALS OR ROAD WORK

- METER WAS REPLACED _____ (STORES CODE)
- REGULATOR WAS REPLACED _____ (STORES CODE)
- TEMPORARY ASPHALT REPAIR _____ (SQ. FT.)
- PERMANENT ASPHALT REPAIR _____ (SQ. FT.)

PARTY TO INVOICE

NAME: Dan Christiani Excavating

ADDRESS: 1221 Old Hwy 31

CITY/STATE/ZIP: Clarksville, IN 47129

REVIEWED BY FIELD SUPERVISOR _____ DATE _____

INCLUDE ANY OBSERVATIONS ON BACK OF FORM

Loc #

1103282065
For multipipeline

NORMAL NOTICE REMARK

Ticket : 1103180495 Date: 03/18/2011 Time: 09:23 Oper: JUDY.JONAS Chan:000
 Old Tkt: 1103041174 Date: 03/04/2011 Time: 13:09 Oper: JUDY.JONAS Rev: 00A

State: IN Cnty: CLARK Twp: JEFFERSONVILLE
 Cityname: JEFFERSONVILLE Inside: Y Near: N
 Subdivision:

Address : 2519
 Street : COOPERS LN
 Cross 1 : GRAVES DRIVE Within 1/4 mile: N
 Location: LOCATE FRONT OF LOTS 2519 2605 2623
 :
 Grids : 3820C8544B 3820B8544B 3820C8544A 3820B8544A

Work type : SEWERS
 Done for : DAN CRISTIANI
 Start date: 03/22/2011 Time: 09:45 Hours notice: 96/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : UNKNOWN Depth: 20 FEET

Company : DAN CRISTIANI EXCAVATING Type: CONT
 Co addr : 1221 OLD HIGHWAY 31 EAST
 City : CLARKSVILLE State: IN Zip: 47129
 Caller : JUDY JONAS Phone: (812)282-9866
 Contact : DANNY CRISTIANI Phone:
 BestTime:
 Mobile : (502)376-0105
 Fax : (812)282-9908

Remarks : All tickets are taken and processed on Eastern Daylight Time
 REMARK AS NEEDED
 Will you be white-lining the dig site area? NO
 :

Submitted date: 03/18/2011 Time: 09:23
 Members: ID0002 ID0340 ID4866 ID5693 ID6451 ID7053 ID7714 ID8203 ID8233 ID8401
 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
AT&T - TRANSMISSION	FIBER OPTIC
CLARKSVILLE STORMWATER DEPARTMENT	
CLARKSVILLE WASTEWATER	
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
IN AMERICAN WATER SOUTHERN INDIANA	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
JEFFERSONVILLE WASTEWATER AND SEWER	
QWEST COMMUNICATIONS	FIBER OPTIC
VECTREN - CLARKSVILLE	GAS
ZAYO BANDWIDTH	FIBER OPTIC

[View Map](#) | [Close Map](#)

Service Order Status

Sunday, February 5, 2012

Enter Service Order Number:

4756642



Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: N4756642

Order Type: LEAK

Order Status: Completed

Customer: 600312588 - SHUCK JOHN F

Prem: 5257450 - 2519 COOPERS LN

Technician: 2722 - Vissing, Kevin

Order Dates and Times

Need Date: 3/28/2011 11:01:00 AM
Time Created: 3/28/2011 10:48:35 AM
Time Dispatched: 3/28/2011 10:48:36 AM
Time In Route: 3/28/2011 10:52:01 AM
Time On-Site: 3/28/2011 11:03:41 AM
Tech Complete: 3/28/2011 12:38:20 PM
Time Closed: 3/28/2011 12:38:20 PM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current Read Status

Old Meter: 9505 Inactive

New Meter:

Completion Notes

service hit and blew until millerr pipeline screwed in tap. they are here to rep air. meter locked off and cust advised to call in when he gets back home later.

Request Notes

PER JUDY JONES WITH DAN CHRISTIANA EXC/PH 812 282 9866/REP HIT LINE/WAS BLOWINSTEEL LINE/NO INFO ON ENTERING BUILDING/LOC#1103180495/XST: GRAVES/CONTON SITE DAN CRISTIANI/502 376 0105/GAVE PRECAUTIONS

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	3/28/2011 10:50:43 AM	Vissing, Kevin
AsnAssignmentEnRoute_evt	3/28/2011 10:52:01 AM	Vissing, Kevin
AsnAssignmentOnSite_evt	3/28/2011 11:03:41 AM	Vissing, Kevin
OrdOrderComplete_evt	3/28/2011 12:38:20 PM	Vissing, Kevin

NOTE:The Reporting database replicates in near real-time; it has been approximately 1 minute(s) since the last transaction replicated.

DAMAGE DAMAGE

Ticket : 1103281298 Date: 03/28/2011 Time: 10:45 Oper: LPORTER Chan:046

State: IN Cnty: CLARK Twp: JEFFERSONVILLE
 Cityname: JEFFERSONVILLE Inside: Y Near: N
 Subdivision:

Address : 2519
 Street : COOPERS LN
 Cross 1 : GRAVES DRIVE Within 1/4 mile: N
 Location: LOCATE FRONT OF LOTS 2519 2605 2623
 :
 Grids : 3820C8544B 3820B8544B 3820C8544A 3820B8544A

Work type : SEWERS
 Done for : DAN CRISTIANI
 Start date: 03/28/2011 Time: 10:46 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : UNKNOWN Depth: 20 FEET


Company : DAN CRISTIANI EXCAVATING Type: CONT
 Co addr : 1221 OLD HIGHWAY 31 EAST
 City : CLARKSVILLE State: IN Zip: 47129
 Caller : JUDY JONAS Phone: (812)282-9866
 Contact : DANNY CRISTIANI Phone:
 BestTime:
 Mobile : (502)468-8097
 Fax : (812)282-9908

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PER JUDY JONAS - HIT A VECTREN GAS LINE - LINE SMALL THREE QUARTER INCH SERVICE
 LINE - DIGGING IN FRONT OF 2519 COOPERS LN - CREW STILL ON SITE - GAS NOT
 BLOWING HAS PINCHED OFF - JUDY HAS CONTACTED VECTREN - -PREVIOUS TICKET
 1103180495
 Will you be white-lining the dig site area? NO
 :


Submitted date: 03/28/2011 Time: 10:45
 Members: ID0002 ID0340 ID4866 ID5693 ID6451 ID7053 ID7714 ID8203 ID8233 ID8401
 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
AT&T - TRANSMISSION	FIBER OPTIC
CLARKSVILLE STORMWATER DEPARTMENT	
CLARKSVILLE WASTEWATER	
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
IN AMERICAN WATER SOUTHERN INDIANA	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
JEFFERSONVILLE WASTEWATER AND SEWER	
QWEST COMMUNICATIONS	FIBER OPTIC
VECTREN - CLARKSVILLE	GAS
ZAYO BANDWIDTH	FIBER OPTIC

[View Map](#) | [Close Map](#)



Property of United States Infrastructure Corporation
Photo taken on 3/28/2011 12:10:28 PM



Property of United States Infrastructure Corporation
Photo taken on 3/28/2011 12:10:50 PM



Property of United States Infrastructure Corporation
Photo taken on 3/28/2011 12:12:22 PM

MISCELLANEOUS CASH RECEIPT

(PLEASE ATTACH A COPY OF ALL CHECKS TO THIS FORM AND
USE PAPER CLIPS/DO NOT STAPLE CHECKS TO FORM)

PROCESS ROUTING FOR ALL VECTREN COMPANIES INCLUDING UTILITIES
AND NON REGULATED SUBSIDIARIES: SEND COMPLETED FORM,
ORIGINAL CHECK AND COPY OF CHECK TO REBECCA MINEAR IN
FINANCIAL ACCOUNTING, BRAUN BUILDING, EVANSVILLE. RETAIN COPY
OF CHECK AND FORM FOR YOUR RECORDS. PLEASE INCLUDE PROPER
ACCOUNTING SO RECEIPT MAY BE CREDITED ACCURATELY. PLEASE
INCLUDE YOUR PHONE NUMBER SO THE RECEIPT MAY BE EASILY
RESEARCHED BY THE FINANCIAL ACCOUNTING GROUP.

Activity Date: **6/13/2011
12:00:00 AM**

Your Name, not your initials (employee): **Pam Barber**

Your Phone Number (employee): **812-491-4734**

Party Check Received From (Check Payor):

Address of Check Writer (Check Payor):

BATCH2-DAN CRUSTUABU EXCAVATING CO INC

Check Number **54122**

Amount of Check **\$778.70**

Utility/Company Name **VECTREN ENERGY DELIVERY OF INDIANA - NORTH**

Task Number **103.0510**

Job Number **FDS0014067**

Date Printed: 6/14/2011



Transaction Information G-6160069 CHI-861239 2011/06/13

[Back to Table of Contents](#)

Transaction Level Details

Env Num	5	Envelope	G-6160069
Transaction	G-6160069	Lockbox	CHI-861239
Date	2011/06/13	Time	17:00
Batch	2	Batch Item	3
Check	5	Amount	\$778.70
ABA/RT	083000920	Account Num	05116299
Check Num	054122		

Envelope and Check Image




Transaction Level Keyed Data

Remitter Name : DAN CRUSTUABU EXCAVATING CO INC Check Date : 2011/06/08

Invoice Level Keyed Data

Invoice Number	Reference Number
FDS0014067	30035

DAN CRISTIANI EXCAVATING CO., INC. CLARKSVILLE, IN 47131-2427				054122		
Vectren Energy Delivery of IN North 1239 Reliable Parkway Chicago, IL 40686-0012				Check: 54122 Date: 6/8/2011 Vendor: VECTRENE		
<u>Invoice</u>	<u>P.O. Num.</u>	<u>Invoice Amt</u>	<u>Prior Balance</u>	<u>Retention</u>	<u>Discount</u>	<u>Amt. Paid</u>
FDS0014067		778.70	778.70	0.00	0.00	778.70
		<u>778.70</u>	<u>778.70</u>	<u>0.00</u>	<u>0.00</u>	<u>778.70</u>

	2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH	NOW DUE \$778.70
DAN CHRISTIANI EXCAVATING 1221 OLD HIGHWAY 31 CLARKSVILLE, IN 47129		Type: GAS Invoice: FDS0014067 BillToID: 30035 Billing Date: 6/2/2011 Date of Loss: 3/28/2011 5920 103.0510
Please return this portion with your remittance.		

Information Request
Pipeline Safety Division
Indiana Utility Regulatory Commission

RECEIVED

FEB 13 2012

INDIANA UTILITY REGULATORY COMMISSION

Case No. 1810

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Information:

Business Name: Dan Cristiani Excavating Co., Inc.

Responsible Party Personal Name: Bart O'Leary

Title (if any): Safety Director

Address: 1221 Old Hwy 31E

City, State Zip: Clarksville, IN 47129

Preferred Telephone: (812) 282-9866

Cell Phone Number: (502) 664-3661

Email Address: bart@dcexc.com

Facility Information:

Business Name:

Responsible Party Personal Name:

Title (if any):

Address:

City, State, Zip:

Preferred Telephone:

Cell Phone Number:

Email Address:

Locator Service Information:

Business Name: USIC

Responsible Party Personal Name:

Title (if any):

Address: 9045 N River Road, Suite 300

City, State Zip: Indianapolis, IN 46240

Preferred Telephone: (317) 575-7800

Cell Phone Number:

Email Address:

Other (Witness, Police, Fire, Other) Information:

Personal Contact:

Business/Organization Name:

Title (if any)

Address:

City, State, Zip:

Preferred Telephone:

Cell Phone Number:

Email Address:

Utility Line Impact:

Location of Damage:

Address: 2519 Coopers Lane

City, State Zip: Jeffersonville, IN 47130

Nearest Intersection: Hamburg Pike

Product Type (circle one):

Natural Gas

Liquid Pipeline

Unknown/Other

Facility Type (circle one):

Distribution

Gathering

Service/Drop

Transmission

Unknown/Other

Size (Diameter/etc.): 3/4 inch

Pressure (PSIG/Inches): _____

Interruption in Service: Yes / No

Number of Customers Affected: 1

Evacuation: Yes / No If yes, How Many Evacuated? _____

Repair Cost (if known): \$ _____

Cause of Damage Information:

Type of Equipment (circle one):

Auger

Backhoe/Trackhoe

Boring /Drilling

Directional Drilling

Explosives

Farm Equipment

Grader/Scraper

Hand Tools

Milling Equipment

Probing Device

Trencher

Vacuum Equipment

Unknown/Other

Type of Work Performed (circle one):

Agriculture

Cable TV

Curb/Sidewalk

Bldg. Construction

Bldg. Demolition

Drainage

Driveway

Electric

Engineering/Surveying

Fencing

Grading

Irrigation

Landscaping

Liquid Pipeline

Milling

Natural Gas

Pole

Public Transit Authority

Railroad Maintenance

Road Work

Sewer (Sanitary/Storm)

Site Development

Steam

Storm Drain/Culvert

Street Light

Telecommunications

Traffic Signal

Traffic Sign

Water

Waterway Improvement

Unknown/Other

Release of Product: Yes / No

Ignition and/or Fire: Yes / No

Excavator Notify 811: Yes / No

Locate Information:

Excavator Request Locate: Yes / No

Indiana 811 Locate Ticket Number: 1103180495

Locate Marks Visible: Yes / No

Locate Marks Correct: Yes / No

Excavator "White Lined": Yes / No

Maps Used to Mark Facilities: Yes / No

Was Locate Provided within Two (2) Working Days: Yes / No

Operator Employees On-site during Excavation: Yes / No

Incident Impact Information:

Number of Outpatient Treated: N/A

Number of Inpatient Treated: N/A

Number of Fatalities: N/A

Fire Department Response: Yes / No

Police Department Response: Yes / No

Ambulance Response: Yes / No

Additional Information/Comments:

2519 Coopers Lane

On 3/28/11 Dan Cristiani Excavating Co., Inc. was installing sewer pipe on Coopers Lane. The sewer line that was being installed was down the middle Coopers Lane. The asphalt was cut and the operator was removing it when he struck the gas service line. The service line was directly underneath the asphalt. There was no way to hand dig and locate the line until the asphalt was removed.

White lining was not needed because the addresses and specific locations for excavation were given to the locating company. This was also noted on the locate ticket that was called in for this location. Locates were called in for this location on 3/4/11 and updated throughout this Coopers Lane project.

YOUR PIPELINE SAFETY DIVISION CASE NO. 1810

YOUR FULL NAME: Barton R. O'Leary

FULL NAME OF BUSINESS/ENTITY (if applicable): Dan Cristiani Excavating Co., Inc.

YOUR BUSINESS TITLE (if applicable): Safety Director

ADDRESS: 1221 Old Hwy 31E

CITY: Clarksville STATE: IN ZIP CODE: 47129

YOUR TELEPHONE NUMBER: (812) 282 - 9866 SECOND NO. (502) 664 - 3661

YOUR EMAIL ADDRESS: bart@dcexc.com

TODAY'S DATE: 2/13/12

YOUR SIGNATURE:  TITLE (if any) Safety Director

Please return your Narrative Statement and Answers to the above questions to:

**Pipeline Safety Division – Case No. 1810
Indiana Utility Regulatory Commission
101 West Washington Street, # 1500E
Indianapolis, IN 46204**

Or scan document(s) and Email to:

PipelineDamageCase@urc.in.gov



SUMMARY OF PROCEDURES
AND
RESPONDENT'S RIGHTS

INDIANA DAMAGE TO UNDERGROUND FACILITIES ACT
I.C. 8-1-26

Note: The following is offered for informational purposes and does not constitute legal advice. Anyone involved in this process is entitled to individual legal representation and should retain their own counsel in order preserve their rights.

- Any person or entity may report a violation of the Indiana Damage to Underground Facilities Act ("Act") to the Indiana Utility Regulatory Commission Pipeline Safety Division ("Pipeline Division"), but most reports of violations are communicated regularly to the Pipeline Division from the Indiana Plant Underground Protection Service, commonly referred to as the 811 Association Office; 170 IAC 5-5-2 (a);
- Violations are to be reported to the Pipeline Division within thirty 30 days of their occurrence; 170 IAC 5-5-2 (b);
- The Pipeline Division shall commence an investigation of each report by contacting all known persons or entities involved by sending a written request for information within 60 days; 170 IAC 5-5-3 (a);

You have been contacted and have this current opportunity to present written evidence (documents, photographs, maps, drawings, narrative statements or whatever written materials you want to submit) for the Pipeline Division's investigation of the incident in which you were allegedly involved. If you know of additional interested persons, entities or witnesses that you think should be contacted, you must immediately provide their name, address, telephone number and email address in writing to: Pipeline Safety Division, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Be sure to include your Investigation Number on your correspondence. You may also provide your information electronically to: PipelineDamageCase@urc.in.gov

Underground Plant Protection Advisory Committee, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204 or: PipelineDamageCase@urc.in.gov Be sure to include the Pipeline Division Case Number on your materials.

- The Commission will provide the Respondent with a copy of the Advisory Committee's recommendation, if any, for a civil penalty; 170 IAC 5-5-3 (f); civil penalties are defined in the Act; they are: "(1) Civil penalties consistent with this chapter. (2) Participation in education or training programs developed and implemented by the commission. (3) Warning letters. (4) Development of a plan to avoid future violations of this chapter."; I.C. 8-1-26-23 (h)

You are entitled to receive a copy of the Advisory Committee's advisory recommendation of a civil penalty to the Commission. Potential civil penalties are limited to: a warning letter, civil penalty up to \$10,000.00, a requirement of participation in an education and training program, a development plan to avoid future violations of the Act.

- The Respondent has 30 days to request in writing for a public hearing before the Commission to appeal the Advisory Committee's civil penalty recommendation; 170 IAC 5-5-3 (f) and (g);

If you disagree with the Advisory Committee's recommended civil penalty to the Commission, you have the right to a full-fledged hearing before the Commission. In order to preserve your right to a hearing, you must file a written request for such a hearing with the Commission Secretary, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Be sure to include your Case Number with your request. Such a request for a hearing must be filed within 30 days of the date of the Advisory Committee's recommendation. Appeal requests to the Commission will be dated upon their receipt by the Commission.

- If the Respondent requests a public hearing before the Commission to contest the Advisory Committee's recommendation for a civil penalty, the parties are required to comply with the formal rules of practice and procedure of the Commission; 170 IAC 5-5-3 (i);

There are formal procedures required by law to be followed regarding all proceedings pending before the Commission. For instance, corporations and some business entities are required to be represented by an attorney admitted to practice law in Indiana.

- The Commission's formal rules of practice and procedure are specified in "Rule 1.1 Practice and Procedure Before the Commission"; 170 IAC 1-1.1-1.

The formal procedures required to be followed in Commission proceedings are specified in the Indiana Administrative Code and may be found at 170 IAC 1-1.1-1. It may be advisable to seek the advice or representation by an attorney.

- If a monetary civil penalty is imposed by the Commission, Respondents must make payment within 90 days of being assessed to the Commission; 170 IAC 5-5-3 (j);

ACCIDENT WORKMAN'S COMP
AND PROPERTY DAMAGE REPORT

NAME David Nichols PHONE _____

TYPE OF INCIDENT Gas line

DATE OF INCIDENT 3/28/11 TIME OF INCIDENT 10:40 a.m.

TIME UTILITY ON SITE 11:02 a.m. TIME UTILITY SECURED 11:57 a.m.

VEHICLE/EQUIPMENT INVOLVED E-39

JOB NUMBER _____ PERSONAL INJURY Y

IF YES, EXPLAIN _____

DESCRIPTION OF INCIDENT Operator was digging up road to install sewer line. Operator was pulling up a piece of asphalt when hit the gas line below it. Gas line was marked, but directly below the road. Line appears to have been repaired before.

LOCATION OF INCIDENT 2519 Cooper's Ln

OPERATOR _____ SUPERVISOR _____

POLICE/FIRE NOTIFIED Y DEPARTMENT _____

MEDICAL TREATMENT REQUIRED Y FACILITY _____

EMPLOYEE SIGNATURE David Nichols DATE 3/28/11
Safety Director



2011 3 28



2011 3 28



2011 3 28



2011 3 28

CASE No: 1810

NORMAL NOTICE

Ticket : 1103041174 Date: 03/04/2011 Time: 01:09 Oper: JUDY.JONAS Chan:000

State: IN Cnty: CLARK Twp: JEFFERSONVILLE
 Cityname: JEFFERSONVILLE Inside: Y Near: N
 Subdivision:

Address : 2519
 Street : COOPERS LN
 Cross 1 : GRAVES DRIVE Within 1/4 mile: N
 Location: LOCATE FRONT OF LOTS 2519 2605 2623
 :
 Grids : 3820C8544B 3820B8544B 3820C8544A 3820B8544A

Work type : SEWERS
 Done for : DAN CRISTIANI
 Start date: 03/08/2011 Time: 13:30 Hours notice: 108/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : UNKNOWN Depth: 20 FEET

Company : DAN CRISTIANI EXCAVATING Type: CONT
 Co addr : 1221 OLD HIGHWAY 31 EAST
 City : CLARKSVILLE State: IN Zip: 47129
 Caller : JUDY JONAS Phone: (812)282-9866
 Contact : DANNY CRISTIANI Phone:
 BestTime:
 Mobile : (502)376-0105
 Fax : (812)282-9908

Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? NO
 :

Submitted date: 03/04/2011 Time: 01:09
 Members: ID0002 ID0340 ID4866 ID5693 ID6451 ID7053 ID7714 ID8203 ID8233 ID8401
 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
AT&T - TRANSMISSION	FIBER OPTIC
CLARKSVILLE STORMWATER DEPARTMENT	
CLARKSVILLE WASTEWATER	
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
IN AMERICAN WATER SOUTHERN INDIANA	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
JEFFERSONVILLE WASTEWATER AND SEWER	
QWEST COMMUNICATIONS	FIBER OPTIC
VECTREN - CLARKSVILLE	GAS
ZAYO BANDWIDTH	FIBER OPTIC

DAMAGE DAMAGE

Ticket : 1103281298 Date: 03/28/2011 Time: 10:45 Oper: LPORTER Chan:046

State: IN Cnty: CLARK Twp: JEFFERSONVILLE
 Cityname: JEFFERSONVILLE Inside: Y Near: N
 Subdivision:

Address : 2519
 Street : COOPERS LN
 Cross 1 : GRAVES DRIVE Within 1/4 mile: N
 Location: LOCATE FRONT OF LOTS 2519 2605 2623
 :
 Grids : 3820C8544B 3820B8544B 3820C8544A 3820B8544A

Work type : SEWERS
 Done for : DAN CRISTIANI
 Start date: 03/28/2011 Time: 10:46 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : UNKNOWN Depth: 20 FEET

Company : DAN CRISTIANI EXCAVATING Type: CONT
 Co addr : 1221 OLD HIGHWAY 31 EAST
 City : CLARKSVILLE State: IN Zip: 47129
 Caller : JUDY JONAS Phone: (812)282-9866
 Contact : DANNY CRISTIANI Phone:
 BestTime:
 Mobile : (502)468-8097
 Fax : (812)282-9908

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PER JUDY JONAS - HIT A VECTREN GAS LINE - LINE SMALL THREE QUARTER INCH SERVICE
 LINE - DIGGING IN FRONT OF 2519 COOPERS LN - CREW STILL ON SITE - GAS NOT
 BLOWING HAS PINCHED OFF - JUDY HAS CONTACTED VECTREN - -PREVIOUS TICKET
 1103180495
 Will you be white-lining the dig site area? NO
 :

Submitted date: 03/28/2011 Time: 10:45
 Members: ID0002 ID0340 ID4866 ID5693 ID6451 ID7053 ID7714 ID8203 ID8233 ID8401
 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
AT&T - TRANSMISSION	FIBER OPTIC
CLARKSVILLE STORMWATER DEPARTMENT	
CLARKSVILLE WASTEWATER	
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
IN AMERICAN WATER SOUTHERN INDIANA	
INSIGHT COMMUNICATIONS - NEW ALBANY	CABLE TV
JEFFERSONVILLE WASTEWATER AND SEWER	
QWEST COMMUNICATIONS	FIBER OPTIC
VECTREN - CLARKSVILLE	GAS
ZAYO BANDWIDTH	FIBER OPTIC

[View Map](#) [Close Map](#)