



Pipeline Safety Division Investigation Report

Investigation regarding: **Minnesota Limited Llc**

UPPAC Database Record ID: 3146

Investigator: Mike Orr

Report Date: 1/3/2013

Damage Date: 6/6/2012 11:43:13 AM

Damage Address: 3800 Bergdolt Rd

City: Evansville

County: Vanderburgh

The Parties

Excavator: **Minnesota Limited Llc**

Contact: Greg Frazier

Address: 2717 Kotter Ave, Evansville, In 47715

Telephone:

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Minnesota Limited Llc

UPPAC Database Record ID: 3146

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$382.00

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1205303133

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Natural Gas

Synopsis: Damage to a natural gas service occurred during a procedure to install a natural gas line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 7/19/2012. Excavator had a valid locate prior to beginning; however, the gas operator failed to locate the facility or provided incorrect locate markings resulting in an OPERATOR VIOLATION and after having been put on notice by the IURC in a mailing 8/7/2012 of the finding with allotted time having elapsed; the same finding has resulted.

Conclusion: The gas operator failed to locate or provided incorrect locate markings.

Violation: IC 8-1-26-18(f): Operator failed to locate or provided incorrect locate markings.



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

July 13, 2012

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 6/6/2012

Event Location: 3800 Bergdolt Rd, Evansville

Facility Owner: Vectren

Excavator: Minnesota Limited Llc

Other Party: N/A

Pipeline Division Case No. 3146

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 07-19-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Minnesota Limited LLC

Business address (*number and street*): 2717 Kotter Avenue

City, State, and ZIP code: Evansville, IN 47715

Telephone number (*area code*): 812-474-0189

Fax number (*area code*): 812-474-0685

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Natural Gas

Date and Location of Damage

Date of damage (*month, day, year*): 6-6-2012

County: Vanderburgh

City: Evansville

Street address (*number and street, city, state, and ZIP code*):
3800 Bergdolt Road, Evansville, IN

Nearest intersection: Unknown

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (*in hours*): 2.5

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 381.89

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1205303133

Was the locate request completed within two working days? No

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC _____

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? No

Type of markings used: Other

If other, please specify: None _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Facility marking or location not sufficient

Additional Comments

1/2" plastic service severed by backhoe. Incomplete.



1 VECTREN ENERGY DELIVERY OF INDIANA - SOUTH


NOW DUE

\$381.89

USIC INC
9045 N RIVER ROAD, SUITE 300
INDIANAPOLIS, IN 46240

Type: GAS
Invoice: FDS0016346
BillToID: 32121
Billing Date: 7/10/2012
Date of Loss: 6/6/2012
5854 103.0510

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holding Group Inc
1239 Reliable Parkway
Chicago, IL 60688-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

USIC INC
9045 N RIVER ROAD, SUITE 300
INDIANAPOLIS, IN 46240

Type: GAS
Invoice: FDS0016346
BillToID: 32121
Billing Date: 7/10/2012
Date of Loss: 6/6/2012

NOW DUE

\$381.89

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 3800 BERGDOLT RD, EVANSVILLE

1/2" PLASTIC SERVICE SEVERED BY BACKHOE. INCOMPLETE.

Material:	\$21.23
Company Labor:	\$324.80
Contract Labor:	\$0.00
Transportation/Equipment:	\$34.38
Misc:	\$0.00
Gas Loss:	\$1.48
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$381.89

5854 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FDS 16346

Task No: 103.0510 Capital/O & M (circle one)

Vectren Claim Number: _____

Date of Damage 6/6/12

Police Report /MO #: _____

Cost Center # 5854

Time Occurred 10:30 am/pm

Time Found 10:40 am/pm

Latitude _____ Longitude: _____

FACILITIES DAMAGE REPORT

GAS

Vectren Claims Camera:

VE00768
Form 3112

DAMAGE SITE: Address 3800 Bergdatt Rd Lot # _____
County Vard City Coville State In Township Center/Out

FACILITY TYPE:
 Distribution Propane
 Service Storage
 Transmission: (include supplemental report)

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

VISUAL OBSERVATION AT DAMAGE SITE: Max # 7820022
Visual Observation: Above Ground Below Ground
Locate Applicable Yes No N/S
Facilities Properly Marked Yes No N/S
Marking Methods: Conventional Flags None Whiskers
 Offset Paint Stakes
Locate Marking Faded: Yes No N/S
Wrong Address Requested Yes No N/S

TYPE OF MATERIAL: Cast Iron Plastic (HDPE) Plastic (MDPE) Steel
DAMAGE TYPE: Severed Not Cut Severed
Size 5 x _____

PRESSURE: 25 PSIG 40 PSIG 50 PSIG 55 PSIG 60 PSIG 6 WC (.2163) 7 WC (252) Other _____

Facilities Improperly Located:
 Qualified Locator Could Not Have Accurately Located
 Inaccurate Maps / Cards
 Broken or No Tracer Wire (Plastic)
 Insulation Preventing Accurate Locate
Locator Error:
 Failure to Follow Policy
 Inappropriate Site Markings
 Incomplete Locate
 No Locates Performed
 Qualified Locator Could Have Accurately Located
 Wrong Address Located
 Marking Off By: _____ (Feet / Inches)

PROTECTION IN PLACE: Building Fence None Post Rail Vault N/A Other _____

DURATION OF ESCAPING GAS: Minutes: 5

Were Facility Marks Visible Yes No
Was Area White Lined Yes No Destroyed
Positive Response Yes No Destroyed
Tolerance Zone Violated Yes No
Part of Project Yes No
Company Representative On-Site Yes No

LEAK REPORT NUMBER: 658855

EFV Activated Yes No N/S

Observation by (ID#): _____

FEED TYPE: One-Way Feed Two-Way Feed

Number of Customers Affected: 1
Total Hours Service _____
Was Off: _____

Name of Locator: _____
LOCATING ORGANIZATION:
 Contract Locator
 Unknown / Other
 Utility Owner

SERVICE ORDER NUMBER: Prem 1145651

DAMAGED BY: Company Crew Contractor County Developer Farmer Municipality Property Owner/ Tenant Railroad State Unknown Utility Vehicle Accident Other _____

TYPE OF CONSTRUCTION: Agriculture Building Construction Building Demolition Cable TV Curbs / Sidewalk Drainage Driveway Electric Engineering / Surveying Fencing Grading Irrigation Landscaping Liquid Pipeline Milling Pole Natural Gas Public Transit Authority Railroad Maintenance Other Gas work

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:
 Locate Ticket: _____
Date: _____ Time: _____ am / pm

TYPE OF REQUEST: Regular Request Emergency Request
 Locate Company Notified
Contact Name: _____
Time Called: _____ am / pm
Time Locator Arrived at the Site: _____ am / pm

WORKING FOR: City County Developer State Property Owner Utility
Vectren

Company Notified of Locate Near Critical Facilities Yes No N/S
Copy of Mark Out Request Provided Within 2 Working Days Yes No N/S

ONE-CALL CENTER: IUPPS OUPS Unknown

Vectren Claim Number: _____

TYPE OF EQUIPMENT:

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other _____

ROOT DAMAGING CAUSE:

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other _____

CONTRACTOR REPAIRS:

- Contractor Working for Vectren Made Repairs at Own Expense
 Yes No N/S
- Contractor Repaired Damage
 Yes No N/S

Name of Contractor: _____
 # of Regular Hours; _____
 # of Overtime Hours; _____
 # of Regular Hours; _____
 Crew Type: _____

MATERIALS OR ROAD WORK:

- Meter was replaced _____ (Stores Code)
- Regulator Was Replaced _____ (Stores Code)
- Temporary Asphalt Repair: _____ (sq. ft.)
- Permanent Asphalt Repair: _____ (sq. ft.)

RIGHT OF WAY:

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

Did Excavator Notify You

- Yes No

Excavation Required

- Yes No

Media at Site

- Yes No

Was There Ignition of Gas?

- Yes No


INVOICE:

- Yes No N/S

DAMAGING PARTY:

Name: _____
 Address: _____
 City/ State/ Zip: _____
 Phone: (_____) _____
 Prepared / Investigated By: _____ Date: _____

PARTY TO INVOICE:

Name: _____
 Address: _____
 City/ State/ Zip: _____
 Phone: (_____) _____
 Reviewed by Field Supervisor:  Date: _____

Vectren Contract crew hit unmarked or mis marked service.

NORMAL NOTICE

Ticket : 1205303133 Date: 05/30/2012 Time: 02:05 Oper: LISA.WILKE Chan:000

State: IN Cnty: VANDERBURGH Twp: KNIGHT
 Cityname: EVANSVILLE Inside: Y Near: N
 Subdivision:

Address : 3800
 Street : BERGDOLT RD
 Cross 1 : GRACE LN Within 1/4 mile: Y
 Location: LOCATE SOUTH SIDE OF PROPERTY GOING ACROSS BERGDOLT RD TO VECTREN 12
 INCH TRANSMISSION LINE
 :
 Grids : 3801D8730D 3801C8730D

Work type : DIG UP FARM TAP
 Done for : VECTREN
 Start date: 06/01/2012 Time: 14:15 Hours notice: 60/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 3 DAYS Depth: 5 FEET

Company : MINNESOTA LIMITED LLC Type: CONT
 Co addr : 2717 KOTTER AVE
 City : EVANSVILLE State: IN Zip: 47715
 Caller : LISA WILKE Phone: (812)474-0189
 Contact : GREG FRAZIER Phone:
 BestTime:
 Mobile : (812)568-9814
 Fax : (812)474-0685
 Email : LISA.WILKE@MNLIMITED.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? NO
 :

Submitted date: 05/30/2012 Time: 02:05
 Members: ID0716 ID0723 ID2470 ID5347 ID9411 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
EVANSVILLE WATER & SEWER UTILITY	SEWER & WATER
INSIGHT COMMUNICATIONS OF EVANSVILLE	CABLE TV
VECTREN - EVANSVILLE	GAS & ELECTRIC
VECTRENS-HCJMR	
WIDE OPEN WEST	CABLE TV

[View Map](#)

[Close Map](#)

DAMAGE SEE REMARKS

Ticket : 1206061968 Date: 06/06/2012 Time: 11:37 Oper: SMCCLORE Chan:092

State: IN Cnty: VANDERBURGH Twp: KNIGHT
 Cityname: EVANSVILLE Inside: Y Near: N
 Subdivision:

Address : 3800
 Street : BERGDOLT RD
 Cross 1 : GRACE LN Within 1/4 mile: Y
 Location: LOCATE SOUTH SIDE OF PROPERTY GOING ACROSS BERGDOLT RD TO VECTREN 12
 INCH TRANSMISSION LINE
 :
 Grids : 3801D8730D 3801C8730D

Work type : DIG UP FARM TAP
 Done for : VECTREN
 Start date: 06/06/2012 Time: 11:38 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : 3 DAYS Depth: 5 FEET

Company : MINNESOTA LIMITED LLC Type: CONT
 Co addr : 2717 KOTTER AVE
 City : EVANSVILLE State: IN Zip: 47715
 Caller : GREG FRAZIER Phone: (812)474-0189
 Contact : GREG FRAZIER Phone:
 BestTime:
 Mobile : (812)568-9814
 Fax : (812)474-0685
 Email : LISA.WILKE@MNLIMITED.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PER GREG FRAZIER VECTREN GAS LINE WAS DAMAGED - GAS LINE IS BLOWING CAN BE
 HEARD AND SMELLED - DAMAGED ON THE SOUTHSIDE OF THE PROPERTY - LINE IS 1/2 INCH
 AND YELLOW - ADVISED GREG FRAZIER TO CALL 911 - CREW IS ONSITE -VECTREN HAS BEEN
 NOTIFIED - PREVIOUS TICKET 1205303133 - THANK YOU
 Will you be white-lining the dig site area? NO
 :

Submitted date: 06/06/2012 Time: 11:37
 Members: ID0716 ID0724 ID2470 ID5347 ID9411 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
EVANSVILLE WATER & SEWER UTILITY	
INSIGHT COMMUNICATIONS OF EVANSVILLE	CABLE TV
VECTREN - EVANSVILLE	GAS & ELECTRIC
VECTRENS-HCJMR	
WIDE OPEN WEST	CABLE TV

[View Map](#)
[Close Map](#)

Service Order Status

Monday, June 25, 2012

Enter Service Order Number:

2069802



Get Form

Refresh Data

Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: S2069802 ***** Needs Review *****

Order Type: LEAK

Order Status: Completed

Customer: 300148501 - STOFLETH SUZANNE N

Prem: 1147672 - 3800 BERGDOLT RD

Technician: 0333 - Pate, Phil

Order Dates and Times

Need Date: 6/6/2012 10:41:00 AM
Time Created: 6/6/2012 10:32:28 AM
Time Dispatched: 6/6/2012 10:32:28 AM
Time In Route: 6/6/2012 10:38:20 AM
Time On-Site: 6/6/2012 10:51:15 AM
Tech Complete: 6/6/2012 11:05:54 AM
Time Closed: 6/6/2012 11:05:54 AM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current ReadStatus

Old Meter: 7123 Active
New Meter:

Completion Notes

CUT SERV LR#658855 CREW ON SITR GAS OFF

Request Notes

HIT 1/2" PL SERV PER OPERATION SUPER, HEATH WILKEY..MINNESOTA CREW ONSITE..XST OAKHILL....PH 474-018 9....HEATH'S #457-9672....THANKS

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	6/6/2012 10:33:38 AM	Pate, Phil
AsnAssignmentEnRoute_evt	6/6/2012 10:38:20 AM	Pate, Phil
AsnAssignmentOnSite_evt	6/6/2012 10:51:15 AM	Pate, Phil
OrdOrderComplete_evt	6/6/2012 11:05:54 AM	Pate, Phil

NOTE: The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

Service Order Status

Monday, June 25, 2012

Enter Service Order Number:

2069807



Clear Form

Refresh Data

Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: S2069807 *** Needs Review ***

Order Type: LEAK

Order Status: Completed

Customer: 300148500 - PEPE FRANK H

Prem: 1147671 - 3803 BERGDOLT RD

Technician: 0333 - Pate, Phil

Order Dates and Times

Need Date: 6/6/2012 10:47:00 AM
Time Created: 6/6/2012 10:39:03 AM
Time Dispatched: 6/6/2012 10:39:03 AM
Time In Route: 6/6/2012 11:06:07 AM
Time On-Site: 6/6/2012 11:06:09 AM
Tech Complete: 6/6/2012 11:15:25 AM
Time Closed: 6/6/2012 11:15:25 AM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current ReadStatus

Old Meter: 7535 Active

New Meter:

Completion Notes

ODER FROM CUT SERV AT 8300 ALL SAFE

Request Notes

PER JOHN PEPE GAS ODOR OUTSIDE OF HOSUE, SOMEONE HAS HITA GAS LINE...NO PETS...CELL 228-6418...X/ST OKAHILL

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	6/6/2012 11:06:03 AM	Pate, Phil
AsnAssignmentEnRoute_evt	6/6/2012 11:06:07 AM	Pate, Phil
AsnAssignmentOnSite_evt	6/6/2012 11:06:09 AM	Pate, Phil
OrdOrderComplete_evt	6/6/2012 11:15:25 AM	Pate, Phil

NOTE: The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

[Close Window]

Called damage
6-6-12

"If you have a pencil handy, I have a ticket number to provide to you. If you need to call us back for any reason, your ticket number will assist us in locating this ticket. Are you ready for your number?"

120 606 1968 - DAMAGE TICKET NUMBER

NORMAL NOTICE

Ticket : 1205303133 Date: 05/30/2012 Time: 02:05 Oper: LISA.WILKE Chan:000

State: IN Cnty: VANDERBURGH Twp: KNIGHT
Cityname: EVANSVILLE Inside: Y Near: N
Subdivision:

Address : 3800
Street : BERGDOLT RD
Cross 1 : GRACE LN Within 1/4 mile: Y
Location: LOCATE SOUTH SIDE OF PROPERTY GOING ACROSS BERGDOLT RD TO VECTREN 12 INCH TRANSMISSION LINE
:
Grids : 3801D8730D 3801C8730D

Work type : DIG UP FARM TAP
Done for : VECTREN
Start date: 06/01/2012 Time: 14:15 Hours notice: 60/48 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
Duration : 3 DAYS Depth: 5 FEET

Company : MINNESOTA LIMITED LLC Type: CONT
Co addr : 2717 KOTTER AVE
City : EVANSVILLE State: IN Zip: 47715
Caller : LISA WILKE Phone: (812)474-0189
Contact : GREG FRAZIER Phone:
BestTime:
Mobile : (812)568-9814
Fax : (812)474-0685
Email : LISA.WILKE@MNLIMITED.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? NO
:

Submitted date: 05/30/2012 Time: 02:05
Members: ID0716 ID0723 ID2470 ID5347 ID9411 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
EVANSVILLE WATER & SEWER UTILITY	SEWER & WATER
INSIGHT COMMUNICATIONS OF EVANSVILLE	CABLE TV
VECTREN - EVANSVILLE	GAS & ELECTRIC
VECTRENS-HCJMR	
WIDE OPEN WEST	CABLE TV