STATE OF INDIANA

INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

http://www.in.gov/iurc
Office: (317) 232-2701
Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Kevin Sharick Underground

UPPAC Database Record ID: 3289

Investigator: Mike Orr

Report Date: 1/4/2013

Damage Date: 6/28/2012 9:51:00 AM

Damage Address: N 900 W

City: Shipshewana

County: Lagrange

The Parties

Excavator: **Kevin Sharick Underground**

Contact: Kevin Sharick

Address: 8785 West 750 North, Shipshewana, In 46565

Telephone:

Facility Owner: NIPSCO

Contact: Kit Earle

Address: 101 West Ohio Street, Indianapolis, IN 46204

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Kevin Sharick Underground

UPPAC Database Record ID: 3289

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): $

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1206184362

Type of Equipment: Boring

Type of work performed: Telecommunications

Synopsis: Damage to a natural gas service occurred during a boring procedure to install telecommunications.

Findings: Reported by Indiana 811; excavator did not respond to initial notice mailed 7/13/2012. The excavator had a valid locate request prior to beginning the boring procedure; however, the gas operator failed to properly locate the gas facility; and, after IURC notice 9/13/2012 with response time expired, a resulting determination is an OPERATOR VIOLATION.

Conclusion: There was a failure to locate or provided incorrect locate markings.

Violation: IC 8-1-26-18(f): Operator failed to locate or provided incorrect locate markings.

101 West Ohio Street, Suite 1707
Indianapolis, IN 46204

August 13, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3289
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3289

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 6/28/2012

Event Location: N 900 W, Shipshewana

Facility Owner: Northern Indiana Public Service Company

Excavator: Kevin Sharick Underground

Other Party: N/A

Pipeline Division Case No. 3289

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit") Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 3289	
Date of Event	6/28/2012
Event Location	N 900 W, Shipshewana
Facility Owner	Northern Indiana Public Service Company
Excavator	Kevin Sharick Underground
Date of IURC Information Request	7/13/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	Kevin Sharick Underground
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	8785 W 750 N
CITY/ STATE/ZIP	Shipshewana, IN 46565
PREFERRED TELEPHONE	260 768 7986
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	6870 N 900 W
CITY/STATE/ZIP	Shipshewana, IN
NEAREST INTERSECTION	IN RT 120
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8”
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) ($)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	
Boring/Drilling	X
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scrapper	
Hand Tools	
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	X
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y 1206280715
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1206184362
LOCATE MARKS VISIBLE (YES/NO)	N
LOCATE MARKS CORRECT (YES/NO)	N
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FACILITIES	
FIRE DEPARTMENT RESPONSE (YES/NO)	
FPOLICE DEPARTMENT RESPONSE (YES/NO	
AMBULANCE RESPONSE (YES/NO)	
ADDITIONAL INFORMATION/COMMENTS	
Locate contractor failed to accurately locate facility. Nipsco emergency repair ticket #: 1206280925	

Fact Based Investigation Report

NOTIFICATION ID:	01820120628003
DISTRICT:	Northern IN
DAMAGE DATE:	6/28/2012 9:46:00 AM
NOTIFICATION DATE:	6/28/2012 9:55:10 AM
NOTIFIED BY:	KEVIN SHARICK
DAMAGE ADDRESS:	N 900 W
CITY:	SHIPSHEWANA
ST: IN **ZIP:**	

DAMAGED CUSTOMER:	NIPSCO

INVESTIGATION DATE:	06/28/2012
FROM:	10:30:00
TO:	11:00:00

EXCAVATOR INVOLVED:	KEVIN SHARICK UNDERGROUND
TYPE OF EXCAVATION:	BORE

ORIG. LOCATE REQ.:	1206184362
START DATE/TIME:	
TYPE OF TICKET:	
LOCATE REQ. INFO N/A:	

DIG UP/DAMAGE REQ.:	1206280715
START DATE/TIME:	

PICTURES TAKEN BY:	MIKE OBERLIN
DATE/TIME:	6/28/2012 10:30:00 AM
PHOTOGRAPHY TYPE:	Digital
FRAME #:	

INVESTIGATOR EMP#:	113397
INVESTIGATOR NAME:	MIKEOBERLIN

BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED?
Possibly

Fact Based Investigation Customer Information

NOTIFICATION ID: 01820120628003

SELECT A CUSTOMER: NIPSCO

CUSTOMER #: *(optional)*

FACILITY DESCRIPTION: LOWPROF

FACILITY ID: service

LOCATOR NAME & EMP #: Cunningham Andrew - 131784

LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:
Other

Other: NOT MARKED

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):
Visual, Facility Exposed At Time Of Investigation

INVESTIGATOR STATEMENT/CAUSAL FACTORS:
CONTRACTOR HIT AN UNMARKED GAS SERVICE LINE

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:
U/K

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:
U/K

LIST ANY OTHER INDIVIDUALS ON SITE:
U/K

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? Yes

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? Yes

WAS THE EXCAVATION WITHIN THE TOLERENCE ZONE OF MARKS? No

EXTENT OF FACILITY DAMAGE PLASTIC SERVICE

REPLACEMENT FOOTAGE 2'

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No

WHAT CONTRACTOR EQUIPMENT WAS USED?

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? No

IF YES, PLEASE LIST RECORD #(S)

NIPSCO 00237 IUPPSa 06/28/2012 09:51:05 1206280715-00A EMER DAMG GRID

DAMAGE SEE REMARKS

Ticket : 1206280715 Date: 06/28/2012 Time: 09:46 Oper: AHINES Chan:085

State: IN Cnty: LAGRANGE Twp: VAN BUREN
Cityname: SHIPSHEWANA Inside: N Near: Y
Subdivision:

#3289

Address :
Street : N 900 W
Cross 1 : IN RT 120 Within 1/4 mile: Y
Location: STARTING 2500 FEET NORTH OF THE INTERSECTION LOCATE GOING NORTH ON THE WEST SIDE OF 900 W FOR 2500 FEET
***Boring Where = IN THE R-O-W
:
Grids : 4143A8536D 4144D8536D 4144C8536D
Boundary: n 41.741230 s 41.733242 w -85.602509 e -85.600945

Work type : INSTALLING FIBER OPTIC PHONE CABLE
Done for : CENTURYLINK
Start date: 06/28/2012 Time: 09:46 Hours notice: 0/0 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y
Duration : 1 WEEK Depth: 10 FEET

Company : KEVIN SHARICK UNDERGROUND Type: CONT
Co addr : 8785 WEST 750 NORTH
City : SHIPSHEWANA State: IN Zip: 46565
Caller : KEVIN SHARICK Phone: (260)768-7986
Contact : KEVIN SHARICK - CELL Phone:
BestTime:
Mobile : (260)350-1534
Fax : (888)691-5007
Email : KSHARICK@EMBARQMAIL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
A GAS LINE HAS BEEN DAMAGED - THE LINE BELONGS TO NIPSCO - THE LINE IS BLOWING - LINE WAS DAMAGED IN FRONT OF THE ADDRESS 6870 900 W IN THE ROAD ROW - CALLER CANNOT DESCRIBE THE LINE THAT WAS DAMAGED - ADVISED CALLER TO CALL 911 - CREW IS ON SITE - CALLER HAS CONTACTED THE UTILITY COMPANY TO REPORT THE DAMAGE - PREVIOUS TICKET 1206184362
Will you be white-lining the dig site area? NO
:

Submitted date: 06/28/2012 Time: 09:46
Members: ID2034 NIPSCO ID5857

NIPSCO 00013 IUPPSa 06/27/2012 06:32:26 1206184362-01A NORM 2NDR GRID

SECOND NOTICE 2ND NOTICE

Ticket : 1206184362 Date: 06/27/2012 Time: 06:22 Oper: LTHOMPSON Chan:021
Old Tkt: 1206184362 Date: 06/18/2012 Time: 21:55 Oper: LWORTON Rev: 00A

State: IN Cnty: LAGRANGE Twp: VAN BUREN
Cityname: SHIPSHEWANA Inside: N Near: Y
Subdivision:

#3289

Address :
Street : N 900 W
Cross 1 : IN RT 120 Within 1/4 mile: Y
Location: STARTING 2500 FEET NORTH OF THE INTERSECTION LOCATE GOING NORTH ON THE WEST SIDE OF 900 W FOR 2500 FEET
***Boring Where = IN THE R-O-W
:
Grids : 4143A8536D 4144D8536D 4144C8536D
Boundary: n 41.741230 s 41.733242 w -85.602509 e -85.600945

Work type : INSTALLING FIBER OPTIC PHONE CABLE
Done for : CENTURYLINK
Start date: 06/21/2012 Time: 07:00 Hours notice: 0/0 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
Duration : 1 WEEK Depth: 10 FEET

Company : KEVIN SHARICK UNDERGROUND Type: CONT
Co addr : 8785 WEST 750 NORTH
City : SHIPSHEWANA State: IN Zip: 46565
Caller : KEVIN SHARICK Phone: (260)768-7986
Contact : KEVIN SHARICK - CELL Phone:
BestTime:
Mobile : (260)350-1534
Fax : (888)691-5007
Email : KSHARICK@EMBARQMAIL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
PER KEVIN--THEY ARE STILL WAITING ON NIPSCO TO RESPOND--THANKS
Will you be white-lining the dig site area? NO
:

Submitted date: 06/27/2012 Time: 06:22
Members: ID2034 NIPSCO ID5857

NIPSCO 01448 IUPPSa 06/18/2012 21:59:55 1206184362-00A NORM NEW GRID

NORMAL NOTICE

Ticket : 1206184362 Date: 06/18/2012 Time: 21:55 Oper: LWORTON Chan:062

State: IN Cnty: LAGRANGE Twp: VAN BUREN
Cityname: SHIPSHEWANA Inside: N Near: Y
Subdivision:

#3289

Address :
Street : N 900 W
Cross 1 : IN RT 120 Within 1/4 mile: Y
Location: STARTING 2500 FEET NORTH OF THE INTERSECTION LOCATE GOING NORTH ON THE WEST SIDE OF 900 W FOR 2500 FEET
***Boring Where = IN THE R-O-W
:
Grids : 4143A8536D 4144D8536D 4144C8536D
Boundary: n 41.741230 s 41.733242 w -85.602509 e -85.600945

Work type : INSTALLING FIBER OPTIC PHONE CABLE
Done for : CENTURYLINK
Start date: 06/21/2012 Time: 07:00 Hours notice: 57/48 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
Duration : 1 WEEK Depth: 10 FEET

Company : KEVIN SHARICK UNDERGROUND Type: CONT
Co addr : 8785 WEST 750 NORTH
City : SHIPSHEWANA State: IN Zip: 46565
Caller : KEVIN SHARICK Phone: (260)768-7986
Contact : KEVIN SHARICK - CELL Phone:
BestTime:
Mobile : (260)350-1534
Fax : (888)691-5007
Email : KSHARICK@EMBARQMAIL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? NO
:

Submitted date: 06/18/2012 Time: 21:55
Members: ID2034 NIPSCO ID5857

NIPSCO 00315 IUPPSa 06/28/2012 10:25:46 1206280928-00A EMER NEW GRID

EMERGENCY EMERGENCY

Ticket : 1206280928 Date: 06/28/2012 Time: 10:21 Oper: LSTEVENSON Chan:018

State: IN Cnty: LAGRANGE Twp: VAN BUREN
Cityname: SHIPSHEWANA Inside: Y Near: N
Subdivision:

#3289

Address : 6870
Street : N 900 W
Cross 1 : W 600 N Within 1/4 mile: Y
Location: LOCATE THE ENTIRE PROPERTY
:
Grids : 4143B8535D 4143A8535D 4144D8535D 4144C8535D 4143B8535C
Grids : 4143A8535C 4144D8535C 4144C8535C 4143B8535B 4143A8535B
Grids : 4144D8535B 4144C8535B 4143B8535A 4143A8535A 4144D8535A
Grids : 4144C8535A 4143B8536D 4143A8536D 4144D8536D 4144C8536D
Grids : 4143B8536C 4143A8536C 4144D8536C 4144C8536C 4143B8536B
Grids : 4143A8536B 4144D8536B 4144C8536B 4143B8536A 4143A8536A
Grids : 4144D8536A 4144C8536A
Boundary: n 41.737537 s 41.726646 w -85.615654 e -85.584930

Work type : REPAIR GAS LINE
Done for : NIPSCO
Start date: 06/28/2012 Time: 10:23 Hours notice: 0/0 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 6 FEET

Company : NIPSCO Type: MEMB
Co addr : 801 EAST 86TH AVENUE
City : MERRILLVILLE State: IN Zip: 46410
Caller : NICOLE WADDELL Phone: (800)322-2806
Contact : MARK KNISLEY---CELL Phone:
BestTime:
Mobile : (574)535-3001

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW IS EN ROUTE
Will you be white-lining the dig site area? NO
:

Submitted date: 06/28/2012 Time: 10:21
Members: ID2034 NIPSCO ID5857

Kevin Sharick caller in CIS

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

**** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES ****

REPORTING OPERATING AREA Goshen **MAXIMO WO #** M496975 + M497048 (Repair) (3rd party)

OPERATING AREA CONTACT Mark Knisley **JOB ORDER #** 546368

TRACKING NUMBER 018 20120628 003 **LOCATE REF #** 120 618 4361

Locate Performed By: _____

DATE AND TIME OF ACCIDENT 6-28 2012, 10:05 AM DATE OF REPORT _____

PLACE OF DAMAGE (INCLUDE CITY) 6870N 900W Shipshewana

DAMAGE WAS TO:

ELECTRIC - POLE / TRANSFORMER: # N/A SIZE N/A YEAR INSTALLED N/A BROKEN YES ( ) NO ( )

OTHER (DESCRIBE) N/A

GAS: SERVICE (X) MAIN ( ) SIZE 5/8 MATERIAL: PLASTIC (X) STEEL ( ) METER ( ) REG STATION ( ) STUB ( )
OTHER (DESCRIBE) _____

DEPTH OF FACILITY (inches) 19 1/2 PRESSURE (PSI) 40 Lbs.

RELEASE OF GAS: YES (X) NO ( ) IGNITION OF GAS: YES ( ) NO (X) EVACUATION REQUIRED: YES ( ) # _____ NO (X)

INTERRUPTION OF SERVICE: YES ( ) NO (X) NUMBER OF CUSTOMERS LOST: 0

DURATION OF INTERRUPTION: TIME REPORTED 10:05 Am TIME RESTORED 10:40

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 5/8

LOCATE MARKS ON SITE: YES (X) — only not the service DISTANCE BETWEEN FACILITY AND LOCATE MARKS _____ NO ( )
HOW LOCATED: PAINT ( ) FLAGS ( ) BOTH ( ) WHITE LINED ( )

PARTY THAT CAUSED DAMAGES (NAME) KLS underground

ADDRESS OF PARTY (INCLUDE CITY) 8785W 750N Shipshewana, IN 46565

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE Kevin Sherick

WITNESS NAME AND ADRESS N/A

WITNESS REMARKS N/A

AGENCIES NOTIFIED / ONSITE: POLICE ( ) AGENCY N/A REPORT # _____

FIRE ( ) AGENCY N/A REPORT # _____

OTHER ( ) N/A Any Injuries? ( ) YES # _____ (X) NO

PHOTOS TAKEN: YES (X) NO ( ) TAKEN BY: A. Jackson (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES ( ) NO (X)

WORK IN PROGRESS WHEN FACILITY DAMAGED – CHECK APPROPRIATE CHOICE BELOW

( ) AGRIGULTURE/FARMING	( ) CABLE TV	( ) CURB/SIDEWALK	(X) TELECOMMUNICATIONS
( ) BLDG CONSTRUCTION	( ) DEMOLITION	( ) DRAINAGE	( ) WATER
( ) DRIVEWAY	( ) ELECTRIC	( ) SURVEYING	( ) DRAINS/CULVERTS
( ) FENCING	( ) GRADING	( ) IRRIGATION	( ) MOWING
( ) LANDSCAPING	( ) PIPELINE	( ) MILLING	( ) OTHER _____
( ) POLE/SIGN POST	( ) ROAD WORK	( ) SEWER	

TYPE OF EQUPMENT USED – CHECK APPROPRIATE CHOICE BELOW

( ) AUGER	( ) HAND TOOLS	( ) BACKHOE/TRACKHOE
( ) MILLING EQUIPMENT	( ) PROBING DEVICE	(X) BORING / DRILLING
( ) EXPLOSIVES	( ) TRENCHER	( ) FARM EQUIPMENT
( ) VACCUUM EQUIPMENT	( ) GRADER	( ) OTHER

REASON DAMAGE OCCURRED– CHECK APPROPRIATE CHOICE BELOW

( ) AUTOMOTIVE ACCIDENT	( ) EXCAVATING BEFORE LOCATES DUE	( ) CARELESS MACHINE OPERATOR	
( ) NO NOTIFICATION	( ) MARKS DISTURBED	( ) STUB	(X) OTHER Service Not located

- **SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM**

COMMENTS : Service Not located

PERSON PREPARING REPORT A. Jackson

FIELD SUPERVISOR Mark Knisley

FIELD MANAGER

- **ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY**
- **COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION**

SKETCH: - Show position of all pertinent information



FOR OFFICE USE ONLY:

• DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE	YES	NO
• NO IN 811 LOCATE CALLED IN	YES	NO
• DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE	YES	NO
• EXPIRED LOCATE	YES	NO
• WAS WHITE LINING INDICATED ON LOCATE REQUEST	YES	NO

COMPLETED BY: A. Jackson DATE: 7/18/12

Knisley

101 West Ohio Street, Suite 1707
Indianapolis, IN 46204

October 3, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3289
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Notification of Possible Violations; Pipeline Division Case No. 3289
Date of Event: 6/28/2012
Event Location: N 900 W, Shipshewana, IN
Excavator: Kevin Sharick Underground
Other Party: N/A

To Whom It May Concern:

This letter responds to the Indiana Utility Regulatory Commission, Division of Pipeline Safety, Notification of Possible Violations for Case No. 3289 (as detailed above) identifying potential violations of Indiana law dated September 13, 2012. NIPSCO has not identified any additional information related to this incident not already provided in its August 13, 2012 response.

If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com