



Pipeline Safety Division Investigation Report

Investigation regarding: **Gariup Construction Company, Inc.**

UPPAC Database Record ID: 3349

Investigator: Howard Friend

Report Date: 11/19/2012

Damage Date: 7/11/2012 10:12:56 AM

Damage Address: Oak Ave

City: Miller

County: Lake

The Parties

Excavator: **Gariup Construction Company, Inc.**

Contact: Darren Demoree, Senior Project Manager

Address: Po Box 64879, Gary, In 46401

Telephone:

Facility Owner: NIPSCO

Contact: Kit Earle

Address: 101 West Ohio Street, Indianapolis, IN 46204

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: Gariup Construction Company, Inc.

UPPAC Database Record ID: 3349

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1207093853

Type of Equipment: Hand Tools

Type of work performed: Pole

Synopsis: A natural gas service was damaged during excavation for a curb and sidewalk.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 9/11/2012. The excavator had a valid locate request and the operator provided accurate locate markings.

Conclusion: The excavator reported the natural gas line should have been deeper than the 8" in depth and does not feel responsible for the damage. Nevertheless, the excavator failed to plan the excavation to avoid damage or interference with underground facilities.

Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.



INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 3349

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.

Upon completion of answers select email button for submission.

The Parties

Excavator Information:

Business Name: GARIUP CONSTRUCTION CO., INC

Responsible Party Personal Name: DARREN DEMAREE

Title (if any): SENIOR PROJECT MANAGER

Address (number and street): 3965 HARRISON ST

City, State and ZIP Code: GARY, IN 46408

Preferred Telephone Number (area code): 219-887-5233

Cellular Telephone Number (area code): NOT APPLICABLE

Email Address: darren.demaree@gariup.com

Facility Information:

Business Name: NORTHERN INDIANA PUBLIC SERVICE CO

Responsible Party Personal Name: Jeff Webb

Title (if any): EMPLOYEE #012526

Address (number and street): 801 EAST 86TH AVE

City, State and ZIP Code: MERRILLVILLE, IN 46410

Preferred Telephone Number (area code): 219-647-4033

Cellular Telephone Number (area code): UNKNOWN

Email Address: UNKNOWN

Locator Service Information:

Business Name: UNITED STATES INFRASTRUCTURE CORP (USIC)

Responsible Party Personal Name: BOB

Title (if any): UNKNOWN

Address (number and street): UNKNOWN

City, State and ZIP Code: UNKNOWN

Preferred Telephone Number (area code): UNKNOWN

Cellular Telephone Number (area code): 574-320-5665

Email Address: UNKNOWN

Cause of Damage Information

Type of Equipment (select one): Hand Tools

Type of Work Performed (select one): Curb/Sidewalk

Other Information (Witness, Police, Fire, Other):

Personal Contact: NONE

Business/Organization Name: NONE

Title (if any): NONE

Address (number and street): NONE

City, State and ZIP Code: NONE

Preferred Telephone Number (area code): NONE

Cellular Telephone Number (area code): NONE

Email Address: NONE

Utility Line Impact

Location of Damage:

Address (*number and street*): 6700 EAST OAK AVE

City, State and ZIP Code: GARY, IN 46402

Nearest Intersection: MONTGOMERY

Product Type (*select one*): Natural Gas

Facility Type (*select one*): Distribution

Size (Diameter/etc.): 1-1/8"

Pressure (PSIG/Inches): UNKNOWN

Interruption in Service: Yes No Number of Customers Affected: 0

Evacuation: Yes No If yes, How Many Evacuated?

Repair Cost (if known): \$ 336.66

Release of Product: Yes No

Ignition and/or Fire: Yes No

Excavator Notify 811: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1207093853

Locate Marks Visible: Yes No

Locate Marks Correct: Yes No

Excavator "White Lined": Yes No

Maps Used to Mark Facilities: Yes No

Was Locate Provided within Two (2) Working Days: Yes No

Operator Employees On-site during Excavation: Yes No

Incident Impact Information

Number of Outpatient Treated: ⁰ _____

Number of Inpatient Treated: ⁰ _____

Number of Fatalities: ⁰ _____

Fire Department Response: Yes No

Police Department Response: Yes No

Ambulance Response: Yes No

Additional Information / Comments

SAME GAS LINE AS WAS HIT IN CASE 3276. THIS GAS LINE WAS HIT/PUNCTURED BY DRIVING A STEEL STAKE USED FOR SUPPORT A CONCRETE CURB FORM.

IT SHOULD BE NOTED THAT THIS GAS LINE VARIED IN DEPTH FROM 4 FEET DOWN TO 8 INCHES DOWN AND PER ARTICLE 10-3.05 (03) OF THE 10-3.0 UTILITY ACCOMODATION POLICY THE LINE SHOULD HAVE BEEN 5 FEET DEEP NOT 8 INCHES.

NARRATIVE STATEMENT

Your Pipeline Safety Division Case Number: #3349

Your Full Name: DARREN DEMAREE

Full Name of Business / Entity (if applicable): GARIUP CONSTRUCTION CO., INC


Your Business Title (if applicable): SENIOR PROJECT MANAGER

Address (number and street): 3965 HARRISON ST

City: GARY, IN 46408 State: _____ ZIP Code: _____

Your E-mail Address: darren.demaree@gariup.com

Today's Date (month, day, year): 9/11/2012

Your Signature:  Title (if any) Senior Project Mgr

Please return your Narrative Statement to:

Pipeline Safety Division – Case Number 3349
Indiana Utility Regulatory Commission
101 West Washington Street, 1500E
Indianapolis, IN 46204

Or scan the statement and Email to:

PipelineDamageCase@urc.in.gov



101 West Ohio Street, Suite 1707
Indianapolis, IN 46204

September 14, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3349
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3349

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 7/11/2012

Event Location: Oak Ave, Miller

Facility Owner: Northern Indiana Public Service Company

Excavator: Gariup Construction Company, Inc.

Other Party: N/A

Pipeline Division Case No. 3349

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 3349	
Date of Event	7/11/2012
Event Location	Oak Ave, Miller
Facility Owner	Northern Indiana Public Service Company
Excavator	Gariup Construction Company, Inc.
Date of IURC Information Request	8/16/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	Gariup Construction Company, Inc.
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	PO Box 64879
CITY/ STATE/ZIP	Gary, IN 46401
PREFERRED TELEPHONE	219 887 5233
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	6700 Oak Ave
CITY/STATE/ZIP	Gary, IN
NEAREST INTERSECTION	N Montgomery St
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	1 1/8"
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	X
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	X
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y 1207111079
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1206261041
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	Y
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	
POLICE DEPARTMENT RESPONSE (YES/NO)	
AMBULANCE RESPONSE (YES/NO)	
ADDITIONAL INFORMATION/COMMENTS	
Excavator hit accurately marked facility Nipsco emergency repair ticket #: 1207111369	

Fact Based Investigation Report

01820120711003

Northern IN

7/11/2012 10:08:00 AM

7/11/2012 10:15:14 AM

JASON HINOJOSA

OAK AVE

MILLER

ST: IN ZIP:

NOTIFICATION ID:

DISTRICT:

DAMAGE DATE:

NOTIFICATION DATE:

NOTIFIED BY:

DAMAGE ADDRESS:

CITY:

NIPSCO

DAMAGED CUSTOMER:

07/11/2012

INVESTIGATION DATE:

11:15:00

FROM:

11:30:00

TO:

GARIUP CONSTRUCTION

EXCAVATOR INVOLVED:

General Construction

TYPE OF EXCAVATION:

1206261041

ORIG. LOCATE REQ.:

START DATE/TIME:

TYPE OF TICKET:

LOCATE REQ. INFO N/A:

1207111079

DIG UP/DAMAGE REQ.:

7/11/2012 10:10:00 AM

START DATE/TIME:

Bob Anderson

PICTURES TAKEN BY:

7/11/2012 11:15:00 AM

DATE/TIME:

Digital

PHOTOGRAPHY TYPE:

1

FRAME #:

122566

INVESTIGATOR EMP#:

Bob Squzert

INVESTIGATOR NAME:

BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED?

No

Fact Based Investigation Customer Information

01820120711003

NIPSCO

(optional)

NOTIFICATION ID:

SELECT A CUSTOMER:

CUSTOMER #:

LOWPROF

service - 1 1/8"

Squzert Robert - 122566

FACILITY DESCRIPTION:

FACILITY ID:

LOCATOR NAME & EMP #:

LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:

Facility Marked Accurately

Other:

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):

Visual, Facility Exposed At Time Of Investigation,
Investigator Verified Existing Marks By Hooking Up,
Investigation Results Verified By Utility Representative

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

This is an ongoing project area and Bob checks on them everyday. This gas line was marked numerous times and has also gotten hit before. Marks and flags were still visable from a recent locate.

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

Nipsco contacted and made the necessary repairs.

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

Gariup Construction crew on site also stated that gas was marked but shallow.

LIST ANY OTHER INDIVIDUALS ON SITE:

None

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL?
Yes

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA?
Yes

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS?
Yes

EXTENT OF FACILITY DAMAGE
cut 1 1/8" service line

REPLACEMENT FOOTAGE
N/A

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO?
No

WHAT CONTRACTOR EQUIPMENT WAS USED?
Unknown

IS THE FACILITY SHOWN ON THE UTILITY RECORDS?
No

IF YES, PLEASE LIST RECORD #(S)

NIPSCO 00302 IUPPSa 06/26/2012 10:01:27 1206261041-00A EMER DAMG GRID

Case 3349

DAMAGE DAMAGE

Ticket : 1206261041 Date: 06/26/2012 Time: 09:58 Oper: RJOHNSON Chan:002

State: IN Cnty: LAKE Twp: CALUMET
Cityname: MILLER Inside: Y Near: N
Subdivision:

Address :

Street : OAK AVE

Cross 1 : N MONTGOMERY ST Within 1/4 mile: Y

Location: THIS IS MARQUETTE PARK - FROM THE INTERSECTION - TRAVEL WEST ON OAK AVE FOR 1500 FEET - LOCATE CONTINUING WEST FOR APPROX 800 FEET ON THE NORTH SIDE OF THE ROAD - TO WHERE THE ROAD TURNS SOUTH

:
Grids : 4137D8715D 4137C8715D 4137D8715C 4137D8715B
Boundary: n 41.620850 s 41.618557 w -87.259552 e -87.250786

Work type : SITE CLEARING

Done for : MARQUETTE PARK

Start date: 06/26/2012 Time: 09:58 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 6 MONTHS Depth: 4 FEET

Company : GARIUP CONSTRUCTION CO INC Type: CONT

Co addr : PO BOX 64879

City : GARY State: IN Zip: 46401

Caller : JASON HINOJOSA Phone: (219)887-5233

Contact : JASON HINOJOSA - CELL Phone:

BestTime:

Mobile : (219)746-8958

Fax : (219)981-3679

Remarks : All tickets are taken and processed on Eastern Daylight Time
GAS LINE HAS BEEN DAMAGED--NIPSCO IS THE UTILITY COMPANY--GAS LINE IS NOT
BLOWING--LINE IS DAMAGED ON THE SOUTH SIDE OF THE AQUATORIUM--ON THE NORTH SIDE
OF OAK AVE--YELLOW 1" DIAMETER LINE--UNKNOWN MATERIAL--HAVE NOT CALLED 911--CREW
IS ON SITE--HAVE NOT CALLED NIPSCO TO REPORT THE DAMAGED LINE--GAVE
NUMBER--PREVIOUS TICKET 1206213018

Will you be white-lining the dig site area? NO

:

Submitted date: 06/26/2012 Time: 09:58

Members: COMCN IB ID2227 NIPSCO SM

NIPSCO 00383 IUPPSa 07/11/2012 10:13:06 1207111079-00A EMER DAMG GRID

DAMAGE DAMAGE-SEE REMARKS

Case 3349

Ticket : 1207111079 Date: 07/11/2012 Time: 10:08 Oper: CALEVI Chan:031

State: IN Cnty: LAKE Twp: CALUMET
Cityname: MILLER Inside: Y Near: N
Subdivision:

Address :

Street : OAK AVE

Cross 1 : N MONTGOMERY ST Within 1/4 mile: Y

Location: THIS IS MARQUETTE PARK - FROM THE INTERSECTION - TRAVEL WEST ON OAK
AVE FOR 1500 FEET - LOCATE CONTINUING WEST FOR APPROX 800 FEET ON THE NORTH SIDE
OF THE ROAD - TO WHERE THE ROAD TURNS SOUTH

:

Grids : 4137D8715D 4137C8715D 4137D8715C 4137D8715B

Boundary: n 41.620850 s 41.618557 w -87.259552 e -87.250786

Work type : SITE CLEARING

Done for : MARQUETTE PARK

Start date: 07/11/2012 Time: 10:09 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 6 MONTHS Depth: 4 FEET

Company : GARIUP CONSTRUCTION CO INC Type: CONT

Co addr : PO BOX 64879

City : GARY State: IN Zip: 46401

Caller : JASON HINOJOSA Phone: (219)887-5233

Contact : JASON HINOJOSA - CELL Phone:

BestTime:

Mobile : (219)746-8958

Fax : (219)981-3679

Remarks : All tickets are taken and processed on Eastern Daylight Time
PER JASON -HAVE PUNCTURED A GAS LINE AND IT IS LEAKING-ON SOUTHEAST CORNER THE
AQUATORIUM- 1 1/8TH SERVICE LINE -IT IS LEAKING-CREW IS ON SITE-WILL CALL 911
AND WILL CALL NIPSCO-PREVIOUS TICKET NUMBER-1207093853

Will you be white-lining the dig site area? NO

:

Submitted date: 07/11/2012 Time: 10:08

Members: COMCN IB ID2227 NIPSCO SM

NIPSCO 01222 IUPPSa 07/09/2012 16:21:56 1207093853-00A NORM NEW GRID

Case 3349

NORMAL NOTICE

Ticket : 1207093853 Date: 07/09/2012 Time: 16:20 Oper: BLIEVERTZ Chan:025

State: IN Cnty: LAKE Twp: CALUMET
Cityname: MILLER Inside: Y Near: N
Subdivision:

Address :

Street : OAK AVE

Cross 1 : N MONTGOMERY ST Within 1/4 mile: Y

Location: THIS IS MARQUETTE PARK - FROM THE INTERSECTION - TRAVEL WEST ON OAK
AVE FOR 1500 FEET - LOCATE CONTINUING WEST FOR APPROX 800 FEET ON THE NORTH SIDE
OF THE ROAD - TO WHERE THE ROAD TURNS SOUTH

:

Grids : 4137D8715D 4137C8715D 4137D8715C 4137D8715B

Boundary: n 41.620850 s 41.618557 w -87.259552 e -87.250786

Work type : SITE CLEARING

Done for : MARQUETTE PARK

Start date: 07/11/2012 Time: 16:30 Hours notice: 48/48 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N

Duration : 6 MONTHS Depth: 4 FEET

Company : GARIUP CONSTRUCTION CO INC Type: CONT

Co addr : PO BOX 64879

City : GARY State: IN Zip: 46401

Caller : JASON HINOJOSA Phone: (219)887-5233

Contact : JASON HINOJOSA - CELL Phone:

BestTime:

Mobile : (219)746-8958

Fax : (219)981-3679

Remarks : All tickets are taken and processed on Eastern Daylight Time

Will you be white-lining the dig site area? NO

:

Submitted date: 07/09/2012 Time: 16:20

Members: COMCN IB ID2227 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA GARY (ISO) MAXIMO WO # _____
OPERATING AREA CONTACT GARY JOB ORDER # 477205
TRACKING NUMBER 018-2012-0711-006 LOCATE REF # 1207111369
Locate Performed By: OSIC

DATE AND TIME OF ACCIDENT 7-11-12 0912 2012 A M DATE OF REPORT 7-11-12
PLACE OF DAMAGE (INCLUDE CITY) 6700 OAK

DAMAGE WAS TO:
ELECTRIC - POLE / TRANSFORMER: # _____ SIZE _____ YEAR INSTALLED _____ BROKEN YES () NO ()

OTHER (DESCRIBE) _____
GAS: SERVICE MAIN () SIZE 1 1/2" MATERIAL: PLASTIC STEEL () METER () REG STATION () STUB ()
OTHER (DESCRIBE) _____

DEPTH OF FACILITY (inches) 10" PRESSURE (PSI) 28 Lbs.
RELEASE OF GAS: YES NO () IGNITION OF GAS: YES () NO EVACUATION REQUIRED: YES () # _____ NO
INTERRUPTION OF SERVICE: YES NO () NUMBER OF CUSTOMERS LOST: 1
DURATION OF INTERRUPTION: TIME REPORTED 09:00 TIME RESTORED 10:30
DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: .75"

LOCATE MARKS ON SITE: YES () DISTANCE BETWEEN FACILITY AND LOCATE MARKS _____ NO
HOW LOCATED: PAINT () FLAGS () BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) Gavinup
ADDRESS OF PARTY (INCLUDE CITY) 8965 HARRISON GARY

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE _____
WITNESS NAME AND ADDRESS _____

WITNESS REMARKS _____

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY _____ REPORT # _____
FIRE () AGENCY _____ REPORT # _____
OTHER () _____ Any Injures? () YES # _____ () NO _____

PHOTOS TAKEN: YES () NO TAKEN BY: _____ (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW
() AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK () TELECOMMUNICATIONS
() BLDG CONSTRUCTION () DEMOLITION () DRAINAGE () WATER
() DRIVEWAY () ELECTRIC () SURVEYING () DRAINS/CULVERTS
() FENCING () GRADING () IRRIGATION () MOWING
() LANDSCAPING () PIPELINE () MILLING () OTHER _____
() POLE/SIGN POST () ROAD WORK () SEWER

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW
() AUGER HAND TOOLS () BACKHOE/TRACKHOE
() MILLING EQUIPMENT () PROBING DEVICE () BORING / DRILLING
() EXPLOSIVES () TRENCHER () FARM EQUIPMENT
() VACCUUM EQUIPMENT () GRADER () OTHER _____

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW
() AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE CARELESS MACHINE OPERATOR
() NO NOTIFICATION () MARKS DISTURBED () STUB () OTHER _____