



Pipeline Safety Division Investigation Report

Investigation regarding: S & S Directional Boring

UPPAC Database Record ID: 3385

Report Date: 4/18/2013

Investigator: Howard Friend

Damage Date: 7/18/2012 11:29:39 AM

Damage Address: S Martin St, Ligonier, Noble

The Parties

Excavator: S & S Directional Boring

Address: 1116 County Road 17, Bryan, Ohio 43506

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Directional Drilling

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 20

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A four (4) inch natural gas line was damaged during directional boring operations to install a sewer.

Findings: Reported by Indiana 811; excavator failed to respond to initial notice which was delivered and signed for on 2/20/2013. This original excavator, Land Construction, provided notice of excavation. They contracted out the directional bore operation to the excavator named in this case and they failed to provide notice of excavation. It is important to know that the operator exposed the gas facility for the excavator prior to the boring operation. The operator informed the excavator not to boring the water near the gas facility.

Conclusion: There was a failure to provide notice of excavation by the boring excavator.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.



101 West Ohio Street, Suite 1707
Indianapolis, IN 46204

September 14, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3385
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3385

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 7/18/2012

Event Location: S Martin St, Ligonier

Facility Owner: Northern Indiana Public Service Company

Excavator: Land Inc.

Other Party: N/A

Pipeline Division Case No. 3385

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 3385	
Date of Event	7/18/2012
Event Location	S Martin St, Ligonier
Facility Owner	Northern Indiana Public Service Company
Excavator	Land Inc.
Date of IURC Information Request	8/16/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	Land Inc
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	PO Box 192
CITY/ STATE/ZIP	Laotto, IN 46763
PREFERRED TELEPHONE	260 897 2407
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	Lincolnway & Martin
CITY/STATE/ZIP	Ligonier, IN
NEAREST INTERSECTION	Lincolnway & Martin
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	4"
PRESSURE (PSIG/INCHES)	40
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	20
EVACUATION (YES/NO)	Y
IF YES, HOW MANY EVACUATED	30
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	
Boring/Drilling	X
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	X
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y 1207181518
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1207120330
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	Y
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	Y
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	Y Ligonier FD
POLICE DEPARTMENT RESPONSE (YES/NO)	Y Ligonier PD
AMBULANCE RESPONSE (YES/NO)	
ADDITIONAL INFORMATION/COMMENTS	
<p>Excavator failed to maintain clearance of facility while boring underwater. Nipsco emergency repair ticket #: 1207181800</p>	

Fact Based Investigation Report

01820120718008
Northern IN
7/18/2012 11:29:46 AM
7/18/2012 11:35:11 AM
SHARON WARNER
S MARTIN ST
LIGONIER
ST: IN ZIP:

NOTIFICATION ID:
DISTRICT:
DAMAGE DATE:
NOTIFICATION DATE:
NOTIFIED BY:
DAMAGE ADDRESS:
CITY:

NIPSCO

DAMAGED CUSTOMER:

07/18/2012
12:00:00
12:30:00

INVESTIGATION DATE:
FROM:
TO:

Land Inc.
BORING A CREEK

EXCAVATOR INVOLVED:
TYPE OF EXCAVATION:

1207120413

ORIG. LOCATE REQ.:
START DATE/TIME:
TYPE OF TICKET:
LOCATE REQ. INFO N/A:

1207181800

DIG UP/DAMAGE REQ.:
START DATE/TIME:

MIKEOBERLIN
7/18/2012 12:20:00 PM
Digital

PICTURES TAKEN BY:
DATE/TIME:
PHOTOGRAPHY TYPE:
FRAME #:

113397

INVESTIGATOR EMP#:
INVESTIGATOR NAME:

MIKEOBERLIN
BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED?
No

Fact Based Investigation Customer Information

01820120718008

NIPSCO

(optional)

NOTIFICATION ID:

SELECT A CUSTOMER:

CUSTOMER #:

LOWPROF

main - 4"

Rumbaugh Christophe - 132171

FACILITY DESCRIPTION:

FACILITY ID:

LOCATOR NAME & EMP #:

LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:

Contractor Damaged Exposed Facility,
Facility Marked Accurately,
Other

Other: UNTONEABLE SENT TO NIPSCO

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):

Visual, Facility Exposed At Time Of Investigation,
Investigator Verified Existing Marks By Hooking Up

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

THIS TICKET WAS SENT TO NIPSCO AS A UNTONEABLE NIPSCO RESPONDED ESPOSED THE MAIN ON BOTH SIDES OF CREEK. AND TOLD THEM NOT TO BORE UNDER THE RIVER. MARK KNISLEY FROM NIPSCO WAS ON SITE AND VERIFIED THAT NIPSCO HAD TOLD THEM NOT TO BORE WHERE THEY HIT THE MAIN.

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

THIS TICKET WAS SENT TO NIPSCO AS A UNTONEABLE NIPSCO RESPONDED ESPOSED THE MAIN ON BOTH SIDES OF CREEK. AND TOLD THEM NOT TO BORE UNDER THE RIVER. MARK KNISLEY FROM NIPSCO WAS ON SITE AND VERIFIED THAT NIPSCO HAD TOLD THEM NOT TO BORE WHERE THEY HIT THE MAIN.

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

U/K

LIST ANY OTHER INDIVIDUALS ON SITE:

MARK KNISLEY NIPSCO

Yes **WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL?**

Yes **WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA?**

Yes **WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS?**

4" MAIN **EXTENT OF FACILITY DAMAGE**

U/K **REPLACEMENT FOOTAGE**

No **WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO?**

No **WHAT CONTRACTOR EQUIPMENT WAS USED?**

No **IS THE FACILITY SHOWN ON THE UTILITY RECORDS?**

IF YES, PLEASE LIST RECORD #(S)

NIPSCO 00523 IUPPSa 07/18/2012 11:29:46 1207181518-00A EMER DAMG STRT

DAMAGE SEE REMARKS

Case 3385

Ticket : 1207181518 Date: 07/18/2012 Time: 11:25 Oper: LSTEVENSON Chan:018

State: IN Cnty: NOBLE Twp: PERRY
Cityname: LIGONIER Inside: Y Near: N
Subdivision:

Address :

Street : S MARTIN ST

Cross 1 : LINCOLNWAY W Within 1/4 mile: Y

Location: LOCATE THE ENTIRE INTERSECTION OF MARTIN AND LINCOLNWAY FOR A RADIUS
OF 200 FT IN ALL DIRECTIONS

:

Grids : 4127A8535C

Boundary: n 41.466049 s 41.464951 w -85.591385 e -85.589920

Work type : SANITARY SEWER INSTALLATION

Done for : CITY OF LIGONIER

Start date: 07/18/2012 Time: 11:25 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 2 MONTHS Depth: 17 FEET

Company : LAND INC Type: CONT

Co addr : PO BOX 192

City : LAOTTO State: IN Zip: 46763

Caller : SHARON WARNER Phone: (260)897-2407

Contact : DARRIN PARKER Phone:

BestTime:

Mobile : (260)897-2407

Fax : (260)897-2432

Email : S.WARNER@APILAND.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
PER SHARON WARNER--A NIPSCO GAS LINE WAS HIT--GAS IS BLOWING--CAN BE HEARD AND
SMELLED--LINE WAS HIT ON THE NORTH SIDE OF THE LINCOLNWAY W NEAR THE RIVER---NO
DISCRIPTION OF THE LINE--CREW IS ON SITE--NIPSCO HAS BEEN NOTIFIED AND FIRE DEPT
IS EN ROUTE--PREVIOUS TICKET NUMBER IS 1207120330
Will you be white-lining the dig site area? NO

:

Submitted date: 07/18/2012 Time: 11:25

Members: AEPIN ID3032 ID4123 ID7613 NIPSCO SM

NIPSCO 00160 IUPPSa 07/12/2012 08:18:49 1207120330-00A NORM NEW STRT

NORMAL NOTICE

Case 3385

Ticket : 1207120330 Date: 07/12/2012 Time: 08:05 Oper: SHARON.WARNER Chan:000

State: IN Cnty: NOBLE Twp: PERRY
Cityname: LIGONIER Inside: Y Near: N
Subdivision:

Address :

Street : S MARTIN ST

Cross 1 : LINCOLNWAY W Within 1/4 mile: Y

Location: LOCATE THE ENTIRE INTERSECTION OF MARTIN AND LINCOLNWAY FOR A RADIUS
OF 200 FT IN ALL DIRECTIONS

:

Grids : 4127A8535C

Boundary: n 41.466049 s 41.464951 w -85.591385 e -85.589920

Work type : SANITARY SEWER INSTALLATION

Done for : CITY OF LIGONIER

Start date: 07/16/2012 Time: 08:30 Hours notice: 96/48 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N

Duration : 2 MONTHS Depth: 17 FEET

Company : LAND INC Type: CONT

Co addr : PO BOX 192

City : LAOTTO State: IN Zip: 46763

Caller : SHARON WARNER Phone: (260)897-2407

Contact : DARRIN PARKER Phone:

BestTime:

Mobile : (260)897-2407

Fax : (260)897-2432

Email : S.WARNER@APILAND.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time

Will you be white-lining the dig site area? NO

:

Submitted date: 07/12/2012 Time: 08:05

Members: AEPIN ID3032 ID4123 ID7613 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA Goshen MAXIMO WO# M511506 & M511514
OPERATING AREA CONTACT Mark Knisley JOB ORDER # 546372
TRACKING NUMBER 018 2012 0718 0011 LOCATE REF # 1207120413
Locate Performed By:

DATE AND TIME OF ACCIDENT 7-18 2012, 11:12 AM DATE OF REPORT

PLACE OF DAMAGE (INCLUDE CITY) Lincolnway + martin st Ligonier

DAMAGE WAS TO:

ELECTRIC - POLE / TRANSFORMER: # SIZE YEAR INSTALLED BROKEN YES () NO ()

OTHER (DESCRIBE)

GAS: SERVICE () MAIN (X) SIZE 4" MATERIAL: PLASTIC (X) STEEL () METER () REG STATION () STUB ()
OTHER (DESCRIBE)

DEPTH OF FACILITY (Inches) under water PRESSURE (PSI) 40 Lbs.

RELEASE OF GAS: YES (X) NO () IGNITION OF GAS: YES () NO (X) EVACUATION REQUIRED: YES (X) # 30 NO ()

INTERRUPTION OF SERVICE: YES (X) NO () NUMBER OF CUSTOMERS LOST: 20

DURATION OF INTERRUPTION: TIME REPORTED 11:12 am TIME RESTORED 13:34

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 4"

LOCATE MARKS ON SITE: YES () DISTANCE BETWEEN FACILITY AND LOCATE MARKS under water NO ()
HOW LOCATED: PAINT () FLAGS () BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) S+S Directional Boring, Ltd.

ADDRESS OF PARTY (INCLUDE CITY) 01116 CR17 Bryan, Oh 43506

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE Lucas Revis

WITNESS NAME AND ADDRESS

WITNESS REMARKS

AGENCIES NOTIFIED / ONSITE: POLICE (X) AGENCY Ligonier PD REPORT #

FIRE (X) AGENCY Ligonier Fire REPORT #

OTHER () Any Injuries? () YES # NO

PHOTOS TAKEN: YES (X) NO () TAKEN BY: Gary King (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES (X) NO ()

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW

- () AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK () TELECOMMUNICATIONS
() BLDG CONSTRUCTION () DEMOLITION () DRAINAGE () WATER
() DRIVEWAY () ELECTRIC () SURVEYING () DRAINS/CULVERTS
() FENCING () GRADING () IRRIGATION () MOWING
() LANDSCAPING () PIPELINE () MILLING () OTHER
() POLE/SIGN POST () ROAD WORK (X) SEWER

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW

- () AUGER () HAND TOOLS () BACKHOE/TRACKHOE
() MILLING EQUIPMENT () PROBING DEVICE (X) BORING / DRILLING
() EXPLOSIVES () TRENCHER () FARM EQUIPMENT
() VACCUUM EQUIPMENT () GRADER () OTHER

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW

- () AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE () CARELESS MACHINE OPERATOR
() NO NOTIFICATION () MARKS DISTURBED () STUB (X) OTHER under water

SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

COMMENTS: hit 4" main under the river while boring


PERSON PREPARING REPORT A. Jackson

FIELD SUPERVISOR Mark Knisley

FIELD MANAGER Rick Gray R. Gray

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information



FOR OFFICE USE ONLY:

- | | | |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE | YES | NO |
| • NO IN 811 LOCATE CALLED IN | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST | YES | NO |

COMPLETED BY: A. Jackson DATE: 7/19/12
M. Knisley 7/19/12

Coahran, Lisa

From: Kirk Braun [k.braun@apiland.net]
Sent: Monday, September 10, 2012 11:25 AM
To: IURC PipelineDamageCase
Subject: Case # 3385
Attachments: Ligonier Sanitary - IURC Case # 3385 9-10-12.pdf

Please see attached information request for Case 3385. Please note that damage was caused by the following company and not Land, Inc.

S & S Directional Boring, Inc.
01116 CR 17
Bryan, Ohio 43506
419-630-0726
Attn: Tod Schlachter

Thanks – Kirk Braun



*"Building Infrastructure
For The 21st Century"*



Kirk Braun, P.E.
P O Box 191
11808 SR 205 E
LaOtto, IN 46763
(260) 897-2743 Office
(260) 897-2432 Fax
www.apiland.net
Equal Opportunity Employer



INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 3385

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.

Upon completion of answers select email button for submission.

The Parties

Excavator Information:

Business Name: Land Inc.

Responsible Party Personal Name: Kirk M. Braun

Title (if any): President

Address (number and street): P.O. Box 192, 11808 SR 205 East

City, State and ZIP Code: Laotto, In 46763

Preferred Telephone Number (area code): 260-897-2407

Cellular Telephone Number (area code): n/a

Email Address: k.braun@apiland.net

Facility Information:

Business Name: NIPSCO

Responsible Party Personal Name: N/A

Title (if any): N/A

Address (number and street): South Martin Street.

City, State and ZIP Code: Ligonier In 46767

Preferred Telephone Number (area code): n/a

Cellular Telephone Number (area code): n/a

Email Address: n/a

Locator Service Information:

Business Name: S, M & P

Responsible Party Personal Name: Chris Rumbaugh, Mike Overlin

Title (if any): Field Locator

Address (number and street): n/a

City, State and ZIP Code: n/a

Preferred Telephone Number (area code): n/a

Cellular Telephone Number (area code): unknown

Email Address: n/a

Cause of Damage Information

Type of Equipment (select one): Boring/Drilling

Type of Work Performed (select one): Sewer (Sanitary/Storm)

Other Information (Witness, Police, Fire, Other):

Personal Contact: Harry Brown

Business/Organization Name: Land Inc.

Title (if any): Foreman

Address (number and street): P.O. Box 192, 11808 SR 205 East

City, State and ZIP Code: Laotto, In 46763

Preferred Telephone Number (area code): n/a

Cellular Telephone Number (area code): 260-417-6696

Email Address: n/a

Utility Line Impact

Location of Damage:

Address (*number and street*): Martin Street

City, State and ZIP Code: Ligonier, In 46767

Nearest Intersection: Lincolnway

Product Type (*select one*): Natural Gas

Facility Type (*select one*): Distribution

Size (Diameter/etc.): 4"

Pressure (PSIG/Inches): unknown

Interruption in Service: Yes No **Number of Customers Affected:** 0

Evacuation: Yes No **If yes, How Many Evacuated?** 0

Repair Cost (if known): \$ 0

Release of Product: Yes No

Ignition and/or Fire: Yes No

Excavator Notify 811: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1207120330

- Locate Marks Visible:** Yes No
- Locate Marks Correct:** Yes No
- Excavator "White Lined":** Yes No
- Maps Used to Mark Facilities:** Yes No
- Was Locate Provided within Two (2) Working Days:** Yes No
- Operator Employees On-site during Excavation:** Yes No

Incident Impact Information

Number of Outpatient Treated: none

Number of Inpatient Treated: none

Number of Fatalities: none

Fire Department Response: Yes No

Police Department Response: Yes No

Ambulance Response: Yes No

Additional Information / Comments

The 4" gas main was not damaged by Land, Inc. It was broken by S & S Directional Boring, 01116 CR 17, Bryan Ohio, 43506. Contact Tod Schlachter 419-630-0726. S & S was directional boring under the Elkhart River and damaged the line during their boring process. They were responsible for also calling in locates.

The 4" gas main was properly located on each side of the river, but was not located on the river banks.

NARRATIVE STATEMENT

Your Pipeline Safety Division Case Number: 3385

Your Full Name: Kirk M. Braun

Full Name of Business / Entity (if applicable): Land, inc.


Your Business Title (if applicable): President

Address (number and street): P.O. Box 192, 11808 SR 205 East

City: Laotto State: In ZIP Code: 46763

Your E-mail Address: k.braun@apiland.net

Today's Date (month, day, year): 9-10-12

Your Signature:  Title (if any) President

Please return your Narrative Statement to:

**Pipeline Safety Division – Case Number 3385
Indiana Utility Regulatory Commission
101 West Washington Street, 1500E
Indianapolis, IN 46204**

Or scan the statement and Email to:

PipelineDamageCase@urc.in.gov