



Pipeline Safety Division Investigation Report

Investigation regarding: **D. R. Watson Company**

UPPAC Database Record ID: 3519

Investigator: Howard Friend

Report Date: 10/24/2012

Damage Date: 7/31/2012 8:33:00 AM

Damage Address: 670 Colin Dr

City: Avon

County: Hendricks

The Parties

Excavator: **D. R. Watson Company**

Contact: Chuck Watson

Address: 1966 Midwest Boulevard, Indianapolis, In 46214

Telephone: (317) 271-1667

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Investigation regarding: D. R. Watson Company

UPPAC Database Record ID: 3519

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$409

Excavator Activities/Cause of damage information:

Excavator request locates: Yes Indiana 811 ticket Number: 1207241002

Type of Equipment: Backhoe/Trackhoe

Type of work performed: Water

Synopsis: A one inch plastic natural gas service was damaged during excavation to install a water line.

Findings: Excavator worked under a valid, accurately marked locate request but failed to maintain required clearance from the gas main with the excavator. Reported by Indiana 811; excavator signed for initial notice on 09/17/2012 but has not responded.

Conclusion: Excavator failed to maintain the required clearance with mechanized equipment.

Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

September 18, 2012

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 7/31/2012

Event Location: 670 Colin Dr, Avon

Facility Owner: Vectren

Excavator: D. R. Watson Company

Other Party: N/A

Pipeline Division Case No. 3519

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 9-28-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: D. R. Watson Company

Business address (*number and street*): 1966 Midwest Blvd.

City, State, and ZIP code: Indianapolis, IN 46214

Telephone number (*area code*): 317-271-1667

Fax number (*area code*): 317-271-2799

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Water

Date and Location of Damage

Date of damage (month, day, year): 7-31-2012

County: Hendricks

City: Avon, IN

Street address (number and street, city, state, and ZIP code):
670 Colin Drive, Avon, IN

Nearest intersection: Unknown

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours): 2

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 409.32

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1207241002

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint and Flags

If other, please specify: None

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? No

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

Additional Comments

1" plastic service damaged by hoe. Not Hand Exposed.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

PAID

NOW DUE
FINAL
\$409.32

WATSON, D R CO
1966 MIDWEST BLVD,
INDIANAPOLIS, IN 46214

Type: GAS
Invoice: FDS0016642
BillToID: 32338
Billing Date: 9/6/2012
Date of Loss: 7/31/2012
5953 103.0510

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holding Corp., P.O. Box 10000
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE
FINAL
\$409.32

WATSON, D R CO
1966 MIDWEST BLVD,
INDIANAPOLIS, IN 46214

Type: GAS
Invoice: FDS0016642
BillToID: 32338
Billing Date: 9/6/2012
Date of Loss: 7/31/2012

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 670 COLIN DRIVE, AVON

1" PLASTIC SERVICE DAMAGED BY HOE. NOT HAND EXPOSED.

Material:	\$41.54
Company Labor:	\$90.46
Contract Labor:	\$261.38
Transportation/Equipment:	\$15.94
Misc:	\$0.00
Gas Loss:	\$0.00
Adjustments:	\$0.00
Payments:	\$0.00
<hr/> Total:	\$409.32

5953 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

~~MINIMUM \$ 8159910~~

FDS0016642

Task No: 103.0510 Capital / O & M (circle one)
Date of Damage 7/31/12
Cost Center # 5953
Time Occurred 8:40 am / pm
Time Found 8:55 am / pm
Latitude 39.7690 Longitude: -86.389750

Vectren Claim Number: _____
Police Report / MO #: _____

Vectren Claims Camera:
VE02491
4

FACILITIES DAMAGE REPORT

GAS

DAMAGE SITE:
Address 670 Colin Dr Lot # _____
County Hendricks City AUDON State IN Township WASHINGTON

FACILITY TYPE:
 Distribution Propane
 Service Storage
 Transmission: (include supplemental report)

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Henter	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Other _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

564

VISUAL OBSERVATION AT DAMAGE SITE: 7/31
Visual Observation: Above Ground Below Ground
Locate Applicable: Yes No N/S
Facilities Properly Marked: Yes No N/S
Marking Methods: Conventional Flags None Whiskers
 Offset Paint Stakes
Locate Marking Faded: Yes No N/S
Wrong Address Requested: Yes No N/S

Facilities Improperly Located:
 Qualified Locator Could Not Have Accurately Located
 Inaccurate Maps / Cards
 Broken or No Tracer Wire (Plastic)
 Insulation Preventing Accurate Locate

Locator Error:
 Failure to Follow Policy
 Inappropriate Site Markings
 Incomplete Locate
 No Locates Performed
 Qualified Locator Could Have Accurately Located
 Wrong Address Located
Marking Off By: _____ (Feet / Inches)

TYPE OF MATERIAL: Cast Iron Plastic (HDPE) Plastic (MDPE) Steel Other _____
DAMAGE TYPE: Severed Not Cut Severed Crushed
Size 1/2" x 1/2"
PRESSURE: 25 PSIG 40 PSIG 50 PSIG 55 PSIG 60 PSIG 6 WC (.2163) 7 WC (.252) Other _____

12-337

PROTECTION IN PLACE: Building Fence None Post Rail Vault N/A Other _____
DURATION OF ESCAPING GAS:
Minutes: 1

Were Facility Marks Visible: Yes No
Was Area White Lined: Yes No Destroyed
Positive Response: Yes No Destroyed
Tolerance Zone Violated: Yes No
Part of Project: Yes No
Company Representative On-Site: Yes No

LEAK REPORT NUMBER: 503729
FEED TYPE: One-Way Feed Two-Way Feed
EFV Activated: Yes No N/S
Number of Customers Affected: 1
Total Hours Service Was Off: 2

Observation by (ID#): Rick Riggs 3465
Name of Locator: _____
LOCATING ORGANIZATION:
 Contract Locator Unknown / Other Utility Owner

SERVICE ORDER NUMBER: _____

DAMAGED BY: Company Crew Contractor County Developer Farmer Municipality Property Owner / Tenant Railroad State Unknown Utility Vehicle Accident Other _____
TYPE OF CONSTRUCTION: Agriculture Building Construction Building Demolition Cable TV Curbs / Sidewalk Drainage Driveway Electric Engineering / Surveying Fencing Grading Irrigation Landscaping Liquid Pipeline Milling Pole Natural Gas Public Transit Authority Railroad Maintenance Other WATER

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:
 Locate Ticket: _____
Date: _____ Time: _____ am / pm

TYPE OF REQUEST:
 Regular Request Emergency Request
 Locate Company Notified
Contact Name: _____
Time Called: _____ am / pm
Time Locator Arrived at the Site: _____ am / pm

Company Notified of Locate Near Critical Facilities: Yes No N/S
Copy of Mark Out Request Provided Within 2 Working Days: Yes No N/S

ONE-CALL CENTER:
 IUPPS OUPS Unknown

WORKING FOR: City County Developer State Property Owner Utility

Vectren Claim Number: _____

TYPE OF EQUIPMENT:


- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other _____

ROOT DAMAGING CAUSE:

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found / Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other _____

CONTRACTOR REPAIRS:

- Contractor Working for Vectren Made Repairs at Own Expense
 - Yes No N/S
- Contractor Repaired Damage
 - Yes No N/S

Name of Contractor: Miller Pipelines 
 # of Regular Hours: 1.0
 # of Overtime Hours: _____
 # of Regular Hours: _____
 Crew Type: 3-MAN

MATERIALS OR ROAD WORK:

- Meter was replaced _____ (Stores Code)
- Regulator Was Replaced _____ (Stores Code)
- Temporary Asphalt Repair: _____ (sq. ft.)
- Permanent Asphalt Repair: _____ (sq. ft.)

Did Excavator Notify You

- Yes No

Excavation Required

- Yes No

Media at Site

- Yes No

Was There Ignition of Gas?

- Yes No

INVOICE:

- Yes No N/S

RIGHT OF WAY:

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

DAMAGING PARTY:

Name: D. R. WATSON
 Address: 1966 MIDWEST Blvd
 City/ State/ Zip: INDIANAPOLIS, IN 46214
 Phone: () _____
 Prepared / Investigated by: Rick Riggs Date: 8-1-12

PARTY TO INVOICE:

Name: D. R. WATSON
 Address: _____
 City/ State/ Zip: _____
 Phone: () _____
 Reviewed by Field Supervisor: Alexander Date: 8-1-12

NORMAL NOTICE REMARK

Ticket : 1207241002 Date: 07/24/2012 Time: 10:10 Oper: SMCCLORE Chan:092

State: IN Cnty: HENDRICKS Twp: WASHINGTON
 Cityname: AVON Inside: Y Near: N
 Subdivision: GROVES AT BEECHWOOD FARMS Lot: 86

Address : 670
 Street : COLIN DR
 Cross 1 : JESSICA LN Within 1/4 mile: Y
 Location: LOCATE THE NORTHSIDE OF THE PROPERTY
 :
 Grids : 3946D8623C 3946C8623C

Work type : WATER HOOKUP
 Done for : BEAZER HOMES
 Start date: 07/26/2012 Time: 10:30 Hours notice: 48/048 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 1 DAY Depth: 5 FEET

Company : D R WATSON COMPANY Type: CONT
 Co addr : 1966 MIDWEST BOULEVARD
 City : INDIANAPOLIS State: IN Zip: 46214
 Caller : RHONDA MOORE Phone: (317)271-1667
 Contact : CHUCK WATSON - OFFICE Phone:
 BestTime:
 Mobile : (317)271-1667
 Fax : (317)271-2799
 Email : SALES@DRWATSONCO.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 REMARK NEEDED DUE TO CONSTRUCTION - PREVIOUS TICKET 1206121108
 Will you be white-lining the dig site area? NO
 :

Submitted date: 07/24/2012 Time: 10:10
 Members: ID0002 ID1501 ID2980 ID4471 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CITIZENS WATER / FORMERLY VEOLIA WATER	WATER
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
VECTREN - DANVILLE	GAS
WEST CENTRAL CONSERVANCY DISTRICT	

[View Map](#)

[Close Map](#)

DAMAGE SEE REMARKS

Ticket : 1207310428 Date: 07/31/2012 Time: 08:29 Oper: SLUCAS Chan:060

State: IN Cnty: HENDRICKS Twp: WASHINGTON
 Cityname: AVON Inside: Y Near: N
 Subdivision: GROVES AT BEECHWOOD FARMS Lot: 86

Address : 670
 Street : COLIN DR
 Cross 1 : JESSICA LN Within 1/4 mile: Y
 Location: LOCATE THE NORTHSIDE OF THE PROPERTY
 :
 Grids : 3946D8623C 3946C8623C

Work type : WATER HOOKUP
 Done for : BEAZER HOMES
 Start date: 07/31/2012 Time: 08:29 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : 1 DAY Depth: 5 FEET

Company : D R WATSON COMPANY Type: CONT
 Co addr : 1966 MIDWEST BOULEVARD
 City : INDIANAPOLIS State: IN Zip: 46214
 Caller : RHONDA MOORE Phone: (317)271-1667
 Contact : CHUCK WATSON - OFFICE Phone:
 BestTime:
 Mobile : (317)271-1667
 Fax : (317)271-2799
 Email : SALES@DRWATSONCO.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
 A VECTREN GAS LINE HAS BEEN HIT IN THE FRONT OF THE PROPERTY - GAS CAN BE
 SMELLED BUT ITS FAINT - CALLER HAS NOT CALLED 911 BUT WAS ADVISED TO DO SO -
 CREW IS ON SITE - CALLER HAS NOT CALLED THE UTILITY YET BUT WAS ALSO ADVISED TO
 DO SO - PREVIOUS TICKET NUMBER IS 1207241002 - THANK YOU
 Will you be white-lining the dig site area? NO
 :

Submitted date: 07/31/2012 Time: 08:29
 Members: ID0002 ID1501 ID2980 ID4471 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CITIZENS WATER / FORMERLY VEOLIA WATER	WATER
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
VECTREN - DANVILLE	GAS
WEST CENTRAL CONSERVANCY DISTRICT	

[View Map](#) | [Close Map](#)

Service Order Status

Monday, August 13, 2012

Enter Service Order Number:

5324446



Order History Request Date

Banner Instance: CS03PROD CS01PROD CS02PROD
Order Number: N5324446
Order Type: LEAK
Order Status: Completed

Customer: 620277326 - BEAZER HOMES INDIANA, LLP
Prem: 5715890 - 670 COLIN DR

Technician: 2256 - Godfrey, Gary

Order Dates and Times

Need Date: 7/31/2012 8:56:00 AM
Time Created: 7/31/2012 8:38:58 AM
Time Dispatched: 7/31/2012 8:38:58 AM
Time In Route: 7/31/2012 8:41:14 AM
Time On-Site: 7/31/2012 8:53:10 AM
Tech Complete: 7/31/2012 9:11:35 AM
Time Closed: 7/31/2012 9:11:35 AM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current ReadStatus

Old Meter:
New Meter:

Completion Notes

1" PLASTIC SERVICE NICKED BY CONT. CREW ON SITE TO REPAIR. LEFT IT TO THEM G.GODFREY

Request Notes

HIT LINE ON NORTH SIDE OF PROPERTY ...LEAKING PER SHERRI WITH 811...317-893-1416...CONT DR WATSON 31 7-271-1667...XST: JESSICA LANE...LOCATES 1207241002...

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	7/31/2012 8:40:12 AM	Godfrey, Gary
AsnAssignmentEnRoute_evt	7/31/2012 8:41:14 AM	Godfrey, Gary
AsnAssignmentOnSite_evt	7/31/2012 8:53:10 AM	Godfrey, Gary
OrdOrderComplete_evt	7/31/2012 9:11:35 AM	Godfrey, Gary

NOTE: The Reporting database replicates in near real-time; it has been approximately 1 minute(s) since the last transaction replicated.

MISCELLANEOUS CASH RECEIPT

(PLEASE ATTACH A COPY OF ALL CHECKS TO THIS FORM AND
USE PAPER CLIPS/DO NOT STAPLE CHECKS TO FORM)

PROCESS ROUTING FOR ALL VECTREN COMPANIES INCLUDING UTILITIES
AND NON REGULATED SUBSIDIARIES: SEND COMPLETED FORM,
ORIGINAL CHECK AND COPY OF CHECK TO REBECCA MINEAR IN
FINANCIAL ACCOUNTING, BRAUN BUILDING, EVANSVILLE. RETAIN COPY
OF CHECK AND FORM FOR YOUR RECORDS. PLEASE INCLUDE PROPER
ACCOUNTING SO RECEIPT MAY BE CREDITED ACCURATELY. PLEASE
INCLUDE YOUR PHONE NUMBER SO THE RECEIPT MAY BE EASILY
RESEARCHED BY THE FINANCIAL ACCOUNTING GROUP.

Activity Date: 9/14/2012
12:00:00 AM
Your Name, not your initials (employee): Pam Barber
Your Phone Number (employee): 812-491-4734
Party Check Received From (Check Payor):
Address of Check Writer (Check Payor):
BATCH1-DR WATSON CO INC

Check Number 1179
Amount of Check \$409.32
Utility/Company Name VECTREN ENERGY DELIVERY OF INDIANA - NORTH
Task Number 103.0510
Job Number FDS0016642

Date Printed: 9/17/2012

Transaction Information G-5307598 CHI-861239 2012/09/14

[Back to Table of Contents](#)

Transaction Level Details

Env Num	2	Envelope	G-5307598
Transaction	G-5307598	Lockbox	CHI-861239
Date	2012/09/14	Time	17:00
Batch	1	Batch Item	2
Check	2	Amount	\$409.32
ABA/RT	074014187	Account Num	300728435
Check Num	001179		

Envelope and Check Image

1179

D.R. WATSON CO., INC.
1966 MIDWEST BLVD. SUITE B
INDIANAPOLIS, IN 46214-4314
(317) 271-1667

FIRST INTERNET BANK
20-1418/740

9/11/2012

PAY TO THE ORDER OF: VECTREC UTILITIES HOLDING GROUP, INC. \$409.32

Four Hundred Nine and 32/100 DOLLARS

VECTREN UTILITIES HOLDING GROUP, INC.
1239 RELIABLE PARKWAY
CHICAGO, IL 60688-0012

MEMO *Phonda [Signature]* AUTHORIZED SIGNATURE

⑈001179⑈ ⑆074014187⑆ 300728435⑈

D. R. WATSON CO., INC
1966 MIDWEST BLVD
SUITE B
INDIANAPOLIS, IN 46214

Liberty
FOREVER

Vectren Utilities Holding Group, Inc.
1239 Reliable Parkway
Chicago, IL 60688-0012

606880012 ⑈001179⑈

Transaction Level Keyed Data

Remitter Name : DR WATSON CO INC Check Date : 2012/09/11

Invoice Level Keyed Data

Invoice Number	Reference Number
FDS0016642	32338

		NOW DUE
2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH		FINAL
		\$408.32
WATSON, D R CO 1988 MIDWEST BLVD, INDIANAPOLIS, IN 46214	Type: GAS Invoice: FDS0016642 BillToID: 32338 Billing Date: 9/6/2012 Date of Loss: 7/31/2012 5953 103.0510	
Please return this portion with your remittance.		