



Pipeline Safety Division Investigation Report

Investigation regarding: Precision Utilities Group Inc

UPPAC Database Record ID: 3543

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 8/7/2012 9:32:52 PM

Damage Address: 6450 E Haythorne Ave, Terre Haute, Vigo

The Parties

Excavator: **Precision Utilities Group Inc**

Address: 5714 Saint Joe Road, Ft Wayne, In 46835

Facility Owner: **Vectren**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Boring

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 6

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$3109

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1208012027

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A four inch (4") plastic gas line was damaged during excavation for a telecommunications line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 9/27/2012. The excavator had a valid locate request however, the operator failed to locate the Natural gas facility.

Conclusion: There was a failure to locate the natural gas facility.

Violation: 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

September 18, 2012

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

Subject: Investigation Request for Information

Date of Event: 8/7/2012

Event Location: 6450 E Haythorne Ave, Terre Haute

Facility Owner: Vectren

Excavator: Precision Utilities Group Inc

Other Party: N/A

Pipeline Division Case No. 3543

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation, maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.**



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: 9-28-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (*number and street*): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (*area code*): 812-491-4227

Fax number (*area code*): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Precision Utilities Group Inc.

Business address (*number and street*): 5714 St Joe Rd.

City, State, and ZIP code: Ft Wayne, IN 46835

Telephone number (*area code*): 260-485-8300

Fax number (*area code*): 260-485-8398

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Boring

Type of work performed: Telecommunications

Date and Location of Damage

Date of damage (month, day, year): 8-7-2012

County: Vigo

City: Terre Haute

Street address (number and street, city, state, and ZIP code):
6450 E Haythorne Avenue, Terre Haute, IN

Nearest intersection: Unknown

Right of way where damage occurred: Public - County Road

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 6

Time to restore service (in hours): 14

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 3,108.55

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Distribution

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1208012027

Was the locate request completed within two working days? No

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC _____

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? No

Type of markings used: Other

If other, please specify: None _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? No

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Facility marking or location not sufficient

Additional Comments

4" plastic main damaged by bore. Not Marked.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH


NOW DUE

\$3,108.55

USIC INC
9045 N RIVER ROAD, SUITE 300
INDIANAPOLIS, IN 46240

Type: GAS
Invoice: FDS0016685
BillToID: 32365
Billing Date: 9/7/2012
Date of Loss: 8/7/2012
5950 103.0509

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holdings Company
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE

\$3,108.55

USIC INC
9045 N RIVER ROAD, SUITE 300
INDIANAPOLIS, IN 46240

Type: GAS
Invoice: FDS0016685
BillToID: 32365
Billing Date: 9/7/2012
Date of Loss: 8/7/2012

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 6450 E HAYTHORNE AVE, TERRE HAUTE
4" PLASTIC MAIN DAMAGED BY BORE. NOT MARKED.

Material:	\$78.76
Company Labor:	\$1,860.05
Contract Labor:	\$0.00
Transportation/Equipment:	\$463.13
Misc:	\$0.00
Gas Loss:	\$706.61
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$3,108.55

5950 103.0509

Remember, call two (2) working days before digging. Contact I.U.P.S. at 1- 800-382-5544.

Task No: 103.0509 Capital / O&M (circle one)

Vectren Claim Number: _____

Date of Damage 8/17/12

Police Report / MO #: _____

Cost Center # 5950

Time Occurred 7:45 am / pm

Time Found 8:10 am / pm

Latitude 39.5750 Longitude: 87.318757

FACILITIES DAMAGE REPORT

GAS

Vectren Claims Camera:

VE00107

Form 3112

DAMAGE SITE:

Address 6450 E HAYTHORNE AVE Lot # _____

County UNION City TERRE HAUTE State IN Township LOST CREEK

FACILITY TYPE:

- Distribution Propane
- Service Storage
- Transmission: (include supplemental report)

FACILITIES DAMAGED:

	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Other			

1.693

VISUAL OBSERVATION AT DAMAGE SITE:

- Visual Observation: Above Ground Below Ground
- Locate Applicable Yes No N/S
- Facilities Properly Marked Yes No N/S
- Marking Methods: Conventional Flags None Whiskers
- Offset Paint Stakes
- Locate Marking Faded: Yes No N/S
- Wrong Address Requested Yes No N/S

Facilities Improperly Located:

- Qualified Locator Could Not Have Accurately Located
- Inaccurate Maps / Cards
- Broken or No Tracer Wire (Plastic)
- Insulation Preventing Accurate Locate

Locator Error:

- Failure to Follow Policy
- Inappropriate Site Markings
- Incomplete Locate
- No Locates Performed
- Qualified Locator Could Have Accurately Located
- Wrong Address Located
- Marking Off By: _____ (Feet / Inches)

AUG 13 2012

TYPE OF MATERIAL:

- Cast Iron
- Plastic (HDPE)
- Plastic (MDPE)
- Steel
- Other _____

Severed fractured Size 1 1/2 x 1 1/2

133.967

133.967

133.967

133.967

133.967

133.967

133.967

133.967

133.967

133.967

133.967

133.967

133.967

133.967

DAMAGE TYPE:

- Severed
- Not Cut
- Severed fractured
- Other _____

PRESSURE:

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 55 PSIG
- 60 PSIG
- 6 WC (.2163)
- 7 WC (252)
- Other _____

PROTECTION IN PLACE:

- Building Fence None
- Post Rail Vault N/A
- Other _____

DURATION OF ESCAPING GAS:

Minutes: 55 minutes

LEAK REPORT

NUMBER: MAXIMO 8188459

LEAK DISC

EFV Activated Yes No N/S

FEED TYPE:

- One-Way Feed
- Two-Way Feed

Number of Customers Affected: 6

Total Hours Service Was Off: 14 hrs

SERVICE ORDER NUMBER: AT 5383251

DAMAGED BY:

- Company Crew
- Contractor
- County
- Developer
- Farmer
- Municipality
- Property Owner/ Tenant
- Railroad
- State
- Unknown
- Utility
- Vehicle Accident
- Other _____

TYPE OF CONSTRUCTION:

- Agriculture
- Building Construction
- Building Demolition
- Cable TV
- Curbs / Sidewalk
- Drainage
- Driveway
- Electric
- Engineering / Surveying
- Fencing
- Grading
- Irrigation
- Landscaping
- Liquid Pipeline
- Milling
- Pole
- Natural Gas
- Public Transit Authority
- Railroad Maintenance
- Other Phone

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:

- Locate Ticket: 12088012027
- Date: 8-3-12 Time: 1:30 am / pm

TYPE OF REQUEST:

- Regular Request Emergency Request
- Locate Company Notified
- Contact Name: _____
- Time Called: _____ am / pm
- Time Locator Arrived at the Site: _____ am / pm

Company Notified of Locate Near Critical Facilities

- Yes No N/S

Copy of Mark Out Request Provided Within 2 Working Days

- Yes No N/S

ONE-CALL CENTER:

- IUPPS
- OUPS
- Unknown

Vectren Claim Number: _____

TYPE OF EQUIPMENT:

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other _____

ROOT DAMAGING CAUSE:

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other _____

CONTRACTOR REPAIRS:

- Contractor Working for Vectren Made Repairs at Own Expense
 Yes No N/S
- Contractor Repaired Damage
 Yes No N/S

Name of Contractor: _____
 # of Regular Hours; _____
 # of Overtime Hours; _____
 # of Regular Hours; _____
 Crew Type: _____

MATERIALS OR ROAD WORK:

- Meter was replaced _____ (Stores Code)
- Regulator Was Replaced _____ (Stores Code)
- Temporary Asphalt Repair: _____ (sq. ft.)
- Permanent Asphalt Repair: _____ (sq. ft.)

RIGHT OF WAY:

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

- Did Excavator Notify You Yes No
- Excavation Required Yes No
- Media at Site Yes No
- Was There Ignition of Gas? Yes No
- INVOICE: Yes No N/S

DAMAGING PARTY:
 Name: Precision Utilities Group
 Address: 5714 SAINT JOE RD
 City/ State/ Zip: FORT WAYNE, IN, 46835
 Phone: (260) 485-8300
 Prepared / Investigated By: Amalal Deaper Date: 8-7-12

PARTY TO INVOICE:
 Name: _____
 Address: SAME USIC
 City/ State/ Zip: _____
 Phone: () _____
 Reviewed by Field Supervisor: [Signature] Date: 8/8/12

NORMAL NOTICE

Ticket : 1208012027 Date: 08/01/2012 Time: 01:10 Oper: SPENCER.PACULA Chan:000

State: IN Cnty: VIGO Twp: LOST CREEK
 Cityname: TERRE HAUTE Inside: N Near: Y
 Subdivision:

Address : 6450
 Street : E HAYTHORNE AVE
 Cross 1 : N HUNT ST Within 1/4 mile: Y
 Location: LOCATE ENTIRE PROPERTY AND ALL EASEMENTS - LOCATE FROM PROTECTOR ON
 THE STRUCTURE TO FRONTIER LEAD 30900 AND PED-POLE 95S1 - PLEASE FLAG AND PAINT -
 THANK YOU
 ***Boring Where = ROAD

:
 Grids : 3931D8718A 3931D8719D 3931D8719C 3931D8719B 3931D8719A
 Grids : 3931C8719A

Work type : BURY PHONE DROP
 Done for : FRONTIER
 Start date: 08/03/2012 Time: 13:30 Hours notice: 60/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
 Duration : 3 WEEKS Depth: 6 FEET

Company : PRECISION UTILITIES GROUP INC Type: CONT
 Co addr : 5714 SAINT JOE ROAD
 City : FT WAYNE State: IN Zip: 46835
 Caller : SPENCER PACULA Phone: (260)485-8300
 Contact : SPENCER PACULA OFFICE Phone:
 BestTime:
 Mobile : (260)485-8300
 Fax : (260)485-8398
 Email : SPENCERPACULA@PRECISIONUG.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PRECISION REFERENCE NUMBER - 8124600484
 Will you be white-lining the dig site area? NO
 :

Submitted date: 08/01/2012 Time: 01:10
 Members: ID0002 ID5790 ID7754 ID8000 ID8729 SM

Member Name	Facility Types
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
TEXAS GAS TRANSMISSION - SHELburn PIPELINE	
TIME WARNER CABLE - TERRE HAUTE	CABLE TV
VECTREN - TERRE HAUTE	GAS

[View Map](#) | [Close Map](#)

DAMAGE

Ticket : 1208073625 Date: 08/07/2012 Time: 21:25 Oper: SWOODFORD Chan:022

State: IN Cnty: VIGO Twp: LOST CREEK
 Cityname: TERRE HAUTE Inside: N Near: Y
 Subdivision:

Address : 6450
 Street : E HAYTHORNE AVE
 Cross 1 : N HUNT ST Within 1/4 mile: Y
 Location: LOCATE ENTIRE PROPERTY AND ALL EASEMENTS - LOCATE FROM PROTECTOR ON THE STRUCTURE TO FRONTIER LEAD 30900 AND PED-POLE 95S1 - PLEASE FLAG AND PAINT - THANK YOU
 ***Boring Where = ROAD

Grids : 3931D8718A 3931D8719D 3931D8719C 3931D8719B 3931D8719A
 Grids : 3931C8719A

Work type : BURY PHONE DROP
 Done for : FRONTIER
 Start date: 08/07/2012 Time: 21:26 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y
 Duration : 3 WEEKS Depth: 6 FEET

Company : PRECISION UTILITIES GROUP INC Type: CONT
 Co addr : 5714 SAINT JOE ROAD
 City : FT WAYNE State: IN Zip: 46835
 Caller : SHANE GANN Phone: (260)485-8300
 Contact : SPENCER PACULA OFFICE Phone:
 BestTime:
 Mobile : (260)485-8300
 Fax : (260)485-8398
 Email : SPENCERPACULA@PRECISIONUG.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PER SHANE GANN--A VECTREN GAS LINE HAS BEEN DAMAGED--HAS NO INFORMATION ON THE SIZE AND COLOR OF LINE--LINE WAS HESSING--PER SHANE HAS CONTACTED VECTREN--AND IS ON SITE REPAIRING LINE NOW--WAS DIGGING ON THE SOUTH SIDE OF THE ROAD AT THE WEST END OF THE PROPERTY ACROSS THE STREET FROM THE TERMINAL OF 951--CREW IS ON SITE--PREVIOUS TICKET NUMBER 1208012027.
 Will you be white-lining the dig site area? NO

Submitted date: 08/07/2012 Time: 21:25
 Members: ID0002 ID5790 ID7754 ID8000 ID8729 SM

Member Name	Facility Types
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
TEXAS GAS TRANSMISSION - SHELBURN PIPELINE	
TIME WARNER CABLE - TERRE HAUTE	CABLE TV
VECTREN - TERRE HAUTE	GAS

[View Map](#) | [Close Map](#)

Service Order Status

Tuesday, August 14, 2012

Enter Service Order Number:

5333251



Enter Form Refresh Data

Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: N5333251

Order Type: INVE

Order Status: Completed

Customer: 008888888 - INACTIVE CUSTOMER

Prem: 5722130 - 6450 E HAYTHORNE

Technician: 2752 - Draper, Don

Order Dates and Times

Need Date: 8/7/2012 8:09:00 PM
Time Created: 8/7/2012 7:56:51 PM
Time Dispatched: 8/7/2012 7:56:51 PM
Time In Route: 8/7/2012 7:58:11 PM
Time On-Site: 8/7/2012 8:42:18 PM
Tech Complete: 8/7/2012 11:45:14 PM
Time Closed: 8/7/2012 11:45:14 PM

Events Performed/Completion Code

IVEG - CMP

Meter Information

Current ReadStatus

Old Meter:

New Meter:

Completion Notes

contractor had bored into a 4in plastic gas main, was blowing, cut out 12in of main and electric fused in new piece, did not see any locates, contractors locate # is 1208012027

Request Notes


PER AMANDA WITH VIGO 911, 812-232-3801. HIT 2 INCH MAIN, GAS BLOWING NEAR A PARK, SOME RESIDENTIAL, THIS IS THE 2ND DR OFF E OF HUNTSHANE GANN HIT LINE, 260-409-9564, F/D & HASMAT ENROUTE.

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentManualAck_evt	8/7/2012 7:57:35 PM	Draper, Don
AsnAssignmentEnRoute_evt	8/7/2012 7:58:11 PM	Draper, Don
AsnAssignmentOnSite_evt	8/7/2012 8:42:18 PM	Draper, Don
OrdOrderComplete_evt	8/7/2012 11:45:14 PM	Draper, Don

NOTE: The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

Precision Utilities Group, Inc.
5714 St. Joe Road
Fort Wayne, IN 46835



RECEIVED

SEP 27 2012

INDIANA UTILITY
REGULATORY COMMISSION

Indiana Utility Regulatory Commission

In reference to case #3543 @ 6450 E Haythorne Ave, Terre Haute, IN
Precision Utilities Group, INC is disputing this violation due to the fact
That we did call in a notice of excavation and the job site was marked
OK / Vectron on job site. The gas line that was hit was not located
Correctly by Vectren locators. Attached is a copy of the locate ticket
1208012027 .

Thank you

Tom Salkeld

Director of Buried Drops



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

September 14, 2012

Shane Gann
Precision Utilities Group Inc
5714 Saint Joe Road
Ft Wayne, In 46835

**Re: Notice of Preliminary Determination of Violation
Pipeline Safety Division Case No. 3543**

Date of Event: 8/7/2012
Event Location: 6450 E Haythorne Ave, Terre Haute, Vigo County
Excavator: Precision Utilities Group Inc
Facility Owner: Vectren

Dear Shane Gann,

On behalf of the Indiana Utility Regulatory Commission ("Commission"), I am writing to inform you that information has been filed with the Commission's Pipeline Safety Division regarding an alleged violation of Indiana Code chapter 8-1-26, the Indiana Damage to Underground Facilities Act ("the Act"). You are receiving this letter because you have been identified as the Respondent Excavator.

To ensure safety, the Indiana Underground Plant Protection Service (Indiana 811) and gas operators routinely provide reports to the Pipeline Safety Division when an operator's facility is damaged. The Division has received a report from one of these entities that on **8/7/2012**, you or your business damaged a pipeline facility owned by **Vectren** and located at **6450 E Haythorne Ave, Terre Haute, Vigo County**.

Based upon the information received, the Pipeline Safety Division is commencing an investigation into the event concerning you or your business to determine whether any statutory violations were committed regarding public safety, specifically the following:

- IC 8-1-26-16(g): Failure to provide notice of excavation.
- IC 8-1-26-16(h): Failure to perform required white lining.
- IC 8-1-26-20(b): Failure to maintain two (2) feet clearance with mechanized equipment.
- IC 8-1-26-18(f): Failure to properly locate facilities (operator violation)

The Division provides both you and Vectren with an opportunity to send in documentation explaining what occurred. This may include maps, photographs, narrative statements, and any other evidence you wish to provide. You have thirty (30) days from the date this letter is received to send in information, but an extension may be given for good cause shown. Please note that the Division's

NORMAL NOTICE

Ticket : 1208012027 Date: 08/01/2012 Time: 01:10 Oper: SPENCER.PACULA Chan:000

State: IN Cnty: VIGO Twp: LOST CREEK
 Cityname: TERRE HAUTE Inside: N Near: Y
 Subdivision:

Address : 6450
 Street : E HAYTHORNE AVE
 Cross 1 : N HUNT ST Within 1/4 mile: Y
 Location: LOCATE ENTIRE PROPERTY AND ALL EASEMENTS - LOCATE FROM PROTECTOR ON
 THE STRUCTURE TO FRONTIER LEAD 30900 AND PED-POLE 95S1 - PLEASE FLAG AND PAINT -
 THANK YOU

***Boring Where = ROAD

:

Grids : 3931D8718A 3931D8719D 3931D8719C 3931D8719B 3931D8719A
 Grids : 3931C8719A

Work type : BURY PHONE DROP
 Done for : FRONTIER
 Start date: 08/03/2012 Time: 13:30 Hours notice: 60/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N
 Duration : 3 WEEKS Depth: 6 FEET

Company : PRECISION UTILITIES GROUP INC Type: CONT
 Co addr : 5714 SAINT JOE ROAD
 City : FT WAYNE State: IN Zip: 46835
 Caller : SPENCER PACULA Phone: (260)485-8300
 Contact : SPENCER PACULA OFFICE Phone:
 BestTime:
 Mobile : (260)485-8300
 Fax : (260)485-8398
 Email : SPENCERPACULA@PRECISIONUG.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PRECISION REFERENCE NUMBER - 8124600484
 Will you be white-lining the dig site area? NO
 :

Submitted date: 08/01/2012 Time: 01:10
 Members: ID0002 ID5790 ID7754 ID8000 ID8729 SM

Member Name	Facility Types
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
TEXAS GAS TRANSMISSION - SHELBURN	PIPELINE
TIME WARNER CABLE - TERRE HAUTE	CABLE TV
VECTREN - TERRE HAUTE	GAS

[View Map](#) [Close Map](#)