



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

## Pipeline Safety Division Investigation Report

### Investigation regarding: **Berry-it, Inc.**

UPPAC Database Record ID: 3681

Report Date: 9/11/2013

Investigator: Mike Orr

Damage Date: 8/27/2012 12:18:37 PM

Damage Address: Michigan Rd, Plymouth, Marshall

### The Parties

Excavator: **Berry-it, Inc.**

Address: 225 West 450 North, Kokomo, In 46901

Facility Owner: **NIPSCO**

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Trencher

Type of Work Performed: Telecommunications

### Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 2

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

### Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1208142043

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

**Synopsis:** Excavator struck and damaged an underground natural gas service while performing telecommunications work.

**Findings:** Reported by Indiana 811; excavator did not respond to initial notice mailed 9/14/2012. Excavator had a valid locate ticket; however, the gas operator self reported failing to provide locate markings for a live service stub.

**Conclusion:** There was a failure to provide facility locate markings.

**Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.**



101 West Ohio Street, Suite 1707  
Indianapolis, IN 46204

October 22, 2012

*Via Electronic Transmission – [PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)*

Pipeline Safety Division – Case No. 3681  
Indiana Utility Regulatory Commission  
101 West Washington Street, Suite 1500 East  
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3681

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 8/27/2012

Event Location: Michigan Rd, Plymouth

Facility Owner: Northern Indiana Public Service Company

Excavator: Berry-it, Inc.

Other Party: N/A

Pipeline Division Case No. 3681

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher Earle".

Christopher C. (Kit) Earle  
NiSource Corporate Services - Legal  
Phone: 317-684-4904  
Fax: 317-684-4918  
Email: [cearle@nisource.com](mailto:cearle@nisource.com)

<b>IURC INFORMATION REQUEST</b>	
<b>Pipeline Safety Division Case No. 3681</b>	
Date of Event	8/27/2012
Event Location	Michigan Rd, Plymouth
Facility Owner	Northern Indiana Public Service Company
Excavator	Berry-it, Inc.
Date of IURC Information Request	9/18/2012
<b>THE PARTIES</b>	
<b>EXCAVATOR:</b>	
BUSINESS NAME	Berry-It Inc
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	225 W 450 N
CITY/ STATE/ZIP	Kokomo, IN 46901
PREFERRED TELEPHONE	(765)450-8804
CELL PHONE TELEPHONE	(317)508-2807
EMAIL ADDRESS	DISPATCH@BERRYIT.NET
<b>FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:</b>	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
<b>LOCATOR SERVICE INFORMATION</b>	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
<b>OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION</b>	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	

TITLE (IF ANY)	
ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
<b>UTILITY LINE IMPACT</b>	
<b>LOCATION OF DAMAGE</b>	
ADDRESS	12003 Michigan Rd
CITY/STATE/ZIP	Plymouth
NEAREST INTERSECTION	12 <sup>th</sup> Rd
<b>PRODUCT TYPE (Select One)</b>	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
<b>FACILITY TYPE (Select One)</b>	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	2
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) (\$)	
<b>CAUSE OF DAMAGE INFORMATION:</b>	
<b>TYPE OF EQUIPMENT (Select One)</b>	
Auger	
Backhoe/Trackhoe	
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	

Probing Device	
Trancher	X
Vacuum Equipment	
Unknown/Other	
<b>TYPE OF WORK PERFORMED (Select One)</b>	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	X
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y - 1208271702
<b>LOCATE INFORMATION:</b>	

EXCAVATOR REQUEST LOCATE (YES/NO)	Y
INDIANA 811 LOCATE TICKET NUMBER	1208142043
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	N
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
<b>INCIDENT IMPACT INFORMATION</b>	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	
POLICE DEPARTMENT RESPONSE (YES/NO)	
AMBULANCE RESPONSE (YES/NO)	
<b>ADDITIONAL INFORMATION/COMMENTS</b>	
Excavator struck unmarked service stub leading to retired farm tap.	

From: IRTHNet At: 08/27/12 11:19 AM Seq No: 56  
Facility: Transmission Lines

# 3681

NIPSCO 00588 IUPPSa 08/27/2012 12:18:42 1208271702-00A EMER DAMG STRT

DAMAGE

Ticket : 1208271702 Date: 08/27/2012 Time: 12:15 Oper: TFRICKE Chan:028

State: IN Cnty: MARSHALL Twp: CENTER  
Cityname: PLYMOUTH Inside: N Near: Y  
Subdivision:

Address :

Street : MICHIGAN RD

Cross 1 : 12TH RD Within 1/4 mile: Y

Location: PAINT AND FLAG ENTIRE AREA FROM NORTHEAST CORNER OF MICHIGAN RD AND  
GRAVEL DR GOING SOUTH DOWN WEST SIDE OF MICHIGAN RD TO 12TH RD ACROSS 12TH RD  
TO

SOUTHWEST CORNER OF MICHIGAN RD AND 12TH RD

\*\*\*Boring Where = DIRECTIONAL

:

Grids : 4118D8616B 4118D8616A

Boundary: n 41.304108 s 41.301895 w -86.280495 e -86.278145

Work type : FIBER

Done for : FRONTIER

Start date: 08/27/2012 Time: 12:15 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y

Duration : 2 WEEKS Depth: 12 FEET

Company : BERRY-IT INCORPORATED Type: CONT

Co addr : 225 WEST 450 NORTH

City : KOKOMO State: IN Zip: 46901

Caller : KAMIE ALLEN Phone: (765)450-8804

Contact : DAN JONES Phone:

BestTime:

Mobile : (765)450-8804

Fax : (765)450-6042

Email : DISPATCH@BERRYIT.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time  
PER DAN - A NIPSCO GAS LINE HAS BEEN CUT - LINE IS BLOWING - ADVISE CALLER TO  
CONTACT 911 - DOES NOT KNOW WHAT SIZE OF COLOR LINE IS - NIPSCO HAS BEEN  
CALLED

- DIGGING IN EASEMENT - CREW IS ON SITE - PREVIOUS TICKET 1208142043

Will you be white-lining the dig site area? NO

:

Submitted date: 08/27/2012 Time: 12:15

NIPSCO 00642 IUPPSa 08/14/2012 12:03:42 1208142043-00A NORM NEW STRT

NORMAL NOTICE

Ticket : 1208142043 Date: 08/14/2012 Time: 12:00 Oper: KAMIE.ALLEN Chan:000

State: IN Cnty: MARSHALL Twp: CENTER  
 Cityname: PLYMOUTH Inside: N Near: Y  
 Subdivision:

#3681

Address :

Street : MICHIGAN RD  
 Cross 1 : 12TH RD Within 1/4 mile: Y  
 Location: PAINT AND FLAG ENTIRE AREA FROM NORTHEAST CORNER OF MICHIGAN RD AND GRAVEL DR GOING SOUTH DOWN WEST SIDE OF MICHIGAN RD TO 12TH RD ACROSS 12TH RD TO SOUTHWEST CORNER OF MICHIGAN RD AND 12TH RD  
 \*\*\*Boring Where = DIRECTIONAL

:  
 Grids : 4118D8616B 4118D8616A  
 Boundary: n 41.304108 s 41.301895 w -86.280495 e -86.278145

Work type : FIBER  
 Done for : FRONTIER  
 Start date: 08/16/2012 Time: 12:15 Hours notice: 48/48 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
 Duration : 2 WEEKS Depth: 12 FEET

Company : BERRY-IT INCORPORATED Type: CONT  
 Co addr : 225 WEST 450 NORTH  
 City : KOKOMO State: IN Zip: 46901  
 Caller : KAMIE ALLEN Phone: (765)450-8804  
 Contact : DAN JONES Phone:  
 BestTime:  
 Mobile : (317)508-2807  
 Fax : (765)450-6042  
 Email : DISPATCH@BERRYIT.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 Will you be white-lining the dig site area? NO

:

Submitted date: 08/14/2012 Time: 12:00  
 Members: COMCN ID2034 ID3161 NIPSCO SBCIN SM ID5857

#### Audit History:

**8/14/2012 11:03:49 AM:** Received  
*DETAILS:* Ticket received for registration code NIPSCO

#### Audit History: Distribution Lines

**8/14/2012 11:03:49 AM:** Put in Folder  
*DETAILS:* Put in REGION 2 by auto process  
*NOTE:* Auto Processed per State, County, and Place

**8/14/2012 11:05:34 AM:** Assigned  
*DETAILS:* Assigned to USIC by Steve Noffsinger

**8/14/2012 11:05:34 AM:** Ticket Queued  
*DETAILS:* Ticket queued for delivery

**8/14/2012 11:05:37 AM:** Ticket Delivered  
*DETAILS:* Ticket successfully sent to onecall7+indy-nipsco2@smptickets.com

#### Audit History: Transmission Lines

**8/14/2012 11:03:49 AM:** Put in Folder

**Fact Based Investigation Report**

**NOTIFICATION ID:** 01820120827005                      **DISTRICT:** Northern IN  
**DAMAGE DATE:** 8/27/2012 12:18:42 PM      **NOTIFICATION DATE:** 8/27/2012 12:25:15 PM  
**NOTIFIED BY:** KAMIE ALLEN  
**DAMAGE ADDRESS:** MICHIGAN RD  
**CITY:** PLYMOUTH                      **ST:** IN    **ZIP:**

---

**DAMAGED CUSTOMER:** NIPSCO

---

**INVESTIGATION DATE:** 08/27/2012  
**FROM:** 13:15:00                                      **TO:** 15:00:00

---

**EXCAVATOR INVOLVED:** BERRY IT INC  
**TYPE OF EXCAVATION:** FIBER INSTALL

---

**ORIG. LOCATE REQ.:** 1208142043                      **START DATE/TIME:**  
**TYPE OF TICKET:**                                      **LOCATE REQ. INFO N/A:**

---

**DIG UP/DAMAGE REQ.:** 1208271707                      **START DATE/TIME:**

---

**PICTURES TAKEN BY:** JIM HOSTETLER    **DATE/TIME:** 8/27/2012 2:45:00 PM  
**PHOTOGRAPHY TYPE:** Digital                      **FRAME #:** NA

---

**INVESTIGATOR EMP#:** 117330                      **INVESTIGATOR NAME:** BRAD WELLMAN  
**BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED?** No

---

**Fact Based Investigation Customer Information**

**NOTIFICATION ID:** 01820120827005  
**SELECT A CUSTOMER:** NIPSCO  
**CUSTOMER #:** *(optional)*

---

**FACILITY DESCRIPTION:** LOWPROF                      **FACILITY ID:** service - 2"  
**LOCATOR NAME & EMP #:** Ferguson Richard - 112319  
**LOCATOR NOT KNOWN:**

---

**CHECK ALL THAT APPLY TO INVESTIGATION:**

Other

**Other:** STUBBED SERVICE

---

**CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):**

Visual, Facility Exposed At Time Of Investigation,

Investigation Results Verified By Utility Representative

---

**INVESTIGATOR STATEMENT/CAUSAL FACTORS:**

CONTRACTOR TRENCHED THROUGH A STUBBED SERVICE, USED TO FEED A FARM WHICH IS NO LONGER THERE, EMPTY LOT, NO FOUNDATION, RISER. NIPSCO CUT MAIN OFF AS THIS WAS THE LAST HOUSE WHICH USED TO FEED OFF OF IT, 6 INCH ST. MAIN CAPPED OFF.

**NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**

GARRY KING

**NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**

NA

**LIST ANY OTHER INDIVIDUALS ON SITE:**

NA

---

**WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL?** Yes

**WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA?** No

**WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS?** No

**EXTENT OF FACILITY DAMAGE** CUT STUBBED SERVICE

**REPLACEMENT FOOTAGE** CAPPED OFF MAIN

**WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO?** No

**WHAT CONTRACTOR EQUIPMENT WAS USED?** NA

**IS THE FACILITY SHOWN ON THE UTILITY RECORDS?** No

**IF YES, PLEASE LIST RECORD #(S)**



Investigation Results Verified By Utility Representative

---

**INVESTIGATOR STATEMENT/CAUSAL FACTORS:**

CONTRACTOR TRENCHED THROUGH A STUBBED SERVICE, USED TO FEED A FARM WHICH IS NO LONGER THERE, EMPTY LOT, NO FOUNDATION, RISER. NIPSCO CUT MAIN OFF AS THIS WAS THE LAST HOUSE WHICH USED TO FEED OFF OF IT, 6 INCH ST. MAIN CAPPED OFF.

**NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**

GARRY KING

**NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**

NA

**LIST ANY OTHER INDIVIDUALS ON SITE:**

NA

---

**WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL?** Yes

**WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA?** No

**WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS?** No

**EXTENT OF FACILITY DAMAGE** CUT STUBBED SERVICE

**REPLACEMENT FOOTAGE** CAPPED OFF MAIN

**WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO?** No

**WHAT CONTRACTOR EQUIPMENT WAS USED?** NA

**IS THE FACILITY SHOWN ON THE UTILITY RECORDS?** No

**IF YES, PLEASE LIST RECORD #(S)**

# NORTHERN INDIANA PUBLIC SERVICE COMPANY FACILITY DAMAGE REPORT

\*\* COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES \*\*

REPORTING OPERATING AREA Plymouth MAXIMO WO # COST37 46204  
 OPERATING AREA CONTACT Bob Sommers JOB ORDER # 566127  
 TRACKING NUMBER 08 2012 0827006 LOCATE REF # \_\_\_\_\_  
 Locate Performed By: \_\_\_\_\_

DATE AND TIME OF ACCIDENT 8-27-2012, 12:26 PM DATE OF REPORT 8/28/12  
 PLACE OF DAMAGE (INCLUDE CITY) 12003 MICHIGAN RD - PLYMOUTH

**DAMAGE WAS TO:**

**ELECTRIC** - POLE / TRANSFORMER: # \_\_\_\_\_ SIZE \_\_\_\_\_ YEAR INSTALLED \_\_\_\_\_ BROKEN YES ( ) NO ( )

OTHER (DESCRIBE) \_\_\_\_\_

**GAS:** SERVICE  MAIN ( ) SIZE \_\_\_\_\_ MATERIAL: PLASTIC ( ) STEEL ( ) METER ( ) REG STATION ( )  STUB ( )  
 OTHER (DESCRIBE) \_\_\_\_\_

DEPTH OF FACILITY (inches) 38" PRESSURE (PSI) 92 Lbs.

RELEASE OF GAS: YES  NO ( ) IGNITION OF GAS: YES ( ) NO  EVACUATION REQUIRED: YES ( ) # \_\_\_\_\_ NO

INTERRUPTION OF SERVICE: YES  NO ( ) NUMBER OF CUSTOMERS LOST: 2

DURATION OF INTERRUPTION: TIME REPORTED 1226 TIME SHUT OFF 2230 TIME RESTORED 27 HR 2

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 3/4" LATER

LOCATE MARKS ON SITE: YES  DISTANCE BETWEEN FACILITY AND LOCATE MARKS 4 FT NO ( )  
 HOW LOCATED: PAINT ( ) FLAGS ( ) BOTH  WHITE LINED ( )

PARTY THAT CAUSED DAMAGES (NAME) Berry ET

ADDRESS OF PARTY (INCLUDE CITY) 1800 368-8511 225W CR 450N Rockton, IL 61154

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE Harry Brook

WITNESS NAME AND ADDRESS \_\_\_\_\_

WITNESS REMARKS \_\_\_\_\_

AGENCIES NOTIFIED / ONSITE: POLICE ( ) AGENCY \_\_\_\_\_ REPORT # \_\_\_\_\_

FIRE ( ) AGENCY \_\_\_\_\_ REPORT # \_\_\_\_\_

OTHER ( ) \_\_\_\_\_ Any Injuries? ( ) YES # \_\_\_\_\_  NO

PHOTOS TAKEN: YES ( ) NO  TAKEN BY: \_\_\_\_\_ (ATTACH PHOTOS TO REPORT)  
 MEDIA ON SITE YES ( ) NO

**WORK IN PROGRESS WHEN FACILITY DAMAGED** - CHECK APPROPRIATE CHOICE BELOW

- |  |                                     |  |  |
|--|-------------------------------------|--|--|
| <input type="checkbox"/> AGRICULTURE/FARMING | <input type="checkbox"/> CABLE TV   | <input type="checkbox"/> CURB/SIDEWALK | <input checked="" type="checkbox"/> TELECOMMUNICATIONS |
| <input type="checkbox"/> BLDG CONSTRUCTION   | <input type="checkbox"/> DEMOLITION | <input type="checkbox"/> DRAINAGE      | <input type="checkbox"/> WATER                         |
| <input type="checkbox"/> DRIVEWAY            | <input type="checkbox"/> ELECTRIC   | <input type="checkbox"/> SURVEYING     | <input type="checkbox"/> DRAINS/CULVERTS               |
| <input type="checkbox"/> FENCING             | <input type="checkbox"/> GRADING    | <input type="checkbox"/> IRRIGATION    | <input type="checkbox"/> MOWING                        |
| <input type="checkbox"/> LANDSCAPING         | <input type="checkbox"/> PIPELINE   | <input type="checkbox"/> MILLING       | <input type="checkbox"/> OTHER _____                   |
| <input type="checkbox"/> POLE/SIGN POST      | <input type="checkbox"/> ROAD WORK  | <input type="checkbox"/> SEWER         |  |

**TYPE OF EQUIPMENT USED** - CHECK APPROPRIATE CHOICE BELOW

- |  |  |  |
|--|--|--|
| <input type="checkbox"/> AUGER             | <input type="checkbox"/> HAND TOOLS          | <input type="checkbox"/> BACKHOE/TRACKHOE  |
| <input type="checkbox"/> MILLING EQUIPMENT | <input type="checkbox"/> PROBING DEVICE      | <input type="checkbox"/> BORING / DRILLING |
| <input type="checkbox"/> EXPLOSIVES        | <input checked="" type="checkbox"/> TRENCHER | <input type="checkbox"/> FARM EQUIPMENT    |
| <input type="checkbox"/> VACCUUM EQUIPMENT | <input type="checkbox"/> GRADER              | <input type="checkbox"/> OTHER _____       |

**REASON DAMAGE OCCURRED** - CHECK APPROPRIATE CHOICE BELOW

- |  |  |   |
|--|--|---|
| <input type="checkbox"/> AUTOMOTIVE ACCIDENT | <input type="checkbox"/> EXCAVATING BEFORE LOCATES DUE | <input type="checkbox"/> CARELESS MACHINE OPERATOR          |
| <input type="checkbox"/> NO NOTIFICATION     | <input type="checkbox"/> MARKS DISTURBED               | <input type="checkbox"/> STUB                               |
|  |  | <input checked="" type="checkbox"/> OTHER <u>NOT MARKED</u> |

• SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

COMMENTS: LIVE TO NON RETIRED FARM  
TAP - NO LOCATED MARKS BUT  
PRINTS SHOWED RETIRED STATION

PERSON PREPARING REPORT BRAD SOKITS

FIELD SUPERVISOR BOB SOMERS

FIELD MANAGER \_\_\_\_\_

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information

**FOR OFFICE USE ONLY:**

- |   |     |    |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE  | YES | NO |
| • NO IN 811 LOCATE CALLED IN                    | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE                                | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST  | YES | NO |

COMPLETED BY: Br A DATE: 5-27-11