



Pipeline Safety Division Investigation Report

Investigation regarding: NIPSCO

UPPAC Database Record ID: 3711

Report Date: 5/22/2013

Investigator: Mike Orr

Damage Date: 9/5/2012 3:16:59 PM

Damage Address: Parrish Ave, Cedar Lake, Lake

The Parties

Excavator: **Mcallister General Contractors**

Address: Po Box 810, Cedar Lake, In 46303

Facility Owner: **NIPSCO**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Construction

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1208012787

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service stub was damaged during excavation for a loading dock.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 11/19/2012. The excavator had a valid locate request however, the operator failed to locate a service stub due to inaccurate records.

Conclusion: There was a failure to provide accurate locate markings.

Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.



101 West Ohio Street, Suite 1707
Indianapolis, IN 46204

October 24, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3711
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3711

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 9/5/2012

Event Location: Parrish Ave, Cedar Lake

Facility Owner: Northern Indiana Public Service Company

Excavator: Mcallister General Contractors

Other Party: N/A

Pipeline Division Case No. 3711

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher Earle".

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 3711	
Date of Event	9/5/2012
Event Location	Parrish Ave, Cedar Lake
Facility Owner	Northern Indiana Public Service Company
Excavator	Mcallister General Contractors
Date of IURC Information Request	9/18/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	McAllister General Contractor
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	PO Box 810
CITY/ STATE/ZIP	Cedar Lake, IN 46303
PREFERRED TELEPHONE	219-374-9498
CELL PHONE TELEPHONE	219-746-3479
EMAIL ADDRESS	CSANDERS@MCALLISTERSINC.COM
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	9603 Lincoln Plz
CITY/STATE/ZIP	Cedar Lake, IN 46303
NEAREST INTERSECTION	Parrish Ave
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	¾" Steel
PRESSURE (PSIG/INCHES)	40
INTERRUPTION IN SERVICE (YES/NO)	N
NUMBER OF CUSTOMERS AFFECTED	0
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	X
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trancher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	X
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y- 1209053280
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1208012787
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	N
EXCAVATOR "WHITE LINED" (YES/NO)	Y
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	
POLICE DEPARTMENT RESPONSE (YES/NO)	
AMBULANCE RESPONSE (YES/NO)	
ADDITIONAL INFORMATION/COMMENTS	
<p>Facility could not be found/located. In service gas stub.</p>	

Fact Based Investigation Report

NOTIFICATION ID: 01820120905016 **DISTRICT:** Northern IN
DAMAGE DATE: 9/5/2012 3:55:00 PM **NOTIFICATION DATE:** 9/5/2012 3:59:33 PM
NOTIFIED BY: JOEL Facility Owner
DAMAGE ADDRESS: 9708 LINCOLN PLAZA
CITY: CEDAR LAKE **ST:** IN **ZIP:**

DAMAGED CUSTOMER: NIPSCO

INVESTIGATION DATE: 09/05/2012
FROM: 14:30:00 **TO:** 15:00:00

EXCAVATOR INVOLVED: MCALLISTER CONSTRUCTION
TYPE OF EXCAVATION: sewer/water

ORIG. LOCATE REQ.: 1208101511 **START DATE/TIME:** 8/21/2012 2:00:00 PM
TYPE OF TICKET: Ongoing Project **LOCATE REQ. INFO N/A:**

DIG UP/DAMAGE REQ.: 1209053280 **START DATE/TIME:** 9/5/2012 3:15:00 PM

PICTURES TAKEN BY: cody black **DATE/TIME:** 9/5/2012 2:45:00 PM
PHOTOGRAPHY TYPE: Digital **FRAME #:**

INVESTIGATOR EMP#: 134729 **INVESTIGATOR NAME:** cody black
BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED? No

Fact Based Investigation Customer Information

NOTIFICATION ID: 01820120905016
SELECT A CUSTOMER: NIPSCO
CUSTOMER #: (optional)

FACILITY DESCRIPTION: LOWPROF **FACILITY ID:** Gas Service
LOCATOR NAME & EMP #: Black Cody - 134729
LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:
Abandoned Facility

Other:

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):
Visual, Facility Exposed At Time Of Investigation

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

abandoned gas service hit to old grocery store that used to be on this site. No evidence of service was visible on site at time of locate. Service was supposed to be retired, but was capped off 15 feet out from the main, and was still active up to the capped off underground stub. Locator had no way of knowing it was there, and no way to hook to it. USIC not at fault

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

na

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

na

LIST ANY OTHER INDIVIDUALS ON SITE:

na

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? Yes

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? No

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? No

EXTENT OF FACILITY DAMAGE cut service

REPLACEMENT FOOTAGE none

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No

WHAT CONTRACTOR EQUIPMENT WAS USED? unknown

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? No

IF YES, PLEASE LIST RECORD #(S)

NIPSCO 01065 IUPPSa 09/05/2012 15:17:01 1209053280-00A EMER DAMG GRID

DAMAGE DAMAGE

Ticket : 1209053280 Date: 09/05/2012 Time: 15:13 Oper: RJOHNSON Chan:002

State: IN Cnty: LAKE Twp: HANOVER
Cityname: CEDAR LAKE Inside: Y Near: N
Subdivision:

*9603 W
LINCOLN PLZ
#3711
ON
DATABASE*

Address :

Street : PARRISH AVE

Cross 1 : W 133RD AVE Within 1/4 mile: Y

Location: FROM THE INTERSECTION--TRAVEL SOUTH ON THE WEST SIDE OF PARRISH AVE
FOR APPROX 300 FEET TO THE EMPTY LOT--LOCATE THE ENTIRE PROPERTY---AREA IS WHITE
LINED WITH INSTRUCTION FOR THE LOCATORS

Grids : 4122B8726A 4122B8727D 4122C8726A 4122C8727D

Boundary: n 41.378056 s 41.374435 w -87.451378 e -87.449852

Work type : NEW SEWER AND WATER

Done for : STRACK AND VANTIL

Start date: 09/05/2012 Time: 15:13 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 1 YEAR Depth: 6 FEET

Company : MCALLISTER GENERAL CONTRACTORS Type: CONT

Co addr : PO BOX 810

City : CEDAR LAKE State: IN Zip: 46303

Caller : CAROL SANDERS Phone: (219)374-9498

Contact : TOM CLELAND - CELL Phone:

BestTime:

Mobile : (219)746-3479

Fax : (219)374-7017

Email : CSANDERS@MCALLISTERSINC.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
GAS LINE HAS BEEN EXPOSED--NIPSCO IS THE UTILITY COMPANY--GAS LINE IS
BLOWING--UNKNOWN IF THEY CAN HEAR AND SMELL IT--UNKNOWN LOCATION OF THE DAMAGED
LINE--UNKNOWN DESCRIPTION--HAVE NOT CALLED 911--NIPSCO STATED NOT AN
EMERGENCY--CREW IS ON SITE--HAVE NOTIFIED NIPSCO TO REPORT THE DAMAGED
LINE--PREVIOUS TICKET 1208012787

Will you be white-lining the dig site area? YES

Submitted date: 09/05/2012 Time: 15:13

Members: COMCN IB ID7478 NIPSCO SM

NIPSCO 00917 IUPPSa 08/01/2012 15:48:07 1208012787-00A NORM NEW GRID

NORMAL NOTICE

Ticket : 1208012787 Date: 08/01/2012 Time: 15:35 Oper: LSTEVENSON Chan:018

3711

State: IN Cnty: LAKE Twp: HANOVER
Cityname: CEDAR LAKE Inside: Y Near: N
Subdivision:

Address :

Street : PARRISH AVE

Cross 1 : W 133RD AVE Within 1/4 mile: Y

Location: FROM THE INTERSECTION---TRAVEL SOUTH ON THE WEST SIDE OF PARRISH AVE
FOR APPROX 300 FEET TO THE EMPTY LOT--LOCATE THE ENTIRE PROPERTY---AREA IS WHITE
LINED WITH INSTRUCTION FOR THE LOCATORS

:
Grids : 4122B8726A 4122B8727D 4122C8726A 4122C8727D
Boundary: n 41.378056 s 41.374435 w -87.451378 e -87.449852

Work type : NEW SEWER AND WATER
Done for : STRACK AND VANTIL
Start date: 08/03/2012 Time: 15:45 Hours notice: 48/48 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
Duration : 1 YEAR Depth: 6 FEET

Company : MCALLISTER GENERAL CONTRACTORS Type: CONT
Co addr : PO BOX 810
City : CEDAR LAKE State: IN Zip: 46303
Caller : CAROL SANDERS Phone: (219)374-9498
Contact : TOM CLELAND - CELL Phone:
BestTime:
Mobile : (219)746-3479
Fax : (219)374-7017
Email : CSANDERS@MCALLISTERSINC.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? YES
:

Submitted date: 08/01/2012 Time: 15:35
Members: COMCN IB ID7478 NIPSCO SM

COMMENTS :

Excavator hit a 10-12" steel left from
A retrench that happened some time in
the past - very hard to know it was there back
the back of excavator

PERSON PREPARING REPORT

for the back of excavator
M. Schissel


FIELD SUPERVISOR

M. Schissel

FIELD MANAGER

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information



FOR OFFICE USE ONLY:

- | | | |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE | YES | NO |
| • NO IN 811 LOCATE CALLED IN | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST | YES | NO |

COMPLETED BY: _____

DATE: _____

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA Crown Point MAXIMO WO # _____
OPERATING AREA CONTACT M. Schessle JOB ORDER # 573015
TRACKING NUMBER 018 2012 0905 016 LOCATE REF # 1208012787
Locate Performed By: _____

DATE AND TIME OF ACCIDENT: 9-5-12 14:04 20 M DATE OF REPORT 9-5-12
PLACE OF DAMAGE (INCLUDE CITY) 9603 Lincoln Plz Cedar Lake

DAMAGE WAS TO: _____ BROKEN YES () NO ()
ELECTRIC - POLE / TRANSFORMER: # _____ SIZE _____ YEAR INSTALLED _____

OTHER (DESCRIBE) _____

GAS: SERVICE MAIN () SIZE 3/4 MATERIAL: PLASTIC () STEEL METER () REG STATION () STUB ()
OTHER (DESCRIBE) _____

DEPTH OF FACILITY (inches) 21" PRESSURE (PSI) 40 Lbs.

RELEASE OF GAS: YES NO () IGNITION OF GAS: YES () NO EVACUATION REQUIRED: YES () # _____ NO

INTERRUPTION OF SERVICE: YES () NO NUMBER OF CUSTOMERS LOST: 0

DURATION OF INTERRUPTION: TIME REPORTED 14:04 TIME SHUT OFF 15:34 TIME RESTORED N/A

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 2"

LOCATE MARKS ON SITE: YES DISTANCE BETWEEN FACILITY AND LOCATE MARKS _____ NO ()
HOW LOCATED: PAINT () FLAGS BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) McLester Inc.

ADDRESS OF PARTY (INCLUDE CITY) 10501 SA W. 153rd Ave. Cedar Lake.

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE McLester Inc.

WITNESS NAME AND ADDRESS _____

WITNESS REMARKS _____

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY _____ REPORT # _____

FIRE () AGENCY _____ REPORT # _____

OTHER () _____ Any Injuries? () YES # _____ NO

PHOTOS TAKEN: YES () NO TAKEN BY: _____ (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW
 AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK
 BLDG CONSTRUCTION () DEMOLITION () DRAINAGE
 DRIVEWAY () ELECTRIC () SURVEYING
 FENCING () GRADING () IRRIGATION
 LANDSCAPING () PIPELINE () MILLING
 POLE/SIGN POST () ROAD WORK () SEWER
 TELECOMMUNICATIONS
 WATER
 DRAINS/CULVERTS
 MOWING
 OTHER

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW
 AUGER () HAND TOOLS
 MILLING EQUIPMENT () PROBING DEVICE
 EXPLOSIVES () TRENCHER
 VACUUM EQUIPMENT () GRADER
 BACKHOE/TRACKHOE
 BORING / DRILLING
 FARM EQUIPMENT
 OTHER

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW
 AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE () CARELESS MACHINE OPERATOR
 NO NOTIFICATION () MARKS DISTURBED STUB () OTHER

SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM



150 West Market Street, Suite 600
Indianapolis, IN 46204

February 15, 2013

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3711
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Notification of Possible Violations; Pipeline Division Case No. 3711
Date of Event: 9/5/12
Event Location: PARRISH AVE, NEW HAVEN
Excavator: McALLISTER GENERAL CONTRACTORS
Other Party: N/A

To Whom It May Concern:

This letter responds to the Indiana Utility Regulatory Commission, Division of Pipeline Safety, Notification of Possible Violations for Case No. 3711 (as detailed above) identifying potential violations of Indiana law dated January 16, 2013. NIPSCO has not identified any additional information related to this incident not already provided in its October 24, 2012 response. The excavator struck a line that had not been correctly marked.

If there are any additional questions, please contact the undersigned.

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher Earle".

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com



INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

RECEIVED

OCT 19 2012

INDIANA UTILITY
REGULATORY COMMISSION

Case Number: 3711

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.

Upon completion of answers select email button for submission.

The Parties

Excavator Information:

Business Name: McAllister General Contractors, Inc.

Responsible Party Personal Name: Christopher McAllister

Title (if any): V.P

Address (number and street): 10501 -8 A W. 133rd Ave

City, State and ZIP Code: Cedar Lake, Indiana 46303

Preferred Telephone Number (area code): 219-374-9498

Cellular Telephone Number (area code): 219-746-9188

Email Address: -

Facility Information:

Business Name: Stracks & Van Til

Responsible Party Personal Name: -

Title (if any): -

Address (number and street): -

City, State and ZIP Code: Cedar Lake, Indiana 46303 _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Locator Service Information:

Business Name: Indiana 811 _____

Responsible Party Personal Name: _____

Title (if any): _____

Address (number and street): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): 1-800-382-5544 _____

Cellular Telephone Number (area code): _____

Email Address: _____

Cause of Damage Information

Type of Equipment (select one): Unknown/Other

Type of Work Performed (select one): Bldg. Construction

Other Information (Witness, Police, Fire, Other):

Personal Contact: _____

Business/Organization Name: _____

Title (if any): _____

Address (number and street): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Utility Line Impact

Location of Damage:

Address (number and street): 9704 Parrish Ave _____

City, State and ZIP Code: Cedar Lake, IN 46303 _____

Nearest Intersection: W. 133rd Ave _____

Product Type (select one): Natural Gas

Facility Type (select one): Unknown/Other

Size (Diameter/etc.): _____

Pressure (PSIG/Inches): _____

Interruption in Service: Yes No **Number of Customers Affected:** _____

Evacuation: Yes No **If yes, How Many Evacuated?** _____

Repair Cost (if known): \$⁰ _____

Release of Product: Yes No

Ignition and/or Fire: Yes No

Excavator Notify 811: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1209053367 (3rd) _____

Locate Marks Visible: Yes No
Locate Marks Correct: Yes No *for main NOT for service*
Excavator "White Lined": Yes No
Maps Used to Mark Facilities: Yes No
Was Locate Provided within Two (2) Working Days: Yes No
Operator Employees On-site during Excavation: Yes No

Incident Impact Information

Number of Outpatient Treated: _____

Number of Inpatient Treated: _____

Number of Fatalities: _____

Fire Department Response: Yes No

Police Department Response: Yes No

Ambulance Response: Yes No

Additional Information / Comments

McAllister called in several locates for this site prior to the hit. Ticket 1st) 1208012787 2nd) 1208101511 3rd) 1209053367, and white lined all. See pictures attached. McAllister was excavating for a new loading dock where the gas main was 11' away, the service was branched off the main wasn't located and was hit. White lining was done in multiple locations see pictures.

NARRATIVE STATEMENT

Your Pipeline Safety Division Case Number: 3711

Your Full Name: Christopher McAllister

Full Name of Business / Entity (if applicable): McAllister General Contractors, Inc.

Your Business Title (if applicable): VP

Address (number and street): 10501 -8A W. 133rd Ave

City: Cedar Lake State: IN ZIP Code: 46303

Your E-mail Address: _____

Today's Date (month, day, year): 10/2/2012

Your Signature:  Title (if any) VP

Please return your Narrative Statement to:

Pipeline Safety Division – Case Number 3711
Indiana Utility Regulatory Commission
101 West Washington Street, 1500E
Indianapolis, IN 46204

Or scan the statement and Email to:

PipelineDamageCase@urc.in.gov

①




Hit Pipe

2

2

1



3

1m

2

LOCATION OF HIT*



4

11' / main
to
service
NOT
located

11'

Service

15
Trench
Bench



5



CONTACT

M105

SEARCH

M141m



6



7



8



9



10



11

