



Pipeline Safety Division Investigation Report

Investigation regarding: Ge Marshall Inc

UPPAC Database Record ID: 3821

Report Date: 3/7/2013

Investigator: William Boyd

Damage Date: 9/17/2012 9:28:32 AM

Damage Address: Wood St, Valparaiso, Porter

The Parties

Excavator: Ge Marshall Inc

Address: 1351 Joliet Road, Valparaiso, In 46384

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: No

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$0

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1209121418

Original Start Date:

Locate Instructions: At the intersection of Roosevelt Road and Wood locate the northside of Wood going west for 1500 feet - then from the center of the road locate 50 feet north for the entire length

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas main while excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 12/20/2012. Excavator failed to maintain required clearance.

Conclusion: There was a failure to maintain clearance.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.



150 West Market Street, Suite 600
Indianapolis, IN 46204

January 28, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3821
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3821

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 9/17/2012

Event Location: Wood St

Facility Owner: Northern Indiana Public Service Company

Excavator: Ge Marshall Inc

Other Party: N/A

Pipeline Division Case No. 3821

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 3821	
Date of Event	9/17/2012
Event Location	Wood St
Event City	Valparaiso
Facility Owner	Northern Indiana Public Service Company
Excavator	Ge Marshall Inc
Date of IURC Information Request	12/5/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	GE Marshall
RESPONSIBLE PARTY PERSONAL NAME	Kevin Pullins
TITLE (IF ANY)	
ADDRESS	902 Wood St
CITY/ STATE/ZIP	Valparaiso, IN 46384
PREFERRED TELEPHONE	219-405-8448
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	902 Wood St
CITY/STATE/ZIP	Valparaiso, IN 46384
NEAREST INTERSECTION	
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8"
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	X
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	X
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	N
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y 1209170989
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1209121418
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	Y
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	N
POLICE DEPARTMENT RESPONSE (YES/NO)	N
AMBULANCE RESPONSE (YES/NO)	N
ADDITIONAL INFORMATION/COMMENTS	
Failure to use hand tools where required. NO RELEASE OF GAS.	

Investigation Results Verified By Utility Representative

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

UPON ARRIVAL TO JOB SITE, SNAGGED //PULLED 3/4" STEEL GAS SERVICE EXPOSED NOT LEAKING. HARD MARKINGS WITHIN 18" MARKINGS LINE UP TO DAMAGED AREA. UNTO NEABLE HAD BEEN FILED AT TIME OF LOCATE. FACILITY WITHIN TOLERANCE AND MARKED ACCURATELY.

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

NIPSCO ON SITE//UNTO NEABLE FOR THIS SPECIFIC ADDRESS WAS FILED AT TIME OF LOCATES

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

JERRY CORNET STATING IT MARKS ARE GOOD. THEY JUST SNAGGED IT WITH EXCAVATOR.

LIST ANY OTHER INDIVIDUALS ON SITE:

N/A

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? Yes

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? No

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? Yes

EXTENT OF FACILITY DAMAGE SNAGGED GAS SERVICE

REPLACEMENT FOOTAGE UNKNOW

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No

WHAT CONTRACTOR EQUIPMENT WAS USED? EXCAVATOR

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? No

IF YES, PLEASE LIST RECORD #(S)

NIPSCO 00456 IUPPSa 09/12/2012 11:12:31 1209121418-00A NORM NEW GRID

NORMAL NOTICE

Ticket : 1209121418 Date: 09/12/2012 Time: 11:06 Oper: NAN.MURPHY Chan:000

State: IN Cnty: PORTER Twp: CENTER
Cityname: VALPARAISO Inside: Y Near: N
Subdivision:

Case : 3821

Address :

Street : WOOD ST

Cross 1 : ROOSEVELT RD Within 1/4 mile: Y

Location: AT THE INTERSECTION OF ROOSEVELT ROAD AND WOOD LOCATE THE NORTHSIDE
OF WOOD GOING WEST FOR 1500 FEET - THEN FROM THE CENTER OF THE ROAD LOCATE 50
FEET NORTH FOR THE ENTIRE LENGTH

:

Grids : 4128D8702A 4128C8702A 4128D8703D 4128C8703D

Boundary: n 41.471642 s 41.470818 w -87.051384 e -87.046654

Work type : STORM/SANITARY SEWER

Done for : CITY OF VALPARAISO

Start date: 09/14/2012 Time: 11:30 Hours notice: 48/48 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N

Duration : 2 MONTHS Depth: 10 FEET

Company : GE MARSHALL INC Type: CONT

Co addr : 1351 JOLIET ROAD

City : VALPARAISO State: IN Zip: 46384

Caller : NAN MURPHY Phone: (219)462-3415

Contact : KEVIN PULLINS Phone:

BestTime:

Mobile : (219)405-8448

Fax : (219)462-3964

Email : INFO@GEMARSHALL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? NO

:

Submitted date: 09/12/2012 Time: 11:06

Members: COMCN ID3800 ID8000 NIPSCO SM

NIPSCO 00246 IUPPSa 09/17/2012 09:28:43 1209170989-00A EMER DAMG GRID

DAMAGE SEE REMARKS

Ticket : 1209170989 Date: 09/17/2012 Time: 09:26 Oper: JWRIGHT Chan:033

State: IN Cnty: PORTER Twp: CENTER
Cityname: VALPARAISO Inside: Y Near: N
Subdivision:

CASE: 13821

Address :

Street : WOOD ST

Cross 1 : ROOSEVELT RD Within 1/4 mile: Y

Location: AT THE INTERSECTION OF ROOSEVELT ROAD AND WOOD LOCATE THE NORTHSIDE
OF WOOD GOING WEST FOR 1500 FEET - THEN FROM THE CENTER OF THE ROAD LOCATE 50
FEET NORTH FOR THE ENTIRE LENGTH

:

Grids : 4128D8702A 4128C8702A 4128D8703D 4128C8703D

Boundary: n 41.471642 s 41.470818 w -87.051384 e -87.046654

Work type : STORM/SANITARY SEWER

Done for : CITY OF VALPARAISO

Start date: 09/17/2012 Time: 09:27 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 2 MONTHS Depth: 10 FEET

Company : GE MARSHALL INC Type: CONT

Co addr : 1351 JOLIET ROAD

City : VALPARAISO State: IN Zip: 46384

Caller : LORI SCHROEDER Phone: (219)462-3415

Contact : KEVIN PULLINS Phone:

BestTime:

Mobile : (219)405-8448

Fax : (219)462-3964

Email : INFO@GEMARSHALL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
NIPSCO GAS LINE HAS BEEN SNAGGED IN FRONT OF 813 WOOD ST - GAS IS NOT BLOWING -
NO GAS CAN BE HEARD OR SMELLED - CREW ON STE - HAS CALLED NIPSCO - PREVIOUS
TICKET - 1209121418 - THANK YOU

Will you be white-lining the dig site area? NO

:

Submitted date: 09/17/2012 Time: 09:26

Members: COMCN ID3800 ID8000 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA 050 MAXIMO WO #

OPERATING AREA CONTACT Rick Smith JOB ORDER # 581190

TRACKING NUMBER 018-2012-091-7001 LOCATE REF #

Locate Performed By: USIC

DATE AND TIME OF ACCIDENT 9/17 2012 8:20 AM DATE OF REPORT 9/17/12

PLACE OF DAMAGE (INCLUDE CITY) 902 Wood St.

DAMAGE WAS TO:

ELECTRIC - POLE / TRANSFORMER: # SIZE YEAR INSTALLED BROKEN YES () NO ()

OTHER (DESCRIBE)

GAS: SERVICE (X) MAIN () SIZE 5/8 MATERIAL: PLASTIC (X) STEEL () METER () REG STATION () STUB ()

DEPTH OF FACILITY (inches) 16 PRESSURE (PSI) 45 Lbs.

RELEASE OF GAS: YES () NO (X) IGNITION OF GAS: YES () NO (X) EVACUATION REQUIRED: YES () # NO (X)

INTERRUPTION OF SERVICE: YES (X) NO () NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED N/A TIME RESTORED N/A

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: N/A Did not puncture line

LOCATE MARKS ON SITE: YES (X) DISTANCE BETWEEN FACILITY AND LOCATE MARKS NO ()

HOW LOCATED: PAINT () FLAGS () BOTH (X) WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) GE Marshall Inc

ADDRESS OF PARTY (INCLUDE CITY) 1351 Joliet Rd 46385

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE Jerry Cornett

WITNESS NAME AND ADDRESS

WITNESS REMARKS

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY REPORT #

FIRE () AGENCY REPORT #

OTHER () Any Injuries? () YES # NO (X)

PHOTOS TAKEN: YES () NO (X) TAKEN BY: (ATTACH PHOTOS TO REPORT)

MEDIA ON SITE YES () NO (X)

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW

- () AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK () TELECOMMUNICATIONS
() BLDG CONSTRUCTION () DEMOLITION () DRAINAGE () WATER
() DRIVEWAY () ELECTRIC () SURVEYING () DRAINS/CULVERTS
() FENCING () GRADING () IRRIGATION () MOWING
() LANDSCAPING () PIPELINE () MILLING () OTHER
() POLE/SIGN POST () ROAD WORK (X) SEWER

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW

- () AUGER () HAND TOOLS (X) BACKHOE/TRACKHOE
() MILLING EQUIPMENT () PROBING DEVICE () BORING / DRILLING
() EXPLOSIVES () TRENCHER () FARM EQUIPMENT
() VACCUUM EQUIPMENT () GRADER () OTHER

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW

- () AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE (X) CARELESS MACHINE OPERATOR
() NO NOTIFICATION () MARKS DISTURBED () STUB () OTHER

SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

From: [Jamie Marshall](#)
To: [IURC PipelineDamageCase](#)
Subject: CASE NO. 3821 (INITIAL DOCUMENTS - EXCAVATOR)
Date: Thursday, December 20, 2012 4:22:24 PM
Attachments: [Case #3821 Initial Documents - Excavator.pdf](#)

To Whom It May Concern,

Per your request, please see the attached Information Request Form, along with supporting documentation, in regards to the above referenced case.

Let me know if you have any questions or need anything further.

Respectfully,

Jamie L. Marshall

Office Administrator

G.E. MARSHALL INC.

1351 Joliet Rd.

Valparaiso, IN 46385

Phone: 219-462-3415

Fax: 219-462-3964

Email: jamiem@gemarshall.com



INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 3821

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.

Upon completion of answers select email button for submission.

The Parties

Excavator Information:

Business Name: G.E. Marshall, Inc.

Responsible Party Personal Name: Frank Marshall

Title (if any): President

Address (number and street): 1351 Joliet Rd.

City, State and ZIP Code: Valparaiso, IN 46385

Preferred Telephone Number (area code): 219-462-3415

Cellular Telephone Number (area code): _____

Email Address: jamiem@gemarshall.com

Facility Information:

Business Name: Northern Indiana Public Service Company

Responsible Party Personal Name: _____

Title (if any): _____

Address (number and street): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Locator Service Information:

Business Name: Unknown

Responsible Party Personal Name: _____

Title (if any): _____

Address (number and street): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Cause of Damage Information

Type of Equipment (*select one*): Backhoe/Trackhoe

Type of Work Performed (*select one*): Sewer (Sanitary/Storm)

Other Information (Witness, Police, Fire, Other):

Personal Contact: Employees On Site: Jerry Cornett, Kevin Pullins, & Craig Vergon

Business/Organization Name: G.E. Marshall, Inc.

Title (if any): Project Foreman, Operator, & Laborer

Address (number and street): 1351 Joliet Rd.

City, State and ZIP Code: Valparaiso, IN 46385

Preferred Telephone Number (area code): 219-462-3415

Locate Marks Visible: Yes No
Locate Marks Correct: Yes No
Excavator "White Lined": Yes No *Not Required in this Case.
Maps Used to Mark Facilities: Yes No *Unknown (Question for Locator Service).
Was Locate Provided within Two (2) Working Days: Yes No
Operator Employees On-site during Excavation: Yes No

Incident Impact Information

Number of Outpatient Treated: 0

Number of Inpatient Treated: 0

Number of Fatalities: 0

Fire Department Response: Yes No

Police Department Response: Yes No

Ambulance Response: Yes No

Additional Information / Comments

Depth of buried utility is the main issue in this case. There was a drastic fluctuation in the grade of the utility line within a 3-ft. distance. The depth of the utility on the south side of the 3-ft. wide trench was 14". The depth of the utility on the north side of the 3-ft. wide trench was at most 4". What is the minimum depth of a gas main or service? It has to be more than 4" (I believe it is 30"). The crew was just trying to break hard slag/stone off top of excavation in order to hand dig when pipe was hit at 4" deep.

Please see the below listed documentation I have included with this report:

Active Ticket at the time from 811
Damage Ticket Report called into 811
Pictures #1-7

Cellular Telephone Number (area code): Jerry Cornett (Project Foreman): 219-405-5129

Email Address: _____

Utility Line Impact

Location of Damage:

Address (number and street): 813 Wood Street

City, State and ZIP Code: Valparaiso, IN 46383

Nearest Intersection: Roosevelt Road

Product Type (select one): Natural Gas

Facility Type (select one): Service/Drop

Size (Diameter/etc.): 1"

Pressure (PSIG/Inches): Unknown

Interruption in Service: Yes No Number of Customers Affected: 1

Evacuation: Yes No If yes, How Many Evacuated? _____

Repair Cost (if known): \$ _____

Release of Product: Yes No

Ignition and/or Fire: Yes No

Excavator Notify 811: Yes No

Damage Ticket #1209170989

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1209121418

NARRATIVE STATEMENT

Your Pipeline Safety Division Case Number: 3821

Your Full Name: Frank Marshall

Full Name of Business / Entity (if applicable): G.E. Marshall, Inc.


Your Business Title (if applicable): President

Address (number and street): 1351 Joliet Rd.

City: Valparaiso State: IN ZIP Code: 46385

Your E-mail Address: jamiem@gemarshall.com

Today's Date (month, day/year): December 20, 2012

Your Signature:  Title (if any) President

Please return your Narrative Statement to:

Pipeline Safety Division – Case Number 3821
Indiana Utility Regulatory Commission
101 West Washington Street, 1500E
Indianapolis, IN 46204

Or scan the statement and Email to:

PipelineDamageCase@urc.in.gov

CASE # 3821

Wood St
Northside

9/27

Close Window

"If you have a pencil handy, I have a ticket number to provide to you. If you need to call us back for any reason, your ticket number will assist us in locating this ticket. Are you ready for your number?"

NORMAL NOTICE

Ticket : 1209121418 Date: 09/12/2012 Time: 11:06 Oper: NAN.MURPHY Chan:000

State: IN Cnty: PORTER Twp: CENTER
Cityname: VALPARAISO Inside: Y Near: N
Subdivision:

Address :
Street : WOOD ST
Cross 1 : ROOSEVELT RD Within 1/4 mile: Y
Location: AT THE INTERSECTION OF ROOSEVELT ROAD AND WOOD LOCATE THE NORTHSIDE
OF WOOD GOING WEST FOR 1500 FEET - THEN FROM THE CENTER OF THE ROAD LOCATE 50
FEET NORTH FOR THE ENTIRE LENGTH

Grids : 4128D8702A 4128C8702A 4128D8703D 4128C8703D

Work type : STORM/SANITARY SEWER
Done for : CITY OF VALPARAISO
Start date: 09/14/2012 Time: 11:30 Hours notice: 48/48 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
Duration : 2 MONTHS Depth: 10 FEET

Company : GE MARSHALL INC Type: CONT
Co addr : 1351 JOLIET ROAD
City : VALPARAISO State: IN Zip: 46384
Caller : NAN MURPHY Phone: (219)462-3415
Contact : KEVIN PULLINS Phone:
BestTime:
Mobile : (219)405-8448
Fax : (219)462-3964
Email : INFO@GEMARSHALL.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? NO

Submitted date: 09/12/2012 Time: 11:06
Members: COMCN ID3800 ID8000 NIPSCO SM

Member Name	Facility Types
COMCAST NORTH	CABLETV
FRONTIER	TELEPHONE
NIPSCO	GAS & ELECTRIC
VALPARAISO UTILITIES, CITY OF SEWER & WATER	

CASE # 3821

DAMAGED TICKET REPORT

G.E. Marshall, Inc.

*****STOP*****

If NipSCO Line Was Cut Call NipSCO First! 1-800-634-3524
Then, Call Indiana 811 (811) or IUPPS (1-800-382-5544)

Job Name? WOOD STREET SEWER Replacement

Active Ticket Number? 1209121418

Date and Time Reported to Office? 9-17-12 8:10 a.m.

Date and Time Reported to Utility Company? 9-17-12 8:13 a.m.

Date and Time Reported to IUPPS? 9-17-12

Has Crew Onsite Contacted the Locating Company? NO - I DID

Has Crew Onsite Contacted the Utility Company? NO I DID - LORI

What Utility Line was Damaged? NIPSCO gas

Was the Line HIT or CUT? SNAGGED & PULLED HAS A KINK IN IT

Is it a Main Line? NO LATERAL TO HOUSE

If NipSCO was Hit, is it Gas or Electric? Gas

If Gas Line was Hit, is Gas Line Blowing? NO

If Phone Line was Hit,
What is Phone # or Area Code Affected? NA

If Utility Hit is Unknown,
What is Size and Color of Line? NA

Where on Property was Line Hit? Northside ^{of} WOOD ST @ 813 WOOD St

Was it a Marked or Unmarked Area? Marked

Is Crew on Onsite? yes

Has Anyone Onsite been Affected by Cut? NO

Have We Called 911? NO

DAMAGED TICKET NUMBER? 1209170989

Please make sure to put a copy in the locate book & give the original to Jamie.



CASE # 3821 PHOTO # 1



CASE # 3821 PHOTO # 2



CASE # 382-1 PHOTO # 3



CASE # 382-1 PHOTO # 4



CASE #3821 PHOTO #5



CASE #3821 PHOTO #6



CASE # 3821 PHOTO #7