



Pipeline Safety Division Investigation Report

Investigation regarding: Town Of Fishers

UPPAC Database Record ID: 3828

Report Date: 9/11/2013

Investigator: Mike Orr

Damage Date: 9/18/2012 9:43:00 AM

Damage Address: 9680 Geist Woods North Dr, Fishers, Hamilton

The Parties

Excavator: **Town Of Fishers**

Address: 10210 Eller Road, Fishers, In 46038

Facility Owner: **Vectren**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Drainage

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1209120065

Original Start Date:

Locate Instructions: LOCATE THE FRONT OF THE PROPERTY TO INCLUDE BOTH SIDES OF THE STREET OF GEIST WOODS NORTH DR

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing drainage work.

Findings: Reported by Indiana 811; excavator did not respond to initial notice mailed 11/30/2012. Excavator had a valid locate ticket; however, the gas operator self reported a failure to provide accurate facility locate markings.

Conclusion: There was a failure to provide accurate facility locate markings.

Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -
OPERATOR
CASE 3828

Submitted to IURC-Pipeline Safety on: 12-7-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: Town of Fishers

Business address (number and street): 10210 Eller Rd.

City, State, and ZIP code: Fishers, IN 46038

Telephone number (area code): 317-595-3160

Fax number (area code): 317-595-3108

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Municipality

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Drainage

Date and Location of Damage

Date of damage (month, day, year): 9-18-2012

County: Hamilton

City: Fishers

Street address (number and street, city, state, and ZIP code):
11017 Geistwood Drive, Castleton, IN

Nearest intersection: Unknown

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours): 4

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$915.8

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? 22

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1209120065

Was the locate request completed within two working days? No

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? No

Type of markings used: Other

If other, please specify: None

Was site marked by "White Lining"? Yes

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Unknown/Other

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Facility marking or location not sufficient

Additional Comments

1" plastic service severed by trackhoe. Incomplete.



2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

NOW DUE

\$915.80

USIC INC
9045 N RIVER ROAD, SUITE 300
INDIANAPOLIS, IN 46240

Type: GAS
Invoice: FDS0016945
BillToID: 32639
Billing Date: 10/30/2012
Date of Loss: 9/18/2012
5830 103.0510

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holdings Group
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE

\$915.80

USIC INC
9045 N RIVER ROAD, SUITE 300
INDIANAPOLIS, IN 46240

Type: GAS
Invoice: FDS0016945
BillToID: 32639
Billing Date: 10/30/2012
Date of Loss: 9/18/2012

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 11017 GEISTWOOD DR, CASTLETON
1" PLASTIC SERVICE SEVERED BY TRACKHOE. INCOMPLETE

Material:	\$66.33
Company Labor:	\$531.21
Contract Labor:	\$0.00
Transportation/Equipment:	\$112.36
Misc:	\$0.00
Gas Loss:	\$205.90
Adjustments:	\$0.00
Payments:	\$0.00
Total:	\$915.80

5830 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

Vectren Claim Number: _____

FDS 0016945

Task No: 103-0510 Capital (O & M) (circle one)

Police Report /MO #: _____

Date of Damage 9/1/13

Cost Center # 5B30

Time Occurred 9:30 AM pm

Time Found 9:55 AM pm

Latitude 39.9805 Longitude: 85.97273

FACILITIES DAMAGE REPORT

GAS

Vectren Claims Camera:

VE01399
Form 3112

DAMAGE SITE:

Address 11017 Geist Road Dr N Lot # _____

County Hamilton City Castletown State IN Township Fall Creek

FACILITY TYPE:

- Distribution
- Service
- Transmission: (include supplemental report)
- Propane
- Storage

FACILITIES DAMAGED:

	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	Other _____			

927

TYPE OF MATERIAL:

- Cast Iron
- Plastic (HDPE)
- Plastic (MDPE)
- Steel
- Other _____

DAMAGE TYPE:

- Severed
- Not Cut
- Severed
- Size 1" x 1"

PRESSURE:

- 25 PSIG
- 40 PSIG
- 50 PSIG
- 55 PSIG
- 60 PSIG
- 6 WC (.2163)
- 7 WC (.252)
- Other _____

24.262

PROTECTION IN PLACE:

- Building Fence None
- Post Rail Vault N/A
- Other _____

DURATION OF ESCAPING GAS:

Minutes: 90

LEAK REPORT

NUMBER: 01640

EFV Activated Yes No N/S

FEED TYPE:

- One-Way Feed
- Two-Way Feed

Number of Customers Affected: 1
 Total Hours Service Was Off: 4

SERVICE ORDER NUMBER: N5368944

DAMAGED BY:

- Company Crew
- Contractor
- County
- Developer
- Farmer
- Municipality
- Property Owner/ Tenant
- Railroad
- State
- Unknown
- Utility
- Vehicle Accident
- Other _____

TYPE OF CONSTRUCTION:

- Agriculture
- Building Construction
- Building Demolition
- Cable TV
- Curbs / Sidewalk
- Drainage
- Driveway
- Electric
- Engineering / Surveying
- Fencing
- Grading
- Irrigation
- Landseaping
- Liquid Pipeline
- Milling
- Pole
- Natural Gas
- Public Transit Authority
- Railroad Maintenance
- Other _____

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:

Locate Ticket: _____
 Date: _____ Time: _____ am / pm

TYPE OF REQUEST:

- Regular Request Emergency Request
- Locate Company Notified
- Contact Name: _____
- Time Called: _____ am / pm
- Time Locator Arrived at the Site: _____ am / pm

Company Notified of Locate Near Critical Facilities
 Yes No N/S

Copy of Mark Out Request Provided Within 2 Working Days
 Yes No N/S

ONE-CALL CENTER:

- MUPPS
- OUPS
- Unknown

10/3 EN
Molly
10/8
SARCASTIC

SEP 21 2012

Vectren Claim Number: _____

TYPE OF EQUIPMENT:

- Auger
- Backhoe Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other _____

ROOT DAMAGING CAUSE:

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other _____

CONTRACTOR REPAIRS:

- Contractor Working for Vectren Made Repairs at Own Expense
 Yes No N/S
- Contractor Repaired Damage
 Yes No N/S

Name of Contractor: _____
 # of Regular Hours; _____
 # of Overtime Hours; _____
 # of Regular Hours; _____
 Crew Type: _____

MATERIALS OR ROAD WORK:

- Meter was replaced _____ (Stores Code)
- Regulator Was Replaced _____ (Stores Code)
- Temporary Asphalt Repair: _____ (sq. ft.)
- Permanent Asphalt Repair: _____ (sq. ft.)

- Did Excavator Notify You Yes No
- Excavation Required Yes No
- Media at Site Yes No
- Was There Ignition of Gas? Yes No
- INVOICE: Yes No N/S

RIGHT OF WAY:

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

DAMAGING PARTY:
 Name: Town of Fishers
 Address: _____
 City/ State/ Zip: _____
 Phone: (____) _____
 Prepared / Investigated By: Gregory Date: _____

PARTY TO INVOICE:
 Name: USIC
 Address: _____
 City/ State/ Zip: _____
 Phone: (____) _____
 Reviewed By Field Supervisor: [Signature] Date: 9-19-12

2 Locations called By Fishar, 1st No marks for service,
 2 Lote for dig no marks on service.
 USIC shows 4 service cand. for this address only
 only is correct.
 NO MARKS FOUND FOR SERVICE ON PROPERTY OR STREET.

NORMAL NOTICE

Ticket : 1209120065 Date: 09/12/2012 Time: 06:49 Oper: CALEVI Chan:031

State: IN Cnty: HAMILTON Twp: FALL CREEK
 Cityname: FISHERS Inside: Y Near: N
 Subdivision: GEIST WOODS

Address : 9680
 Street : GEIST WOODS NORTH DR
 Cross 1 : GEIST WOODS EAST DR Within 1/4 mile: Y
 Location: LOCATE THE FRONT OF THE PROPERTY TO INCLUDE BOTH SIDES OF THE STREET
 OF GEIST WOODS NORTH DR
 :
 Grids : 3955B8558C 3955A8558C 3955B8558B 3955A8558B

Work type : INSTALL STORM INLET AND CROSS PIPE
 Done for : TOWN OF FISHERS
 Start date: 09/14/2012 Time: 07:00 Hours notice: 48/048 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 3 DAYS Depth: 4 FEET

Company : TOWN OF FISHERS Type: OTHR
 Co addr : 10210 ELLER ROAD
 City : FISHERS State: IN Zip: 46038
 Caller : DAN TUCKER Phone: (317)595-3160
 Contact : DAN TUCKER--CELL Phone:
 BestTime:
 Mobile : (317)339-8683
 Fax : (317)595-3108
 Email : TUCKERD@FISHERS.IN.US

Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? YES
 :

Submitted date: 09/12/2012 Time: 06:49
 Members: CTG CV ID0002 ID0103 ID0660 ID1501 ID3162 ID3639 ID3642 ID5555
 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CITIZENS GAS & COKE UTILITY - INDPLS.	GAS
CITIZENS WATER / FORMERLY VEOLIA WATER	WATER
COMCAST CABLEVISION - INDIANAPOLIS	CABLE TV
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FISHERS, TOWN OF	
HAMILTON SOUTHEASTERN UTILITIES	
INDIANAPOLIS POWER & LIGHT COMPANY	ELECTRIC
INDIANAPOLIS, CITY OF	
VECTREN - NOBLESVILLE #1	GAS

[View Map](#)

[Close Map](#)



Property of United States Infrastructure Corporation
Photo taken on 9/13/2012 10:48:02 AM



Property of United States Infrastructure Corporation
Photo taken on 9/13/2012 10:48:12 AM

DAMAGE .SEE REMARKS

Ticket : 1209180856 Date: 09/18/2012 Time: 09:40 Oper: AGRIGGS Chan:074

State: IN Cnty: HAMILTON Twp: FALL CREEK
 Cityname: FISHERS Inside: Y Near: N
 Subdivision: GEIST WOODS

Address : 9680
 Street : GEIST WOODS NORTH DR
 Cross 1 : GEIST WOODS EAST DR Within 1/4 mile: Y
 Location: LOCATE THE FRONT OF THE PROPERTY TO INCLUDE BOTH SIDES OF THE STREET
 OF GEIST WOODS NORTH DR
 :
 Grids : 3955B8558C 3955A8558C 3955B8558B 3955A8558B

Work type : INSTALL STORM INLET AND CROSS PIPE
 Done for : TOWN OF FISHERS
 Start date: 09/18/2012 Time: 09:40 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : 3 DAYS Depth: 4 FEET

Company : TOWN OF FISHERS Type: OTHR
 Co addr : 10210 ELLER ROAD
 City : FISHERS State: IN Zip: 46038
 Caller : DAN TUCKER Phone: (317)595-3160
 Contact : DAN TUCKER--CELL Phone:
 BestTime:
 Mobile : (317)339-8683
 Fax : (317)595-3108
 Email : TUCKERD@FISHERS.IN.US

Remarks : All tickets are taken and processed on Eastern Daylight Time
 A CITIZENS GAS LINE HAS BEEN HIT AND IS BLOWING ON THE FRONT OF THE PROPERTY BY
 THE STREET - SIZE COLOR AND MATERIAL UNKNOWN - HAS CALLED 911 - ADVISED TO CALL
 CITIZENS TO REPORT - CREW ON SITE - PREVIOUS TICKET NUMBER 1209120065
 Will you be white-lining the dig site area? YES
 :

Submitted date: 09/18/2012 Time: 09:40
 Members: CTG CV ID0002 ID0103 ID0660 ID1501 ID3162 ID3639 ID3642 ID5555
 ID9999 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CITIZENS GAS & COKE UTILITY - INDPLS.	GAS
CITIZENS WATER / FORMERLY VEOLIA WATER	WATER
COMCAST CABLEVISION - INDIANAPOLIS	CABLE TV
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FISHERS, TOWN OF	
HAMILTON SOUTHEASTERN UTILITIES	
INDIANAPOLIS POWER & LIGHT COMPANY	ELECTRIC
INDIANAPOLIS, CITY OF	
VECTREN - NOBLESVILLE #1	GAS

[View Map](#)

[Close Map](#)



Property of United States Infrastructure Corporation
Photo taken on 9/18/2012 11:17:32 AM



Property of United States Infrastructure Corporation
Photo taken on 9/18/2012 11:17:38 AM



Property of United States Infrastructure Corporation
Photo taken on 9/18/2012 11:17:45 AM

EMERGENCY SEE REMARKS

Ticket : 1209181006 Date: 09/18/2012 Time: 10:10 Oper: AGRIGGS Chan:074

State: IN Cnty: HAMILTON Twp: FALL CREEK
 Cityname: FISHERS Inside: Y Near: N
 Subdivision: GEIST WOODS

Address :
 Street : GEIST WOODS LN
 Cross 1 : GEIST WOODS CT Within 1/4 mile: Y
 Location: LOCATE A 100 FOOT RADIUS OF THE SOUTHWEST CORNER OF THE INTERSECTION
 :
 Grids : 3955A8558C

Work type : REPAIR GAS LEAK
 Done for : VECTREN
 Start date: 09/18/2012 Time: 10:11 Hours notice: 0/000 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : 1 DAY Depth: 4 FEET

Company : VECTREN Type: MEMB
 Co addr : 1600 ALLISONVILLE ROAD
 City : NOBLESVILLE State: IN Zip: 46060
 Caller : GREG WYATT Phone: (317)776-5594
 Contact : GREG WYATT - CELL Phone:
 BestTime:
 Mobile : (317)997-4129

Remarks : All tickets are taken and processed on Eastern Daylight Time
 CREW ON SITE
 Will you be white-lining the dig site area? YES
 :

Submitted date: 09/18/2012 Time: 10:10
 Members: CTG CV ID0002 ID0103 ID0660 ID1501 ID3162 ID3639 ID5555 ID9999
 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
BRIGHT HOUSE NETWORKS INDIANAPOLIS	CABLE TV
CITIZENS GAS & COKE UTILITY - INDPLS.	GAS
CITIZENS WATER / FORMERLY VEOLIA WATER	WATER
COMCAST CABLEVISION - INDIANAPOLIS	CABLE TV
COMCAST NORTHEAST (NOBLESVILLE)	CABLE TV
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FISHERS, TOWN OF	
INDIANAPOLIS POWER & LIGHT COMPANY	ELECTRIC
INDIANAPOLIS, CITY OF	
VECTREN - NOBLESVILLE #1	GAS

[View Map](#)

[Close Map](#)

Service Order Status

Wednesday, October 10, 2012

Enter Service Order Number:

5368944



[Close Print](#) [Refresh Data](#)

Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: N5368944

Order Type: INVE

Order Status: Completed

Customer: 008888888 - INACTIVE CUSTOMER

Prem: 5724534 - GEISTWOODS CT & GEISTWOOD N DR

Technician: 2976 - Wyatt, Greg

Order Dates and Times

Need Date: 9/18/2012 9:55:00 AM
Time Created: 9/18/2012 9:43:27 AM
Time Dispatched: 9/18/2012 9:43:27 AM
Time In Route: 9/18/2012 9:45:59 AM
Time On-Site: 9/18/2012 9:53:56 AM
Tech Complete: 9/18/2012 12:10:20 PM
Time Closed: 9/18/2012 12:10:20 PM

Events Performed/Completion Code

IVEG - CMP

Meter Information

Current ReadStatus

Old Meter:

New Meter:

Completion Notes

1 in cut fishers 16945 hse off crew fixed

Request Notes

HIT LINE / BLOWING PER KIRSTEN WITH 911 FIRE DEPT INROUTE...PUBLIC WORKS DEPTHIT LINE AT GEISTWOODS COURT AND GEISTWOOD NORTH DRIVE AT THE GEISTWOODSSUBDIVISION...317-846-2525

MDSI Event Dates and Times

Event:	Date/Time	User
AsnAssignmentManualAck_evt	9/18/2012 9:44:10 AM	Wyatt, Greg
AsnAssignmentEnRoute_evt	9/18/2012 9:45:59 AM	Wyatt, Greg
AsnAssignmentOnSite_evt	9/18/2012 9:53:56 AM	Wyatt, Greg
OrdOrderComplete_evt	9/18/2012 12:10:20 PM	Wyatt, Greg

NOTE:The Reporting database replicates in near real-time; it has been approximately 2 minute(s) since the last transaction replicated.

Visual, Facility Exposed At Time Of Investigation,
Investigator Verified Existing Marks By Hooking Up

INVESTIGATOR STATEMENT/CAUSAL FACTORS:
NOT MARKED

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:
N/A

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:
N/A

LIST ANY OTHER INDIVIDUALS ON SITE:
N/A

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? Yes

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? Yes

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? No

EXTENT OF FACILITY DAMAGE SERVERED

REPLACEMENT FOOTAGE N/A

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No

WHAT CONTRACTOR EQUIPMENT WAS USED? NONE

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? Yes

IF YES, PLEASE LIST RECORD #(S) VECTREN