



Pipeline Safety Division Investigation Report

Investigation regarding: Precision Utilities Group Inc

UPPAC Database Record ID: 3852

Report Date: 6/27/2013

Investigator: Mike Orr

Damage Date: 9/20/2012 11:42:05 AM

Damage Address: 1015 Orlando Dr, Fort Wayne, Allen

The Parties

Excavator: Precision Utilities Group Inc

Address: 5714 Saint Joe Road, Ft Wayne, In 46835

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Hand Tools

Type of Work Performed: Cable TV

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$138

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1209112260

Original Start Date:

Locate Instructions: LOCATE ENTIRE PROPERTY AND ALL EASEMENTS - LOCATE FROM PROTECTOR ON THE STRUCTURE TO FRONTIER TERMINAL H3002-143 - PLEASE FLAG AND PAINT - THANK YOU

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing cable TV work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/7/2013. The excavator had a valid locate; however, the gas operator failed to mark the natural gas service.

Conclusion: There was a failure to provide notice of excavation.

Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.



150 West Market Street, Suite 600
Indianapolis, IN 46204

February 4, 2013

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 3852
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3852

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 9/20/2012

Event Location: 1015 Orlando Dr

Facility Owner: Northern Indiana Public Service Company

Excavator: Precision Utilities Group Inc

Other Party:

Pipeline Division Case No. 3852

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 3852	
Date of Event	9/20/2012
Event Location	1015 Orlando Dr
Event City	Fort Wayne
Facility Owner	Northern Indiana Public Service Company
Excavator	Precision Utilities Group Inc
Date of IURC Information Request	12/5/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	Precision Utilities
RESPONSIBLE PARTY PERSONAL NAME	Spencer Pacula
TITLE (IF ANY)	
ADDRESS	5714 Saint Joe Rd
CITY/ STATE/ZIP	Fort Wayne, IN 46835
PREFERRED TELEPHONE	260-485-8300
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	1015 Orlando Dr
CITY/STATE/ZIP	Fort Wayne, IN 46835
NEAREST INTERSECTION	
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8"
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	N
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	X
Milling Equipment	
Probing Device	

Trancher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	X
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	N
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y 1209201654
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1209112260
LOCATE MARKS VISIBLE (YES/NO)	N
LOCATE MARKS CORRECT (YES/NO)	N
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	N
POLICE DEPARTMENT RESPONSE (YES/NO)	N
AMBULANCE RESPONSE (YES/NO)	N
ADDITIONAL INFORMATION/COMMENTS	
<p>Scope of locate was not followed. Locate requested "LOCATE ENTIRE PROPERTY" per USIC report, tech followed temp drop that was lying on ground and assumed that gas would be clear. USIC failed to locate facility.</p> <p>Nipsco emergency repair ticket 1209201767</p>	

NIPSCO 00696 IUPPSa 09/11/2012 13:33:04 1209112260-00A NORM NEW STRT

NORMAL NOTICE

Ticket : 1209112260 Date: 09/11/2012 Time: 13:31 Oper: SPENCER.PACULA Chan:000

State: IN Cnty: ALLEN Twp: WASHINGTON
Cityname: FORT WAYNE Inside: N Near: Y
Subdivision:

CASE:3852

Address : 1015
Street : ORLANDO DR
Cross 1 : RODENBECK DR Within 1/4 mile: Y
Location: LOCATE ENTIRE PROPERTY AND ALL EASEMENTS - LOCATE FROM PROTECTOR ON
THE STRUCTURE TO FRONTIER TERMINAL H3002-143 - PLEASE FLAG AND PAINT - THANK
YOU

:
Grids : 4108D8508A 4108D8509D 4108D8509C
Boundary: n 41.137157 s 41.135956 w -85.154625 e -85.148079

Work type : FTTP DROP INSTALLATION
Done for : FRONTIER
Start date: 09/13/2012 Time: 13:45 Hours notice: 48/48 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
Duration : 2 WEEKS Depth: 30 INCHES

Company : PRECISION UTILITIES GROUP INC Type: CONT
Co addr : 5714 SAINT JOE ROAD
City : FT WAYNE State: IN Zip: 46835
Caller : SPENCER PACULA Phone: (260)485-8300
Contact : SPENCER PACULA OFFICE Phone:
BestTime:
Mobile : (260)485-8300
Fax : (260)485-8398
Email : SPENCERPACULA@PRECISIONUG.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
PRECISION REFERENCE NUMBER - 26045103841
Will you be white-lining the dig site area? NO

:

Submitted date: 09/11/2012 Time: 13:31
Members: AEPIN CC FW ID8000 NIPSCO SM

NIPSCO 00535 IUPPSa 09/20/2012 11:42:23 1209201654-00A EMER DAMG STRT

DAMAGE DAMAGE

Ticket : 1209201654 Date: 09/20/2012 Time: 11:40 Oper: LPORTER Chan:046

Case:3852

State: IN Cnty: ALLEN Twp: WASHINGTON
Cityname: FORT WAYNE Inside: N Near: Y
Subdivision:

Address : 1015
Street : ORLANDO DR
Cross 1 : RODENBECK DR Within 1/4 mile: Y
Location: LOCATE ENTIRE PROPERTY AND ALL EASEMENTS - LOCATE FROM PROTECTOR ON
THE STRUCTURE TO FRONTIER TERMINAL H3002-143 - PLEASE FLAG AND PAINT - THANK
YOU

:
Grids : 4108D8508A 4108D8509D 4108D8509C
Boundary: n 41.137157 s 41.135956 w -85.154625 e -85.148079

Work type : FTTP DROP INSTALLATION
Done for : FRONTIER
Start date: 09/20/2012 Time: 11:40 Hours notice: 0/0 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 2 WEEKS Depth: 30 INCHES

Company : PRECISION UTILITIES GROUP INC Type: CONT
Co addr : 5714 SAINT JOE ROAD
City : FT WAYNE State: IN Zip: 46835
Caller : SPENCER PACULA Phone: (260)485-8300
Contact : SPENCER PACULA OFFICE Phone:
BestTime:
Mobile : (260)485-8300
Fax : (260)485-8398
Email : SPENCERPACULA@PRECISIONUG.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
PER SPENCER PACILA - HIT A NIPSCO GAS LINE - GAS IS BLOWING - LINE DESCRIPTION
UNKNOWN - DIGGING IN UNKNOWN AREA - CREW STILL ON SITE - SPENCER TO CONTACT
NIPSCO - PREVIOUS TICKET 1209112260
Will you be white-lining the dig site area? NO
:

Submitted date: 09/20/2012 Time: 11:40
Members: AEPIN CC FW ID8000 NIPSCO SM

Fact Based Investigation Report

NOTIFICATION ID: 01820120920002 **DISTRICT:** Northern IN
DAMAGE DATE: 9/20/2012 11:42:23 AM **NOTIFICATION DATE:** 9/20/2012 11:45:14 AM
NOTIFIED BY: SPENCER PACULA
DAMAGE ADDRESS: 1015 ORLANDO DR
CITY: FORT WAYNE **ST:** IN **ZIP:**

DAMAGED CUSTOMER: NIPSCO

INVESTIGATION DATE: 09/20/2012
FROM: 12:00:00 **TO:** 12:25:00

EXCAVATOR INVOLVED: PRECISION
TYPE OF EXCAVATION: INST FFTP DROP

ORIG. LOCATE REQ.: 1209112260 **START DATE/TIME:**
TYPE OF TICKET: Routine **LOCATE REQ. INFO N/A:**

DIG UP/DAMAGE REQ.: 1209201654 **START DATE/TIME:**

PICTURES TAKEN BY: STEVE SEDIK **DATE/TIME:** 9/20/2012 12:05:00 PM
PHOTOGRAPHY TYPE: Digital **FRAME #:**

INVESTIGATOR EMP#: 113185 **INVESTIGATOR NAME:** ROSS GILLESPIE
BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED? No

Fact Based Investigation Customer Information

NOTIFICATION ID: 01820120920002
SELECT A CUSTOMER: NIPSCO
CUSTOMER #: *(optional)*

FACILITY DESCRIPTION: LOWPROF **FACILITY ID:** Gas Service
LOCATOR NAME & EMP #: Sedik Stephen - 125397
LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:

Other

Other: Not Marked

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):

Visual, Facility Exposed At Time Of Investigation,

Investigator Verified Existing Marks By Hooking Up

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

TECH FOLLOWED TEMP DROP ON GROUND, CONT CHANGED ROUTE AND BORED A SIDEWALK WHILE DIGGING ON EITHER SIDE OF THE WALK THEY HIT THE SERVICE WITH A SHOVEL

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

NA

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

NA

LIST ANY OTHER INDIVIDUALS ON SITE:

NA

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? No

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? Yes

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? No

EXTENT OF FACILITY DAMAGE PL SER

REPLACEMENT FOOTAGE 1

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No

WHAT CONTRACTOR EQUIPMENT WAS USED? SHOVEL

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? No

IF YES, PLEASE LIST RECORD #(S)

**NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT**

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA FT WAYNE - 280 MAXIMO WO # M.562070
 OPERATING AREA CONTACT Jesse GAVEL JOB ORDER # JD 574494
 TRACKING NUMBER 018-2012-0920-002 LOCATE REF # 1209112260-5A
 Locate Performed By: USIC

DATE AND TIME OF ACCIDENT 8-20-2012 M DATE OF REPORT 8-20-2012
 PLACE OF DAMAGE (INCLUDE CITY) 1015 ORLANDO DR. FT WAYNE, IN 46825

DAMAGE WAS TO:
ELECTRIC - POLE / TRANSFORMER: # _____ SIZE _____ YEAR INSTALLED _____ BROKEN YES () NO ()
 OTHER (DESCRIBE) _____

GAS: SERVICE MAIN () SIZE 2" MATERIAL: PLASTIC STEEL () METER () REG STATION () STUB ()
 OTHER (DESCRIBE) CUT 2" SERVICE

DEPTH OF FACILITY (Inches) 18" PRESSURE (PSI) 15 Lbs.

RELEASE OF GAS: YES NO () IGNITION OF GAS: YES () NO EVACUATION REQUIRED: YES () # _____ NO

INTERRUPTION OF SERVICE: YES NO () NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED 11:48 EST TIME SHUT OFF 12:20 EST TIME RESTORED 13:00

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: CUT IN HALF

LOCATE MARKS ON SITE: YES () DISTANCE BETWEEN FACILITY AND LOCATE MARKS _____ NO
 HOW LOCATED: PAINT () FLAGS () BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) PRECISION UTILITIES GROUP INC

ADDRESS OF PARTY (INCLUDE CITY) 5714 ST JOE RD., FT WAYNE, IN 46835

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE SHANE GANN - SUPERVISOR

WITNESS NAME AND ADDRESS MIKE FINK - NIPSCO EMPLOYEE

WITNESS REMARKS NO LOCATE MARKS, DIGGING WITH SHOVEL & CUT LINE IN HALF

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY _____ REPORT # _____
 FIRE () AGENCY _____ REPORT # _____
 OTHER () _____ Any Injuries? () YES # _____ NO

PHOTOS TAKEN: YES NO () TAKEN BY: MICHAEL J FINK (ATTACH PHOTOS TO REPORT)
 MEDIA ON SITE YES () NO

- WORK IN PROGRESS WHEN FACILITY DAMAGED** - CHECK APPROPRIATE CHOICE BELOW
- | | | | |
|--|--|--|---|
| <input type="checkbox"/> AGRICULTURE/FARMING | <input checked="" type="checkbox"/> CABLE TV | <input type="checkbox"/> CURB/SIDEWALK | <input type="checkbox"/> TELECOMMUNICATIONS |
| <input type="checkbox"/> BLDG CONSTRUCTION | <input type="checkbox"/> DEMOLITION | <input type="checkbox"/> DRAINAGE | <input type="checkbox"/> WATER |
| <input type="checkbox"/> DRIVEWAY | <input type="checkbox"/> ELECTRIC | <input type="checkbox"/> SURVEYING | <input type="checkbox"/> DRAINS/CULVERTS |
| <input type="checkbox"/> FENCING | <input type="checkbox"/> GRADING | <input type="checkbox"/> IRRIGATION | <input type="checkbox"/> MOWING |
| <input type="checkbox"/> LANDSCAPING | <input type="checkbox"/> PIPELINE | <input type="checkbox"/> MILLING | <input type="checkbox"/> OTHER _____ |
| <input type="checkbox"/> POLE/SIGN POST | <input type="checkbox"/> ROAD WORK | <input type="checkbox"/> SEWER | |

- TYPE OF EQUIPMENT USED** - CHECK APPROPRIATE CHOICE BELOW
- | | | |
|--|--|--|
| <input type="checkbox"/> AUGER | <input checked="" type="checkbox"/> HAND TOOLS | <input type="checkbox"/> BACKHOE/TRACKHOE |
| <input type="checkbox"/> MILLING EQUIPMENT | <input type="checkbox"/> PROBING DEVICE | <input type="checkbox"/> BORING / DRILLING |
| <input type="checkbox"/> EXPLOSIVES | <input type="checkbox"/> TRENCHER | <input type="checkbox"/> FARM EQUIPMENT |
| <input type="checkbox"/> VACCUUM EQUIPMENT | <input type="checkbox"/> GRADER | <input type="checkbox"/> OTHER _____ |

- REASON DAMAGE OCCURRED** - CHECK APPROPRIATE CHOICE BELOW
- | | | |
|--|--|--|
| <input type="checkbox"/> AUTOMOTIVE ACCIDENT | <input type="checkbox"/> EXCAVATING BEFORE LOCATES DUE | <input type="checkbox"/> CARELESS MACHINE OPERATOR |
| <input type="checkbox"/> NO NOTIFICATION | <input type="checkbox"/> MARKS DISTURBED | <input type="checkbox"/> STUB |
| | | <input checked="" type="checkbox"/> OTHER <u>NO LOCATE MARKS</u> |

COMMENTS: NO LOCATE MARKS, CUT IN HALF WITH
SHOVEL WHILE DIGGING


PERSON PREPARING REPORT [Signature] 121557

FIELD SUPERVISOR [Signature]

FIELD MANAGER Rachel Dunn

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information




FOR OFFICE USE ONLY:

- | | | |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE | YES | NO |
| • NO IN 811 LOCATE CALLED IN | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST | YES | NO |

COMPLETED BY: _____ DATE: _____

3852



Precision Utilities Group, Inc.
5714 St. Joe Road
Fort Wayne, IN 46835

RECEIVED

MAR 07 2013

INDIANA UTILITY
REGULATORY COMMISSION

Nipsco

Reference to claim # 12 2043 in the amount of \$138.22 at 1015 Orland Dr,FTW,IN
Precision Utilities Group,INC is disputing claim due to the fact that we had a good locate
and nothing was located.

See attached documents.

Sincerely

Tom Salkeld

Director of Buried Drops

Precision Utilities Group,INC

Tom Salkeld
10/18/12

DLC SSP
UTILITY DAMAGE ROOT CAUSE REPORT

DATE: 9/20/2012

ITEM DAMAGED: Gas line

LOCATION OF DAMAGE: 1015 Orlando Dr

WORK ORDER NUMBER: 13244247

LOCATE #: 1209112260 - Sp

DAMAGED REPAIRED BY: NipSCO

NUMBER OF CUSTOMERS AFFECTED/OUT OF SERVICE? 1

DATE OF DAMAGE: 9/20/2012 TIME: 11:36am

CONTRACTOR: Precision Utilities Group, Inc

CONTRACTOR SUPERVISOR: Shane

OPERATOR: Thomas Brigham

TYPE OF EQUIPMENT USED (CHECK ONE):
DIRECTIONAL DRILL _____ BACKHOE _____ MISSILE _____

HAND DIGGING _____ OTHER Shovels

MARKS ON SITE Y _____ N No IF NOT WHY? _____

CONDITION OF MARKS? EXCELLENT _____ GOOD _____ POOR _____

NOT VISIBLE _____

DISTANCE FROM MARKS TO DAMAGE? _____ MARKS WITHIN TOLERANCE: YES _____ NO _____

POTHOLED: Y _____ N _____ CROSS TRENCHED? Y _____ N _____

DEPTH OF MISSILE OR BORE? _____ IF NOT WHY? _____

WHO'S AT FAULT? CONTRACTOR: _____ LOCATOR _____

WHY? _____

CONTRACTOR? RELEASED _____ RETAINED _____

SUB-CONTRACTORS NAME? _____

IF NOT WHY? _____

TIME REPAIR CREW ARRIVED: _____ SURFACE? _____ GRASS _____ CONCRETE _____

REPAIR PIT EXCAVATED BY? _____ ASPHALT _____

CONTRACTOR _____ FACILITY OWNER _____

OTHER _____

NORMAL NOTICE

Ticket : 1209112260 Date: 09/11/2012 Time: 01:31 Oper: SPENCER.PACULA Chan:000

State: IN Cnty: ALLEN Twp: WASHINGTON
 Cityname: FORT WAYNE Inside: N Near: Y
 Subdivision:

Address : 1015
 Street : ORLANDO DR
 Cross 1 : RODENBECK DR Within 1/4 mile: Y
 Location: LOCATE ENTIRE PROPERTY AND ALL EASEMENTS - LOCATE FROM PROTECTOR ON
 THE STRUCTURE TO FRONTIER TERMINAL H3002-143 - PLEASE FLAG AND PAINT - THANK
 YOU

Grids : 4108D8508A 4108D8509D 4108D8509C

Work type : FTTP DROP INSTALLATION
 Done for : FRONTIER
 Start date: 09/13/2012 Time: 13:45 Hours notice: 60/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 2 WEEKS Depth: 30 INCHES


Company : PRECISION UTILITIES GROUP INC Type: CONT
 Co addr : 5714 SAINT JOE ROAD
 City : FT WAYNE State: IN Zip: 46835
 Caller : SPENCER PACULA Phone: (260)485-8300
 Contact : SPENCER PACULA OFFICE Phone:
 BestTime:
 Mobile : (260)485-8300
 Fax : (260)485-8398
 Email : SPENCERPACULA@PRECISIONUG.NET

Remarks : All tickets are taken and processed on Eastern Daylight Time
 PRECISION REFERENCE NUMBER - 26045103841
 Will you be white-lining the dig site area? NO
 :


Submitted date: 09/11/2012 Time: 01:31
 Members: AEPIN CC FW ID8000 NIPSCO SM

Member Name	Facility Types
AMERICAN ELECTRIC POWER	ELECTRIC
COMCAST CABLEVISION - FT WAYNE	CABLE TV
FORT WAYNE, CITY OF	TRAFFIC
FRONTIER	TELEPHONE
NIPSCO	GAS & ELECTRIC

[View Map](#) [Close Map](#)



1015 ORLANDO DR. FTW, FL 9/20/12



Precision Utilities Group, Inc.
5714 St. Joe Road
Fort Wayne, IN 46835

Dear IURC

Precision Utilities Grouping feels that we are no in violation in Case # 3852 @ 1015 Orlando Dr, Fort Wayne, Allen County. We did have a valid locate # to due excavating at this address. The property was not located by The locate company for Nipsco. Please see attached documents which are ticket #1209112260, Picture of site after hit the gas line on 9/20/12, Damage form and letter to Nipsco.

Thank You

A handwritten signature in black ink, appearing to read "Tom Salkeld", written in a cursive style.

Tom Salkeld

Director of Buried Drops

Precision Utilities Grouping