



## Pipeline Safety Division Investigation Report

### Investigation regarding: Culy Contracting

UPPAC Database Record ID: 3855

Report Date: 7/11/2013

Investigator: Mike Orr

Damage Date: 9/21/2012 9:24:26 AM

Damage Address: Green St, New Haven, Allen

### The Parties

Excavator: **Culy Contracting**

Address: 5 Industrial Park Dr, Winchester, In 47394

Facility Owner: **NIPSCO**

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

### Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

### Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1209183326

Original Start Date:

Locate Instructions: FROM ABOVE INTERSECTION - LOCATE GOING NORTH APPROX 400 FEET ON BOTH SIDES OF GREEN ST TO 1708 GREEN ST

Follow-Up Locate Instructions (if applicable):

**Synopsis:** Excavator struck and damaged an underground natural gas service while performing water work.

**Findings:** Reported by Indiana 811; excavator's response to initial notice was received on 12/4/2012. Excavator had a valid locate; however, the gas operator provided an inaccurate facility locate marking.

**Conclusion:** There was a failure to provide accurate facility locate markings.

**Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.**



150 West Market Street, Suite 600  
Indianapolis, IN 46204

January 29, 2012

*Via Electronic Transmission – [PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)*

Pipeline Safety Division – Case No. 3855  
Indiana Utility Regulatory Commission  
101 West Washington Street, Suite 1500 East  
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3855

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 9/21/2012

Event Location: Green St

Facility Owner: Northern Indiana Public Service Company

Excavator: Culy Contracting

Other Party: N/A

Pipeline Division Case No. 3855

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle  
NiSource Corporate Services - Legal  
Phone: 317-684-4904  
Fax: 317-684-4918  
Email: [cearle@nisource.com](mailto:cearle@nisource.com)

<b>IURC INFORMATION REQUEST</b>	
<b>Pipeline Safety Division Case No. 3855</b>	
Date of Event	9/21/2012
Event Location	Green St
Event City	New Haven
Facility Owner	Northern Indiana Public Service Company
Excavator	Culy Contracting
Date of IURC Information Request	12/5/2012
<b>THE PARTIES</b>	
<b>EXCAVATOR:</b>	
BUSINESS NAME	Culy Contracting
RESPONSIBLE PARTY PERSONAL NAME	Rick Smith
TITLE (IF ANY)	
ADDRESS	5 Industrial Park Dr
CITY/ STATE/ZIP	Winchester, IN 47394
PREFERRED TELEPHONE	765-584-8509
CELL PHONE TELEPHONE	765-546-1611
EMAIL ADDRESS	
<b>FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:</b>	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
<b>LOCATOR SERVICE INFORMATION</b>	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	
EMAIL ADDRESS	morganthompson@usicinc.com
<b>OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION</b>	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
<b>UTILITY LINE IMPACT</b>	
<b>LOCATION OF DAMAGE</b>	
ADDRESS	1720 Green Rd
CITY/STATE/ZIP	New Haven, IN 46774
NEAREST INTERSECTION	
<b>PRODUCT TYPE (Select One)</b>	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
<b>FACILITY TYPE (Select One)</b>	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8"
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	
REPAIR COST (IF KNOWN) (\$)	
<b>CAUSE OF DAMAGE INFORMATION:</b>	
<b>TYPE OF EQUIPMENT (Select One)</b>	
Auger	
Backhoe/Trackhoe	X
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trancher	
Vacuum Equipment	
Unknown/Other	
<b>TYPE OF WORK PERFORMED (Select One)</b>	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	X
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y 1209210676
<b>LOCATE INFORMATION:</b>	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1209183326
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	N
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
<b>INCIDENT IMPACT INFORMATION</b>	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	N
POLICE DEPARTMENT RESPONSE (YES/NO)	N
AMBULANCE RESPONSE (YES/NO)	N
<b>ADDITIONAL INFORMATION/COMMENTS</b>	
Facility marking or location not sufficient.	



**NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**  
NA

**NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**  
NA

**LIST ANY OTHER INDIVIDUALS ON SITE:**  
NA

**WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL?** Yes

**WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA?** Yes

**WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS?** No

**EXTENT OF FACILITY DAMAGE** SER

**REPLACEMENT FOOTAGE** 1

**WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO?** No

**WHAT CONTRACTOR EQUIPMENT WAS USED?** BACKHOE

**IS THE FACILITY SHOWN ON THE UTILITY RECORDS?** No

**IF YES, PLEASE LIST RECORD #(S)**

NIPSCO 01117 IUPPSa 09/18/2012 19:59:21 1209183326-00A NORM NEW GRID

NORMAL NOTICE REMARK

Ticket : 1209183326 Date: 09/18/2012 Time: 19:48 Oper: MWALLACE Chan:043

State: IN Cnty: ALLEN Twp: ADAMS  
Cityname: NEW HAVEN Inside: Y Near: N  
Subdivision:

CASE: 3855

Address :

Street : GREEN ST

Cross 1 : MOELLER RD Within 1/4 mile: Y

Location: FROM ABOVE INTERSECTION - LOCATE GOING NORTH APPROX 400 FEET ON BOTH  
SIDES OF GREEN ST TO 1708 GREEN ST

:

Grids : 4103C8500B 4103B8500B

Boundary: n 41.058796 s 41.055359 w -85.011597 e -85.010071

Work type : INSTALL WATER MAIN

Done for : CITY OF NEW HAVEN

Start date: 09/21/2012 Time: 07:00 Hours notice: 59/48 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N

Duration : 1 MONTH Depth: 5 FEET

Company : CULY CONTRACTING Type: CONT

Co addr : 5 INDUSTRIAL PARK DR

City : WINCHESTER State: IN Zip: 47394

Caller : RICK SMITH Phone: (765)584-8509

Contact : RICK SMITH---CELL Phone:

BestTime:

Mobile : (765)546-1611

Fax : (765)584-8060

Email : RICKS@CULYCONTRACTING.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
REMARK DUE TO CONSTRUCTION --- PREV TICKET NUMBER 1209040162 - THANK YOU  
Will you be white-lining the dig site area? YES

:

Submitted date: 09/18/2012 Time: 19:48

Members: AEPIN CC FW ID7050 ID8000 NIPSCO SM

NIPSCO 00147 IUPPSa 09/21/2012 09:24:31 1209210676-00A EMER DAMG GRID

## DAMAGE REMARK

Ticket : 1209210676 Date: 09/21/2012 Time: 09:21 Oper: JSMITH Chan:088

State: IN Cnty: ALLEN Twp: ADAMS  
Cityname: NEW HAVEN Inside: Y Near: N  
Subdivision:

Case: 3855

## Address :

Street : GREEN ST

Cross 1 : MOELLER RD Within 1/4 mile: Y

Location: FROM ABOVE INTERSECTION - LOCATE GOING NORTH APPROX 400 FEET ON BOTH SIDES OF GREEN ST TO 1708 GREEN ST

:

Grids : 4103C8500B 4103B8500B

Boundary: n 41.058796 s 41.055359 w -85.011597 e -85.010071

Work type : INSTALL WATER MAIN

Done for : CITY OF NEW HAVEN

Start date: 09/21/2012 Time: 09:24 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 1 MONTH Depth: 5 FEET

Company : CULY CONTRACTING Type: CONT

Co addr : 5 INDUSTRIAL PARK DR

City : WINCHESTER State: IN Zip: 47394

Caller : DARREN YANEY Phone: (765)584-8509

Contact : RICK SMITH---CELL Phone:

BestTime:

Mobile : (765)546-1611

Fax : (765)584-8060

Email : RICKS@CULYCONTRACTING.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
PER DARREN YANEY--NIPSCO GAS LINE WAS CUT APPROX 40 FEET NORTH OF DEVERON STREET  
ON THE WEST SIDE OF GREEN STREET--CREW IS ON SITE--GAS LINE IS SEEPING BUT NOT  
BLOWING--CALLER HAS NOTIFIED NIPSCO OF THE DAMAGED LINE AND HAS BEEN ADVISED TO  
PLEASE ALSO NOTIFY 911--CALLER DESCRIBES THE LINE AS YELLOW PLASTIC AND IS  
APPROX 1/2 TO 3/4 OF AN INCH IN DIAMETER--PREVIOUS TICKET NUMBER IS  
1209183326--THANK YOU!!

Will you be white-lining the dig site area? YES

:

Submitted date: 09/21/2012 Time: 09:21

Members: AEPIN CC FW ID7050 ID8000 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY  
FACILITY DAMAGE REPORT

\*\* COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES \*\*

REPORTING OPERATING AREA FT. WAYNE MAXIMO WO# 17562841  
OPERATING AREA CONTACT \_\_\_\_\_ JOB ORDER # 574240  
TRACKING NUMBER 018 2012 0921 003 LOCATE REF # \_\_\_\_\_  
Locate Performed By: USIC

DATE AND TIME OF ACCIDENT 9-21 2012 9:22<sup>PM</sup> DATE OF REPORT 9-21-12  
PLACE OF DAMAGE (INCLUDE CITY) 1720 GREEN ST., NEW HAVEN

DAMAGE WAS TO:  
ELECTRIC - POLE / TRANSFORMER: # \_\_\_\_\_ SIZE \_\_\_\_\_ YEAR INSTALLED \_\_\_\_\_ BROKEN YES ( ) NO ( )  
OTHER (DESCRIBE) \_\_\_\_\_

GAS: SERVICE  MAIN ( ) SIZE 5/8 MATERIAL: PLASTIC  STEEL ( ) METER ( ) REG STATION ( ) STUB ( )  
OTHER (DESCRIBE) \_\_\_\_\_

DEPTH OF FACILITY (Inches) 23" PRESSURE (PSI) 50 Lbs.

RELEASE OF GAS: YES  NO ( ) IGNITION OF GAS: YES ( ) NO  EVACUATION REQUIRED: YES ( ) # \_\_\_\_\_ NO

INTERRUPTION OF SERVICE: YES  NO ( ) NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED 9:22am TIME SHUT OFF 9:42am TIME RESTORED 10:42am  
DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 5/8 CUT INTO SER. HAS FLOW VALVE REPAIR IN 1 HR  
CUST. NOT HOME C.B.I.

LOCATE MARKS ON SITE: YES  DISTANCE BETWEEN FACILITY AND LOCATE MARKS 60" NO ( )  
HOW LOCATED: PAINT ( ) FLAGS ( ) BOTH  WHITE LINED ( )

PARTY THAT CAUSED DAMAGES (NAME) GOULY CONTRACTING

ADDRESS OF PARTY (INCLUDE CITY) 5 INDUSTRIAL DR, WINCHESTER, IN, 47394

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE DARRM TANEY 765-546-0316

WITNESS NAME AND ADDRESS D TANEY

WITNESS REMARKS. MARKS WAS OFF

AGENCIES NOTIFIED / ONSITE: POLICE ( ) AGENCY \_\_\_\_\_ REPORT # \_\_\_\_\_  
FIRE ( ) AGENCY \_\_\_\_\_ REPORT # \_\_\_\_\_  
OTHER ( ) \_\_\_\_\_ Any Injuries? ( ) YES # \_\_\_\_\_  NO

PHOTOS TAKEN: YES ( ) NO  TAKEN BY: \_\_\_\_\_ (ATTACH PHOTOS TO REPORT)  
MEDIA ON SITE YES ( ) NO

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW  
( ) AGRICULTURE/FARMING ( ) CABLE TV ( ) CURB/SIDEWALK ( ) TELECOMMUNICATIONS  
( ) BLDG CONSTRUCTION ( ) DEMOLITION ( ) DRAINAGE  WATER  
( ) DRIVEWAY ( ) ELECTRIC ( ) SURVEYING ( ) DRAINS/CULVERTS  
( ) FENCING ( ) GRADING ( ) IRRIGATION ( ) MOWING  
( ) LANDSCAPING ( ) PIPELINE ( ) MILLING ( ) OTHER \_\_\_\_\_  
( ) POLE/SIGN POST ( ) ROAD WORK ( ) SEWER

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW  
( ) AUGER ( ) HAND TOOLS  BACKHOE/TRACKHOE  
( ) MILLING EQUIPMENT ( ) PROBING DEVICE ( ) BORING / DRILLING  
( ) EXPLOSIVES ( ) TRENCHER ( ) FARM EQUIPMENT  
( ) VACCUUM EQUIPMENT ( ) GRADER ( ) OTHER

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW  
( ) AUTOMOTIVE ACCIDENT ( ) EXCAVATING BEFORE LOCATES DUE ( ) CARELESS MACHINE OPERATOR  
( ) NO NOTIFICATION ( ) MARKS DISTURBED ( ) STUB  OTHER MARKS WAS OFF

• SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

COMMENTS: LOCATED OLD GAS SERVICE, NEW SERVICE WAS  
HIT AT SPOT LOCATER GAVE OK TO DIG


PERSON PREPARING REPORT JON HOGGLAND

FIELD SUPERVISOR Dwight Wagner

FIELD MANAGER Reid Dumm

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information



FOR OFFICE USE ONLY:

- |   |     |    |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE  | YES | NO |
| • NO IN 811 LOCATE CALLED IN                    | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE                                | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST  | YES | NO |

COMPLETED BY: \_\_\_\_\_ DATE: \_\_\_\_\_



## INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 3855

---

*The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.*

*Upon completion of answers select email button for submission.*

---

### The Parties

#### Excavator Information:

Business Name: Culy Contracting, Inc.

Responsible Party Personal Name: JJ Hall

Title (if any): Safety Environmental Director

Address (number and street): 5 Industrial Park Drive

City, State and ZIP Code: Winchester IN 47394

Preferred Telephone Number (area code): 765-584-8509

Cellular Telephone Number (area code): 765-220-2327

Email Address: jjh@culycontracting.com

#### Facility Information:

Business Name: Northern Indiana Public Service Company

Responsible Party Personal Name: \_\_\_\_\_

Title (if any): \_\_\_\_\_

Address (number and street): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

**Locator Service Information:**

Business Name: Nipsco

Responsible Party Personal Name: Rodger Brown

Title (if any): Locator

Address (number and street): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

---

**Cause of Damage Information**

Type of Equipment (select one): Backhoe/Trackhoe

Type of Work Performed (select one): Water

**Other Information (Witness, Police, Fire, Other):**

Personal Contact: Darin Yaney

Business/Organization Name: Culy Contracting

Title (if any): Supervisor

Address (number and street): 5 Industrial Park Dr

City, State and ZIP Code: Winchester IN 47394

Preferred Telephone Number (area code): 765-546-0316

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: N/A \_\_\_\_\_

---

### Utility Line Impact

#### Location of Damage:

Address (*number and street*): Green St \_\_\_\_\_

City, State and ZIP Code: New Haven IN Allen County \_\_\_\_\_

Nearest Intersection: \_\_\_\_\_

**Product Type (*select one*):** Natural Gas

**Facility Type (*select one*):** Service/Drop

**Size (Diameter/etc.):** 3/4 inch \_\_\_\_\_

**Pressure (PSIG/Inches):** \_\_\_\_\_

**Interruption in Service:**      Yes      No     **Number of Customers Affected:** 1 \_\_\_\_\_

**Evacuation:**      Yes      No     **If yes, How Many Evacuated?** \_\_\_\_\_

**Repair Cost (if known):** \$ 0 \_\_\_\_\_

**Release of Product:**      Yes      No

**Ignition and/or Fire:**      Yes      No

**Excavator Notify 811:**      Yes      No

---

### Locate Information

**Excavator Request Locate:**      Yes      No

**Indiana 811 Locate Ticket Number:** 1209040162 / 1209183326 \_\_\_\_\_

**Locate Marks Visible:**  Yes  No

**Locate Marks Correct:**  Yes  No

**Excavator "White Lined":**  Yes  No

**Maps Used to Mark Facilities:**  Yes  No

**Was Locate Provided within Two (2) Working Days:**  Yes  No

**Operator Employees On-site during Excavation:**  Yes  No

---

### Incident Impact Information

**Number of Outpatient Treated:** <sup>0</sup> \_\_\_\_\_

**Number of Inpatient Treated:** <sup>0</sup> \_\_\_\_\_

**Number of Fatalities:** <sup>0</sup> \_\_\_\_\_

**Fire Department Response:**  Yes  No

**Police Department Response:**  Yes  No

**Ambulance Response:**  Yes  No

---

### Additional Information / Comments

Where we was digging there was a yellow ok painted on the ground. The new gas service was not on the gas companies records.

**NARRATIVE STATEMENT**

Your Pipeline Safety Division Case Number: 3855

Your Full Name: JJ Hall

Full Name of Business / Entity (if applicable): Culy Contracting

Your Business Title (if applicable): Safety Director

Address (number and street): 5 Industrial Park Dr

City: Winchester State: in ZIP Code: 47394

Your E-mail Address: jjh@culycontracting.com

Today's Date (month, day, year): 12/04/12

Your Signature: \_\_\_\_\_ Title (if any) \_\_\_\_\_

Please return your Narrative Statement to:

**Pipeline Safety Division – Case Number 3855**  
**Indiana Utility Regulatory Commission**  
**101 West Washington Street, 1500E**  
**Indianapolis, IN 46204**

Or scan the statement and Email to:

[PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)

### DAILY TRUCK TICKET LOG

Truck #	Driver Name	Hours	Description (include stone ticket numbers, number of loads, number of dump fees, etc.)
T089			
T143			
T161			
T227			
T230			
T450			
T484			
T674			
T680			
T935			

**SUBCONTRACTORS USED:** Underground pipe and value, Inc. Ticket # 342253  
 (Sub-contractor Material/Stone Ticket #s)

MATERIAL PURCHASED AND/OR RENTAL EQUIPMENT			MATERIALS USED			
Type of Material/Equipment	P.O. #	Hours/Qty/Amount	Type of Material	In	Out	Quantity

**WORK PERFORMED:** Extended Trench on west side of Green Rd to the north. Made enough room to install a fire hydr onto the end of 12" to blow off water for samples.

**PROBLEMS/DELAYS:** Hit an unmarked gas service that had OK marked on the ground right above it

Was a line hit? yes Was it marked? no Are we responsible for the payment of fixing it? no Were pictures taken? yes

What is the name of the company representative contacted? NipSLO Rodger Brown

What is the dig-in-number? \_\_\_\_\_ What is the date of the dig-in? \_\_\_\_\_

Comments: OK was marked on the ground right above where we took out the ~~old~~ new gas service that was not on their records.

The existing dig-in # 120-904-0162  
The new ticket # good on 9-21-12 120-918-3326

Damage # 120-921-0676

**From:** [JJ Hall](#)  
**To:** [IURC PipelineDamageCase](#)  
**Subject:** CASE #3855  
**Date:** Tuesday, December 04, 2012 2:41:31 PM

---

To whom it may concern,

I have attached pictures of the job sight and of our ticket numbers and a brief description of what happened. Where we was digging was a yellow OK marked beside the hydrant we was working on. We did not receive a bill for this because it was unmarked. If you have any questions please let me know.

Thanks

*JJ Hall*

Vice President /

Safety & Environmental Director

[jjh@culycontracting.com](mailto:jjh@culycontracting.com)

[www.culycontracting.com](http://www.culycontracting.com)

Office: 765-584-8509

Mobile :765-220-2327

Fax :765-584-8060



MP





BUMP

