



Pipeline Safety Division Investigation Report

Investigation regarding: New Growth Landscapes

UPPAC Database Record ID: 3864

Report Date: 5/31/2013

Investigator: Mike Orr

Damage Date: 9/24/2012 10:56:15 AM

Damage Address: 4478 Huntington Ridge Dr, Newburgh, Warrick

The Parties

Excavator: **New Growth Landscapes**

Address: 1402 Brimm Street, Boonville, In 47601

Facility Owner: **Vectren**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Trencher

Type of Work Performed: Irrigation

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$199

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1209190803

Original Start Date:

Locate Instructions: LOCATE--ENTIRE PROPERTY--

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing irrigation work.

Findings: Reported by Indiana 811; excavator did not respond to initial notice mailed 11/30/2012. The excavator had a valid locate and the gas operator provided accurate locate markings; however, the excavator damaged the gas service line with a trencher.

Conclusion: There was a failure use hand tools within two (2) feet of the facility.

Violation: IC 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -
OPERATOR

CASE 3864

Submitted to IURC-Pipeline Safety on: 12-7-2012

Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

Excavator Information, if known

Full name: New Growth Landscapes

Business address (number and street): 1402 Brimm Street

City, State, and ZIP code: Boonville, IN 47601

Telephone number (area code): 812-598-3533

Fax number (area code): Unknown

E-mail address: Unknown

Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Trencher

Type of work performed: Irrigation

Date and Location of Damage

Date of damage (month, day, year): 9-24-2012

County: Warrick

City: Newburgh

Street address (number and street, city, state, and ZIP code):
4478 Huntington Ridge Circle, Newburgh, In

Nearest intersection: Unknown

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours): 1

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 198.76

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? _____

Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1209190803

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC _____

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Flags

If other, please specify: None _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? No

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

Additional Comments

1/2" plastic service severed by trencher. Not hand exposed.



PAID

NOW DUE


1 VECTREN ENERGY DELIVERY OF INDIANA - SOUTH

\$198.76

NEW GROWTH LANDSCAPES & IRRIGATION
1402 BRIMM STREET
BOONSVILLE, IN 47601

Type: GAS
Invoice: FDS0016992
BillToID: 32591
Billing Date: 10/31/2012
Date of Loss: 9/24/2012
5856 105.0510

Please return this portion with your remittance.



Mail Payment To:
Vectren Utilities Holding Company
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE
\$198.76

NEW GROWTH LANDSCAPES & IRRIGATION
1402 BRIMM STREET
BOONSVILLE, IN 47601

Type: GAS
Invoice: FDS0016992
BillToID: 32591
Billing Date: 10/31/2012
Date of Loss: 9/24/2012

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 4478 HUNTINGTON RIDGE CIR, NEWBURGH
1/2" PLASTIC SERVICE SEVERED BY TRENCHER. NOT HAND EXPOSED.

| | |
|---------------------------|----------|
| Material: | \$21.11 |
| Company Labor: | \$151.09 |
| Contract Labor: | \$0.00 |
| Transportation/Equipment: | \$26.56 |
| Misc: | \$0.00 |
| Gas Loss: | \$0.00 |
| Adjustments: | \$0.00 |
| Payments: | \$0.00 |
| <hr/> Total: | \$198.76 |

5856 105.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

TASK NO: 103,0510 Capital / O & M (circle one)
Date of Damage 9 / 24 / 12
Cost Center # 5856
Time Occurred 10:00 am / pm
Time Found 10:13 am / pm
Latitude 37.969780 Longitude: -87.419620

Vectren Claim Number: _____
Police Report / MO #: _____

FACILITIES DAMAGE REPORT

GAS

Vectren Claims Camera:
VE02965
4

DAMAGE SITE:
Address 4478 Huntington Ridge Cca Lot # _____
County Warrick City Newburg State IN Township 0 Hz 0

FACILITY TYPE:
 Distribution Propane
 Service Storage
 Transmission: (include supplemental report)

| FACILITIES DAMAGED: | ORIFICE SIZE(S): | (1) | (2) | (3) |
|--|------------------|-------------------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> Farm Tap | 0.50 inch | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Heater | 5/8 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Main | 0.75 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Meter (Residential) | 1.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Meter (Industrial / Commercial) | 1.25 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Odorizer | 2.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Regulator Station | 3.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Relief Valve | 4.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Riser | 5.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input checked="" type="checkbox"/> Service Line | 6.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Valve | 10.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| | 12.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| | 16.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> Other _____ | 20.00 inch | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| | Other _____ | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

VISUAL OBSERVATION AT DAMAGE SITE: 9/25
 Visual Observation: Above Ground Below Ground
 Locate Applicable: Yes No N/S
 Facilities Properly Marked: Yes No N/S
 Marking Methods: Conventional Flags None
 Offset Paint Stakes Whiskers
 Locate Marking Faded: Yes No N/S
 Wrong Address Requested: Yes No N/S

Facilities Improperly Located:
 Qualified Locator Could Not Have Accurately Located
 Inaccurate Maps / Cards
 Broken or No Tracer Wire (Plastic)
 Insulation Preventing Accurate Locate
 Locator Error:
 Failure to Follow Policy
 Inappropriate Site Markings
 Incomplete Locate
 No Locates Performed
 Qualified Locator Could Have Accurately Located
 Wrong Address Located
 Marking Off By: _____ (Feet / Inches)

TYPE OF MATERIAL: Cast Iron Plastic (HDPE) Plastic (MDPE) Steel
 DAMAGE TYPE: Severed Not Cut Severed
 Size 1/2 x 1/2
 PRESSURE: 25 PSIG 40 PSIG 50 PSIG 55 PSIG 60 PSIG 6 WC (.2163) 7 WC (252) Other 55

PROTECTION IN PLACE:
 Building Fence None
 Post Rail Vault N/A
 Other _____

DURATION OF ESCAPING GAS:

Minutes: 1

LEAK REPORT NUMBER: 20016

EFV Activated Yes No N/S

FEED TYPE:
 One-Way Feed
 Two-Way Feed

Number of Customers Affected: 1
Total Hours Service Was Off: 1

Were Facility Marks Visible: Yes No
 Was Area White Lined: Yes No Destroyed
 Positive Response: Yes No Destroyed
 Tolerance Zone Violated: Yes No
 Part of Project: Yes No
 Company Representative On-Site: Yes No

Observation by (ID#): 0268

Name of Locator: _____

LOCATING ORGANIZATION:

Contract Locator
 Unknown / Other
 Utility Owner

SERVICE ORDER NUMBER: _____

DAMAGED BY:
 Company Crew
 Contractor
 County
 Developer
 Farmer
 Municipality
 Property Owner/ Tenant
 Railroad
 State
 Unknown
 Utility
 Vehicle Accident
 Other _____

TYPE OF CONSTRUCTION:

Agriculture
 Building Construction
 Building Demolition
 Cable TV
 Curbs / Sidewalk
 Drainage
 Driveway
 Electric
 Engineering / Surveying
 Fencing
 Grading
 Irrigation
 Landscaping
 Liquid Pipeline
 Milling
 Pole
 Natural Gas
 Public Transit Authority
 Railroad Maintenance
 Other _____

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:

Locate Ticket: _____
Date: _____ Time: _____ am / pm

TYPE OF REQUEST:

Regular Request Emergency Request
 Locate Company Notified
 Contact Name: _____
 Time Called: _____ am / pm
 Time Locator Arrived at the Site: _____ am / pm

Company Notified of Locate Near Critical Facilities
 Yes No N/S

Copy of Mark Out Request Provided Within 2 Working Days
 Yes No N/S

ONE-CALL CENTER:

IUPPS
 OUPS
 Unknown

SEP 26 2012

Vectren Claim Number: _____

TYPE OF EQUIPMENT:

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other _____

ROOT DAMAGING CAUSE:

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other _____

Did Excavator Notify You

Yes No

Excavation Required

Yes No

Media at Site

Yes No

Was There Ignition of Gas?

Yes No

INVOICE:

Yes No N/S

CONTRACTOR REPAIRS:

- Contractor Working for Vectren Made Repairs at Own Expense
 - Yes No N/S
- Contractor Repaired Damage
 - Yes No N/S

Name of Contractor: _____

of Regular Hours; _____

of Overtime Hours; _____

of Regular Hours; _____

Crew Type: _____

MATERIALS OR ROAD WORK:

- Meter was replaced _____ (Stores Code)
- Regulator Was Replaced _____ (Stores Code)
- Temporary Asphalt Repair: _____ (sq. ft.)
- Permanent Asphalt Repair: _____ (sq. ft.)

RIGHT OF WAY:

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

DAMAGING PARTY:

Name: New Growth Landscapes & Irrigation

Address: 1402 Brimm St

City/ State/ Zip: Bonnieville IN 47601

Phone: (812) 598-3533

M. Bueh Prepared / Investigated By: 9-24-12 Date:

PARTY TO INVOICE:

Name: New Growth

Address: _____

City/ State/ Zip: _____

Phone: (_____) _____

Reviewed by Field Supervisor: _____ Date: _____

Ticket Portal Production

Ticket Text **Photos**

Ticket Text

ID5856 00309 IUPPSa 09/19/2012 10:06:21 1209190803-00A NORM NEW GRID
 NORMAL NOTICE
 Ticket : 1209190803 Date: 09/19/2012 Time: 10:00 Oper: BBASTIN Chan:045
 State: IN Cnty: WARRICK Twp: OHIO
 Cityname: NEWBURGH Inside: N Near: Y
 Subdivision: HUNTINGTON RIDGE
 Address : 4478
 Street : HUNTINGTON RIDGE DR
 Cross 1 : E LINCOLN AVE Within 1/4 mile: Y
 Location: LOCATE--ENTIRE PROPERTY
 :
 Grids : 3758D8725C 3758C8725C 3758D8725B 3758C8725B
 Boundary: n 37.972595 s 37.969181 w -87.428200 e -87.422119
 Work type : IRRIGATION INSTALL
 Done for : JORGE MORAN
 Start date: 09/21/2012 Time: 10:15 Hours notice: 48/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 2 DAYS Depth: 18 INCHES
 Company : NEW GROWTH LANDSCAPES Type: CONT
 Co addr : 1402 BRIMM STREET
 City : BOONVILLE State: IN Zip: 47601
 Caller : MATT WISSNER Phone: (812)598-3533
 Contact : MATT WISSNER - CELL Phone:
 BestTime:
 Mobile : (812)598-3533
 Email : MATTWISSNER@ATT.NET
 Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? NO
 :
 Submitted date: 09/19/2012 Time: 10:00
 Members: ID0716 ID2935 ID3356 ID5845 ID5856 ID6412 SBCIN SM

 Email_From: irth@iupps.org
 Email_Subject: IUPPS ID5856 2012/09/19 #00309 1209190803-00A NORM NEW
 Email_Sent_Date: 2012-09-19 09:06:22 CDT
 Email_host: tickets6.811tickets.com
 Email_user: 811.in.oc-vvc
 Email_To: 811.in.oc-vvc@tickets.811tickets.com
 Email_Contenttype: text/plain

Ticket Portal Production

Ticket Text **Photos**

Ticket Text

ATTIN Seq: 966 Transmitted: Mon Sep 24 09:58:05 CDT 2012
 SBCIN 00966 IUPPSa 09/24/2012 10:56:26 1209241526-00A EMER DAMG GRID
 DAMAGE DAMAGED
 Ticket : 1209241526 Date: 09/24/2012 Time: 10:52 Oper: DWILSON Chan:006
 State: IN Cnty: WARRICK Twp: OHIO
 Cityname: NEWBURGH Inside: N Near: Y
 Subdivision: HUNTINGTON RIDGE
 Address : 4478
 Street : HUNTINGTON RIDGE DR
 Cross 1 : E LINCOLN AVE Within 1/4 mile: Y
 Location: LOCATE--ENTIRE PROPERTY--
 :
 Grids : 3758D8725C 3758C8725C 3758D8725B 3758C8725B
 Boundary: n 37.972595 s 37.969181 w -87.428200 e -87.422119
 Work type : IRRIGATION INSTALL
 Done for : JORGE MORAN
 Start date: 09/24/2012 Time: 10:52 Hours notice: 0/0 Priority: EMER
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
 Duration : 2 DAYS Depth: 18 INCHES
 Company : NEW GROWTH LANDSCAPES Type: CONT
 Co addr : 1402 BRIMM STREET
 City : BOONVILLE State: IN Zip: 47601
 Caller : MATT WISSNER Phone: (812)598-3533
 Contact : MATT WISSNER - CELL Phone:
 BestTime:
 Mobile : (812)598-3533
 Email : MATTWISSNER@ATT.NET
 Remarks : All tickets are taken and processed on Eastern Daylight Time
 VECTREN GAS LINE HAS BEEN DAMAGED--GAS IS BLOWING--CAN SMELL THE GAS AND CAN
 HEAR IT--LINE WAS DAMAGED ON SOUTH SIDE OF THE HOUSE--CANNOT DESCRIBE THE
 LINE--DID ADVISE TO CALL 911--CREW IS ON SITE--ADVISED TO CALL VECTREN--PREVIOUS
 TICKET 1209190803--
 Will you be white-lining the dig site area? NO
 :
 Submitted date: 09/24/2012 Time: 10:52
 Members: ID0716 ID2935 ID3356 ID5845 ID5856 ID6412 SBCIN SM

 Email_From: att-tickets@tickets.translore.com
 Email_Subject: ATT Translore - 1209241526
 Email_Sent_Date: 2012-09-24 09:58:05 CDT
 Email_MessageID: <1348498685817.799728325.TransLore.att-tickets@tickets.translore.com>
 Email_host: tickets6.811tickets.com
 Email_user: 811.in.att
 Email_To: 811.in.att@tickets.811tickets.com
 Email_ContentType: text/plain; charset=ISO-8859-1



Property of United States Infrastructure Corporation
Photo taken on 9/24/2012 10:32:16 AM



Property of United States Infrastructure Corporation
Photo taken on 9/24/2012 10:34:20 AM

Service Order Status

Enter Service Order Number:

2120935



Home

Help

Banner Instance: CS03PROD CS01PROD CS02PROD

Order Number: S2120935

Order Type: LEAK

Order Status: Completed

Customer: 300638842 - MORAN JORGE

Prem: 1416713 - 4478 HUNTINGTON RIDGE CIR LOT 2

Technician: TS01 - TechSwitchEV

Order Dates and Times

Need Date: 9/24/2012 10:37:00 AM
Time Created: 9/24/2012 10:03:04 AM
Time Dispatched: 9/24/2012 10:23:33 AM
Time In Route: 9/24/2012 10:03:17 AM
Time On-Site: 9/24/2012 10:13:17 AM
Tech Complete: 9/24/2012 10:17:17 AM
Time Closed: 9/24/2012 10:17:17 AM

Events Performed/Completion Code

LKOT - CMP

Meter Information

Current ReadStatus

Old Meter: 0644 Active

New Meter:

Completion Notes

FOUND CUT SERVICE..EXCESS FLOW VALVE HAD SHUT OFF...SQUEEZED OFF AND REFERRED TO CREW FOR REPAIR...ORDER CLOSED BY LEBERHARD FORT M. BRETZ

Request Notes

HIT LINE /BLOWING SOUTH SIDE OF PROPERTY PER DONNIE WITH 811...HIT BY MATTWISSNER WITH NEW GROWTH L ANDSCAPE..CONT 812-598-3533...LOCATES1209190803/DAMAGE 1209241526/

MDSI Event Dates and Times

| Event | Date/Time | User |
|----------------------|-----------------------|--------------|
| OrdOrderComplete_evt | 9/24/2012 10:17:17 AM | TechSwitchEV |

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

MISCELLANEOUS CASH RECEIPT

(PLEASE ATTACH A COPY OF ALL CHECKS TO THIS FORM AND
USE PAPER CLIPS/DO NOT STAPLE CHECKS TO FORM)

PROCESS ROUTING FOR ALL VECTREN COMPANIES INCLUDING UTILITIES
AND NON REGULATED SUBSIDIARIES: SEND COMPLETED FORM,
ORIGINAL CHECK AND COPY OF CHECK TO REBECCA MINEAR IN
FINANCIAL ACCOUNTING, BRAUN BUILDING, EVANSVILLE. RETAIN COPY
OF CHECK AND FORM FOR YOUR RECORDS. PLEASE INCLUDE PROPER
ACCOUNTING SO RECEIPT MAY BE CREDITED ACCURATELY. PLEASE
INCLUDE YOUR PHONE NUMBER SO THE RECEIPT MAY BE EASILY
RESEARCHED BY THE FINANCIAL ACCOUNTING GROUP.

Activity Date: **11/15/2012
12:00:00 AM**

Your Name, not your initials (employee): **Pam Barber**

Your Phone Number (employee): **812-491-4734**

Party Check Received From (Check Payor):

Address of Check Writer (Check Payor):
BATCH1-NEW GROWTH LANDSCAPES AND IRRIGATIO

Check Number **3688**

Amount of Check **\$198.76**

Utility/Company Name **VECTREN ENERGY DELIVERY OF INDIANA - SOUTH**

Task Number **105.0510**

Job Number **FDS0016992**

Date Printed: 11/16/2012

Transaction Information G-7078054 CHI-861239 2012/11/15

[Back to Table of Contents](#)

Transaction Level Details

| | | | |
|-------------|------------|-------------|------------|
| Env Num | 4 | Envelope | G-7078054 |
| Transaction | G-7078054 | Lockbox | CHI-861239 |
| Date | 2012/11/15 | Time | 17:00 |
| Batch | 1 | Batch Item | 4 |
| Check | 4 | Amount | \$198.76 |
| ABA/RT | 286377777 | Account Num | 01051069 |
| Check Num | 03688 | | |

Envelope and Check Image

NEW GROWTH LANDSCAPES & IRRIGATION LLC 71-7777/2863 3688
MATTHEW K WISSNER
PH. 812-598-3533
1402 BRIMM STREET
BOONVILLE, IN 47601-2467

DATE 11/12/12

PAY TO Vectren
THE ORDER OF one hundred ninety eight ⁷⁶/₁₀₀ \$ 198.76
DOLLARS  Security Features Included Details on Back.

 EVANSVILLE TEACHERS FEDERAL CREDIT UNION
4401 Theater Drive • P.O. Box 5129
Evansville, IN 47715-3129

MEMO _____ MP

⑆ 286377777⑆ 01051069⑆ 03688


SPECIALTY B.V.E

YOUR ADDRESS

~~NEW GROWTH LAND~~
~~1402 S. BF~~
~~BOONVILLE~~


M. Wissner
2000 S. Center Rd.
Boonville, IN 47601

EVANSVILLE IN 476
E3 NON-POSTAGE



Vectren Utilities Holding Group, Inc.
1239 Reliable Parkway
Chicago, IL 60686-0012

606860012




Transaction Level Keyed Data

Remitter Name : NEW GROWTH LANDSCAPES AND IRRIGATIO Check Date : 2012/11/12

Invoice Level Keyed Data

| Invoice Number | Reference Number |
|----------------|------------------|
| FDS0016992 | 32591 |

| | | |
|---|---|----------------|
|  | | NOW DUE |
| 1 VECTREN ENERGY DELIVERY OF INDIANA - SOUTH | | \$198.76 |
| NEW GROWTH LANDSCAPES & IRRIGATION 1402 BRIMM STREET BOONSVILLE, IN 47801 | Type: GAS Invoice: FDS0016992 BillToID: 32591 Billing Date: 10/31/2012 Date of Loss: 9/24/2012 6858 105.0510 | |
| Please return this portion with your remittance. | | |