



## Pipeline Safety Division Investigation Report

### Investigation regarding: Taylor Made Rite

UPPAC Database Record ID: 3896

Report Date: 5/27/2013

Investigator: Mike Orr

Damage Date: 7/25/2012

Damage Address: 1040 Conkey St., Hammond, Lake

### The Parties

Excavator: Taylor Made Rite

Address: 6251 Madison Avenue, Hammond, In 46324

Facility Owner: NIPSCO

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Construction

### Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

### Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number: Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

**Synopsis:** A natural gas service line was damaged by a backhoe while building construction work was performed.

**Findings:** Reported by Carrie Ludwig (NIPSCO); excavator did not respond to initial notice mailed 3/27/2013. A general contractor had requested a locate on 6/8/2012 which had expired. The excavator causing damage failed to provide notice of excavation resulting in compromising the service line.

**Conclusion:** There was a failure to provide notice of excavation.

**Violation: IC 8-1-26-16(g) Failure to provide notice of excavation.**



150 West Market Street, Suite 600  
Indianapolis, IN 46204

January 29, 2012

*Via Electronic Transmission – [PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)*

Pipeline Safety Division – Case No. 3896  
Indiana Utility Regulatory Commission  
101 West Washington Street, Suite 1500 East  
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 3896

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 7/25/2012

Event Location: 1040 Conkey St.

Facility Owner: Northern Indiana Public Service Company

Excavator: Taylor Made Rite

Other Party: N/A

Pipeline Division Case No. 3896

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle  
NiSource Corporate Services - Legal  
Phone: 317-684-4904  
Fax: 317-684-4918  
Email: [cearle@nisource.com](mailto:cearle@nisource.com)

<b>IURC INFORMATION REQUEST</b>	
<b>Pipeline Safety Division Case No. 3896</b>	
Date of Event	7/25/2012
Event Location	1040 Conkey St.
Event City	Hammond
Facility Owner	Northern Indiana Public Service Company
Excavator	Taylor Made Rite
Date of IURC Information Request	12/5/2012
<b>THE PARTIES</b>	
<b>EXCAVATOR:</b>	
BUSINESS NAME	Taylor Made Rite
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	3110 Calumet Ave
CITY/ STATE/ZIP	Hammond, IN 46320
PREFERRED TELEPHONE	219-902-4172
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
<b>FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:</b>	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
<b>LOCATOR SERVICE INFORMATION</b>	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	
EMAIL ADDRESS	<a href="mailto:morganthompson@usicinc.com">morganthompson@usicinc.com</a>
<b>OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION</b>	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
<b>UTILITY LINE IMPACT</b>	
<b>LOCATION OF DAMAGE</b>	
ADDRESS	1040 Conkey St
CITY/STATE/ZIP	Hammond, IN 46320
NEAREST INTERSECTION	Calumet Ave
<b>PRODUCT TYPE (Select One)</b>	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
<b>FACILITY TYPE (Select One)</b>	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8" plastic
PRESSURE (PSIG/INCHES)	N/A
INTERRUPTION IN SERVICE (YES/NO)	Yes
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	No
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) (\$)	N/A
<b>CAUSE OF DAMAGE INFORMATION:</b>	
<b>TYPE OF EQUIPMENT (Select One)</b>	
Auger	
Backhoe/Trackhoe	X
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trancher	
Vacuum Equipment	
Unknown/Other	
<b>TYPE OF WORK PERFORMED (Select One)</b>	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	X
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Yes
IGNITION AND/OR FIRE (YES/NO)	No
EXCAVATOR NOTIFY 811 (YES/NO)	No
<b>LOCATE INFORMATION:</b>	
EXCAVATOR REQUEST LOCATE (YES/NO)	No

INDIANA 811 LOCATE TICKET NUMBER	N/A
LOCATE MARKS VISIBLE (YES/NO)	No
LOCATE MARKS CORRECT (YES/NO)	No
EXCAVATOR "WHITE LINED" (YES/NO)	No
MAPS USED TO MARK FACILITIES (YES/NO)	No
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	No
<b>INCIDENT IMPACT INFORMATION</b>	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	Yes
POLICE DEPARTMENT RESPONSE (YES/NO)	N/A
AMBULANCE RESPONSE (YES/NO)	N/A
<b>ADDITIONAL INFORMATION/COMMENTS</b>	
<p>No notification made to the one-call center.  Nipsco emergency repair ticket – 1207253268.</p>	

**Fact Based Investigation Report**

**NOTIFICATION ID:** 01820120725019                      **DISTRICT:** Northern IN  
**DAMAGE DATE:** 7/25/2012 6:45:00 PM      **NOTIFICATION DATE:** 7/25/2012 6:51:03 PM  
**NOTIFIED BY:** CARLA Other  
**DAMAGE ADDRESS:** 1040 CONKEY ST  
**CITY:** HAMMOND                      **ST:** IN      **ZIP:**

---

**DAMAGED CUSTOMER:** NIPSCO

---

**INVESTIGATION DATE:** 07/25/2012  
**FROM:** 18:35:00    **TO:** 20:10:00

---

**EXCAVATOR INVOLVED:** Homeowner  
**TYPE OF EXCAVATION:** Unknown

---

**ORIG. LOCATE REQ.:**    **START DATE/TIME:**  
**TYPE OF TICKET:**    **LOCATE REQ. INFO N/A:** Yes

---

**DIG UP/DAMAGE REQ.:** 1207253280                      **START DATE/TIME:** 7/25/2012 7:00:00 PM

---

**PICTURES TAKEN BY:** Vince Johnson      **DATE/TIME:** 7/25/2012 6:45:00 PM  
**PHOTOGRAPHY TYPE:** Digital                      **FRAME #:** 1

---

**INVESTIGATOR EMP#:** 118013                      **INVESTIGATOR NAME:** Vince Johnson  
**BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED?** No

---

**Fact Based Investigation Customer Information**

**NOTIFICATION ID:** 01820120725019  
**SELECT A CUSTOMER:** NIPSCO  
**CUSTOMER #:** (optional)

---

**FACILITY DESCRIPTION:** LOWPROF      **FACILITY ID:** Gas Service  
**LOCATOR NAME & EMP #:**  
**LOCATOR NOT KNOWN:** Yes

---

**CHECK ALL THAT APPLY TO INVESTIGATION:**  
No Locate Req. By Contractor

**Other:**

---

**CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):**  
Visual, Facility Exposed At Time Of Investigation,

Investigation Results Verified By Utility Representative

---

**INVESTIGATOR STATEMENT/CAUSAL FACTORS:**

Homeowner did not have a locate ticket for digging in his yard. Hit a plastic gas service behind house. Marked for Nipsco repairs. Photos attached to 1207253280.

**NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**

Nipsco on site made repairs as needed.

**NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:**

Homeowner on site, no locate called in.

**LIST ANY OTHER INDIVIDUALS ON SITE:**

N/a

---

**WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL?** No

**WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA?** No

**WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS?** No

**EXTENT OF FACILITY DAMAGE** cut plastic gas service

**REPLACEMENT FOOTAGE** splice kit 2ft

**WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO?** No

**WHAT CONTRACTOR EQUIPMENT WAS USED?** Unk.

**IS THE FACILITY SHOWN ON THE UTILITY RECORDS?** No

**IF YES, PLEASE LIST RECORD #(S)**



# DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: Nov 5, 2012

## Who is submitting this information?

Name of person providing this information: Carrie Ludwig

Business address (*number and street*): 3511 East 15th Ave

City, State, and ZIP code: Gary, IN 46403

Telephone number (*area code*): 219 962 0422

Fax number (*area code*): 219 962 0404

E-mail address: cludwig@nisource.com

## Excavator Information, if known

Full name: Taylor Made Rite

Business address (*number and street*): 3110 Calumet Ave

City, State, and ZIP code: Hammond, IN 46307

Telephone number (*area code*): (219) 902-4172

Fax number (*area code*): \_\_\_\_\_

E-mail address: \_\_\_\_\_

## Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Bldg. Construction

**Date and Location of Damage**

Date of damage (month, day, year): Jul 25, 2012

County: Lake

City: Hammond

Street address (number and street, city, state, and ZIP code):  
1040 Conkey St Hammond IN

Nearest intersection: Calumet Ave

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours):

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? 36

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? No

Enter Indiana 811 ticket number, if known:

Was the locate request completed within two working days? Unknown/Other

If locates were performed, were they done so by a contractor or pipeline employee? Unknown/Other

If a contractor locator, enter the company name, if known: \_\_\_\_\_

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? Unknown/Other

Type of markings used: Other

If other, please specify: no locates \_\_\_\_\_

Was site marked by "White Lining"?

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? No

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

**Description of Cause**

Select from the list the most accurate cause for the damage: --No notification made to the one-call center

---

**Additional Comments**

Nipsco emergency repair ticket #: 1207253268

Locates were called in for Thor General Contracting LLC # 1206081834

NORTHERN INDIANA PUBLIC SERVICE COMPANY  
FACILITY DAMAGE REPORT

\*\* COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES \*\*

REPORTING OPERATING AREA Hammond MAXIMO WO # \_\_\_\_\_  
OPERATING AREA CONTACT TaylorMade Rite JOB ORDER # 583051  
TRACKING NUMBER 018-2012-0725-019 LOCATE REF # \_\_\_\_\_  
Locate Performed By: \_\_\_\_\_

DATE AND TIME OF ACCIDENT 7-25-12 2012 5:28 PM DATE OF REPORT 7-25-12  
PLACE OF DAMAGE (INCLUDE CITY) 1040 Conkey St, Hammond, IN

DAMAGE WAS TO:  
ELECTRIC - POLE / TRANSFORMER: # \_\_\_\_\_ SIZE \_\_\_\_\_ YEAR INSTALLED \_\_\_\_\_ BROKEN YES ( ) NO ( )

OTHER (DESCRIBE) \_\_\_\_\_  
GAS:  SERVICE ( ) MAIN ( ) SIZE 5/8" MATERIAL  PLASTIC ( ) STEEL ( ) METER ( ) REG STATION ( ) STUB ( )  
OTHER (DESCRIBE) \_\_\_\_\_

DEPTH OF FACILITY (Inches) 36" PRESSURE (PSI) 40 Lbs.

RELEASE OF GAS  YES ( ) NO ( ) IGNITION OF GAS: YES ( )  NO ( ) EVACUATION REQUIRED: YES ( ) # \_\_\_\_\_  NO ( )

INTERRUPTION OF SERVICE  YES ( ) NO ( ) NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED \_\_\_\_\_ TIME RESTORED \_\_\_\_\_

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: cut in half

LOCATE MARKS ON SITE: YES ( ) DISTANCE BETWEEN FACILITY AND LOCATE MARKS \_\_\_\_\_ NO ( )  
HOW LOCATED: PAINT ( ) FLAGS ( ) BOTH ( ) WHITE LINED ( )

PARTY THAT CAUSED DAMAGES (NAME) TaylorMade Rite

ADDRESS OF PARTY (INCLUDE CITY) 3110 Calumet Ave, Hammond, IN

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE \_\_\_\_\_

WITNESS NAME AND ADDRESS \_\_\_\_\_

WITNESS REMARKS \_\_\_\_\_

AGENCIES NOTIFIED / ONSITE: POLICE ( ) AGENCY \_\_\_\_\_ REPORT # \_\_\_\_\_

FIRE  AGENCY Hammond Fire REPORT # \_\_\_\_\_

OTHER ( ) \_\_\_\_\_ Any Injuries? ( ) YES # \_\_\_\_\_ ( ) NO

PHOTOS TAKEN: YES ( ) NO ( ) TAKEN BY: \_\_\_\_\_ (ATTACH PHOTOS TO REPORT)  
MEDIA ON SITE YES ( ) NO ( )

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW

- |   |                                     |  |   |
|---|-------------------------------------|--|---|
| <input type="checkbox"/> AGRICULTURE/FARMING          | <input type="checkbox"/> CABLE TV   | <input type="checkbox"/> CURB/SIDEWALK | <input type="checkbox"/> TELECOMMUNICATIONS |
| <input checked="" type="checkbox"/> BLDG CONSTRUCTION | <input type="checkbox"/> DEMOLITION | <input type="checkbox"/> DRAINAGE      | <input type="checkbox"/> WATER              |
| <input type="checkbox"/> DRIVEWAY                     | <input type="checkbox"/> ELECTRIC   | <input type="checkbox"/> SURVEYING     | <input type="checkbox"/> DRAINS/CULVERTS    |
| <input type="checkbox"/> FENCING                      | <input type="checkbox"/> GRADING    | <input type="checkbox"/> IRRIGATION    | <input type="checkbox"/> MOWING             |
| <input type="checkbox"/> LANDSCAPING                  | <input type="checkbox"/> PIPELINE   | <input type="checkbox"/> MILLING       | <input type="checkbox"/> OTHER _____        |
| <input type="checkbox"/> POLE/SIGN POST               | <input type="checkbox"/> ROAD WORK  | <input type="checkbox"/> SEWER         |   |

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> AUGER             | <input type="checkbox"/> HAND TOOLS     | <input checked="" type="checkbox"/> BACKHOE/TRACKHOE |
| <input type="checkbox"/> MILLING EQUIPMENT | <input type="checkbox"/> PROBING DEVICE | <input type="checkbox"/> BORING / DRILLING           |
| <input type="checkbox"/> EXPLOSIVES        | <input type="checkbox"/> TRENCHER       | <input type="checkbox"/> FARM EQUIPMENT              |
| <input type="checkbox"/> VACCUUM EQUIPMENT | <input type="checkbox"/> GRADER         | <input type="checkbox"/> OTHER _____                 |

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW

- |  |  |  |
|--|--|--|
| <input type="checkbox"/> AUTOMOTIVE ACCIDENT | <input type="checkbox"/> EXCAVATING BEFORE LOCATES DUE | <input type="checkbox"/> CARELESS MACHINE OPERATOR |
| <input type="checkbox"/> NO NOTIFICATION     | <input type="checkbox"/> MARKS DISTURBED               | <input checked="" type="checkbox"/> OTHER _____    |

• SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

COMMENTS :

---

---

---

PERSON PREPARING REPORT

#076955

FIELD SUPERVISOR

*Tom Sandy* 4122732

FIELD MANAGER

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information

FOR OFFICE USE ONLY:

- |   |     |    |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE  | YES | NO |
| • NO IN 811 LOCATE CALLED IN                    | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE                                | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST  | YES | NO |

COMPLETED BY: \_\_\_\_\_ DATE: \_\_\_\_\_



## DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)

INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: Sep 28, 2012

---

### Who is submitting this information?

Name of person providing this information: Steve Noffsinger (NIPSCo)

Business address (*number and street*): 3511 E 15th Ave

City, State, and ZIP code: Gary, IN, 46403

Telephone number (*area code*): (219)962-0422

Fax number (*area code*): (219)962-0404

E-mail address: cludwig@nisource.com

---

### Excavator Information, if known

Full name: Phil Winter

Business address (*number and street*): 7724 W 1000 N

City, State, and ZIP code: Demotte, IN, 46310

Telephone number (*area code*): \_\_\_\_\_

Fax number (*area code*): \_\_\_\_\_

E-mail address: \_\_\_\_\_

---

### Excavation or Demolition Information

Excavator type: Occupant

Excavation or demolition equipment: Unknown/Other

Type of work performed: Driveway

---

**Date and Location of Damage**

Date of damage (*month, day, year*): Sep 8, 2012

County: Jasper

City: DeMotte

Street address (*number and street, city, state, and ZIP code*):  
7724 W 1000 N

Nearest intersection: Glendale Rd

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 0

Time to restore service (*in hours*): 1

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$

---

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? 18

---

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? No

Enter Indiana 811 ticket number, if known:

Was the locate request completed within two working days? Unknown/Other

If locates were performed, were they done so by a contractor or pipeline employee? Unknown/Other

If a contractor locator, enter the company name, if known: \_\_\_\_\_

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? Unknown/Other

Type of markings used: Other

If other, please specify: No locates \_\_\_\_\_

Was site marked by "White Lining"? No

Were special instructions part of the locate request? No

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? No

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### **Description of Cause**

Select from the list the most accurate cause for the damage: --No notification made to the one-call center

---

### **Additional Comments**

Nipsco emergency repair ticket 1209080129

Type of equipment used was a bobcat