



## Pipeline Safety Division Investigation Report

### Investigation regarding: Sun Communications

UPPAC Database Record ID: 4122

Investigator: Howard Friend

Report Date: 1/16/2013

Damage Date: 11/15/2012 11:27:20 AM

Damage Address: David Howarth Dr

City: Lafayette

County: Tippecanoe

### The Parties

Excavator: **Sun Communications**

Contact: Joe Hilbert, General Manager

Address: 17728 Sun Park Drive, Westfield, In 46074

Telephone:

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

## **Investigation regarding: Sun Communications**

UPPAC Database Record ID: 4122

### **Damage Impact**

Product release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$2139

### **Excavator Activities/Cause of damage information:**

Excavator request locates: Yes    Indiana 811 ticket Number: 1211011570

Type of Equipment: Directional Drilling

Type of work performed: Electric

**Synopsis:** Damage to a natural gas main occurred during excavation to install an electric line.

**Findings:** Reported by Indiana 811; excavator's response to initial notice was received on 1/4/2013. The excavator provided notice of excavation and the operator provided accurate locate markings. The excavator spotted the natural gas facility 15' from the actual crossing location. They failed to spot the facility at the location of the damage.

**Conclusion:** The excavator failed to spot the facility at the point of crossing and, therefore, failed to maintain clearance with the bore head.

**Violation: IC 8-1-26-20(b): Failure to plan excavation to avoid damage or interference with underground facilities; Failure to maintain two (2) feet clearance with mechanized equipment.**



## INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 4122

*The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.*

*Upon completion of answers select email button for submission.*

### The Parties

#### Excavator Information:

Business Name: Sun Communications Inc

Responsible Party Personal Name: Levi Harrison

Title (if any): Crew Leader

Address (number and street): 17728 Sun Park Drive

City, State and ZIP Code: Westfield, IN 46074

Preferred Telephone Number (area code): 317-896-2593

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

#### Facility Information:

Business Name: Vectren

Responsible Party Personal Name: \_\_\_\_\_

Title (if any): \_\_\_\_\_

Address (number and street): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

**Locator Service Information:**

Business Name: USIC \_\_\_\_\_

Responsible Party Personal Name: \_\_\_\_\_

Title (*if any*): \_\_\_\_\_

Address (*number and street*): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

**Cause of Damage Information**

**Type of Equipment (*select one*):** Directional Drilling

**Type of Work Performed (*select one*):** Electric

**Other Information (Witness, Police, Fire, Other):**

Personal Contact: \_\_\_\_\_

Business/Organization Name: \_\_\_\_\_

Title (*if any*): \_\_\_\_\_

Address (*number and street*): \_\_\_\_\_

City, State and ZIP Code: \_\_\_\_\_

Preferred Telephone Number (area code): \_\_\_\_\_

Cellular Telephone Number (area code): \_\_\_\_\_

Email Address: \_\_\_\_\_

---

**Utility Line Impact**

**Location of Damage:**

Address (number and street): David Howarth Dr.

City, State and ZIP Code: ~~Westfield, IN~~ West Lafayette, IN

Nearest Intersection: David Howarth Dr. and S 350

**Product Type (select one):** Natural Gas

**Facility Type (select one):** Distribution

**Size (Diameter/etc.):** 4"

**Pressure (PSIG/Inches):** \_\_\_\_\_

**Interruption in Service:**       Yes       No      **Number of Customers Affected:** \_\_\_\_\_

**Evacuation:**       Yes       No      **If yes, How Many Evacuated?** \_\_\_\_\_

**Repair Cost (if known):** \$ 3,000

**Release of Product:**       Yes       No

**Ignition and/or Fire:**       Yes       No

**Excavator Notify 811:**       Yes       No

---

**Locate Information**

**Excavator Request Locate:**       Yes       No

**Indiana 811 Locate Ticket Number:** 1211011570 / 1211151323

- Locate Marks Visible:**  Yes  No
- Locate Marks Correct:**  Yes  No
- Excavator "White Lined":**  Yes  No
- Maps Used to Mark Facilities:**  Yes  No
- Was Locate Provided within Two (2) Working Days:**  Yes  No
- Operator Employees On-site during Excavation:**  Yes  No

---

### Incident Impact Information

**Number of Outpatient Treated:** <sup>0</sup> \_\_\_\_\_

**Number of Inpatient Treated:** <sup>0</sup> \_\_\_\_\_

**Number of Fatalities:** <sup>0</sup> \_\_\_\_\_

**Fire Department Response:**  Yes  No

**Police Department Response:**  Yes  No

**Ambulance Response:**  Yes  No

---

### Additional Information / Comments

The line was spotted at 34" 15' away from damage. The damage site was hit at 55".

**NARRATIVE STATEMENT**

Your Pipeline Safety Division Case Number: 4122

Your Full Name: Joe Hilbert

Full Name of Business / Entity (if applicable): Sun Communications Inc

Your Business Title (if applicable): General Manager

Address (number and street): 17728 Sun Park Dr

City: Westfield State: IN ZIP Code: 40674

Your E-mail Address: joeh@suncommunication.com

Today's Date (month, day, year): 1/3/2013

Your Signature:  Title (if any) GM

Please return your Narrative Statement to:

**Pipeline Safety Division – Case Number 4122**  
**Indiana Utility Regulatory Commission**  
**101 West Washington Street, 1500E**  
**Indianapolis, IN 46204**

Or scan the statement and Email to:

**[PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)**



# DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -  
OPERATOR  
CASE 4122

Submitted to IURC-Pipeline Safety on: 12-14-2012

## Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

## Excavator Information, if known

Full name: Sun Communications

Business address (number and street): 17728 Sun Park Drive

City, State, and ZIP code: Westfield, IN 46074

Telephone number (area code): 317-896-2593

Fax number (area code): 317-867-0425

E-mail address: Unknown

## Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Boring

Type of work performed: Electric

**Date and Location of Damage**

Date of damage (month, day, year): 11-15-2012

County: Tippecanoe

City: Lafayette

Street address (number and street, city, state, and ZIP code):  
3701 S Howarth Street, Lafayette, IN (

Nearest intersection: Howarth & Burrswezey

Right of way where damage occurred: Dedicated Public Utility Easement

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (in hours): 2

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 2,138.87

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Distribution

What was the depth of the facility, in inches? 36

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1211011570

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? Yes

Type of markings used: Paint and Flags

If other, please specify: \_\_\_\_\_

Was site marked by "White Lining"? Yes

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

### **Description of Cause**

Select from the list the most accurate cause for the damage: --Failure to use hand tools where required

### **Additional Comments**

2" plastic main damaged by bore. Not hand exposed.

Vectren Claim Number: \_\_\_\_\_

FDS0017223

Task No: 103.0509 Capital O & M (circle one)

Police Report / MO #: \_\_\_\_\_

Date of Damage 11/15/12

Cost Center # 5955

Time Occurred 11:?? am / pm

Time Found 11:50 am / pm

Latitude 40.7663 Longitude: -86.834493

# FACILITIES DAMAGE REPORT

Vectren Claims Camera:

VE02350

DAMAGE SITE: 3701 S. HOWARTH ST. GAS  
Address: DAVID HOWARTH DR + BURRSWEZEY Lot # \_\_\_\_\_  
County: TIPPECANOE City: LAFAYETTE State: IN Township: FAIRFIELD

FACILITY TYPE:  
 Distribution  Propane  
 Service  Storage  
 Transmission: (include supplemental report)

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other _____	Other _____			

3.385

VISUAL OBSERVATION AT DAMAGE SITE: 11/15

Visual Observation:  Above Ground  Below Ground

Locate Applicable:  Yes  No  N/S

Facilities Properly Marked:  Yes  No  N/S

Marking Methods:  Conventional  Flags  None  Whiskers  
 Offset  Paint  Stakes

Locate Marking Faded:  Yes  No  N/S

Wrong Address Requested:  Yes  No  N/S

Facilities Improperly Located:

Qualified Locator Could Not Have Accurately Located

Inaccurate Maps / Cards

Broken or No Tracer Wire (Plastic)

Insulation Preventing Accurate Locate

Locator Error:

Failure to Follow Policy

Inappropriate Site Markings

Incomplete Locate

No Locates Performed

Qualified Locator Could Have Accurately Located

Wrong Address Located

Marking Off By: \_\_\_\_\_ (Feet / Inches)

TYPE OF MATERIAL:  Cast Iron  Plastic (HDPE)  Plastic (MDPE)  Steel  Other \_\_\_\_\_

DAMAGE TYPE:  Severed  Not Cut  Severed

Size: 3" x 3"

PRESSURE:

25 PSIG  40 PSIG  50 PSIG  55 PSIG  60 PSIG  6 WC (.2163)  7 WC (252)  Other \_\_\_\_\_

260.566

PROTECTION IN PLACE:

Building  Fence  None  Post  Rail  Vault  N/A  Other \_\_\_\_\_

DURATION OF ESCAPING GAS:

Minutes: 15 mins

LEAK REPORT NUMBER: \_\_\_\_\_

EFV Activated  Yes  No  N/S

Were Facility Marks Visible:  Yes  No  Destroyed

Was Area White Lined:  Yes  No  Destroyed

Positive Response:  Yes  No  Destroyed

Tolerance Zone Violated:  Yes  No

Part of Project:  Yes  No

Company Representative On-Site:  Yes  No

FEED TYPE:  One-Way Feed  Two-Way Feed

Number of Customers Affected: 1

Total Hours Service Was Off: 2 Hrs

Observation by (ID#): 2375

Name of Locator: \_\_\_\_\_

LOCATING ORGANIZATION:

Contract Locator  Unknown / Other  Utility Owner

SERVICE ORDER NUMBER: \_\_\_\_\_

DAMAGED BY:

Company Crew  Contractor  County  Developer  Farmer  Municipality  Property Owner/ Tenant  Railroad  State  Unknown  Utility  Vehicle Accident  Other \_\_\_\_\_

TYPE OF CONSTRUCTION:

Agriculture  Building Construction  Building Demolition  Cable TV  Curbs / Sidewalk  Drainage  Driveway  Electric  Engineering / Surveying  Fencing  Grading  Irrigation  Landscaping  Liquid Pipeline  Milling  Pole  Natural Gas  Public Transit Authority  Railroad Maintenance  Other \_\_\_\_\_

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:

Locate Ticket: \_\_\_\_\_

Date: \_\_\_\_\_ Time: \_\_\_\_\_ am / pm

TYPE OF REQUEST:

Regular Request  Emergency Request

Locate Company Notified

Contact Name: \_\_\_\_\_

Time Called: \_\_\_\_\_ am / pm

Time Locator Arrived at the Site: \_\_\_\_\_ am / pm

Company Notified of Locate Near Critical Facilities  Yes  No  N/S

Copy of Mark Out Request Provided Within 2 Working Days  Yes  No  N/S

ONE-CALL CENTER:

IUPPS  OUPS  Unknown

Vectren Claim Number: \_\_\_\_\_

**TYPE OF EQUIPMENT:**

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other \_\_\_\_\_

**ROOT DAMAGING CAUSE:**

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided

Other **DID NOT EXPOSE MAIN AT CROSS OVER**

**CONTRACTOR REPAIRS:**

- Contractor Working for Vectren Made Repairs at Own Expense  
 Yes  No  N/S
- Contractor Repaired Damage  
 Yes  No  N/S

Name of Contractor: \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 # of Overtime Hours; \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 Crew Type: \_\_\_\_\_

**MATERIALS OR ROAD WORK:**

- Meter was replaced \_\_\_\_\_ (Stores Code)
- Regulator Was Replaced \_\_\_\_\_ (Stores Code)
- Temporary Asphalt Repair: \_\_\_\_\_ (sq. ft.)
- Permanent Asphalt Repair: \_\_\_\_\_ (sq. ft.)

Did Excavator Notify You

- Yes  No

Excavation Required

- Yes  No

Media at Site

- Yes  No

Was There Ignition of Gas?

- Yes  No

INVOICE:

- Yes  No  N/S

**RIGHT OF WAY:**

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other - **Public right of way**
- Public - State Highway
- Public - City Street
- Unknown

**DAMAGING PARTY:**

Name: SUN COMMUNICATIONS INC  
 Address: 17728 SUN PARK DRIVE  
 City/ State/ Zip: WESTFIELD IN  
 Phone: (317) 896-2593 46074  
 Prepared/ Investigated By: [Signature] Date: 11-15-12

**PARTY TO INVOICE:**

Name: \_\_\_\_\_  
 Address: \_\_\_\_\_  
 City/ State/ Zip: SAME  
 Phone: \_\_\_\_\_  
 Reviewed by Field Supervisor: [Signature] Date: 11-16-12

FDRS ID: 8442

NORMAL NOTICE

Ticket : 1211011570 Date: 11/01/2012 Time: 11:23 Oper: SPEOPLES Chan:036

State: IN Cnty: TIPPECANOE Twp: WEA  
 Cityname: LAFAYETTE Inside: Y Near: N  
 Subdivision:

Address :  
 Street : DAVID HOWARTH DR  
 Cross 1 : BURR SWEZEY DR Within 1/4 mile: Y  
 Location: FROM THE ABOVE INTERSECTION - START LOCATE FROM NORTHEAST CORNER OF THE INTERSECTION - LOCATE GOING WEST TO THE WEST SIDE OF DAVID HOWARTH DRIVE - BORING INCLUDED  
 \*\*\*Boring Where = UNDER DAVID HOWARTH DR  
 :  
 Grids : 4021A8650D 4022D8650D

Work type : INSTALL POWER LINE  
 Done for : DUKE ENERGY  
 Start date: 11/05/2012 Time: 11:45 Hours notice: 97/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
 Duration : 1 WEEK Depth: 3 FEET

Company : SUN COMMUNICATIONS Type: CONT  
 Co addr : 17728 SUN PARK DRIVE  
 City : WESTFIELD State: IN Zip: 46074  
 Caller : BRAD WEIMER Phone: (317)896-2593  
 Contact : BRAD WEIMER - CELL Phone:  
 BestTime:  
 Mobile : (317)523-4656  
 Fax : (317)867-0425  
 Email : BRADW@SUNCOMMUNICATION.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 Will you be white-lining the dig site area? YES  
 :

Submitted date: 11/01/2012 Time: 11:23  
 Members: ID0002 ID4561 ID4866 ID5958 ID6383 ID8000 SM

Member Name	Facility Types
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
LAFAYETTE UTILITIES, CITY OF	WATER
PURDUE UNIV I LIGHT FIBER	FIBER OPTIC
VECTREN-CRAWFORDSVILLE	GAS
ZAYO BANDWIDTH	FIBER OPTIC

NORMAL NOTICE

Ticket : 1211011524 Date: 11/01/2012 Time: 11:13 Oper: SPEOPLES Chan:036

State: IN Cnty: TIPPECANOE Twp: WEA  
 Cityname: LAFAYETTE Inside: Y Near: N  
 Subdivision:

Address :  
 Street : DAVID HOWARTH DR  
 Cross 1 : E 350 S Within 1/4 mile: Y  
 Location: FROM THE ABOVE INTERSECTION - LOCATE SOUTH ON THE EAST SIDE OF DAVID HOWARTH DR FOR 500 FEET TO THE DUKE ENERGY SWITCH GEAR - THEN LOCATE A 25 FOOT RADIUS OF DUKE ENERGY SWITCH GEAR TPI2518 -  
 \*\*\*Boring Where = UNDER DAVID HOWARTH DR

Grids : 4021A8649A 4022D8649A 4021A8650D 4022D8650D

Work type : INSTALL POWER LINE  
 Done for : DUKE ENERGY  
 Start date: 11/05/2012 Time: 11:30 Hours notice: 97/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
 Duration : 1 WEEK Depth: 3 FEET

Company : SUN COMMUNICATIONS Type: CONT  
 Co addr : 17728 SUN PARK DRIVE  
 City : WESTFIELD State: IN Zip: 46074  
 Caller : BRAD WEIMER Phone: (317)896-2593  
 Contact : BRAD WEIMER - CELL Phone:  
 BestTime:  
 Mobile : (317)523-4656  
 Fax : (317)867-0425  
 Email : BRADW@SUNCOMMUNICATION.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 Will you be white-lining the dig site area? YES  
 :

Submitted date: 11/01/2012 Time: 11:13  
 Members: ID0002 ID4561 ID4866 ID5958 ID6383 ID8000 SM

Member Name	Facility Types
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
LAFAYETTE UTILITIES, CITY OF	WATER
PURDUE UNIV I LIGHT FIBER	FIBER OPTIC
VECTREN-CRAWFORDSVILLE	GAS
ZAYO BANDWIDTH	FIBER OPTIC

# Service Order Status

Monday, December 3, 2012

**Enter Service Order Number:**

5430007



View Order | Refresh Page

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD  
**Order Number:** N5430007  
**Order Type:** INVE  
**Order Status:** Completed

**Customer:** 008888888 - INACTIVE CUSTOMER  
**Prem:** 5728315 - DAVID HOWARTH DR& BURRS WEZEY

**Technician:** 2375 - Shirley, Gary

**Order Dates and Times**

**Need Date:** 11/15/2012 11:51:00 AM  
**Time Created:** 11/15/2012 11:52:13 AM  
**Time Dispatched:** 11/15/2012 11:52:13 AM  
**Time In Route:** 11/15/2012 11:54:23 AM  
**Time On-Site:** 11/15/2012 11:54:27 AM  
**Tech Complete:** 11/15/2012 2:34:37 PM  
**Time Closed:** 11/15/2012 2:34:37 PM

**Events Performed/Completion Code**

IVEG - CMP

**Meter Information**

**Current Read/Status**

**Old Meter:**  
**New Meter:**

**Completion Notes**

FOUND 4" MAIN HIT BY BORING ARGER, SHUT OFF VALVE THAT FEED'S 3701 DAVID HOWARTH DR M# 116250, READ 68653, WAS ABLE TO RELIGHT AFTER CREW REPAIRED,OK, MAIN WAS 5'FT DEEP, SUN COMMUNICATION'S DID NOT SPOT MAIN, G SHIRLEY

**Request Notes**

HIT 4 INCH MAIN/BLOWING REPORTED BY BRAD WEIMER WITH SUN COMMUNICATION/PH317 523 4656/XST: SOUTH OF VETERANS MEM HWY/LOCAT#1211011570/DAM TICKET1211151323/NO OTHER INFO AVAIL

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentEnRoute_evt	11/15/2012 11:54:23 AM	Shirley, Gary
AsnAssignmentManualAck_evt	11/15/2012 11:54:24 AM	Shirley, Gary
AsnAssignmentOnSite_evt	11/15/2012 11:54:27 AM	Shirley, Gary
OrdOrderComplete_evt	11/15/2012 2:34:37 PM	Shirley, Gary

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

DAMAGE DAMAGE

Ticket : 1211151323 Date: 11/15/2012 Time: 11:26 Oper: BBASTIN Chan:045

State: IN Cnty: TIPPECANOE Twp: WEA  
 Cityname: LAFAYETTE Inside: Y Near: N  
 Subdivision:

Address :  
 Street : DAVID HOWARTH DR  
 Cross 1 : BURR SWEZEY DR Within 1/4 mile: Y  
 Location: FROM THE ABOVE INTERSECTION - START LOCATE FROM NORTHEAST CORNER OF THE INTERSECTION - LOCATE GOING WEST TO THE WEST SIDE OF DAVID HOWARTH DRIVE - BORING INCLUDED  
 \*\*\*Boring Where = UNDER DAVID HOWARTH DR  
 :  
 Grids : 4021A8650D 4022D8650D

Work type : INSTALL POWER LINE  
 Done for : DUKE ENERGY  
 Start date: 11/15/2012 Time: 11:26 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y  
 Duration : 1 WEEK Depth: 3 FEET

Company : SUN COMMUNICATIONS Type: CONT  
 Co addr : 17728 SUN PARK DRIVE  
 City : WESTFIELD State: IN Zip: 46074  
 Caller : BRAD WEIMER Phone: (317)896-2593  
 Contact : BRAD WEIMER - CELL Phone:  
 BestTime:  
 Mobile : (317)523-4656  
 Fax : (317)867-0425  
 Email : BRADW@SUNCOMMUNICATION.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 A VECTREN GAS LINE HAS BEEN DAMAGED AT THE INTERSECTION--GAS LINE IS BLOWING--LINE IS YELLOW 4INCH PLASTIC--ADVISED TO CALL 911 AND VECTREN--CREW IS ON SITE--PREV TICKET NUMBER IS 1211011570  
 Will you be white-lining the dig site area? YES  
 :

Submitted date: 11/15/2012 Time: 11:26  
 Members: ID0002 ID4561 ID4866 ID5958 ID6383 ID8000 SM

Member Name	Facility Types
DUKE ENERGY / FORMERLY CINERGY	ELECTRIC
FRONTIER	TELEPHONE
LAFAYETTE UTILITIES, CITY OF	WATER
PURDUE UNIV I LIGHT FIBER	FIBER OPTIC
VECTREN-CRAWFORDSVILLE	GAS
ZAYO BANDWIDTH	FIBER OPTIC



Property of United States Infrastructure Corporation  
Photo taken on 11/15/2012 12:46:16 PM



Property of United States Infrastructure Corporation  
Photo taken on 11/15/2012 12:45:56 PM



Property of United States Infrastructure Corporation  
Photo taken on 11/15/2012 12:46:46 PM



Property of United States Infrastructure Corporation  
Photo taken on 11/15/2012 12:47:02 PM



Property of United States Infrastructure Corporation  
Photo taken on 11/15/2012 12:48:34 PM



Property of United States Infrastructure Corporation  
Photo taken on 11/15/2012 12:47:24 PM