



Pipeline Safety Division Investigation Report

Investigation regarding: Hasse Construction Company

UPPAC Database Record ID: 4281

Report Date: 7/15/2013

Investigator: Mike Orr

Damage Date: 12/11/2012 4:00:24 PM

Damage Address: Greenwood Ave, Munster, Lake

The Parties

Excavator: **Hasse Construction Company**

Address: 10 Lincoln Ave, Calumet City, Il 60409

Facility Owner: **NIPSCO**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Storm Drain

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1211291104

Original Start Date:

Locate Instructions: locate center line to west right of way on greenwood avenue from fisher street north to 35th street approx 1100 feet

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas live service stub while performing storm sewer work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 2/27/2013. The excavator had a valid locate ticket; however, the gas operator self reported the maps and records did not reflect the long steel service stub.

Conclusion: There was a failure to provide locate markings for the live service stub.

Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.



150 West Market Street, Suite 600
Indianapolis, IN 46204

March 7, 2013

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 4281
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 4281

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 12/11/2012

Event Location: Greenwood Ave

City: Munster

Facility Owner: Northern Indiana Public Service Company

Excavator: Hasse Construction Company

Other Party: N/A

Pipeline Division Case No. 4281

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher C. Earle".

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 4281	
Date of Event	12/11/2012
Event Location	Greenwood Ave
Event City	Munster
Facility Owner	Northern Indiana Public Service Company
Excavator	Hasse Construction Company
Date of IURC Information Request	2/13/2013
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	Hasse Construction Company
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	10 Lincoln Avenue
CITY/ STATE/ZIP	Calumet City / IL / 60409
PREFERRED TELEPHONE	(219) 932-1611
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	8810 Greenwood Avenue
CITY/STATE/ZIP	Munster / IN / 46321
NEAREST INTERSECTION	Fisher Street
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	3/4"
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	0
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	X
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	X
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y – Ticket# 1212112074
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1211291104
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	Y
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	Y
POLICE DEPARTMENT RESPONSE (YES/NO)	N/A
AMBULANCE RESPONSE (YES/NO)	N/A
ADDITIONAL INFORMATION/COMMENTS	
<p>Facility could not be found/located (stub). Emergency ticket# 1212112134.</p>	

Fact Based Investigation Report

NOTIFICATION ID: 01820121211008

DISTRICT: Northern IN

DAMAGE DATE: 12/11/2012 4:00:33 PM

NOTIFICATION DATE: 12/11/2012 4:05:22 PM

NOTIFIED BY: SCOTT SHADER

DAMAGE ADDRESS: GREENWOOD AVE

CITY: MUNSTER

ST: IN ZIP:

DAMAGED CUSTOMER: NIPSCO

INVESTIGATION DATE: 12/11/2012

FROM: 17:50:00

TO: 18:00:00

EXCAVATOR INVOLVED: HASSE CONSTRUCTION

TYPE OF EXCAVATION: Storm Sewer install

ORIG. LOCATE REQ.: 1211291104

START DATE/TIME: 12/4/2012 3:30:00 PM

TYPE OF TICKET: Routine

LOCATE REQ. INFO N/A:

DIG UP/DAMAGE REQ.: 1212112074

START DATE/TIME: 12/11/2012 5:50:00 PM

PICTURES TAKEN BY: Brad Nagel

DATE/TIME: 12/11/2012 5:50:00 PM

PHOTOGRAPHY TYPE: Digital

FRAME #:

INVESTIGATOR EMP#: 134728

INVESTIGATOR NAME: Brad Nagel

BASED ON YOUR INVESTIGATION, IS FURTHER INVESTIGATION NEEDED? No

Fact Based Investigation Customer Information

NOTIFICATION ID: 01820121211008

SELECT A CUSTOMER: NIPSCO

CUSTOMER #: *(optional)*

FACILITY DESCRIPTION: LOWPROF

FACILITY ID: Gas Service

LOCATOR NAME & EMP #: Wesley Tony - 124875

LOCATOR NOT KNOWN:

CHECK ALL THAT APPLY TO INVESTIGATION:

Old Request

Other: Retired long side steel service

CHECK ALL THAT APPLY TO METHOD OF INVESTIGATION (at least one must be checked):

Visual, Facility Exposed At Time Of Investigation

INVESTIGATOR STATEMENT/CAUSAL FACTORS:

There was a retired long side steel service that damaged during the installation of a storm sewer. There was no indication of the line the on the prints. All connected services were marked correctly. There was nothing wrong with the locate that was done at the site. Matt Gray LOA from NIPSCO agreed that the locates were good USIC is not at fault. Post locate photos are on master ticket 1211291101.

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

Matt Gray agreed the area was marked correctly.

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:

n/a

LIST ANY OTHER INDIVIDUALS ON SITE:

n/a

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? No

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? No

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? No

EXTENT OF FACILITY DAMAGE punctured line

REPLACEMENT FOOTAGE 3'

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO?

WHAT CONTRACTOR EQUIPMENT WAS USED?

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? No

IF YES, PLEASE LIST RECORD #(S)

Facility: Transmission Lines; Folder: GM & T tickets; Assigned To: N/A

NIPSCO 00358 IUPPSa 11/29/2012 10:24:02 1211291104-00A NORM NEW GRID

NORMAL NOTICE REMARK

Ticket : 1211291104 Date: 11/29/2012 Time: 10:22 Oper: BRIAN.STARESINA Chan:000
Old Tkt: 1211090824 Date: 11/09/2012 Time: 10:18 Oper: BRIAN.STARESINA Rev: 00A

State: IN Cnty: LAKE Twp: NORTH
Cityname: MUNSTER Inside: N Near: Y
Subdivision:

Address :
Street : GREENWOOD AVE
Cross 1 : FISHER ST Within 1/4 mile: Y
Location: LOCATE CENTER LINE TO WEST RIGHT OF WAY ON GREENWOOD AVENUE FROM
FISHER STREET NORTH TO 35TH STREET APPROX 1100 FEET
:
Grids : 4133D8729B 4133C8729B 4133D8729A 4133C8729A
Boundary: n 41.556328 s 41.552246 w -87.496017 e -87.494537

Work type : STORM SEWER
Done for : TOWN OF MUNSTER
Start date: 12/03/2012 Time: 10:30 Hours notice: 96/48 Priority: NORM
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
Duration : 3 MONTHS Depth: 9 FEET

Company : HASSE CONSTRUCTION COMPANY Type: CONT
Co addr : 10 LINCOLN AVE
City : CALUMET CITY State: IL Zip: 60409
Caller : BRIAN STARESINA Phone: (219)932-1611
Contact : JOE PATRICK Phone:
BestTime:
Mobile : (219)746-0271
Fax : (708)862-2455

Remarks : All tickets are taken and processed on Eastern Daylight Time
Will you be white-lining the dig site area? NO
:

Submitted date: 11/29/2012 Time: 10:22
Members: COMCN IB ID6978 ID9330 NIPSCO SM

Facility: Transmission Lines; Folder: GM & T tickets; Assigned To: N/A

NIPSCO 00588 IUPPSa 12/11/2012 16:00:33 1212112074-00A EMER DAMG GRID

DAMAGE SEE REMARKS

Ticket : 1212112074 Date: 12/11/2012 Time: 15:59 Oper: SPOPE Chan:044

State: IN Cnty: LAKE Twp: NORTH
Cityname: MUNSTER Inside: N Near: Y
Subdivision:

Address :
Street : GREENWOOD AVE
Cross 1 : FISHER ST Within 1/4 mile: Y
Location: LOCATE CENTER LINE TO WEST RIGHT OF WAY ON GREENWOOD AVENUE FROM
FISHER STREET NORTH TO 35TH STREET APPROX 1100 FEET
:
Grids : 4133C8729A 4133C8729B 4133D8729A 4133D8729B
Boundary: n 41.556328 s 41.552246 w -87.496017 e -87.494537

Work type : STORM SEWER
Done for : TOWN OF MUNSTER
Start date: 12/11/2012 Time: 15:59 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 3 MONTHS Depth: 9 FEET

Company : HASSE CONSTRUCTION COMPANY Type: CONT
Co addr : 10 LINCOLN AVE
City : CALUMET CITY State: IL Zip: 60409
Caller : SCOTT SHADER Phone: (219)932-1611
Contact : JOE PATRICK Phone:
BestTime:
Mobile : (219)746-0271
Fax : (708)862-2455

Remarks : All tickets are taken and processed on Eastern Daylight Time
NIPSCO GAS LINE HAS BEEN CUT--LINE IS BLOWING--ADVISED TO CALL 911--LINE WAS CUT
IN FRONT OF 8818 GREENWOOD AVE--1 INCH STEEL LINE--CREW ON SITE--PREV TICKET
1211291104--THANK YOU
Will you be white-lining the dig site area? NO
:

Submitted date: 12/11/2012 Time: 15:59
Members: COMCN IB ID6978 ID9330 NIPSCO SM

Facility: Transmission Lines; Folder: GM & T tickets; Assigned To: N/A

NIPSCO 00599 IUPPSa 12/11/2012 16:34:01 1212112134-00A EMER NEW STRT

EMERGENCY EMERGENCY

Ticket : 1212112134 Date: 12/11/2012 Time: 16:31 Oper: LWORTON Chan:062

State: IN Cnty: LAKE Twp: NORTH
Cityname: MUNSTER Inside: Y Near: N
Subdivision:

Address : 8810
Street : GREENWOOD AVE
Cross 1 : FISHER ST Within 1/4 mile: Y
Location: LOCATE THE ENTIRE PROPERTY
:
Grids : 4133C8729B 4133D8729A 4133D8729B
Boundary: n 41.554336 s 41.552246 w -87.496038 e -87.494573

Work type : REPAIR GAS LINE
Done for : NIPSCO
Start date: 12/11/2012 Time: 16:32 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 6 FEET

Company : NIPSCO Type: MEMB
Co addr : 801 EAST 86TH AVENUE
City : MERRILLVILLE State: IN Zip: 46410
Caller : TANISHA GHOLSTON Phone: (800)322-2806
Contact : TONY SANCHEZ CELL Phone:
BestTime:
Mobile : (219)742-5267

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW IS ENROUTE
Will you be white-lining the dig site area? NO
:

Submitted date: 12/11/2012 Time: 16:31
Members: COMCN IB ID6978 ID9330 NIPSCO SM

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA HAMMOND MAXIMO WO #
OPERATING AREA CONTACT JOB ORDER # 568640
TRACKING NUMBER 01820121211008 LOCATE REF # 1211291104
Locate Performed By:

DATE AND TIME OF ACCIDENT 12-11 2012, 3:17P M DATE OF REPORT 12-11-2012
PLACE OF DAMAGE (INCLUDE CITY) 8810 GREENWOOD AVE. MUNSTER

DAMAGE WAS TO:
ELECTRIC - POLE / TRANSFORMER: # SIZE YEAR INSTALLED BROKEN YES () NO ()

OTHER (DESCRIBE)
GAS: SERVICE MAIN () SIZE 3/4" MATERIAL: PLASTIC () STEEL (X) METER () REG STATION () STUB ()

DEPTH OF FACILITY (Inches) 25" PRESSURE (PSI) 45 Lbs.
RELEASE OF GAS: YES (X) NO () IGNITION OF GAS: YES () NO (X) EVACUATION REQUIRED: YES () # NO (X)
INTERRUPTION OF SERVICE: YES (X) NO (X) NUMBER OF CUSTOMERS LOST: 0
DURATION OF INTERRUPTION: TIME REPORTED TIME RESTORED
DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY:

LOCATE MARKS ON SITE: YES () DISTANCE BETWEEN FACILITY AND LOCATE MARKS NO ()
HOW LOCATED: PAINT () FLAGS () BOTH () WHITE LINED ()
PARTY THAT CAUSED DAMAGES (NAME) HASSE CONSTRUCTION

ADDRESS OF PARTY (INCLUDE CITY)
WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE
WITNESS NAME AND ADDRESS
WITNESS REMARKS

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY REPORT #
FIRE (X) AGENCY MUNSTER FID REPORT #
OTHER () Any Injuries? () YES # () NO

PHOTOS TAKEN: YES () NO (X) TAKEN BY: (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO (X)

- WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW
() AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK () TELECOMMUNICATIONS
() BLDG CONSTRUCTION () DEMOLITION () DRAINAGE () WATER
() DRIVEWAY () ELECTRIC () SURVEYING () DRAINS/CULVERTS
() FENCING () GRADING () IRRIGATION () MOWING
() LANDSCAPING () PIPELINE () MILLING () OTHER
() POLE/SIGN POST (X) ROAD WORK () SEWER

- TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW
() AUGER () HAND TOOLS (X) BACKHOE/TRACKHOE
() MILLING EQUIPMENT () PROBING DEVICE () BORING / DRILLING
() EXPLOSIVES () TRENCHER () FARM EQUIPMENT
() VACCUUM EQUIPMENT () GRADER () OTHER

- REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW
() AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE () CARELESS MACHINE OPERATOR
() NO NOTIFICATION () MARKS DISTURBED (X) STUB () OTHER



INFORMATION REQUEST

State Form 54909 (2-12)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 4281

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria.

Upon completion of answers select email button for submission.

The Parties

Excavator Information:

Business Name: Hasse Construction Company, Inc.

Responsible Party Personal Name: Brian Staresina

Title (if any): Project Manager

Address (number and street): 10 Lincoln Ave

City, State and ZIP Code: Calumet City, IL 60409

Preferred Telephone Number (area code): 219-932-1611

Cellular Telephone Number (area code): 219-545-1082

Email Address: bstaresina@hasseconstruction.com

Facility Information:

Business Name: NIPSCO

Responsible Party Personal Name: _____

Title (if any): _____

Address (number and street): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Locator Service Information:

Business Name: _____

Responsible Party Personal Name: _____

Title (*if any*): _____

Address (*number and street*): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Cause of Damage Information

Type of Equipment (*select one*): Backhoe/Trackhoe

Type of Work Performed (*select one*): Storm Drain/Culvert

Other Information (Witness, Police, Fire, Other):

Personal Contact: _____

Business/Organization Name: _____

Title (*if any*): _____

Address (*number and street*): _____

City, State and ZIP Code: _____

Preferred Telephone Number (area code): _____

Cellular Telephone Number (area code): _____

Email Address: _____

Utility Line Impact

Location of Damage:

Address (number and street): 8810 Greenwood Ave _____

City, State and ZIP Code: Munster, IN 46321 _____

Nearest Intersection: Kraft Dr _____

Product Type (select one): Natural Gas

Facility Type (select one): Service/Drop

Size (Diameter/etc.): 3/4" _____

Pressure (PSIG/Inches): _____

Interruption in Service: Yes No **Number of Customers Affected:** _____

Evacuation: Yes No **If yes, How Many Evacuated?** _____

Repair Cost (if known): \$ _____

Release of Product: Yes No

Ignition and/or Fire: Yes No

Excavator Notify 811: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: 1211291102 _____

- Locate Marks Visible:** Yes No
- Locate Marks Correct:** Yes No
- Excavator "White Lined":** Yes No
- Maps Used to Mark Facilities:** Yes No
- Was Locate Provided within Two (2) Working Days:** Yes No
- Operator Employees On-site during Excavation:** Yes No

Incident Impact Information

Number of Outpatient Treated: N/A

Number of Inpatient Treated: N/A

Number of Fatalities: N/A

Fire Department Response: Yes No

Police Department Response: Yes No

Ambulance Response: Yes No

Additional Information / Comments

The gas main and services on Greenwood Avenue were correctly marked. The service that was damaged was a "retired" service still connected to main that was not marked. The locating service did not know it was there and neither did Hasse Construction. NIPSCO has since sent a representative to the site from their Underground Prevention Department to work with us to identify and locate "retired" services.

NARRATIVE STATEMENT

Your Pipeline Safety Division Case Number: 4281

Your Full Name: Brian Staresina

Full Name of Business / Entity (if applicable): Hasse Construction Company Inc.

Your Business Title (if applicable): Project Manager

Address (number and street): 10 Lincoln Ave

City: Calumet City State: IL ZIP Code: 60409

Your E-mail Address: bstaresina@hasseconstruction.com

Today's Date (month, day, year): 2/27/13

Your Signature: _____ Title (if any) Project Manager

Please return your Narrative Statement to:

Pipeline Safety Division – Case Number 4281
Indiana Utility Regulatory Commission
101 West Washington Street, 1500E
Indianapolis, IN 46204

Or scan the statement and Email to:

PipelineDamageCase@urc.in.gov

NORMAL NOTICE REMARK

Ticket : 1211291102 Date: 11/29/2012 Time: 10:22 Oper: BRIAN.STARESINA Chan:000
 Old Tkt: 1211090825 Date: 11/09/2012 Time: 10:18 Oper: BRIAN.STARESINA Rev: 00A

State: IN Cnty: LAKE Twp: NORTH
 Cityname: MUNSTER Inside: N Near: Y
 Subdivision:

Address :
 Street : GREENWOOD AVE
 Cross 1 : FISHER ST Within 1/4 mile: Y
 Location: LOCATE CENTER LINE TO EAST RIGHT OF WAY ON GREENWOOD AVENUE FROM
 FISHER STREET NORTH TO 35TH STREET APPROX 1100 FEET
 :
 Grids : 4133D8729B 4133C8729B 4133D8729A 4133C8729A

Work type : STORM SEWER
 Done for : TOWN OF MUNSTER
 Start date: 12/03/2012 Time: 10:30 Hours notice: 96/48 Priority: NORM
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N
 Duration : 3 MONTHS Depth: 9 FEET

Company : HASSE CONSTRUCTION COMPANY Type: CONT
 Co addr : 10 LINCOLN AVE
 City : CALUMET CITY State: IL Zip: 60409
 Caller : BRIAN STARESINA Phone: (219)932-1611
 Contact : JOE PATRICK Phone:
 BestTime:
 Mobile : (219)746-0271
 Fax : (708)862-2455

Remarks : All tickets are taken and processed on Eastern Daylight Time
 Will you be white-lining the dig site area? NO
 :

Submitted date: 11/29/2012 Time: 10:22
 Members: COMCN IB ID6978 ID9330 NIPSCO SM

Member Name	Facility Types
AT&T - DISTRIBUTION	TELEPHONE
COMCAST NORTH	CABLE TV
MUNSTER UTILITY DEPT., THE CIVIL TOWN OF	
NIPSCO	GAS & ELECTRIC
WOLVERINE PIPELINE	PIPELINE

*8810 GREEN WOOD
 GAS SERVICE
 3/4"*



"RETIRED" SERVICE
HIT BETWEEN THESE
TWO LOCATED
SERVICES.

W/G

1574V

MARKED
SERVICE

LOCATION OF "RETIRED"
SERVICE THAT WAS HIT

~~SEE~~

