



INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>
Office: (317) 232-2701
Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: **Greg Roesner**

UPPAC Database Record ID: 4398

Report Date: 8/6/2013

Investigator: Mike Orr

Damage Date: 11/19/2012

Damage Address: 119 N. Coquillard Drive, South Bend, St. Joseph

The Parties

Excavator: **Greg Roesner**

Address: 119 N. Coquillard Drive, South Bend, In 46617

Facility Owner: **NIPSCO**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Hand Tools

Type of Work Performed: Unknown/Other

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number: Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator/occupant struck and damaged an underground natural gas service while performing animal waste burial.

Findings: Reported by Carrie Ludwig (NIPSCO); excavator did not respond to initial notice mailed 2/14/2013. The excavator/occupant failed to request a locate ticket prior to excavating deeper than twelve (12) inches.

Conclusion: There was a failure to provide notice of excavation.

Violation: IC 8-1-26-16(g) Failure to provide notice of excavation.



150 West Market Street, Suite 600
Indianapolis, IN 46204

March 13, 2013

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 4398
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 4398

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 11/19/2012

Event Location: 119 N. Coquillard Drive

City: South Bend

Facility Owner: Northern Indiana Public Service Company

Excavator: Greg Roesner

Other Party: N/A

Pipeline Division Case No. 4398

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 4398	
Date of Event	11/19/2012
Event Location	119 N. Coquillard Drive
Event City	South Bend
Facility Owner	Northern Indiana Public Service Company
Excavator	Greg Roesner
Date of IURC Information Request	2/13/2013
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	Greg Roesener
RESPONSIBLE PARTY PERSONAL NAME	Greg Roesener
TITLE (IF ANY)	
ADDRESS	119 N Coquillard Dr
CITY/ STATE/ZIP	South Bend, IN 46617
PREFERRED TELEPHONE	574-229-1006
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	1-317-538-7301
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	

TITLE (IF ANY)	
ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	119 N Coquillard Dr
CITY/STATE/ZIP	South Bend, IN 46617
NEAREST INTERSECTION	E Washington St
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8"
PRESSURE (PSIG/INCHES)	35
INTERRUPTION IN SERVICE (YES/NO)	YES
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	NO
IF YES, HOW MANY EVACUATED	0
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	
Boring/Drilling	
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	X
Milling Equipment	

Probing Device	
Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	X-Animal waste disposal
RELEASE OF PRODUCT (YES/NO)	YES
IGNITION AND/OR FIRE (YES/NO)	NO
EXCAVATOR NOTIFY 811 (YES/NO)	NO
LOCATE INFORMATION:	

EXCAVATOR REQUEST LOCATE (YES/NO)	NO
INDIANA 811 LOCATE TICKET NUMBER	N/A
LOCATE MARKS VISIBLE (YES/NO)	NO
LOCATE MARKS CORRECT (YES/NO)	N/A
EXCAVATOR "WHITE LINED" (YES/NO)	N/A
MAPS USED TO MARK FACILITIES (YES/NO)	N/A
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	NO
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	
POLICE DEPARTMENT RESPONSE (YES/NO)	
AMBULANCE RESPONSE (YES/NO)	
ADDITIONAL INFORMATION/COMMENTS	
No notification made to the one-call center	

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA 060 MAXIMO WO #
OPERATING AREA CONTACT AMSS/only JOB ORDER # 576276
TRACKING NUMBER 018 2012 1119 011 LOCATE REF # N/A
Locate Performed By:

DATE AND TIME OF ACCIDENT 11/19 2012, 1852 DATE OF REPORT 11/19
PLACE OF DAMAGE (INCLUDE CITY) 119 N COQUILLARD DR SOUTH BEND

DAMAGE WAS TO:

ELECTRIC - POLE / TRANSFORMER: # SIZE YEAR INSTALLED BROKEN YES () NO ()

OTHER (DESCRIBE)

GAS: SERVICE MAIN () SIZE 5/8" MATERIAL: PLASTIC () STEEL () METER () REG STATION () STUB ()
OTHER (DESCRIBE)

DEPTH OF FACILITY (inches) 24" PRESSURE (PSI) 35 Lbs.

RELEASE OF GAS: YES () NO () IGNITION OF GAS: YES () NO () EVACUATION REQUIRED: YES () # NO ()

INTERRUPTION OF SERVICE: YES () NO () NUMBER OF CUSTOMERS LOST: 1930

DURATION OF INTERRUPTION: TIME REPORTED 1852 TIME SHUT OFF 1930 TIME RESTORED 2000

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 1/4" - BARELY NICKED W/ SPOON. TINY LEAK, MINIMAL GAS LOSS

LOCATE MARKS ON SITE: YES () DISTANCE BETWEEN FACILITY AND LOCATE MARKS NONE
HOW LOCATED: PAINT () FLAGS () BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) GARY ROESNER 574 229 1006

ADDRESS OF PARTY (INCLUDE CITY) 119 N COQUILLARD, SOUTH BEND

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE GARY

WITNESS NAME AND ADDRESS

WITNESS REMARKS

AGENCIES NOTIFIED / ON SITE: POLICE () AGENCY REPORT #
NA FIRE () AGENCY REPORT #

OTHER () Any Injuries? () YES # NO

PHOTOS TAKEN: YES () NO () TAKEN BY: (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO ()

WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW

- () AGRICULTURE/FARMING () CABLE TV () CURB/SIDEWALK () TELECOMMUNICATIONS
() BLDG CONSTRUCTION () DEMOLITION () DRAINAGE () WATER
() DRIVEWAY () ELECTRIC () SURVEYING () DRAINS/CULVERTS
() FENCING () GRADING () IRRIGATION () MOWING
() LANDSCAPING () PIPELINE () MILLING () OTHER
() POLE/SIGN POST () ROAD WORK () SEWER ANIMAL WASTE DISPOSAL

TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW

- () AUGER () HAND TOOLS () BACKHOE/TRACKHOE
() MILLING EQUIPMENT () PROBING DEVICE () BORING / DRILLING
() EXPLOSIVES () TRENCHER () FARM EQUIPMENT
() VACCUUM EQUIPMENT () GRADER () OTHER

REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW

- () AUTOMOTIVE ACCIDENT () EXCAVATING BEFORE LOCATES DUE () CARELESS MACHINE OPERATOR
() NO NOTIFICATION () MARKS DISTURBED () STUB () OTHER

SEE REVERSE SIDE FOR COMMENTS AND DIAGRAM

COMMENTS :

PERSON PREPARING REPORT BANDERDORF

FIELD SUPERVISOR ARMSTRONG - Tim CJ

FIELD MANAGER CLAY

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information

FOR OFFICE USE ONLY:

- | | | |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE | YES | NO |
| • NO IN 811 LOCATE CALLED IN | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST | YES | NO |

COMPLETED BY: _____ DATE: _____



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)
INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: Jan 16, 2013

Who is submitting this information?

Name of person providing this information: Carrie Ludwig

Business address (*number and street*): 3511 East 15th Avenue

City, State, and ZIP code: Gary, IN 46403

Telephone number (*area code*): (219) 962-0422

Fax number (*area code*): (219) 962-0404

E-mail address: cludwig@nisource.com

Excavator Information, if known

Full name: Greg Roesner

Business address (*number and street*): 119 N. Coquillard Drive

City, State, and ZIP code: South Bend, IN 46617

Telephone number (*area code*): (574) 229-1006

Fax number (*area code*): _____

E-mail address: _____

Excavation or Demolition Information

Excavator type: Occupant

Excavation or demolition equipment: Hand Tools

Type of work performed: Sewer (Sanitary/Storm)

Date and Location of DamageDate of damage (*month, day, year*): Nov 19, 2012County: St. JosephCity: South BendStreet address (*number and street, city, state, and ZIP code*):
119 N. Coquillard Drive, South Bend, IN 46617

Nearest intersection: _____

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? _____

Was there a customer service interruption? Yes

If yes, how many affected? 1Time to restore service (*in hours*): 1

Enter number of injuries, if applicable and known: _____

Enter number of fatalities, if applicable and known: _____

Property damage, Estimate \$ _____

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? 24

Notification, Locating, Marking

Did excavator request locates prior to commencing work? No

Enter Indiana 811 ticket number, if known: _____

Was the locate request completed within two working days? Unknown/Other

If locates were performed, were they done so by a contractor or pipeline employee? Unknown/Other

If a contractor locator, enter the company name, if known: _____

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? Unknown/Other

Type of markings used:

If other, please specify: _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request?

Were maps used to complete the locate request?

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? No

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --No notification made to the one-call center

Additional Comments

NAMES OF UTILITY REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:
n/a

NAMES OF EXCAVATOR'S REPRESENTATIVES CONTACTED OR ON SITE AND STATEMENT:
n/a

LIST ANY OTHER INDIVIDUALS ON SITE:
n/a

WERE ANY MARKINGS VISIBLE ON THE DAMAGE SITE UPON ARRIVAL? No

WERE ANY OTHER INDICATORS OF FACILITY PRESENT IN THE AREA? No

WAS THE EXCAVATION WITHIN THE TOLERANCE ZONE OF MARKS? No

EXTENT OF FACILITY DAMAGE n/a

REPLACEMENT FOOTAGE n/a

WAS CONTRACTOR ASSISTANCE REQUIRED? IF YES, WHO? No n/a

WHAT CONTRACTOR EQUIPMENT WAS USED? n/a

IS THE FACILITY SHOWN ON THE UTILITY RECORDS? No

IF YES, PLEASE LIST RECORD #(S) n/a



DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)

INDIANA UTILITY REGULATORY COMMISSION

Submitted to IURC-Pipeline Safety on: Jan 16, 2013

Who is submitting this information?

Name of person providing this information: Carrie Ludwig (NIPSCo)

Business address (*number and street*): 3511 East 15th Avenue

City, State, and ZIP code: Gary, IN 46403

Telephone number (*area code*): (219) 962-0422

Fax number (*area code*): (219) 962-0404

E-mail address: cludwig@nisource.com

Excavator Information, if known

Full name: Greg Roesner

Business address (*number and street*): 119 N. Coquillard Drive

City, State, and ZIP code: South Bend, IN 46617

Telephone number (*area code*): (574) 229-1006

Fax number (*area code*): _____

E-mail address: _____

Excavation or Demolition Information

Excavator type: Occupant

Excavation or demolition equipment: Hand Tools

Type of work performed: Sewer (Sanitary/Storm)

Date and Location of Damage

Date of damage (*month, day, year*): Nov 19, 2012

County: St. Joseph

City: South Bend

Street address (*number and street, city, state, and ZIP code*):
119 N. Coquillard Drive

Nearest intersection: _____

Right of way where damage occurred: Private - Land Owner

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? _____

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (*in hours*): 1

Enter number of injuries, if applicable and known: _____

Enter number of fatalities, if applicable and known: _____

Property damage, Estimate \$ _____

Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? 24

Notification, Locating, Marking

Did excavator request locates prior to commencing work? No

Enter Indiana 811 ticket number, if known: _____

Was the locate request completed within two working days? Unknown/Other

If locates were performed, were they done so by a contractor or pipeline employee? Unknown/Other

If a contractor locator, enter the company name, if known: _____

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? Unknown/Other

Type of markings used: Other

If other, please specify: _____

Was site marked by "White Lining"? No

Were special instructions part of the locate request?

Were maps used to complete the locate request?

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? No

Did the excavator notify 911 in the event of a release of product? Unknown/Other

Description of Cause

Select from the list the most accurate cause for the damage: --No notification made to the one-call center

Additional Comments