



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

## Pipeline Safety Division Investigation Report

### Investigation regarding: Sdp Manufacturing

UPPAC Database Record ID: 4461

Report Date: 7/18/2013

Investigator: William Boyd

Damage Date: 2/8/2013 1:57:34 PM

Damage Address: 112 W Walnut St, Albany, Delaware

### The Parties

Excavator: **Sdp Manufacturing**

Address: 400 Industrial Drive, Dunkirk, In 47336

Facility Owner: **Vectren**

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Auger

Type of Work Performed: Pole

### Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1351.78

### Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes  
2/1/2013

Indiana 811 Ticket Number: 1301301763

Original Start Date:

Locate Instructions: LOCATE--FROM THE BACK SIDE OF THE PROPERTY LINE TO THE MIDDLE OF THE PROPERTY (PARKING LOT) AROUND THE WHITE STAKE

Follow-Up Locate Instructions (if applicable):

**Synopsis:** Excavator struck and damaged an underground natural gas service while performing a pole installation.

**Findings:** Reported by Indiana 811; excavator's response to initial notice was received on 4/29/2013. The excavator damaged the line outside of the requested locate area. Excavator claims he called in a locate for 112 W. Walnut St. IN 811 claims the locate was for 211 W. Walnut St. The Pipeline Safety Division contacted IN 811 and asked them to review the call and they indicated the caller requested a locate for 211. A copy of the email from IN 811 confirming the locate location is included with the excavator and operator response.

**Conclusion:** The excavator damaged the line outside of the requested locate area.

**Violation: IC 8-1-26-16(g)(out) Failure to provide notice of excavation - damage occurred outside requested locate area.**



## DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -  
OPERATOR

CASE # 4461

Submitted to IURC-Pipeline Safety on: 04/03/2013

### Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

### Excavator Information, if known

Full name: SDP Manufacturing

Business address (number and street): 400 Industrial Drive

City, State, and ZIP code: Dunkirk, IN

Telephone number (area code): 765-730-9868

Fax number (area code): 765-768-5015

E-mail address: Unknown

### Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Auger

Type of work performed: Pole

---

**Date and Location of Damage**

Date of damage (month, day, year): 2-8-2013

County: Delaware

City: Albany

Street address (number and street, city, state, and ZIP code):  
112 W Walnut, Albany, IN

Nearest intersection: Unknown

Right of way where damage occurred: Private - Business

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? No

If yes, how many affected? 0

Time to restore service (in hours): 0

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 1,351.78

---

**Affected Facility Information**

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? \_\_\_\_\_

---

**Notification, Locating, Marking**

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1301301763

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? No

Were facilities marked correctly? No

Type of markings used: Other

If other, please specify: None

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### **Description of Cause**

Select from the list the most accurate cause for the damage: --Notification to one-call center made but not sufficient

---

### **Additional Comments**

1" plastic service severed by auger. Gave wrong address.




2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

NOW DUE  
FINAL  
\$1,351.78

S D P MANUFACTURING  
400 INDUSTRIAL DRIVE,  
DUNKIRK, IN 47336

Type: GAS  
Invoice: FDS0017463  
BillToID: 33020  
Billing Date: 3/20/2013  
Date of Loss: 2/8/2013  
5733 103.0510

Please return this portion with your remittance.



Mail Payment To:  
Vectren Utilities Holding Group  
1239 Reliable Parkway  
Chicago, IL 60686-0012  
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5  
Risk Management/Claims Department

S D P MANUFACTURING  
400 INDUSTRIAL DRIVE,  
DUNKIRK, IN 47336

Type: GAS  
Invoice: FDS0017463  
BillToID: 33020  
Billing Date: 3/20/2013  
Date of Loss: 2/8/2013

NOW DUE  
FINAL  
\$1,351.78

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 112 W WALNUT, ALBANY

1" PLASTIC SERVICE SEVERED BY AUGER. WRONG ADDRESS PROVIDED TO INDIANA 811.

Material:	\$69.43
Company Labor:	\$394.33
Contract Labor:	\$708.26
Transportation/Equipment:	\$55.00
Misc:	\$0.00
Gas Loss:	\$124.76
Adjustments:	\$0.00
Payments:	\$0.00
<b>Total:</b>	<b>\$1,351.78</b>

5733 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS

Task No.: 103.0510

Capital / O&M (circle one)

FDS 001.7463

FACILITY TYPE

- DISTRIBUTION
PROPANE
SERVICE
STORAGE
TRANSMISSION (include supplemental report)

TIME OCCURRED: 14:11 AM/PM
TIME FOUND: 14:36 AM/PM

DATE OF DAMAGE: 2/8/13

LATITUDE: 40.303870
LONGITUDE: -85.234340

Cost Center No.: 605 5733

DAMAGE SITE ADDRESS: 102 W. WALNUT LOT #

COUNTY: DEL CITY: MEN STATE: PA TOWNSHIP

Table with columns: FACILITIES DAMAGED, ORIFICE SIZE(S), (1), (2), (3). Includes rows for FARM TAP, HEATER, MAIN, METER RESIDENTIAL, etc.

- VISUAL OBSERVATION AT DAMAGE SITE
VISUAL OBSERVATION ABOVE GROUND
LOCATE APPLICABLE? YES NO N/S
FACILITIES PROPERLY MARKED
MARKING METHODS: CONVENTIONAL FLAGS
NONE OFFSET PAINT STAKES WHISKERS

Table with columns: TYPE OF MATERIAL, DAMAGE TYPE, PRESSURE. Includes rows for CAST IRON, PLASTIC (HDPE), PLASTIC (MDPE), STEEL.

- WERE FACILITY MARKS VISIBLE YES NO
WAS AREA WHITE LINED? YES NO DESTROYED
POSITIVE RESPONSE YES NO DESTROYED

PROTECTION IN PLACE: BUILDING FENCE NONE
DURATION OF ESCAPING GAS: 65 MINUTES

COMPANY REPRESENTATIVE ON SITE YES NO
OBSERVATION BY: Doug Meranda
NAME OF LOCATOR:
LOCATING ORGANIZATION:

LEAK REPORT NUMBER #:
EFV ACTIVATED YES NO N/S

FEED TYPE: ONE-WAY FEED
NUMBER OF CUSTOMERS AFFECTED: 1
TOTAL HOURS SERVICE WAS OFF: HOUSE VACANT GAS WAS OFF

COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS
YES NO N/S

Table with columns: DAMAGED BY, TYPE OF CONSTRUCTION. Includes rows for COMPANY CREW, CONTRACTOR, COUNTY, DEVELOPER, FARMER, etc.

NOTIFICATION AND OTHER DETAILS OF LOCATE
LOCATE TICKET #:
DATE: TIME: AM/PM
REGULAR REQUEST EMERGENCY REQUEST

WORKING FOR: CITY COUNTY DEVELOPER
PROPERTY OWNER STATE
UTILITY
IF OTHER

CONTACT NAME:
TIME CALLED: AM/PM
TIME LOCATOR ARRIVED AT SITE: AM/PM
LOCATE COMPANY NOTIFIED YES NO N/S
COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES
ONE CALL CENTER: IUPPS OUPS UNKNOWN

Handwritten note: 1/1 to 2/8 no ticket for Jay Co Rem...

TYPE OF EQUIPMENT	DAMAGING CAUSE
<input checked="" type="checkbox"/> AUGER	<input type="checkbox"/> ABANDON FACILITY
<input type="checkbox"/> BACKHOE/TRACKHOE	<input type="checkbox"/> DETERIORATED FACILITY
<input type="checkbox"/> BORING	<input type="checkbox"/> FACILITY COULD NOT BE FOUND/LOCATED
<input type="checkbox"/> DRILLING	<input checked="" type="checkbox"/> FACILITY WAS NOT LOCATED/MARKED
<input type="checkbox"/> EXPLOSIVES	<input type="checkbox"/> FAILURE TO MAINTAIN CLEARANCE
<input type="checkbox"/> FARM EQUIPMENT	<input type="checkbox"/> FAILURE TO MAINTAIN MARKS
<input type="checkbox"/> GRADER/SCRAPER	<input type="checkbox"/> FAILURE TO SUPPORT EXPOSED FACILITY
<input type="checkbox"/> HAND TOOLS	<input type="checkbox"/> FAILURE TO USE HAND TOOLS WHERE REQ
<input type="checkbox"/> MILLING EQUIPMENT	<input type="checkbox"/> IMPROPER BACKFILLING
<input type="checkbox"/> PLOW	<input checked="" type="checkbox"/> INCORRECT RECORDS/MAPS
<input type="checkbox"/> PROBING DEVICE	<input type="checkbox"/> MARKING OR LOCATIONS NOT SUFFICIENT
<input type="checkbox"/> TRENCHER	<input type="checkbox"/> NO NOTIFICATION MADE TO ONE-CALL CENT
<input type="checkbox"/> VACUUM EQUIPMENT	<input type="checkbox"/> ONE-CALL NOTIFICATION ERROR
<input type="checkbox"/> VEHICLE	<input type="checkbox"/> PREVIOUS DAMAGE
<input type="checkbox"/> IF OTHER _____	<input checked="" type="checkbox"/> WRONG INFORMATION PROVIDED
	<input type="checkbox"/> IF OTHER <u>WRONG ADDRESS GIVEN TO LOCATE</u>

**CONTRACTOR REPAIRS**

CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWNERS EXPENSE  
 YES  NO  N/S

CONTRACTOR REPAIRED DAMAGE  
 YES  NO  N/S

NAME OF CONTRACTOR: Miller Pipeline

# OF REGULAR HOURS: 1.50 total 4.50

# OF OVERTIME HOURS: 1.0 at 3.0

# OF REGULAR HOURS: \_\_\_\_\_

CREWTYPE: 3 Man Crew

**MATERIALS OR ROAD WORK**

METER WAS REPLACED \_\_\_\_\_ (STORES CODE)

REGULATOR WAS REPLACED \_\_\_\_\_ (STORES CODE)

TEMPORARY ASPHALT REPAIR \_\_\_\_\_ (SQ.FT.)

PERMANENT ASPHALT REPAIR \_\_\_\_\_ (SQ.FT.)

DID EXCAVATOR NOTIFY YOU?  YES  NO

EVACUATION REQUIRED?  YES  NO

MEDIA AT SITE?  YES  NO

WAS THERE IGNITION OF GAS?  YES  NO

**RIGHT OF WAY**

DEDICATED UTILITY EASEMENT

FEDERAL UTILITY EASEMENT

PIPELINE

POWER/TRANSMISSION LINE

PRIVATE - BUSINESS

PRIVATE - EASEMENT

PRIVATE - LAND OWNER

PUBLIC - COUNTY ROAD

PUBLIC - INTERSTATE HIGHWAY

PUBLIC - OTHER

PUBLIC - STATE HIGHWAY

PUBLIC - CITY STREET

UNKNOWN

INVOICE:  YES  NO  N/S

I think so

**DAMAGING PARTY**

NAME: JAY COUNTY REMC

ADDRESS: 484 S. 200th P.O. Box 904

CITY/STATE/ZIP: PORTLAND, INDI 47371

PHONE NUMBER: 260-726-7121 / 800-835-7362

PREPARED BY: MERANDA DATE: 8-8-13

**PARTY TO INVOICE**

NAME: Same

ADDRESS: \_\_\_\_\_

CITY/STATE/ZIP: \_\_\_\_\_

PHONE NUMBER: \_\_\_\_\_

REVIEWED BY FIELD SUPERVISOR: \_\_\_\_\_ DATE: 8-11-13

Locates Called in For all W. Walnut I was told

NORMAL NOTICE

Ticket : 1301301763 Date: 01/30/2013 Time: 16:02 Oper: SWOODFORD Chan:058

State: IN Cnty: DELAWARE Twp: DELAWARE  
 Cityname: ALBANY Inside: Y Near: N  
 Subdivision:

Address : 211  
 Street : W WALNUT ST  
 Cross 1 : N MAIN ST Within 1/4 mile: Y  
 Location: LOCATE--FROM THE BACK SIDE OF THE PROPERTY LINE TO THE MIDDLE OF THE  
 PROPERTY (PARKING LOT) AROUND THE WHITE STAKE  
 :  
 Grids : 4018C8514C 4018D8514C  
 Boundary: n 40.304361 s 40.303245 w -85.240473 e -85.237814

Work type : SETTING UTILITY POLE  
 Done for : DREW HALL  
 Start date: 02/01/2013 Time: 16:15 Hours notice: 48/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: N  
 Duration : 1 HOUR Depth: 7 FEET

Company : SDP MANUFACTURING Type: OTHR  
 Co addr : 400 INDUSTRIAL DRIVE  
 City : DUNKIRK State: IN Zip: 47336  
 Caller : DREW HALL Phone: (765)730-9868  
 Contact : SCOTT PITTMAN--CELL Phone:  
 BestTime:  
 Mobile : (765)730-9868  
 Fax : (765)768-5015  
 Email : DRU@SDPMFG.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 Will you be white-lining the dig site area? YES  
 :

Submitted date: 01/30/2013 Time: 16:02  
 Members: AEPIN ID4245 ID6112 ID8822 SBCIN SM

Member Name	Facility Types
ALBANY, TOWN OF	
AMERICAN ELECTRIC POWER	ELECTRIC
AT&T - DISTRIBUTION	COMMUNICATIONS
COMCAST NORTHEAST (HARTFORD CITY)	CABLE TV
VECTREN - MUNCIE	GAS



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 5:27:19 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 5:27:23 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 5:27:39 PM

DAMAGE SEE REMARKS

Ticket : 1302081457 Date: 02/08/2013 Time: 13:51 Oper: BMORRIS Chan:016

State: IN Cnty: DELAWARE Twp: DELAWARE  
 Cityname: ALBANY Inside: Y Near: N  
 Subdivision:

Address : 211  
 Street : W WALNUT ST  
 Cross 1 : N MAIN ST Within 1/4 mile: Y  
 Location: LOCATE--FROM THE BACK SIDE OF THE PROPERTY LINE TO THE MIDDLE OF THE  
 PROPERTY (PARKING LOT) AROUND THE WHITE STAKE

:  
 Grids : 4018C8514C 4018C8514D 4018D8514C 4018D8514D  
 Boundary: n 40.304435 s 40.303244 w -85.240508 e -85.236579

Work type : SETTING UTILITY POLE  
 Done for : DREW HALL  
 Start date: 02/08/2013 Time: 13:52 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y  
 Duration : 1 HOUR Depth: 7 FEET

Company : SDP MANUFACTURING Type: OTHR  
 Co addr : 400 INDUSTRIAL DRIVE  
 City : DUNKIRK State: IN Zip: 47336  
 Caller : DREW HALL Phone: (765)730-9868  
 Contact : SCOTT PITTMAN--CELL Phone:  
 BestTime:  
 Mobile : (765)730-9868  
 Fax : (765)768-5015  
 Email : DRU@SDPMFG.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 VECTREN GAS LINE HAS BEEN CUT IN THE REAR OF THE PROPERTY - SEEING AND SMELLING  
 GAS VAPORS - UNSURE OF SIZE/COLOR/MATERIAL - CREW IS ON SITE - 911 HAS BEEN  
 CALLED - HAVE ADVISED HIM TO CALL VECTREN - PREVIOUS TICKET - 1301301763  
 Will you be white-lining the dig site area? YES  
 :

Submitted date: 02/08/2013 Time: 13:51  
 Members: AEPIN ID4245 ID6112 ID8822 SBCIN SM

Member Name	Facility Types
ALBANY, TOWN OF	
AMERICAN ELECTRIC POWER	ELECTRIC
AT&T - DISTRIBUTION	COMMUNICATIONS
COMCAST NORTHEAST (HARTFORD CITY)	CABLE TV
VECTREN - MUNCIE	GAS



Property of United States Infrastructure Corporation  
Photo taken on 2/8/2013 3:22:30 PM



Property of United States Infrastructure Corporation  
Photo taken on 2/8/2013 3:22:36 PM



Property of United States Infrastructure Corporation  
Photo taken on 2/8/2013 3:22:39 PM

Thursday, February 14, 2013

# Service Order Status

**Enter Service Order Number:**

5518658



Clear Form

Refresh Data

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD

**Order Number:** N5518658

**Order Type:** LEAK

**Order Status:** Completed

**Customer:** 009999999 - OWNER UNKNOWN

**Prem:** 5734585 - 211 W WALNUT

**Technician:** 1896 - Meranda, Doug

**Order Dates and Times**

**Need Date:** 2/8/2013 2:27:00 PM  
**Time Created:** 2/8/2013 2:11:05 PM  
**Time Dispatched:** 2/8/2013 2:11:05 PM  
**Time In Route:** 2/8/2013 2:16:56 PM  
**Time On-Site:** 2/8/2013 2:58:24 PM  
**Tech Complete:** 2/8/2013 4:05:29 PM  
**Time Closed:** 2/8/2013 4:05:29 PM

**Events Performed/Completion Code**

LKNS - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:**

**New Meter:**

**Completion Notes**

hit service actual address 112 w. walnut.....dispatch sent right order

**Request Notes**

PER KRISTEN W/811 SDP MANUFACTURING HIT LINE BLOWING CONT# SCOTT PITMAN ONSITE CONT# 765-730-9868  
 BACK OF PROPERTY..DID NOT KNOW SIZE, TYPE OR WHAT WAS HIT WITH..

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentEnRoute_evt	2/8/2013 2:12:13 PM	Meranda, Doug
AsnAssignmentManualAck_evt	2/8/2013 2:12:16 PM	Meranda, Doug
OrdOrderSuspend_evt	2/8/2013 2:16:46 PM	Meranda, Doug
AsnAssignmentEnRoute_evt	2/8/2013 2:16:56 PM	Meranda, Doug
AsnAssignmentOnSite_evt	2/8/2013 2:58:24 PM	Meranda, Doug
OrdOrderComplete_evt	2/8/2013 4:05:29 PM	Meranda, Doug

NOTE: The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

Thursday, February 14, 2013

# Service Order Status

**Enter Service Order Number:**

5518789



Clear Form

Refresh Data

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD

**Order Number:** N5518789

**Order Type:** LEAK

**Order Status:** Completed

**Customer:** 600635854 - HALL DRU E

**Prem:** 5542694 - 112 W WALNUT ST

**Technician:** 1896 - Meranda, Doug

**Order Dates and Times**

**Need Date:** 2/8/2013 3:49:00 PM  
**Time Created:** 2/8/2013 3:50:16 PM  
**Time Dispatched:** 2/8/2013 3:50:16 PM  
**Time In Route:** 2/8/2013 4:05:33 PM  
**Time On-Site:** 2/8/2013 4:05:34 PM  
**Tech Complete:** 2/8/2013 4:21:38 PM  
**Time Closed:** 2/8/2013 4:21:38 PM

**Events Performed/Completion Code**

LKOT - CMP

**Meter Information**

**Current ReadStatus**

**Old Meter:** 0009 Active  
**New Meter:**

**Completion Notes**

hit service called for crew, dug up and squeezed off by j kurtz, repaired by contractor for vectren.....FDS# 0017463.....mrs and fds to kurtz for completion.....arrived originally at 14:36

**Request Notes**

CORRECTED ADDRESS FROM ORIGINAL HIT LINE ORDER# 5518658

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentManualAck_evt	2/8/2013 4:03:12 PM	Meranda, Doug
AsnAssignmentEnRoute_evt	2/8/2013 4:05:33 PM	Meranda, Doug
AsnAssignmentOnSite_evt	2/8/2013 4:05:34 PM	Meranda, Doug
OrdOrderComplete_evt	2/8/2013 4:21:38 PM	Meranda, Doug

NOTE: The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

## Orr, Michael

---

**From:** Lisa Eldridge [leldridge@indiana811.org]  
**Sent:** Monday, June 10, 2013 11:30 AM  
**To:** Orr, Michael; Connie Geiger  
**Subject:** RE: I need your help

Good morning Mr. Orr!!

My apologies for it taking so long to get back with you but we had some software issues. The caller gave the address of 211 W. Walnut street.

Thanks!!

Lisa

---

**From:** Orr, Michael [<mailto:MOrr@urc.IN.gov>]  
**Sent:** Thursday, June 06, 2013 8:58 AM  
**To:** Connie Geiger; Lisa Eldridge  
**Subject:** I need your help


Ladies,

I have an excavator claiming the address he gave to 811 was not the address the locator marked. I need to know if it was an electronic entry or a call to the 811 Center. If it was electronic; then, he might have transposed the address number. If it was a voice call to 811; then, I need to know what was said. The ticket number is 1301301763. Caller was Drew Hall.

Thanks,

*Michael A. Orr*

**Chief Technical Advisor  
Pipeline Safety Division  
Indiana Utility Regulatory Commission  
(317) 460-8397  
[Morr@urc.IN.gov](mailto:Morr@urc.IN.gov)**



Att. William Boyd  
Indiana Utility Regulatory Commission


From: DRU Hall  
Case # 4461

RECEIVED

APR 29 2013

INDIANA UTILITY  
REGULATORY COMMISSION

F a t  
317-233 2410





**INFORMATION REQUEST**

State Form 54909 (R / 3-13)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 4461

Date of Damage (month, day, year): 2/8/2013

**Location of Damage:**

Address (number and street): 112 West Walnut Ave.

City, State and ZIP Code: Albany, In 47320

Nearest Intersection: Main Street and West Walnut Ave. (Highway 67)

**Excavator Information:**

Business Name: The Cottage

Responsible Party Personal Name: Dru Hall

Title (if any): Owner

Address (number and street): 4175 S 1000 W.

City, State and ZIP Code: Redkey, In 47373

Preferred Telephone Number (area code): 765-744-2642

Email Address: dru@sdpmfg.com

**Utility Information:**

Utility Name: Vectren Gas

Contact Person: \_\_\_\_\_

Title (if any): \_\_\_\_\_

**Cause of Damage Information**

Type of Equipment (select one):

digger Derrick

Type of Work Performed (select one):

Setting a utility pole

Repair Cost: \$ 1,100.00

Did a leak result from damage:  Yes  No

Was there ignition:  Yes  No

Excavator Notify 911 due to leak:  Yes  No

Excavator Notify 811 upon damage:  Yes  No

Excavator Notify Utility upon Damage:  Yes  No

**Locate Information**

Excavator Request Locate:  Yes  No

Indiana 811 Locate Ticket Number: 1302081457

Locate Marks Visible:  Yes  No

Locate Marks Correct:  Yes  No

Excavator "White Lined":  Yes  No ?

Was Locate Provided within Two (2) Working Days:  Yes  No

Utility Employees On-site during Excavation:  Yes  No

**Incident Information:**

Fire Department Response:  Yes  No

Police Department Response:  Yes  No

Ambulance Response:  Yes  No

**Additional Information / Comments**

In good faith. I made every attempt to get this situation taken care of correctly, I am not an excavator so I did everything by the book. I called the locator service and I waited roughly 5 days before contacting the guys to go out & set the pole when we arrived there were some paint marks on the curb across from the property, so I assumed that they had been out & done what was needed done. The guys drilled on the property because there were no locator marks in the area where we needed to put the pole. SEE Additional page

Printed Name: DRU Hall

Signature: *DRU Hall* Date (month, day, year): 4-28-13

*\*If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

**Please return completed form to:**

[PipelineDamageCase@ure.in.gov](mailto:PipelineDamageCase@ure.in.gov)

**Or mail to:**

**Indiana Utility Regulatory Commission  
Pipeline Safety Division - Case Number \_\_\_\_\_  
101 West Washington Street, 1500E  
Indianapolis, IN 46204**

**Or fax to:  
317-233-2410**

Indiana 811 claim that I gave the wrong address 211 W Walnut  
the address is 112 W. Walnut Albany IN. There is no 211 W Walnut  
in Albany IN. As soon as the gas ~~line~~ was hit we stopped dig  
& called it in. When the Gas Company came out they did not  
have the line even on their maps. It was a plastic line & they  
did not even know it was there. Please call FREE to call

me 765 7442642

Drew Hall