



Pipeline Safety Division Investigation Report

Investigation regarding: All Bore, Inc.

UPPAC Database Record ID: 4464

Report Date: 7/18/2013

Investigator: Mike Orr

Damage Date: 2/11/2013 1:41:31 PM

Damage Address: 708 West 2nd St, Ligonier, Noble

The Parties

Excavator: **All Bore, Inc.**

Address: 16100 Allisonville Road, Noblesville, In 46060

Facility Owner: **NIPSCO**

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Boring

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes
2/7/2013

Indiana 811 Ticket Number: 1302050505

Original Start Date:

Locate Instructions: STARTING AT THE SOUTHEAST CORNER OF THE INTERSECTION - LOCATE GOING EAST ON THE FOR APPROX 1250 FEET ON THE SOUTHSIDE OF W 2ND ST - ENDING AT THE SOUTHWEST CORNER OF W 2ND ST AND THE ALLEY

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged an underground natural gas service while performing telecommunication work.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 5/16/2013. While the excavator was attempting to expose the service to maintain 2 feet of clearance, the excavator used a backhoe to expose the service. Excavator indicated he had to let the entire crew go (terminated employment). NIPSCO's response also indicated a careless machine operator was the root cause of the damage. Excavator also admitted in his response that he did not contact 911 upon release of natural gas.

Conclusion: The excavator failed to expose the facility with hand tools.

Violation: IC 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.



150 West Market Street, Suite 600
Indianapolis, IN 46204

April 22, 2012

Via Electronic Transmission – PipelineDamageCase@urc.in.gov

Pipeline Safety Division – Case No. 4464
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 East
Indianapolis, Indiana 46204

RE: Investigation Request for Information; Pipeline Division Case No. 4464

To Whom It May Concern:

Attached please find Northern Indiana Public Service Company's ("NIPSCO") written information, and supporting documentation, relating to the following event:

Date of Event: 2/11/2013

Event Location: W 2nd St

City: Perry

Facility Owner: Northern Indiana Public Service Company

Excavator: All Bore

Other Party: N/A

Pipeline Division Case No. 4464

NIPSCO has reviewed its recovery and damage prevention files for this matter and has provided answers, when known, to the list of questions set forth in the Information Request. To the extent available, NIPSCO is also providing a copy of the Damage Information Report – Pipeline Safety Division previously submitted by NIPSCO to IURC Pipeline Safety as well as additional documentation relating to this Event Location.

Upon completion of the investigation, NIPSCO requests that it be provided with a copy of the Pipeline Division's Investigation Report with findings that will be forwarded to the Underground Plant Protection Advisory Committee. If there are any additional questions, please contact the undersigned.

Very truly yours,

Christopher C. (Kit) Earle
NiSource Corporate Services - Legal
Phone: 317-684-4904
Fax: 317-684-4918
Email: cearle@nisource.com

IURC INFORMATION REQUEST	
Pipeline Safety Division Case No. 4464	
Date of Event	2/11/2013
Event Location	W 2nd St
Event City	Perry
Facility Owner	Northern Indiana Public Service Company
Excavator	All Bore
Date of IURC Information Request	3/27/2012
THE PARTIES	
EXCAVATOR:	
BUSINESS NAME	All Bore
RESPONSIBLE PARTY PERSONAL NAME	
TITLE (IF ANY)	
ADDRESS	16100 Allisonville Road
CITY/ STATE/ZIP	Noblesville / IN / 46060
PREFERRED TELEPHONE	(317)670-5509
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
FACILITY INFORMATION - OWNER/OPERATOR OF UTILITY LINE:	
BUSINESS NAME	NORTHERN INDIANA PUBLIC SERVICE COMPANY
RESPONSIBLE PARTY PERSONAL NAME	LUKE SELKING
TITLE	
ADDRESS	1501 HALE AVENUE
CITY/STATE/ZIP	FORT WAYNE, IN 46802
PREFERRED TELEPHONE	260/439-1290
SECONDARY TELEPHONE	
EMAIL ADDRESS	LSELKING@NISOURCE.COM
LOCATOR SERVICE INFORMATION	
BUSINESS NAME	USIC
RESPONSIBLE PARTY PERSONAL NAME	Morgan Thompson
TITLE (IF ANY)	Claims Coordinator
ADDRESS	9045 N. River Rd. Suite 300
CITY/ STATE/ZIP	Indianapolis, IN 46240
PREFERRED TELEPHONE	1-317-538-7301
CELL PHONE TELEPHONE	Same
EMAIL ADDRESS	morganthompson@usicinc.com
OTHER (WITNESS, POLICE, FIRE, OTHER) INFORMATION	
PERSONAL CONTACT	
BUSINESS/ORGANIZATION NAME	
TITLE (IF ANY)	

ADDRESS	
CITY/ STATE/ZIP	
PREFERRED TELEPHONE	
CELL PHONE TELEPHONE	
EMAIL ADDRESS	
UTILITY LINE IMPACT	
LOCATION OF DAMAGE	
ADDRESS	708 W 2 nd Street
CITY/STATE/ZIP	Ligonier / IN / 46767
NEAREST INTERSECTION	Greenlawn Street
PRODUCT TYPE (Select One)	
NATURAL GAS	X
LIQUID PIPELINE	
UNKNOWN/OTHER	
FACILITY TYPE (Select One)	
DISTRIBUTION	
GATHERING	
SERVICE/DROP	X
TRANSMISSION	
UNKNOWN/OTHER	
SIZE (DIAMETER/ETC.)	5/8"
PRESSURE (PSIG/INCHES)	
INTERRUPTION IN SERVICE (YES/NO)	Y
NUMBER OF CUSTOMERS AFFECTED	1
EVACUATION (YES/NO)	N
IF YES, HOW MANY EVACUATED	
REPAIR COST (IF KNOWN) (\$)	
CAUSE OF DAMAGE INFORMATION:	
TYPE OF EQUIPMENT (Select One)	
Auger	
Backhoe/Trackhoe	
Boring/Drilling	X
Directional Drilling	
Explosives	
Farm Equipment	
Grader/Scraper	
Hand Tools	
Milling Equipment	
Probing Device	

Trencher	
Vacuum Equipment	
Unknown/Other	
TYPE OF WORK PERFORMED (Select One)	
Agriculture	
Cable TV	
Curb/Sidewalk	
Bldg. Construction	
Bldg. Demolition	
Drainage	
Driveway	
Electric	
Engineering/Surveying	
Fencing	
Grading	
Irrigation	
Landscaping	
Liquid Pipeline	
Milling	
Natural Gas	
Pole	
Public Transit Authority	
Railroad Maintenance	
Road Work	
Sewer (Sanitary/Storm)	
Site Development	
Steam	
Storm Drain/Culvert	
Street Light	
Telecommunications	X
Traffic Signal	
Traffic Sign	
Water	
Waterway Improvement	
Unknown/Other	
RELEASE OF PRODUCT (YES/NO)	Y
IGNITION AND/OR FIRE (YES/NO)	N
EXCAVATOR NOTIFY 811 (YES/NO)	Y – 1302111584
LOCATE INFORMATION:	
EXCAVATOR REQUEST LOCATE (YES/NO)	Y

INDIANA 811 LOCATE TICKET NUMBER	1302050505
LOCATE MARKS VISIBLE (YES/NO)	Y
LOCATE MARKS CORRECT (YES/NO)	Y
EXCAVATOR "WHITE LINED" (YES/NO)	N
MAPS USED TO MARK FACILITIES (YES/NO)	Y
OPERATOR EMPLOYEES ON-SITE DURING EXCAVATION (YES/NO)	N
INCIDENT IMPACT INFORMATION	
NUMBER OF OUTPATIENT TREATED	0
NUMBER OF INPATIENT TREATED	0
NUMBER OF FATALITIES	0
FIRE DEPARTMENT RESPONSE (YES/NO)	N/A
POLICE DEPARTMENT RESPONSE (YES/NO)	N/A
AMBULANCE RESPONSE (YES/NO)	N/A
ADDITIONAL INFORMATION/COMMENTS	
<p>Failure to verify location by test-hole (pot-holing).</p> <p>Emergency ticket# 1302111905.</p>	

Fact Based Investigation Report

Notification ID 01820130211001
Damage Date 02/11/2013 13:41
Notified By STEVE
SPILLER ()
Damage Address 708 W 2ND ST
LIGONIER, IN
District Northern Indiana
Notification Date 02/11/2013 13:45

Damaged Customer NIPSCO

Investigation Date From 02/11/2013 00:00:00 **To** 02/11/2013 00:05:00

Excavator Involved ALL BORE INC
Type of Excavation install fiber

Orig. Locate Request 1301280117 **Start Date**
Type of Ticket **Locate Req. Info** N/A

Damage Request # 1302111693 **Start Date**

Pictures Taken By james kraushaar **Date** 02/11/2013 00:05
Photography Type Digital **Frame #**

Investigator Emp. # 131779 **Investigator Name** james kraushaar
Based on your investigation, is further investigation needed? No



Fact Based Investigation Customer Information

Facility Description Low Profile **Facility ID** Gas Service
Locator Name & EMP # Krauchaar James - 131779 **Locator Not Known**

Investigation Findings
Facility Marked Accurately
Other Notes

Investigation Methods
Investigator Verified Existing Marks By Hooking Up
Visual, Facility Exposed At Time Of Investigation

Investigator Statement/Causal Factors
contractor hit svc while boring for new fiber / svc marked accurately
Names of Utility Representatives Contacted or on Site and Statement
n/a
Names of Excavator's Representatives Contacted or on Site and Statement
n/a

Other individuals on site

n/a

Were any markings visible on the damage site upon arrival?	Yes
Were any other indicators of facility present in the area?	Yes
Was the excavation within the tolerance zone of marks?	Yes
Extent of facility damage	cut svc
Replacement Footage	n/a
Was contractor assistance required? If yes, who?	No
What contractor equipment was used?	bore machine
Is the facility shown on the utility records?	No
If yes, list record numbers	nipsco

NORTHERN INDIANA PUBLIC SERVICE COMPANY
FACILITY DAMAGE REPORT

** COMPLETE FORM FOR ALL DAMAGES TO NIPSCO FACILITIES **

REPORTING OPERATING AREA Goshen MAXIMO WO # _____
OPERATING AREA CONTACT Goshen JOB ORDER # 547277
TRACKING NUMBER 01820130201001 LOCATE REF # 1302050505
Locate Performed By: _____

DATE AND TIME OF ACCIDENT Feb 11 2013 2:33 P M DATE OF REPORT 2-11-13
PLACE OF DAMAGE (INCLUDE CITY) 208 W 2nd St Ligonier

DAMAGE WAS TO:
ELECTRIC - POLE / TRANSFORMER: # _____ SIZE _____ YEAR INSTALLED _____ BROKEN YES () NO ()
OTHER (DESCRIBE) _____

GAS: SERVICE MAIN () SIZE 5/8 MATERIAL: PLASTIC STEEL () METER () REG STATION () STUB ()
OTHER (DESCRIBE) _____

DEPTH OF FACILITY (inches) 24" PRESSURE (PSI) 45 Lbs.

RELEASE OF GAS: YES NO IGNITION OF GAS: YES () NO EVACUATION REQUIRED: YES () # _____ NO

INTERRUPTION OF SERVICE: YES NO () NUMBER OF CUSTOMERS LOST: 1

DURATION OF INTERRUPTION: TIME REPORTED 2:33 PM TIME RESTORED 3:45 PM

DIAMETER/MEASUREMENT OF HOLE IN GAS FACILITY: 5/8 cut in hole

LOCATE MARKS ON SITE: YES DISTANCE BETWEEN FACILITY AND LOCATE MARKS on mark NO ()
HOW LOCATED: PAINT FLAGS () BOTH () WHITE LINED ()

PARTY THAT CAUSED DAMAGES (NAME) Cable Bore Company (All Bore Const)

ADDRESS OF PARTY (INCLUDE CITY) N/A 16100 Allisonville Rd, Boblesville, IN 46060

WHO WAS IN CHARGE OF THE WORK SITE AT TIME OF DAMAGE N/A Steve Spiller 317-670-5509

WITNESS NAME AND ADDRESS N/A

WITNESS REMARKS N/A

AGENCIES NOTIFIED / ONSITE: POLICE () AGENCY N/A REPORT # _____

FIRE () AGENCY N/A REPORT # _____

OTHER () N/A Any Injuries? () YES # _____ NO

PHOTOS TAKEN: YES NO () TAKEN BY: Locate Company (ATTACH PHOTOS TO REPORT)
MEDIA ON SITE YES () NO

- WORK IN PROGRESS WHEN FACILITY DAMAGED - CHECK APPROPRIATE CHOICE BELOW
- | | | | |
|--|-------------------------------------|--|--|
| <input type="checkbox"/> AGRICULTURE/FARMING | <input type="checkbox"/> CABLE TV | <input type="checkbox"/> CURB/SIDEWALK | <input checked="" type="checkbox"/> TELECOMMUNICATIONS |
| <input type="checkbox"/> BLDG CONSTRUCTION | <input type="checkbox"/> DEMOLITION | <input type="checkbox"/> DRAINAGE | <input type="checkbox"/> WATER |
| <input type="checkbox"/> DRIVEWAY | <input type="checkbox"/> ELECTRIC | <input type="checkbox"/> SURVEYING | <input type="checkbox"/> DRAINS/CULVERTS |
| <input type="checkbox"/> FENCING | <input type="checkbox"/> GRADING | <input type="checkbox"/> IRRIGATION | <input type="checkbox"/> MOWING |
| <input type="checkbox"/> LANDSCAPING | <input type="checkbox"/> PIPELINE | <input type="checkbox"/> MILLING | <input type="checkbox"/> OTHER _____ |
| <input type="checkbox"/> POLE/SIGN POST | <input type="checkbox"/> ROAD WORK | <input type="checkbox"/> SEWER | |

- TYPE OF EQUIPMENT USED - CHECK APPROPRIATE CHOICE BELOW
- | | | |
|--|---|---|
| <input type="checkbox"/> AUGER | <input type="checkbox"/> HAND TOOLS | <input checked="" type="checkbox"/> BACK-HOE/TRACKHOE |
| <input type="checkbox"/> MILLING EQUIPMENT | <input type="checkbox"/> PROBING DEVICE | <input type="checkbox"/> BORING / DRILLING |
| <input type="checkbox"/> EXPLOSIVES | <input type="checkbox"/> TRENCHER | <input type="checkbox"/> FARM EQUIPMENT |
| <input type="checkbox"/> VACCUUM EQUIPMENT | <input type="checkbox"/> GRADER | <input type="checkbox"/> OTHER _____ |

- REASON DAMAGE OCCURRED - CHECK APPROPRIATE CHOICE BELOW
- | | | | |
|--|--|---|--------------------------------------|
| <input type="checkbox"/> AUTOMOTIVE ACCIDENT | <input type="checkbox"/> EXCAVATING BEFORE LOCATES DUE | <input checked="" type="checkbox"/> CARELESS MACHINE OPERATOR | |
| <input type="checkbox"/> NO NOTIFICATION | <input type="checkbox"/> MARKS DISTURBED | <input type="checkbox"/> STUB | <input type="checkbox"/> OTHER _____ |

COMMENTS: Careless operator


PERSON PREPARING REPORT William J. Sample

FIELD SUPERVISOR Joe Cole

FIELD MANAGER Rick Gray

- ORIGINAL REPORT AND SUPPORTING INFORMATION IS TO BE SENT TO FACILITY DAMAGE RECOVERY
- COPY OF REPORT IS TO BE SENT TO DAMAGE PREVENTION

SKETCH: - Show position of all pertinent information



FOR OFFICE USE ONLY:

- | | | |
|---|-----|----|
| • DID EXCAVATION OCCUR BEFORE LOCATES WERE DUE | YES | NO |
| • NO IN 811 LOCATE CALLED IN | YES | NO |
| • DAMAGE CAUSED FROM EXCAVATION WITHIN 24" ZONE | YES | NO |
| • EXPIRED LOCATE | YES | NO |
| • WAS WHITE LINING INDICATED ON LOCATE REQUEST | YES | NO |

COMPLETED BY: _____ DATE: _____

Facility: Transmission Lines; Folder: N/A; Assigned To: N/A

NIPSCO 00125 IUPPSa 02/05/2013 09:22:52 1302050505-00A NORM NEW GRID

NORMAL NOTICE REMARK SEE REMARKS

Ticket : 1302050505 Date: 02/05/2013 Time: 09:19 Oper: BMORRIS Chan:016
Old Tkt: 1301280117 Date: 01/28/2013 Time: 07:58 Oper: SMCCLURE Rev: 00A

State: IN Cnty: NOBLE Twp: PERRY
Cityname: LIGONIER Inside: Y Near: N
Subdivision:

Address :

Street : W 2ND ST

Cross 1 : GREENLAWN ST Within 1/4 mile: Y

Location: STARTING AT THE SOUTHEAST CORNER OF THE INTERSECTION - LOCATE GOING
EAST ON THE FOR APPROX 1250 FEET ON THE SOUTHSIDE OF W 2ND ST - ENDING AT THE
SOUTHWEST CORNER OF W 2ND ST AND THE ALLEY

***Boring Where = UNDER DRIVEWAY AND ROW

:

Grids : 4127A8535A 4127A8535B 4127A8536D

Boundary: n 41.464999 s 41.463901 w -85.602563 e -85.594252

Work type : INSTALL NEW FIBER OPTIC CONDUIT

Done for : LAYO BANDWIDTH

Start date: 02/07/2013 Time: 09:30 Hours notice: 48/048 Priority: NORM

Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N

Duration : 10 DAYS Depth: 15 FEET

Company : ALL BORE Type: CONT

Co addr : 16100 ALLISONVILLE ROAD

City : NOBLESVILLE State: IN Zip: 46060

Caller : STEVE SPILLER Phone: (317)670-5509

Contact : STEVE SPILLER--CELL Phone:

BestTime:

Mobile : (317)670-5509

Remarks : All tickets are taken and processed on Eastern Daylight Time
DUE TO WEATHER

Will you be white-lining the dig site area? NO

:

Submitted date: 02/05/2013 Time: 09:19

Members: AEPIN ID3032 ID4123 ID4866 ID7613 NIPSCO SM

Facility: Distribution Lines; Folder: N/A; Assigned To: USIC

NIPSCO 00396 IUPPSa 02/11/2013 13:41:36 1302111584-00A EMER DAMG GRID

DAMAGE SEE REMARKS

Ticket : 1302111584 Date: 02/11/2013 Time: 13:32 Oper: SFOX Chan:050

State: IN Cnty: NOBLE Twp: FERRY
Cityname: LIGONIER Inside: Y Near: N
Subdivision:

Address :

Street : W 2ND ST

Cross 1 : GREENLAWN ST Within 1/4 mile: Y

Location: STARTING AT THE SOUTHEAST CORNER OF THE INTERSECTION - LOCATE GOING EAST ON THE FOR APPROX 1250 FEET ON THE SOUTHSIDE OF W 2ND ST - ENDING AT THE SOUTHWEST CORNER OF W 2ND ST AND THE ALLEY

***Boring Where = UNDER DRIVEWAY AND ROW

:

Grids : 4127A8535A 4127A8535B 4127A8536D

Boundary: n 41.464999 s 41.463901 w -85.602563 e -85.594252

Work type : INSTALL NEW FIBER OPTIC CONDUIT

Done for : LAYO BANDWIDTH

Start date: 02/11/2013 Time: 13:33 Hours notice: 0/000 Priority: EMER

Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y

Duration : 10 DAYS Depth: 15 FEET

Company : ALL BORE Type: CONT

Co addr : 16100 ALLISONVILLE ROAD

City : NOBLESVILLE State: IN Zip: 46060

Caller : STEVE SPILLER Phone: (317)670-5509

Contact : STEVE SPILLER--CELL Phone:

BestTime:

Mobile : (317)670-5509

Remarks : All tickets are taken and processed on Eastern Daylight Time
A NIPSCO GAS SERVICE LINE WAS HIT ON THE FRONT OF THE PROPERTY - GAS LINE IS NOT BLOWING AND HAS BEEN CAPPED OFF - ADDRESS UNKNOWN - 3/4 INCH/UNKNOWN COLOR/UNKNOWN MATERIAL - CALLER HAS BEEN ADVISED TO CALL 911 - CREW IS ON SITE - CALLER HAS BEEN ADVISED TO CALL NIPSCO TO REPORT DAMAGE - PREVIOUS TICKET NUMBER 1302050505 - THANK YOU

Will you be white-lining the dig site area? NO

:

Submitted date: 02/11/2013 Time: 13:32

Members: AEPIN ID3032 ID4123 ID4866 ID7613 NIPSCO SM

Facility: Distribution Lines; Folder: N/A; Assigned To: USIC

NIPSCO 00411 IUPPSa 02/11/2013 14:02:22 1302111693-00A EMER NEW STRT

EMERGENCY

Ticket : 1302111693 Date: 02/11/2013 Time: 13:58 Oper: LPOHIER Chan:046

State: IN Cnty: NOBLE Twp: FERRY
Cityname: LIGONIER Inside: Y Near: N
Subdivision:

Address :

Street : W 2ND ST

Cross 1 : GREENLAWN ST Within 1/4 mile: Y

Location: LOCATE ENTIRE INTERSECTION

:

Grids : 4127A8536D

Boundary: n 41.465039 s 41.463941 w -85.601449 e -85.599989

Work type : REPAIR GAS LINE

Done for : NIPSCO

Start date: 02/11/2013 Time: 14:00 Hours notice: 0/000 Priority: EMER

Ug/Ch/Both: U Blasting: N Boring: N Railroad: N Emergency: Y

Duration : 1 DAY Depth: 6 FEET

Company : NIPSCO Type: MEMB

Co addr : 801 EAST 86TH AVENUE

City : MERRILLVILLE State: IN Zip: 46410

Caller : TANECIA GHOLSTON Phone: (800)322-2806

Contact : MARK KNISLEY - CELL Phone:

BestTime:

Mobile : (574)535-3001

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW ENROUTE

Will you be white-lining the dig site area? NO

:

Submitted date: 02/11/2013 Time: 13:58

Members: ASPIN ID3032 ID4123 ID4866 ID7613 NIPSCO SM

Facility: Transmission Lines; Folder: N/A; Assigned To: N/A

NIPSCO 00486 IUPPSa 02/11/2013 14:45:50 1302111905-00A EMER NEW STRT

EMERGENCY SEE REMARLS

Ticket : 1302111905 Date: 02/11/2013 Time: 14:42 Oper: SLUCAS Chan:060

State: IN Cnty: NOBLE Twp: PERRY
Cityname: LIGONIER Inside: Y Near: N
Subdivision:

Address : 708
Street : W 2ND ST
Cross 1 : WALNUT ST Within 1/4 mile: Y
Location: LOCATE THE ENTIRE PROPERTY
:
Grids : 4127A8535A
Boundary: n 41.465049 s 41.463925 w -85.599342 e -85.596166

Work type : REPAIR GAS LINE
Done for : NIPSCO
Start date: 02/11/2013 Time: 14:43 Hours notice: 0/000 Priority: EMER
Ug/Oh/Both: U Blasting: N Boring: N Railroad: N Emergency: Y
Duration : 1 DAY Depth: 6 FEET

Company : NIPSCO Type: MEMB
Co addr : 801 EAST 86TH AVENUE
City : MERRILLVILLE State: IN Zip: 46410
Caller : TANECIA GHOLSTON Phone: (800)322-2806
Contact : MARK KNISLEY - CELL Phone:
BestTime:
Mobile : (574)535-3001

Remarks : All tickets are taken and processed on Eastern Daylight Time
CREW EN ROUTE - THIS TICKET REPLACES EMERGENCY TICKET NUMBER 1302111693 - THANK
YOU

Will you be white-lining the dig site area? NO
:

Submitted date: 02/11/2013 Time: 14:42
Members: AEPIN ID3032 ID4123 ID4866 ID7613 NIPSCO SM



Property of United States Infrastructure Corporation
Photo taken on 2/11/2013 2:43:26 PM



Property of United States Infrastructure Corporation
Photo taken on 2/11/2013 2:44:55 PM



Property of United States Infrastructure Corporation
Photo taken on 2/11/2013 2:43:00 PM

**INFORMATION REQUEST**

State Form 54909 (R / 3-13)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

RECEIVED

MAY 16 2013

INDIANA UTILITY
REGULATORY COMMISSION**Case Number:** 4464 _____**Date of Damage** (*month, day, year*): 02, 11, 2013 _____**Location of Damage:****Address** (*number and street*): W. 2nd St _____**City, State and ZIP Code:** Ligonier _____**Nearest Intersection:** Greenlawn _____**Excavator Information:****Business Name:** All Bore Inc _____**Responsible Party Personal Name:** Steven L Spiller _____**Title** (*if any*): Supervisor _____**Address** (*number and street*): 16100 Allisonville Rd _____**City, State and ZIP Code:** Noblesville, IN 46060 _____**Preferred Telephone Number** (area code): 317 670 5509 _____**Email Address:** Diverconstsrv@aol.com _____**Utility Information:****Utility Name:** nipSCO _____**Contact Person:** _____**Title** (*if any*): _____

Cause of Damage Information

Type of Equipment (*select one*):

Backhoe/Trackhoe

Type of Work Performed (*select one*):

Telecommunications

Repair Cost: \$ 150.00

Did a leak result from damage: Yes No

Was there ignition: Yes No

Excavator Notify 911 due to leak: Yes No

Excavator Notify 811 upon damage: Yes No

Excavator Notify Utility upon Damage: Yes No

Locate Information

Excavator Request Locate: Yes No

Indiana 811 Locate Ticket Number: _____

Locate Marks Visible: Yes No

Locate Marks Correct: Yes No

Excavator "White Lined": Yes No

Was Locate Provided within Two (2) Working Days: Yes No

Utility Employees On-site during Excavation: Yes No

Incident Information:

Fire Department Response: Yes No

Police Department Response: Yes No


Ambulance Response: Yes No

Additional Information / Comments

The crew hit the service while trying to expose so that the drill crew could maintain 2 feet clearance.

* NOTE I LET THE CREW GO, HAD TO FIRE THEM, WE JUST TALKED ABOUT THIS 2 DAYS AGO. #4454

Printed Name: STEVEN L SPILLER

Signature: 

Date (month, day, year): 5/14/13

**If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

Please return completed form to:

PipelineDamageCase@urc.in.gov

Or mail to:

**Indiana Utility Regulatory Commission
Pipeline Safety Division - Case Number _____
101 West Washington Street, 1500E
Indianapolis, IN 46204**

**Or fax to:
317-233-2410**